

Available from

NRC/GPO Sales Program
Superintendent of Documents
Government Printing Office
Washington, D.C. 20402

A year's subscription consists of
12 issues of this publication

Single copies of this publication
are available from National Technical
Information Service, Springfield, VA 22161

Microfiche of single copies are
available from NRC/GPO Sales Program
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Title List of Documents Made Publicly Available

January 1-31, 1981

Division of Technical Information and Document Control
Office of Administration
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555



CONTENTS

Preface	v
Arrangement of Items by Docket Number	ix
Alphabetic Arrangement of Docket 50 Items by Facility Name	xvii
Docketed Items	1
Low Level Radwaste Disposal Sites – Docket 27	1
Domestic Licensing of Source Material – Docket 40	1
Domestic Licensing of Production and Utilization Facilities – Docket 50	5
Domestic Licensing of Special Nuclear Material – Docket 70	268
Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions – Docket 71	276
Nondocketed Items	281
10CFR – Commission Meeting Records	281
ACRS – Advisory Committee on Reactor Safeguards	282
COMMISSION – NRC Commissioners	284
CONTRACT – NRC Contracts and Modifications	287
DISCLOSURE – Financial Disclosure Information	291
FOIA – Freedom of Information Act Requests and Releases	292
GEN TECH IS – Generic Technical Issues	299
I&E – Inspection and Enforcement	299
MISC – Public Document Room Miscellaneous	300
NUREG – NUREG Reports and Related Correspondence	300
ORG – Correspondence with Other Organizations	304
PR – Proposed Rule	304
PRM – Petition for Rulemaking	335
PROJ – Projects – Predocket Licensing	335
PT21 – Noncompliance Reports and Related Correspondence	335
QA999 – Quality Assurance Inspections	335
REGGD – Regulatory Guides	337
RES – Research and Technical Assistance Reports	339
REVIEW GRP – NRC Research Review Groups	342
SECY – Position Papers Before the Commission	343
STATE PROG – State Programs	344
TOPREP – Vendor Reports and Related Correspondence	346
WASTE MGT – Nuclear Waste Management	348
XPORTLIC – Export and Import Licenses	348
Personal Author Index	357
Corporate Source Index	389
Report Number Index	413
Cross Reference of Enclosures to Principal Documents	417
Appendix A – Definitions of Docket 50 Categories	431
Appendix B – Definitions of Nondocketed Categories	439

PREFACE

The *Title List of Documents Made Publicly Available* is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, *docketed* does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.


DOCKETED ITEMS

The listings within dockets are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence
- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences, LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters

Appendix A sets forth those categories and described the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:



1. NRC/PDR Document category (see Appendix A).
2. NRC Accession Number
3. Description of information contained in the document
4. Personal author. An asterisk in this position indicates that there is no personal author.
5. Corporate, agency or nonindividual source
6. Date of document described
7. Pages in document
8. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who do not have access to video terminals.
9. This three-digit portion of this entry is the number of the frame on which this document starts.
10. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

NONDOCKETED ITEMS


The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories and their symbols are:

10CFR — Commission Meeting Records
 ACRS — Advisory Committee on Reactor Safeguards
 COMMISSION — NRC Commissioners
 CONTRACT — NRC Contracts and Modifications
 DISCLOSURE — Financial Disclosure Information
 FOIA — Freedom of Information Act Requests and Releases

I&E — Inspection and Enforcement
 MISC — Public Document Room Miscellaneous
 NUREG — NUREG Reports and Related Correspondence
 ORG — Correspondence with other organizations
 PR — Proposed Rule
 PRM — Petition for Rulemaking
 PROJ — Projects-Predocket Licensing
 PT9 — Public Records
 PT21 — Noncompliance Reports and Related Correspondence
 QA999 — Quality Assurance Inspections
 REGGD — Regulatory Guides
 RES — Research and Technical Assistance Reports
 REVIEW GRP — NRC Research Review Groups
 RM — Rulemakings
 SECY — Position Papers Before the Commission
 STATE PROG — State Programs
 TOPREP — Vendor Reports and Related Correspondence
 WASTE MGT — Nuclear Waste Management
 XPORTLIC — Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:



1. Nondocketed category
2. NRC Accession Number
3. NRC Report Number
4. Title and description of information contained in the document
5. Personal author(s). An asterisk in this position indicates that there is no personal author
6. Corporate, agency or other nonindividual source
7. Contract or financial (FIN) number (if any). If the document has a secondary report number it will appear following this entry.
8. Date of document described
9. Pages in document
10. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who do not have access to video terminals.
11. This three-digit portion of this entry is the number of the frame on which this document starts.

the document. The entry may be "Available at NRC" or "Available at NTIS." See NOTES on this page for information on ordering publications.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NRC is:

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:

National Technical Information Service
Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the charge-card number when placing your order.

3. The address for the PDR is:

1717 H Street, N.W.
Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: 8¢ per page for standard size paper; 11¢ per page for oversized paper (drawings); 25¢ per microfiche for 24x diazo duplicates. A minimum charge of \$2.00 plus postage is charged for mail orders.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Potomac Research, Inc.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
27-039	Sheffield, IL., Nuclear Engineering Co.	1	40-8649	Flinchbaugh Products, Inc.	4
27-047	Barnwell, SC, Chem-Nuclear Systems	1	40-8674	Plateau Resources, Ltd.	4
27-048	Richland, WA, Nuclear Engineering Co.	1	40-8681	Energy Fuels Nuclear, Inc.	4
40-0299	Union Carbide Corp.	1	40-8693	Ogle Petroleum, Inc.	4
40-0800	Transnuclear, Inc.	1	40-8697	Rocky Mountain Energy Co.	4
40-1162	Western Nuclear, Inc.	1	40-8698	Plateau Resources, Ltd.	5
40-1341	Edgemont Uranium Mine, TVA and Mines Development, Inc.	2	40-8707	Envirologic Systems, Inc.	5
40-2061	West Chicago Facility, Kerr-McGee Corp.	2	40-8712	Gulf Oil Corp.	5
40-2259	Pathfinder Mines Corp.	2	40-8724	Chemtron Corp.	5
40-3392	Allied Chemical Corp.	2	40-8728	Teton Exploration Drilling Co., Inc.	5
40-3453	Atlas Minerals	2	40-8743	Conoco	5
40-3698	Bell	3	40-8768	Kerr-McGee Corp.	5
40-4492	Federal American Partners (Mining)	3	40-8771	Nuclear Assurance Corp.	5
40-5939	Bell	3	40-8778	Teton Exploration Drilling Co., Inc.	5
40-6439	Univ. of New Mexico	3	50-3	Indian Point Station, Unit 1	5
40-6622	Pathfinder Mines Corp.	3	50-5	Pennsylvania State Univ. Research Reactor	6
40-7869	Plateau Resources, Ltd.	3	50-6	Battelle Memorial Institute Research Reactor	6
40-8003	General Electric Co.	3	50-10	Dresden Nuclear Power Station, Unit 1	6
40-8027	Kerr-McGee Corp.	3	50-16	Enrico Fermi Atomic Power Plant, Unit 1	8
40-8084	Lisbon Mine, Rio Algom Corp.	3	50-27	Washington State Univ. Research Reactor	9
40-8200	Cleveland-Cliffs Iron Co.	3	50-29	Yankee-Rowe Nuclear Power Station	9
40-8304	Wyoming Mineral Corp.	3	50-54	Union Carbide Research Reactor	10
40-8380	Rocky Mountain Energy Co.	3	50-57	State Univ. of New York Research Reactor	10
40-8452	Bear Creek Uranium Co.	3	50-62	Univ. of Virginia Research Reactor	10
40-8502	Irigaray Mine, Wyoming Mining Corp.	4	50-70	General Electric Test Reactor	10
40-8511	Cotter Corp.	4	50-87	Westinghouse Critical Experiment	11
40-8584	Union 76 Minerals Exploration Co.	4	50-89	General Atomic Co.	11
40-8585	Wyoming Mineral Corp.	4			

Docket	Name	Page	Docket	Name	Page
50-111	North Carolina State Univ. Research Reactor	11	50-250	Turkey Point Plant, Unit 3	39
50-131	Omaha Veterans Administration Hospital Research Reactor	11	50-251	Turkey Point Plant, Unit 4	41
50-133	Humboldt Bay Power Plant, Unit 3	11	50-254	Quad-Cities Station, Unit 1	44
50-134	Worcester Polytechnic Institute Research Reactor	12	50-255	Palisades Nuclear Plant	46
50-142	UCLA Training Reactor	13	50-259	Browns Ferry Nuclear Power Station, Unit 1	48
50-148	Univ. of Kansas Research Reactor	13	50-260	Browns Ferry Nuclear Power Station, Unit 2	50
50-151	Univ. of Illinois Research Reactor	13	50-261	H.B. Robinson Plant, Unit 2	52
50-155	Big Rock Point Nuclear Plant	13	50-262	Brigham Young Univ. Research Reactor	54
50-156	Univ. of Wisconsin Research Reactor	17	50-263	Monticello Nuclear Generating Plant	54
50-163	General Atomic Co.	17	50-265	Quad-Cities Station, Unit 2	55
50-170	National Naval Medical Center	17	50-266	Point Beach Nuclear Plant, Unit 1	57
50-184	National Bureau of Standards Reactor	17	50-267	Fort St. Vrain Nuclear Generating Station	59
50-186	Univ. of Missouri Research Reactor	18	50-269	Oconee Nuclear Station, Unit 1	61
50-187	Space Radiation Research Reactor	18	50-270	Oconee Nuclear Station, Unit 2	63
50-188	Kansas State Univ. Research Reactor	18	50-271	Vermont Yankee Nuclear Power Station	64
50-193	Rhode Island & Providence Plantations AEC	18	50-272	Salem Nuclear Generating Station, Unit 1	67
50-201	West Valley Reprocessing Plant	18	50-275	Diablo Canyon Nuclear Power Plant, Unit 1	70
50-206	San Onofre Nuclear Station, Unit 1	18	50-277	Peach Bottom Atomic Power Station, Unit 2	72
50-208	Columbia Univ. Research Reactor	20	50-278	Peach Bottom Atomic Power Station, Unit 3	74
50-213	Haddam Neck Plant	20	50-280	Surry Power Station, Unit 1	76
50-219	Oyster Creek Nuclear Power Plant	22	50-281	Surry Power Station, Unit 2	78
50-220	Nine Mile Point Nuclear Station, Unit 1	24	50-282	Prairie Island Nuclear Station, Unit 1	81
50-224	Univ. of California Research Reactor	26	50-285	Fort Calhoun Station, Unit 1	82
50-225	RPI Critical Experiment	27	50-286	Indian Point Station, Unit 3	84
50-228	Aerotest Radiography & Research Reactor	27	50-287	Oconee Nuclear Station, Unit 3	86
50-237	Dresden Nuclear Power Station, Unit 2	27	50-289	Three Mile Island Nuclear Station, Unit 1	88
50-238	Nuclear Ship Savannah	29	50-293	Pilgrim Nuclear Power Station, Unit 1	95
50-241	Mississippi State Univ. Research Reactor	29	50-295	Zion Nuclear Power Station, Unit 1	97
50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	30	50-296	Browns Ferry Nuclear Power Station, Unit 3	99
50-245	Millstone Nuclear Power Station, Unit 1	31	50-298	Cooper Nuclear Station	101
50-247	Indian Point Station, Unit 2	33	50-301	Point Beach Nuclear Plant, Unit 2	103
50-249	Dresden Nuclear Power Station, Unit 3	36	50-302	Crystal River Nuclear Plant, Unit 3	104
			50-304	Zion Nuclear Power Station, Unit 2	106

Docket	Name	Page	Docket	Name	Page
50-305	Kewaunee Nuclear Power Plant	108	50-353	Limerick Generating Station, Unit 2	172
50-306	Prairie Island Nuclear Station, Unit 2	110	50-354	Hope Creek Nuclear Station, Unit 1	173
50-309	Maine Yankee Atomic Power Plant	111	50-355	Hope Creek Nuclear Station, Unit 2	174
50-311	Salem Nuclear Generating Station, Unit 2	113	50-356	Univ. of Illinois LOPRA Research Reactor	174
50-312	Rancho Seco Nuclear Generating Station	115	50-358	William H. Zimmer Nuclear Station, Unit 1	175
50-313	Arkansas Nuclear One, Unit 1	117	50-361	San Onofre Nuclear Station, Unit 2	176
50-315	Donald C. Cook Nuclear Power Plant, Unit 1	119	50-362	San Onofre Nuclear Station, Unit 3	178
50-316	Donald C. Cook Nuclear Power Plant, Unit 2	120	50-363	Forked River Nuclear Station, Unit 1	180
50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	122	50-364	Joseph M. Farley Nuclear Plant, Unit 2	180
50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	124	50-366	Edwin I. Hatch Nuclear Plant, Unit 2	182
50-320	Three Mile Island Nuclear Station, Unit 2	126	50-367	Bailly Generating Station	183
50-321	Edwin I. Hatch Nuclear Plant, Unit 1	131	50-368	Arkansas Nuclear One, Unit 2	185
50-322	Shoreham Nuclear Power Station	132	50-369	William B. McGuire Nuclear Station, Unit 1	188
50-323	Diablo Canyon Nuclear Power Plant, Unit 2	134	50-370	William B. McGuire Nuclear Station, Unit 2	190
50-324	Brunswick Steam Electric Plant, Unit 2	135	50-373	LaSalle County Station, Unit 1	191
50-325	Brunswick Steam Electric Plant, Unit 1	138	50-374	LaSalle County Station, Unit 2	193
50-327	Sequoyah Nuclear Plant, Unit 1	140	50-376	North Coast Nuclear Plant, Puerto Rico	194
50-328	Sequoyah Nuclear Plant, Unit 2	143	50-382	Waterford Generating Station, Unit 3	194
50-329	Midland Plant, Unit 1	145	50-387	Susquehanna Steam Electric Station, Unit 1	195
50-330	Midland Plant, Unit 2	148	50-388	Susquehanna Steam Electric Station, Unit 2	198
50-331	Duane Arnold Energy Center	151	50-389	St. Lucie Plant, Unit 2	200
50-332	Barnwell Reprocessing Plant	152	50-390	Watts Bar Nuclear Plant, Unit 1	201
50-333	James A. Fitzpatrick Nuclear Power Plant	152	50-391	Watts Bar Nuclear Plant, Unit 2	202
50-334	Beaver Valley Power Station, Unit 1	154	50-392	Chi-shan Power Reactor, Unit 1, Taiwan	204
50-335	St. Lucie Plant, Unit 1	156	50-395	Virgil C. Summer Nuclear Station, Unit 1	204
50-336	Millstone Nuclear Power Station, Unit 2	158	50-396	Univ. of Virginia Cavalier Reactor	207
50-338	North Anna Power Station, Unit 1	160	50-397	WPPSS Nuclear Project, Unit 2	207
50-339	North Anna Power Station, Unit 2	162	50-400	Shearon Harris Nuclear Power Plant, Unit 1	208
50-341	Enrico Fermi Atomic Power Plant, Unit 2	164	50-401	Shearon Harris Nuclear Power Plant, Unit 2	208
50-344	Trojan Nuclear Plant	165	50-402	Shearon Harris Nuclear Power Plant, Unit 3	209
50-346	Davis-Besse Nuclear Power Station, Unit 1	167	50-403	Shearon Harris Nuclear Power Plant, Unit 4	209
50-348	Joseph M. Farley Nuclear Plant, Unit 1	169	50-404	North Anna Power Station, Unit 3	209
50-352	Limerick Generating Station, Unit 1	171	50-405	North Anna Power Station, Unit 4	209

Docket	Name	Page	Docket	Name	Page
50-409	La Crosse Boiling Water Reactor	210	50-462	Clinton Power Station, Unit 2	23
50-410	Nine Mile Point Nuclear Station, Unit 2	212	50-463	Fulton Generating Station, Unit 1	23
50-412	Beaver Valley Power Station, Unit 2	212	50-464	Fulton Generating Station, Unit 2	23
50-413	Catawba Nuclear Station, Unit 1	212	50-466	Allens Creek Nuclear Station, Unit 1	23
50-414	Catawba Nuclear Station, Unit 2	213	50-467	Allens Creek Nuclear Station, Unit 2	23
50-416	Grand Gulf Nuclear Station, Unit 1	214	STN-50-470	CESSAR System 80	23
50-417	Grand Gulf Nuclear Station, Unit 2	216	50-471	Pilgrim Nuclear Power Station, Unit 2	23
50-423	Millstone Nuclear Power Station, Unit 3	218	STN-50-480	RESAR-41	23
50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	218	STN-50-482	Wolf Creek Generating Station	23
50-425	Alvin W. Vogtle Nuclear Plant, Unit 2	219	STN-50-483	Callaway Plant, Unit 1	24
STN-50-437	Floating Nuclear Plant	219	STN-50-485	Sterling Power Nuclear Project, Unit 1	24
50-438	Bellefonte Nuclear Plant, Unit 1	220	STN-50-486	Callaway Plant, Unit 2	24
50-439	Bellefonte Nuclear Plant, Unit 2	221	STN-50-488	Perkins Nuclear Station, Unit 1	24
50-440	Perry Nuclear Power Plant, Unit 1	223	STN-50-489	Perkins Nuclear Station, Unit 2	24
50-441	Perry Nuclear Power Plant, Unit 2	224	STN-50-490	Perkins Nuclear Station, Unit 3	24
50-443	Seabrook Nuclear Station, Unit 1	224	STN-50-491	Cherokee Nuclear Station, Unit 1	24
50-444	Seabrook Nuclear Station, Unit 2	225	STN-50-492	Cherokee Nuclear Station, Unit 2	24
50-445	Comanche Peak Steam Electric Station, Unit 1	226	STN-50-493	Cherokee Nuclear Station, Unit 3	24
50-446	Comanche Peak Steam Electric Station, Unit 2	228	50-496	Montague Nuclear Power Station, Unit 1	24
			50-497	Montague Nuclear Power Station, Unit 2	24
STN-50-447	CESSAR-238	229	STN-50-498	South Texas Project, Unit 1	24
50-448	Douglas Point Nuclear Station, Unit 1	229	STN-50-499	South Texas Project, Unit 2	24
50-449	Douglas Point Nuclear Station, Unit 2	229	50-500	Davis-Besse Nuclear Power Station, Unit 2	25
50-452	Greenwood Energy Center, Unit 2	229	50-501	Davis-Besse Nuclear Power Station, Unit 3	25
50-453	Greenwood Energy Center, Unit 3	230	STN-50-508	WPPSS Nuclear Project, Unit 3	25
50-454	Byron Station, Unit 1	230	STN-50-509	WPPSS Nuclear Project, Unit 5	25
50-455	Byron Station, Unit 2	231	50-510	Blue Hills Station, Unit 1	25
50-456	Braidwood Station, Unit 1	232	50-511	Blue Hills Station, Unit 2	25
50-457	Braidwood Station, Unit 2	233	50-512	Laguna Verde Station	25
50-458	River Bend Station, Unit 1	234	50-513	WPPSS Nuclear Project, Unit 4	25
50-459	River Bend Station, Unit 2	234	50-514	Pebble Springs Nuclear Plant, Unit 1	25
50-460	WPPSS Nuclear Project, Unit 1	235	50-515	Pebble Springs Nuclear Plant, Unit 2	25
50-461	Clinton Power Station, Unit 1	235	STN-50-516	Jamesport Nuclear Station, Unit 1	25

Docket	Name	Page	Docket	Name	Page
STN-50-517	Jamesport Nuclear Station, Unit 2	253	70-0033	Texas Instruments, Inc.	2
STN-50-518	Hartsville Nuclear Plant, Unit 1	253	70-0121	Dept. of Interior, Geological Survey	2
STN-50-519	Hartsville Nuclear Plant, Unit 2	254	70-0124	Teledyne Isotopes	2
STN-50-520	Hartsville Nuclear Plant, Unit 3	255	70-0135	Babcock & Wilcox Co.	2
STN-50-521	Hartsville Nuclear Plant, Unit 4	256	70-0143	Nuclear Fuel Services, Inc.	2
STN-50-522	Skagit Nuclear Power Project Unit 1	257	70-0157	Univ. of Texas	2
STN-50-523	Skagit Nuclear Power Project, Unit 2	257	70-0168	Nuclide Corp.	2
50-524	Barton, Unit 1	257	70-0261	Schlumberger Technology Corp.	2
50-525	Barton, Unit 2	257	70-0354	Univ. of Kansas	2
50-526	Barton, Unit 3	257	70-0364	Parks Township Site, Babcock & Wilcox Co.	2
50-527	Barton, Unit 4	257	70-0371	United Nuclear Corp.	2
STN-50-528	Palo Verde Nuclear Station, Unit 1	257	70-0568	Brigham Young Univ.	2
STN-50-529	Palo Verde Nuclear Station, Unit 2	258	70-0687	Union Carbide Corp.	2
STN-50-530	Palo Verde Nuclear Station, Unit 3	260	70-0728	Univ. of Utah	2
50-537	Clinch River Breeder Reactor	261	70-0734	General Atomic Co.	2
STN-50-546	Marble Hill Nuclear Station, Unit 1	261	70-0754	Vallecitos Nuclear Center, General Electric Co.	2
STN-50-547	Marble Hill Nuclear Station, Unit 2	262	70-0818	Eastern Nazarene College	2
50-548	Fort Calhoun Station, Unit 2	263	70-0820	United Nuclear Corp.	2
STN-50-553	Phipps Bend Nuclear Station, Unit 1	263	70-0821	Washington & Lee Univ.	2
STN-50-554	Phipps Bend Nuclear Station, Unit 2	264	70-0824	Babcock & Wilcox Co.	2
STN-50-556	Black Fox Station, Unit 1	265	70-0882	Columbia Univ.	2
STN-50-557	Black Fox Station, Unit 2	265	70-0925	Cimarron Facility	2
STN-50-566	Yellow Creek Nuclear Plant, Unit 1	265	70-1007	General Electric Co.	2
STN-50-567	Yellow Creek Nuclear Plant, Unit 2	266	70-1035	Brigham Young Univ.	2
STN-50-580	Erie Nuclear Plant, Unit 1	267	70-1100	Combustion Engineering, Inc.	2
STN-50-581	Erie Nuclear Plant, Unit 2	267	70-1110	C-E Power Systems	2
50-582	Sundesort, Unit 1	267	70-1111	Elizabethtown College	2
50-583	Sundesort, Unit 2	267	70-1113	General Electric Co.	2
STN-50-592	Palo Verde Nuclear Station, Unit 4	267	70-1151	Westinghouse Electric Corp.	2
STN-50-593	Palo Verde Nuclear Station, Unit 5	268	70-1257	Mixed Oxide Fabrication Plant, Exxon Nuclear Co., Inc.	2
70-0008	Battelle Columbus Laboratories	268	70-1288	Univ. of Utah	2
70-0025	Rockwell International Corp.	268			
70-0027	Babcock & Wilcox Co.	268			

Docket	Name	Page	Docket	Name	Page
70-1308	Morris Operations, General Electric Co.	273	71-0401	Reliance Testing Laboratories, Inc.	273
70-1327	UF-6 Conversion Facility, Allied-General Nuclear Services Corp.	274	71-0402	C&R Laboratories	273
70-1374	Idaho State Univ.	274	71-0403	Schlumberger Well Service	273
70-1436	Univ. of Oklahoma	274	71-0404	Alaska Welding Center	273
70-1462	Harper-Grace Hospital, Harper Hospital Division, Detroit, MI	274	71-0405	Energy, Inc.	273
70-1470	Veterans Administration Hospital, Los Angeles, CA	274	71-4986	Model: RA-2, Exxon Nuclear Co., Inc.	273
70-1738	Pacific Gas & Electric Co.	274	71-5059	Model: URANY NIT-TNK, Nuclear Fuel Services, Inc.	273
70-1739	Tri-State Motor Transit Co.	274	71-5086	Model: UNC-2600, General Atomic Co.	273
70-1821	Plutonium Production Facility, Allied-General Nuclear Services Corp.	274	71-5364	Model: NPI-67-0442 Neutron Products, Inc.	273
70-1936	Texas A&M Univ.	274	71-5768	Model: BB-250-2, Combustion Engineering Co., Inc.	273
70-2249	Hutzel Hospital, Detroit, MI	274	71-5796	Model: 181361, Picker Corporation	273
70-2322	Edlow International Co.	274	71-5805	Model: ATCOR VNDB Cask, Atcor, Inc.	273
70-2375	Pacific Gas & Electric Co.	274	71-5908	Model: DOT-GM Type B, Babcock & Wilcox Co.	273
70-2434	Transnuclear, Inc.	275	71-5926	Model: 100, General Electric Co.	273
70-2479	Transnuclear, Inc.	275	71-5938	Model: HNPF, General Atomic Co.	273
70-2511	Transnuclear, Inc.	275	71-5939	Model: GE-1500, General Electric Co.	273
70-2529	Cardinal Cushing General Hospital, Breckton, MA	275	71-5957	Model: BMI-1, Dept. of Energy	273
70-2623	McGuire Spent Fuel Pool, Duke Power Co.	275	71-5971	Model: GE-200, General Electric Co.	273
70-2838	Cincinnati Gas & Electric Co.	275	71-5980	Model: GE-600, General Electric Co.	273
70-2882	Southern California Edison Co.	275	71-6144	Model: B2, Nuclear Engineering Co.	273
70-2901	Southern California Edison Co.	275	71-6273	Model: 48X, F, A, Y, Allied-General Nuclear Services Corp.	273
70-2908	Veterans Administration Hospital, San Diego, CA	275	71-6375	Model: PB-1, Chem-Nuclear Systems, Inc.	273
70-2909	Westinghouse Electric Corp. Power Systems	275	71-6400	Model: Super Tiger, Westinghouse Electric Corp.	273
70-2936	Mississippi Power & Light Co.	276	71-6458	Model: BU-5, General Electric Co.	273
70-2937	Pennsylvania Power & Light Co.	276	71-6573	Model: HIT-506, Nuclear Battery Corp.	273
71-0102	Source Products & Equipment Co., Inc.	276	71-6574	Model: HN-200, Hittman Nuclear & Development Corp.	273
71-0179	Nuclear Containers, Inc.	276	71-6601	Model: LL-50-100, Chem-Nuclear Systems, Inc.	273
71-0358	Dept. of the Navy, USS Sierra	276	71-6642	Model: 4.5 Ton Cf, Dept. of Energy	273
71-0398	Texas A&M Univ.	276	71-6698	Model: NFS-4, Nuclear Fuel Services, Inc.	273
71-0400	Dept. of the Navy	276			

Docket	Name	Page	Docket	Name	Page
71-6717	Model: 6717-B, Gamma Industries	278	71-9079	Model: HN-100 Series 2, Hittman Nuclear & Development Corp.	279
71-6744	Model: Poly Tiger, Nuclear Engineering Co.	278	71-9080	Model: HN-600, Hittman Nuclear & Development Corp.	279
71-9001	Model: IF-300, General Electric Co.	278	71-9086	Model: HN-100 Series 1, Hittman Nuclear & Development Corp.	279
71-9007	Model: 520, Automation Industries, Inc.	278	71-9089	Model: HN-100S, Hittman Nuclear & Development Corp.	279
71-9010	Model: NLI-1/2, NL Industries, Inc.	278	71-9094	Model: CNSI-14-195-H, Chem-Nuclear Systems, Inc.	279
71-9019	Model: BU-7, General Electric Co.	278	71-9111	Model: CN6-80A, Chem-Nuclear, Inc.	279
71-9023	Model: NLI-10/24, NL Industries, Inc.	278	71-9124	Model: L2-181 & L3-181, Nuclear Engineering Co., Inc.	279
71-9032	Model: 650, Technical Operations, Inc.	278	71-9129	Model: UNI LA-50, Northeast Utilities	279
71-9033	Model: 660 & 660E, Technical Operations, Inc.	278	71-9130	Model: NP-50-XXL, Nuclear Packaging, Inc.	279
71-9035	Model: 680, Technical Operations, Inc.	278	71-9132	Model: T-3, Nuclear Packaging, Inc.	280
71-9036	Model: C-1, Source Production & Equipment Co.	278	71-9133	Model: C-10, Gamma Industries	280
71-9044	Model: GE-1600, General Electric Co.	279	71-9141	Model: 900 Type B, Technical Operations, Inc.	280
71-9065	Model: BU-4, General Electric Co.	279	71-9145	Model: NUPAC-50, Nuclear Packaging, Inc.	280
71-9070	Model: N-55, Dept. of Energy	279			
71-9072	Model: GAHC-1, General Atomic Co.	279			
71-9074	Model: AP-100, ANEFCO, Inc.	279			

ALPHABETIC ARRANGEMENT OF DOCKET 50 ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Aerotest Radiography & Research Reactor	50-228	27	Browns Ferry Nuclear Power Station, Unit 3	50-296	9
Allens Creek Nuclear Station, Unit 1	50-466	237	Brunswick Steam Electric Plant, Unit 1	50-325	13
Allens Creek Nuclear Station, Unit 2	50-467	239	Brunswick Steam Electric Plant, Unit 2	50-324	13
Arkansas Nuclear One, Unit 1	50-313	117	Byron Station, Unit 1	50-454	23
Arkansas Nuclear One, Unit 2	50-368	185	Byron Station, Unit 2	50-455	23
Duane Arnold Energy-Center	50-331	151	Callaway Plant, Unit 1	STN-50-483	24
Edgley Generating Station	50-367	183	Callaway Plant, Unit 2	STN-50-486	24
Barnwell Reprocessing Plant	50-332	152	Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	12
Barton, Unit 1	50-524	257	Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	12
Barton, Unit 2	50-525	257	Catawba Nuclear Station, Unit 1	50-413	21
Barton, Unit 3	50-526	257	Catawba Nuclear Station, Unit 2	50-414	21
Barton, Unit 4	50-527	257	CASSAR System 80	STN-50-470	23
Battelle Memorial Institute Research Reactor	50-6	6	Cherokee Nuclear Station, Unit 1	STN-50-491	24
Beaver Valley Power Station, Unit 1	50-334	154	Cherokee Nuclear Station, Unit 2	STN-50-492	24
Beaver Valley Power Station, Unit 2	50-412	212	Cherokee Nuclear Station, Unit 3	STN-50-493	24
Bellefonte Nuclear Plant, Unit 1	50-438	220	Chi-shan Power Reactor, Unit 1, Taiwan	50-392	20
Bellefonte Nuclear Plant, Unit 2	50-439	221	Clinch River Breeder Reactor	50-537	26
Big Rock Point Nuclear Power Plant	50-155	13	Clinton Power Station, Unit 1	50-461	23
Black Fox Station, Unit 1	STN-50-556	265	Clinton Power Station, Unit 2	50-462	23
Black Fox Station, Unit 2	STN-50-557	265	Columbia Univ. Research Reactor	50-208	2
Blue Hills Station, Unit 1	50-510	251	Comanche Peak Steam Electric Station, Unit 1	50-445	23
Blue Hills Station, Unit 2	50-511	252	Comanche Peak Steam Electric Station, Unit 2	50-446	23
Braidwood Station, Unit 1	50-456	232	Donald C. Cook Nuclear Power Plant, Unit 1	50-315	1
Braidwood Station, Unit 2	50-457	233	Donald C. Cook Nuclear Power Plant, Unit 2	50-316	1
Brigham Young Univ. Research Reactor	50-262	54	Cooper Nuclear Station	50-298	10
Browns Ferry Nuclear Power Station, Unit 1	50-289	48			
Browns Ferry Nuclear Power Station, Unit 2	50-250	50			

Name	Docket	Page	Name	Docket	Page
Crystal River Nuclear Plant, Unit 3	50-302	104	Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	30
Davis-Besse Nuclear Power Station, Unit 1	50-346	167	Grand Gulf Nuclear Station, Unit 1	50-416	214
Davis-Besse Nuclear Power Station, Unit 1	50-500	250	Grand Gulf Nuclear Station, Unit 2	50-417	216
Davis-Besse Nuclear Power Station, Unit 3	50-501	251	Greenwood Energy Center, Unit 2	50-452	229
Diablo Canyon Nuclear Power Plant, Unit 1	50-275	70	Greenwood Energy Center, Unit 3	50-453	230
Diablo Canyon Nuclear Power Plant, Unit 2	50-323	134	Haddam Neck Plant	50-213	20
Douglas Point Nuclear Station, Unit 1	50-448	229	Shearon Harris Nuclear Power Plant, Unit 1	50-400	208
Douglas Point Nuclear Station, Unit 2	50-449	229	Shearon Harris Nuclear Power Plant, Unit 2	50-401	208
Dresden Nuclear Power Station, Unit 1	50-10	6	Shearon Harris Nuclear Power Plant, Unit 3	50-402	209
Dresden Nuclear Power Station, Unit 2	50-237	27	Shearon Harris Nuclear Power Plant, Unit 4	50-403	209
Dresden Nuclear Power Station, Unit 3	50-249	36	Hartsville Nuclear Plant, Unit 1	STN-50-518	253
Joseph M. Farley Nuclear Plant, Unit 1	50-348	169	Hartsville Nuclear Plant, Unit 2	STN-50-519	254
Joseph M. Farley Nuclear Plant, Unit 2	50-364	180	Hartsville Nuclear Plant, Unit 3	STN-50-520	255
Enrico Fermi Atomic Power Plant, Unit 1	50-16	8	Hartsville Nuclear Plant, Unit 4	STN-50-521	256
Enrico Fermi Atomic Power Plant, Unit 2	50-341	164	Edwin I. Hatch Nuclear Plant, Unit 1	50-321	131
Erie Nuclear Plant, Unit 1	STN-50-580	267	Edwin I. Hatch Nuclear Plant, Unit 2	50-366	182
Erie Nuclear Plant, Unit 2	STN-50-581	267	Hope Creek Nuclear Station, Unit 1	50-354	173
James A. Fitzpatrick Nuclear Power Plant	50-333	152	Hope Creek Nuclear Station, Unit 2	50-355	174
Floating Nuclear Plant	STN-50-437	219	Humboldt Bay Power Plant, Unit 3	50-133	11
Forked River Nuclear Station, Unit 1	50-363	180	Indian Point Station, Unit 1	50-3	5
Fort Calhoun Station, Unit 1	50-285	82	Indian Point Station, Unit 2	50-247	33
Fort Calhoun Station, Unit 2	50-548	263	Indian Point Station, Unit 3	50-286	84
Fort St. Vrain Nuclear Generating Station	50-267	59	Jamesport Nuclear Station, Unit 1	STN-50-516	253
Fulton Generating Station, Unit 1	50-463	237	Jamesport Nuclear Station, Unit 2	STN-50-517	253
Fulton Generating Station, Unit 2	50-464	237	Kansas State Univ. Research Reactor	50-188	18
General Atomic Co.	50-89	11	Kewaunee Nuclear Power Plant	50-305	108
General Atomic Co.	50-163	17	La Crosse Boiling Water Reactor	50-409	210
General Electric Test Reactor	50-70	10	Laguna Verde Station	50-512	252
GESSAR-238	STN-50-447	229	LaSalle County Station, Unit 1	50-373	191
			LaSalle County Station, Unit 2	50-374	193

Name	Docket	Page	Name	Docket	Page
Limerick Generating Station, Unit 1	50-352	171	Oconee Nuclear Station, Unit 3	50-287	80
Limerick Generating Station, Unit 2	50-353	172	Omaha Veterans Administration Hospital Research Reactor	50-131	1
Maine Yankee Atomic Power Plant	50-309	111	Oyster Creek Nuclear Power Plant	50-219	2
Marble Hill Nuclear Station, Unit 1	STN-50-546	261	Palisades Nuclear Plant	50-255	4
Marble Hill Nuclear Station, Unit 2	STN-50-547	262	Palo Verde Nuclear Station, Unit 1	STN-50-528	25
William B. McGuire Nuclear Station, Unit 1	50-369	188	Palo Verde Nuclear Station, Unit 2	STN-50-529	25
William B. McGuire Nuclear Station, Unit 2	50-370	190	Palo Verde Nuclear Station, Unit 3	STN-50-530	26
Midland Plant, Unit 1	50-329	145	Palo Verde Nuclear Station, Unit 4	STN-50-592	26
Midland Plant, Unit 2	50-330	148	Palo Verde Nuclear Station, Unit 5	STN-50-593	26
Millstone Nuclear Power Station, Unit 1	50-245	31	Peach Bottom Atomic Power Station, Unit 2	50-277	7
Millstone Nuclear Power Station, Unit 2	50-336	158	Peach Bottom Atomic Power Station, Unit 3	50-278	7
Millstone Nuclear Power Station, Unit 3	50-423	218	Pebble Springs Nuclear Plant, Unit 1	50-514	25
Mississippi State Univ. Research Reactor	50-241	29	Pebble Springs Nuclear Plant, Unit 2	50-515	25
Montague Nuclear Power Station, Unit 1	50-496	246	Pennsylvania State Univ. Research Reactor	50-5	
Montague Nuclear Power Station, Unit 2	50-497	246	Perkins Nuclear Station, Unit 1	STN-50-488	24
Monticello Nuclear Generating Plant	50-263	54	Perkins Nuclear Station, Unit 2	STN-50-489	24
National Bureau of Standards Reactor	50-184	17	Perkins Nuclear Station, Unit 3	STN-50-490	24
National Naval Medical Center	50-170	17	Perry Nuclear Power Plant, Unit 1	50-440	22
Nine Mile Point Nuclear Station, Unit 1	50-220	24	Perry Nuclear Power Plant, Unit 2	50-441	22
Nine Mile Point Nuclear Station, Unit 2	50-410	212	Phipps Bend Nuclear Plant, Unit 1	STN-50-553	26
North Anna Power Station, Unit 1	50-338	160	Phipps Bend Nuclear Plant, Unit 2	STN-50-554	26
North Anna Power Station, Unit 2	50-339	162	Pilgrim Nuclear Power Station, Unit 1	50-293	9
North Anna Power Station, Unit 3	50-404	209	Pilgrim Nuclear Power Station, Unit 2	50-471	23
North Anna Power Station, Unit 4	50-405	209	Point Beach Nuclear Plant, Unit 1	50-266	5
North Carolina State Univ. Research Reactor	50-111	11	Point Beach Nuclear Plant, Unit 2	50-301	10
North Coast Nuclear Plant, Puerto Rico	50-376	194	Prairie Island Nuclear Station, Unit 1	50-282	8
Nuclear Ship Savannah	50-238	29	Prairie Island Nuclear Station, Unit 2	50-306	11
Oconee Nuclear Station, Unit 1	50-269	61	Quad-Cities Station, Unit 1	50-254	4
Oconee Nuclear Station, Unit 2	50-270	63	Quad-Cities Station, Unit 2	50-265	5
			Rancho Seco Nuclear Generating Station	50-312	11

Name	Docket	Page	Name	Docket	Page
RESAR-41	STN-50-480	239	Susquehanna Steam Electric Station, Unit 2	50-388	19
Rhode Island & Providence Plantations AEC	50-193	18	Three Mile Island Nuclear Station, Unit 1	50-289	8
River Bend Station, Unit 1	50-458	234	Three Mile Island Nuclear Station, Unit 2	50-320	12
River Bend Station, Unit 2	50-459	234	Trojan Nuclear Plant	50-344	16
H.B. Robinson Plant, Unit 2	50-261	52	Turkey Point Plant, Unit 3	50-250	3
RPI Critical Experiment	50-225	27	Turkey Point Plant, Unit 4	50-251	4
Salem Nuclear Generating Station, Unit 1	50-272	67	UCLA Training Reactor	50-142	0
Salem Nuclear Generating Station, Unit 2	50-311	113	Union Carbide Research Reactor	50-54	1
San Onofre Nuclear Station, Unit 1	50-206	18	Univ. of California Research Reactor	50-224	2
San Onofre Nuclear Station, Unit 2	50-361	176	Univ. of Illinois LOPRA Research Reactor	50-356	1
San Onofre Nuclear Station, Unit 3	50-362	178	Univ. of Illinois Research Reactor	50-151	
Seabrook Nuclear Station, Unit 1	50-443	224	Univ. of Kansas Research Reactor	50-148	
Seabrook Nuclear Station, Unit 2	50-444	225	Univ. of Missouri Research Reactor	50-186	
Sequoyah Nuclear Plant, Unit 1	50-327	140	Univ. of Virginia Cavalier Reactor	50-396	2
Sequoyah Nuclear Plant, Unit 2	50-328	143	Univ. of Virginia Research Reactor	50-62	
Shoreham Nuclear Power Station	50-322	132	Univ. of Wisconsin Research Reactor	50-156	
Skagit Nuclear Power Project, Unit 1	STN-50-522	257	Vermont Yankee Nuclear Power Station	50-271	
Skagit Nuclear Power Project, Unit 2	STN-50-523	257	Alvin W. Vogtle Nuclear Plant, Unit 1	50-424	2
South Texas Project, Unit 1	STN-50-498	246	Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	2
South Texas Project, Unit 2	STN-50-499	248	Washington State Univ. Research Reactor	50-27	
Space Radiation Research Reactor	50-187	18	Waterford Generating Station, Unit 3	50-382	1
State Univ. of New York Research Reactor	50-57	10	Watts Bar Nuclear Plant, Unit 1	50-390	2
Sterling Power Project, Nuclear, Unit 1	STN-50-485	243	Watts Bar Nuclear Plant, Unit 2	50-391	2
St. Lucie Plant, Unit 1	50-335	156	Westinghouse Critical Experiment	50-87	
St. Lucie Plant, Unit 2	50-389	200	West Valley Reprocessing Plant	50-201	
Virgil C. Summer Nuclear Station, Unit 1	50-395	204	Wolf Creek Generating Station	STN-50-482	2
Sundesert, Unit 1	50-582	267	Worcester Polytechnic Institute Research Reactor	50-134	
Sundesert, Unit 2	50-583	267	WPPSS Nuclear Project, Unit 1	50-460	23
Sutry Power Station, Unit 1	50-280	76	WPPSS Nuclear Project, Unit 2	50-397	20
Sutry Power Station, Unit 2	50-281	78	WPPSS Nuclear Project, Unit 3	STN-50-508	25
Susquehanna Steam Electric Station, Unit 1	50-387	195	WPPSS Nuclear Project, Unit 4	50-513	25
			WPPSS Nuclear Project, Unit 5	STN-50-509	25

Name	Docket	Page	Name	Docket	Page
Yankee-Rowe Nuclear Power Station	50-29	9	William H. Zimmer Nuclear Station, Unit 1	50-358	175
Yellow Creek Nuclear Plant, Unit 1	STN-50-566	265	Zion Nuclear Power Station, Unit 1	50-295	97
Yellow Creek Nuclear Plant, Unit 2	STN-50-567	266	Zion Nuclear Power Station, Unit 2	50-304	106

DOCKETED ITEMS

LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-039 SHEFFIELD, IL, NUCLEAR ENGINEERING CO

B101160120 Advises that Nuclear Engineering Co. Inc is changing name to US Ecology, Inc.
BAER, T.B. US Ecology, Inc. (Formerly Nuclear Engineering) 81/12/29.
1p. 07469:337.

B101280060 Notification of contract execution, Mod 6 to "EIS on Sheffield Low Level Waste Disposal Site." Contractor: NUB Corp.
HAIRBTON, C., SMITH, P. Technical Assistance Contracts Branch.
NRC-02-78-035 81/01/02 1p 07555:115

--B101280075 Mod 6, revoking change order to contract Mod 5 to "EIS on Sheffield Low Level Waste Disposal Site."
NUB Corp. MATTIA, M.J. Administrative Contracts Branch.
NRC-02-78-035 81/01/02 1p 07555:116

B101300116 Forwards trip rept re B01124-25 meetings w/IL govt agencies & USOR re status of low level waste disposal at Sheffield facility.
SHAFFNER, J.A. Low Level Waste Licensing Branch. 81/01/12. 3pp.
07579:341.

B101280041 Notice of ABLB reconstitution. AC Goodhope, chairman. JR Kline & FJ Remick, members. Certificate of Svc encl.
COTTER, B.P. Atomic Safety and Licensing Board Panel. 81/01/22
4pp. 07555:092.

DOCKET 27-047 BARNWELL, SC., CHEM-NUCLEAR SYSTEMS

B101270118 Forwards Waste Packaging Insp Rept 15-000039/80-20 on B01106-07. No noncompliance noted.
BIDDER, J.P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/12/02. 1p. 07547:213

--B101270122 Waste Packaging Insp Rept 15-000039/80-20 on B01106-07. No noncompliance noted. Major areas inspected: licensee-shipper vehicle insp for compliance w/DOT & NRC regulations re shipping paper requirements & radiation levels.
MACARTHUR, T.C., POTTER, J.P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/12/02. 3pp. 07547:214.

DOCKET 27-048 RICHLAND, WA., NUCLEAR ENGINEERING CO.

B101160120 Advises that Nuclear Engineering Co. Inc is changing name to US Ecology, Inc.
BAER, T.B. US Ecology, Inc. (Formerly Nuclear Engineering). 81/12/29.
1p. 07469:337.

DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0299 UNION CARBIDE CORP.

B101070272 Trip rept of 800708-09 meetings w/State of CO & Union Carbide Corp in Denver. CO re alternative tailings mgt study for Uravan mill. Investigation to determine whether tailings ponds can be reclaimed underway.
PERBON, R. Uranium Recovery Licensing Branch. 80/12/12. 8pp.
07410:345.

B101290087 Responds to vendor B01113 ltr refuting NRC 800805 comments re A-9 pit aquifer tests. Long-term aquifer pumping test in lower river aquifer, w/observation wells in Lower Wind River & Upper Wind River, is necessary. Specific comments encl.
LINEHAN, J.J. Uranium Recovery Licensing Branch. 81/01/09. 7pp.
07575:177.

DOCKET 40-0800 TRANSNUCLEAR, INC

B101200409 Application for license to import Specs are similar to License BUI-1079, w/expiration date of B50731.
MATSON, V. Transnuclear, Inc. 80/12/23 1p 07486:316

DOCKET 40-1162 WESTERN NUCLEAR, INC

B101270044 Forwards "Magnetometer & Drilling Program Results at Western Nuclear's Split Rock Impoundment."
NELSON, J.D. Colorado State Univ. 80/11/10 1p. 07547:184

--B101270049 "Magnetometer & Drilling Program Results at Western Nuclear's Split Rock Impoundment."
NELSON, J.D., ROBINETTE, M.S. Colorado State Univ. 80/11/10. 11pp
07547:185

B101100015 Forwards Split Rock Mill tailings dam insp rept for B01110-16.
BOODEN, O. Western Nuclear, Inc. 80/11/26. 4pp. 07443:053

B101100021 Forwards Split Rock Mill tailing dam insp rept for B01110-23.
BOODEN, O. Western Nuclear, Inc. 80/11/26. 4pp 07309:001

B101280536 Forwards Source Mat'l License BUA-56
SCARANO, R.A. Uranium Recovery Licensing Branch. 80/12/04. 1p
07550:231.

--B101280540 Source Mat'l License BUA-56, authorizing Western Nuclear, Inc. to possess byproduct mat'l in form of U waste tailings generated by licensee milling operations. Scope of work for hydrology study & decontamination guidelines encl.
SCARANO, R.A. Division of Waste Management. 80/12/04. 27pp
07550:232.

B101270346 Forwards Split Rock mill tailings dam insp rept for B01201-07.
BOODEN, O. Westinghouse Electric Corp., Nuclear Energy Systems. 80/12/10. 4pp. 07546:169

B101120151 Forwards safety evaluation supporting renewal of License BUA-56.
GARCIA, P.J. Uranium Recovery Licensing Branch. 80/12/15 1p
07439:001.

--B101120154 Safety evaluation supporting renewal of License BUA-56.
GARCIA, P.J., PETTENGILL, H. Uranium Recovery Licensing Branch. 80/12/04. 32pp. 07439:002.

B101270957 Forwards Split Rock mill tailings dam insp rept for B01215-21
BOODEN, O. Western Nuclear, Inc. (subs. of Phelps Dodge Corp.). 80/12/30. 4pp. 07549:170.

B101290200 Forwards safety evaluation in support of renewal of license BUA-56. Rept is provided in response to B00104 memorandum of understanding. W/b encl.
PETTENGILL, H.J. Uranium Recovery Licensing Branch. 81/01/02. 1p
07575:216.

B101290054 Trip rept of B01110-12 visit to Split Rock U Mill re resistivity survey to be conducted for identification of seepage pathways from tailings impoundment.
GARCIA, P.J. Uranium Recovery Licensing Branch. 81/01/12 2pp.
07575:111.

DOCKET 40-1341 EDGE MONT URANIUM MINE, TVA & MINES DEVELOPMENT, INC

H101050220 Notification of contract execution, Mod 2 to "TVA Edgemont Tailings Mgt Evaluation - Contractor Geotechnical Engineers, Inc.
HARRISTON, C. A. FIELDS, J. A. Technical Assistance Contracts Branch
FIN B-6994-0 80/11/15 1p 07383 219

--B101050234 Mod 2, extending period of performance of contract through 801231 at no addl cost to "TVA Edgemont Tailings Mgt Evaluation"
CASTRO, G. Geotechnical Engineers, Inc. DOUGHERTY, D. J. Technical Assistance Contracts Branch. FIN B-6994-0 80/11/15 1p 07383 220

H101094854 Requests consultation w/ assistance of DOI to further purposes of Endangered Species Act 1978 Amends List of possible endangered or threatened species in vicinity of proposed tailings disposal site desired
MILLER, H. J. Uranium Recovery Licensing Branch 80/12/10 1p 07439 063

B101270121 Lists endangered species which may be present at site & discusses actions to be taken by licensee.
BALYER, J. W. Interior, Dept. of Fish & Wildlife Service. 80/12/22 2pp. 07547 045

B101270193 Responds to FOIA request for four categories of documents
Forwards documents listed in App A. NRC could not locate documents re items 2 & 3
FELTON, J. H. Division of Rules and Records 81/01/15, 2pp. 07543 221

--B101270217 Requests that JC Gilliland, EE Evans & RF Bell be deleted as occupational medical & radiation consultants from Licenses EUA-B16, EUA-652 & EUA-160 Svcs were terminated as of 751001
KL Hudson 750707 ltr encl
BELL, R. F. Bell, R. F. MO 75/11/24 2pp

--B101270231 Summarizes preliminary results of more detailed radiation monitoring program recently completed at facility. Includes info re offsite radiation levels at Edgemont, SD U mill & YLB results Minutes of EPA 76072B meeting w/ TVA encl
GILLELAND, J. E. Tennessee Valley Authority 76/03/17 13pp

--B101270234 Forwards "Semiannual Effluent Release Rept 3, Jul-Dec 1976"
GILLELAND, J. E. Tennessee Valley Authority 77/02/25 1p

--B101270242 "Semiannual Effluent Release Rept 3, Jul-Dec 1976."
* Tennessee Valley Authority Rtr-77-2-ED-1 76/12/31 13pp.

--B101270251 Forwards "Semiannual Effluent Release Rept 2, Jan-June 1976"
GILLELAND, J. E. Tennessee Valley Authority 76/08/26 1p.

--B101270255 "Semiannual Effluent Release Rept 2, Jan-June 1976" Undated versions of quarterly monitoring repts from 1974 to present encl
* Tennessee Valley Authority 76/08/26 242pp

DOCKET 40-2061 WEST CHICAGO FACILITY, KERR-MCGEE CORP

B101050618 Discusses need for long-term solutions to site-related problems re project EPA anticipates responding to draft EIS upon release
MCQUIRE, J. Environmental Protection Agency 80/11/13 1p 07391:050

B101130005 Requests DOI assistance in evaluating presence of endangered species in plant area in response to vendor decommissioning plan
NIXON, W. A. Uranium Fuel Licensing Branch 80/11/13, 2pp 07308:001

B101100232 Forwards response to 791003 "Info Required for Commission Approval of Treatment of Disposal by Incinerations"
SHELLEY, W. J. Kerr-McGee Corp. 80/12/05 8pp 07443 266

B101130537 Informs of problems associated w/ site decommissioning, such as Areas Creek contamination, use of waste sand as offsite fill matl & radioactive matl leaching to groundwater
Requests info on EIS currently being prepared
SUMMERLEE, K. L. Environmental Protection Agency 80/12/12 2pp. 07454:141

B101290535 Clarifies apparent anomalies found in stabilization plan to License STA-0583 High radium anomaly in Table 3.2.3g caused by coal ash spread on surface of tailings pile Table 2 was calculated to include total fugitive dust generation
SHELLEY, W. J. Kerr-McGee Corp 80/12/23 2pp 07575:293

B101290145 Confirms B10106 response to NRC 801212 request for info re EIS for decommissioning of site EIS will not address thorium residuals NRC is developing federal position re responsibilities for contamination in unrestricted areas
CROW, W. T. Uranium Fuel Licensing Branch 81/01/14, 2pp 07375:194

DOCKET 40-2259 PATHFINDER MINES CORP

B011290288 Forwards monitoring data from Lucky Mc mill per 801114 request info includes airborne radiation monitoring, radon daughter monitoring for Jan 1979-Oct 1980 & personnel monitoring including bioassays for 1978-1980.
PDVEER, R. W. Pathfinder Mines Corp 80/11/19 900pp 07096 082

B101270681 Forwards revised mill organization chart reflecting administration change discussed per 800612 ltr
MUGENT, E. L. Pathfinder Mines Corp 81/01/23 2pp 07546 058

DOCKET 40-3392 ALLIED CHEMICAL CORP

B101100256 Informs that low level radioactive disposal permit was reinstated per encl State of NV 801202 ltr
CIPOLLA, A. J. Allied Chemical Corp 80/12/11 2pp. 07443:288

DOCKET 40-3453 ATLAS MINERALS

B101100025 Lists items for discussion at 801211 meeting in Washington DC includes future storage of tailings, seepage study, surety, License Condition 11 & 801003 FR regulations
SWANBY, G. T. Atlas Minerals 80/12/01 1p. 07443 001

B101060926 Requests that T Johnson participate in 801211 meeting w/ Atlas Minerals re riprap requirements for Moab project
SCARANO, R. A. Uranium Recovery Licensing Branch 80/12/05 1p 07401 103

B101060693 Responds to 801024 ltr re water & seepage. Visual check of river bank in Oct did not reveal seepage outflow to substantiate higher velocity statements contained in NRC 801024 ltr
SWANBY, G. T. Atlas Minerals 80/12/08 6pp 07400 183

B101210197 Advises that response to NRC 801125 ltr could not be submitted by 801208 due to late arrival of ltr. Items have been discussed previously Audit results of environ monitoring & reporting procedures available late Jan 1981
SWANBY, G. T. Atlas Minerals 80/12/08 1p. 07488:326

B101280205 "U Feasibility Preliminary Hydrological Study for Design of Dewatering Sys for Atlas Minerals Tailings Pond, Moab, UT."
SWANBY, G. T. Atlas Minerals 80/12/12 2pp (07187:001

--B101280210 "U Feasibility Preliminary Hydrological Study for Design of Dewatering Sys for Atlas Minerals Tailings Pond, Moab, UT."
FORSEER, B. Solution Engineering, Inc 79/05/31 21pp. 07187:001

B101290249 Forwards portions of radon rept sent to Arches Natl Park to put original numbers for sampling & analysis in perspective.
DOUGHERD, T. R. Utah, State of 80/12/30 5pp 07569:357

B101290234 RD on 80102, fire occurred in yellowcake scrubber stack fire extinguished in 15 minutes. Cause unknown. Operations in area suspended. Air sampling conducted. Employees will submit urine samples for concentration evaluation
* Atlas Minerals 81/01/02 2pp. 07569 362

B101290043 Documents review of licensee semiannual monitoring repts. Data required under License Condition 37 was not collected. Vendor must submit data or provide justification for omission
GARCIA, P. J. Uranium Recovery Licensing Branch 81/01/07 1p. 07372 351

8101290031 Forwards formal responses to 801208 submittal & request for addl info & detailed outline of proposed hydrologic study to be performed at site Drill hole info & documented inflow & outflow quantities required
LIFEHAW, J. J. Uranium Recovery Licensing Branch 81/01/12 3pp
07570 339.

8101290402 Requests amend fee for 801103 application Failure to respond will indicate that application has been abandoned
WELLS, D. License Fee Management Branch 81/01/16 1p 07568 361

DOCKET 40-3698 BELL

8101270193 Responds to FOIA request for four categories of documents. Forwards documents listed in App A NRC could not locate documents re Items 2 & 3
FELTON, J. M. Division of Rules and Records 81/01/15 2pp
07543 221.

---8101270217 Requests that JC Gilliland, EE Evans & RF Bell be deleted as occupational medical & radiation consultants from Licenses SUA-816, SUA-652 & SUA-160 Svcs were terminated as of 751001
KL Hudson 750707 ltr encl
BELL, R F Bell, R F MD. 75/11/24 2pp

DOCKET 40-4492 FEDERAL AMERICAN PARTNERS (MININO)

8101070311 Forwards Category 2A fee for minor amend to License SUA-667
ANDRUS, N J. Federal American Partners 80/12/01 1p 07415 214

DOCKET 40-5937 BELL

8101270193 Responds to FOIA request for four categories of documents. Forwards documents listed in App A NRC could not locate documents re Items 2 & 3
FELTON, J. M. Division of Rules and Records 81/01/15 2pp

---8101270217 Requests that JC Gilliland, EE Evans & RF Bell be deleted as occupational medical & radiation consultants from Licenses SUA-816, SUA-652 & SUA-160 Svcs were terminated as of 751001
KL Hudson 750707 ltr encl
BELL, R F Bell, R F MD. 75/11/24 2pp

DOCKET 40-6439 NEW MEXICO UNIV OF

8101070392 Forwards IE Info Notice 80-32. 'Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Materials.' No written response required
ENIEZEK, J. H. Division of Fuel Facility & Materials Safety 80/08/29 1p 07415 333

DOCKET 40-6622 PATHFINDER MINES CORP

8101200019 Expresses opposition to Amend 2 to License SUA-442 Mine has not been guilty of any willful violation Jeopardy to public health, interest or safety has not been shown.
RUBBELL, J. E. Pathfinder Mines Corp 80/12/05 2pp 07487 007.

8101280635 Notifies that Amend 2 to License SUA-442, issued on 801121, should be exempt from license fee
MEYER, R. B., LINEMAN, J. Uranium Recovery Licensing Branch 80/12/29 1p. 07550 291

DOCKET 40-7869 PLATEAU RESOURCES, LTD.

8101220301 Forwards organization chart. Primary contact is UK Gupta, process manager. Secondary or alternate contact is K Jackson, licensing coordinator.
HEAD, W. J. Plateau Resources, Ltd 81/01/15 1p 07309 001.

DOCKET 40-8003 GENERAL ELECTRIC CO

8101290628 Discusses IE Insp Rpt 40-8003/80-01 conducted on 801027. No noncompliance noted Major areas inspected: activities re radiation safety, including examination of procedures, records & personnel interviews.
KINNEMAN, J. D. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/12/04 1p. 07571 327.

DOCKET 40-8027 KERR-MCQUEEN CORP

8101140748 Confirms discussion re applicability of Condition 13 of License SUB-1010 to existing Pond 2. Condition 13 requires that no addl process wastes be added after 801231
CROW, W. T. Uranium Fuel Licensing Branch 81/01/02 1p 07455 1

DOCKET 40-8084 LEBBON MINE, RIO ALGON CORP

8101290580 Summary of 801114 meeting w/vendor re 40CFR190 order amending all licenses & Amend 4 to License SUA-1119 updating environ monitoring program
KOLIC, J. L. Uranium Recovery Licensing Branch 80/12/21 3pp
07575 174

8101150931 Responds to 801028 ltr re notice of violation & notice of proposed imposition of civil penalties & forwards order imposing civil monetary penalties Addl info re noncompliance requested
STELLO, V. Director's Office, Office of Inspection and Enforcement 81/01/13 2pp. 07465 037

---8101150955 Order imposing civil monetary penalties in amount of \$ based on item of noncompliance re inadequate surveys to assure against recurrence whenever intake of U ore dust by any individual exceeded 40-h control measure
STELLO, V. Director's Office, Office of Inspection and Enforcement 81/01/13 12pp 07465 039

8101200141 EN-80-48A: notice of violation & notice of proposed imposition of civil penalties to be issued to License SUA-1119 Action based on alleged noncompliance re failure to evaluate contamination on workers prior to departure.
BROCKETT, T. W., THOMPSON, D. Office of Inspection & Enforcement, Office of the Director. 81/01/13 1p 07487 036

DOCKET 40-8200 CLEVELAND-CLIFFS IRON CO

8101290547 Forwards North Rolling Pin restoration project wastewater analytical rept All drums showed exposures of less than 0.01 rem/hr Drums will be stored in warehouse in Casper, WY pending approval of disposal at Getty-Petrotonics U mill
LOUDERBACK, T. E. Cleveland-Cliffs Iron Co 80/12/22 3pp
07309 001

8101290663 Requests appropriate action re unauthorized transfer of solution mining tailings from site to Casper, WY warehouse
SCARANO, R. A. Uranium Recovery Licensing Branch 81/01/07 1p
07573 347

---8101290070 Requests approval for disposal of 12 drums of waste in Getty-Petrotonics U mill tailings pond Getty-Petrotonics 801113 approval of request encl.
LOUDERBACK, T. E. Cleveland-Cliffs Iron Co 80/11/18 4pp
07573 348.

DOCKET 40-8304 WYOMING MINERAL CORP

8101290952 Forwards initial baseline analysis for wells located in test area info constitutes basis for establishment of action levels for monitor wells 317-M-1, M-2, M-3, M-4, M-5, M-6 & UBMF M-21B through M-221
WICHERS, D. L. Wyoming Mineral Corp. 80/12/22 3pp. 07575 268

DOCKET 40-8380 ROCKY MOUNTAIN ENERGY CO

8101290539 Forwards results of Dec 1980 sampling of Patterns 3 & 4 monitor wells Analysis of assay results shows that all parameters below U control limit on Pattern 4 wells Pattern 3 wells show elevated levels of U & vanadium
NEUMAN, M. R. Rocky Mountain Energy Co 80/12/29 7pp 07309 001

8101280066 Forwards "Semiannual Effluent Monitoring Rept. Jul-Dec 1980" Data supports conclusion that leaching operation has not caused negative impact in unrestricted areas adjoining property
SPIELER, P. R. Rocky Mountain Energy Co. 81/01/21 4pp. 07557 1

DOCKET 40-8452 BEAR CREEK URANIUM CO

8101100144 Forwards semiannual rept for Jan-June 1980
DLOSOM, J. H. Bear Creek Uranium Co 80/12/04 1p. 07441 338

economic of U tailings mgmt Assessment of conformance with
technical criteria & list of disposal options encl
LANZ, E. A Rocky Mountain Energy Co 80/12/19 8pp 07575:232

DOCKET 40-8502 IRIGARAY MINE, WYOMING MINING CORP

B101270606 Submits status of excursion in shallow monitor wells Four
probable leaders discovered out of 200 wells tested Thirty
wells remain to be tested
MORROW, D Wyoming, State of 79/06/21 1p 07576:140.

B101270601 Requests that pumping of Injection Well C13 be discontinued.
pending discussion at 790814 meeting Addl pumping may
increase area groundwater sink Related info encl
MORROW, D Wyoming, State of 79/08/08 3pp 07576:137

B101250115 Affidavit re company 790709 request that electrical logs,
geological cross-sections & Hydrology Associates rept be
kept confidential
EISENBARTH, W A Wyoming Mineral Corp 79/08/13 3pp 07309:001.

B101270109 Confirms extension until 790910 to connect shallow monitor
well excursion in Well SM-4 & grants 790810 request for
extension to prepare annual rept Requests addl info to
evaluate excursion
MORROW, D Wyoming, State of 79/08/23 12pp 07309:001.

B012180067 Forwards "Irigaray Mine Site First Quarterly Rept. Jul-Sept
1980."
WICHERS, D L Wyoming Mineral Corp 80/11/11 2pp 07244:001

--B012180073 "Irigaray Mine Site First Quarterly Rept. Jul-Sept 1980 "
Three oversized drawings encl
* Wyoming Mineral Corp 80/09/30. 200pp

B101270944 Forwards Casing Integrity Test Procedure, REP-80-626.
CARMODY, B W Wyoming Mineral Corp 80/12/16 1p 07549:151

--B101270749 Casing Integrity Test Procedure, REP-80-626
* Wyoming Mineral Corp 80/12/16 1p 07549:132

B101280629 Requests addl info re casing integrity test procedure
(REP-80-627) Test pressures, max acceptable leakage rates &
procedures to be followed in event of unacceptable leakage
must be specified.
MARTIN, D E Uranium Recovery Licensing Branch 81/01/12 2pp
07550:288

DOCKET 40-8511 COTTER CORP

B101200390 Source Mat'l License SUA-1273 for Uranium, USA, Inc. authorizing
research & development of U solution mining & recovery
operation
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 76/08/13
1p. 07187:001

DOCKET 40-8584 UNION 76 MINERALS EXPLORATION CO

B101100129 Forwards revised format for QA program for U in urine
samples, superseding B00827 ltr.
ACOSTA, A P Minerals Exploration Co (subs of Union Oil Co. of
California) 80/11/20 1p 07441:331

--B101100134 QA program for U in urine samples, revised format.
* Minerals Exploration Co (subs of Union Oil Co of California)
80/08/31 3pp. 07441:332

B101090462 Responds to NRC telcon re leak in tailings pond liner
Measures to mitigate leak effects & monitor surrounding
wells discussed Underdrain leak sys will be sampled daily.
Liner installer will inspect seals on B10105
SNYDER, H L Union Minerals. 80/12/31 2pp 07442:263.

B101290448 Confirms B01231 telcon re leak in tailings pond liner. Pond
liquid sampled & undergoing analysis Increased monitoring
schedule established for wells surrounding pond Seam will be
inspected B10105
SNYDER, H L Union 76 Minerals Exploration Co 80/12/31 2pp
07570:340.

FEELICATION costs
SCARANO, R A Uranium Recovery Licensing Branch 81/01/02 1p
07550:287

B101210327 Forwards interim rept submitted to WY Dept of Environ
Quality on B10105
SNYDER, H L Union Minerals 81/01/06 3pp 07487:244.

B101280631 Authorizes payment for R Williams travel costs & prof svcs
re site visits to Sweetwater & Teton projects on B10109-12
SCARANO, R A Uranium Recovery Licensing Branch 81/01/07. 1p
07550:290

B101270610 Advises of Sweetwater U Mill B10223 startup
SNYDER, H L Union 76 Minerals Exploration Co 81/01/21 1p
07549:066

DOCKET 40-8589 WYOMING MINERAL CORP

B101060146 Informs that WY Mineral Corp submitted info re stack
emissions for Jan-Jul 1980 Emissions considered within
acceptable limits
MEYER, R S Uranium Recovery Licensing Branch 80/12/04 1p.
07399:086

DOCKET 40-8647 FLINCHBAUGH PRODUCTS, INC

B101290620 Discusses IE Insp Rept 40-8649/80-01 conducted on B01031
noncompliance noted Major areas inspected activities re
radiation safety, including examination of procedures &
records, personnel interviews & selective measurements
KIRKEMAN, J D Region I, Philadelphia, Fuel Facility & Materials
Safety Branch 80/12/03 1p. 07571:326

DOCKET 40-8674 PLATEAU RESOURCE

B101220301 Forwards organization chart Primary contact is UK Gupta,
process manager Secondary or alternate contact is K Jackson,
licensing coordinator
HEAD, W J Plateau Resources, Ltd 81/01/15 1p 07309:001.

DOCKET 40-8681 ENERGY FUELS NUCLEAR, INC

B101100023 Forwards map per B01803 telcon, confirming that historic
referenced in memorandum of agreement has not been affected
by project
BAKER, C E Energy Fuels Nuclear, Inc 80/12/03. 2pp 07443:03

B101290028 Lists steps to ensure continuity & satisfactory completion
of archeology studies Licensee & contractors shall complete
1979-B0 excavations as detailed in NRC 790409 ltr.
SCARANO, R A Uranium Recovery Licensing Branch 81/01/14 3pp.
07570:356

B101290095 Notifies of NRC plans to modify memorandum of agreement
mitigation of adverse effects of project Addl Condition 11
will insure involvement of Dept in determination of
acceptability of contractors & labs
SCARANO, R A Uranium Recovery Licensing Branch 81/01/14 5pp.
07575:184

DOCKET 40-0693 DOLE PETROLEUM, INC

B101220596 Forwards quarterly rept. Aug-Oct 1980, for pilot R&D in sl
U solution mining operation in Bison Basin area of WY.
BAUNDERS, O A, CATCHPOLE, O J Dole Petroleum, Inc. 80/12/04. 7
07309:031

DOCKET 40-8697 ROCKY MOUNTAIN ENERGY CO

B101280061 Forwards Semiannual Effluent Monitoring Rept. Jul-Dec 19
Data supports conclusion that leaching operation has not
caused negative impact in unrestricted areas adjoining
property
SPTELES, P R Rocky Mountain Energy Co 81/01/21. 4pp. 07557:1

B101300438 Submits quarterly rept for Oct-Dec 1980.
NEUMANN, M R Rocky Mountain Energy Co 81/01/23. 9pp 07586:3

DOCKET 40-0693 PLATEAU RESOURCES, LTD.

B101120184 Requests followup embankment const insp at Plateau Resource Shooting Canyon site. Preliminary indication is that at least one violation has occurred.
SCARANO, R A Uranium Recovery Licensing Branch. 00/12/17. 1p
07439.361.

B101220301 Forwards organization chart. Primary contact is UK Oupth, process manager. Secondary or alternate contact is K Jackson, licensing coordinator.
HEAD, W J Plateau Resources, Ltd. 01/01/15 1p 07309.001

DOCKET 40-0707 ENVIRONMENTAL SYSTEMS, INC.

B1012100002 Addl response to FOIA request for nine categories of records re fees concerning withdrawn, suspended or postponed applications. Forwards documents listed in App A.
FELTON, J. M. Division of Rules and Records. 00/11/21 5pp

--B1012100351 Requests payment of new fee re review of 780927 license application. Payment is due whether or not license is still requested & should be made within 30 days.
MILLER, W O License Fee Management Branch. 00/02/07. 1p.

DOCKET 40-0712 GULF OIL CORP.

B1012100002 Addl response to FOIA request for nine categories of records re fees concerning withdrawn, suspended or postponed applications. Forwards documents listed in App A.
FELTON, J. M. Division of Rules and Records. 00/11/21 5pp

--B1012100220 Requests partial refund of fee due Gulf Research & Development Co in connection w/withdrawal of application for license. Lists actual manhours required for review & amount of refund due.
MILLER, W O License Fee Management Branch. 79/06/26. 1p.

DOCKET 40-0724 CHEMTRON CORP.

B101200122 IE Insp Rpt 40-0724/00-01 on 000617-18, 0902-05 & 18-19. No noncompliance noted. Major areas inspected Rooms C, D, E & F in Bldg 21 at McGee Facility. Facility meets criteria for release to unrestricted use.
BRENTAWSKI, D J Region 3, Chicago, Office of the Director
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch. 00/11/14. 21pp.

DOCKET 40-0728 TETON EXPLORATION DRILLING CO., INC.

B101100026 RD on 001031, water noted in leak detection sys for north & south ponds. South pond leakage caused by liner damage during sprinkler float placement. North pond leaks only at high water level.
* United Nuclear Corp. 00/12/04. 10pp 07443.042.

B101290343 Forwards 001210 leak insp rpt re WY R&D Testing License 2RD. After receiving estimate of water lost, better estimation of need for monitoring well in down gradient direction can be made.
MATHISEN, R L Wyoming, State of. 00/12/30. 5pp. 07309.001.

DOCKET 40-0743 CONOCO

B101090866 Confirms schedule impacts resulting from efforts to evaluate Agreement States revised programs. Conoco, Inc. application review will be delayed & may necessitate contract extensions for technical assistance.
HAMILL, K Uranium Recovery Licensing Branch. 00/12/10. 1p.
07428.359.

B101270328 Advises that encl Advisory Council on Historic Preservation B101030 ltr re cultural clearance for project is being forwarded to NRC. No entries exist in Natl Register for Campbell County, WY.
QUIGLEY, T W CONOCO, Inc. (Continental Oil Co.). 00/12/10. 2pp.
07546.176.

B101270979 Forwards Sand Rock mill project environ rpt. D Tipton B10123 & W Tomlinson B10118 requests for rpt encl. W/o rpt.
QUIGLEY, T W CONOCO, Inc. (Continental Oil Co.). 00/12/16. 3pp.
07549.199.

DOCKET 40-0768 KFRR-McGEE CORP.

B101100162 Forwards responses to questions re SPRB 0 Sand Project research & development license as requested in B101024 telcon.
SHELLEY, W J Kerr-McGee Nuclear Corp. 00/12/05. 15pp. 07441.349.

DOCKET 40-0771 NUCLEAR ASSURANCE CORP.

B101270321 Advises that response to NRC B10121 ltr requesting addl info re license application cannot be met by B101219 Response will be forwarded upon completion of response to State of WY.
WARD, R Nuclear Assurance Corp. 00/12/09. 1p. 07546.175.

DOCKET 40-0778 TETON EXPLORATION DRILLING CO., INC.

B101210369 Forwards quarterly operating rpt for Oct-Dec 1980.
RIEGER, S. M., HILDEBRAND, P., HERLIHY, D M Teton Exploration Drilling Co., Inc. 01/01/09. 5pp. 07487.127.

--B101210370 Quarterly operating rpt for Oct-Dec 1980.
* Teton Exploration Drilling Co., Inc. 01/01/09. 40pp.
07487.132.

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 30-3 INDIAN POINT STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants. CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR.
EISENHUT, D O Division of Licensing. 00/11/13. 2pp. 07422.243.

B101070250 Requests that encl emergency planning info be made public available. W/o encl.
SQUER, J L Division of Rules and Records. 00/12/17. 1p.
07414.297.

B101230589 Forwards security plan mods. Mods withheld (ref 10CFR2.790).
O'TOOLE, J D Consolidated Edison Co of New York. 01/01/16. 1p.
95196.249.

P. Operating license stage documents & correspondence

B101100537 Ltr to all power reactor licensees & applicants forwarding summary of B100827 meeting re guidance from Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." W/o encl.
EISENHUT, D O Division of Licensing. 00/10/06. 6pp.

B101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under B18 License amend application adding model Tech Specs to App A should be submitted within 120 days.
EISENHUT, D O Division of Licensing. 00/11/20. 1p. 07443.274.

--B101100271 Revised Pages 3/4 7-22 through 28, B 3/4 7-5 & 7-6 & 6-1.
BTS snubber inservice insp requirements.
* Division of Licensing. 00/11/20. 10pp. 07443.278.

B101060420 Corrects B10124 FR notice. Effective date should be B10217.
EISENHUT, D O Division of Licensing. 00/11/25. 1p. 07397.361.

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B10112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D O Division of Licensing. 00/11/26. 8pp. 07501.234.

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B10112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D O Division of Licensing. 00/11/26. 8pp.

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B10112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D O Division of Licensing. 00/11/26. 8pp.

--B0101220516 Summary of B01120 meeting w/EPRI licensees & consultants re inclusion of linear elastic fracture mechanics in resolution of Unresolved Safety Issue A-12 Attendee list encl
SNAIDER, R Generic Issues Branch 80/11/29 7pp 07501 23A

B0101240906 Informs of NRC activities re basis for license application review scheduling & manpower & resource allocation planning
Applications & reviews which will be submitted by 1983 should be identified
T-OMP/SDM, H L Resource & Scheduling Branch 80/12/05 13pp
07401 071

B0101210445 Forwards responses to questions on Rule 50.71e. "Periodic Updating of FSARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame
EISENHUT, D O Division of Licensing 80/12/15 13pp 07489 087

B010120003 Responds to B00903 ltr re decommissioning of facility power reactor Authorization for decommissioning allowed only after applicant demonstrates that dismantling & disposal of components will follow NRC guidelines Draft reply encl
DEWITT, H R Office of Nuclear Reactor Regulation, Director.
80/12/16 5pp 07447 098

--B010120004 Requests NRC response to Con Ed proposal to evade NRC stds for decommissioning reactors & leave site as is through NY 2006 legislator ltr to colleagues encl
BRIDGES, R L Westchester County, NY 80/09/03 5pp 07447 101

G Inspection reports, IE Bulletins & correspondence

B0101200143 Forwards IE Insp Repts 50-003/80-02 & 50-247/80-14 on B00903-04 No noncompliance noted
ENLTH, D H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/11/10 2pp 07583 105

--B0101200151 IE Insp Repts 50-003/80-02 & 50-247/80-14 on B00903-04 No noncompliance noted Major areas inspected meteorological monitoring sys including monitoring equipment & support facilities in emergency operations facility
JACKSON, T J Region 1, Philadelphia, Office of the Director
BORGES, J Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/10/24 7pp 07583 107

B0101200890 Forwards Suppl 1 to IE Info Notice 80-29. "Broken Studs on Terry Turbine Steam Inlet Flange" No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director.
80/11/26 1p 07396 342

B0101200851 Forwards IE Info Notice 80-44. "Actuation of ECCS in Recirculation Mode while in Hot Shutdown" No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/12/16 1p 07397 005

R Periodic operating reports & related correspondence

B0101230582 Forwards tabulation of daily record of fish collections for Dec 1980
O'TOOLE, J D Consolidated Edison Co of New York. 81/01/15 5pp
07510 279

T Hearing transcripts on non-entirety matters

B010120285 Commission determination releasing transcript of B01210 discussion of Indian Point enforcement action
CHILK, B J Office of the Secretary of the Commission. 80/12/19 2pp 07438 132

--B010120288 Marked-up transcript of B01210 closed discussion of Indian Point enforcement action Pp 1-77 Supporting documentation encl
* Commissioners 80/12/10 67pp 07438 134

DOCKET 50-5 PENNSYLVANIA STATE UNIV RESEARCH REACTOR

P Operating license stage documents & correspondence

B0101200419 Submits info re cost of providing add criticality monitoring sys at facility Requests 2-yr exemption from code requirements
LEVINE, B H Pennsylvania State Univ 81/01/23 2pp. 07587 002

DOCKET 50-6 DAITELLE MEMORIAL INST RESEARCH REACTOR

O Inspection reports, IE Bulletins & correspondence

B0101200777 Forwards IE Insp Repts 70-0008/80-02, 30-05728/80-02 & 50-036/80-01 & notice of violation
HEPLER, J O Region 3, Chicago, Office of the Director 80/12/25 07444 062

--B0101200763 Notice of violation from Insp on B00922-26 & 1112
HEPLER, J O Region 3, Chicago, Office of the Director 80/12/1p. 07444 064

--B0101200811 IE Insp Repts 50-006/80-01, 70-0308/80-02 & 30-05728/80-02 & 1112 Noncompliance noted overexposure of one individual to external radiation & excess radioactivity concentrations in fuel storage pool
PECK, C C Region 3, Chicago, Office of the Director FISHER
Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/11/29 10pp 07444 065

DOCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B0101200387 Ltr to all licensees of operating reactor plants, CP No & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B0102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp.

O Adjudicatory correspondence

B012110423 Requests that NRC establish licensing board to consider request for license amends to carry out chemical cleaning of primary coolant sys NRC should allow cleaning to proceed prior to hearings on basis of safety evaluation
STEPTOE, P Isman, Lincoln & Beale 80/12/03 2pp 07227 133

B012110288 Order requiring NRC applicant & petitioners to file a info on license mod re proposed decontamination before Commission rules on B00708 petition to hold hearing. JF Ahearn dissenting views & Certificate of Svc encl
CHILK, B J Office of the Secretary of the Commission 81/01/4pp 07470 345

H General correspondence

B012220439 FOIA request for four categories of documents re decontamination of facility
GOLDEN, M R Citizens for a Better Environment 80/11/03 1p 07301 166

B01200072 Opposes facility flushout w/corrosive solvent Certif of Svc encl
FENSKER, R E Affiliation Unknown 81/01/11 3pp 07486 344

B01290518 Advises that future correspondence should be addressed to IL Dept of Nuclear Safety, 1039 Custer Park Drive, 5th Floor Springfield, IL 62704
WRIGHT, C H Illinois, State of 81/01/22 1p 07566 357

J Insurance & indemnity information

B01090608 Forwards guarantee of payment of deferred premiums for OSTER, J Commonwealth Edison Co 81/01/05 1p 07442 073

B01270614 Forwards Endorsements 125 & 126, 65 & 66, 53 & 54, & 13 to NELIA Policies NF-43, NF-187, NF-201 & NF-293, respectively
OSTER, J Commonwealth Edison Co 81/01/21 13pp 07183 001

B01270737 Forwards Endorsement 4 to Binders EB-1, EB-2, EB-3, EB-2 EB-30, EB-42 & EB-43 evidencing secondary financial protection
OSTER, J Commonwealth Edison Co 81/01/21 8pp 07309 001

O Advisory Committee on Reactor Safeguards reports & correspondence

B010300837 Certified minutes of ACRS Subcommittee on Dresden Nuclear Station, Unit 1 B01008 meeting in Washington, DC re facility, decontamination Visiographs encl
* ACRS - Advisory Committee on Reactor Safeguards 80/11/21 07556 002

7911270339 Forwards revised pages re proposed amend to Tech Specs in support of primary sys chemical cleaning Fee encl
PEOPLES, D L Commonwealth Edison Co. 79/11/14 3pp 01399 117

--7911270340 Revised pages to proposed amend to Tech Specs in support of chemical cleaning of primary sys
* Commonwealth Edison Co. 79/11/14 3pp 01399 119.

8010140126 Submits addl SEP topics to be added to NRC 791114 list for deletion from plant review. Items removed are not applicable to facility or are being reviewed as generic issue Revised listing of DBE accident & transient groups encl
CRUTCHFIELD, D Operating Reactors Branch 5 80/09/11 3pp 06707-080.

801220456 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D O Division of Licensing 80/11/26 8pp

801220437 Responds to FOIA request for four categories of documents re decontamination of facility Forwards documents listed in App A Addl documents are available in PDR & in LPDR Morris, IL.
FELTON, J M. Division of Rules and Records. 80/11/28 3pp 07301.163.

--8009190849 "Chemical Cleaning Licensing Submittal."
* Commonwealth Edison Co 016-NR-01-012. 79/04/14 106pp 03568 106

--801220448 Forwards "Evaluation of Dresden I Chemical Cleaning Licensing Submittal." Approves cleaning operation pending review of completed test program results before cleaning begins & formulation of acceptable preservice insp program.
MACCARY, R R. Division of Reactor Licensing (NRR-1975 only) 79/06/27. 2pp.

--801190372 "Evaluation of Dresden I Chemical Cleaning Licensing Submittal."
* Materials Engineering Branch 79/06/20 9pp 03627 044

--8010011003 Forwards addl questions required to complete review of Dow Chemical Co repts on technical study for chemical cleaning of facility
BHAQ, L C Engineering Branch (Pre 7910301). 77/10/27. 4pp 03619 307

--8010280823 informs that chemical cleaning licensing submittal reviewed
Decontamination program as proposed releases no effluents to environ & solid wastes produced are similar in type & quantity to wastes handled routinely at plant site.
YOUNGBL, ODD, B. Assistant Director for Environmental Projects. 79/06/29. 1p. 03402 174

--7904040095 Responds to 790216 memo Staff did consider SRP 11.4s EISB 11-3 in review of proposed solidification sys for chemical decontamination. Since amend addressed special decontamination program, SRP & RTP were not addressed.
WILCHISON, O W. Environmental Evaluation Branch (Pre 790625) 79/03/13. 2pp 03663 224

--7905230626 Reviews general design criteria for nuclear power plants for facilitation of operating plant decontamination or minimization of radioactive buildup on reactor plant surfaces. (M H & B 3-3)
WITT, F J. Fuel Process Systems Standards Branch. 79/03/21. 13pp.

--801220449 Draft safety evaluation supporting 791114 application for amend to License DPR-2, requesting changes to Tech Specs to delete requirements for primary containment integrity during chemical cleaning of primary coolant sys
* Office of Nuclear Reactor Regulation, Director. 79/12/31 3pp.

--801220436 Proposed changes to Tech Specs 3 D.4 7.3 D & 4.8 re limiting conditions for operation & surveillance requirements, deleting requirements for primary containment integrity during cleaning of primary coolant sys
* Commonwealth Edison Co 79/12/11. 3pp

--8010170782 Forwards request for addl info re decontamination of facility. Response to questions required to complete evaluation
GRINES, O X Environmental Evaluation Branch (Pre 790625) 77/12/05 13pp. 03650 257.

--8010090608 Requests review of BNWL rept on chemical cleaning Comm required by 780928
CHALINA, O Environmental Evaluation Branch (Pre 790625) 78/09/07 1p. 03507 001

--8010090609 Forwards working draft rept on chemical cleaning. Rept currently undergoing review & revision at lab Requests comments
HOENES, O R Battelle Memorial Institute, Pacific Northwest Laboratory 78/08/24. 22pp. 03507 001

--7809210151 Discusses decision against revising draft PNL rept on chemical cleaning at facility. Revision would not have significant impact
KREGER, W E Radiological Assessment Branch. 78/09/11 1p

801050555 Confirms proposal made by SEP owners group at 801202 meeting w/NRC increased involvement in SEP completion will be made Presentation matl used in meeting encl
SCHAFFBTALL, R. Kerr-McGee Chemical Corp (subs of Kerr-McGee Cor 80/12/05 12pp 07390 144

8010190113 Ltr to all BWR licensees forwarding 801201 generic safety evaluation re BWR scram discharge sys Recommends short-term actions necessary to assure safe operation of GE BWRs pending permanent design changes.
EISENHUT, D O Division of Licensing. 80/12/09. 2pp. 07183 001

--801190141 Generic safety evaluation re short-term actions required to assure continued safe operation of operating BWRs Continued operation of plants is acceptable pending permanent design mods Criteria for implementing design mods encl
* Division of Licensing. 80/12/01. 212pp. 07183 001

801070594 Forwards safety evaluation of SEP Topic 11-2 A. "Severe Weather Phenomena" & TX Tech Univ rept, "Tornado & Straight Wind Hazard Probability for Dresden Nuclear Power Reactor Bito, IL."
CRUTCHFIELD, D Operating Reactors Branch 5. 80/12/15 7pp 07404 289

--801070608 "Tornado & Straight Wind Hazard Probability for Dresden Nuclear Power Reactor Bito, IL."
MCDONALD, J R Texas Tech Univ NRC-04-76-345 80/05/31 26p 07404 296

801140047 Requests info re SEP Topic 1V-2, reactivity control sys design & protection against single failures Info should be provided within 90 days of receipt of ltr
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/15. 4pp 07458 210

801210445 Forwards responses to questions on Rule 50.71a, "Periodic Updating of FSAs" & FR notice of final rule SEP plants need not comply w/rule until program is complete. Non-SEP plants must comply within specified time frame.
EISENHUT, D O Division of Licensing. 80/12/15 13pp

801160029 Notification of 801218 meeting w/SEP owners group in Bethesda, MD re SEP program schedule for licensee topic completion & assignment of lead topics to plants
RUESFLL, W T Technical Support Branch 80/12/16 2pp 07466 1

801230339 Forwards listing of all SEP correspondence re Facility SEP owners group 801202 meeting List provides basis upon which to determine plant status Review & comments requested.
N/A encl
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/22 3pp 07512 097

801080144 Forwards 36 revised electrical drawings for HPCI sys addition Aperture cards in PDR
MARCEY, R E Commonwealth Edison Co. 80/12/29 2pp 07522 111

B101050500 Forwards response to NUREC-0737 No response provided for Dresden I Unit undergoing extensive rod & decontamination outage. Requirements of NUREC-0737 will be addressed prior to startup of unit scheduled for June 1986
ABEL, J S Commonwealth Edison Co 80/12/31 5pp 07385 211

B101300942 "Adequacy of Station Electric Distribution Sys Voltages, Dresden Station, Unit 1." Informal rept
UDV, A C EGLO Idaho, Inc FIN A-6256 B101300842 80/12/31 14pp. 07584 319

B101090301 Forwards Revision 15 pages to CE-1-A, QA program topical rept. Revisions reflect Summer 1980 addenda to Section III of ASME code & recent ASME survey for renewal of ASME corporate certification
ABEL, J S Commonwealth Edison Co 81/01/02 1p 07441 007

--B101090305 Revision 15 pages to QA program topical rept
* Commonwealth Edison Co. CE-1-A R15. 81/01/02 32pp. 07441 008

B101300470 Responds to B01114 ltr re alleged water loss from facilities. Belief that no direct unmonitored water has been released from station has been repeatedly confirmed by effluent monitoring program
SCOTT, D J Commonwealth Edison Co 81/01/18 3pp 07586 265

B101220368 Forwards offsite dose calculation sys description per meteorological data requirements in NUREC-0737 Task III A 2
DELGORGEE, L O Commonwealth Edison Co 81/01/19 1p 07497 014

--B101220374 "Offsite Dose Calculation Sys Meteorological Monitoring, Offsite Dose Calculation Program for Emergency Preparedness at Operating Nuclear Power Plants." Revision 2
COLEMAN, J C Commonwealth Edison Co BRADLEY, J P Murray & Trettel, Inc LAHTI, G P Sargent & Lundy, Inc. 80/07/31 130pp. 07497 015

--B101220379 "Study of Low Level Dispersion Over Northern IL"
* Murray & Trettel, Inc 74/06/30 106pp 07497 159

--B101220391 QA program for meteorological monitoring programs, Revision 2
MURRAY, J H Murray & Trettel, Inc 79/12/05 34pp 07497 264

B101260597 Forwards Util B01126 revision of facility electrical drawing index & marked-up version of NRC index of drawings indices available in Central Files only
JANECZEK, R F Commonwealth Edison Co 81/01/19 1p. 07519 029

B101290786 Ack receipt of B01222 ltr informing NRC of wells to be sampled. Requests environ contractor monthly rept
FISHER, M L Region 3, Chicago, Fuel Facility & Materials Safety Branch 81/01/19 1p 07568 035

--B101290791 Responds to NRC B01119 ltr re well samples. New samples to begin Jan 1981 & be analyzed for gross alpha, gross beta & tritium
OHLSEN, J C Commonwealth Edison Co 80/12/22 1p 07568 036

B101270661 Responds to NRC loss of offsite power survey status rept. Partial loss of offsite power survey data should have been examined prior to processing so that only data significant to safety were included. Calculated target values not valid
JANECZEK, R F Commonwealth Edison Co 81/01/20 3pp 07549 006

Q Inspection reports, IE Bulletins & correspondence

B101050249 Forwards IE Info Notice B0-38, "Cracking in Charging Pump Casing Cladding." No response required.
KEPPLER, J G Region 3, Chicago, Office of the Director 80/10/30 2pp 07389 130

B101050462 Forwards IE Bulletin B0-21, "Valve Notes Supplied by Malcolm Foundry Co, Inc." Written response required
KEPPLER, J G Region 3, Chicago, Office of the Director 80/11/06 2pp 07390 017

B101070113 Forwards IE Insp Repts 50-010/80-21, 50-237/80-23 & 50-249/80-27 on B01103-07 & notice of violation
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/11/25 2pp 07415 011

--B101070118 Notice of violation from insp on B01103-07.
* Region 3, Chicago, Office of the Director 80/11/24 1p 07415 013

--B101070125 IE Insp Repts 50-010/80-21, 50-237/80-23 & 50-249/80-27 on B01103-07. Noncompliance noted failure to collect weekly cooling water sample
JANUSKA, A Q, PHILLIPS, M P, PAPERIELLO, C J Region 3, Chicago, Office of the Director 80/11/24 10pp 07415 014

B101050533 Forwards IE Info Notice B0-43, "Failures of Continuous Water Level Monitor for Steam Discharge Val at Dresden Unit 2." No response required
KEPPLER, J G Region 3, Chicago, Office of the Director 80/12/05 2pp 07390 302

B101090778 Forwards IE Insp Repts 50-010/80-22, 50-237/80-24 & 50-249/80-28 on B01004-1114. No noncompliance noted
WEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/12/05 2pp 07430 245

--B101090785 IE Insp Repts 50-010/80-22, 50-237/80-24 & 50-249/80-28 on B01004-1114. No noncompliance noted. Major areas inspected: operational safety verification & monthly maint observation
TONGUE, I M, JORDAN, M J, WALKER, R D Region 3, Chicago, Office of the Director 80/12/05 6pp 07430 247

B101060073 Responds to IE Bulletin B0-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Valves V70900-21-1 or V70900-21-3 not used in any safety-related functions. Approx 40 manhours expended in bulletin review
RAUSCH, T J Commonwealth Edison Co 80/12/12 1p 07399 122

B101080060 Forwards IE Info Notice B0-45, "Potential Failure of BWR Backup Manual Steam Capability." No written response required
KEPPLER, J G Region 3, Chicago, Office of the Director 80/12/17 2pp 07420 329

B101130140 EN-B0-56 on or about B01219, notice of violation & notice of proposed imposition of civil penalty in amount of \$4,000 will be issued to licensees. Action based on alleged item of noncompliance re shipment of waste not packaged properly
METZGER, J Enforcement Branch THOMPSON, D Director's Office. 80/12/17 1p 07457 026

B101150240 Forwards Suppl 4 to IE Bulletin B0-17, "Failure of Control Rods to Insert During Scram at BWR." Written response required
KEPPLER, J G Region 3, Chicago, Office of the Director 80/12/18 1p 07465 348

B101050170 Forwards IE Bulletin B0-25, "Operating Problems w/Target Rod Safety Relief Valves at BWRs." No response required.
KEPPLER, J G Region 3, Chicago, Office of the Director 80/12/19 2pp 07377 301

B101060785 Addl response to FOIA request for documents re experimental use of DOW HS-1 solvent at Dresden 1 & Peach Bottom Forwards GE rept, "Radiation Level Assessment of Dresden 1 Decontamination Pilot Loop - Final Rept."
FELTON, J M Division of Rules and Records 80/12/29 1p 07400 104

B101200155 Forwards response to IE Bulletin B0-24, "Prevention of Damage Due to Water Leakage Inside Containment (B01017 Indian Point 2 Event)." Surveillance procedures, if at least monthly repetition, will be instituted by B10601
RAUSCH, T J Commonwealth Edison Co 81/01/05 6pp 07486 202

R Periodic operating reports & related correspondence

B101270515 Forwards monthly operating repts for Dec 1980.
SCOTT, D J Commonwealth Edison Co 81/01/19 1p 07546 299

--B101270520 Monthly operating repts for Dec 1980.
MAXWELL, D C Commonwealth Edison Co 81/01/16 16pp 07546 300

S Reportable occurrences, LERs & related correspondence

B101290514 LER B0-003 has been cancelled
* Commonwealth Edison Co 81/01/15 2pp 07575 242

DOCKEY 50-16 ENRICO FERMI ATOMIC POWER PLANT, UNIT 1

J Insurance & indemnity information

B101270400 Forwards Endorsements 95 & 96 to NELA Policy NF-92
MATHERS, B R Detroit Edison Co 81/01/22 4pp 07549 035

DOCKET 50-27 WASHINGTON STATE UNIV RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

B101100295 Forwards proprietary comments on B01015 physical security plan Plan does not satisfy requirements applying to reactor in event that core becomes non self-protecting Response requested by B10116 Comments withheld (ref 10CFR2 790) TEDESCHCO, R L Assistant Director for Licensing 80/12/16 1p 07445 060.

DOCKET 50-29 YANKEE-ROWE NUCLEAR POWER STATION

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR EISENHUT, D O Division of Licensing 80/11/13 2pp

B101270720 Denies B01120 request for use of shift supervisor as fire brigade leader Util must submit official request for exemption from App R requirements Util commitment to control smoking in safety-related areas acceptable CRUTCHFIELD, D Operating Reactors Branch 5 80/12/18 3pp 07549 131

H General correspondence

B101140181 Responds to Rowe Nuclear Conversion Campaign B01006 ltr re operation of facility NRC requires util to answer citizens groups questions during formal proceedings Specific violations must be cited in order to warrant public hearing DENTON, H R Office of Nuclear Reactor Regulation, Director 81/01/02 3pp 07461 205

P. Operating license stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." EISENHUT, D O Division of Licensing 80/11/26 8pp

B101090088 Confirms B01202 proposal made by SEP owners group at B01202 meeting w/NRC for completion of 60% of SEP topics by B10630 Forwards matl used during B01202 presentation BCHAFFETALL, R KMC, Inc 80/12/05 12pp 07379 321

B101060020 Informs that SEP technical evaluations on SEP Topics III-10, A, V-11, A, VI-4, VI-7, C, I, VI-7, F & VIII-2 are final since comments were not made by util within 60-days of receipt of NRC B00915 request. CRUTCHFIELD, D Operating Reactors Branch 5 80/12/09 1p 07399 159

B101070115 Notifies that technical evaluations are final re SEP Topics III-10, A, V-11, A, VI-4, VI-7, C, I, VI-7, F & VIII-2 Evaluations will be basic inputs to Facility integrated safety assessment. CRUTCHFIELD, D Operating Reactors Branch 5 80/12/08 2pp 07414 227

B101070474 Notifies that as result of NRC B01104 site visit, util must increase seismic capability of auxiliary feedwater sys Bolts should be tightened on tanks which can supply emergency feedwater to steam generators CRUTCHFIELD, D Operating Reactors Branch 5 80/12/11 3pp 07415 255

B101070281 Notification of B10121 meeting w/vendor in Bethesda, MD to discuss small break LOCA methodology (Action Item 11, K 3 30) GUTTMAN, J Reactor Systems Branch 80/12/12 2pp 07415 198

B101140068 Requests info re SEP Topic IV-2, reactivity control sys design & protection against single failures Info should be provided within 90 days of receipt of ltr. CRUTCHFIELD, D Operating Reactors Branch 5 80/12/13 4pp 07458 198

B101200639 Forwards guidelines for performing soil-structure interaction reviews for SEP facilities & simplified analytical approach for evaluating effects of soil-structure interaction using lumped parameter model. CRUTCHFIELD, D Operating Reactors Branch 5 80/12/15 2pp 07477 143

B101210445 Forwards responses to questions on Rule 50 71c, "Periodic Updating of FSARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants just comply within specified time frame EISENHUT, D O Division of Licensing 80/12/15 13pp

B101160029 Notification of B01216 meeting w/SEP owners group in Bethesda, MD re SEP program schedule for licensee topic completion & assignment of lead topics to plants RUSSELL, W T Technical Support Branch 80/12/16 2pp

B101200200 Advises that SEP review of Topic III-2 A, "Severe Weather Phenomena," is completed Safety evaluation encl Forwards Inst of Disaster Research rept, "Tornado & Straight Wind Hazard Probability for Yankee Rowe Nuclear Power Reactor Site, MA." CRUTCHFIELD, D Operating Reactors Branch 5 80/12/17 7pp 07486 155

--B101200206 "Tornado & Straight Wind Hazard Probability for Yankee Rowe Nuclear Power Reactor Site, MA." MCCONNELL, J H Texas Tech Univ NRC-04-76-345 80/05/01 26p 07486 162

B101230032 Forwards listing of all SEP correspondence re facility p SEP owners group B01202 meeting List provides basis upon which to determine plant status Review & comments requested W/o encl. CRUTCHFIELD, D Operating Reactors Branch 5 80/12/22 2pp 07512 095

B101070383 Forwards Class II license amend fee for review of Proposed Change 169 re License BPR-3 KAY, J A Yankee Atomic Electric Co 80/12/26 1p 07414 319

--B101070389 Forwards util B01226 ltr & payment of license amend fee DIGGS, R M License Fee Management Branch 81/01/05 1p 07414 322

B101270150 Advises that SEP Topic III-3 D has been deleted from rev of facility Site does not have underdrain sys to lower groundwater table. CRUTCHFIELD, D Operating Reactors Branch 5 80/12/26 2pp 07547 293

B101280477 Forwards safety evaluation re susceptibility of safety-related sys to flooding from failure of Noncategory I sys & "Technical Evaluation of Susceptibility of Safety-Related Sys to Flooding Caused by Failure." CRUTCHFIELD, D Operating Reactors Branch 5 80/12/29 2pp 07550 296

--B101280486 Safety evaluation re susceptibility of safety-related flooding from failure of Noncategory I sys Addl protective measures, in conjunction w/original design features are acceptable * Operating Reactors Branch 5 80/12/29 1p 07550 298

--B101200622 "Technical Evaluation of Susceptibility of Safety-Related Sys to Flooding Caused by Failure of Noncategory I Sys for Yankee Rowe Power Station." * Lawrence Livermore Laboratory FIN A-0231 80/11/30 10pp 07550 299

B101140361 Forwards addl info required by NUREG-0737 re TMI Action Items addressed shift technical advisor, noble gas effluent monitor, sampling & analysis of plant effluents & control room habitability. KAY, J A Yankee Atomic Electric Co 81/01/01 33pp 07458 051

B101280460 Requests addl info re B00916 Tech Specs change request for TMI Category A Lessons Learned Items Schedule is required for installation of suitable flow indication for primary relief valves or justification of why indication not needed. CRUTCHFIELD, D Operating Reactors Branch 5 81/01/02 2pp 07187 001

B101090521 Clarifies responses to NRC staff requirements on open item in App R to 10CFR50 re alternate shutdown capability. Inclusion of statement that util has not responded to NRC request was unnecessary & misleading HODDY, D E Yankee Atomic Electric Co 81/01/09 2pp 07426 30

B101120293 Forwards "Reactor Containment Bldg Integrated Leak Rate Test," performed in Sept 1980 KAY, J A Yankee Atomic Electric Co 81/01/06 1p 07439 034

--B101120296 "Reactor Containment Bldg Integrated Leak Rate Test." WARNER, B L HENDERSON, J K, AUIO, H A Yankee Atomic Electric Co 80/09/30 84pp 07439 035

80111668 07600713 1p
KAY, J A Yankee Atomic Electric Co 81/01/06 1p 07452 001
--B101130135 Submits application for withholding proprietary info from public disclosure Affidavit encl
GAUL, R H Westinghouse Electric Corp. 80/11/07 9pp 07452 002

B101140664 Forwards Reactor Containment Bldg Integrated Leak Rate Test, which provides evaluation of Type A test results & summary analysis of periodic Type B & Type C tests per 10CFR50 App J
KAY, J A Yankee Atomic Electric Co 81/01/06 1p 07461 167

--B101140678 Separate Accompanying Summary Rpt of Type B & C Events Since June 1977 Type A Test
WARNER, D E HENDERSON, T A, AUTIO, H A Yankee Atomic Electric Co 80/09/30 3pp 07461 167

--B101140682 Forwards LER 77-044/03L-0
AUTIO, H A Yankee Atomic Electric Co 77/09/16 1p 07461 172

--B101140692 LER 77-044/03L-0 on 770817, observed that leakage of valves TV-211 & TV-40B greater than acceptable limits. Caused by worn seat & disc & deteriorated diaphragm, respectively
Valve seat & disc machined & diaphragm replaced
KAY, E L Yankee Atomic Electric Co 77/09/16 1p 07461 173

B101290475 Confirms B10112 authorization for Tech Specs change requested in B101022 for Surveillance requirements section may be deferred past 18-month limit, but no later than B10531
LAINAS, O C Assistant Director for Safety Assessment 81/01/12 2pp 07575 142

B101300077 Forwards Amend 62 to License DPR-3, safety evaluation & notice of issuance & availability.
CRUTCHFIELD, D Operating Reactors Branch 5 81/01/12 2pp 07583 055

--B101300082 Amend 62 to License DPR-3, revising Tech Specs to clarify term operable as applied to single failure criterion for power reactor safety sys
CRUTCHFIELD, D Operating Reactors Branch 5 81/01/12 14pp 07583 057

--B101300085 Safety evaluation supporting Amend 62 to License DPR-3
Office of Nuclear Reactor Regulation, Director 81/01/12 2pp 07583 071

--B101300089 Notice of issuance & availability of Amend 62 to License DPR-3
CRUTCHFIELD, D Operating Reactors Branch 5 81/01/12 2pp 07583 073

B101276362 Submits info to be incorporated in evaluation of SEP Topic VIII-2, diesel generators
KAY, J A Yankee Atomic Electric Co 81/01/20 2pp 07543 068

B101270652 Responds to NRC BOC620 request for addl info re adequacy of station electric distribution sys voltages. Addl analysis for start of largest nonsafety load & analysis for 120-volt ac buses encl
KAY, J A Yankee Atomic Electric Co 81/01/21 8pp 07548 351

B101300481 Submits addl info on TMI Lessons Learned Item 2.1.3 b re four 1-inch loop relief valves on main coolant loop bypass line in response to NRC B10102 request Relief valves provide individual loop overpressure protection
KAY, J A Yankee Atomic Electric Co 81/01/23 2pp 07587 065

G Inspection reports, IE Bulletins & correspondence

B101070413 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required.
CRIER, D H Region 1, Philadelphia, Office of the Director 80/12/26 1p 07414 056

B101140750 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Holdings, Co. Inc." No cracking found in safety-related valves required for safe shutdown or to mitigate accident
MCARDLE, E Yankee Atomic Electric Co 80/12/05 2pp 07461 001

B101140751 Responds to IE Bulletin 80-20, "Failure of Bolts and Valves on Safety Shutdown System." No cracking found in safety-related valves required for safe shutdown or to mitigate accident
MCARDLE, E Yankee Atomic Electric Co 80/12/15 1p 07461 204

response required
CRIER, D H Region 1, Philadelphia, Office of the Director 80/12/16 1p 07397 013

R Periodic operating reports & related correspondence

B101150512 Forwards monthly operating rpt for Dec 1980
MCARDLE, E Yankee Atomic Electric Co 81/01/12 1p 07463 151

--B101150514 Monthly operating rpt for Dec 1980.
MCARDLE, D H Yankee Atomic Electric Co 81/01/12 4pp 07463 158

S Reportable occurrences, LERs & related correspondence

B101300703 Forwards LER 80-023/03L-0
AUTIO, H A Yankee Atomic Electric Co 81/01/26 1p 07583 321

--B101350726 LER 80-023/03L-0 on B101227, nitrogen regulator B1-PR-5 output pressure noted outside Tech Spec Caused by setpoint shift of regulator pilot Regulator adjusted
FRENCH, L D Yankee Atomic Electric Co 81/01/26 1p 07583 321

V Operator Examinations

B101140061 Forwards addl info required by NUREG-0737 re TMI Action Items addressed shift technical advisor, noble gas effluent monitor, sampling & analysis of plant effluents & control room habitability
KAY, J A Yankee Atomic Electric Co 81/01/01 33pp 07458 051

DOCKET 80-54 UNION CARBIDE RESEARCH REACTOR

P Operating license stage documents & correspondence

B101300123 Application for amend to License R-B1 & License SNM-62M change licensee name from Union Carbide Corp to Union Carbide Subsidiary B, Inc (Co B)
MCARDLE, J J Union Carbide Corp 81/01/08 1p 07449 361

DOCKET 80-57 STATE UNIV OF NEW YORK RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

B101280173 Forwards security plan, Revision 3, Encl withheld (ref 10CFR2.790)
HENRY, L O New York, State Univ of, Buffalo 81/01/23 1p 07556 141

DOCKET 80-52 UNIV OF VIRGINIA RESEARCH REACTOR

R Periodic operating reports & related correspondence

B101300382 Submits annual operating rpt for 1980, per Section 6.7 Tech Specs
FARRAR, J D Virginia, Univ of 81/01/09 14pp 07581 336

S Reportable occurrences, LERs & related correspondence

B101300443 RO on B10119, during routine core visual examination, small air bubble discovered on top of fuel element in grid plate Position 43 Operator lifted source, which became lodged under fuel element handling bar Caused by personnel error
SHRIVER, D L Virginia, Univ of 81/01/27 5pp 07581 336

DOCKET 80-70 GENERAL ELECTRIC TEST REACTOR

F Security, medical, emergency & fire protection plans

B101140620 Ack receipt of 800514 ltr transmitting proposed security plan Class III fee required
MCARDLE, E License Fee Management Branch 80/12/10 1p 07461 210

B101140613 Forwards revised fee for model 400314 security plan in response to 800514 ltr
MCARDLE, E Yankee Atomic Electric Co 81/01/12 1p 07461 210

--B101280171 Requests processing licenses B10122 ltr forwarding review fee for security plan
01008, R M License Fee Management Branch. 81/01/27 1p
07358 050

Q Adjudicatory correspondence

B101050494 Response to ASLD B01210 notice of second prehearing conference. Prehearing process should resume immediately. Evidentiary hearing should begin 60 days after B10106 prehearing conference.
EDGAR, O. L. General Electric Co 80/12/29 3pp 07390 221

--B101050506 Ninth discovery status rept Response filed opposing intervenor 780808 motion to compel & 780821 cross-motion for protective order. Lists individuals who inspected trenches on 781017 & 27.
EDGAR, O. L., GALLEN, K. P. General Electric Co. GALLEN, K. P. Morgan, Lewis & Bockius. 78/11/08 App. 07390 224

--B101050515 Tenth discovery status rept Answers filed on 781130 to intervenors' 780803 interrogatories, completing all outstanding discovery obligations. Response submitted on 781117 to ASLD 781024 order. Certificate of Bvc encl.
EDGAR, O. L., GALLEN, K. P. General Electric Co. GALLEN, K. P. Morgan, Lewis & Bockius. 79/01/10 App. 07390 230

B101160197 Responds to ASLD B10105 request for schedule re future conduct of proceeding. Final SER suppl will be issued B10115, discovery commenced B10121, final responses filed by B10327 & hearing commenced B10504. Certificate of Bvc encl.
EDGAR, O. L. General Electric Co 81/01/13 5pp 07470 048

B101200040 Proposed discovery schedule per ASLD B10105 request. Certificate of Bvc encl.
BACHMANN, R. G. Office of the Executive Legal Director. 81/01/15 App. 07477 318

B101270057 Joint response of intervenors Dellums, Burton & Burton, Friends of the Earth & B Shockley, proposing scheduling of prehearing conference & deadlines for discovery & testimony. Certificate of Bvc encl. Related correspondence.
HALTERMAN, H. L. Affiliation Unknown BALDWIN, W. A. Friends of the Earth, BALDWIN, W. A. Baldwin, W. A. 81/01/15 5pp 07547 026

D. Advisory Committee on Reactor Safeguards reports & correspondence

B101300844 Certified minutes of ACRS Subcommittee on OETR B01104 meeting in Washington, DC to continue review of restart request. Tentative schedule & attendees list encl.
* ACRS - Advisory Committee on Reactor Safeguards. 80/12/02 8pp. 07582 295

P. Operating license stage documents & correspondence

B101290538 Notification of contract execution, Mod 2 to "OETR." Contractor: D Slemmons.
PERLMAN, J. Administrative Contracts Branch. FIN B-6829. 81/01/05 1p. 07575 255

B101290016 Forwards suppl to B10127 safety evaluation re vendor B01203 "Analysis of Subgrade Rupture Mechanism at GETR." Potential load combinations resulting from surface offset & vibratory ground motion are limited.
MOVAK, T. H. Assistant Director for Operating Reactors. 81/01/15 10pp. 07570 346

B101290541 Mod 2, closing out contract, to "OETR." SLEMMONS, D. B. Slemmons, D. B. PERLMAN, J. Administrative Contracts Branch. FIN B-6829. 81/01/05 1p. 07575 256

T. Hearing transcripts on non-antitrust matters

B101090048 Transcript of B10105 prehearing conference in San Francisco, CA. Pp 91-178
* Atomic Safety and Licensing Board Panel 81/01/05. B9pp 07426 146

DOCKET 50-87 WESTINGHOUSE CRITICAL EXPERIMENT

F. Security, medical, emergency & fire protection plans

B101200090 Ack receipt of B00319 transmittal of Revision 2 to security plan Class III fee should be submitted, per ICFR170 requirements for review.
D1008, R. M. License Fee Management Branch. 80/12/23 1p 07487 111

DOCKET 50-89 GENERAL ATOMIC CO

Q Inspection reports, IE Bulletins & correspondence

B101210133 Forwards IE Insp Repts 50-089/B0-02 & 50-163/B0-02 on B01215-17. No noncompliance noted.
CREW8, J. L. Region 5, San Francisco. Reactor Operations Nuclear Support Branch. 80/12/23 2pp 07487 355

--B101210138 IE Insp Repts 50-089/B0-02 & 50-163/B0-02 on B01215-17. No noncompliance noted. Major areas inspected logs & records, review & audit & operator requalification program.
FAULKENSBERY, B. Region 5, San Francisco. Reactor Operations Nuclear Support Branch. JOHNSON, A. D. Region 5, San Francisco. Office of the Director. 80/12/23 App. 07489 357

DOCKET 50-111 NORTH CAROLINA STATE UNIV. RESEARCH REACTOR

P Operating license stage documents & correspondence

B101120178 Forwards Amend B to License R-63 & safety evaluation.
REID, R. W. Operating Reactors Branch 4. 80/12/24 2pp 07446

--B101120181 Amend B to License R-63, revising bldg & campus monitoring requirements & deleting weekly reactor & control apparatus insp.
REID, R. W. Operating Reactors Branch 4. 80/12/24 7pp 07446 360

--B101120185 Safety evaluation supporting Amend B to License R-63 * Office of Nuclear Reactor Regulation, Director. 80/12/24 07447 005

DOCKET 50-131 OMAHA VET ADMIN HOSP RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

B101050585 Requests assistance in reviewing encl emergency plan P part of application for renewal of License R-57 & includes add'l background info on reactor facility.
MILLER, J. R. Standardization & Special Projects Branch. 80/12/1p. 07390 342

--B101050589 Forwards excerpt of application for renewal of License R-57. Section on emergency planning encl.
MULLDH, T. P. Vet Admin. Hosp Omaha, NE. 79/05/10 37pp. 07390 343

Q Inspection reports, IE Bulletins & correspondence

B101070584 Forwards IE Info Notice B0-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Materials." No written response required.
SNIETEK, J. H. Division of Fuel Facility & Materials Safety. 80/08/29 1p. 07415 331

DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP ho & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR.
EISENHUT, D. Q. Division of Licensing. 80/11/13 2pp.

Q Adjudicatory correspondence

B101070135 Motion to withdraw w/o prejudice 770520 application for license amend to permit resumption of operation. Certificate of Bvc encl.
LOCKE, R. F. Pacific Gas & Electric Co. 80/12/31 16pp. 07408

--B101070139 "Future Licensing Requirement Cost Impact." * Bechtel Power Corp. (subs. of Bechtel Corp.). 80/12/31. 07408 152

B101230238 Response of intervenors TK Collins, E Hones, FP Cranston, Chesbro, DL Mitranas, Six Rivers Branch of Friends of the Earth & Sierra Club in support of util B01231 motion to withdraw amend application. Certificate of Bvc encl.
BROWN, L. J. Jones, Brown & Clifford. SHERWOOD, M. R. Sierra Club. SHERWOOD, M. R. Sherwood, M. R. 81/01/15 13pp 07512 056

DOCKETED ITEMS

B101230642 Response supporting applicant B01231 motion to withdraw license amend application w/o prejudice ASLB lacks jurisdiction to grant intervenors' request to order immediate decommissioning of plant. w/ Certificate of Svt GOLDBERG, S C Hearing Branch 2 B1/01/21 App. 07512 286

B101260917 Answer opposing until B01231 motion to withdraw license amend application Matter should be resolved permanently Certificate of Svt encl KERR, J. E. SIMPSON, J. C. EUMAS, G California, State of B1/01/22 7pp 07529 241

P Operating license stage documents & correspondence

B101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under STS License amend application adding model Tech Specs to App A should be submitted within 120 days EISENHUT, D O Division of Licensing 80/11/20 1p

--B101109271 Revised Pages 3/4 7-22 through 28.8 3/4 7-5 & 7-6 & 6-17 to STS snubber inservice insp requirements Division of Licensing 80/11/20 10pp

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" EISENHUT, D O Division of Licensing 80/11/26 8pp

B101190113 Ltr to all BWR licensees forwarding B01201 generic safety evaluation re BWR scram discharge sys Recommendations short-term actions necessary to assure safe operation of QE BWRs pending permanent design changes EISENHUT, D O Division of Licensing 80/12/09 2pp

--B101190141 Generic safety evaluation re short-term actions required to assure continued safe operation of operating BWRs Continued operation of plants is acceptable pending permanent design mods Criteria for implementing design mods encl Division of Licensing 80/12/01 212pp 07183:001

B101210445 Forwards responses to questions on Rule 50.71e, "Periodic Updating of FSARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame EISENHUT, D O Division of Licensing 80/12/15 13pp.

B101210342 Advises that Board of Supervisors will cooperate w/agencies in event of decommissioning WALSH, D Humboldt County, CA B1/01/08 1p 07490 119

B101220309 Responds to NRC B01031 ltr requesting info re participation in development of design & performance criteria for BWR scram sys. Tests, equipment, procedure verifications & any design mods will be completed before return to operation CRANE, P A Pacific Gas & Electric Co B1/01/14 1p 07500 068

B101270452 Responds to NRC B01113 ltr requesting confirmation that implementation dates in NUREG-0619 will be met Facility is shut down until decision is made re future operation. CRANE, P A Pacific Gas & Electric Co B1/01/22 1p 07549 058

G. Inspection reports, IE Bulletins & correspondence

B101120232 Forwards response to Revision 1, IE Bulletin 79-26 Plans for replacement of control rod blades will not be made until resolution of seismic issue. CRANE, P A Pacific Gas & Electric Co. 80/12/01 2pp. 07309 001

B101090504 Forwards IE Info Notice 80-43. "Failures of Continuous Water Level Monitor for Scram Discharge Val at Dresden Unit 2." No response required. ENGELKEN, R H Region 5, San Francisco, Office of the Director. 80/12/05 1p. 07387 292

B101070206 Responds to IE Bulletin 80-21. Util unable to determine if valve gates supplied by Malcolm Foundry Co. Inc are used in safety-related sys since plant is in cold shutdown issue will be resolved prior to power operation. CRANE, P A Pacific Gas & Electric Co. 80/12/09 2pp. 07187 001.

B101120547 Responds to IE Bulletin 80-23. "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." No valves used presently or planned for use in safety-related applications.

B101130108 Forwards IE Info Notice 80-45. "Potential Failure of BWR Backup Manual Scram Capability" No response required. ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/12/17 1p 07449 220

B101090775 Forwards Suppl 4 to IE Bulletin 80-17. "Failure of 76 of 10 Control Rods to Fully Insert During Scram at BWR." Written response required. ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/12/19 1p 07430 355.

B101090166 Forwards IE Bulletin 80-25. "Operating Problems W/Target Rod Safety Relief Valves at BWRs." No response required. ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/12/19 2pp 07377 274

B101290354 Forwards IE Insp Rept 50-133/80-05 on B01215-18. No noncompliance noted Encl withheld (ref 10CFR2 790). MORDERHAUD, L R Region 5, San Francisco, Safeguards Branch. B1/01/09 2pp. 07575 271.

R. Periodic operating reports & related correspondence

B101130578 Forwards monthly operating rept for Dec 1980 WEEKS, E D. Pacific Gas & Electric Co B1/01/07 2pp 07493:230

--B101130585 Monthly operating rept for Dec 1980 BAUM, P W Pacific Gas & Electric Co B1/01/05 3pp. 07453 232.

S. Reportable Occurrences, LERs & related correspondence

B101050406 Forwards LER 80-007/03L-0 CRANE, P A Pacific Gas & Electric Co 80/12/30 1p. 07390:114.

--B101050410 LER 80-007/03L-0 on B01130, sparks observed coming from pump 2 diesel engine fan area during testing. Caused by pulley sheave mounting flange breaking away from hub New part mfg on site GETTY, B C. Pacific Gas & Electric Co. 80/12/30 1p 07390:115

DOCKET 50-134 WORCESTER POLYTECH INST RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

B101290624 Releases public version of univ released emergency plan, representing pages of FSAR. FELTON, J. H. Division of Rules and Records B1/01/27 1p 07574:245.

--B101290631 Forwards public version of revised emergency plan for facility, consisting of FSAR Pages 36-38d WILBUR, L C. Worcester Polytechnic Inst. B1/01/19 1p. 07574:246

--B101290637 Public version of revised emergency plan for facility, consisting of FSAR Pages 36-38d. Worcester Polytechnic Inst. B1/01/19 7pp. 07574 247

K. Utility Final Safety Analysis Report (FSAR) & amends

B101290624 Releases public version of univ released emergency plan, representing pages of FSAR. FELTON, J. H. Division of Rules and Records B1/01/27 1p 07574:245

--B101290631 Forwards public version of revised emergency plan for facility, consisting of FSAR Pages 36-38d. WILBUR, L C. Worcester Polytechnic Inst. B1/01/19 1p. 07574:246

--B101290637 Public version of revised emergency plan for facility, consisting of FSAR Pages 36-38d. Worcester Polytechnic Inst. B1/01/19 7pp. 07574:247.

R. Periodic operating reports & related correspondence

B101160929 Submits annual operating rept for 1980. No unusual events or abnormal radiation exposures to personnel occurred. Annual major overhaul of reactor control sys was completed on schedule & all sys appear in excellent condition. WILBUR, L C. Worcester Polytechnic Inst. B1/01/12 1p. 07472 240

DOCKET 50-142 UCLA TRAINING REACTOR

Q Adjudicatory correspondence

B101120133 Responds to NRC B01124 ltr raising questions re Ar-41 concentrations from facility. Operation of reactor meets identified regulatory requirements.
DIRCKB, W. J. Office of the Executive Director for Operations
80/12/12 1p. 07309:001

--B101120137 Ack receipt of B00103 ltr transmitting comments on 10CFR2.206 petition submitted by Committee to Bridge the Gap. Info will be considered in preparation of response to petition.
STELLO, V. Office of Inspection & Enforcement, Office of the Director.
80/01/24 1p. 07309:001

B101070446 Request, submitted on behalf of intervenor Bridge the Gap, for date Univ will provide further response to intervenor first set of interrogatories. Questions 4-6 & 9 re Contention 2.
POLLOCK, M. B. Pollack, M. B. 80/12/30. 2pp 07415:308

B101160284 Order scheduling B10204-05 prehearing conference re disputed contentions. Conference will be open to public but no limited appearance statements accepted. Certificate of Svc encl.
BOWERS, E. S. Atomic Safety and Licensing Board Panel. 81/01/12. 4pp. 07470:341.

P. Operating license stage documents & correspondence

B101120133 Responds to NRC B01124 ltr raising questions re Ar-41 concentrations from facility. Operation of reactor meets identified regulatory requirements.
DIRCKB, W. J. Office of the Executive Director for Operations.
80/12/12 1p. 07309:001

--B101120135 Requests justification for allowing licensee to average Argon concentrations in unrestricted areas over 12-month period. Response requested by B101210.
BRADFORD, P. A. Commissioners. 80/11/24. 1p. 07309:001.

--B101120137 Ack receipt of B00103 ltr transmitting comments on 10CFR2.206 petition submitted by Committee to Bridge the Gap. Info will be considered in preparation of response to petition.
STELLO, V. Office of Inspection & Enforcement, Office of the Director.
80/01/24. 1p. 07309:001.

Q. Inspection reports, IE Bulletins & correspondence

B101290369 Forwards IE Insp Rept 50-142/80-03 on B01112-14. No noncompliance noted.
BOOK, H. E. Region 3, San Francisco, Fuel Facility & Materials Safety Branch. 80/12/16. 2pp. 07571:308.

--B101290574 IE Insp Rept 50-142/80-03 on B01112-14. No noncompliance noted. Major areas inspected: responses to IE Bulletin 79-19 & IE Circular 80-14 & environ protection, environ controls & emergency response planning programs.
CURTIS, J. R., WENSLAWSKI, F. Region 5, San Francisco, Office of the Director. BOOK, H. E. Region 3, San Francisco, Fuel Facility & Materials Safety Branch. 80/12/16. 6pp. 07571:310.

DOCKET 50-148 UNIV. OF KANSAS RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

B101160378 Releases public version of emergency plan as part of license renewal application.
FELTON, J. M. Division of Rules and Records. 80/12/02. 1p. 07471:036.

--B101160391 Forwards Tech Specs, public version of emergency preparedness plan, EIA & financial liability statement re application to renew license.
MEBLER, R. B. Kansas, Univ. of. 80/03/04. 1p. 07471:057.

--B101160404 Public version of Univ emergency preparedness plan.
* Kansas, Univ. of. 80/02/29. 46pp 07471:089.

--B101160411 Forwards statement of financial considerations supporting renewal of License R-7B. Ltr certifies that future budgets for School of Engineering will include support at level indicated under Section 2 W/o encl.
KRAFT, D. C. Kansas, Univ. of. 80/03/04. 1p. 07471:143.

I Financial information

B101160378 Releases public version of emergency plan as part of license renewal application.
FELTON, J. M. Division of Rules and Records. 80/12/02. 1p. 07471:036.

--B101160391 Forwards Tech Specs, public version of emergency preparedness plan, EIA & financial liability statement re application to renew license.
MEBLER, R. B. Kansas, Univ. of. 80/03/04. 1p. 07471:057.

--B101160411 Forwards statement of financial considerations supporting renewal of License R-7B. Ltr certifies that future budgets for School of Engineering will include support at level indicated under Section 2 W/o encl.
KRAFT, D. C. Kansas, Univ. of. 80/03/04. 1p. 07471:143.

P. Operating license stage documents & correspondence

B101160378 Releases public version of emergency plan as part of license renewal application.
FELTON, J. M. Division of Rules and Records. 80/12/02. 1p. 07471:036.

--B101160391 Forwards Tech Specs, public version of emergency preparedness plan, EIA & financial liability statement re application to renew license.
MEBLER, R. B. Kansas, Univ. of. 80/03/04. 1p. 07471:057.

--B101160398 Tech Specs 1 0-7. Q for nuclear reactor facility License R-7B.
* Kansas, Univ. of. 80/03/31. 31pp. 07471:058.

--B101160404 Public version of Univ emergency preparedness plan.
* Kansas, Univ. of. 80/02/29. 46pp 07471:089.

--B101160408 EIA supporting renewal of facility License R-7B Financial liability statement encl.
* Kansas, Univ. of. 80/03/31. 13pp 07471:134.

--B101160411 Forwards statement of financial considerations supporting renewal of License R-7B. Ltr certifies that future budgets for School of Engineering will include support at level indicated under Section 2 W/o encl.
KRAFT, D. C. Kansas, Univ. of. 80/03/04. 1p. 07471:143.

DOCKET 50-151 UNIV OF ILLINOIS RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

B101160368 Forwards IE Insp Repts 50-151/80-03 & 50-356/80-03 on B01117-19 & notice of violation.
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/12/10. 2pp. 07470:352.

--B101160374 Notice of violation from insp on B01117-19.
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/12/09. 1p. 07470:354.

--B101160382 IE Insp Repts 50-151/80-03 & 50-356/80-03 on B01117-19. Noncompliance noted: nuclear reactor committee meetings exceeded specified frequency.
RIDGWAY, K. R., BOONE, J. M. Region 3, Chicago, Office of the Director. BOYD, D. C. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/12/09. 8pp. 07470:355.

DOCKET 50-155 BIO ROCK POINT NUCLEAR PLANT

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FBAR.
EISENHUT, D. G. Division of Licensing. 80/11/13. 2pp.

B101300558 Forwards comments re required revisions to util physical security plan. Encl withheld (ref 10CFR2.790).
CRUTCHFIELD, D. Operating Reactors Branch 5. 80/12/15. 3pp 07584:352.

B101050570 Releases public version of util revised site emergency plan.
FELTON, J. M. Division of Rules and Records. 80/12/29. 1p. 07368:141.

DOCKETED ITEMS

--B101090576 Forwards public version of Revision 60 to site emergency plan in response to NRC B01113 ltr Addl revisions or justification for current position is required.
HCCFIHAN, D P Consumers Power Co. 80/12/19 1p 07388 143

--B101050580 Public version of Revision 60 to site emergency plan
Consumers Power Co 80/12/31. 225pp 07388 144.

B101100749 Requests that encl facility emergency planning info be made publicly available w/o encl.
SOUDEK, J L Division of Rules and Records 80/12/31. 1p. 07443 358

B101270995 Requests that encl facility emergency planning info be made publicly available w/o encl.
SOUDEK, J L Division of Rules and Records 81/01/13. 1p 07548 362

B101290174 Forwards facility emergency planning info to be made publicly available w/o encl.
SOUDEK, J L Division of Rules and Records 81/01/23. 1p 07575 203

O Adjudicatory correspondence

B012240475 Responds to B00318 ltr expressing concern re insufficient shielding & emergency planning at facility Shielding concern is being treated as 10CFR2 206 request & upgraded emergency plan will be implemented within several months
DENTON, H R Office of Nuclear Reactor Regulation, Director 80/12/10 2pp 07324 323

--B011100496 Responds to util B00825 & 0902 addl info re deferment of plant mods pending completed risk assessment re feasibility of continued operation ATWS recirculation pump trip & alternate shutdown panel mods cannot be deferred
DENTON, H R Office of Nuclear Reactor Regulation, Director 80/10/14 8pp 06931 202.

--B003270417 Discusses util proposed cost-benefit analysis study re equipment which NRC proposes util implement at facility discussed in encl Petoskey News-Review B00228 article
CHRISTA-MARIA Christa-Maria 80/03/18. 2pp 02919 314

B101090932 Forwards Director's decision & notice of issuance in response to B00401 petition on behalf of Concerned Citizens for Charlevoix Area requesting facility shutdown.
DENTON, H R Office of Nuclear Reactor Regulation, Director 80/12/18. 2pp 07430 203

--B101090937 Notice of issuance of Director's decision under 10CFR2 206, denying B00401 petition on behalf of Concerned Citizens for Charlevoix Area for facility shutdown
DENTON, H R Office of Nuclear Reactor Regulation, Director 80/12/18 2pp 07430 204.

--B101090940 Director's decision under 10CFR2 206, denying B00401 petition on behalf of Concerned Citizens for Charlevoix Area for facility shutdown
DENTON, H R Office of Nuclear Reactor Regulation, Director 80/12/18 6pp. 07430 207

--B101090942 Urges facility shutdown on behalf of Concerned Citizens for Charlevoix Area Unshielded steel containment insufficient to contain radiation.
CHRISTA-MARIA Christa-Maria 80/04/01 1p 07430 212

B101150379 Forwards Director's decision & notice of issuance in response to J Bier & BJ Johns 791104 & B00106 petitions to delay restart of facility. Petition treated as request for order to show cause, due to receipt after restart.
DENTON, H R Office of Nuclear Reactor Regulation, Director 80/12/18 4pp 07463 055.

--B101150390 Director's decision under 10CFR2 206, denying 791104 & B00106 petitions for order to show cause why OL should not be suspended.
DENTON, H R Office of Nuclear Reactor Regulation, Director. 80/12/18 14pp. 07463 060

--B101150397 Notice of issuance of Director's decision under 10CFR2 206, denying J Bier & BJ Johns 791104 & B00106 petitions for order to show cause why OL should not be suspended
DENTON, H R Office of Nuclear Reactor Regulation, Director. 80/12/18 2pp 07463 074

--B101030022 Corrections to B01204 brief in support of ASLB finding that NEPA requires preparation of EIS in spent fuel pool expansion proceeding
LEITHAUSER, J Affiliation Unknown 80/12/19 1p 07309 001

B101030627 Response to ASLAB B01212 order advising intervenor will appear at B10109 oral argument & response to ASLAB B00912 order stating that NEPA requires EIS preparation Table of citations to B01204 brief encl
O'NEILL, J Affiliation Unknown 80/12/22 17pp. 07309 001

B101060921 Response opposing Leithauser B01219 motion to postpone oral arguments from B10109 to B10121 Intervenor failed to show good cause Certificate of Bvc encl
GULLO, J Consumers Power Co 80/12/29 3pp. 07401 093.

B101050613 Order denying intervenor Leithauser motion to postpone oral arguments until B10121. Also denies intervenor O'Neill Motion for separate w/or addl time for oral argument O'Neill reply brief stricken & errata sheet filed
DMPKINS, B A Atomic Safety and Licensing Appeal Panel. 80/12/31. 3pp 07390 256

B101070520 Order granting extension until B10116 for Commission to decide to review Director's decision re facility.
CHILK, B J Office of the Secretary of the Commission. 81/01/02. 1p 07415 114

B101080080 Informs that JE Moore will represent NRC at B10109 oral argument
MOORE, J E Hearing Branch 2 81/01/06 1p. 03775 001.

B101130148 Motion to afford J O'Neil, H Bommel for Christa-Maria & CEG opportunity to present oral arguments. Denied by ASLAB
LEITHAUSER, J A Affiliation Unknown 81/01/06 1p. 07492 147.

--B101130154 Motion supporting J O'Neil request to grant J Leithauser opportunity to present oral arguments. Denied by ASLAB
LEITHAUSER, J A Affiliation Unknown 81/01/06 1p. 07492 140

--B101130158 Withdrawal of intervenor J Leithauser motion to postpone oral arguments on applicability of NEPA until B10121. Denied by ASLB B10106.
LEITHAUSER, J A Affiliation Unknown. 81/01/06 1p. 07492 149.

B101150003 Order granting extension until B10130 for Commission to review Director's decision on Bier & Jones petition. Certificate of Bvc encl.
CHILK, B J Office of the Secretary of the Commission. 81/01/12. 2pp 07462 132

B101160209 Reviews transcript of 791205 prehearing conference re scope of EIA
GALL, G J. Isham, Lincoln & Seale. 81/01/12 6pp. 07470 057.

B101230091 Memorandum & order determining that J Bier, P Barnett & BJ Johns Nov 1980 pleading is not petition to intervene. If any party considers pleading as such petition, responses due within 15 days of order Certificate of Bvc encl.
GROSSMAN, H Atomic Safety and Licensing Board Panel 81/01/16. 6pp 07511 335.

B101230437 Order granting extension until B10123 for Commission to decide whether to review Director's decision re Christa-Maria petition Certificate of Bvc encl
CHILK, B J Office of the Secretary of the Commission. 81/01/16. 2pp 07512 133

B101220001 Confirms that B01113 petition was not intended as petition for leave to intervene in pending spent fuel pool expansion proceeding, per B01126 telcon
MOORE, J E Hearing Branch 2 81/01/19 1p 07501 314.

B101220017 Confirms that B01113 petition was not intended as petition for leave to intervene in pending spent fuel pool expansion proceeding, per B01126 telcon.
MOORE, J E Hearing Branch 2 81/01/19 1p. 07501 341

B101220020 Confirms that B01113 petition was not intended as petition for leave to intervene in pending spent fuel pool expansion proceeding
MOORE, J E Hearing Branch 2 81/01/19 1p. 07501 342.

8101230653 Order granting extension until 810213 for Commission to decide whether to review Director's decision re Bier & Johns petition NRC may prepare suppl explaining basis for original decision Certificate of Evc encl
CHILK.B J Office of the Secretary of the Commission 81/01/19. 2pp. 07512 294

8101280226 Forwards A6L8 8101116 order per 810123 telcon. W/o encl
MOORE, J.E Hearing Branch 2. 81/01/23 1p. 07556 299.

H. General correspondence

8101070376 Demands that facility stay down until NUREG-0654 & FEMA Rept 1 requirements satisfied
CHRISTA-MARIA Christa-Maria 81/01/02 1p 07414.123

J. Insurance & indemnity information

8101220250 Forwards Endorsements B3 & B4 to ANI Policy NF-117. W/o Endorsement B4
IRELAND, J.H Consumers Power Co. 81/01/16 2pp 07496:062

P. Operating license stage documents & correspondence

8101180019 Advises that SEP Topics 11-2, B, 11-2 D, 111-B B & VI-B should be added to 791116 list of topics removed from review due to related generic NRC activities & nonapplicability. BWR DBE topic list encl
CRUTCHFIELD, D Operating Reactors Branch 5. 80/09/26 5pp.

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D.O. Division of Licensing. 80/11/26 8pp.

8101050555 Confirms proposal made by SEP owners group at 801202 meeting w/NRC increased involvement in SEP completion will be made Presentation matl used in meeting encl.
BCHAFFSTALL, R. Kerr-McGee Chemical Corp. (subs of Kerr-McGee Corp.) 80/12/05. 12pp. 07390.144

8101190113 Ltr to all BWR licensees forwarding 801201 generic safety evaluation re BWR steam discharge sys Recommends short-term actions necessary to assure safe operation of OE BWRs pending permanent design changes.
EISENHUT, D.O. Division of Licensing. 80/12/09. 2pp.

--8101190141 Generic safety evaluation re short-term actions required to assure continued safe operation of operating BWRs Continued operation of plants is acceptable pending permanent design mods Criteria for implementing design mods encl.
* Division of Licensing 80/12/01 212pp 07183:001.

8101070618 Forwards request for addl info necessary for review of SEP Topic-1V-2 re reactivity control sys design & protection against single failures. Data requested within 90 days
CRUTCHFIELD, D. Operating Reactors Branch 5. 80/12/15. 3pp. 07414:154.

8101210445 Forwards responses to questions on Rule 50.71e. "Periodic Updating of FBARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete. Non-SEP plants must comply within specified time frame.
EISENHUT, D.O. Division of Licensing. 80/12/15 13pp.

8101160029 Notification of 801218 meeting w/SEP owners group in Bethesda, MD re SEP program, schedule for licensee topic completion & assignment of lead topics to plants.
RUSSELL, W.T. Technical Support Branch 80/12/16 2pp.

8101210229 Advises that SEP review of Topic 11-2 A "Severe Weather Phenomena." has been completed. Safety evaluation encl.
Forwards TX Tech Univ rept. "Tornado & Straight Wind Hazard Probability for Big Rock Point..."
CRUTCHFIELD, D. Operating Reactors Branch 5. 80/12/17. 7pp 07492:001.

--8101210233 "Tornado & Straight Wind Hazard Probability for Big Rock Point Nuclear Power Reactor Btts, MI."
MCDONALD, J.R Texas Tech Univ. NRC-04-76-345. 80/05/31. 26pp. 07492:008.

8101230337 Forwards listing of all SEP correspondence re facility per SEP owners group 801202 meeting. List provides basis upon which to determine plant status. Review & comments requested. W/o encl.
CRUTCHFIELD, D. Operating Reactors Branch 5 80/12/22. 2pp 07512:097.

8101190644 Informs that SEP Topic 111-3 B, structural & other consequences of underdrain sys failure, has been deleted from facility SEP review due to inapplicability
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/26. 2pp. 07476 069

8101120224 Forwards preliminary "Seismic Safety Margin Evaluation." response to SEP program
HOFFMAN, D.P Consumers Power Co 81/01/09 1p 07445 264.

--8101120227 Preliminary "Seismic Safety Margin Evaluation."
* D'Appolonia Consulting Engineers, Inc 81/01/09 27pp 07445 265

8101130086 Forwards addl info re adequacy of offsite power sys per N 790925 request Problems encountered in generating, relocating & assembling info in required form caused extension in requested submittal date
HOFFMAN, D.P Consumers Power Co. 81/01/09. 5pp 07456 011

8101220234 Forwards response to NUREG-0619. "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking." NUREG not applicable due to plant design differences
HOFFMAN, D.P. Consumers Power Co. 81/01/16 3pp 07500 071.

8101230347 Notification of 810119 meeting w/util in Bethesda, MD for overview of probabilistic risk assessment program being conducted for facility.
PAULSON, W.A Operating Reactors Branch 5 81/01/16 2pp 07512 106

8101270373 Forwards emergency procedures & training program re recognition & mitigation of ATWS event Procedures provide emergency & off normal responses to ATWS & inability to insert control rods.
HOFFMAN, D.P. Consumers Power Co 81/01/22 31pp 07543 052.

8101280093 Submits info re anchorage & support of safety-related electrical equipment. Evaluations have been completed List of mods to be performed encl. Mods will be completed by 810401
HOFFMAN, D.P Consumers Power Co 81/01/22 3pp. 07550 036

8101270691 Responds to NRC evaluation of SEP Topic 11-2 A re severe weather phenomena DBT described in Reg Guide 1.7c differs greatly from actual occurrences near site Reg guide unnecessarily severe
VINCENT, R.A. Consumers Power Co. 81/01/23 2p. 07543.232

8101290350 Forwards balance of payment for Class III fee determination re util 801029 request for Tech Specs change re control rod drive sys isolation
HOFFMAN, D.P Consumers Power Co. 81/01/26 1p. 07575 128

O. Inspection reports, IE Bulletins & correspondence

8101050214 Forwards IE Info Notice 80-38. "Cracking in Charging Pump Casing Cladding." No response required.
KEPPLER, J.O Region 3, Chicago, Office of the Director 80/10/20 2pp 07389.041.

8101060118 Forwards IE Circular 80-23. "Potential Defects in Beloit Power Sys Emergency Generators." No written response required
KEPPLER, J.O. Region 3, Chicago, Office of the Director 80/10/31 1p. 07397:329

8101060644 Forwards IE Info Notice 80-39. "Malfunction of Solenoid Valves Rfg by Veltor Engineering Corp." No written response is required
KEPPLER, J.O. Region 3, Chicago, Office of the Director. 80/10/31 2pp 07401:206

8101050457 Forwards IE Bulletin 80-21. "Valve Yokes Supplied by Malco Foundry Co, Inc." Written response required
KEPPLER, J.O. Region 3, Chicago, Office of the Director 80/11/2pp. 07390 001.

8101060628 Forwards IE Info Notice 80-40. "Excessive Nitrogen Supp Pressure Actuates Safety-Relief Valve Operation to Cause Reactor Depressurization." No written response required
KEPPLER, J.O. Region 3, Chicago, Office of the Director. 80/11/01 2pp 07392.165

8101060344 Forwards IE Info Notice 80-41. "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.
KEPPLER, J.O Region 3, Chicago, Office of the Director 80/11/10 2pp. 07392.070.

DOCKETED ITEMS

B101060501 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves
Mfg by Valcor Engineering Corp. Written response required
KEPPLER, J G Region 3, Chicago, Office of the Director 80/11/14
2pp 07391 229

B101150997 Forwards IE Insp Rept 50-155/80-17 on 801103 & 07 No
noncompliance noted
KIORELLI, G Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/11/25 2pp 07463 195

--B101150599 IE Insp Rept 50-155/80-17 on 801103 & 07 No noncompliance
noted Major areas inspected work activities & IE Bulletins
79-03A & 80-08 activities.
WARD, K D Region 3, Chicago, Office of the Director
DANIELSON, D H Region 3, Chicago, Reactor Construction &
Engineering Support Branch 80/11/25 5pp 07463 197.

B101080124 Responds to IE Bulletin 80-23 re failure of Valcor solenoid
valves No such valves used in safety-related functions
Approx 8-h of manpower expended
HOFFMAN, D P Consumers Power Co 80/12/01 1p 07420 356

B101080134 Responds to IE Bulletin 80-21 re Malcolm Foundry Co. Inc
supplied valve yokes. No valve parts cast by vendor used
Approx 34 man-hours expected in review
HOFFMAN, D P Consumers Power Co. 80/12/01 1p 07420 357

B101120013 Forwards IE Insp Rept 50-155/80-16 on 801103-06 & notice of
violation
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety
Branch. 80/12/03. 2pp 07446 226

--B101120016 Notice of violation from insp on 801103-06.
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety
Branch 80/12/02 1p 07446 228

--B101120018 IE Insp Rept 50-155/80-16 on 801103-05 Noncompliance noted
Failure to post radiation areas
LOVEDALE, P C, HUETER, L J Region 3, Chicago, Office of the
Director. FISHER, W L Region 3, Chicago, Fuel Facility &
Materials Safety Branch 80/12/01. 10pp. 07446 229

B101050562 Forwards IE Info Notice 80-43, "Failures of Continuous Water
Level Monitor for Scram Discharge Vol at Dresden Unit 2 " No
response required
KEPPLER, J G Region 3, Chicago, Office of the Director 80/12/05
2pp 07390 332

B101080070 Forwards IE Info Notice 80-45, "Potential Failure of BWR
Backup Manual Scram Capability " No written response
required
KEPPLER, J G Region 3, Chicago, Office of the Director 80/12/17
2pp. 07420 337.

B101300788 Forwards IE Insp Rept 50-155/80-14 on 801020-24 & notice of
violation.
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support
Branch 80/12/17 2pp 07585 230

--B101300791 Notice of violation from insp on 801020-24
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear
Support Branch 80/12/17. 2pp. 07585 232

--B101300796 IE Insp Rept 50-155/80-14 on 801020-24 Noncompliance noted
spec/field change package 80-015 closed out w/o required
testing
SHEPLEY, B E., SPEESARD, R L Region 3, Chicago, Office of the
Director 80/12/17. 6pp. 07583 234

B101150204 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of Control
Rods to Insert During Scram at BWR." No written response
required.
KEPPLER, J G Region 3, Chicago, Office of the Director 80/12/18
2pp. 07462 193

B101050179 Forwards IE Bulletin 80-25, "Operating Problems W/Target
Rack Safety Relief Valves at BWRs." No response required
KEPPLER, J G Region 3, Chicago, Office of the Director 80/12/19
2pp 07377 307

B101210609 Clarifies 800711 & 1202 responses to IE Bulletin 80-10 on

B10120574 Responds to IE Bulletin 80-24, "Prevention of Damage Due to
Water Leakage Inside Containment (October 17, 1980 Indian
Point 2 Event)." Describes open svc water sys & experiences
w/closed cooling water sys
HOFFMAN, D P Consumers Power Co. 80/12/23. 7pp 07447 197

B101290076 Ack receipt of 801218 ltr informing NRC of steps taken to
correct violation noted in IE Insp Rept 50-155/80-12
WILCO, J A Region 3, Chicago, Safeguards Branch 81/01/06 1p
07366 358

--B101290083 Responds to NRC 801204 ltr requesting addl info for
completion of response to IE Insp Rept 50-155/80-12 Addl
info withheld (ref 10CFR2 790)
HOFFMAN, D P Consumers Power Co. 80/12/18 1p. 07366 359

B101270860 Ack receipt of 801219 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-155/80-16 &
801219 response to IE Bulletin 80-10
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety
Branch 81/01/08 1p 07590 134.

--B101270864 Responds to NRC 801203 ltr re violations noted in IE Insp
Rept 50-155/80-16 Corrective actions, bulletin issued
requesting radiation signs be visible, storage drums moved &
operations procedure revised
HOFFMAN, D P Consumers Power Co 80/12/19. 3pp 07590 135

B101290231 Forwards long-term evaluation criteria for scram discharge
vol sys per util 801027 commitment & IE Bulletin 80-17
Clarifications of applicability & results of evaluation
encl. Corrective actions to be implemented by B10501.
HOFFMAN, D P Consumers Power Co. 81/01/26 11pp. 07367 179

R Periodic operating reports & related correspondence

B101130229 Forwards monthly operating rept for Dec 1980.
HARTMAN, C J Consumers Power Co. 81/01/06 1p 07452 068

--B101130233 Monthly operating rept for Dec 1980
AMSTUTZ, S Consumers Power Co. 81/01/06. 7pp. 07452 069

S Reportable occurrences, LERs & related correspondence

B101060630 Forwards LER 80-040/03L-0
FROST, S R Consumers Power Co 80/12/30. 1p 07392 168.

--B101060635 LER 80-040/03L-0 on 801202, diesel fire pump unit did not
produce full discharge pressure output until after starting
time acceptance criteria Cause undetermined Engine jacket
heater thermostat control setting increased.
* Consumers Power Co. 80/12/30. 1p 07392 169.

B101060668 Forwards LER 80-048/01T-0.
FROST, S R Consumers Power Co. 80/12/30 1p 07400 174

--B101060674 LER 80-048/01T-0 on 801219, 150 splices & five terminal
defects were found Caused by installation of faulty
equipment in original const. Splices & blocks repaired or
replaced
* Consumers Power Co 80/12/30. 2pp. 07400 175

B101120339 Forwards LER 80-045/03L-0.
HOFFMAN, D P Consumers Power Co 81/01/06 1p. 07447 150

--B101120379 LER 80-045/03L-0 on 801210, check valve VRD 310 in common
control rod drive 2-inch suction line leaked in excess of
acceptable criteria Caused by slight imperfections in valve
disc due to fabrication flaws
* Consumers Power Co. 81/01/06 1p. 07447 159

B101130518 Forwards LER 80-046/03L-0
HOFFMAN, D P Consumers Power Co. 81/01/07. 1p. 07454 128

--B101130525 LER 80-046/03L-0 on 801211, during specific gravity checks
of 60 cell batteries for reactor depressurizing channel A
found below required specific gravity. Caused by inadequate
cleaning & reconnecting of cell terminals
* Consumers Power Co. 81/01/07. 2pp. 07454 129

DOCKETED ITEMS

--B101210422 LER 80-047/03L-0 on B01217.generator output voltage failed to build up during test start of emergency diesel generator
Caused by broken pins in plug-in socket of relay socket in regulation board. Stronger socket installed.
* Consumers Power Co B1/01/14 1p 07493 131

B101230533 Forwards LER 80-030/03L-0.
HOFFMAN, D. P Consumers Power Co B1/01/20 1p. 07512 226.

--B101230535 LER 80-030/03L-0 on B01223.monthly tests for dc batteries found overdue Caused by inadequate administrative controls & personnel error Maint dept daily working schedule form revised to include surveillance of test status board
* Consumers Power Co B1/01/20 1p. 07512 227.

B101290523 Forwards LER B1-002/01T-0.
HOFFMAN, D. P Consumers Power Co. B1/01/26 1p. 07575 249.

--B101290528 LER B1-002/01T-0 on B10112.discovered potential for overpressurization of control rod drive water supply sys suction line piping Caused by addition of check valve VRD-310. Design changes will be made.
* Consumers Power Co B1/01/26. 2pp. 07575 250.

T. Hearing transcripts on non-antitrust matters

B10130282 Transcript of B10109 hearing in Bethesda,MD re spent fuel pool mod Pp 1-97
* Atomic Safety and Licensing Appeal Panel B1/01/09. 99pp.
07456 205

V. Operator Examinations

B101270373 Forwards emergency procedures & training program re recognition & mitigation of ATWS event Procedures provide emergency & off normal responses to ATWS & inability to insert control rods
HOFFMAN, D. P Consumers Power Co. B1/01/22. 31pp 07343 052

DOCKET 80-156 UNIV. OF WISCONSIN RESEARCH REACTOR

P. Operating license stage documents & correspondence

B101260467 Submits rept of changes in facility organization RJ Cashwell is appointed reactor director,BH Matusevic will be reactor supervisor & BI Abdel-Khalik is appointed to reactor safety committee.
CASHWELL, R J Wisconsin, Univ. of, Madison. B1/01/15. 1p.
07532 032

DOCKET 80-163 GENERAL ATOMIC COMPANY

Q. Inspection reports, IE Bulletins & correspondence

B101210133 Forwards IE Insp Repts 80-089/80-02 & 80-163/80-02 on B01215-17.No noncompliance noted.
CRENS, J.L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/12/23. 2pp. 07489 355

--B101210138 IE Insp Repts 80-089/80-02 & 80-163/80-02 on B01215-17 No noncompliance noted Major areas inspected: logs & records, review & audit & operator requalification program.
FAULKNERBERRY, B. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. JOHNSON, A. D. Region 5, San Francisco, Office of the Director. 80/12/23. 4pp. 07489 357.

R. Periodic operating reports & related correspondence

B101050024 Forwards 800225 ltr providing annual operating rept for 1979.Expresses regret that original rept submitted on 800225 was not received
MOWRY, W. R General Atomic Co. (subs. of Gulf Oil Co.). 80/12/16. 1p. 07379 334.

--B101050028 Annual operating rept for 1979.
MOWRY, W. R General Atomic Co. (subs. of Gulf Oil Co.). 80/02/25. 3pp 07379 335.

DOCKET 80-170 NATIONAL NAVAL MEDICAL CENTER

F. Security, medical, emergency & fire protection plans

B101210195 Forwards physical security plan.Tech Spec Page 56 & other requested Natl Proposed schedule outlined for meeting prior to prehearing conference re litigable contentions W/o encls Security plan withheld (ref 10CFR2 790)
BACHMANN, R. O Office of the Executive Legal Director B1/01/16 2pp 07490 042

G. Adjudicatory correspondence

B101210195 Forwards physical security plan.Tech Spec Page 56 & other requested Natl Proposed schedule outlined for meeting prior to prehearing conference re litigable contentions W/o encls Security plan withheld (ref 10CFR2 790)
BACHMANN, R. O Office of the Executive Legal Director B1/01/16 2pp 07490 042

B101270282 Amend to petition for leave to intervene to establish identity & interests of individual members & authority for representation Nine affidavits & Certificate of Svc encl
ENTWISLE, E. B Citizens for Nuclear Reactor Safety, Inc
ENTWISLE, E. B Entwisle, E. B B1/01/16 12pp 07346 041

B101270443 Response to Citizens for Nuclear Reactor Safety, Inc B10116 amend to petition for leave to intervene Defects re interest & standing requirements in original filing cured by petition amend Certificate of Svc encl
BACHMANN, R. O Office of the Executive Legal Director B1/01/26 4pp. 07346 295

H. General correspondence

B101060274 Responds to B01015 ltr expressing concerns re potential health & safety risks associated w/location of Armed Forces Radiobiology Research Inst in heavily populated area EIS not needed for low power reactor
DENTON, H. R Office of Nuclear Reactor Regulation, Director 80/12/11. 2pp 07397 070

--B101060277 Expresses concern re Armed Forces Radiobiology Research plans to apply for reactor facility relicensing
BTEERS, N I Affiliation Unknown 80/10/15 4pp. 07397 073

U. Congressional/Executive Correspondence

B101100133 Forwards response to Senator Barbanes 800812 ltr re facility.providing brief description of current operating experience & upcoming renewal application
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 80/09/23 1p 07444 190

--B101100135 Requests brief paper re NRC involvement w/facility, per encl JF Ahearn memo. W/o encl
RDSE, M Commissioners 80/08/19 1p 07444 196

B101200077 Requests preparation of EIS & public hearing prior to relicensing facility.Certificate of Svc encl.
BARNES, M. D. House of Rep. B1/01/09 3pp 07486 347

DOCKET 80-184 NATIONAL BUREAU OF STANDARDS REACTOR

F. Security, medical, emergency & fire protection plans

B101280375 Notification of B10122 meeting w/NBS to review physical security plans Distribution list encl.
BERNARD, H Standardization & Special Projects Branch. B1/01/12 2pp. 07550 229

P. Operating license stage documents & correspondence

B101100253 Forwards FR notice of consideration of application for license renewal at increased power level
MILLER, J. R Standardization & Special Projects Branch. 80/12/18. 2pp. 07443 053.

--B101100259 Notice of consideration of application for license renewal

R Periodic operating reports & related correspondence

B101060627 Forwards "Semiannual Operating Rept 28-Jul-Dec 1979." CARTER, R S Commerce, Dept of, National Bureau of Standards 80/04/08 1p 07393 663

--B101060633 "Semiannual Operating Rept 28-Jul-Dec 1979." CARTER, R S Commerce, Dept of, National Bureau of Standards. 80/04/08. 8pp 07395 064

DOCKET 50-186 UNIV OF MISSOURI RESEARCH REACTOR

P. Operating license stage documents & correspondence

B101090507 Requests info re facility classification re commercial development Annual production costs for commercial purposes at research facility are restricted by federal regulations SULLIVAN, C J Treasury, Dept of. 81/01/05 1p 07427 327

DOCKET 50-187 SPACE RADIATION RESEARCH REACTOR

Q. Inspection reports, IE Bulletins & correspondence

B101070301 Act receipt of B01106 ltr informing NRC of steps taken to correct violations noted in IE insp on B00924 BUCK, M E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 80/12/04 1p 07415 212

--B101070306 Responds to NRC B01016 ltr re violations noted during IE insp on B00924 Corrective actions annual exposure repts for 1978 & 1979 submitted as required & more systematic screening of FR implemented CRAM, DALL, W E Northrop Research & Technical Center. 80/11/06 1p 07415 213

DOCKET 50-188 KANSAS STATE UNIV RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

B101270527 Forwards physical security plan Plan withheld (ref 10CFR2 7901) FARM, R E Kansas State Univ. 81/01/12 2pp 07544 035

Q. Inspection reports, IE Bulletins & correspondence

B101070585 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements For Exclusive Use Shipments of Radioactive Materials." No written response required. SNIETEK, J H Division of Fuel Facility & Materials Safety 80/08/29 1p 07415 329

DOCKET 50-193 RHODE ISLAND & PROVIDENCE PLANTATIONS AEC

P. Operating license stage documents & correspondence

B101090098 Requests route change for shipment of spent fuel from Narragansett, RI to Aiken, SC Police escort arranged for area near Harrisburg, PA DIMEGLIO, A F Rhode Island, State of 80/12/04 1p 07426 293

DOCKET 50-201 WEST VALLEY REPROCESSING PLANT

Q. Adjudicatory correspondence

B101090779 Forwards memos re preliminary estimates of resource needs should "CESMO-type" proceeding be reinstituted Info derived from discussion during B01201 meeting DAVIS, J Q Office of Nuclear Material Safety & Safeguards, Director 80/12/05 1p 07309 001

--B010160686 Advises that CESMO 1976 study & rept should be revised pending congressional mandate to reopen hearings DAVIS, J Q Office of Nuclear Material Safety & Safeguards, Director 80/08/08. 3pp. 03636 212

P. Operating license stage documents & correspondence

B101090238 Forwards West Valley facility info per B01203 request. Draft of Congressional Act authorizing facility encl DAVIS, J Q Office of Nuclear Material Safety & Safeguards, Director. 80/12/05 3pp 07429 316

DOCKET 50-206 SAN ONOFRE NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FEAR EISENHUT, D O Division of Licensing. 80/11/13 2pp.

B101060408 Forwards changes to physical security plan. Changes withheld (ref 10CFR2 7901). DIETCH, R Southern California Edison Co 80/12/12 2pp 07398 079

B101100375 Requests evaluation of potential effects of earthquakes emergency responses, including earthquakes which either initiate or follow initiation of accidents First instance should be included in revised emergency plan YEDESCO, R L Assistant Director for Licensing. 80/12/17 4pp 07309 001

B101100838 Informs that licensee must conduct emergency exercise w one yr from B10401 or prior to issuance of OL Requests schedule of drills & exercises ENGELKEN, R M Region 5, San Francisco, Office of the Director 80/12/19 1p 07443 257

H. General correspondence

B101300256 Responds to EK Johnson ltr re location of facilities Earthquake hazards are being re-reviewed in connection w/OL applications for Units 2 & 3 Facilities meet NRC siting criteria DIRCKS, W J Office of the Executive Director for Operations 81/01/15 3pp. 07586 129

P. Operating license stage documents & correspondence

B101200286 Forwards "Qualification Testing of One 75-HP Submersible Electric Motor Model 7117636003, Type CUL6B for Southern CA Edison Co" & revised info re environ qualification of RHR sgs MOODY, W C Southern California Edison Co. 80/09/19. 4pp. 07187 061

--B101200291 "Qualification Testing of One 75-HP Submersible Electric Motor Model 7117636003, Type CUL6B for Southern CA Edison Co" ANDERSON, J J, FRANZ, W, SHIPWAY, G D Wyle Laboratories. 80/06/27 147pp 07187 001.

B101220466 Ltr to all power reactor licensees & applicants forward summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lateral Tearing on Component Supports." EISENHUT, D O Division of Licensing 80/11/26 8pp

B101160415 Forwards Dfc of Nuclear Reactor Regulation Interim assessment re "Blewing of San Onofre, Unit 1 Steam Generator Tubes." Util may proceed w/production insertion phase of steam generator tube repairs CRUTCHFIELD, D O Operating Reactors Branch 5 80/11/28 3pp. 07471 025

--B101160416 Interim assessment of "Blewing of San Onofre, Unit 1 Generator Tubes." Office of Nuclear Reactor Regulation, Director 80/11/30 22pp. 07471 028

B101050160 Confirms proposal made by BEP owners group at B01202 meeting to assume significantly increased involvement in completion of safety evaluation program Presentation met used during B01202 meeting encl SCHAFFSTALL, R BEP Owners Group 80/12/05. 12pp. 07378 332.

B101070362 Summarizes thoughts re NRC-Southern CA Edison Co B01202 meeting Acceptance of DELTA result, assuming 90% shear velocity as rupture velocity, deemed premature. Extreme case of possible parameter conditions must be considered AKI, K Massachusetts Institute of Technology. 80/12/05. 2pp. 07414 330

B101120142 Informs that BEP Topic 11-2 A has been completed & for staff safety evaluation & TX Tech rept for facility. Requests info within 30 days if as-built facility differs from licensing basis info needed to complete Topic XV-16. CRUTCHFIELD, D O Operating Reactors Branch 5. 80/12/15. 6pp. 07445 318

--B101120149 "Tornado & Straight Wind Hazard Probability for San Onofre Nuclear Power Reactor Site, CA" Sheet requesting info for SEP Topic XV-16 encl
MCDONALD, J. R. Texas Tech Univ. 80/09/31. 26pp. 07445 323

B101140059 Requests info re SEP Topic IV-2, reactivity control sys design & protection against single failures info should be provided within 90 days of receipt of ltr
CRUTCHFIELD, D. Operating Reactors Branch 5 80/12/15 4pp.
07458 201.

B101210445 Forwards responses to questions on Rule 50.71e, "Periodic Updating of FSARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete. Non-SEP plants must comply within specified time frame.
EISENHUT, D. O. Division of Licensing 80/12/15 13pp.

B101160029 Notification of 801218 meeting w/SEP owners group in Bethesda, MD re SEP program, schedule for licensee topic completion & assignment of lead topics to plants
RUSSELL, H. T. Technical Support Branch. 80/12/16 2pp

B101060475 Provides addl info re instrument inverters powering Vital Bus 1, 2 & 3 & operational radiation monitoring sys for review of SEP Topics VI-7, B.VI-7, C.VI-10, VII-3, VIII-2 & VIII-3
BASKIN, K. P. Southern California Edison Co. 80/12/29. 8pp.
07398 114

B101090460 Application to amend License DPR-13, submitted as ETS Proposed Change 94, requesting temp waiver for ETS 3.1.4.1, 4.2 & 4.3 re nonradiological surveillance, chlorine, fish impingement & entrainment.
BASKIN, K. P. Southern California Edison Co. 81/01/05 2pp
07442 267.

B101130289 Confirms implementation dates for approved TMI-related items contained in NUREG-0737 w/exceptions listed. Procurement or const activities will not be initiated until NRC review & concurrence. Mods targeted for completion 830101.
BASKIN, K. P. Southern California Edison Co. 81/01/05 5pp.
07451 352.

B101130247 Notifies that license amend application to incorporate applicable Tech Specs for implementing TMI-2 lessons learned Category A items will be submitted by B10104
BASKIN, K. P. Southern California Edison Co. 81/01/07. 1p.
07449 360.

B101130544 Submits comments on NRC draft rept on 800310 loss of saltwater cooling. Forwards addl info requested in 801223 meeting & interpretation of Tech Specs re saltwater cooling sys Encls available in Central Files only
BASKIN, K. P. Southern California Edison Co. 81/01/12 3pp.
07517 042

B101210527 Advises that licensee inadvertently omitted info from B10105 ltr re plans for implementation of Action Item II.K.3.25 in NUREG-0737 re effect of loss of ac power on pump seals. Evaluation will be submitted by 820101.
DIETCH, R. Southern California Edison Co. 81/01/13 2pp.
07489 281.

B101230477 Forwards corrected copy of "Review of Repts Dealing w/ Simulation of Earthquake Ground Motions for San Onofre Nuclear Generators Station, Unit 1 for NRC."
BERNREUTER, D. L. Lawrence Livermore Laboratory 81/01/13 2pp
07510 292.

--B101230480 "Review of Repts Dealing w/Simulation of Earthquake Ground Motions for San Onofre Nuclear Generators Station, Unit 1 for NRC." Corrected copy.
BERNREUTER, D. L. Lawrence Livermore Laboratory. 81/01/13 6pp
07510 294.

B101160465 Forwards Westinghouse WCAP-9832 & WCAP-9808 re main steam line integrity evaluation Crack appearing instantaneously would be stable both globally & locally. Initial circumferential flaw would show negligible growth.
BASKIN, K. P. Southern California Edison Co. 81/01/14. 2pp.
07470 284.

--B101160473 "Mechanistic Fracture Evaluation of San Onofre Unit 1 Main Steam Line Pipe Containing Postulated Through-Wall Crack."
SWAMY, B. A., YANG, C. Y., CHIRILOS, J. N. Westinghouse Electric Corp., Nuclear Energy Systems. WCAP-9832. 80/11/30. 24pp. 07470 286.

--B101160476 "Fatigue Crack Growth Evaluation for San Onofre Unit 1 Main Steam Line Pipe."
SWAMY, B. A., KAISER, W. T., CHIRILOS, J. N. Westinghouse Electric Corp., Nuclear Energy Systems. WCAP-9808. 80/10/31. 31pp.
07470 310.

B101270751 Provides revised sentences to NRC radiological assess occupational radiation exposure expected to result from steam generator tube sleeving, submitted by NRC. 801128 ltr. Corrected Page 12, reflecting revisions, will soon be issued.
BASKIN, K. P. Southern California Edison Co. 81/01/14 2pp.
07545 275

B101300468 Responds to NRC 801215 ltr requesting response within 90 days if disagreement existed w/licensing basis assumed in SEP Topic II-2 A Assessment will be delayed until 810227
MOODY, W. C. Southern California Edison Co. 81/01/26. 1p
07382 331

B101300403 Forwards evaluation of SEP Topic VIII-3.B, "DC Power Voltage Monitoring & Annunciation," revised to reflect comments provided in 800922 ltr.
CRUTCHFIELD, D. Operating Reactors Branch 5 81/01/28 4pp.
07380 346

--B101300410 "DC Power Sys Bus Voltage Monitoring & Annunciation"
* Operating Reactors Branch 5. 81/01/12 3pp. 07580 350

O. Inspection reports, IE Bulletins & correspondence

B101050074 Forwards addl info in response to Item 2.b of IE Bull 80-11 re masonry wall design.
WAYNES, J. G. Southern California Edison Co. 80/11/10 21pp.
07309 001.

B101210604 Forwards IE Insp Rept 50-206/80-31 on 800929-1031. No noncompliance noted
CRENS, J. L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 80/11/28 2pp. 07488 048.

--B101210608 IE Insp Rept 50-206/80-31 on 800929-1031. No noncomp noted. Major areas inspected plant operations & maint. Followup on response to IE bulletins & significant events.
MILLER, L. Region 5, San Francisco, Office of the Director.
FAULKNER, B. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 80/11/26 12pp. 07488 050.

B101030489 Forwards IE Info Notice 80-43, "Failures of Continuous Level Monitor for Bream Discharge Vol at Dresden Unit 2." No response required
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 80/12/09. 1p. 07387 271

B101130638 Responds to IE Bulletin 80-21 re valve yokes supplied Malcolm Foundry Inc. Info will not be provided by 801205 due to number of valve manufacturers involved.
WAYNES, J. G. Southern California Edison Co. 80/12/10 1p
07453 283.

B101150832 Forwards IE Info Notice 80-44, "Actuation of ECCB in Recirculation Mode While in Hot Shutdown." No response required
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 80/12/16. 1p. 07308 001.

B101210232 Provides justification for util corrective actions re violation from 800310 loss of saltwater cooling incident. Proposed hot shutdown time limit is consistent w/emergency operating instruction 501-3-5.34
WAYNES, J. G. Southern California Edison Co. 80/12/26 2pp.
07491 360

B101270511 Requests extension until 810301 to respond to IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (801017 Indian Point 2 Event)."
WAYNES, J. Southern California Edison Co. 80/12/31. 1p. 075

B101060024 Responds to IE Bulletin 80-23. No Valcor Engineering Co solenoid valves used at facility.
WAYNES, J. G. Southern California Edison Co. 81/01/02. 1p.
07399 158

B101290948 Forwards IE Insp Rept 50-206/80-29 on 801103-07 & 18- notice of violation Encls withheld (ref 10CFR2 790).
NORDERHAUD, L. R. Region 5, San Francisco, Safeguards Branch. 81/01/12. 2pp. 07575 266

R. Periodic operating reports & related correspondence

B101210484 Forwards monthly operating rept for Dec 1980
CURRAN, J. M. Southern California Edison Co. 81/01/07. 1p
07490 161.

--B101210489 Monthly operating rept for Dec 1980
JOY, J. M. Southern California Edison Co. 81/01/07 3pp
07490 162

B. Reportable occurrences, LERs & related correspondence

B101160504 Forwards LER 80-039/03L-0
HAYNES, J. O. Southern California Edison Co. 80/12/23 2pp
07471 268

--B101160513 LER 80-039/03L-0 on 801012, maint insp revealed worn thrust bearings on all turbochargers on emergency diesel generator
1. Cause under investigation Bearings returned to manufacturer for repair
CLARRAN, J. M. Southern California Edison Co. 80/12/23 1p
07471 270

V. Operator Examinations

B101090376 Submits addl info re description of shift technical advisor training program & plans for requalification training per 791031 request.
HAYNES, J. O. Southern California Edison Co. 80/12/30 4pp
07383 285

B101060513 Forwards "Shift Technical Advisor Training & Requalification Program," & related info. in response to NRC 801031 ltr re TMI action plan requirement
HAYNES, J. O. Southern California Edison Co. 80/12/30 5pp
07396 040

--B101060523 "Shift Technical Advisor Training & Requalification Program"
Southern California Edison Co. 80/12/31 31pp 07396 045

DOCKET 80-208 COLUMBIA UNIV. RESEARCH REACTOR

J. Insurance & indemnity information

B101140221 Forwards Endorsement 65 to NELA Policy NF-60.
BREIGHNER, H. Columbia Univ. 80/11/19 2pp. 07461 265

DOCKET 80-213 HADDAM NECK PLANT

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FBAR
EISENHUT, D. O. Division of Licensing 80/11/13 2pp.

B101070248 Releases public version of Revision 7 to util emergency plan
FELTON, J. M. Division of Rules and Records 80/12/02 1p.
07404 340

--B101070256 Public version of Revision 7 to util emergency plan re corrected dose curves in App B, Tables 1a, 2a & 3a.
Connecticut Yankee Atomic Power Co. 80/01/25 3pp 07404 341.

B101140445 Forwards facility emergency planning info to be made publicly available w/o encl.
SOUDER, J. L. Division of Rules and Records. 80/12/16 1p
07461 336

B101210151 Requests schedule of drills, exercises & scenarios re requirements of final rule on emergency planning.
GRIER, B. H. Region I, Philadelphia, Office of the Director 80/12/24 2pp. 07491 307

B101090004 Discusses util commitments re emergency plans. Revised emergency plans addressing Revision 1 to NUREG-0654/FEMA-REP-1, App E to 10CFR50, will be submitted by B10216.
COUNSILL, W. O. Connecticut Yankee Atomic Power Co. COUNSILL, W. O. Northeast Nuclear Energy Co. (subs of Northeast Utilities) 80/12/31 4pp. 07442 247

B101270712 Responds to NRC B01124 ltr re fire protection features. Protection equivalent to NRC seismic criteria provided by backfitting of seismic qualification of reactor coolant pump lubrication oil sys
COUNSILL, W. O. Connecticut Yankee Atomic Power Co. COUNSILL, W. O. Northeast Nuclear Energy Co. (subs of Northeast Utilities) 81/01/13 4pp. 07545 269

B101270175 Forwards facility emergency planning info to be made publicly available w/o encl
SOUDER, J. L. Division of Rules and Records 81/01/23 1p
07575 204

J. Insurance & indemnity information

B101260296 Forwards Endorsements 65 & 66 to ANI Policy NF-151
IFFLAND, R. R. Northeast Utilities. 81/01/21 4pp 07525 134

B101260303 Forwards Endorsement 6 to ANI Binder EB-11
IFFLAND, R. R. Northeast Utilities 81/01/21 2pp 07525 130

P. Operating license stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants Forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D. O. Division of Licensing 80/11/26 8pp

B101050160 Confirms proposal made by SEP owners group at B01202 meeting to assume significantly increased involvement in completion of safety evaluation program Presentation metl used during B01202 meeting encl
SCHAFSTALL, R. SEP Owners Group 80/12/05 12pp 07378 332

B101090447 Informs NRC that util has no substantive comments on NRC draft evaluation of SEP Topic VI-4, "Electrical, Instrumentation & Control Aspects of Override of Containment Purge Valve Isolation" Guidelines are not applicable
COUNSILL, W. O. Connecticut Yankee Atomic Power Co. 80/12/08 1p
07387 264

B101060869 Requests invoice be sent to util for shipping route approval review
MILLER, W. O. License Fee Management Branch 80/12/08 1p
07400 131

--B101060873 Forwards costs & manpower incurred in review of util for route approval
MCCORMACK, Q. W. Physical Security Licensing Branch. PARTLOW, J. O. Material Control Licensing Branch 80/11/09 2pp. 07400 132

B101070126 Forwards evaluation of SEP Topic VIII-2 re diesel generators. Rept has been revised to reflect comments provided in B01003 ltr
CRUTCHFIELD, D. Operating Reactors Branch 5. 80/12/08 12pp.
07414 229.

B101070577 Forwards safety evaluation of SEP Topic II-2 A, "Severe Weather Phenomena" & TX Tech Univ rept, "Tornado & Straight Wind Hazard Probability for Haddam Neck Nuclear Power Reactor Site, CT."
CRUTCHFIELD, D. Operating Reactors Branch 5 80/12/08 7pp.
07404 177.

--B101070586 "Tornado & Straight Wind Hazard Probability for Haddam Nuclear Power Reactor Site, CT."
MACDONALD, J. R. Texas Tech Univ. NRC-04-76-345 80/03/31 2pp.
07404 184.

B101140080 Requests info re SEP Topic IV-2, reactivity control sys design & protection against single failures. Info should be provided within 90 days of receipt of ltr
CRUTCHFIELD, D. Operating Reactors Branch 5 80/12/15 4pp.
07458 207.

B101210445 Forwards responses to questions on Rule 50.71e, "Periodic Updating of FSARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame.
EISENHUT, D. O. Division of Licensing 80/12/15 13pp.

B101160029 Notification of B01218 meeting w/SEP owners group in Bethesda, MD re SEP program, schedule for licensee topic completion & assignment of lead topics to plants.
RUSSELL, W. T. Technical Support Branch. 80/12/16 2pp. 07467 2

B101070179 Forwards safety evaluation of SEP Topic II-2 A re severe weather phenomena for facility w/o encl.
CRUTCHFIELD, D. Operating Reactors Branch 5 80/12/18 1p.
07414 268

--B101070183 Forwards final draft of SEP technical evaluation of Topic VIII-2 re diesel generators.
CRUTCHFIELD, D. Operating Reactors Branch 5. 80/12/08 12pp.
07414 269.

07442:231

8101060410 Responds to NRC 801010 request for status rept of BEP topics re loss of offsite power. Seven losses of offsite power resulting from lightning occurred during 4 yrs preceding 760601.
COUNSIL.W.O. Connecticut Yankee Atomic Power Co. 80/12/23 1p
07399:026

8101190685 Informs that BEP Topic III-3 B structural & other consequences of underdrain sys failure is applicable to facility. Mat sump has been identified beneath containment bldg.
CRUTCHFIELD.D. Operating Reactors Branch 5. 80/12/26 2pp
07476:096

8101270142 Advises that BEP Topic III-3 B re structural consequences of underdrain sys failure is applicable to facility. Mat sump has been identified beneath containment bldg.
CRUTCHFIELD.D. Operating Reactors Branch 5 80/12/26 2pp.
07547:236.

8101090012 Forwards summary of investigation of anchorage & support of safety-related electrical equipment, per 800728 request.
COUNSIL.W.O. Northeast Nuclear Energy Co (subs. of Northeast Utilities) COUNSIL.W.O. Connecticut Yankee Atomic Power Co 80/12/30. 8pp 07442:239.

8101130138 Informs that, as result of numerous changes in interpretations of NRC guidelines, info transmitted on 800429 is superseded by encl revised lists. Info not vital to safety evaluation scheduled for 810201.
COUNSIL.W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 80/12/30 66pp. 07449:238.

8101120325 Finds evaluation of BEP Topic VIII-2 to be factually correct & has no further comment.
COUNSIL.W.O. Connecticut Yankee Atomic Power Co. 80/12/31. 1p.
07447:119.

8101160248 Forwards rept on post-TMI requirements in response to NUREG-0737 & NRC 801031 ltr
COUNSIL.W.O. Connecticut Yankee Atomic Power Co. COUNSIL.W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/12/31 300pp. 07468:014

8101120327 Requests extension to 810131 for submittal of proposed Tech Spec changes re operable/operability clarification.
COUNSIL.W.O. Connecticut Yankee Atomic Power Co. COUNSIL.W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 81/01/02. 1p. 07447:118

8101210337 Forwards final NRC evaluation of BEP Topic V-10.A. "RRR Sys Heat Exchanger Tube Failures." Current sampling required by plant procedures not adequate. No chemistry limits contained in specs as required in SRP 3.2.3
CRUTCHFIELD.D. Operating Reactors Branch 5 81/01/13 7pp.
07487:233.

Q Inspection reports, IE Bulletins & correspondence

8101180242 Forwards IE Insp Rept 50-213/80-19 on 801006-10. No noncompliance noted
MARTIN.W.O. Region 1, Philadelphia, Safeguards Branch. 80/11/25. 2pp. 07465:351.

--8101180249 IE Insp Rept 50-213/80-19 on 801006-10. No noncompliance noted. Major areas inspected security plan & organization, physical barriers in protected & vital areas & access control. Details withheld (ref 10CFR2.790).
DEVLIN.J.W. Region 1, Philadelphia, Safeguards Branch.
LADUN.R.H., SMITH.O. Region 1, Philadelphia, Office of the Director. 80/11/19 1p. 07465:353.

8101070340 Forwards Suppl 1 to IE Info Notice 80-29. "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required.
GRIER.B.H. Region 1, Philadelphia, Office of the Director. 80/11/26 1p. 07414:058.

8101150028 Responds to IE Bulletin 80-23. "Failures of Bolendid Valves Mfg by Valcor Engineering Corp." No valves w/specifed part numbers in use at facilities.
COUNSIL.W.O. Connecticut Yankee Atomic Power Co. COUNSIL.W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/12/03. 1p. 07462:205.

8101160575 Ack receipt of 801016 & 1106 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-213/80-15
BRUNNER.E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/12/12 1p 07471:323

--8101160580 Responds to NRC telcon re violations noted in IE Insp Rept 50-213/80-15. Corrective actions, emergency operating procedures being accomplished by "self-study" technique & operator requalification program revised.
COUNSIL.W.O. Connecticut Yankee Atomic Power Co. 80/11/06 2pp.
07471:324

--8101160587 Responds to NRC 800924 ltr re violations noted in IE Insp Rept 50-213/80-15. Corrective actions, emergency operating procedures review being accomplished by scheduled "self-study" technique & requalification program revised.
COUNSIL.W.O. Connecticut Yankee Atomic Power Co. 80/10/16 3pp.
07471:326

--8101160591 Forwards IE Insp Rept 50-213/80-15 on 800825-28 & notice of violation.
BRUNNER.E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/09/24 2pp. 07471:329.

--8101160595 Notice of violation from insp on 800825-28
* Region 1, Philadelphia, Office of the Director 80/09/23 1p.
07471:331

--8101160604 IE Insp Rept 50-213/80-15 on 800825-28. Noncompliance noted. No evidence available to document that all operators had reviewed all emergency procedures during 1979.
WIGGINS.J.T. Region 1, Philadelphia, Office of the Director.
CAPITON.D.L. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/09/23 7pp. 07471:332

8101060855 Forwards IE Info Notice 80-44. "Actuation of ECCS in Recirculation Mode While in Hot Shutdown." No written response required.
GRIER.B.H. Region 1, Philadelphia, Office of the Director 80/12/16 1p 07397:001

R Periodic operating reports & related correspondence

8101220408 Forwards monthly operating rept for Dec 1980
GRAVES.R.H. Connecticut Yankee Atomic Power Co. 81/01/12. 1p.
07505:178

--8101220410 Monthly operating rept for Dec 1980
* Connecticut Yankee Atomic Power Co. 81/01/12 8pp. 07505:178

S Reportable occurrences, LERs & related correspondence

8101090626 Forwards LER 80-017/03L-O.
GRAVES.R.H. Connecticut Yankee Atomic Power Co. 81/01/05 1p.
07442:173

--8101090632 LER 80-017/03L-O on 800909 reactor thermal power limit exceeded. Caused by abnormal increase in oil pressure due to sticking control valve or governor. Governor adjusted & load brought down.
TEBT.R.Z. Connecticut Yankee Atomic Power Co. 81/01/05. 2pp
07442:174.

8101210376 RO EGT-NR/50-213/81-01 on 801217, increased impingement rate of spottail shiners were observed. Caused by schooling habits & freezing of tributaries, resulting in uneven spatial distribution in CT River.
GRAVES.R.H. Connecticut Yankee Atomic Power Co. 81/01/13. 3pp
07489:061

8101290583 Forwards interim rept. "Investigation of Fuel Rod Failures in CT Yankee Reactor."
COUNSIL.W.O. Northeast Utilities. 81/01/19. 2pp 07574:194.

--8101290588 Interim rept. "Investigation of Fuel Rod Failures in CT Yankee Reactor."
PASUPATHI.V., KLINGENSMITH.R. Battelle Memorial Institute, Columbus Laboratories. BCL-585-19. 80/10/30 51pp Available NRC nrc. 07574:195

V Operator Examinations

B101120237 Advises of implementation of comprehensive program to upgrade & increase shift staffing at util
CO/MBIL.H G Connecticut Yankee Atomic Power Co 80/12/31 2pp
07445 262

DOCKET 50-219 OYSTER CREEK NUCLEAR POWER PLANT

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B10102 & by applicants as part of FSAR
EISENHUT.D G Division of Licensing 80/11/13 2pp

B101090142 Releases public version of util emergency plan & State of
NJ civil defense - disaster control plan.
FELTON.J H Division of Rules and Records 80/12/03 1p
07418:001

--B101080172 Forwards public version of emergency plan, in response to
NRC 791010 request State of NJ civil defense - disaster
control plan encl
FINFROCK.I R Jersey Central Power & Light Co 79/12/31 1p
07418:002

--B101080179 Public version of emergency plan, Amend 1
* Jersey Central Power & Light Co 79/11/01 200pp 07418 004

--B101080186 Public version of State of NJ civil defense - disaster
control plan for major nuclear facilities. Excerpt from util
emergency plan, Amend 1 encl
* New Jersey, State of 77/11/01 250pp 07418 180.

B101120216 Forwards Revision 2 to facility security officer training &
qualification plan, incorporating changes outlined in NRC
B01021 ltr. w/o encl.
FINFROCK.I R Jersey Central Power & Light Co 81/01/07 1p.
07445 255

B101160479 Releases public version of util emergency plan
FELTON.J H. Division of Rules and Records 81/01/13 1p
07183 001

--B101160484 Forwards public version of preliminary emergency plan.
Revision 6. (Facility description & safety analysis) Further
red is required prior to implementation by B10401
Transmittal ltr & Certificate of Svc encl
FINFROCK.I R Jersey Central Power & Light Co 81/01/05 3pp
07183 001.

--B101160489 Public version of preliminary emergency plan Revision 6.
(Facility description & safety analysis)
* Jersey Central Power & Light Co 81/01/05 200pp 07183 001.

B101300108 Forwards facility emergency planning info for placement in
LPDR w/o B101080172
SOUDER.J L Division of Rules and Records 81/01/16 1p
07593 081

I Financial Information

B012160144 Forwards SEC Form 10-Q Quarterly Financial Rept & supporting
mgt comments, in response to NRC 79C921.1109 & B00B11
requests for info re significant financial developments
affecting util's in restart proceeding
COHDOH.V H General Public Utilities 80/11/26 3pp

--B012160154 Quarterly Financial Rept Sept 1980 & supporting mgt
comments
* General Public Utilities. 80/11/14 44pp

J Insurance & indemnity information

B101270753 Forwards Endorsement 73 to MELIA Policy NF-164 Endorsement
71 re advance premium for 1981 will be received &
transmitted soon Due to error in numbering, no Endorsement 72
exists.
GERETY.H F General Public Utilities - GPU Service Corp 81/01/21
3pp 07545 307

P Operating license stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issue A-12. "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
EISENHUT.D G Division of Licensing 80/11/26 8pp

B101050160 Confirms proposal made by SEP owners group at B01202
meeting to assume significantly increased involvement in
completion of safety evaluation program Presentation
matl used during B01202 meeting encl.
SCHAFFSTALL.R SEP Owners Group 80/12/05 12pp 07378 332

B101070153 Forwards request for addl info re containment isolation
CRUTCHFIELD.D Operating Reactors Branch 5 80/12/08 4pp
07414 241

B101100034H Forwards request for addl info re bypass & reset of
containment isolation & other engineered safety features at
facility. Description of purge & vent valves, including
diagrams, is required
CRUTCHFIELD.D Operating Reactors Branch 5 80/12/08 4pp
07445 250

B101190113 Ltr to all BWR licensees forwarding B01201 generic safety
evaluation re BWR screen discharge sys Recommends short-term
actions necessary to assure safe operation of GE BWRs
pending permanent design changes
EISENHUT.D G Division of Licensing 80/12/09 2pp

--B101190141 Generic safety evaluation re short-term actions requir
assure continued safe operation of operating BWRs Continued
operation of plants is acceptable pending permanent design
mods Criteria for implementing design mods encl
* Division of Licensing 80/12/01 212pp 07183:001

B101070630 Notifies that technical evaluations of SEP Topics III-10
V-11 A, VI-7 C I, VIII-3 B & VIII-4 are final NRC has received
no comments re repts. Evaluations will be basic input into
integrated safety assessment for facility
CRUTCHFIELD.D Operating Reactors Branch 5 80/12/15 2pp
07415 319

B101140072 Requests info re SEP Topic IV-2, reactivity control sys
design & protection against single failures. Info should be
provided within 90 days of receipt of ltr
CRUTCHFIELD.D Operating Reactors Branch 5 80/12/15 4pp.
07458 192

B101200639 Forwards guidelines for performing soil-structure
interaction reviews for SEP facilities & simplified
analytical approach for evaluating effects of soil-structure
interaction using lumped parameter model
CRUTCHFIELD.D Operating Reactors Branch 5 80/12/15 2pp
07477 143

B101210445 Forwards responses to questions on Rule 50.71e. "Periodic
Updating of FSARs" & FR notice of final rule SEP plants need
not comply w/rule until program is complete Non-SEP plants
must comply within specified time frame
EISENHUT.D G Division of Licensing 80/12/15 13pp

B101160029 Notification of B01218 meeting w/SEP owners group in
Bethesda, MD re SEP program, schedule for licensee topic
completion & assignment of lead topics to plants
RUSSELL.W T Technical Support Branch 80/12/16 2pp

B101210218 Advises that SEP review of Topic II-2 A. "Severe Weather
Phenomena," has been completed Safety evaluation encl.
Forwards TX Tech Univ rept. "Tornado & Straight Wind Hazard
Probability for Oyster Creek"
CRUTCHFIELD.D Operating Reactors Branch 5 80/12/17 7pp.
07491 315

--B101210223 "Tornado & Straight Wind Hazard Probability for Oyster
Creek Nuclear Power Reactor Site, NJ"
MCDOHALL.D J R. Texas Tech Univ. NRC-04-76-345 80/05/31 26pp
07491 322

B101190704 Forwards request for addl info re SEP Topic VII-1 A.
isolation of reactor protection sys from nonsafety sys
CRUTCHFIELD.D Operating Reactors Branch 5 80/12/26 3pp.
07476 097

B101190710 Advises that NRC assessment of SEP Topic VIII-2, onsite
emergency power sys, is now final & will be basic input to
facility integrated safety assessment
CRUTCHFIELD.D Operating Reactors Branch 5 80/12/26 2pp.
07476:103

B101190719 Informs that SEP Topic III-3 B. structural & other consequences of underdrain sys failure, has been deleted from facility SEP review due to inapplicability
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/26 2pp
07476 106

B101210169 Forwards request for addl info for evaluation of SEP Topic VIII-1 A re isolation of reactor protection sys from non-safety sys Description of isolation buffer circuits used for isolation of signals to on-line computer required
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/26 3pp
07491 312

B101130047 ECOLOGICAL STUDIES OF WOOD-BORING BIVALVE IN THE VICINITY OF THE OYSTER CREEK NUCLEAR GENERATING STATION Progress Report, March-May 1980.
HAGLAND, K E, CROCKET, L Lehigh Univ FIN A-0415 NUREG/CR-1799
80/12/31 41pp Available at NTIS 07454 324

B101060035 Forwards request for addl info within 30 days re NRC evaluation of bypassing & resetting of engineered safety features including containment isolation sys w/o encl
CRUTCHFIELD, D Operating Reactors Branch 5 81/01/02 1p
07399 149

B101090034 Forwards info re implementation dates of NUREG-0737, proposed revised dates & justification for delays Will meet all criteria established in NUREG-0737 that require mod
FINFROCK, I R Jersey Central Power & Light Co 81/01/06 11pp
07430 005

B101160466 Forwards request for amend to App B of License DPR-16 consisting of Tech Spec Change Request 84 Tech Specs encl
FINFROCK, I R Jersey Central Power & Light Co 81/01/08 2pp
07469 001

--B101160471 Application for amend of License DPR-16 authorizing changes to Tech Specs 2 1 1.2 1 2.2 1 4.3 3.4 5.5 2.5 4 & 5 6 & suspension of ETR Monitoring Sections 3 1 2A2 & 3 1 2 C for two yrs.
FINFROCK, I R Jersey Central Power & Light Co 81/01/08 43pp
07469 003

--B101160469 Tech Specs 2 1-5-3 1 1-3 1 2A-D 1-5-5 1-6 1.5 1 6 2-3 & 5 7 re sampling locations
* Jersey Central Power & Light Co. 80/04/15 29pp 07469 054

B101210347 Forwards revised safety evaluation of SEP Topic VIII-3 A re battery capacity tests Evaluation will be used as basic input to integrated safety assessment for facility unless changes reflecting as-built facility are required
CRUTCHFIELD, D Operating Reactors Branch 5 81/01/16 5pp
07487 211

B101210349 Forwards request for addl info re SEP III-4 C, "Internally Generated Missiles (Inside Containment)" Response requested within 30 days of receipt of ltr.
CRUTCHFIELD, D Operating Reactors Branch 5 81/01/19 3pp
07487 208

Q Inspection reports, IE Bulletins & correspondence

B101300034 Forwards IE Insp Rept 80-219/80-26 on 800714-0801 No noncompliance noted
SMITH, O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/11/12 2pp 07582 286

--B101300040 IE Insp Rept 80-219/80-26 on 800714-0801. No noncompliance noted Major areas inspected radiation protection program, including work procedures, practices, plant decontamination & housekeeping
KNAPP, P J Region 1, Philadelphia, Fuel Facility & Materials Safety Branch PLUMLEE, K E Region 1, Philadelphia, Office of the Director 80/11/10 7pp 07582 280

B101050263 Forwards response to IE Bulletin 80-11, "Masonry Wall Design," prepared by GPU Nuclear Corp
FINFROCK, I R Jersey Central Power & Light Co 80/11/14 120pp
07384 265

B101060883 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/11/26 1p 07396 351

B101190140 Forwards Performance Appraisal Branch Mgt Insp Rept 80-219/79-18, 80-312/80-15 & 80-289/80-21 IE Performance Appraisal Branch mgt evaluation tree w/users guide for chart list of licensee recipients of regl & sample ltr encl
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/02 2pp 07466 028

--B101150195 Forwards Performance Appraisal Branch Mgt Insp Rept 80-219/79-18 on 791031-05, 15-19, 29-31, 1101, 02 & 06-08
GRIER, B H Region 1, Philadelphia, Office of the Director 80/01/04 2pp 07466 030

--B101150169 Performance Appraisal Branch Mgt Insp Rept 80-219/79-18 Noncompliance noted failure to provide independent verification for removal of components App A withheld (ref 10CFR2 790)
FASANO, A N, GDDY, A T Region 1, Philadelphia, Office of the Director HUNCKLEY, N Q Region 2, Atlanta, Office of the Director 79/12/19 117pp 07466 031

---B101150195 Performance Appraisal Branch Mgt Insp Rept 80-289/800707-11, 14-18, 27-31 & 0801 Noncompliance noted licensee mgt controls were poor re nonlicensed training Attachment withheld (ref 10CFR2 790).
GDDY, A T Region 1, Philadelphia, Office of the Director HUNTER, D R Region 3, Chicago, Office of the Director 80/10/08 115p 07308 001

B101050138 Forwards IE Info Notice 80-43, "Failures of Continuous Level Monitor for Scram Discharge Val at Dresden Unit 2 " No response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/05 1p 07376 359

B101140938 Responds to IE Bulletin 80-21, "Valve Yokes Supplier Malcolm Foundry Co. Inc " Suppliers being contacted to confirm that subj parts are not in use at facility. Completion of confirmation efforts expected by 810316
FINFROCK, I R Jersey Central Power & Light Co 80/12/09 07450 359

B101140689 Responds to IE Bulletin 80-23, "Failures of Solenoid Mfg by Valcor Engineering Corp " No subj valves in use in safety-related function at facility
FINFROCK, I R Jersey Central Power & Light Co 80/12/12 07462 024

B101060134 Forwards IE Info Notice 80-45, "Potential Failure of Backup Manual Scram Capability " No response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/17 1p 07397 348

B101070042 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of Control Rods to Fully Insert During Scram at BWR " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/18 1p 07413 356

B101130101 Forwards IE Bulletin 80-25, "Operating Problems w/ Rock Safety-Relief Valves at BWRs " Written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/19 1p 07449 169

R Periodic operating reports & related correspondence

B101230546 Forwards monthly operating rept for Dec 1980
FINFROCK, I R Jersey Central Power & Light Co 81/01/14 07512 230

--B101230548 Monthly operating rept for Dec 1980
SKLAR, J B Jersey Central Power & Light Co 81/01/14 07512 231

B101280083 Forwards twenty-second quarterly progress rept on "Study Associated w/Oyster Creek Generating Station," for 800911-1110
FINFROCK, I R Jersey Central Power & Light Co 81/01/20 07598 012

--B101280087 Twenty-second quarterly progress rept on "Woodbury Associated w/Oyster Creek Generating Station," for 800911-1110
MACIOCEK-BLAKE, BELMORE, C L, HILLMAN, R E Battelle Memorial Institute, Columbus Laboratories 80/12/10 23pp

R Reportable occurrences, LERs & related correspondence

B101050379 RO B01121 fire diesel 1-2 removed from svc to determine cause of failure to start automatically on decrease in sys pressure Caused by failure of corrosion resistor element in cooling water line resulting in diesel overheating
FINFROCK, I R Jersey Central Power & Light Co 80/12/17 2pp
07379 344

B101050197 Forwards LER B0-055/03L-0
FINFROCK, I R Jersey Central Power & Light Co 80/12/22 3pp
07383 203

--B101050204 LER B0-055/03L-0 on B01203, core spray sys high drywell pressure switches RV-46B, RV-46C & RV-46D tripped above Tech Spec levels Caused by instrument repeatability switches adjusted & replacement recommended
FITZGERALD, M J Jersey Central Power & Light Co 80/12/22 1p
07383 208

B101050211 Forwards LER B0-057/03L-0
FINFROCK, I R Jersey Central Power & Light Co 80/12/23 3pp
07383 215

--B101050219 LER B0-057/03L-0 on B01205, containment spray high drywell pressure switches P15A, B, C & D tripped above Tech Spec levels during surveillance testing Caused by instrument repeatability switches adjusted
CROSBY, P J Jersey Central Power & Light Co 80/12/23 1p
07383 218

B101050223 Forwards LER B0-056/03L-0
FINFROCK, I R Jersey Central Power & Light Co 80/12/23 3pp
07383 211

--B101050229 LER B0-056/03L-0 on B01204, main steam line high flow sensors RE-22C & RE-22Q tripped above Tech Spec levels. Caused by instrument repeatability Sensor RE-22C reset. Microswitch in sensor RE-22Q replaced
FITZGERALD, M J Jersey Central Power & Light Co 80/12/23 1p
07383 214

B101050252 Forwards LER B0-053/03L-0
FINFROCK, I R Jersey Central Power & Light Co 80/12/23 3pp
07384 246

--B101050259 LER B0-053/03L-0 on B01130, limiting operating condition occurred when control rod drive line pumps NC08A & NC08B removed from svc to repair leaks Caused by personnel action
Pipe replaced & pumps returned to svc.
CROSBY, P J Jersey Central Power & Light Co 80/12/23 1p
07384 249

B101050469 Forwards LER B0-054/03L-0
FINFROCK, I R Jersey Central Power & Light Co 80/12/23 1p
07390 199

--B101050541 LER B0-054/03L-0 on B01130, core spray sys 1 removed from svc to inspect pumps sprayed w/water due to leaking pipes. Caused by water leaking into motor lead connection box due to worn cover gaskets & open ended conduit
CROSBY, P J Jersey Central Power & Light Co 80/12/23 3pp
07390 200

B101150492 Forwards LER B0-058/03L-0
FINFROCK, I R Jersey Central Power & Light Co 81/01/09 1p
07462 314

--B101150497 LER B0-058/03L-0 on B01211, snubbers 19/6 & 19/7 on containment spray & core spray sys failed lockup test. Caused by piston seal failures Snubbers replaced
FITZGERALD, M J Jersey Central Power & Light Co 81/01/09 3pp
07462 315

B101150690 Forwards LER B0-060/03L-0
FINFROCK, I R Jersey Central Power & Light Co 81/01/09 1p
07465 296

--B101150695 LER B0-060/03L-0 on B01211, during routine testing, pipe break sensors for isolation condensate return lines tripped higher than Tech Spec Caused by instrument drift. Switches reset
CROSBY, P J Jersey Central Power & Light Co 81/01/09 3pp
07465 297

B101230551 Forwards LER B0-059/03L-0
FINFROCK, I R Jersey Central Power & Light Co 81/01/15 1p
07512 240

--B101230556 LER B0-059/03L-0 on B01219, discovered that main station diesel generator monthly battery surveillance tests not performed as scheduled on B00801 & 1121 Caused by personnel error Administrative controls implemented
CROSBY, P J Jersey Central Power & Light Co 81/01/15 3pp
07512 241

B101230560 Forwards LER B0-062/03L-0
FINFROCK, I R Jersey Central Power & Light Co 81/01/16 1p
07512 244

--B101230564 LER B0-062/03L-0 on B01218, control rod drive line pump NC08 failed in svc Caused by failure of pump shaft outboard of balancing disc Pump internals & motor replaced
CROSBY, P J Jersey Central Power & Light Co 81/01/16 3pp
07512 245

B101230569 Forwards LER B0-063/03L-0
FINFROCK, I R Jersey Central Power & Light Co 81/01/16 1p
07512 248

--B101230574 LER B0-063/03L-0 on B01217, reactor triple low water level indicator switch RE-18A tripped high. Caused by instrument drift Switch reset
FITZGERALD, M J Jersey Central Power & Light Co 81/01/16 3pp
07512 249

B101260581 Forwards LER B0-061/03L-0
FINFROCK, I R Jersey Central Power & Light Co 81/01/16 1p
07531 115

--B101260664 LER B0-061/03L-0 on B01217, snubbers - 19/11, 19/12 & 19/13 on containment spray & core spray sys common suction header failed to lock up in compression mode Caused by main piston seal failures Snubbers replaced.
FITZGERALD, M J Jersey Central Power & Light Co 81/01/16 3pp
07531 116

B101290546 LER B1-004/01P-0 on B10116, indications show that load on emergency diesel generators, during actual LOCA, plus loss of offsite power, plus single bus failure, could exceed full load rating Caused by anticipated load expansion.
CARROLL, J T Jersey Central Power & Light Co 81/01/16 2pp
07566 355

V Operator Examinations

B101130327 Informs of changes in shift technical advisor program Weaknesses in training program made evident by qualification exam results will be supplemented by requalification program beginning Jan 1981
FINFROCK, I R Jersey Central Power & Light Co 81/01/07 1p
07495 362

DOCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

B101100046 Notifies of interim rule suspending completion dates for fire protection plans previously approved by NRC FR notice encl
EISENHUT, D O Division of Licensing 80/11/26 3pp 07445 249

B101070441 Requests extensions for completion of fire protection plans required by 790725 safety evaluation Affected plans include protection sys, shutdown panel, sprinkler sys & ventilation penetrations
DISE, D P Niagara Mohawk Power Corp. 80/12/31 2pp 07404 322

O Adjudicatory correspondence

B101300358 Forwards NRC B10112 order modifying license & granting extension of exemption from General Design Criterion 50 Reassessment of containment design for suppression pool hydrodynamic loading conditions is required.
IPPOLITO, T A Operating Reactors Branch 2 81/01/13 3pp
07586 270

--B101300373 Order modifying license & granting extension of exemption from General Design Criterion 50 Reassessment of containment design for suppression pool hydrodynamic loading conditions is required. Mods must be installed by B30131.
EISENHUT, D O Division of Licensing 81/01/13 7pp 07586 273

I Financial information

8101060639 Forwards 800808 ltr & encls re guarantee of retrospective premium in response to 801219 ltr
RUSHMORE, J W Niagara Mohawk Power Corp 80/12/29 1p 07395 054

--8101060647 Forwards financial info re guarantee of retrospective premium, per 10CFR140.
RUSHMORE, J W Niagara Mohawk Power Corp 80/08/08 6pp
07395 055

J Insurance & indemnity information

8101060639 Forwards 800808 ltr & encls re guarantee of retrospective premium in response to 801219 ltr.
RUSHMORE, J W Niagara Mohawk Power Corp 80/12/29 1p 07395 054

--8101060647 Forwards financial info re guarantee of retrospective premium, per 10CFR140.
RUSHMORE, J W Niagara Mohawk Power Corp 80/08/08 6pp
07395 055

P Operating license stage documents & correspondence

8101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for scrubbers under STS License amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT, D O Division of Licensing 80/11/20 1p

--8101100271 Revised Pages 3/4 7-22 through 28, B 3/4 7-5 & 7-6 & 6-17 to STS scrubber inservice insp requirements
* Division of Licensing. 80/11/20. 10pp

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

8101190113 Ltr to all BWR licensees forwarding 801201 generic safety evaluation re BWR scram discharge sys Recommends short-term actions necessary to assure safe operation of GE BWRs pending permanent design changes.
EISENHUT, D O Division of Licensing. 80/12/09 2pp.

--8101190141 Generic safety evaluation re short-term actions required to assure continued safe operation of operating BWRs Continued operation of plants is acceptable pending permanent design mode Criteria for implementing design mode encl
* Division of Licensing. 80/12/01 212pp 07103 001

8101120278 Forwards Amend 39 to License DPR-63, safety evaluation & notice of issuance & availability.
IPPOLITO, T A Operating Reactors Branch 2 80/12/12 2pp.
07446.333

--8101120279 Amend 39 to License DPR-63, revising Tech Specs to allow plant operation at reduced power w/three primary coolant loops operable
IPPOLITO, T A Operating Reactors Branch 2. 80/12/12 13pp.
07446.335

--8101120281 Safety evaluation supporting Amend 39 to License DPR-63
* Office of Nuclear Reactor Regulation, Director 80/12/12. 3pp
07446 348

--8101120283 Notice of issuance & availability of Amend 39 to License DPR-63.
IPPOLITO, T A Operating Reactors Branch 2 80/12/12. 2pp
07446.351.

8101210445 Forwards responses to questions on Rule 50.71a, "Periodic Updating of FBARs" & FR notice of final rule EEP plants need not comply w/rule until program is complete. Non-BEP plants must comply within specified time frame.
EISENHUT, D O Division of Licensing. 80/12/15. 13pp

8101140166 Advises of possible deficiencies in Ofc of Nuclear Reactor Regulation followup of licensee. Responds to inquiry re implementation of short-term Lessons Learned requirements. Listed actions will assure that no deficiencies exist
DIRCKB, W J. Office of the Executive Director for Operations 80/12/17. 4pp. 07462.096.

--8101140173 Forwards results of inquiry into Ofc of Nuclear Reactor Regulation implementation of short-term Lessons Learned Category A requirements Results of IE investigation of facility will be reviewed w/o encl
CUMMINGS, J J Office of Inspector & Auditor 80/11/12 1p
07462 099

8101140162 Forwards 801217 memo reflecting agreement outlining Nuclear Reactor Regulation & IE responsibilities for verification of implementation of NRC action plan items
DIRCKB, W J Office of the Executive Director for Operations 80/12/23 1p 07460 355

--8101140327 Requests 800129 document outlining agreement between Nuclear Reactor Regulation & IE re responsibilities for verification of implementation of NRC action plan items
AHEARNE, J F Commissioners 80/12/10 1p 07460 359

8101030087 Responds to NRC 801113 ltr & confirms that until will meet implementation dates in NUREG-0619, "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking"
DISE, D P Niagara Mohawk Power Corp. 80/12/29 2pp 07376 299

8101060400 Forwards documentation of TMI action items requiring 81010 submittal, per NRC 801031 request Sixteen oversize drawings encl
DISE, D P Niagara Mohawk Power Corp. 80/12/31 81pp 07392 093

8101070301 Informs that mod of lab ventilation sys, including preoperational testing, will be completed prior to startup from Spring 1981 refueling outage Procedures for sample analysis per TMI action plan to be issued by 810131.
DISE, D P Niagara Mohawk Power Corp 80/12/31 1p 07414 138.

8101120241 Forwards revised "Section XI Pump & Valve Inservice Testing Program Plan Book," incorporating comments agreed to at 801006-07 meeting w/NRC
DISE, D P Niagara Mohawk Power Corp 81/01/06 1p 07438 227

--8101120245 "Section XI Pump & Valve Inservice Testing Program Plan Book"
BCHMIDT, K Nuclear Energy Service, Inc. 80/12/31. 90pp.
07438 220

8101210357 Forwards EIA for chemical treatment of main condenser cooling water Effect on environ during feed of Nalco 7348 & 7388 to main condenser cooling water negligible Hazleton rept to Nalco Chemical Corp encl
DISE, D P Niagara Mohawk Power Corp 81/01/12 16pp. 07487.189.

8101300358 Forwards NRC 810113 order modifying license & granting extension of exemption from General Design Criterion 50 Reassessment of containment design for suppression pool hydrodynamic loading conditions is required.
IPPOLITO, T A Operating Reactors Branch 2. 81/01/13 3pp.
07586.270

--8101300373 Order modifying license & granting extension of exemption from General Design Criterion 50 Reassessment of containment design for suppression pool hydrodynamic loading conditions is required Mods must be installed by 830131.
EISENHUT, D O Division of Licensing 81/01/13 7pp 07586.273

8101210595 Notifies that further review of facility scram discharge sys for conformance w/BWR owner subgroup criteria necessary. Results of further review will be forwarded by 810202
LEMPGEB, T E Niagara Mohawk Power Corp. 81/01/19. 1p 07489.270

O. Inspection reports, IE Bulletins & correspondence

8101300014 Forwards IE Insp Rept 50-220/80-14 on 801014-17. No noncompliance noted.
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/11/13 2pp. 07582.188.

--8101300019 IE Insp Rept 50-220/80-14 on 801014-17 No noncompliance noted Major areas inspected, administrative controls for surveillance procedures, surveillance testing & technician qualification
GREENMAN, E O, CHUNG, J W Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/11/10. 9pp. 07582.190

8101070427 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director. 80/11/26 1p 07414 032

8101140696 Responds to IE Bulletin 80-23. "Failure of Solenoid Valves
Mfg by Valtor Engineering Corp." No subj valves in use
at facility
LEMPGES, T E Niagara Mohawk Power Corp 80/12/03 1p 07308 001.

8101050144 Forwards IE Info Notice 80-43. "Failures of Continuous Water
Level Monitor For Steam Discharge Vol at Dresden Unit 2 " No
response required
GRIER, B H Region I, Philadelphia, Office of the Director
80/12/05 1p 07377 237

8101300059 Responds to IE Bulletin 80-21. "Valve Notes Supplied by
Malcolm Foundry Co. Inc." Preliminary results of util survey
of manufacturers indicates that no subj parts were used at
facilities
LEMPGES, T E Niagara Mohawk Power Corp 80/12/08 1p 07579-328.

8101220433 Ack receipt of 801104 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-220/80-08
BRUNNER, E J Region I, Philadelphia, Reactor Operations Nuclear
Support Branch 80/12/11 1p 07500 194

--8101220438 Responds to NRC 801015 ltr re violations noted in IE Insp
Rept 50-220/80-08 Corrective actions procedure deleted
requiring valves to be locked Outer door seals properly
installed
LEMPGES, T E Niagara Mohawk Power Corp 80/11/04 3pp
07500 193

--8101220442 Forwards IE Insp Rept 50-220/80-08 on 800816-0915 & notice
of violation
BRUNNER, E J Region I, Philadelphia, Reactor Operations Nuclear
Support Branch 80/10/15 2pp 07500 198

--8101220445 Notice of violation from insp on 800816-0915
" Region I, Philadelphia, Office of the Director 80/10/09 2pp.
07500 200

--8101220450 IE Insp Rept 50-220/80-08 on 800816-0915 Noncompliance
noted failure to maintain reactor bldg track bay door sealed
& to maintain valves locked.
BAUMACH, W. HUDSON, S. Region I, Philadelphia, Office of the
Director KIBTER, H B. Region I, Philadelphia, Reactor Operations
Nuclear Support Branch 80/10/09 11pp 07500 202

8101210215 Immediate Action Ltr 80-53, confirming 801211 telcon re
actions to be taken in response to IE Bulletin 80-17.
"Failure of 7b of 185 Control Rods to Fully Insert During
Scram at BHR" & NRC 801002 confirmatory order.
GRIER, B H Region I, Philadelphia, Office of the Director
80/12/12 2pp 07489 332.

8101060148 Forwards IE Info Notice 80-45. "Potential Failure of BWR
Decup Manual Scram Capability " No response required
GRIER, B H Region I, Philadelphia, Office of the Director
80/12/17 1p 07391 268

8101070064 Forwards Suppl A to IE Bulletin 80-17. "Failure of 7b of 185
Control Rods to Fully Insert During Scram at BHR " No
written response required
GRIER, B H Region I, Philadelphia, Office of the Director
80/12/18 1p 07414 148

8101100419 Forwards response to notice of violation & proposed
imposition of civil penalty. Separate answer will be filed on
810105 re order for mod of license & order to show cause.
DONLON, W J. Niagara Mohawk Power Corp 80/12/19 1p 07443 095

--8101100428 Opposition to NRC 801126 notice of violation & proposed
imposition of civil penalty NRC has committed substantial
errors No risk to public health & safety was caused by util
action
DONLON, W J Niagara Mohawk Power Corp. 80/12/19 78pp
07443 096

8101130103 Forwards IE Bulletin 80-25. "Operating Problems w/Target
Rock Safety-Relief Valves at BHRs." Written response
required
GRIER, B H Region I, Philadelphia, Office of the Director.
80/12/19 1p 07449 215

8101070448 Forwards util answer & protest to NRC order for mod of
license & order to show cause.
DONLON, W J Niagara Mohawk Power Corp. 81/01/03 1p 07413 206

--8101070490 Answer & protest on behalf of util to NRC 801126 order for
mod of license & order to show cause. Noncompliance
allegations w/o foundation NRC should determine that App B
satisfies 801126 order requirements Affidavit encl
DONLON, W J Niagara Mohawk Power Corp. 81/01/03 38pp.
07413 207

--8101070451 Forwards util response to notice of violation & notice of
imposition of civil penalties
DONLON, W J Niagara Mohawk Power Corp 80/12/19 1p 07413 245

--8101070455 Response to 801126 notice of violation & notice of
imposition of civil penalties Util denies noncompliance.
Requests that NRC withdraw 801126 notice of violation,
dismiss proceeding, & eliminate civil penalties App B encl
DONLON, W J Niagara Mohawk Power Corp 80/12/19 47pp.
07413 246.

8101210159 Requests addl info to evaluate util 801219 response to
801126 notice of violation & notice of proposed imposition
of civil penalties & 801229 motion to dismiss proceeding
STELLO, V Director's Office, Office of Inspection and Enforcement
81/01/09 3pp 07491 309

R. Periodic operating reports & related correspondence

8101150501 Forwards monthly operating rept for Dec 1980.
LEMPGES, T E. Niagara Mohawk Power Corp. 81/01/08 2pp 07462:310

--8101150502 Monthly operating rept for Dec 1980
ROMAN, T H Niagara Mohawk Power Corp. 81/01/08 3pp 07462:320

8101230980 Forwards list of mods installed or completed during 1980,
omitted from rept of operating statistics & shutdown
experience for Dec 1980
LEMPGES, T E Niagara Mohawk Power Corp. 81/01/16 2pp 07183:00

5 Reportable occurrences, LERs & related correspondence

8101060540 Forwards LER 80-027/03L-0
DISE, D. P. Niagara Mohawk Power Corp. 80/12/26 1p 07396-0311

--8101060546 LER 80-027/03L-0 on 801126 operability tests were not
immediately performed as required Caused by misunderstanding of
intent of procedure Testing performed
HARRISON, P. Niagara Mohawk Power Corp. 80/12/26 1p 07396 0311

8101070300 Forwards LER 80-029/04T-0
DISE, D. P. Niagara Mohawk Power Corp 80/12/29 1p 07415 0711

--8101070504 LER 80-028/04T-0 on 801215 results of 801103, 26 & 1201
sample tests showed detectable 1-131 at three locations.
Caused by Chinese nuclear weapons test during Oct. Plant not
accountable for detected levels.
HARRISON, P. Niagara Mohawk Power Corp 80/12/29 3pp.
07415 079

8101120335 Forwards LER 80-031/01T-0
LEMPGES, T E. Niagara Mohawk Power Corp. 80/12/30 1p 07447 15

--8101120369 LER 80-031/01T-0 on 801216 feedwater flow control valve
pneumatic positioner unit 11 vented excessive amount of air.
Caused by cracked & worn rubber goods. Rubber goods replaced
& retested
HARRISON, P. Niagara Mohawk Power Corp 80/12/30 1p 07447 15

8101150679 Forwards LER 80-030/04T-0
LEMPGES, T E. Niagara Mohawk Power Corp 81/01/05 1p 07469 291

--8101150684 LER 80-030/04T-0 on 801204 discovered that lower limit of
detection for radiological fish analysis was not within ETS.
Caused by conversion factor Tech Spec changes proposed to
update parameter
HARRISON, P. Niagara Mohawk Power Corp 81/01/03 4pp
07469:292.

DOCKET 50-224 UNIV OF CALIFORNIA RESEARCH REACTOR

P. Operating license stage documents & correspondence

8101300711 Forwards Amend 4 to License R-101, revising physical security
plan
MILLER, J R. Standardization & Special Projects Branch 81/01/19.
3pp. 07584 154

--8101300715 Amend 4 to License R-101, revising physical security plan
MILLER, J R. Standardization & Special Projects Branch. 81/01/19
2pp. 07584 157.

G Inspection reports, IE Bulletins & correspondence

B101290561 Forwards IE Insp Rept 50-224/80-03 on B01202-05 No noncompliance noted.
BDOCK.H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 80/12/19 2pp 07573 286

--B101290565 IE Insp Rept 50-224/80-03 on B01202-05 No noncompliance noted Major areas inspected environ monitoring including effluent monitoring & TLD area studies, radiation protection program, radiation surveys & posting & labeling
CILLIB.M., WENSLAUSKI.F Region 5, San Francisco, Office of the Director BDOCK.H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 80/12/19 12pp. 07573 288

DOCKET 50-225 RPI CRITICAL EXPERIMENT

G Reportable occurrences, IERs & related correspondence

B101280384 PNO-1-B1-07 on B10120, extreme cold resulted in line break & partial drainage of RW3T to reactor room sump. Sample analysis indicated no activity Reactor has been shut down since Aug 1980
REITENHAUSEN.L., CAPHTON.D., SMITH.Q. Region 1, Philadelphia, Office of the Director B1/01/21 1p 07537 060

DOCKET 50-228 AEROTEST RADIOGRAPHY & RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

B101100234 Ack receipt of 790119 ltr submitting revisions to security plan, Class III fee requested
DIOGS.R M License Fee Management Branch 80/12/22 1p 07445:217.

B101060429 Requests temporary hold on review of security plan to allow applicant to incorporate changes bringing plan up-to-date Changes in emergency alarm sys & bldg configuration will be submitted within two months.
NEWACHECK.R.L. Aerotest Operations. 80/12/30 1p. 07396 203

P Operating license stage documents & correspondence

B101220323 Informs that in-pool temporary storage procedure allowing complete defueling is scheduled for B10131-0201 Defective fuel element will be removed at that time Requests confirmation of NRC approval of Tech Spec procedure.
NEWACHECK.R.L. Aerotest Operations B1/01/19 4pp. 07500 152

DOCKET 50-237 DRESDEN NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR.
EISENHUT.D.O. Division of Licensing 80/11/13. 2pp.

B101120273 Forwards suppl to fire protection safety evaluation.
JPPDLITO.T A. Operating Reactors Branch 2 80/12/02. 2pp 07446:325

--B101120276 Suppl to fire protection safety evaluation. Capability to achieve & maintain safe solution to any fire situation not yet adequately demonstrated.
* Office of Nuclear Reactor Regulation, Director. 80/12/02. 6pp 07446:327.

O Adjudicatory correspondence

B101070669 Forwards Deviation Disposition Requests 0001696-00001735 Documents prepared per informal discovery agreement, since record of spent fuel pool mods remains open W/O encl.
Related correspondence
FITZ01880NS.R. Isham, Lincoln & Beale B1/01/03 1p. 07442:050

B101300233 Forwards NRC B10113 orders for mod of licensees & granting extension of exemption Licensee must reassess suppression pool hydrodynamic loads & complete mods to meet General Design Criterion 50.
JPPDLITO.T A. Operating Reactors Branch 2 B1/01/13 3pp

H General correspondence

B101290518 Advises that future correspondence should be addressed IL Dept of Nuclear Safety, 1035 Outer Park Drive, 5th Floor Springfield, IL 62704
WRIGHT.O W Illinois, State of B1/01/22 1p 07566 357

J Insurance & indemnity information

B101090608 Forwards guarantee of payment of deferred premiums for OSIER.J Commonwealth Edison Co B1/01/03 1p.

B101270737 Forwards Endorsement 4 to Binders EB-1, EB-2, EB-3, EB-4, EB-30, EB-42 & EB-43 evidencing secondary financial protection
OSTER.J Commonwealth Edison Co. B1/01/21 8pp 07309 001

P Operating license stage documents & correspondence

B003240464 Forwards proposed amends to App A Tech Specs to include extended exposure max average planar linear test generation rate curves Extended exposures for fuel types have been analyzed by GE & incorporated into NEDC-24146A
PEOPLEB.D L Commonwealth Edison Co 80/03/19 2pp 04309.

B101220466 Ltr to all power reactor licensees & applicants forwa summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lenticular Tearing on Component Supports"
EISENHUT.D O Division of Licensing 80/11/26 8pp.

B101090160 Confirms proposal made by SEP owners group at B01202 meeting to assume significantly increased involvement in completion of safety evaluation program Presentation mail used during B01202 meeting encl
SCHAFFSTALL.R SEP Owners Group 80/12/03 12pp

B101190113 Ltr to all BWR licensees forwarding B01201 generic safety evaluation re BWR scram discharge sys Recommends short-term actions necessary to assure safe operation of GE BWRs pending permanent design changes.
EISENHUT.D.O Division of Licensing 80/12/09 2pp.

--B101190141 Generic safety evaluation re short-term actions required to assure continued safe operation of operating BWRs Continued operation of plants is acceptable pending permanent design mods Criteria for implementing design mods encl.
* Division of Licensing 80/12/01. 212pp. 07103:001.

B101070594 Forwards safety evaluation of SEP Topic 11-2.A. "Severe Weather Phenomena" & IX Tech Univ rept. "Tornado & Straight Wind Hazard Probability for Dresden Nuclear Power Reactor Site, IL."
CRUTCHFIELD.D Operating Reactors Branch 3 80/12/15 7pp 07404:289.

--B101070608 "Tornado & Straight Wind Hazard Probability for Dresden Nuclear Power Reactor Site, IL."
MCDONALD.J.R Texas Tech Univ NRC-04-76-345 80/09/31 07404:296

B101140047 Requests info re SEP Topic IV-2, reactivity control system design & protection against single failures Info should be provided within 90 days of receipt of ltr
CRUTCHFIELD.D. Operating Reactors Branch 3 80/12/18 4pp 07488:210.

B101210445 Forwards responses to questions on Rule 50.71e. "Periodic Updating of FSARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame
EISENHUT.D G Division of Licensing 80/12/15 13pp

B101160029 Notification of B01218 meeting w/SEP owners group in Bethesda, MD re SEP program, schedule for licensee topic completion & assignment of load topics to plants
RUSSELL.W.T Technical Support Branch 80/12/16. 2pp 07404:296

B101230339 Forwards listing of all SEP correspondence re facilities SEP owners group B01202 meeting List provides basis upon which to determine plant status Review & comments requested. W/O encl
CRUTCHFIELD.D Operating Reactors Branch 3 80/12/22 3pp 07512:099.

B101060376 Submits add'l response to NRC B00822 ltr Evaluation of Pratt & Whitney butterfly valve demonstrates that loads imposed & stresses developed in components during valve closure under LOCA event fall within acceptable limits
JANECEK, R F. Commonwealth Edison Co 80/12/26 2pp 07399 027

B101230446 Forwards Amends 52 & 46 to Licenses DPR-19 & DPR-25, respectively, safety evaluation & notice of issuance & availability
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/29 2pp 07512 139

--B101230431 Amends 52 & 46 to Licenses DPR-19 & DPR-25, respectively, authorizing one-time operation for AB-h w/plant chimney monitoring sys out of svc to permit installation of required monitoring improvements
CRUTCHFIELD, D Operating Reactors Branch 5 IPPOLITO, T A Operating Reactors Branch 2 80/12/29 8pp 07512 145

--B101230453 Safety evaluation supporting Amends 52 & 46 to Licenses DPR-19 & DPR-25, respectively
* Office of Nuclear Reactor Regulation, Director 80/12/29 2pp 07512 149

--B101230458 Notice of issuance & availability of Amends 52 & 46 to Licenses DPR-19 & DPR-25, respectively
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/29 2pp 07512 151

B101050500 Forwards response to NUREG-0737 No response provided for Dresden 1 Unit undergoing extensive mod & decontamination outage Requirements of NUREG-0737 will be addressed prior to startup of unit scheduled for June 1986.
ABEL, J B Commonwealth Edison Co 80/12/31 55pp 07385 211

B101230501 Forwards Amends 54 & 47 to Licenses DPR-19 & DPR-25, respectively, safety evaluation & notice of issuance & availability
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/31 3pp 07512 157

--B101230503 Amends 54 & 47 to Licenses DPR-19 & DPR-25, respectively, replacing Tech Spec Inservice insp requirements w/program meeting 10CFR 50.55a1g
CRUTCHFIELD, D Operating Reactors Branch 5 IPPOLITO, T A Operating Reactors Branch 2 80/12/31 6pp 07512 160

--B101230504 Safety evaluation supporting Amends 54 & 47 to Licenses DPR-19 & DPR-25, respectively
* Office of Nuclear Reactor Regulation, Director 80/12/31 16pp 07512 172

--B101230505 Notice of issuance & availability of Amends 54 & 47 to Licenses DPR-19 & DPR-25, respectively
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/31 2pp 07512 188

B101290329 Informs that SEP Topic VIII-2, onsite emergency power sys, diesel generator, will be basic input to integrated safety assessment Assessment may undergo revision if facility design changes
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/31 2pp 07575 008

B101300186 "Adequacy of Station Electric Distribution Sys Voltages, Dresden Station, Units 2 & 3."
USV, A C. EG&O Idaho, Inc FIN A-6237. B101300186 80/12/31 11pp 07582 308

B101090001 Forwards Revision 15 pages to CE-I-A, QA program topical rept Revisions reflect Surber 1980 addenda to Section III of ASME Code & recent ASME survey for renewal of ASME corporate certifications.
ABEL, J B Commonwealth Edison Co 81/01/02 1p 07441 007

--B101090005 Revision 15 pages to QA program topical rept.
* Commonwealth Edison Co CE-I-A R15 81/01/02 57pp 07441 008

B101130337 Submits schedule for completion of topics attached piping sys mods Schedules based upon preliminary engineering analysis completed to date
REED, C Commonwealth Edison Co 81/01/08 1p 07455 360

B101300470 Responds to B01114 ltr re alleged water loss from facilities Belief that no direct unmonitored water has been released from station has been repeatedly confirmed by effluent monitoring program
SCOTT, D J Commonwealth Edison Co 81/01/11 3pp 07586 265

B101300233 Forwards NRC B10113 orders for mod of licensee & granting extension of exemption Licensee must reassess suppression pool hydrodynamic loads & complete mods to meet General Design Criterion 50
IPPOLITO, T A Operating Reactors Branch 2 81/01/13 3pp

--B101300254 Order modifying license & granting extension of exemption Licensee must reassess suppression pool hydrodynamic loads & complete mods to meet General Design Criterion 50 by 820101
EISENHUT, D O Division of Licensing 81/01/13 7pp 07582 155

B101200296 Advises that scram discharge sys re-evaluation has been completed, in response to NRC B01001 ltr Necessary mods will be implemented in first refueling outage beginning 820101
JANECEK, R F Commonwealth Edison Co 81/01/15 2pp 07486 240

B101260482 Forwards Revision 2 to inservice insp & testing programs, deleting testing requirements for ECCS min flow valves & associated relief request (D-10) Valves are verified to close & open during normal sys surveillance tests
JANECEK, R F Commonwealth Edison Co 81/01/16 10pp 07308 003

B101220368 Forwards offsite dose calculation sys description per meteorological data requirements in NUREG-0737 Task III A 2
DELGECORGE, L O Commonwealth Edison Co 81/01/19 1p 07497 014

--B101220374 "Offsite Dose Calculation Sys Meteorological Monitoring, Offsite Dose Calculation Program for Emergency Preparedness at Operating Nuclear Power Plants," Revision 2
GOLDEN, J C Commonwealth Edison Co BRADLEY, J P. Murray & Trettel, Inc LAHTI, O P Sargent & Lundy, Inc 80/07/31 1:05p 07497 015

--B101220379 "Study of Low Level Dispersion Over Northern IL."
* Murray & Trettel, Inc 74/06/30 106pp 07497 159

B101260597 Forwards util B01126 revision of facility electrical drawl index & marked-up version of NRC index of drawings Indices available in Central Files only.
JANECEK, R F Commonwealth Edison Co 81/01/19 1p 07519 029

B101290786 Ack receipt of B01222 ltr informing NRC of wells to be sampled Requests environ contractor Monthly rept.
FISHER, W L Region 3, Chicago, Fuel Facility & Materials Safety Branch 81/01/19 1p 07568 035

--B101290791 Responds to NRC B01119 ltr re well samples New samples begin Jan 1981 & be analyzed for gross alpha, gross beta & tritium
GOLDEN, J C Commonwealth Edison Co 80/12/22 1p 07568 035

B101270661 Responds to NRC loss of offsite power survey status rept Partial loss of offsite power survey data should have been examined prior to processing so that only data significant to safety were included Calculated target values not valid
JANECEK, R F Commonwealth Edison Co 81/01/20 3pp 07549 006

B101270481 Advises of concurrence w/NUREG-0619 re feedwater nozzles & control rod drive return line nozzle cracking, in response to NRC B01113 ltr Results of further evaluations will be submitted by B10220
JANECEK, R F Commonwealth Edison Co 81/01/22 2pp 07543 010

B101280072 Forwards revised NRC evaluation of SEP Topics III-10, A & VIII-3 B to reflect comments on matters in util B01006 ltr
CRUTCHFIELD, D Systematic Evaluation Program Branch 81/01/25 2pp 07557 089

Q Inspection reports, IE Bulletins & correspondence

B101050249 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding" No response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/20 2pp 07389 120

B101050462 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malco Foundry Co, Inc." Written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/06 2pp 07390 017

B101070113 Forwards IE Insp Repts 50-010/80-21, 50-237/80-23 & 50-249/80-27 on B01103-07 & notice of violation
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/11/25 2pp 07415 011

--B101070118 Notice of violation from insp on B01103-07
* Region 3, Chicago, Office of the Director 80/11/24 1p 07415 013

--B101070125 IE Insp Repts 90-010/80-21, 90-237/80-23 & 90-249/80-27 on 801103-07. Noncompliance noted failure to collect weekly cooling water sample
JANUSKA, A. Q., PHILLIPS, M. P., PAPERIELLO, C. J. Region 3, Chicago, Office of the Director. 80/11/24 10pp. 07415 014

B101050530 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Bcrum Discharge Vol at Dresden Unit 2 " No response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/12/03. 2pp. 07390 302.

B101090778 Forwards IE Insp Repts 90-010/80-22, 90-237/80-24 & 90-249/80-28 on 801004-1114 No noncompliance noted
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/12/05 2pp. 07433 245.

--B101090785 IE Insp Repts 90-010/80-22, 90-237/80-24 & 90-249/80-28 on 801004-1114 No noncompliance noted Major areas inspected, operational safety verification & monthly maint observation.
TONQUE, T. M., JORDAN, M. J., WALKER, R. D. Region 3, Chicago, Office of the Director. 80/12/05. 6pp. 07430 247.

B101090132 Addl response to FOIA request for documents re imposition of civil penalties. NRC requests for congressional authorization for more severe penalties & responsibilities & behavior of nuclear plant operators Forwards documents listed in app.
FELTON, J. M. Division of Rules and Records. 80/12/09 3pp. 07441 194

--B101090142 IE Insp Repts 90-237/80-16 & 90-249/80-20 on 800908-10 No noncompliance noted NRC inspector observed two operators apparently asleep Lack of operator attentiveness is considered significant safety matter
PHILLIP, G. A., NORELIUS, C. E., SPESBARD, R. L. Region 3, Chicago, Office of the Director 80/09/29. 31pp.

--B101090150 Discusses IE policies for reporting, evaluating & documenting significant safety matters, in light of incident at facility. Consideration of safety significance always precedes noncompliance in evaluating any concern Related info encl
STELLO, V. Office of Inspection & Enforcement, Office of the Director. 80/10/01 App.

--B101090157 Requests to review any IE noncompliance info re 800808 investigation of alleged sleeping control room operators at facility & info re changing NRC requirements to cover operator sleeping on duty.
BRADFORD, P. A. Commissioners 80/10/10 1p

--B101090161 Forwards draft civil penalty package re inattentiveness of operators at facility
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/10/10. 53pp.

B101060073 Responds to IE Bulletin 80-23, "Failures of Bolenoid Valves Mfg by Valcor Engineering Corp. " Valves V70900-21-1 or V70900-21-3 not used in any safety-related functions. Approx 40 manhours expended in bulletin review.
RAUSCH, T. J. Commonwealth Edison Co 80/12/12 1p 07399 122

B101080060 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Bcrum Capability." No written response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/12/17 2pp. 07420 329.

B101130140 EN-80-36 on or about 801219, notice of violation & notice of proposed imposition of civil penalty in amount of \$4,000 will be issued to licensees. Action based on alleged item of noncompliance re shipment of waste not packaged properly.
HEIZGER, J. Enforcement Branch, THOMPSON, D. Director's Office. 80/12/17. 1p. 07457 026

B101150240 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BWR." Written response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/12/18. 1p. 07465 348.

B101050170 Forwards IE Bulletin 80-25, "Operating Problems W/Target Rod Safety Relief Valves at BWRs." No response required
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/12/19. 2pp. 07377 301.

B101080093 Responds to NRC 800818 request for monthly status rept re evaluations in response to IE Bulletin 79-14. Tabulations of piping sys w/stresses above FSAR levels & below operability limit encl.
JANECEK, R. F. Commonwealth Edison Co. 80/12/22. 5pp. 07421 090

B101200135 Forwards addl response to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Revised initial acceptance allowables for combined piping sys stresses during SSE event provided
JANECEK, R. F. Commonwealth Edison Co 81/01/03. 6pp 07466 16

B101200155 Forwards response to IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (801017 Indian Point 2 Event) " Surveillance procedures, of at least monthly repetition, will be instituted by 810601
RAUSCH, T. J. Commonwealth Edison Co. 81/01/05 6pp. 07486 202

B101260482 Forwards Revision 2 to inservice insp & testing program deleting testing requirements for ECCS min flow valves & associated relief request (8-10) Valves are verified to close & open during normal sys surveillance tests
JANECEK, R. F. Commonwealth Edison Co. 81/01/16 10pp 07308 0

R Periodic operating reports & related correspondence

B101270515 Forwards monthly operating repts for Dec 1980
SCOTT, D. J. Commonwealth Edison Co 81/01/19 1p 07346 299

--B101270520 Monthly operating repts for Dec 1980
MAXWELL, D. C. Commonwealth Edison Co 81/01/16 16pp. 07546

S Reportable occurrences, LERs & related correspondence

B101060481 Forwards LER 80-047/03L-0.
SCOTT, D. J. Commonwealth Edison Co 80/12/27 1p 07391 103

--B101060484 LER 80-047/03L-0 on 801204, pressure switch PS 261-301M level exceeded Tech Spec requirements Caused by setpoint drift. Pressure switch reset
SPEROFF, R. Commonwealth Edison Co. 80/12/29. 2pp 07391 10

B101060608 Forwards LER 80-046/03L-0 & deviation rept
SCOTT, D. J. Commonwealth Edison Co 80/12/29 1p 07391 133

--B101060617 LER 80-046/03L-0 on 801202, control rod driveline vol alarm not received during reactor scram Caused by incorrect cable length & routing, incorrect transducer placement & mounting & redundant transducer signal interference
HOLLAND, P. Commonwealth Edison Co. 80/12/30 2pp 07391 13

B101060590 Forwards LER 80-045/03L-0 & deviation rept
SCOTT, D. J. Commonwealth Edison Co 80/12/30 1p 07391 130

--B101060604 LER 80-045/03L-0 on 801201, LPC1 sys drywell high pressure interlock pressure switch, 1501-62D, found set above limit Caused by instrument drift Instrument setpoint adjusted Monthly checks will continue
* Commonwealth Edison Co 80/12/30. 2pp 07391 131.

B101260586 Forwards LER 80-048/03L-0
SCOTT, D. J. Commonwealth Edison Co 81/01/14 1p 07531 119

--B101260671 LER 80-040/03L-0 on 801219, isolation valve to pressure switch PS-16288 for automatic shutdown found closed Caused by personnel error Valve opened
SPEROFF, R. Commonwealth Edison Co. 81/01/14 2pp 07531 12

DOCKET 50-238 NUCLEAR SHIP SAVANNAH

R Periodic operating reports & related correspondence

B101300586 Forwards "NS Savannah Operations Rept." for 1980
GARVEY, J. J. Commerce, Dept. of, Maritime Administration 81/01/26 1p. 07582 303

--B101300587 "NS Savannah Operations Rept." for 1980
* Commerce, Dept. of, Maritime Administration 81/01/26 3pp. 07582 304.

DOCKET 50-241 MISSISSIPPI STATE UNIV RESEARCH REACTOR

H General correspondence

B101130371 Informs that CT Carley has assumed responsibility for Raleigh homogeneous reactor & is contact person for all matters re facility
PAULK, J. I. Mississippi State Univ. 81/01/03 1p. 07457 018

B101120402 Forwards safety evaluation of SEP Topics II-3 A, II-3 B & II-3 C re hydrology, flooding & ultimate heat sink. Evaluation will be basic input to integrated safety assessment at facility.
CRUTCHFIELD, D. Operating Reactors Branch 5 80/12/12 14pp

F Security, medical, emergency & fire protection plans

B101070387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 90 days of B10102 & by applicants as part of FSAR
EISENHUT, D. Division of Licensing 80/11/13 2pp

B10150368 Immediate Action Ltr 80-54, confirming until 801219 commitments re radiation protection & emergency planning. Instrumentation to meet NUREG-0578 Category A, Item 2.1.B.b requirements will be installed.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 80/12/19 2pp 07474 274

B101290583 Releases public version of evacuation time estimates for facility.
FELTON, J. M. Division of Rules and Records 81/01/27 1p 07573 267

--B101290589 Forwards public version of upgraded evacuation time estimates for facilities in response to NRC B01209 ltr MAIER, J. E. Rochester Gas & Electric Corp 81/01/14 23pp 07573 268

P Operating license stage documents & correspondence

7904270289 Responds to NRC 790405 ltr requesting addl info re sys mod to Class IE DC bus battery chargers. All chargers now in use have been part of plant configuration since 1969. Adequacy of equipment presently under review.
WHITE, L. D. Rochester Gas & Electric Corp 79/04/18 2pp.

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports".
EISENHUT, D. Division of Licensing 80/11/28 8pp.

B101050160 Confirms proposal made by SEP owners group at 801202 meeting to assume significantly increased involvement in completion of safety evaluation program presentation mail used during 801202 meeting encl.
SCHAFFSTALL, R. SEP Owners Group 80/12/05 12pp.

B101070476 Forwards draft technical evaluation of SEP Topic VIII-2, "Diesel Generators". Evaluation will be basic input to integrated safety assessment for facility.
CRUTCHFIELD, D. Operating Reactors Branch 5 80/12/12 19pp 07419:258

B101100161 Responds to FOIA request for five categories of documents re transportation of Pu. Forwards documents listed in Apps A & B. Info partially withheld safeguards info (ref FOIA Exemption 3).
FELTON, J. M. Division of Rules and Records. 80/12/12 6pp 07437 319

--B101100401 Discusses shipment of 72B mixed oxide fuel rods containing 47.7 kg Pu Tri-State Motor Transit will be carrier & until will adopt physical protection, contingency & guard training plan of carrier Tri-State will select route to be used.
WHITE, L. D. Rochester Gas & Electric Corp 80/02/08 1p

B101120323 Forwards draft technical evaluations re SEP Topics III-1, VII-2 & VII-3. Assessment compares facility w/criteria used for licensing new facilities. Evaluation will be basic input to integrated safety assessment for facility.
CRUTCHFIELD, D. Operating Reactors Branch 5 80/12/12 2pp 07439 163

--B101120332 "SEP Review of NRC Safety Topic III-1, Associated w/Electrical, Instrumentation & Control Portion of Classification of Structures, Components & Sys for Ginna Nuclear Power Plant.
LAUDENBACH, D. H. MAYN, J. G. GILMORE, L. W. EG&G, Inc 80/08/31 11pp 07439 165.

--B101120342 "SEP Review of NRC Safety Topic VII-2, Associated w/Electrical, Instrumentation & Control Portions of Engineered Safety Feature Sys Control Logic & Design for Ginna Nuclear Power Plant".
LAUDENBACH, D. H. MAYN, J. G. GILMORE, L. W. EG&G, Inc 80/08/31 23pp 07439 176

--B101120353 "SEP Review of SEP Safety Topic VII-03, Associated w/Electrical, Instrumentation & Control Portions of Sys Required for Safe Shutdown of Ginna Nuclear Power Plant".
LAUDENBACH, D. H. RADOSVIC, J. R. BRODERICK, N. E. EG&G, Inc 80/09/30 38pp 07439 199

B101120402 Forwards safety evaluation of SEP Topics II-3 A, II-3 B & II-3 C re hydrology, flooding & ultimate heat sink. Evaluation will be basic input to integrated safety assessment at facility.
CRUTCHFIELD, D. Operating Reactors Branch 5 80/12/12 14pp 07446 278

B101280441 Forwards draft "SEP Review of NRC Safety Topic V-11.0 Associated w/Electrical, Instrumentation & Control Portions of RHR Sys for Ginna Nuclear Plant". Compares facility against NRC criteria. Requests comments by B10130.
CRUTCHFIELD, D. Operating Reactors Branch 5 80/12/12 2pp 07558 065

--B101280450 Draft "SEP Review of NRC Safety Topic V-11.0 Associated w/Electrical, Instrumentation & Control Portions of RHR Sys for Ginna Nuclear Plant".
LAUDENBACH, D. H. RADOSVIC, J. R. GILMORE, L. W. EG&G, Inc 1183-4154 80/06/06 14pp 07558 087

B101300248 Forwards draft "SEP Review of NRC Safety Topic VII-1 A Associated w/Electrical, Instrumentation & Control Portions of Isolation of Reactor Protection Sys from Nonsafety Sys for Ginna Nuclear Power Plant". Requests comments by B10130.
CRUTCHFIELD, D. Operating Reactors Branch 5 80/12/12 2pp 07183 001

--B101300262 "SEP Review of NRC Safety Topic VII-1 A Associated w/Electrical, Instrumentation & Control Portions of Isolation of Reactor Protection Sys from Nonsafety Sys for Ginna Nuclear Power Plant".
LAUDENBACH, D. H. RADOSVIC, J. R., BRODERICK, N. E. EG&G, Inc 1183-4155 80/06/31 19pp 07183 001

B101140070 Requests info re SEP Topic IV-2, reactivity control sys design & protection against single failures. Info should be provided within 90 days of receipt of ltr.
CRUTCHFIELD, D. Operating Reactors Branch 5. 80/12/15 4pp 07498 199

B101210174 Forwards final technical assessment of SEP Topics VI-10, testing of reactor trip sys & engineered safety features, including response time testing & VI-7 A.3 re ECCB actuation sys.
CRUTCHFIELD, D. Operating Reactors Branch 5. 80/12/15 22pp 07488 305.

B101210445 Forwards responses to questions on Rule 50.71c, "Periodic Updating of FSARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete. Non-SEP plants must comply within specified time frame.
EISENHUT, D. Division of Licensing 80/12/15 13pp.

B101270150 Forwards safety evaluation of SEP Topic II-2, A, "Severe Weather Phenomena" & TX Tech Univ rept. "Tornado & Straight Wind Hazard Probability for Ginna (Brookwood) Nuclear Power Reactor Site, NY".
CRUTCHFIELD, D. Operating Reactors Branch 5 80/12/15 7pp 07547-259.

--B101270156 "Tornado & Straight Wind Hazard Probability for Ginna (Brookwood) Nuclear Power Reactor Site, NY".
MACDONALD, J. R. Texas Tech Univ. NRC-04-76-345 80/05/31 27 07547 266.

B101160029 Notification of 801218 meeting w/SEP owners group in Bethesda, MD re SEP program, schedule for licensee topic completion & assignment of lead topics to plants.
RUGSELL, H. T. Technical Support Branch. 80/12/16 2pp

B101060464 Forwards TMI action plan documentation per NUREG-0737, "Clarification of TMI Action Plan Requirements".
MAIER, J. E. Rochester Gas & Electric Corp. 80/12/30 1p 07396 270

--B101060469 "TMI Action Plan (NUREG-0737) Documentation".
Rochester Gas & Electric Corp 80/12/30. 46pp 07396 271

B101120575 SEISMIC REVIEW OF THE ROBERT E. GINNA NUCLEAR POWER PLANT AS PART OF THE SYSTEMATIC EVALUATION PROGRAM
MURRAY, R. C., NELSON, T. A., NG, D. S. Lawrence Livermore Laboratory
FIN A-0233 NUREG/CR-1821 80/12/31 135pp Available at N1B
07432 001

B101130495 Forwards util comments on SEP Topic V-11 B, "RHR Interlock Requirements (Electrical Review Only)," transmitted in NRC
B01212 1tr
MAIER, J. E. Rochester Gas & Electric Corp 81/01/08 3pp
07463 154

B101150495 Forwards comments on NRC draft assessments of SEP Topics
III-10, A, V-11, A, VI-7, C, I, VI-7, F & VIII-3 B, transmitted in
NRC 800820 1tr Final NRC assessments should not be prepared
until addl opportunity to resolve util comments is provided
MAIER, J. E. Rochester Gas & Electric Corp 81/01/08 7pp

B101150520 Forwards comments on NRC draft assessments of SEP Topics
III-10, A, V-11, A, VI-7, C, I, VI-7, F & VIII-3 B, transmitted in
NRC 800820 1tr Final NRC assessments should not be prepared
until addl opportunity to resolve util comments is provided
MAIER, J. E. Rochester Gas & Electric Corp 81/01/08 7pp
07463 138

B101280414 Requests written notification re steps taken to meet NRC
requirements re override capability of engineered safety
features sys actuation signals for containment purge valve
isolation. Response requested in 45 days
CRUTCHFIELD, D. Operating Reactors Branch 5 81/01/12 3pp
07558 075

--B101280423 Safety evaluation of override of engineered safety features
sys actuation signals for containment purge valve isolation.
Licensee design is not acceptable. Requests mods Draft SEP
technical evaluation encl
* Operating Reactors Branch 5 81/01/12 9pp 07558 078

B101210299 Forwards comments on NRC B01114 safe shutdown evaluation re
SEP Topics V-10, U, V-11, A, V-11, B, VII-3 & IX-3 Integrated
approach of evaluation achieved comprehensive review
MAIER, J. E. Rochester Gas & Electric Corp 81/01/13 6pp
07492 065

B101230418 Forwards response to NRC B01215 questions re SEP Topic IV-2,
"Reactivity Control Sys." Design features which limit
reactivity insertion rates & rod malfunctions from single
failure described
MAIER, J. E. Rochester Gas & Electric Corp 81/01/19 12pp
07308 001

B101230422 Forwards preliminary response to NRC assessment of SEP Topic
II-2, A, "Bare Weather Phenomena." Unnumbered refs impede
verification of info Design basis wind load will be
provided, pending more detailed review
MAIER, J. E. Rochester Gas & Electric Corp 81/01/19 2pp
07511 120

B101270665 Forwards responses to SEP Topic Evaluations III-1,
"Classification," VII-2, "Engineered Safety Feature Sys
Control Logic & Design" & VII-3, "Safe Shutdown Sys." Addl
comments will be transmitted when available.
MAIER, J. E. Rochester Gas & Electric Corp 81/01/23 16pp
07547 009

Q Inspection reports, IE Bulletins & correspondence

B101080112 Suppls 800910 response to IE Bulletin 80-20, "Failures of
Westinghouse Type W-2 Spring Return to Neutral Control
Switches." Mod to provide for continuous continuity testing
planned.
MAIER, J. E. Rochester Gas & Electric Corp 80/11/17 1p
07416 344

B101050124 Requests existing data, summaries & records of inservice insp
tests of containments w/greased prestressing tendons.
ORNL receiving contract to compile & review records of
tendons.
EISENHUT, D. O. Division of Licensing 80/11/25 3pp 07378 353

B101070416 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on
Terry Turbine Steam Inlet Flange." No written response
required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director.
80/11/26 1p 07414 050

B101300064 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by
Helmolt Foundry Co. Inc." No subv valve yokes used at
facility.
WHITE, L. D. Rochester Gas & Electric Corp 80/12/05 1p
07579 329

B101100794 Responds to IE Bulletin 80-23, "Failures of Solenoid
Mfg by Valcor Engineering Corp." No subv valves in use or
planned for use in safety-related functions at facility.
MAIER, J. E. Rochester Gas & Electric Corp 80/12/10 1p
07444 043

B101060843 Forwards IE Info Notice 80-41, "Actuation of ECCS in
Recirculation Mode While in Hot Shutdown." No written
response required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
80/12/16 1p 07397 017

R Periodic operating reports & related correspondence

B101210474 Forwards monthly operating rpt for Dec 1980
BAND, B. A. Rochester Gas & Electric Corp 81/01/14 1p 074

--B101210476 Monthly operating rpt for Dec 1980
MCNAMARA, A. E. Rochester Gas & Electric Corp 81/01/12 5p
07493 246

S Reportable occurrences, LERs & related correspondence

791140298 Responds to Eisenhower 79100B 1tr re multiple equipment
failures & surveillance testing errors. Reactor trip occurred
on 7C0103 when steam pressure channel 47H was isolated.
Details procedure mods implemented.
WHITE, L. D. Rochester Gas & Electric Corp 79/11/07 2pp

B101210634 Submits results of investigation re engaged barring d
for emergency diesel generator 1B. Vendor contended that
engaged barring device would not negate starting emergency
diesel generator. Barring device has been removed.
BAND, B. A., MAIER, J. E. Rochester Gas & Electric Corp 80/11/1
2pp 07408 337

B101120314 Forwards LER 80-011/03L-0
MAIER, J. E. Rochester Gas & Electric Corp 81/01/07 1p
07447 138

--B101120317 LER 80-011/03L-0 on B01211, bus 17 breaker from 1B
generator failed to close. Cause not stated. Testing interval
shortened to verify operability B10106
EDGAR, E. C. Rochester Gas & Electric Corp 81/01/09 1p
07417 139

DOCKET 80-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B101090387 1tr to all licensees of operating reactor plants, CP
& CP applicants. Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B10102 & by applicants as part of FSAR
EISENHUT, D. O. Division of Licensing 80/11/13 2pp

B101210405 Releases public version of emergency plan
FELTON, J. H. Division of Rules and Records 80/11/19 1p
07437 011

--B101120413 Forwards public version of draft Revision 7 to emer
plan
COUNSIL, W. G., FEE, W. F. Northeast Nuclear Energy Co. (subs.
Northeast Utilities) 80/10/14 3pp 07437 013

--B101120415 Public version of draft Revision 7 to emergency pl
* Northeast Nuclear Energy Co. (subs. of Northeast Utilities)
80/10/14 107pp 07437 016

B101090004 Discusses util commitments re emergency plans. Revision
emergency plans addressing Revision 1 to NUREG-0654/FEMA-
REP-1, App E to 10CFR50, will be submitted by B10216
COUNSIL, W. G. Connecticut Yankee Atomic Power Co. COUNSIL, W.
Northeast Nuclear Energy Co. (subs. of Northeast Utilities)
80/12/31 4pp 07442 247

B101100734 Requests that encl facility emergency planning info
publicly available w/o encl
BOJDER, J. L. Division of Rules and Records 80/12/31 1p
07445 128

B101270712 Responds to NRC B01124 1tr re fire protection. Feature
Protection equivalent to NRC seismic criteria provided by
backfitting of seismic qualification of reactor coolant
pump lubrication oil sys
COUNSIL, W. G. Connecticut Yankee Atomic Power Co. COUNSIL, W.
Northeast Nuclear Energy Co. (subs. of Northeast Utilities)

B101290163 Forwards facility emergency planning info to be made publicly available w/o encl
SCUDER, J. L. Division of Rules and Records 81/01/23 1p
07575 159

J Insurance & indemnity information

B101270736 Forwards Endorsement 4 to NELA Binders EB-15 & EB-16
IFFLAND, R R Northeast Utilities 81/01/22 3pp 07548 059

B101270744 Forwards Endorsements 65 & 66 to NELA Policy NF-173
IFFLAND, R R Northeast Utilities 81/01/22 4pp 07548 046

P Operating license stage documents & correspondence

B01180054 Advises that SEP Topics 11-2 B.11-2 D.111-B B & V1-B should be added to 791116 list of topics removed from review due to related generic NRC activities & nonapplicability BWR DBE topic list encl
CRUTCHFIELD, D Operating Reactors Branch 5 80/09/26 5pp

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D G Division of Licensing 80/11/26 6pp

B101050160 Confirms proposal made by SEP owners group at B01202 meeting to assume significantly increased involvement in completion of safety evaluation program Presentation (nat) used during B01202 meeting encl
SCHIFFSTALL, R SEP Owners Group 80/12/05 12pp

B101150033 Forwards request for addl info re bypass & reset of containment isolation sys (per SEP Topic VI-41 & other engineered safety features at facility
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/08 5pp
07462 174

B101190113 Ltr to all BWR licensees forwarding B01201 generic safety evaluation re BWR scram discharge sys. Recommends short-term actions necessary to assure safe operation of GE BWRs pending permanent design changes
EISENHUT, D G Division of Licensing 80/12/09 2pp

--B101190141 Generic safety evaluation re short-term actions required to assure continued safe operation of operating BWRs Continued operation of plants is acceptable pending permanent design mods. Criteria for implementing design mods encl
* Division of Licensing 80/12/01 212pp 07183 001

B101140055 Requests info re SEP Topic IV-2, reactivity control sys design & protection against single failures Info should be provided within 90 days of receipt of ltr
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/15 4pp
05939 001

B101210173 Forward safety evaluation of SEP Topic 11-2.A re severe weather phenomena & "Tornado & Straight Wind Hazard Probability for Millstone Nuclear Power Reactor Site, CT."
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/15 7pp
07488 272

--B101210181 "Tornado & Straight Wind Hazard Probability for Millstone Nuclear Power Reactor Site, CT"
MCDELMALD, J R Texas Tech Univ NRC-D4-76-345 80/03/31 26pp
07488 279

B101210445 Forwards responses to questions on Rule 50.71e. "Periodic Updating of FSARs" & FR notice of final rule. SEP plants need not comply w/rule until program is complete. Non-SEP plants must comply within specified time frame.
EISENHUT, D G Division of Licensing 80/12/13 13pp

B101160029 Notification of B01218 meeting w/SEP owners group in Bethesda, MD re SEP program, schedule for licensee topic completion & assignment of lead topics to plants
RUSSELL, W F Technical Support Branch 80/12/16 2pp

B101230341 Forwards listing of all SEP correspondence re facility per SEP owners group B01202 meeting list provides basis upon which to determine plant status Review & comments requested w/o encl
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/22 2pp
07512 102

B101040946 Submits daily notes for B01223 Status of facilities in 11 IE regions encl
BIRCKS, W J Office of the Executive Director for Operations 80/12/24 3pp 07401 107

B101270124 Advises that SEP Topic 111-3 B re structural consequences underlain sys failure is not applicable to facility & has been deleted from SEP review
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/26 2pp
07547 254

B101160363 Informs that second 10-yr insp interval commenced B01220 Util proceeding w/implementation of inservice insp & testing program per B00918 ltr
COUNSIL, W G Northeast Nuclear Energy Co (subs. of Northeast Utilities) 80/12/29 1p 07470 084

B101090012 Forwards summary of investigation of anchorage & support safety-related electrical equipment, per B00728 request.
COUNSIL, W G Northeast Nuclear Energy Co (subs. of Northeast Utilities) COUNSIL, W G Connecticut Yankee Atomic Power Co 80/12/30 8pp 07442 239

B101130138 Informs that, as result of numerous changes in interpretations of NRC guidelines, info transmitted on B00429 is superseded by encl revised lists Info not vital to safety evaluation scheduled for B10201
COUNSIL, W G Northeast Nuclear Energy Co (subs. of Northeast Utilities) 80/12/30 6pp 07449 238

B101160248 Forwards rept on post-TMI requirements in response to NUREG-0737 & NRC B01031 ltr
COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs. of Northeast Utilities) 80/12/31 300pp 07468 014

B101120327 Requests extension to B10131 for submittal of proposed Spec changes re operable/operability clarification.
COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs. of Northeast Utilities) 81/01/02 1p 07447 118

B101200307 Application to amend License DPR-21, revising fire protection Section 3 F to permit util to proceed w/mods identified in NRC 780926 fire protection safety evaluation. Mods will be completed prior to return to power following 1980 outage
COUNSIL, W G Northeast Nuclear Energy Co (subs. of Northeast Utilities) 81/01/03 9pp 07486 367

B101300508 Forwards draft safety evaluation re SEP Topic 111-7, D. "Containment Structural Integrity Test" Facts upon which evaluation is based should be examined for correctness.
CRUTCHFIELD, D Operating Reactors Branch 5 81/01/07 5pp
07584 358

B101270670 Advises that plans for feedwater trip for reactor vessel high water level will be postponed until TMI followup rept is complete
COUNSIL, W G Northeast Nuclear Energy Co (subs. of Northeast Utilities) 81/01/16 1p 07545 192

B101290265 Responds to NRC B01208 request for info re SEP Topic VI- "Containment Isolation Sys" Delays in delivery of equipment will delay mods Commitment will be fulfilled prior to unit startup from current refueling outage
COUNSIL, W G Northeast Nuclear Energy Co (subs. of Northeast Utilities) 81/01/20 4pp 07567 171

B101290219 Responds to B01113 request for compliance w/requirements contained in NUREG-0619, "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking" All necessary mods to control rod drive/line completed
COUNSIL, W G, FEE, W F Northeast Nuclear Energy Co (subs. of Northeast Utilities) 81/01/22 4pp 07566 321

B101280088 Forwards request for addl info on SEP Topics VII-1, A. "Isolation of Reactor Protection Sys from Nonsafety Sys, Including Qualification of Isolation Devices," & VII-2, "Engineered Safety Features Sys Control Logic & Design."
CRUTCHFIELD, D Operating Reactors Branch 5 81/01/24 3pp
07557 084

Q Inspection reports, IE Bulletins & correspondence

B101300720 Forwards IE Insp Rept 50-245/80-19 on B01006-09. No noncompliances noted
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/11/05 2pp 07583 324

DOCKETED ITEMS

--B010300727 IE Insp Rept 50-245/80-19 on B01006-09 No noncompliance noted. Major areas inspected containment integrated leak rate test procedure, containment local leak rate testing & pipe support & restraint sys
CAPITON, D L Region 1, Philadelphia, Reactor Operations Nuclear Support Branch REKHO, W., WIGGINS, J Region 1, Philadelphia, Office of the Director 80/11/04 7pp. 07583 326.

B01070425 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/11/26 1p 07414 035

B01150028 Responds to IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." No valves w/specifed part numbers in use at facilities
COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/12/03 1p 07462 205.

B01050146 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor For Scram Discharge Vol at Dresden Unit 2." No response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/05 1p 07377 241

B01100789 Responds to IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." No subj valves in use at facilities
COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/12/05 1p 07444 042.

B01150536 Ack receipt of B01016 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-245/80-11 & 50-336/80-09 Item E now considered as single item of noncompliance
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/12/16 1p. 07464 180

--B01150540 Responds to NRC B00922 ltr re violations noted in IE Insp Repts 50-245/80-11 & 50-336/80-09. Corrective actions advised personnel that partial sys lineups will be conducted following maint where appropriate.
COUNSIL, W G, FEE, W F. Northeast Nuclear Energy Co. (subs of Northeast Utilities) 80/10/16 4pp. 07464 181.

--B01150542 Forwards IE Insp Repts 50-245/80-11 & 50-336/80-09 on B00706-0802 & notice of violation.
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/09/22 2pp 07464 183.

--B01150544 Notice of violation from insp on B00706-0802
* Region 1, Philadelphia, Office of the Director. 80/09/16 2pp. 07464 187

--B01150546 IE Insp Repts 50-245/80-11 & 50-336/80-09 on B00706-0802 Noncompliance noted failure to require restoration of equipment following maint & failure to require radiation work permit in accordance w/procedures.
SHEDLOSKY, J T, ZIMMERMAN, R P Region 1, Philadelphia, Office of the Director KEINTO, R R Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/16 10pp. 07464 189.

B01060139 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Scram Capability." No response required.
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/17 1p. 07391 291

B01070066 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of 76 of 183 Control Rods to Fully Insert During Scram at BWR." No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director. 80/12/18 1p 07414 146

B01130099 Forwards IE Bulletin 80-25, "Operating Problems W/Target Rock Safety-Relief Valves at BWRs." Written response required.
GRIER, B H Region 1, Philadelphia, Office of the Director. 80/12/19 1p. 07449 164.

B01160363 Informs that second 10-yr insp interval commenced B01228 Util proceeding w/implementation of inservice insp & testing program per B00918 ltr.
COUNSIL, W G Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 80/12/29 1p. 07470 084.

B Periodic operating reports & related correspondence

B01200274 Forwards monthly operating rept for Dec 1980
MROCKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 81/01/13 1p 07476 335

--B01200277 Monthly operating rept for Dec 1980
HARRAI, O Northeast Nuclear Energy Co (subs of Northeast Utilities) 81/01/07 6pp 07476 356

B Reportable occurrences, LERs & related correspondence

B01050539 PNO-I-80-178 on B01222, Chem Nuclear tractor trailer ca low level radwaste from util was involved in traffic accident near Bordentown, NJ No visible damage to cask detected Shipment proceeded to Barnwell, SC
CAMPELL, M, KINNEHAN, J Region 1, Philadelphia, Office of the Director 80/12/23 2pp 07375 338.

B01160541 Forwards LER 80-018/01x-1
MROCKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 81/01/09 1p 07471 231

--B01160613 LER 80-018/01x-1 on B01105, MERH-32 & MERH-28 main st support members found to have failed welds between support member & support structure Caused by lack of penetration Bys scheduled for reanalysis per IE Bulletin 79-14
* Northeast Nuclear Energy Co (subs of Northeast Utilities) 81/01/09 3pp 07471 282

B01280393 PNO-I-81-06 on B01113, high airborne radioactivity was identified on refueling floor of reactor bldg. Caused by two workers cleaning area around head of reactor below refueling floor Whole body counts indicated 20 & 200 mPC-hrs
NIMTZ, R, KEITH, R, SMITH, O Region 1, Philadelphia, Office of the Director 81/01/13 2pp 07557 058

DOCKET 50-247 INDIAN POINT STATION, UNIT 2

A Application/construction stage documents & correspondence

B01060299 Forwards responses to NRC B01014 ltr re proposed inservice insp & testing program
O'TOOLE, J D Consolidated Edison Co. of New York 80/12/22 07396 136.

F Security, medical, emergency & fire protection plans

B01090387 Ltr to all licensees of operating reactor plants, CP hq & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B0102 & by applicants as part of PSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

B01140848 Advises of provisions of 10CFR50, App R, that are applicable to fire protection features of facility FR notice & summary of staff requirements to resolve open items encl No open items for facility W/O encl
EISENHUT, D O Division of Licensing 80/11/24 3pp. 07461 0

B01070250 Requests that encl emergency planning info be made pub available, W/O encl
SOUDE, J L Division of Rules and Records 80/12/17 1p 07414 277

B01230599 Forwards security plan mods Mods withheld (ref 10CFR2
O'TOOLE, J D Consolidated Edison Co. of New York 81/01/16 93196 249.

G Adjudicatory correspondence

B01100629 Forwards revised order for mod of license, correcting m B00829 order Hearing date also revised
EISENHUT, D O Division of Licensing 80/09/19 3pp 07444 0

--B01100636 Revised order amending License DPR-23 Info requested Bulletin 79-018 must be submitted to IE by B01101.
EISENHUT, D O Division of Licensing 80/09/19 6pp. 07444 0

B01160246 Order denying request for reconsideration of Commission B00530 order but directing ASLB to conduct discretionary proceeding using full adjudicatory format Listed issues must be addressed, Certificate of Svc encl
CHILK, B J Office of the Secretary of the Commission 81/01/07 19pp 07470 228

B101270319 Requests that public hearings re emergency response plans be rescheduled to earlier date
DELBELLO, A. B. Westchester County, NY B1/01/08. 2pp 07646 071

B101220139 Forwards Ltr responses to B01219 notice of violation & notice of proposed imposition of civil penalty from insp of control room activities
O'TOOLE, J. D. Consolidated Edison Co. of New York B1/01/13 2pp 07496 064

--B101220140 Response to notice of violation from insp of control room activities. Procedure change not contrary to Tech Specs & did not involve unreviewed safety, question Alleged noncompliance not in "violation" category. Requests proceeding dismissal
O'TOOLE, J. D. Consumers Power Co. B1/01/13 9pp 07496 066

--B101220147 Response to notice of proposed imposition of civil penalty from insp of control room activities. Imposition of civil penalty inappropriate & unreasonable w/no remedial or deterrent value. Requests that no penalty be imposed
O'TOOLE, J. D. Consolidated Edison Co. of New York B1/01/13 4pp 07496 075

B101270047 Requests hearing on compaction of spent fuel pool & consequences
MILT, J., AUSIN, L., CCHREIN, D. Public Interest Research Group, New York B1/01/19. 2pp. 07547-023

H. General correspondence

B101190190 Responds to B01027 mailgram expressing concern re containment flooding incident at facility. NRC is investigating incident & has imposed civil penalties on util
EISENHUT, D. G. Division of Licensing B0/12/30. 1p. 07475 311.

--B101190197 Expresses concern re containment flooding incident at facility
HARRISON, J. New York, State of B0/10/27 1p 07474 312

--B101190202 Expresses concern re containment flooding incident at facility
HARRISON, J. New York, State of B0/10/27 1p 07475 313

--B101190207 Expresses concern re containment flooding incident at facility
HARRISON, J. New York, State of B0/10/27 1p 07475 314.

--B101190214 Expresses concern re containment flooding incident at facility
HARRISON, J. New York, State of B0/10/27. 1p 07475 315

B101270504 Forwards response to B01204 ltr requesting responses to constituent questions re containment flooding at facility on B01017. Inadequate mgmt control & maint of leak detection sys were primary contributors to event
BIRCHES, M. J. Office of the Executive Director for Operations B1/01/07 3pp 07309 001

--B101270508 Requests response to encl J Barrows B01118 questions re B01017 containment flooding at facility
EMERY, D. F. House of Rep B0/12/04 2pp 07309:001

B101260199 Supports shutdown of facilities
AUREY, C. Affiliation Unknown B1/01/09 1p. 07523 303.

B101280335 Requests NRC ltr to util re B01017 containment flooding event & util response
LEWIS, M. Affiliation Unknown B1/01/10. 1p 07187 001

B101270304 Requests info re B10110 constituent ltr requesting safety hearings be held for facilities Ltr encl.
WILLIAMS, H. A. Senate B1/01/15. 1p 07309 001

B101280272 Supports shutdown of facility
SCLIO, J. Affiliation Unknown B1/01/20 1p 07308:001

B101280605 Supports revocation of license
ALAGO, A., MCCILLICUDDY, C., WILLOUGHBY, R. H. Affiliation Unknown B1/01/22 1p 07557 285

P. Operating license stage documents & correspondence

B101100629 Forwards revised order for mod of license, correcting refs in B00827 order. Hearing date also revised
EISENHUT, D. G. Division of Licensing B0/09/19 3pp. 07444:030

--B101100636 Revised order amending license DPR-23 info requested by Bulletin 79-01B must be submitted to IE by B01101
EISENHUT, D. G. Division of Licensing B0/09/19 6pp 07444 073

B101280376 FOIA request for documents re Task Force on Interim Operation of Indian Point submitted to NRC B00601-1114
MCLT, R. R. New York Univ B0/11/17 1p 07558 062

B101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for scrubbers under ATG License amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT, D. G. Division of Licensing B0/11/20 1p

--B101100271 Revised Pages 3/4 7-22 through 20.B 3/4 7-9 & 7-6 & 6-17 STS scrubber inservice insp requirements
* Division of Licensing B0/11/20 10pp

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D. G. Division of Licensing B0/11/26 8pp 07591 244

B101210445 Forwards responses to questions on Rule 50.71a, "Periodic Updating of FEARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete. Non-SEP plants must comply within specified time frame
EISENHUT, D. G. Division of Licensing B0/12/15 13pp

B101150065 Forwards safety evaluation re susceptibility of safety-related sys to flooding from failure of Noncategory 1 sys
VARQA, B. A. Operating Reactors Branch 1 B0/12/18 2pp 07463 001

--B101150070 Safety evaluation re susceptibility of safety-related sys to flooding from failure of Noncategory 1 sys
* Operating Reactors Branch 1 B0/12/18 2pp 07463 0081

--B101150496 "Technical Evaluation of the Susceptibility of Safety-Related Sys to Flooding Caused by Failure of Noncategory 1 Sys for Indian Point 2"
LATONRE, V. R., VICTOR, R. A. Lawrence Livermore Laboratory B0/11/30 16pp 07463 009

B012290320 Forwards "Rept on 1978-1979 Studies to Evaluate Catch Efficiency of 1 0-+2 Epibenthic Sled" Certificate of Svc encl.
O'TOOLE, E. J. D. Consolidated Edison Co. of New York B0/12/19 3pp 07345 049.

--B012290323 "Rept on 1978-79 Studies to Evaluate Catch Efficiency of 1 0-+2 Epibenthic Sled"
* Texas Instruments, Inc B0/09/30 36pp. 07345 072

B101060461 Forwards response to NRC B01031 ltr re Item E 2 of B00231. Confirmatory Order Changes will be made before unit returns to svc. From present refueling/maint outage. Also forwards change of schedule for implementation of Item F 2
O'TOOLE, J. D. Consolidated Edison Co. of New York B0/12/29 7pp 07398:216.

B101060450 Forwards supplemental response to NRC 790509 ltr re PHR feedwater lines. Details welding procedures employed, defects & post-weld heat treatment
O'TOOLE, J. D. Consolidated Edison Co. of New York B0/12/31 7pp 07396:092.

B101060454 Submits addl clarifications per B00801 ltr re installation of undervoltage relays on buses 2A, 3A, 5A & 6A. Relays will be set at .8s per unit on 460 volt w/time delay of 150-s
O'TOOLE, J. D. Consolidated Edison Co. of New York B0/12/31 2pp 07396 090

B101130711 "Adequacy of Station Electrical Distribution Sys Voltage Indian Point Nuclear Station Unit 2." preliminary technical evaluation rept
WEBER, D. A. Idaho National Engineering Laboratory FIN A-6226. B101130711. B0/12/31 14pp 07454 019

B101290671 Forwards Westinghouse responses & rept "Radiation Data Terminal Block," discussed in B01031 ltr re electrical equipment environ rept. Proprietary portions withheld (ref ECFR2 790)
O'TOOLE, J. D. Consolidated Edison Co. of New York B1/01/14 45pp 07308 001.

--B101290676 Forwards addl info requested in NRC 731218 ltr re WCAP-7929.
"Fan Cooler Motor Unit Test " Requests withholding
EICHELDINGER, C Westinghouse Electric Corp 76/03/31 23pp
07308 001

B101210591 Informs that response to NRC B00827 ltr re valve
qualification program for containment purge & pressure
relief isolation valves will be provided by B10419, BRP & 2 4
Revision 1 & associated position CSB A-4 to be forwarded
O'TOOLE, J D Consolidated Edison Co of New York 81/01/15 1p
07489 252

B101220362 Forwards "1978 Yr Class Rept for Multiplant Impact Study
of Hudson River Estuary " Affidavit of svc encl Rept
available in Central Files only
O'TOOLE, J D Consolidated Edison Co of New York 81/01/16 4pp.
07917 038

B101280365 Responds to FOIA request for documents re Task Force on
Interim Operation of Indian Point submitted to NRC after
B00531 Forwards App A documents App B documents withheld
(ref FOIA Exemption 3)
FELTON, J H Division of Rules and Records 81/01/21 3pp
07550 059.

--B101280381 Forwards draft risk analysis for Facilities Probability of
severe core damage is slight, taking into account
improvements made or committed to as of early 1980 w/o encl
FONTEICILLA, H Commissioners. 80/06/13. 1p.

--B101280380 Staff requirements memo re B00626 briefing on
recommendations of facility task force Commission took no
action during meeting Task force rept & other info re
facility operation will be reviewed further
CHILK, B J Office of the Secretary of the Commission. 80/06/30
1p

--B101280396 Discusses review of task force rept on interim operation of
facilities. Interim operation poses no undue risk to public &
environ health & safety Facilities should be permitted to
continue operation during proceedings
HENDRIE, J H Commissioners 80/07/02 1p.

--B101280402 Provides JM Hendrie comments on order re interim operation
of facility Specific language of order should be modified
Decision on interim operation depends more heavily on task
force results
HABSELL, D F Commissioners 80/06/22. 1p

Q Inspection reports, IE Bulletins & correspondence

B101080117 Submits schedule planned for response to Item 2b of IE
Bulletin 80-11, "Masonry Wall Design " Study will be
completed by May 1981 w/final rept submitted by B10615
Criteria & justification will be sent by B01231.
ZARAKAS, P Commonwealth Edison Co. 80/11/07 2pp. 07416 345.

B101300143 Forwards IE Insp Repts 50-003/80-02 & 50-247/80-14 on
B00903-04 No noncompliance noted
SMITH, Q H Region 1, Philadelphia, Fuel Facility & Materials Safety
Branch. 80/11/10. 2pp. 07503 105

--B101300151 IE Insp Repts 50-003/80-02 & 50-247/80-14 on B00903-04 No
noncompliance noted Major areas inspected meteorological
monitoring sys including monitoring equipment & support
facilities in emergency operations facility.
JACKSON, T J Philadelphia, Office of the Director.
BORES, R J Region 1, Philadelphia, Fuel Facility & Materials
Safety Branch 80/10/24. 7pp 07583 107.

B101060890 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on
Terry Turbine Steam Inlet Flange " No written response
required.
GRIER, B H Region 1, Philadelphia, Office of the Director
80/11/26. 1p 07396 342.

B101080387 Forwards insp rept summarizing results of NRC mgt &
technical review of Con Ed Decision made to re-evaluate mgt
structure, in light of leak of 100,000 gallons of water into
containment at facility w/o encl.
DIRCKS, W J Office of the Executive Director for Operations.
80/12/19. 2pp 07417 335

B101060891 Forwards IE Info Notice 80-44, "Actuation of ECCS in
Recirculation Mode While in Hot Shutdown." No written
response required.
GRIER, B H Region 1, Philadelphia, Office of the Director.
80/12/16 1p. 07397 005

B10130159 EN-80-57 on or about B01219, notice of violation & not
proposed imposition of civil penalties in amount of \$3,000
will be issued to licensee Action based on alleged iter of
noncompliance re changes in procedure w/o NRC approval
RIEGLAND, J Enforcement Branch THOMPSON, D Director's Office
80/12/17 1p 07457 027

B101150575 Ack receipt of B01117 ltr informing NRC of steps taken
correct violations noted in IE Insp Rept 50-247/80-13
URUNER, E J Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 80/12/17 1p 07444 242

--B101150578 Responds to NRC B01017 ltr re violations noted in IE
Rept 50-247/80-13 Corrective actions revised procedure
IPC-A-087 "Lithium by Atomic Absorption" has been issued
Include acceptance criteria
ZARAKAS, P Consolidated Edison Co of New York 80/11/17
07464 243

--B101150580 Forwards IE Insp Rept 50-247/80-13 on B00818-22 & n
violation
BRUNER, E J Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 80/10/17 2pp 07464 245

--B101150581 Notice of violation from insp on B00818-22
* Region 1, Philadelphia, Office of the Director 80/10/19
07464 247

--B101150585 IE Insp Rept 50-247/80-13 on B00818-22 Noncompliance
failure to follow written procedures & to perform calibr
tests in accordance w/procedural steps per Tech Specs
CHUNG, J H MCCANN, J Region 1, Philadelphia, Office of the
Director GREENMAN, E Q Region 1, Philadelphia, Reactor
Operations Nuclear Support Branch 80/10/15 17pp 07464.

B101060299 Forwards responses to NRC B01014 ltr re proposed inspe
insp & testing program
O'TOOLE, J D Consolidated Edison Co of New York. 80/12/22
07396 136

B101220130 Forwards util responses to B01219 notice of violation
notice of proposed imposition of civil penalty from insp
of control room activities
O'TOOLE, J D Consolidated Edison Co of New York 81/01/13
07496 064

--B101220140 Response to notice of violation from insp of control
activities Procedure change not contrary to Tech Specs & did
not involve unreviewed safety question Alleged noncompliance
not in "Violation" category Requests proceeding dismissal
O'TOOLE, J D Consumers Power Co 81/01/13 7pp 07496 06

--B101220147 Response to notice of proposed imposition of civil
penalty from insp of control room activities imposition of civil
penalty inappropriate & unreasonable w/no remedial or
deferent value Requests that no penalty be imposed
O'TOOLE, J D Consolidated Edison Co of New York 81/01/13
07496 075

B101270190 Forwards notice of violation & proposed imposition of
penalty & util B10105 answer re leakage of river water into
containment bldg. in response to request IE Bulletin 80-24
issued to preclude similar event
SNIETEK, J H Division of Resident & Regional Reactor Inspection
81/01/13 2pp 07543 107

--B101270194 Responds to NRC B01211 notice of violation & proposed
imposition of civil penalty based on investigation re water
leakage into containment bldg Differing views on issues have
been cited in encl reply statement & answer to notice
O'TOOLE, J D Consolidated Edison Co of New York. 81/01/05
100pp 07543 114.

B101220315 Confirms profilometry use in current steam generator
program Four tubes in steam generator 22 not passing 610
probe will remain in svc as special test cases to benchmark
predictive capability of profilometry technique
O'TOOLE, J D Consolidated Edison Co of New York 81/01/16.
07500 156

R Periodic operating reports & related correspondence

B101140316 Forwards "1977 Yr Class Rept for Multiplant Impact Study of
Hudson River Estuary " Certificate of Svc encl.
O'TOOLE, J D Consolidated Edison Co of New York 80/12/19.
07459 001.

--B101140326 "1977 Yr Class Rept for Multiplant Impact Study of
River Estuary."
* Texas Instruments, Inc. 80/07/31. 700pp 07459 004.

DOCKETED ITEMS

8101230582 Forwards tabulation of daily record of fish collections for Oct 1980
O'TOOLE, J D Consolidated Edison Co of New York 81/01/13 5pp
07510 279

S Reportable occurrences, LERs & related correspondence

8101090467 Forwards info in response to NRC concerns re 801017 incident of water in containment bldg info, including eight oversize drawings, available in Central Files only Proprietary rept, WCAP-9822, withheld (ref 10CFR2 790).
O'TOOLE, J D Consolidated Edison Co of New York 80/12/22 2pp
07505 212

8101050348 Forwards LER 80-015/03L-0
O'TOOLE, J D Consolidated Edison Co of New York 80/12/29 1p
07385 090

--8101050353 LER 80-015/03L-0 on 801127, setpoint for two low level alarms found 4-ft below min level caused by alarm setpoint drift of level controller & bistable Zener diode in bistable power supply replaced Setpoints reset
MAKEPEACE, J M Consolidated Edison Co of New York 80/12/29 1p 07385 091

8101290355 Responds to request for assistance re Oct 1980 incident. Event did not constitute public health hazard. Particle insp examination of appropriate vessel welds found no indications of cracking
EISENHUT, D G Division of Licensing 80/12/31 2pp 07575 006

8101210102 Forwards responses to 801125 questions re 801017 containment flooding event at facility, investigation rept of event & ltr sent to util forwarding notice of violation & proposed imposition of civil penalties
STELLO, V Director's Office, Office of Inspection and Enforcement 81/01/05 13pp 07491 075

8101210459 RO 81-001/01 review of svc water piping associated w/ containment fan coolers showed return lines from motor coolers are not equipped w/ monitors to detect presence of radioactivity under certain LOCA conditions
MCINT, W A Consolidated Edison Co of New York 81/01/09 3pp
07493 165

8101260374 PND-1-81-05 on 810112, monthly sample of auxiliary boiler condensate return identified 10-5 uCi/ml activity, primarily Cs-134 & Cs-137 Monitor should have detected activity but solenoid valve found closed in sample line
PLUMLEE, A J, WHITE, J J, CROCKER, H W Region 1, Philadelphia, Office of the Director, 81/01/13 2pp 07557 061

8101210434 Forwards LER 81-002/99X-0.
O'TOOLE, J D Consolidated Edison Co of New York 81/01/15 1p
07493 149

--8101210440 LER 81-002/99X-0 on 810106, grid strap damage in form of torn or missing corners found on Westinghouse 1515 (9 grid) fuel assemblies Cause under evaluation Revised LER to be submitted.
MAKEPEACE, J M Consolidated Edison Co of New York 81/01/15 1p 07493 149

8101270654 RO 81-005/01 on 810120, apparent clad perforation found on fuel rod within assembly Cause & corrective actions under evaluation
MCINT, W A Consolidated Edison Co of New York 81/01/20 2pp
07309 001

8101270679 Forwards LER 80-017/03L-0.
O'TOOLE, J D Consolidated Edison Co of New York 81/01/20 1p
07545 227

--8101270689 LER 80-017/03L-0 on 801223, five of first 10 snubbers tested did not meet acceptance criteria for lock-up rate & bleed Cause not stated. Defective snubbers will be replaced Revised LER will be submitted following test completion.
MAKEPEACE, J M Consolidated Edison Co of New York 81/01/20 1p 07183 001

8101270724 Forwards LER 81-001/01T-0
O'TOOLE, J D Consolidated Edison Co of New York 81/01/20 1p
07548 112

I Hearing transcripts on non-antitrust matters

8101120286 Commission determination releasing transcript of 801210 discussion of Indian Point enforcement action
CHILKIS, J Office of the Secretary of the Commission 80/12/11 2pp 07438 132

--8101120288 Marked-up transcript of 801210 closed discussion of Point enforcement action Pp 1-77 Supporting documentation encl.
* Commissioners 80/12/10 67pp 07438 134

V Operator Examinations

8101130364 Responds to NRC 800731 ltr re interim criteria for shift staffing. Training class for add'l licensed reactor operator will start 810202 Interim staffing criteria will be fully met no later than 820701
O'TOOLE, J D Consolidated Edison Co of New York 81/01/07 07454 352

DOCKET 80-249 DRESDEN NUCLEAR POWER STATION, UNIT 3

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FEAR
EISENHUT, D G Division of Licensing 80/11/13 2pp

8101120273 Forwards suppl to fire protection safety evaluation IPFOL110, T A Operating Reactors Branch 2 80/12/02 2pp
07446 325

--8101120276 Suppl to fire protection safety evaluation Capabilities to achieve & maintain safe solution to any fire situation not yet adequately demonstrated
* Office of Nuclear Reactor Regulation, Director 80/12/02 07446 327

O Adjudicatory correspondence

8101090669 Forwards Deviation Disposition Requests 0001696-DD001. Documents prepared per informal discovery agreement, since record of spent fuel pool mods remains open w/o encl.
Related correspondence
FITZ018BONS, R Isham, Lincoln & Seale 81/01/05 1p 07442

H General correspondence

8101290518 Advises that future correspondence should be addressed to IL Dept of Nuclear Safety, 1039 Duter Park Drive, 9th Floor Springfield, IL 62704
WRIGHT, G N Illinois, State of 81/01/22 1p 07566 357

J Insurance & indemnity information

8101090608 Forwards guarantee of payment of deferred premiums for OSTER, J Commonwealth Edison Co 81/01/05 1p

8101270737 Forwards Endorsement 4 to Binders EB-1, EB-2, EB-3, EB-4, EB-30, EB-42 & EB-43 evidencing secondary financial protection
OSTER, J Commonwealth Edison Co 81/01/21 8pp 07309 001

P Operating license stage documents & correspondence

8101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 3 of inservice surveillance requirements for snubbers under STS License amend application adding model Tech Specs to App A should be submitted within 120 days.
EISENHUT, D G Division of Licensing 80/11/20 1p

--8101100271 Revised Pages 3/4 7-22 through 28.8 3/4 7-5 & 7-6 & STS snubber inservice insp requirements.
* Division of Licensing 80/11/20 10pp

DOCKETED ITEMS

B010190113 Ltr to all BWR licensees forwarding B01201 generic safety evaluation re BWR scram discharge sys. Recommends short-term actions necessary to assure safe operation of GE BWRs pending permanent design changes
EISENHUT, D. G. Division of Licensing 80/12/09 2pp

--B010190141 Generic safety evaluation re short-term actions required to assure continued safe operation of operating BWRs Continued operation of plants is acceptable pending permanent design mods. Criteria for implementing design mods encl
* Division of Licensing 80/12/01 212pp 07183 001

B0101070594 Forwards safety evaluation of SEP Topic II-2 A, "Severe Weather Phenomena" & TX Tech Univ rept, "Tornado & Straight Wind Hazard Probability for Dresden Nuclear Power Reactor Site, IL."
CRUTCHFIELD, D. Operating Reactors Branch 5 80/12/15 7pp.
07404:289.

--B0101070608 "Tornado & Straight Wind Hazard Probability for Dresden Nuclear Power Reactor Site, IL."
HCCB:WALD, J. R. Texas Tech Univ NRC-04-76-343 80/05/31 26pp
07404:296.

B0101210445 Forwards responses to questions on Rule 50.71e, "Periodic Updating of FSARs," & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame
EISENHUT, D. O. Division of Licensing 80/12/15 13pp

B0101060946 Submits daily notes for B01223 Status of facilities in five IE regions encl.
DIRCKB, W. J. Office of the Executive Director for Operations.
80/12/24 3pp.

B0101060376 Submits addl response to NRC B00822 ltr Evaluation of Pratt & Whitney butterfly valve demonstrates that loads imposed & stresses developed in components during valve closure under LOCA event fall within acceptable limits
JANECEK, R. F. Commonwealth Edison Co. 80/12/26 2pp 07399:027.

B0101230446 Forwards Amends 52 & 46 to Licenses DPR-19 & DPR-25, respectively, safety evaluation & notice of issuance & availability
CRUTCHFIELD, D. Operating Reactors Branch 5. 80/12/29 2pp
07512:139

--B0101230451 Amends 52 & 46 to Licenses DPR-19 & DPR-25, respectively, authorizing one-time operation for 48-h w/plant chimney monitoring sys out of svc to permit installation of required monitoring improvements.
CRUTCHFIELD, D. Operating Reactors Branch 5. IPPOLITO, T. A. Operating Reactors Branch 2. 80/12/29 6pp 07512:141.

--B0101230453 Safety evaluation supporting Amends 52 & 46 to Licenses DPR-19 & DPR-25, respectively
* Office of Nuclear Reactor Regulation, Director 80/12/29 2pp.
07512:149

--B0101230458 Notice of issuance & availability of Amends 52 & 46 to Licenses DPR-19 & DPR-25, respectively.
CRUTCHFIELD, D. Operating Reactors Branch 5. 80/12/29 2pp.
07512:151

B0101050500 Forwards response to NUREG-0737. No response provided for Dresden 1 Unit undergoing extensive mod & decontamination outage. Requirements of NUREG-0737 will be addressed prior to startup of unit scheduled for June 1986
ABEL, J. B. Commonwealth Edison Co. 80/12/31 55pp 07385:211.

B0101230501 Forwards Amends 54 & 47 to Licenses DPR-19 & DPR-25, respectively, safety evaluation & notice of issuance & availability
CRUTCHFIELD, D. Operating Reactors Branch 5. 80/12/31 3pp.
07512:157.

--B0101230503 Amends 54 & 47 to Licenses DPR-19 & DPR-25, respectively, replacing Tech Spec inservice insp requirements w/program meeting 10CFR 50.55a(g).
CRUTCHFIELD, D. Operating Reactors Branch 5. IPPOLITO, T. A. Operating Reactors Branch 2. 80/12/31 6pp 07512:160.

--B0101230504 Safety evaluation supporting Amends 54 & 47 to Licenses DPR-19 & DPR-25, respectively
* Office of Nuclear Reactor Regulation, Director 80/12/31 16pp 07512:172.

B010300186 "Adequacy of Station Electric Distribution Sys Voltages- Dresden Station, Units 2 & 3"
UDY, A. C. EOLQ Idaho, Inc FIN A-6237 B010300186 80/12/31 11pp 07562 308

B0101090001 Forwards Revision 15 pages to CE-1-A.0A program topical rept. Revisions reflect Summer 1980 addenda to Section III of ASME code & recent ASME survey for renewal of ASME corporate certifications
ABEL, J. B. Commonwealth Edison Co 81/01/02 1p 07441 007

--B0101090005 Revision 15 pages to 0A program topical rept.
* Commonwealth Edison Co CE-1-A R15 81/01/02 57pp
07441 008

B0101300337 Submits schedule for completion of torus attached piping mods. Schedules based upon preliminary engineering analysis completed to date
REED, C. Commonwealth Edison Co 81/01/08 1p. 07455:360

B0101300470 Response to B01114 ltr re alleged water loss from facilities. Belief that no direct unmonitored water has been released from station has been repeatedly confirmed by effluent monitoring program
SCOTT, D. J. Commonwealth Edison Co 81/01/11 3pp 07596 265

B0101300294 Order modifying license & granting extension of exemption. Licensee must reassess suppression pool hydrodynamic loads & complete mods to meet General Design Criterion 50 by 820731
EISENHUT, D. O. Division of Licensing 81/01/13 7pp 07582 159

B0101200296 Advises that scram discharge sys re-evaluation has been completed, in response to NRC B01001 ltr. Necessary mods will be implemented in first refueling outage beginning 820101.
JANECEK, R. F. Commonwealth Edison Co. 81/01/15 2pp 07486 240

B0101260482 Forwards Revision 2 to inservice insp & testing programs, deleting testing requirements for ECCS min flow valves & associated relief request (B-10). Valves are verified to close & open during normal sys surveillance tests
JANECEK, R. F. Commonwealth Edison Co. 81/01/16 10pp 07308 001

B0101220368 Forwards offsite dose calculation sys description per meteorological data requirements in NUREG-0737 Task III A.2
DELGROBE, L. D. Commonwealth Edison Co. 81/01/19 1p 07497 014

--B0101220374 "Offsite Dose Calculation Sys Meteorological Monitoring, Offsite Dose Calculation Program for Emergency Preparedness at Operating Nuclear Power Plants," Revision 2
GOLDEN, J. C. Commonwealth Edison Co. BRACLEY, J. P. Murray & Trettel, Inc LAHTI, O. P. Sargent & Lundy, Inc. 80/07/31 130pp
07497:015

--B0101220379 "Study of Low Level Dispersion Over Northern IL."
* Murray & Trettel, Inc 74/06/30 106pp 07497:159.

B0101260597 Forwards util B01126 revision of facility electrical drawing index & marked-up version of NRC index of drawings. Indices available in Central Files only
JANECEK, R. F. Commonwealth Edison Co 81/01/19 1p. 07519 029.

B0101290786 Ack receipt of B01222 ltr informing NRC of wells to be sampled. Requests environ contractor monthly rept
FISHER, W. L. Region 3, Chicago, Fuel Facility & Materials Safety Branch. 81/01/19 1p 07588 035

--B0101290791 Responds to NRC B01119 ltr re well samples. New samples to begin Jan 1981 & be analyzed for gross alpha, gross beta & tritium
GOLDEN, J. C. Commonwealth Edison Co. 80/12/22 1p 07568:036.

B0101270481 Advises of concurrence w/NUREG-0619 re feedwater nozzles & control rod drive return line nozzle cracking, in response to NRC B01113 ltr. Results of further evaluations will be submitted by B0220
JANECEK, R. F. Commonwealth Edison Co 81/01/22 2pp. 07543:010.

Q. Inspection reports, IE Bulletins & correspondence

B0101050249 Forwards IE Info Notice 80-3B, "Cracking in Charging Pump Casing Cladding." No response required.
KEPPLER, J. Q. Region 3, Chicago, Office of the Director 80/10/30 2pp. 07389:130

B101070113 Forwards IE Insp Repts 50-010/80-21.50-237/80-23 & 50-249/80-27 on 801103-07 & notice of violation.
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/11/25 2pp 07415-011

--B101070118 Notice of violation from insp on 801103-07
* Region 3, Chicago, Office of the Director 80/11/24 1p 07415-013

--B101070125 IE Insp Repts 50-010/80-21.50-237/80-23 & 50-249/80-27 on 801103-07 Noncompliance noted failure to collect weekly cooling water sample
JANUSKA, A G, PHILLIPS, M P, PAPERIELLO, C J Region 3, Chicago, Office of the Director 80/11/24 10pp 07415-014

B101050933 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Steam Discharge Vol at Dresden Unit 2." No response required
KEPPLER, J O Region 3, Chicago, Office of the Director, 80/12/05 2pp 07399-302

B101090778 Forwards IE Insp Repts 50-010/80-22.50-237/80-24 & 50-249/80-28 on 801004-1114 No noncompliance noted.
HEISHAM, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/12/05 2pp 07430-245

--B101090785 IE Insp Repts 50-010/80-22.50-237/80-24 & 50-249/80-28 on 801004-1114 No noncompliance noted. Major areas inspected operational safety verification & monthly maint observation
TONGUE, T H, JORDAN, M J, WALKER, R D Region 3, Chicago, Office of the Director 80/12/05 6pp 07430-247

B101090132 Addl response to FOIA request for documents re imposition of civil penalties. NRC requests for congressional authorization for more severe penalties & responsibilities & behavior of nuclear plant operators Forwards documents listed in app
FELTON, J M Division of Rules and Records 80/12/09 3pp 07441-194

--B101090142 IE Insp Repts 50-237/80-16 & 50-249/80-20 on 800908-10 No noncompliance noted. NRC inspector observed two operators apparently asleep. Lack of operator attentiveness is considered significant safety matter.
PHILLIP, G A, MORELUS, C E, SESSARD, R L Region 3, Chicago, Office of the Director 80/09/29 31pp

--B101090150 Discusses IE policies for reporting, evaluating & documenting significant safety matters, in light of incident at facility. Consideration of safety significance always precedes noncompliance in evaluating any concern. Related info encl
STELLG, V Office of Inspection & Enforcement, Office of the Director, 80/10/01 4pp

--B101090157 Requests to review any IE noncompliance info re 800808 investigation of alleged sleeping control room operators at facility & info re changing NRC requirements to cover operator sleeping on duty
BRADFORD, P A Commissioners 80/10/10 1p

--B101090161 Forwards draft civil penalty package re inattentiveness of operators at facility
KEPPLER, J O Region 3, Chicago, Office of the Director, 80/10/10 3pp

B101050073 Responds to IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Valves V70900-21-1 or VJ3700-21-3 not used in any safety-related functions. Approx 40 manhours expended in bulletin review.
RAUSCH, T J Commonwealth Edison Co 80/12/12 1p 07359-122

B101080260 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Scram Capability." No written response required.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/17 2pp 07420-329

B101130140 EN-80-56 on cr about 801219, notice of violation & notice of proposed imposition of civil penalty in amount of \$4,000 will be issued to licensee. Action based on alleged item of noncompliance re shipment of waste not packaged properly.
HETZGER, J Enforcement Branch 80/12/17 1p

B101150240 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BWR." Written response required.
KEPPLER, J O Region 3, Chicago, Office of the Director, 80/12/18 1p 07465-348

B101050170 Forwards IE Bulletin 80-25, "Operating Problems w/Target Rock Safety Relief Valves at BWRs." No response required.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/15 2pp 07377-301

B101080097 Responds to NRC 800818 request for monthly status rept re evaluations in response to IE Bulletin 79-14 Tabulations of piping sys w/stresses above FSAR levels & below operability limit encl
JANECEK, R F Commonwealth Edison Co 80/12/22 3pp 07421-050

B101200135 Forwards addl response to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Revised initial acceptance allowable for combined piping sys stresses during SSE event provided.
JANECEK, R F Commonwealth Edison Co 81/01/05 6pp 07486-100

B101200155 Forwards response to IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (801017 Indian Point 2 Event)." Surveillance procedures of at least monthly repetition will be instituted by B10501
RAUSCH, T J Commonwealth Edison Co 81/01/05 6pp 07486-202

B101260482 Forwards Revision 2 to inservice insp & testing programs deleting testing requirements for ECCS min flow valves & associated relief request (B-10) Valves are verified to close & open during normal sys surveillance tests
JANECEK, R F Commonwealth Edison Co 81/01/16 10pp

R Periodic operating reports & related correspondence

B101270515 Forwards monthly operating repts for Dec 1980.
SCOTT, D J Commonwealth Edison Co. 81/01/19 1p 07546-279

--B101270520 Monthly operating repts for Dec 1980
MAXWELL, D C Commonwealth Edison Co 81/01/16 16pp 07546-

S Reportable occurrences, LERs & related correspondence

B101200632 Immediate action ltr confirming 801223 telcon re inadvertent repressurization of reactor from cold shutdown conditions on 801220-23. Licensee will complete onsite review to determine safety significance & preventative actions.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/22 2pp 07477-306

B101060469 Forwards LER 80-044/03L-0.
SCOTT, D J Commonwealth Edison Co. 80/12/27 1p 07391-075

--B101060479 LER 80-044/03L-0 on 801215, during hydrostatic test, but found leaking. Caused by concentration cell corrosion. Tubes plugged & leakage stopped
* Commonwealth Edison Co 80/12/29 2pp 07391-096

B101060467 Forwards LER 80-047/01T-0.
SCOTT, D J Commonwealth Edison Co. 80/12/30 1p 07391-090

--B101060471 LER 80-047/01T-0 on 801221, reactor pressure exceeded & primary coolant temp exceeded 212 F w/HPCI sys & isolation condenser out of svc & primary containment integrity broken. Caused by procedural inadequacy.
* Commonwealth Edison Co 80/12/29 4pp 07391-091

B101140620 Forwards LER 80-046/03L-0
SCOTT, D J Commonwealth Edison Co. 81/01/02 1p 07461-101

--B101140623 LER 80-046/03L-0 on 801220, MSIV 3-203-20 did not meet closure time limits. Caused by misadjusted timing mechanism due to leaking hydraulic dashpot. Dashpot repaired, hydraulic oil added & timing adjusted.
SPEROFF, R Commonwealth Edison Co 81/01/02 1p 07461-102

B101210647 Confirms B10105 telcon re B10109 meeting at Region 3 in Elgin, IL. A discuss 801222 event at facility, documented under LER 80-477/01T-0.
KEPPLER, J O Region 3, Chicago, Office of the Director, 81/01/1p 07488-347

B101260570 Forwards LER 80-045/03L-0.
SCOTT, D J Commonwealth Edison Co. 81/01/11 1p 07531-123

--B101260568 LER 80-045/03L-0 on 801219, drywell spray header outboard isolation valve did not close from control room. Probably caused by stuck plunger on closing coil of valve motor breaker. Plunger freed by moving closing coil by hand.
ZIRWAS, K Commonwealth Edison Co. 81/01/17 2pp 07521-100

8101270608 Forwards LER 80-049/03L-0.

SCOTT, D. J. Commonwealth Edison Co 81/01/19 1p 07546 332

--8101270613 LER 80-049/03L-0 on 801225. Unit 3 diesel generator air start regulator valve found blowing air caused by bad seal in air start regulator valve Valve replaced
BADER, S Commonwealth Edison Co 81/01/19 1p 07546 333.

DOCKET 80-250 TURKEY POINT PLANT, UNIT 3

F. Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of PSAR
EISENHUT, D. O. Division of Licensing. 80/11/13 2pp

8101130184 Advises of provisions of 10CFR50, App R, that are applicable to fire protection features of facility FR notice & summary of staff requirements to resolve open items encl
EISENHUT, D. O. Division of Licensing 80/11/24. 6pp. 07452 154

8101120468 Releases public version of util revised emergency plan.
FELTON, J. M. Division of Rules and Records. 80/12/02 1p. 07439 334.

--8101120479 Forwards public version of revised emergency plan for facilities.
WHIRIO, R. E. Florida Power & Light Co 80/02/15 1p. 07439 335

--8101120483 Public version of revised emergency plan for facilities.
* Florida Power & Light Co 80/02/15 23pp. 07439 336

8101190377 Requests response to encl comments from NRC review of util security plan Encl withheld (ref 10CFR2 790).
CLARK, R. A. Operating Reactors Branch 3 80/12/12 2pp. 07474 200

8101140429 Forwards facility emergency planning info to be made publicly available. W/o encl
EQUDEK, J. L. Division of Rules and Records. 80/12/17 1p. 07461 334

8101090392 Advises that response to items re fire protection will be submitted by 810130
WHIRIO, R. E. Florida Power & Light Co. 80/12/30. 1p. 07375 341

8101090453 Forwards security plan info re protected area boundary at facilities info withheld (ref 10CFR2 790).
WHIRIO, R. E. Florida Power & Light Co 80/12/30 1p. 07387 265

G. Adjudicatory correspondence

8101100504 Forwards revised order for mod of licenses correcting refs in 800829 order Hearing date also revised.
EISENHUT, D. O. Division of Licensing 80/09/19 3pp. 07444 263

--8101100519 Revised order amending Licenses DPR-31 & DPR-41 info requested by IE Bulletin 79-01B must be submitted to IE by 801101.
EISENHUT, D. O. Division of Licensing. 80/09/19 6pp. 07444 265

8101090001 Response interposing no objection to motion received 801212 to permit intervenor & designated experts to enter site.
Certificate of Svc encl
GOLDBERG, S. C. Hearing Branch 2. 80/12/29. 3pp 07377 355.

8101140886 Confirms 810107 telcon re preliminary informal conference to discuss facility repairs & schedule for proceedings on proposed amendments to OLA Proposed schedule & Certificate of Svc encl.
COLL, N. A. Florida Power & Light Co. COLL, N. A. Steel, Hector & Davis 81/01/00. 3pp. 07490 222.

8101230622 Directs parties to try to resolve differences re proposed site visit, record review conference & rept conference results to ASLB Board agree w/ rules of reason in ASLB 000623 order.
BOWERS, E. S. Atomic Safety and Licensing Board Panel. 81/01/13 1p 07512 274

encl. Related correspondence
COLL, N. A. Steel, Hector & Davis. 81/01/16 3pp 07529 230

8101260354 Requests on behalf of MP Oncoverage, 20-day extension within which to comment on draft EIS Comments to be submitted by 810317

CHENIN, H. Chonin, N. 81/01/21 2pp. 07525 145

J. Insurance & indemnity information

8101090478 Forwards Endorsement 34 to ANI Policy NF-183
FIELDER, J. Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc Div 80/12/30 3pp 07442 299

8101090971 Forwards Endorsements 4 to ANI Binders EB-25 & EB-26. Endorsement to Binder EB-25 only encl
FIELDER, J. Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc Div 80/12/30 2pp 07427 349

8101090481 Forwards Endorsement 53 to ANI Policy NF-185
FIELDER, J. Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc Div 80/12/31 2pp 07442 297

P. Operating license stage documents & correspondence

8101100504 Forwards revised order for mod of licenses correcting refs in 800829 order Hearing date also revised
EISENHUT, D. O. Division of Licensing 80/09/19 3pp 07444 263

--8101100519 Revised order amending Licenses DPR-31 & DPR-41 info requested by IE Bulletin 79-01B must be submitted to IE by 801101
EISENHUT, D. O. Division of Licensing 80/09/19 6pp. 07444 265

8101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under 81B License amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT, D. O. Division of Licensing. 80/11/20 1p

--8101100271 Revised Pages 3/4 7-22 through 20.8 3/4 7-5 & 7-6 & 6-17 81B snubber inservice insp requirements
* Division of Licensing 80/11/20 10pp

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D. O. Division of Licensing. 80/11/26 8pp.

8101140854 Forwards "Assessment of Impacts of Steam Generator Repair Program at Turkey Point Plant on Threatened or Endangered Species".
VARGA, S. A. Operating Reactors Branch 1 80/12/12. 3pp 07457 322

--8101140863 "Assessment of Impacts of Steam Generator Repair Program at Turkey Point Plant on Threatened or Endangered Species"
HABNIK, M. T. Environmental Engineering Branch. 80/11/30. 21pp 07457 328

8101210445 Forwards responses to questions on Rule 50.71e, "Periodic Updating of PSARs" & FR notice of final rule SEP plants need not comply w/ rule until program is complete. Non-SEP plants must comply within specified time frame
EISENHUT, D. O. Division of Licensing 80/12/15. 13pp

8101140679 Forwards DES safety evaluation & FR notice re steam generator repair at facility
VARGA, S. A. Operating Reactors Branch 1 80/12/18. 2pp. 07462 02

--8101190397 Notice of availability of NUREG-0743, DES re steam generator repair at facilities
VARGA, S. A. Operating Reactors Branch 1 80/12/18 2pp. 07472 176.

---8101190408 SAFETY EVALUATION REPORT RELATED TO STEAM GENERATOR REPAIR AT TURKEY POINT PLANT UNITS 3 AND 4
* Office of Nuclear Reactor Regulation, Director NUREG-0756 80/12/31. 46pp Available at NTIS 63 25 07472 237

8101140916 Forwards list of DES documentation W/o encl.
VARGA, S. A. Operating Reactors Branch 1. 80/12/18 7pp 07398 00

generator repair Requests concept w/o encs
VARQA.S A Operating Reactors Branch 1 80/12/18 3pp 07491:099

B101230522 Forwards DES safety evaluation rept & notice of DES issuance re steam generator repair at facilities
VARQA.S A Licensing Branch 1 80/12/18 2pp 07512 219

--B101230524 Notice of availability of DES re steam generator repair at facilities
VARQA.S A Licensing Branch 1 80/12/18 2pp 07512 221.

B101300223 Forwards Amends 62 & 53 to Licenses DPR-31 & DPR-41, respectively, safety evaluation & EIA & notice of issuance & availability
VARQA.S A Operating Reactors Branch 1. 80/12/19 2pp 07582 322

--B101300237 Amends 62 & 53 to Licenses DPR-31 & DPR-41, respectively, deleting fuel residence time limit from Tech Specs, App A to licenses
VARQA.S A Operating Reactors Branch 1 80/12/19 12pp 07582 324

--B101300250 Safety evaluation & EIA supporting Amends 62 & 53 to Licenses DPR-31 & DPR-41, respectively
* Office of Nuclear Reactor Regulation, Director 80/12/19 3pp 07582:337

--B101300261 Notice of issuance & availability & negative declaration of Amends 62 & 53 to Licenses DPR-31 & DPR-41
VARQA.S A Operating Reactors Branch 1 80/12/19 1p 07582 340

B101050019 Verifies 801219 filing of EIS re steam generator repair Notice of availability scheduled for 801224 FR publication
Public review period ends on 810223
HILBORN, K L Environmental Protection Agency 80/12/22 1p 07385:266

B101140205 Confirms actions discussed in 801223 telcon re low level radioactively contaminated earth at site Site evaluation will be performed to identify & quantify all contaminated areas
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/23 2pp 07461 253

B101050338 Forwards response to 801031 ltr re NUREG-0737 implementation status of post-FMI requirements
WHRIO.R E Florida Power & Light Co 80/12/26 7pp 07376 218

B101060297 Forwards proposed amend to App A of Licenses DPR-31 & DPR-41, to provide for redundancy in decay heat removal sys for all modes of reactor operation, in response to NRC BDD411 request
WHRIO.R E Florida Power & Light Co 80/12/30 2pp 07399 036

--B101060303 Proposed Tech Specs providing for redundancy in decay heat removal sys for all modes of reactor operation.
* Florida Power & Light Co 80/12/30 10pp 07399 038

B101190339 Forwards list of TLD station locations near facility & proposed route for exchanging TLDs for NRC direct radiation monitoring network w/o encs.
STCHER, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/12/30 2pp 07476 087.

B101060309 Application to amend Licenses DPR-31 & DPR-41, moving one sample location from onsite location T79 to onsite location T72, due to high potential for oil contamination at old location
WHRIO.R E Florida Power & Light Co. 80/12/31 1p 07399:031

--B101060311 Proposed environ Tech Spec Table 4.12-1, Sheet 1 Util safety evaluation & sampling location map encl
* Florida Power & Light Co. 80/12/31 4pp 07399:032

B101060206 Forwards responses to NUREG-0737 re shift technical advisor & ECCS outages per 801031 ltr Rept re improving emergency preparedness long-term to be submitted separately.
WHRIO.R E Florida Power & Light Co. 81/01/02 22pp 07396:181.

B101120421 Act receipt of draft environ impact documentation for facilities.
COYNER, M L. Agriculture, Dept of. 81/01/05 1p 07449 349

B101220150 Submits info re proposed undervoltage protection sys design, acc. in response to NRC B00818 ltr Two OE Type IAV undervoltage relays will be installed on each 4160 V bus. Proposed Tech Specs will be submitted upon completion
WHRIO.R E Florida Power & Light Co 81/01/14 2pp 07495 236

B101230428 Forwards "Auxiliary Feedwater Pumps Endurance Test." per NRC B00939 ltr
WHRIO.R E Florida Power & Light Co. 81/01/14 1p 07308 001

--B101230430 "Auxiliary Feedwater Pumps Endurance Test"
* Florida Power & Light Co 81-80-04. 81/01/14. 31pp 07308 001

B101210380 Agrees w/NRC B01212 biological assessment that facility repair program will not adversely impact threatened or endangered species No definite decision has been made for onsite burial of spent resin.
PETERSON, B W Interior, Dept of. Fish & Wildlife Service 81/01/19 2pp 07489:070.

B101230558 Forwards BNWL 801212 ltr re steam generator repair program Requests placement in docket files info forms basis for conclusions reached in review of facility steam generator repair program
GROTHENHUIS, M Operating Reactors Branch 1. 81/01/21 1p 07308 001

--B101230566 Submits info in response to 801126 & 1202 telcons re potential drop of steam generator & subsequent release of radioactive gas Release of radioactivity would be less than 10% Forwards article on deposits in primary sys.
MOENES, O R Battelle Memorial Institute, Pacific Northwest Laboratory. 80/12/12. 7pp 07308 001

B101290452 Comments on DES re steam generator repair, per NRC B01218 request No significant impacts to electric power, natural gas or oil pipeline industries
HEINENHAW, J M Federal Energy Regulatory Commission. 81/01/21 1p 0756B 360

0 Inspection reports, IE Bulletins & correspondence

B012160019 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2" No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director. 00/10/24 1p 07261:179.

B101080206 Forwards IE Insp Repts 50-250/80-30 & 50-251/80-30 on 800925-26 No noncompliance noted.
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/11/17 2pp 07421:035.

--B101080210 IE Insp Repts 50-250/80-30 & 50-251/80-30 on 800925-26 No noncompliance noted Major areas inspected: emergency planning drill observation & previously identified items.
QIBSON, O T Region 2, Atlanta, Office of the Director.
JENKINS, C R Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/11/10 4pp 07421:037

B101090124 Requests existing data, summaries & records of inservice tests of containments w/greased prestressing tendons
ORNL receiving contract to compile & review records of tendons.
EISENHUT, D O Division of Licensing. 80/11/25 3pp.

B101100829 Forwards IE Insp Repts 50-250/80-29 & 50-251/80-28 on 801021-24 No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/11/28 2pp 07443:247.

--B101100834 IE Insp Repts 50-250/80-29 & 50-251/80-28 on 801021-24 noncompliance noted Major areas inspected: IE Bulletin 80-11 followup & containment bldg tendon surveillance insp program.
LENAHAN, J J Region 2, Atlanta, Office of the Director.
COMLON, T E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/11/17 5pp 07443:249.

B101140108 Forwards IE Insp Rept 50-250/80-34 on 801113-14 No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/12/02 2pp 07460:315

--B101140113 IE Insp Rept 50-250/80-34 on B01113-14 No noncompliance noted. Major areas inspected IE Bulletin 79-13 re feedwater line repairs
CROWLEY, B R Region 2, Atlanta, Office of the Director
HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch, 80/11/26 4pp 07460 317

B101140036 Submits B01210 daily staff notes IE informs of concrete block wall deviations at Farley 2 & breach of radioactive package integrity at Turkey Point 3 & 4 Plant status encl
DIRCKS, W J. Office of the Executive Director for Operations.
80/12/11 3pp. 07460 252

B101140608 Requests extension until B10130 to respond to IE Bulletin B0-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Add time needed to contact all suppliers.
UHRIO, R E Florida Power & Light Co. 80/12/11 2pp 07462 010

B101150125 Responds to IE Bulletin 80-23 Facilities do not use Valcor solenoid valves w/Part Numbers V70900-21-1 & 21-3
UHRIO, R E Florida Power & Light Co 80/12/17 1p 07462 190

B101190330 Forwards response to IE Bulletin 80-08 re containment liner penetration weld examination Defects Found in welds have been repaired & re-examined Table of nondestructive examination results encl
UHRIO, R E Florida Power & Light Co 80/12/30 15pp 07475 223

B101210208 Responds to IE Bulletin 80-24 re water damage inside containment. Current sys configuration combined w/NUREG-0578 implementation provides assurance that component cooling water leaks will be detected & minimized
UHRIO, R E Florida Power & Light Co 81/01/07 3pp. 07488 014

B101290557 Act receipt of B10109 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-250/80-19 & 50-231/80-20
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 81/01/13 1p 07575 277

R Periodic operating reports & related correspondence

B101210414 Forwards monthly operating repts for Dec 1980.
SCHMIDT, A D Florida Power & Light Co 81/01/10 1p. 07493 132.

--B101210418 Monthly operating repts for Dec 1980
CHILSON, V T Florida Power & Light Co 81/01/10 3pp
07493 133.

B101210425 Forwards monthly operating repts for Dec 1980
SCHMIDT, A. D. Florida Power & Light Co 81/01/10 1p. 07493 136.

--B101210429 Monthly operating repts for Dec 1980
CHILSON, V T Florida Power & Light Co 81/01/10 9pp.
07493 137

9 Reportable occurrences, LERs & related correspondence

B101050324 Forwards LER B0-021/03L-0
SCHMIDT, A D Florida Power & Light Co 80/11/28 1p. 07379 303.

--B101050342 LER B0-021/03L-0 on B01101, seismograph found inoperable following initial successful calibr check. Caused by batteries discharged by electrical problem in seismograph. Assembly returned to manufacturer for expedited repair
PACE, P. L. Florida Power & Light Co 80/11/28 1p 07379 304

B101050484 Forwards LER B0-022/03L-0
SCHMIDT, A D Florida Power & Light Co 80/12/03 1p. 07378 356

--B101050542 LER B0-022/03L-0 on B01103, control rod M-B (in control bank D) dropped during power operation. Cause unknown Rod retrieved & unit returned to full power per approved procedures.
PACE, P. L. Florida Power & Light Co. 80/12/03 1p. 07378 357.

B101050360 Forwards LER B0-023/03L-0.
SCHMIDT, A D Florida Power & Light Co. 80/12/08 1p. 07389 298

--B101050363 LER B0-023/03L-0 on B01108, surveillance check of refueling water storage tank level was not completed within required time interval. Caused by personnel error resulting in missed entry on check list Personnel have been retrained.
PACE, P. L. Florida Power & Light Co. 80/12/08 1p. 07389 299.

B101130325 Forwards LER B0-025/01T-0
SCHMIDT, A D Florida Power & Light Co. 80/12/15 1p. 07451 357

--B101130334 LER B0-025/01T-0 on B01203, AE advised that insp per IE Bulletin 79-14 revealed potential deficiency in support of accumulator nozzles JA & JB during seismic event Caused by max stress exceeding acceptance criteria
PACE, P L Florida Power & Light Co 80/12/15 2pp. 07451 358

B101130348 Forwards LER B0-026/01T-0
SCHMIDT, A D Florida Power & Light Co 80/12/23 1p 07452 16

--B101130377 LER B0-026/01T-0 on B01211, 125-volt dc battery AB out for approx 25-h Caused by servicing for annual discharge test Battery returned to full charge
PACE, P L Florida Power & Light Co 80/12/23 1p 07452 05

B101130393 Forwards LER B0-027/01T-0
SCHMIDT, A D Florida Power & Light Co 80/12/23 1p 07452 18

--B101130392 LER B0-027/01T-0 on B01212, motor operated valve in steam line from steam generator JA found closed, precluding generator monitoring Caused by valve operator inadvertently closing valve during maint
PACE, P L Florida Power & Light Co. 80/12/23 1p 07452 07

DOCKET 50-251 TURKEY POINT PLANT, UNIT 4

F Security, radical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of PSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

B101130184 Advises of provisions of 10CFR50, App R, that are applicable to fire protection features of Facility. FR notice & summary of staff requirements to resolve open items encl
EISENHUT, D O Division of Licensing 80/11/24 6pp 07452 15

B101120460 Releases public version of util revised emergency plan
FELTON, J H Division of Rules and Records 80/12/02 1p
07435 334

--B101120479 Forwards public version of revised emergency plan for facilities
UHRIO, R E Florida Power & Light Co 80/02/15 1p. 07435 10

--B101120403 Public version of revised emergency plan for facilities
Florida Power & Light Co 80/02/15 23pp 07435 336.

B101190377 Requests response to encl comments from NRC review of security plan Encl withheld (ref 10CFR2 790).
CLARK, R A Operating Reactors Branch 3 80/12/12 2pp 07474

B101140429 Forwards facility emergency planning info to be made publicly available w/o encl
BOUDER, J. L. Division of Rules and Records. 80/12/17 1p
07461 334

B101050392 Advises that response to items re fire protection will be submitted by B10130.
UHRIO, R E Florida Power & Light Co. 80/12/30 1p. 07375 341

B101050453 Forwards security plan info re protected area boundary facilities info withheld (ref 10CFR2 790)
UHRIO, R E Florida Power & Light Co. 80/12/30 1p. 07387 245

0 Adjudicatory correspondence

B101100504 Forwards revised order for mod of licenses correcting r in B00829 order Hearing date also revised.
EISENHUT, D O Division of Licensing, 80/09/19 3pp.

--B101100519 Revised order amending Licenses DPR-31 & DPR-41 info requested by IE Bulletin 79-01B must be submitted to IE by B01101.
EISENHUT, D O Division of Licensing 80/09/19 6pp

B101050001 Response interposing no objection to motion received B0 to permit intervenor & designated experts to enter site Certificate of Svc encl.
GOLDBERG, S C Hearing Branch 2 80/12/29 3pp. 07377 359

8101140896 Confirms 810107 telcon re preliminary informal conference to discuss facility repairs & schedule for proceedings on proposed Amends to DLS Proposed schedule & Certificate of Svc encl
COLL.N.A Florida Power & Light Co COLL.N.A Steel, Hector & Davis 81/01/03 3pp 07458 222

8101230622 Directs parties to try to resolve differences re proposed site visit, record review conference & rept conference results to ASLB Board agrees w/rule of reason in ASLB 800623 order
BOKERB.E.S Atomic Safety and Licensing Board Panel 81/01/13 1p 07512 274

8101260503 Forwards ASLB 800723 order re steam generator repair proceedings per 810113 order Certificate of Svc encl W/o encl Related correspondence
COLL.N.A Steel, Hector & Davis 81/01/16 3pp 07529 230

8101260554 Requests on behalf of KP Encavage, 20-day extension within which to comment on draft EIS. Comments to be submitted by 810317
CHENH.M.N Chen, H. 81/01/21 2pp 07523 149

J Insurance & Indemnity Information

8101090478 Forwards Endorsement 54 to ANI Policy NF-189
FIELDER, J Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc Div. 80/12/30 3pp 07442 259

8101090571 Forwards Endorsements 4 to ANI Binders EB-25 & EB-26 Endorsement to Binder EB-25 only encl
FIELDER, J Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc Div 80/12/30 2pp 07427 349

8101090481 Forwards Endorsement 53 to ANI Policy NF-185.
FIELDER, J Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc Div. 80/12/31 2pp 07442 257

P. Operating license stage documents & correspondence

8101100304 Forwards revised order for ncs of licenses correcting refs in 800829 order Hearing date also revised.
EISENHUT.D.G Division of Licensing 80/09/19 3pp 07444 263

--8101100319 Revised order amending Licenses DPR-31 & DPR-41. Info requested by IE Bulletin 79-018 must be submitted to IE by 810110
EISENHUT.D.G Division of Licensing 80/09/19 6pp 07444 265

8101100234 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under STB License Amend application adding model Tech Spec 4 to App A should be submitted within 120 days
EISENHUT.D.G Division of Licensing. 80/11/20 1p

--8101100271 Revised Pages 3/4 7-22 through 28.0 3/4 7-5 & 7-6 & 6-17 to STB snubber inservice insp requirements
* Division of Licensing 80/11/20 10pp

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issues A-12, "Potential for Low Fracture Toughness & Lateral Tearing on Component Supports."
EISENHUT.D.G Division of Licensing 80/11/26 8pp

8101140894 Forwards "Assessment of Impacts of Steam Generator Repair Program at Turkey Point Plant on Threatened or Endangered Species"
VARQA.S.A Operating Reactors Branch 1 80/12/12 3pp 07457 325

--8101140853 "Assessment of Impacts of Steam Generator Repair Program at Turkey Point Plant on Threatened or Endangered Species"
HAGNIK.M.T Environmental Engineering Branch 80/11/30 21pp 07457 328

8101210443 Forwards responses to questions on Rule 50.71c. "Periodic Updating of FSARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame
EISENHUT.D.G Division of Licensing 80/12/13 13pp

8101140679 Forwards DES safety evaluation & FR notice re steam generator repair at facility
VARQA.S.A Operating Reactors Branch 1 80/12/18 2pp 07462 062

--8101190397 Notice of availability of NUREO-0743, DES re repair at facilities
VARQA.S.A Operating Reactors Branch 1 80/12/18 07472 176

--8101190408 SAFETY EVALUATION REPORT RELATED TO STEAM GENERATOR AT TURKEY POINT PLANT UNITS 3 AND 4
* Office of Nuclear Reactor Regulation, Director 80/12/31 46pp Available at NTIS \$3.25 07472 2

8101140916 Forwards list of DES documentation W/o encl
VARQA.S.A Operating Reactors Branch 1 80/12/18 7p

8101210069 Forwards notice of availability of NUREO-0743, steam generator repair at facilities
VARQA.S.A Operating Reactors Branch 1 80/12/18 1p

8101210126 Forwards NUREO-0743 & NUREO-0756 re facility generator repair Requests comment W/o encl
VARQA.S.A Operating Reactors Branch 1 80/12/18 3p

8101230522 Forwards DES safety evaluation rept & notice re steam generator repair at facilities.
VARQA.S.A Licensing Branch 1 80/12/18 2pp 07512 274

--8101230524 Notice of availability of DES re steam generator repair at facilities
VARQA.S.A Licensing Branch 1 80/12/18 2pp 07512 274

8101300223 Forwards Amends 62 & 53 to Licenses DPR-31 & DPR-41, respectively, safety evaluation & EIA & notice of issuance of licenses
VARQA.S.A Operating Reactors Branch 1 80/12/19 2p

--8101300239 Amends 62 & 53 to Licenses DPR-31 & DPR-41, deleting Fuel residence time limit from Tech Specs, A & B
VARQA.S.A Operating Reactors Branch 1 80/12/19 07582 324

--8101300250 Safety evaluation & EIA supporting Amends 62 & 53 to Licenses DPR-31 & DPR-41, respectively
* Office of Nuclear Reactor Regulation, Director 07582 337

--8101300261 Notice of issuance & availability & negative impact of Amends 62 & 53 to Licenses DPR-31 & DPR-41
VARQA.S.A Operating Reactors Branch 1 80/12/19 07582 340

8101050019 Verifies 801219 filing of EIS re steam generator repair at facilities
Notice of availability scheduled for 801224 FR public hearing. Public review period ends on 810223.
WILSON, K.L. Environmental Protection Agency 80/12/20 07385 266

8101140205 Confirms actions discussed in 801223 telcon re radioactively contaminated earth at site Site evaluation will be performed to identify & quantify all contaminated areas
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 2pp 07461 253

8101050038 Forwards response to 801031 ltr re NUREO-0731 status of post-TMI requirements
WRIGHT, R.E. Florida Power & Light Co. 80/12/26 7pp

8101060297 Forwards proposed amend to App A of Licenses DPR-31, to provide for redundancy in decay heat removal for all modes of reactor operation, in response to NRC request.
WRIGHT, R.E. Florida Power & Light Co. 80/12/30 2pp

--8101060303 Proposed Tech Spec providing for redundancy in decay heat removal for all modes of reactor operation
* Florida Power & Light Co 80/12/30 10pp 07582 337

8101190339 Forwards list of TLD station locations near proposed route for exchanging TLDs for NRC direct radiation monitoring network W/o encl
STOHR, J.P. Region 2, Atlanta, Fuel Facility & Materials Branch. 80/12/30 2pp 07476 087

8101060304 Application to amend Licenses DPR-31 & DPR-41 sample location from onsite location T79 to onsite location T72, due to high potential for oil contamination at location
WRIGHT, R.E. Florida Power & Light Co. 80/12/31 1p

--B01060311 Proposed environ Tech Spec Table 4 12-1, Sheet 1 Util safety evaluation & sampling location map encl
* Florida Power & Light Co. 80/12/31. 4pp 07399 032

B01060286 Forwards responses to NUREG-0737 re shift technical advisor & ECCB outages per B01031 ltr Rept re improving emergency preparedness long-term to be submitted separately
UHRIO, R E Florida Power & Light Co. 81/01/02 22pp 07396 181

B01120421 Ack receipt of draft environ impact documentation for facilities
COTNER, H L. Agriculture, Dept. of. 81/01/05. 1p 07445 349.

B01210345 Advises that no historical sites will be affected by steam generator repair in response to B01218 cultural resource assessment request
PERCY, O W Florida, State of 81/01/09 1p 07490 118

B01220150 Submits info re proposed undervoltage protection sys design mod. in response to NRC B00818 ltr. Two OE Type IAW undervoltage relays will be installed on each 4160 V bus
Proposed Tech Specs will be submitted upon completion
UHRIO, R E Florida Power & Light Co. 81/01/14. 2pp. 07495 236.

B01230428 Forwards "Auxiliary Feedwater Pumps Endurance Test." per NRC B00530 ltr.
UHRIO, R E Florida Power & Light Co. 81/01/14 1p. 07308 001

--B01230430 "Auxiliary Feedwater Pumps Endurance Test."
* Florida Power & Light Co. 81-00-04. 81/01/14. 31pp.
07308 001

B01210380 Agrees w/NRC B01212 biological assessment that facility repair program will not adversely impact threatened or endangered species. No definite decision has been made for onsite burial of spent resin
PETERSON, D W Interior, Dept of, Fish & Wildlife Service 81/01/15 2pp. 07409 070

B01300406 Forwards Amend 54 to License DPR-41, safety evaluation & notice of issuance & availability.
VARQA, S A Operating Reactors Branch 1. 81/01/15 2pp 07383 301

--B01300491 Amend 54 to License DPR-41, permitting continued operation of Unit 4 for six equivalent months of operation from B01013, at which time steam generator shall be inspected.
VARQA, S A Operating Reactors Branch 1 81/01/15 3pp.
07383 303

--B01300495 Safety evaluation supporting Amend 54 to License DPR-41.
* Office of Nuclear Reactor Regulation, Director. 81/01/15. 7pp.
07383 308.

--B01300499 Notice of issuance & availability of Amend 54 to License DPR-41.
VARQA, S A Operating Reactors Branch 1 81/01/15. 2pp
07383 315

B01230558 Forwards BNWL B01212 ltr re steam generator repair program Requests placement in docket files info forms basis for conclusions reached in review of facility steam generator repair program
GROTE, N U B M Operating Reactors Branch 1 81/01/21 1p
07308 001.

--B01230566 Submits info in response to B01126 & 1202 telcons re potential drop of steam generator & subsequent release of radioactive mat. Release of radioactivity would be less than 10% Forwards article on deposits in primary sys.
HOENES, O R Battelle Memorial Institute, Pacific Northwest Laboratory. 80/12/12 7pp. 07308 001.

B01290452 Comments on DES re steam generator repair, per NRC B01218 request. No significant impacts to electric power, natural gas or oil pipeline industries.
IEINEMANN, J M Federal Energy Regulatory Commission. 81/01/21. 1p.
07568 360.

Q Inspection reports, IE Bulletins & correspondence

B012160019 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2." No written response required.
D'REILLY, J P. Region 2, Atlanta, Office of the Director. 80/10/24 1p. 07261 179

B01030206 Forwards IE Insp Repts 80-250/80-30 & 80-251/80-30 on B00925-26 No noncompliance noted
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/11/17 2pp 07421 035

--B01080210 IE Insp Repts 80-250/80-30 & 80-251/80-30 on B00925-26 No noncompliance noted Major areas inspected emergency planning drill observation & previously identified items
O'BROU, L O T Region 2, Atlanta, Office of the Director
JERKINS, O R Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/11/10 4pp 07421 037

B01050124 Requests existing data, summaries & records of inservice insp tests of containments w/grossed prestressing tendons
ORCA, receiving contract to compile & review records of tendons
EISENHART, D W Division of Licensing 80/11/25 3pp

B010100829 Forwards IE Insp Repts 80-250/80-29 & 80-251/80-28 on B01021-24 No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/28 2pp 07443 247

--B010100834 IE Insp Repts 80-250/80-29 & 80-251/80-28 on B01021-24 No noncompliance noted Major areas inspected IE Bulletin 80-11 followup & containment bldg tendon surveillance insp program
LENAHAN, J J Region 2, Atlanta, Office of the Director.
CUNLON, T E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/17 3pp 07443 249.

B01140036 Submits B01210 daily staff notes. IE informs of concrete block wall deviations at Ferry 2 & breach of radwaste package integrity at Turkey Point 3 & 4 Plant status encl.
DIRCKE, W J. Office of the Executive Director for Operations 80/12/11 3pp 07460 252

B01140600 Requests extension until B01030 to respond to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc."
Addl time needed to contact all suppliers
UHRIO, R E Florida Power & Light Co. 80/12/11 2pp 07462 010

B01150125 Responds to IE Bulletin 80-23 Facilities do not use Valcor solenoid valves w/Part Numbers V70900-21-1 & 21-3.
UHRIO, R E Florida Power & Light Co. 80/12/17. 1p 07462 190

B01190350 Forwards response to IE Bulletin 80-08 re containment liner penetration void examination Defects found in voids have been repaired & re-examined Table of nondestructive examination results encl
UHRIO, R E. Florida Power & Light Co. 80/12/30 15pp 07479 243

B01210200 Responds to IE Bulletin 80-24 re water damage inside containment Current sys configuration combined w/NUREG-0578 implementation provides assurance that component cooling water leaks will be detected & minimized
UHRIO, R E Florida Power & Light Co. 81/01/07. 3pp 07488 014.

B01290557 Ack receipt of B01019 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 80-250/80-19 & 80-251/80-20
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 81/01/13 1p. 07575 277

R Periodic operating reports & related correspondence

B01210414 Forwards monthly operating repts for Dec 1980.
SCHMIDT, A D Florida Power & Light Co. 81/01/10. 1p. 07493 132.

--B01210418 Monthly operating repts for Dec 1980
CHILSDON, V T Florida Power & Light Co. 81/01/10 3pp.
07493 132.

B01210425 Forwards monthly operating repts for Dec 1980.
SCHMIDT, A D Florida Power & Light Co. 81/01/10 1p 07493 136.

--B01210429 Monthly operating repts for Dec 1980
CHILSDON, V T Florida Power & Light Co. 81/01/10 9pp.
07493 137.

S Reportable occurrences, LERs & related correspondence

B01050460 Forwards LER 80-014/01T-O.
SCHMIDT, A D Florida Power & Light Co. 80/12/10 1p 07309 001.

--B101050534 LER E0-014/011-0 on B01126, insp per IE Bulletin 79-14 revealed deficiency in portions of accumulator & RHR sys piping inside containment. Calculated max stress exceeded criteria. Mod will be made before unit returns to svc.
PACE, P. L. Florida Power & Light Co. 80/12/10 2pp. 07309 001

B101050390 Forwards LER 80-013/03L-0
SCHWARTZ, A. D. Florida Power & Light Co. 80/12/11 1p. 07309:001

--B101050547 LER 80-013/03L-0 on B01111, six of ten ionization type detectors found inoperable during test on fire detection sys. Caused by corrosion of both detector base terminals & outer chamber of type D18-3/5A detector head.
PACE, P. L. Florida Power & Light Co. 80/12/11 1p. 07309 001.

COCKET 50-254 QUAD-CITIES STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR.
EISENHUT, D. G. Division of Licensing 80/11/13 2pp.

H. General correspondence

B101290518 Advises that future correspondence should be addressed to IL Dept of Nuclear Safety, 1035 Outer Park Drive, 5th Floor Springfield, IL 62704
WRIGHT, G. N. Illinois, State of. 81/01/22 1p

J. Insurance & indemnity information

B101090603 Forwards guarantee of payment of deferred premiums for 1980
OSTER, J. Commonwealth Edison Co. 81/01/05 1p

B101270614 Forwards Endorsements 125 & 126.65 & 66.53 & 54. & 13 & 14 to NELA Policies NF-43, NF-187, NF-201 & NF-283, respectively.
OSTER, J. Commonwealth Edison Co. 81/01/21. 13pp. 07183:001

B101270737 Forwards Endorsement 4 to Sincere EB-1, EB-2, EB-3, EB-29, EB-30, EB-42 & EB-43 evidencing secondary financial protection.
OSTER, J. Commonwealth Edison Co. 81/01/21 8pp.

P. Operating license stage documents & correspondence

B101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for submittal under B15 License Amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT, D. G. Division of Licensing. 80/11/20. 1p

--B101100271 Revised Pages 3/4 7-22 through 28.B 3/4 7-5 & 7-6 & 6-17 to B15 snubber inservice insp requirements.
* Division of Licensing 80/11/20 10pp

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 testing re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lateral Tearing on Component Supports"
EISENHUT, D. G. Division of Licensing. 80/11/26 8pp

B101190113 Ltr to all BWR licensees forwarding B01201 generic safety evaluation re BWR scram discharge sys. Recommends short-term actions necessary to assure safe operation of GE BWRs pending permanent design changes.
EISENHUT, D. G. Division of Licensing 80/12/09. 2pp.

--B101190141 Generic safety evaluation re short-term actions required to assure continued safe operation of operating BWRs. Continued operation of plants is acceptable pending permanent design mods. Criteria for implementing design mods encl.
* Division of Licensing 80/12/01 212pp. 07183.001

B101210445 Forwards responses to questions on Rule 50.71e, "Periodic Updating of FSARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete. Non-SEP plants must comply within specified time frame.
EISENHUT, D. G. Division of Licensing 80/12/15 13pp.

B101050376 Submits addl response to NRC B00822 ltr Evaluation of Pratt & Whitney butterfly valve demonstrates that loads imposed & stresses developed in components during valve closure under LOCA event fall within acceptable limits
JANECEK, R. F. Commonwealth Edison Co. 80/12/26. 2pp. 07399:027.

B101050500 Forwards response to NUREG-0737 No response. Dresden 1 Unit undergoing extensive mod & decontamination. Outage Requirements of NUREG-0737 will be addressed prior to startup of unit scheduled for June 1985
ABEL, J. S. Commonwealth Edison Co. 80/12/31 55pp

B101300154 "Adequacy of Station Electric Distribution for Quad Cities Units 1 & 2"
LDV, A. C. EGB Idaho, Inc. FIN A-6236 B101300154 07583 114

B101090001 Forwards Revision 15 pages to CE-1-A, QA program. Revisions reflect Summer 1980 addenda to Section ASME code & recent ASME survey for renewal of ASME corporate certifications
ABEL, J. B. Commonwealth Edison Co. 81/01/02 1p

--B101090005 Revision 15 pages to QA program topical re
* Commonwealth Edison Co. CE-1-A R15. 81/01/02

B101300337 Submits schedule for completion of torus attachment. Schedules based upon preliminary engineering mod completed to date.
REED, C. Commonwealth Edison Co. 81/01/08 1p. 074

B101200296 Advises that scram discharge sys re-evaluation completed in response to NRC B01001 ltr. Necessary mod to be implemented in first refueling outage beginning B2
JANECEK, R. F. Commonwealth Edison Co. 81/01/15 2pp

B101220368 Forwards offsite dose calculation sys description meteorological data requirements in NUREG-0737 Task III A 2
DELGEORGE, L. D. Commonwealth Edison Co. 81/01/19 1

--B101220374 "Offsite Dose Calculation Sys. Meteorologic Offsite Dose Calculation Program for Emergency Prep at Operating Nuclear Power Plants," Revision 2.
GOLDEN, J. C. Commonwealth Edison Co. 80/07/31. 12

--B101220379 "Study of Low Level Dispersion Over North
* Murray & Trettel, Inc. 74/06/30. 106pp.

B101270481 Advises of concurrence w/NUREG-0619 re feedwater control rod drive return line nozzle cracking, in response to NRC B01113 ltr. Results of further evaluations will be submitted by B10220
JANECEK, R. F. Commonwealth Edison Co. 81/01/22 2pp

O. Inspection reports, IE Bulletins & correspondence

B101050249 Forwards IE Info Notice 80-38, "Cracking in Casing Cladding." No response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 2pp.

B101050462 Forwards IE Bulletin 80-21, "Valve Yokes Bup Foundry Co. Inc." Written response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 2pp

B101100115 Forwards IE Insp Repts 50-254/80-23 & 50-261/80-265/80-23, 18-19, 100B, 18-16 & 1106 No noncompliance no FIORELLI, O. Region 3, Chicago, Reactor Construction Support Branch 80/11/24. 2pp. 07441:318

--B101100153 IE Insp Repts 50-254/80-23 & 50-265/80-23 noted. Major areas inspected. QA/QC program, inservice data, torus mod & activities per IE Bulletins 79-03 & 80-13
WARD, K. D. Region 3, Chicago, Office of the Director DANIELSON, D. H. Region 3, Chicago, Reactor Construction Engineering Support Branch. 80/11/19. 11pp. 074

B101050079 Forwards IE Insp Repts 50-254/80-25 & 50-261/80-265/80-23 & notice of violation.
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Branch 80/11/28 2pp. 07421:001.

--B101080083 Notice of violation from insp on B01020-1
* Region 3, Chicago, Office of the Director. 80/07421:003

--B101080092 IE Insp Repts 50-254/80-25 & 50-265/80-265 Noncompliance noted: incorrect surveillance performed inoperable diesel generator. Inadequate testing re pump failure.
SPESBARD, R. L., CHRISTOPHER, N., DUPONT, S. O. Region 3, Chicago, Office of the Director. 80/11/28. 14pp. 07421:0

B101090800 Ack receipt of B01112 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-254/80-20 & 50-265/80-22
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/12/01
1p 07187 001

--B101090810 Responds to NRC B01021 ltr re violations noted in IE Insp Repts 50-254/80-20 & 50-265/80-22 Corrective actions lead blankets added to piping & ladder by Unit 2 CRD accumulators removed
ABEL, J. B. Commonwealth Edison Co. 80/11/12 10pp. 07187 001

B101090930 Forwards IE Info Notice B0-43, "Failures of Continuous Water Level Monitor for Scram Discharge Vol at Dresden Unit 2" No response required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/12/05
2pp

B101090234 Ack receipt of B01201 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-254/80-22 & 50-265/80-24
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/12/09 1p 07425 274

--B101090244 Responds to NRC B01106 ltr re violations noted in IE Insp Repts 50-254/80-22 & 50-265/80-24 Corrective actions: closed charging water isolation valves & resumed control rod blade unclenching
ABEL, J. B. Commonwealth Edison Co. 80/12/01 2pp. 07425 275

B101060073 Responds to IE Bulletin B0-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Valves V70900-21-1 or V70900-21-3 not used in any safety-related functions Approx 40 manhours expended in bulletin review
RAUSCH, T. J. Commonwealth Edison Co. 80/12/12 1p.

B101080060 Forwards IE Info Notice B0-45, "Potential Failure of BWR Backup Manual Scram Capability" No written response required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/12/17
2pp

B101130240 Forwards Suppl 4 to IE Bulletin B0-17, "Failure of Control Rods to Insert During Scram at BWR." Written response required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/12/18
1p

B101290434 Forwards IE Insp Repts 50-254/80-28 & 50-265/80-29 on B01119-20 No noncompliance noted.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/12/18 2pp. 07570 325.

--B10129043D IE Insp Repts 50-254/80-28 & 50-265/80-29 on B01119-20 No noncompliance noted. Major areas inspected licensee actions re IE Bulletin 79-14.
YIN, I. T. Region 3, Chicago, Office of the Director.
DANIELSDON, D. H. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/12/18 5pp 07570 327

B101050170 Forwards IE Bulletin B0-25, "Operating Problems W/Target Rock Safety Relief Valves at BWRs." No response required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/12/19
2pp.

B101080093 Responds to NRC B00B18 request for monthly status rept re evaluations in response to IE Bulletin 79-14. Tabulations of piping sys w/stresses above FBAR levels & below operability limit encl.
JANECEK, R. F. Commonwealth Edison Co. 80/12/22 5pp 07421 090.

B101130198 Forwards IE Insp Repts 50-254/80-29 & 50-265/80-30 on B01208-12 No noncompliance noted.
HIND, J. A. Region 3, Chicago, Safeguards Branch. 80/12/24 2pp. 07452 083.

--B101130206 IE Insp Repts 50-254/80-29 & 50-265/80-30 on B01208-12 No noncompliance noted. Major areas inspected: security plan & program audit. Details withheld (ref 10CFR2 790)
CHRISTOFFER, G., KNICELEY, J. R. Region 3, Chicago, Office of the Director. HIND, J. A. Region 3, Chicago, Safeguards Branch. 80/12/23 2pp. 07452 085

B101200135 Forwards addl response to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Revised initial acceptance allowables for combined piping sys stresses during BSE event provided.
JANECEK, R. F. Commonwealth Edison Co 81/01/05 6pp. 07486 108.

B101200195 Forwards response to IE Bulletin B0-24, "Prevention of Damage Due to Water Leakage Inside Containment (B01017 Indian Point 2 Event)" Surveillance procedures of at least monthly repetition will be instituted by B10601
RAUSCH, T. J. Commonwealth Edison Co 81/01/05 6pp

B101300574 Ack receipt of B01211 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-254/79-31
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 81/01/21 1p 07585 327

--B101300577 Responds to NRC B00214 ltr re violations noted in IE Insp Rept 50-254/79-31 Corrective actions: locked switch boxes will be inspected as part of routine shift rounds
JANECEK, R. F. Commonwealth Edison Co. 80/12/11 1p 07586 328

R Periodic operating reports & related correspondence

B101120193 Forwards "Environ Dose Pathway Study," Spring 1979 through Summer 1980
JANECEK, R. F. Commonwealth Edison Co 80/12/30 1p 07446 168

--B101120196 "Environ Dose Pathway Study," Spring 1979 through Summer 1980
Eberline Instrument Corp 80/12/30 44pp 07446 169

B101200302 Forwards list of changes, test & experiments completed during Dec 1980
KALIVIANAKIS, N. Commonwealth Edison Co 81/01/02 5pp 07486 28

B101210463 Forwards monthly operating repts for Dec 1980
KALIVIANAKIS, N. Commonwealth Edison Co 81/01/02 1p 07493 187

--B101210465 Monthly operating repts for Dec 1980
TUBBS, R. C. Commonwealth Edison Co 81/01/01 32pp 07493 188

S Reportable occurrences, LERs & related correspondence

B011250354 Forwards LER B0-029/01T-0
KALIVIANAKIS, N. Commonwealth Edison Co 80/11/12 1p 07056 065

--B01125035B LER B0-027/01T-0: on B01103, during suppression chamber mod to make weld fit-up, safety relief valve line 1-3019E-B suffered 4-inch crack at pipe penetration. Caused by excessive force. Pipe will be repaired before startup
KOPACZ, J. J. Commonwealth Edison Co 80/11/12 2pp 07056 089

B101090064 Forwards six updated LERs B0-021/03L-1
KALIVIANAKIS, N. Commonwealth Edison Co 80/12/19 1p 07426 235

--B101090066 First of six updated LERs B0-021/03L-1 on B00903, during local leak rate test, leakage through containment purge vol valves AD-1-1601-21, 22, 24, 60, 61, 62 & 63 found to have leakage rates in excess of Tech Specs. Caused by misalignment of main shaft w/butterfly disc
KEHERT, D. Commonwealth Edison Co. 80/12/19 1p 07426 236.

--B101090070 Second of six updated LERs B0-021/03L-1: on B00904, during local leak rate test, leakage through containment purge vol valves AD-1-1601-21, 22, 55 & 56 found excessive. Caused by main shaft misalignment preventing butterfly disc seating
HANNUM, D. Commonwealth Edison Co. 80/12/19 1p. 07426 237.

--B101090088 Third of six updated LERs B0-021/03L-1 on B00901, during main steam line local leak rate test, valves AD-1-0203-2A, 1B, 2B, 1D & 2D found to have excessive leakage. Caused by cracks in satellite disc & cage. Discs turned & seats lapped.
TUBBS, R. C. Commonwealth Edison Co. 80/12/19 3pp 07426 238

--B101090091 Fourth of six updated LERs B0-021/03L-1: on B00901, during main steam line drain local leak rate test, valve AD-1-220-1 found to have leakage in excess of Tech Specs. Caused by worn seal ring. Seal replaced, valve repacked & stroked.
MURRAY, B. Commonwealth Edison Co. 80/12/19 1p 07426 241

--B101090096 Fifth of six updated LERs B0-021/03L-1: on B00906, during feedwater check valve local leak rate test, leakage through feedwater check valve 1-220-62B found excessive. Caused by worn valve seat & dirty pivot. Valve relapped & cleaned
WYKOFF, D. Commonwealth Edison Co 80/12/19 1p. 07426 242

--B101090103 Sixth of six updated LERs B0-021/03L-1: on B00917, during feedwater check valve local leak rate test, leakage through feedwater check valve 1-220-62A found excessive. Caused by dirty valve internals. Valve retested
WUNDERLICH, J. R. Commonwealth Edison Co. 80/12/19 1p. 07426 243

B101050390 Forwards LER 80-032/017-0
KALIVIANAKIS, N Commonwealth Edison Co 80/12/22 1p 07390.108

--B101050396 LER 80-032/017-0 on 801211, during installation of hanger per
IE Bulletin 79-14, two 1/2-inch anchor bolt holes were
drilled which penetrated primary containment. Caused by
faulty design. Plugs welded in holes.
MURRAY, R Commonwealth Edison Co 80/12/22 2pp. 07390.109

B101270763 Forwards LER 80-033/03-0
KALIVIANAKIS, N Commonwealth Edison Co. 81/01/06 1p 07549.079.

--B101270770 LER 80-033/03-0 on 801217, while placing standby gas
treatment in normal standby operation, suction valve
W0-1-7503 failed to open from control room. Caused by dirty
auxiliary contacts. Contacts were cleaned & replaced.
EISENHUT, D Commonwealth Edison Co 81/01/06 1p 07549.080

LOCHET 30-295 PALISADES NUCLEAR PLANT

F. Security, medical, emergency & fire protection plans

B101070387 Ltr to all licensees of operating reactor plants, CP holders
& CP applicants. Revised radiological emergency response
plans must be submitted by licensees within 60 days of
810102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing. 80/11/13 2pp

B101300558 Forwards comments re required revisions to util physical
security plan Encl withheld (ref 10CFR2.790)
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/15 3pp
07594.352

B101140310 Requests that encl facility emergency planning info be made
publicly available w/ encl
SOUER, J L Division of Rules and Records 80/12/31 1p
07461.264

B101260732 Releases public version of util revised site emergency plan
FELTON, J H Division of Rules and Records. 81/01/16 1p.
07535.176

--B101260738 Forwards public version of revised site emergency plan
HOFFMAN, B P Consumers Power Co 81/01/02. 1p 07535.177

--B101260743 Public version of revised site emergency plan
* Consumers Power Co 81/01/01 173pp 07535.179.

G. Adjudicatory correspondence

B101120494 Discovery rept per ASLB 800227 memorandum & order. Answers to
util third round interrogatories filed 801223. Further
discovery to be conducted in Jan 1981. Stello, Kessler &
Jorgenson depositions postponed.
MCJUN, R E Rulemaking & Enforcement Division 81/01/07. 1p.
07447.209

B101130053 Third round interrogatories directed to CPC to be answered
by B10130. Concerns local leak tests of Penetration 4 &
HEPA filter replacement. Certificate of Svc encl.
BURNS, B O Rulemaking & Enforcement Division. 81/01/09 5pp
07448.297

B101140970 Notice of FD Leckie 810202 deposition in Columbus, OH re
alleged noncompliance by util Certificate of Svc encl.
BURNS, B O Rulemaking & Enforcement Division 81/01/13 2pp.
07448.297.

B101260523 Application for subpoena requiring F Leckie to attend,
testify & produce documents at 810209 deposition in
Columbus, OH re activities on filter testing & replacement.
Proposed subpoena & Certificate of Svc encl.
BURNS, B O Rulemaking & Enforcement Division 81/01/22. 4pp
07529.293

I. Financial information

B101150506 Forwards statement of internal case flow for yr ending
801130 & projected for yr ending 811130
BORIS, W R Consumers Power Co 81/01/09 3pp 07463.150.

J. Insurance & indemnity information

B101220332 Forwards Enforcements 66 & 67 to ANI Policy NF-179
Enforcement 67 not encl
IRELAND, J H Consumers Power Co 81/01/16 2pp. 07494.094.

B101260462 Forwards Endorsement 4 to ANI Binder EB-20
IRELAND, J H Consumers Power Co 81/01/21 2pp

P. Operating license stage documents & correspondence

B101300367 Forwards Amend 62 to license DPR-20, safety
notice of issuance & availability
CRUTCHFIELD, D Operating Reactors Branch 5 80/10/20
07586.174

--B101300377 Amend 62 to License DPR-20, changing Tech
re limiting condition for operation for auxiliary
sys & fire water pumps
CRUTCHFIELD, D Operating Reactors Branch 5. 80/10/20
07586.178

--B101300363 Safety evaluation supporting Amend 62 to
revising Tech Specs Section 3.5 re limiting condition
for operation for auxiliary feedwater sys & fire water
* Operating Reactors Branch 5. 80/10/20 2pp

--B101300390 Notice of issuance & availability of Amend
DPR-20
CRUTCHFIELD, D Operating Reactors Branch 5 80/10/20
07586.189.

B101220466 Ltr to all power reactor licensees & appli
summary of 801112 meeting re implementation of guide
Unresolved Safety Issue A-12, "Potential for Low Frac
Toughness & Lamellar Tearing on Component Supports".
EISENHUT, D O Division of Licensing 80/11/26 1p.

B101050080 Confirms 801202 proposal made by SEP owner
meeting w/ARC for completion of 60% of SEP topics by
810630. Forwards matl used during 801202 presentation.
BOHAFBSTALL, R NRC, Inc 80/12/05 12pp 07379.2

B101280472 Forwards request for addl info to complete
adequacy of station electric distribution sys voltage
facility Rating of Class IE motor contactors & upper
lower limits for continuous operation required
CRUTCHFIELD, D Operating Reactors Branch 5. 80/12/15
07598.102.

B101210186 Forwards table of structures, sys & component
classification w/respect to quality group & const c
for SEP Topic III-1. Util must complete table & verify
existing data
CRUTCHFIELD, D. Operating Reactors Branch 5. 80/12/15
07468.246

B101210445 Forwards responses to questions on Rule 50
Updating of FSARs" & FR notice of final rule. SEP pl
not comply w/rule until program is complete. Non-SEP
must comply within specified time frame
EISENHUT, D O Division of Licensing 80/12/15. 1p

B101160027 Notification of 801218 meeting w/SEP owner
Bethesda, MD re SEP program, schedule for licensee to
completion & assignment of lead topics to plants.
AUSSELL, W T. Technical Support Branch 80/12/16

B101160017 Trsg rept of 801117-19 visit to site w/BEP
observe facility features re SEP structural, electrical
topic reviews & to discuss open items based on site
review. Util responses to SEP items & list of attend
MICHAELS, T B. Systematic Evaluation Program Branch
36pp 07465.265

B101230337 Forwards listing of all SEP correspondence
SEP owners group 801202 meeting List provides basis
which to determine plant status Review & comments re
W/O encl
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/15
07512.097.

B101190636 Advises of detention of SEP Topic III-3 B. re
consequences of underdrain sys failure, from facility
review due to inapplicability.
CRUTCHFIELD, D Operating Reactors Branch 5. 80/12/15
07476.066

B101210149 Forwards request for addl info for NRC rev
III-4 C, "Internally Generated Missiles
(Classified Containment)" & IX-4, "Boron Addition Sys."
CRUTCHFIELD, D. Operating Reactors Branch 5. 80/12/15
07491.303

01290299 Informs that SEP Topics III-10 A, III-10 B, VI-7 F, VIII-3 B, VII-4 & XV-16 will be basic input to integrated safety assessment. Topic assessments may be revised if facility design is changed.
CRUTCHFIELD, D. Operating Reactors Branch 5 80/12/31 2pp
07575 010

01300847 Technical Evaluation Rept. Degraded Grid Protection for Class IE Power Sys. Palisades Plant.
CLEVELAND, C. J. E&S Idaho, Inc. FIN A-6256 8101300847 80/12/31
12pp 07584 332

01140033H Forwards summary status of rept re "Inadequate Core Cooling Detection Sys." per 801219 commitment in response to NUREG-0737 Rept. includes conceptual design description of inadequate core cooling detection sys.
GFFMAN, D. P. Consumers Power Co. 81/01/05 1pp 07450 011

0101140344 Summary status of rept re "Inadequate Core Cooling Detection Sys."
* Consumers Power Co. 80/12/31 3Bpp 07450-013

01130442 Forwards proprietary & nonproprietary versions of turbine disc cracking into updating 800321 submittal.
GFFMAN, D. P. Consumers Power Co. 81/01/06 2pp 07451 315

010130445 "Turbine Disc Info." nonproprietary version
* Consumers Power Co. 81/01/06 25pp 07451 317

010130450 Requests that info re turbine disc integrity be withheld per 10CFR2.790 as subj. info is considered proprietary.
WILLIAMS, R. Westinghouse Electric Corp. 80/03/14 7pp
09135 116

01140628H Forwards facility equipment list data sheet for rotating equipment w/rating of greater than 30 horsepower in response to NRC 801219 telcon re SEP review.
KUEHN, J. L. Consumers Power Co. 81/01/06 24pp. 07309-001

01120318 Advises that NRC rept re loss of offsite power survey did not still provides misleading info. such as item which shows facility w/four event rates greater than target values.
GFFMAN, D. P. Consumers Power Co. 81/01/08 2pp 07447-111

01210346 Forwards draft safety evaluation of SEP Topic III-4 D, "Site Proximity Missiles." Evaluation will be used as basic input to integrated assessment for facility unless changes reflecting as-built condition are required.
CRUTCHFIELD, D. Operating Reactors Branch 5 81/01/13 9pp
07487-216

01220472 Forwards request for addl info necessary to complete SEP seismic review info identified as open items from draft NUREG/CR-1833, "Seismic Review of Palisades Nuclear Power Plant, Unit 1, As Part of SEP." w/o NUREG.
CRUTCHFIELD, D. Operating Reactors Branch 5 81/01/19 4pp
07505 205

01280077 Forwards draft evaluation of SEP Topic VII-3, "Electrical Instrumentation & Control Aspect of Sys Required for Safe Shutdown," to accompany 801103 ltr Response within 30 days requested.
CRUTCHFIELD, D. Operating Reactors Branch 5 81/01/24 35pp
07557 109

01290785 SEISMIC REVIEW OF THE PALISADES NUCLEAR POWER PLANT UNIT 1 AS PART OF THE SYSTEMATIC EVALUATION PROGRAM.
MELSON, T. A., MURRAY, R. C., KESLEY, D. A. Lawrence Livermore Laboratory. FIN A-0233. NUREG/CR-1833. 81/01/31. 187pp. Available at NTIS 35.50. 07569-005

01200639 Forwards guidelines for performing soil-structure interaction reviews for SEP facilities & simplified analytical approach for evaluating effects of soil-structure interaction using lumped parameter model.
CRUTCHFIELD, D. Operating Reactors Branch 5 80/12/15 2pp.
07477-143

Inspection reports, IE Bulletins & correspondence

01050214 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/10/30
2pp 07389-041

8101060118 Forwards IE Circular 80-23, "Potential Defects in Detroit Power Sys Emergency Generators." No written response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/10/11
1p 07397 329

8101060644 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response is required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/10/11
2pp 07401 206

0101050457 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/11/06
3pp 07390 001

8101060628 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety-Relief Valve Operation to Cause Reactor Depressurization." No written response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/11/07
2pp 07392 165

8101060344 Forwards IE Info Notice 80-41, "Failure of Spring Check Valve in Decay Heat Removal Sys at Davis-Besse Unit 1." No response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/11/10
2pp 07392 070

8101060501 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Written response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/11/14
2pp 07391 229

8101090074 Forwards IE Insp Rept 50-255/80-19 on 801020-24 & notice of violation.
DAVIS, A. J. Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/11/18 2pp 07426-245

--8101090077 Notice of violation from Insp on 801020-24
* Region 3, Chicago, Office of the Director. 80/11/12 1p
07426 247

--8101090114 IE Insp Rept 50-255/80-19 on 801020-24 Noncompliance noted failure to submit annual nonradiological environ rept for CV77 on time & to include all required info.
JANUSAS, A. O., PHILLIPS, M. P., PAPERICLO, C. J. Region 3, Chicago, Office of the Director 80/11/12 12pp 07426-248

8101070170 Forwards IE Insp Rept 50-255/80-21 on 801006-31 & notice of violation.
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/11/21 2pp 07415 127

--8101070174 Notice of violation from Insp on 801006-31
* Region 3, Chicago, Office of the Director. 80/11/21. 1p
07415 129

--8101070181 IE Insp Rept 50-255/80-21 on 801006-31 Noncompliance noted equipment operability requirements not met & steam generator tube pressure differential limit exceeded.
JORGENSEN, B. L., HELLER, J. K., BOYD, D. C. Region 3, Chicago, Office of the Director. 80/11/21 8pp. 07415 130

8101050124 Requests existing data, summaries & records of inservice shop tests of containments w/greased prestressing tendons.
DRNL receiving contract to compile & review records of tendons.
EISENHUT, D. O. Division of Licensing 80/11/25 3pp.

8101300351 Forwards IE Health Physics Appraisal Rept 50-255/80-14, notice of violation & significant appraisal findings.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/11/21
4pp. 07586 134

--8101300355 Notice of violation from health physics appraisal on 800804-15
* Region 3, Chicago, Office of the Director. 80/11/25 2pp
07586 138

--8101300361 IE Health Physics Appraisal Rept 50-255/80-14 Noncompliance noted inadequate evaluation of airborne releases & failure to follow radiation protection procedures.
GREGER, L. R., GRANT, W. B. Region 3, Chicago, Office of the Director CARBAUGH, E. H. Battelle Memorial Institute 80/11/25 34pp
07586 140

B101030562 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Steam Discharge Vot at Dresden Unit 2 - No response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/12/05
2pp 07390 332

B101090168 Ack receipt of B01031 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-255/80-17
HEISMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/12/08 1p 07426 355

--B101090171 Responds to NRC B01038 ltr re violations noted in IE Insp Rept 50-255/80-17 Corrective actions advised dept heads of weekly insp to be conducted re fire protection procedures & of rept to be written
HOFFMAN, D. P. Consumers Power Co. 60/10/31 2pp 07426 355

B101070653 Responds to IE Bulletin 80-21 No records found concerning valves supplied from Falcone Foundry. List of currently installed Anchor Darling valves encl.
HOFFMAN, D. P. Consumers Power Co 80/12/10 3pp 07415 273.

B101070100 Forwards IE Info Notice 80-44, "Activation of ECCS in Recirculation Mode While in Hot Shutdown" No written response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/12/16 1p 07415 027

B101290428 Forwards IE Insp Rept 50-255/80-22 on B01101.03-07.10-12.14.17-22 & 25-26 No noncompliance noted
HEISMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/12/18 2pp 07570 319

--B101250432 IE Insp Rept 50-255/80-22 on B01101.03-07.10-12.14.17-22 & 25-26 No noncompliance noted Major areas inspected maint & surveillance
JEROEISEN, B. L., HELLER, J. A., JOYD, D. C. Region 3, Chicago, Office of the Director 80/12/17 4pp 07570 321

B101150076 Ack receipt of B01210 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-255/80-19
DAVIS, A. J. Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/12/31 1p 07462 183

--B101150079 Responds to NRC B01113 ltr re violations noted in IE Insp Rept 50-255/80-19 Corrective actions summarized rept will be issued by B10115 & effluent particulate activity calculation methods reviewed.
HOFFMAN, D. P. Consumers Power Co 80/12/10 4pp 07462 184.

B101220395 Responds to IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment" Weekly containment entries performed to search for water leakage on lower level of containment & results documented in logbook
HOFFMAN, D. P. Consumers Power Co 81/01/08 8pp. 07500 255

B101220182 Ack receipt of B01017 ltr refuting violations noted in IE Insp Rept 50-255/80-15 Item 1 re plant operation for more than 36-h w/inoperable safety-related snubber remains as issued Item 2 withdrawn.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 81/01/09 2pp 07503 240

--B101220186 Responds to NRC B00924 ltr re violations noted in IE Insp Rept 50-255/80-15 Refutes items of Noncompliance 1 & 2A STB reviewed to provide clarification of problem re cold shutdown after snubber inoperability.
FRCSIT, S. R. Consumers Power Co 80/10/17 3pp 07503 242

B101220190 Ack receipt of B01216 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-255/80-21 Item 1 remains classified as infraction
HEISMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 81/01/09 2pp 07503 245

--B101220200 Responds to NRC B01121 ltr re violations noted in IE Insp Rept 50-255/80-21 Corrective actions ltr sent to const superintendent confirming commitment to adhere to fire protection procedures
HOFFMAN, D. P. Consumers Power Co 80/12/16 3pp 07503 247

R Periodic operating reports & related correspondence

B101130243 Forwards monthly operating rept for Dec 1980.
KENNEDY, D. M. Consumers Power Co 81/01/08 1p 07452 097.

--B101130249 Monthly operating rept for Dec 1980.
BODTKE, P. J. Consumers Power Co 81/01/08 4pp. 07452 098.

B101200304 Submits bimonthly status rept for Dec 1980.
Bechtel Corp is preparing final design details for 1 cooling mods scheduled for 1981 refueling outage
HOFFMAN, D. P. Consumers Power Co 81/01/15 1p. 0

S Reportable occurrences, LERs & related correspondence

B101270123 Immediate action ltr confirming until B10109 prevent recurrence of B10106 event Corporate mgt representative will conduct daily audit of facility operations
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/12/16 2pp. 07547 219

B101230530 Forwards LER B1-001/01T-0
HOFFMAN, D. P. Consumers Power Co 81/01/16 1p. 0

--B101230531 LER B1-001/01T-0 on B10106 output breaker inadvertently opened for 1-h Caused by misalignment personnel failure to follow procedure Safety-related surveillance & maint procedures reviewed prior to
* Consumers Power Co 81/01/16 9pp. 07183 001

B101230479 Forwards NRCES noncompliance notification 1
HOFFMAN, D. P. Consumers Power Co 81/01/20 1p 0

--B101230483 NRCES noncompliance notification on B01222 exceeded Tech Spec limit Caused by rupture of snubber breaker filter element Filter element replaced on Oil removal sys will be cleaned & personnel retrained
FOBER, R. L. Consumers Power Co 81/01/20 1p 0

DOCKET 80-259 BROWN'S FERRY NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor p & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days B10102 & by applicants as part of FSAR
EISENHUT, D. O. Division of Licensing 80/11/13 2pp

B101210607 Transcript of B01217 briefing on TVA emergency facilities in Washington, DC Pp 1-45
* Commissioners. 80/12/17 49pp 07489 137

B101300646 Forwards request for addl info & revisions to facility guard training & qualification plan Min score for qualifying w/rifle should be stated
JPPDUT, J. T. A. Operating Reactors Branch 2. 81/01/07587 079

B101260611 Releases public version of util revised emergency plan
FELTON, J. M. Division of Rules and Records 81/01/07531 230

--B101260619 Forwards public version of revised radiological plan in response to NRC B01113 ltr Includes State emergency plan.
MILLS, L. M. Tennessee Valley Authority. 80/12/31

--B101260624 Public version of revised util radiological plan
* Tennessee Valley Authority 80/12/31. 130pp.

--B101260693 Releases public version of State of AL radiological plan.
FELTON, J. M. Division of Rules and Records 81/01/07531 180.

--B101260706 Public version of State of AL revised radiological plan.
* Tennessee Valley Authority 80/12/31 300pp.

B101300356 Forwards revisions to safeguards contingency withheld (ref 10CFR2.790)
MILLS, L. M. Tennessee Valley Authority. 81/01/23.

Q Adjudicatory correspondence

B101160226 Petition for leave to intervene & request license amend requests
PAUL, T. W., JOBE, R. W., HALL, M. L. Affiliation Unknown 4pp. 07470 180

B101200070 Motion for leave to intervene in proceeding re license
amends to allow onsite storage of low level radwaste for
five yrs
CURDITT, D R , CURDITT, U J Affiliation Unknown B1/01/15 5pp
07486 339

B101200091 Petition for leave to intervene in proceeding.
MARTIN, J R , BECK, N M , BECK, R W Affiliation Unknown B1/01/16
5pp 07187:001

B101200095 Petition for leave to intervene in proceeding
MUSE, N , FREEMAN, R L , COLCLOCK, A N Affiliation Unknown B1/01/16
4pp 07486 353

B101200214 Petition for leave to intervene & request for hearing on
license amend requests
MARTIN, D L , BROUGH, O R , PIERSON, M D Affiliation Unknown
B1/01/16 5pp 07476 341

B101230407 Requests to make limited appearance statement & to receive
EIS on proposed low level radwaste storage project
YOUNG, F. Affiliation Unknown B1/01/21 1p 07187:001.

B101300012 Response supporting DR & UJ Curditt, TH Paul, RW Jobe, ML Hall,
BL Martin, OR Brough, MD Pierson, D Elg, D Ilavas, N Muse, RL
Freeman, AN Colock, JR Martin & NM & RW Beck petitions for
leave to intervene if amended Certificate of Evc encl.
LAVERY, J. H. Office of the Executive Legal Director B1/01/20
12pp 07582 176.

J Insurance & indemnity information

B101090486 Forwards Endorsement 93 to ANI Policy NF-19B for amend to
Condition 2
FIELDER, J Marsh & McLennan, Inc. , M & M Nuclear Consultants, Inc.
Div B0/12/29 3pp 07442 294

B101090490 Forwards Endorsement 92 to ANI Policy NF-19B for 19B1
advances premiums
FIELDER, J Marsh & McLennan, Inc. , M & M Nuclear Consultants, Inc.
Div. B0/12/29 2pp 07442 083

B101090647 Forwards Endorsement 4 to NELIA Binders EB-3B, EB-39 &
EB-40 W/o Binders EB-39 & EB-40
FIELDER, J. Marsh & McLennan, Inc. , M & M Nuclear Consultants, Inc
Div B0/12/29 2pp 07442 060.

P. Operating license stage documents & correspondence

B101100254 Ltr to all licensees (except SEP licensees) forwarding
Revision 1 of inservice surveillance requirements for
snubbers under BTR License amend application adding model
Tech Specs to App A should be submitted within 120 days
EISENHUT, D O Division of Licensing B0/11/20 1p

--B101100271 Revised Pages 3/4 7-22 through 2B-B 3/4 7-9 & 7-6 & 6-17 to
BTR snubber inservice insp requirements.
* Division of Licensing. B0/11/20 10pp.

B101220466 Ltr to all power reactor licensees & applicants forwarding
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issue A-12. "Potential for Low Fracture
Toughness & Laminar Tearing on Component Supports."
EISENHUT, D O. Division of Licensing. B0/11/26 8pp.

B101100030 Requests input deck & simulator time re NRC comparison of
RETRAN results w/simulator results for loss of feedwater &
loss of load transients in BWR.
IPPOLITO, T A Operating Reactors Branch 2 B0/12/02 2pp
07444 299.

B101100022 Forwards FR notice of consideration of amends to facility
DLs re util B00731 & 1117 applications for authorization of
onsite low level waste storage for 5-yr period.
IPPOLITO, T A. Operating Reactors Branch 2. B0/12/05 2pp.
07445:204.

B101190113 Ltr to all BWR licensees forwarding B01201 generic safety
evaluation re BWR scram discharge sys Recommends short-term
actions necessary to assure safe operation of OE BWRs
pending permanent design changes.
EISENHUT, D O. Division of Licensing. B0/12/09 2pp.

--B101190141 Generic safety evaluation re short-term actions required to
assure continued safe operation of operating BWRs. Continued
operation of plants is acceptable pending permanent design
mods. Criteria for implementing design mods encl.
* Division of Licensing. B0/12/01 212pp. 07183:001.

B101050610 Forwards geologic rept re suggested graben in Gravelly
Springs, AL area Distance to facilities precludes
significance of structures. Related documentation encl
LEFEVRE, H E Geosciences Branch B0/12/11 15pp. 03775:001

B101210445 Forwards responses to questions on Rule 50 71e. "Periodic
Updating of FSARs" & FR notice of final rule SEP plants need
not comply w/rule until program is complete Non-SEP plants
must comply within specified time frame
EISENHUT, D O Division of Licensing B0/12/15 13pp

B101210642 Advises that ATWS issue will be subj of future rulemaking
determine requirements & schedules for plant nodes NRC will
not comment on until B00917 ltr describing program for
resolving issue until rulemaking is finalized
EISENHUT, D O Division of Licensing B0/12/29 2pp 07401:112

B101290033 Forwards Amends 65.61 & 36 to Licenses DPR-33, DPR-52 &
DPR-68, respectively. EIA & notice of issuance & negative
declaration
IPPOLITO, T A Operating Reactors Branch 2. B0/12/29 3pp
07309 001

--B101290040 Amends 65.61 & 36 to Licenses DPR-33, DPR-52 & DPR-68,
respectively, changing App B Tech Specs to delete fish
impingement monitoring program
IPPOLITO, T A Operating Reactors Branch 2 B0/12/29 12pp
07309 001

--B101290046 EIA supporting Amends 65.63 & 36 to Licenses DPR-33, DPR-52
& DPR-68, respectively. Summary review of fish impingement
encl
* Office of Nuclear Reactor Regulation, Director B0/12/29
32pp 07309 001

--B101290052 Notice of issuance & availability & negative declaration
Amends 65.61 & 36 to Licenses DPR-33, DPR-52 & DPR-68,
respectively
IPPOLITO, T A Operating Reactors Branch 2 B0/12/29 2pp
07309 001

B101190393 Advises that until B00909 response to NRC B03702 generic
re Tech Specs for TMI Lessons Learned Category A items is
inadequate Outstanding items emergency power supply relief
& safety valve position indication
IPPOLITO, T A Operating Reactors Branch 2 B1/01/02 2pp.
07479 344

B101300460 Order granting extension to exemption from General Design
Criterion 50 & requiring licensee to reassess containment
design for suppression pool hydrodynamic loading
EISENHUT, D O Division of Licensing. B1/01/13 7pp

--B101300467 Order granting extension to exemption from General Design
Criterion 50 & requiring licensee to reassess containment
design for suppression pool hydrodynamic loading
EISENHUT, D O Division of Licensing B1/01/13 7pp 07511:12

B101220411 Requests temporary relief from 5 F thermal rise limit &
max reservoir temp rise of B 5 F be granted until Apr 1981.
Temp rise of 8.5 F will sustain 3-unit operation at facility
w/ current pin hydro releases for navigation.
EL-ASHRY, M I Tennessee Valley Authority B1/01/14 3pp.
07502 246

B101220297 Grants request for temporary relief from permit condition
re allowable temp rise within certain conditions Temp at
edge of mixing zone must not exhibit change greater than
B 5 F
ZELLER, H D Environmental Protection Agency. B1/01/15 2pp
07500 069

B101300493 Forwards response to NRC B01123 request for confirmation
that NUREG-0619 implementation dates will be met Info
justifies continued operation
MILLS, L M Tennessee Valley Authority B1/01/23 3pp. 07183:001

Q Inspection reports, IE Bulletins & correspondence

B101080184 Forwards update to B00104 response to IE Bulletin 79-26
boron loss from BWR control blades Manpower required for
review & preparation approx 20-h
MILLS, L M Tennessee Valley Authority B0/11/29 3pp. 03775 001

B101050588 Forwards IE Info Notice B0-43. "Failures of Continuous
Level Monitor for BWR Discharge Vol at Dresden Unit 2 " No
response required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. B0/12/11
1p. 07391:010.

MILLS, L. M. Tennessee Valley Authority 80/12/15. 1p 07461 035
 spurious signal to operate overspeed trip relay.
 * Tennessee Valley Authority 80/12/31 2pp 07462 016

B101060153 Forwards IE Info Notice 80-45. "Potential Failure of EHR Backup Manual Scram Capability." No response required
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/12/17
 1p 07571 275

B101070032 Forwards Suppl 4 to IE Bulletin 80-17. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR." No written response required
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/12/18
 1p 07413 323

B101050153 Forwards IE Bulletin 80-25. "Operating Problems W/Target Rock Safety Relief Valves at BWRs." No response required
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/12/19
 2pp 07377 249.

B101160252 Forwards response to IE Bulletin 80-07. "BWR Jet Pump Assembly Failure." Ultrasonic & visual insp of jet pump beams & assembly showed no problems
 MILLS, L. M. Tennessee Valley Authority 80/12/30 2pp. 07470 249

B101210157 Informs that insp program re IE Bulletin 79-14 will not be completed by 801125 due to delays in planned schedules. Revised insp schedule & Dec 1980 status rept encl
 MILLS, L. M. Tennessee Valley Authority 81/01/05 3qpp. 07490 010

B101220376 Forwards results of spray sparger insp in response to IE Bulletin 80-13. "Cracking in Core Spray Spargers."
 MILLS, L. M. Tennessee Valley Authority 81/01/05 2pp 07560 294

B101280505 Forwards response to IE Bulletin 80-24. "Prevention of Damage Due to Water Leakage (Oct 17, 1980 Indian Point 2 Event)." Components requiring supplemental cooling are cooled by reactor bldg closed cooling water sys.
 MILLS, L. M. Tennessee Valley Authority 81/01/05 5pp 07550 319.

B101280527 Forwards results of util analyses on diesel generators & KBO V load shed logic re IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls."
 MILLS, L. M. Tennessee Valley Authority 81/01/14. 2pp. 07550 330

B101290350 Forwards monthly status rept as of B10101 for work re IE Bulletin 79-14. "Seismic Analysis for As-Built Safety-Related Piping Sys." Includes description of pipe support & valve insp
 MILLS, L. M. Tennessee Valley Authority 81/01/15 27pp 07572 327

R. Periodic operating reports & related correspondence

B101130582 Forwards monthly operating repts for Dec 1980.
 ABERCROMBIE, H. Tennessee Valley Authority 81/01/09. 1p
 07453 235

--B101130588 Monthly operating repts for Dec 1980
 THOM, T. Tennessee Valley Authority. 31/01/04 37pp. 07453 236

B101130595 Forwards monthly operating repts for Dec 1980
 ABERCROMBIE, H. Tennessee Valley Authority 81/01/09 1p
 07453 288

--B101130601 Monthly operating repts for Dec 1980
 GREEN, D. , THOM, T. Tennessee Valley Authority. 81/01/04. 21pp.
 07453 289

S. Reportable occurrences, LERs & related correspondence

B101060715 Forwards LER 80-087/03L-0.
 GREEN, H. J. Tennessee Valley Authority 80/12/30 1p. 07309 001

--B101060727 LER 80-087/03L-0 on 801201, while performing SI 4 2 B.24, core spray sparger to RPV differential pressure switch PD18-75-2B found to operate out of Tech Specs limits caused by instrument drift. Switch inspected & recaller
 * Tennessee Valley Authority. 80/12/30 2pp 07309 001.

B101090677 Forwards LER 80-088/03L-0
 GREEN, H. J. Tennessee Valley Authority 80/12/31. 1p. 07462 015.

B101190593 Forwards LER 80-090/03L-0
 GREEN, H. J. Tennessee Valley Authority. 81/01/08 1p 07475 016

--B101190603 LER 80-090/03L-0 on 801210, continuous air monitor 1-RM-90-250 declared inoperable due to iodine channel indicating downscale caused by water in sample line due to condensation. Instrument repaired & returned to svc.
 * Tennessee Valley Authority. 81/01/08 2pp 07475 017

B101130409 Forwards updated LER 80-073/01T-1.
 GREEN, H. J. Tennessee Valley Authority 81/01/09. 1p 07456 016

--B101130412 Updated LER 80-073/01T-1 on 800928, river water temp ri peaked above Tech Spec level. Caused by incorrect computer temp rise predictions River flow increased
 * Tennessee Valley Authority. 81/01/09 2pp 07456 020

B101220381 Forwards first interim rept re potential flammability of suspended ceiling tile in control rooms in response to 801104 ltr Addl info to be provided by B10211
 MILLS, L. M. Tennessee Valley Authority 81/01/14 3pp 07494 010

B101160920 Forwards LER 80-091/03L-0
 GREEN, H. J. Tennessee Valley Authority 81/01/15. 1p. 07471 216

--B101160925 LER 80-091/03L-0 on 801217, drywell hydrogen monitor, 1-H2M-76-39, would not calibr properly to calibr gas Tech Spec. Caused by GE Model 47E22642802 sensor failure. Alternate sensor 1-H2E-76-39A connected to hydrogen monitor
 * Tennessee Valley Authority 81/01/19. 2pp. 07471 276

B101390620 Forwards LER 80-092/03L-0
 GREEN, H. J. Tennessee Valley Authority. 81/01/26. 1p 07503 335

--B101390629 LER 80-092/03L-0 on 801230, standby gas treatment train relative humidity heaters did not function properly. Caused by open TE-65-60B switch. Switch repaired.
 * Tennessee Valley Authority. 81/01/26 2pp. 07503 334.

DOCKET 50-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP hol & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
 EISENHUT, D. G. Division of Licensing 80/11/13. 2pp.

B101219607 Transcript of 801217 briefing on TVA emergency offsite facilities in Washington, DC Pp 1-45
 * Commissioners 80/12/17 49pp.

B101300646 Forwards request for addl info & revisions to 801001 ch to facility guard training & qualification plan. Min passing score for qualifying w/rifle should be stated.
 JPPOLITIO, T. A. Operating Reactors Branch 2 81/01/14. 3pp
 07587 079.

B101260611 Releases public version of util revised emergency plan
 FELTON, J. H. Division of Rules and Records. 81/01/15. 1p
 07531 230.

--B101260619 Forwards public version of revised radiological emergency plan in response to NRC 801113 ltr. Includes State of AL emergency plan
 MILLS, L. M. Tennessee Valley Authority. 80/12/31. 1p. 07531 230

--B101260624 Public version of revised util radiological emergency plan
 * Tennessee Valley Authority. 80/12/31. 150pp. 07531 232.

--B101260693 Releases public version of State of AL revised emergency plan
 FELTON, J. H. Division of Rules and Records. 81/01/16. 1p
 07534 180.

--B101260706 Public version of State of AL revised radiological emergency plan.
 * Tennessee Valley Authority. 80/12/31. 300pp. 07534 182.

B101160226 Petition for leave to intervene & request for hearing on TVA license amend requests
PAUL, T. W., JOBE, R. W., HALL, M. L. Affiliation Unknown 81/01/14 4pp. 07470 180

B101200070 Motion for leave to intervene in proceeding re license amends to allow onsite storage of low level radwaste for five yrs
CURDITT, D. R., CURDITT, U. J. Affiliation Unknown 81/01/13 5pp 07486 339

B101200091 Petition for leave to intervene in proceeding
MARTIN, J. R., BECK, N. M., BECK, R. W. Affiliation Unknown 81/01/16 5pp. 07187 001

B101200095 Petition for leave to intervene in proceeding
MUSE, N., FREEMAN, R. L., COLCLOCK, A. N. Affiliation Unknown 81/01/16 4pp. 07486 353

B101200214 Petition for leave to intervene & request for hearing on license amend requests
MARTIN, D. L., BROUGH, Q. R., PIERSON, M. D. Affiliation Unknown 81/01/16 5pp 07476 341

B101230407 Requests to make limited appearance statement & to receive EIS on proposed low level radwaste storage project
YOUSSEF, F. Affiliation Unknown 81/01/21. 1p. 07187 001

B101300012 Response supporting DR & UJ Curditt, TW Paul, RW Jobe, ML Hall, EL Martin, GR Brough, MD Pierson, D Ely, D Havas, N Muso, RL Freeman, AN Colock, JR Martin & NM & RW Beck petitions for leave to intervene if amended Certificate of Evc encl.
LAVERY, J. H. Office of the Executive Legal Director 81/01/20 12pp. 07582 176.

J. Insurance & indemnity information

B101070486 Forwards Endorsement 53 to ANI Policy NF-198 for amend to Condition 2
FIELDER, J. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div. 80/12/29 3pp 07442 254.

B101090490 Forwards Endorsement 52 to ANI Policy NF-198 for 1981 advances premiums
FIELDER, J. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div. 80/12/29. 2pp 07442 003

B101090647 Forwards Endorsement 4 to NELIA Binders EB-38, EB-39 & EB-40, W/o Binders EB-39 & EB-40
FIELDER, J. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div. 80/12/29. 2pp 07442 060.

P. Operating license stage documents & correspondence

B101100284 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under B1S License amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT, D. O. Division of Licensing 80/11/20 1p.

--B101100271 Revised Pages 3/4 7-22 through 28, B 3/4 7-5 & 7-6 & 6-17 to B1S snubber inservice insp requirements.
* Division of Licensing. 80/11/20 10pp

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D. O. Division of Licensing. 80/11/26 8pp

B101100030 Requests input deck & simulator time re NRC comparison of RETRAN results w/simulator results for loss of feedwater & loss of load transients in BMR.
IPPOLITO, T. A. Operating Reactors Branch 2. 80/12/02. 2pp. 07444 299.

B101100022 Forwards FR notice of consideration of amends to facility OLS re util B00731 & 1117 applications for authorization of onsite low level waste storage for 5-yr period
IPPOLITO, T. A. Operating Reactors Branch 2. 80/12/05 2pp. 07445 204.

--B101190141 Generic safety evaluation re short-term actions required to assure continued safe operation of operating BWRs. Continued operation of plants is acceptable pending permanent design mode Criteria for implementing design mods encl.
* Division of Licensing 80/12/01 212pp 07183 001

B101050610 Forwards geologic report re suggested graben in Gravelly Springs, AL area. Distance to facilities precludes significance of structures. Related documentation encl.
LEFEVRE, H. E. Geosciences Branch 80/12/11 15pp 03775 001

B101210445 Forwards responses to questions on Rule 50.71e, "Periodic Upgrading of FSARs" & FR notice of final rule. SEP plants need not comply w/rule until program is complete. Non-SEP plants must comply within specified time frame.
EISENHUT, D. O. Division of Licensing 80/12/15 13pp

B101210642 Advises that ATWS issue will be subj of future rulemaking determining requirements & schedules for plant mods. NRC will not comment on util B00917 ltr describing program for resolving issue until rulemaking is finalized.
EISENHUT, D. O. Division of Licensing 80/12/29 2pp 07488 311

B101290033 Forwards Amends 65.61 & 36 to Licenses DPR-33, DPR-92 & DPR-68, respectively. EIA & notice of issuance & negative declaration.
IPPOLITO, T. A. Operating Reactors Branch 2. 80/12/29 3pp 07309 001

--B101290040 Amends 65.61 & 36 to Licenses DPR-33, DPR-92 & DPR-68, respectively, changing App B Tech Specs to delete fish impingement monitoring program.
IPPOLITO, T. A. Operating Reactors Branch 2. 80/12/29 12pp 07309 001

--B101290046 EIA supporting Amends 65.63 & 36 to Licenses DPR-33, DPR-92 & DPR-68, respectively. Summary review of fish impingement encl.
* Office of Nuclear Reactor Regulation, Director 80/12/29. 32pp 07309 001

--B101290052 Notice of issuance & availability & negative declaration Amends 65.61 & 36 to Licenses DPR-33, DPR-92 & DPR-68, respectively.
IPPOLITO, T. A. Operating Reactors Branch 2. 80/12/29 2pp 07309 001

B101190393 Advises that util B00909 response to NRC B00702 generic re Tech Specs for IMI Lessons Learned Category A items is inadequate. Outstanding items emergency power supply relief & safety valve position indication.
IPPOLITO, T. A. Operating Reactors Branch 2. 81/01/02. 2pp. 07475 344

B101220411 Requests temporary relief from 5 F thermal rise limit & max reservoir temp rise of 8.5 F be granted until Apr 1981. Temp rise of 8.5 F will sustain 3-unit operation at facility w/current min hydro releases for navigation.
EL-ASHRY, M. T. Tennessee Valley Authority 81/01/14 3pp 07502 246.

B101220297 Grants request for temporary relief from permit condition re allowable temp rise within certain conditions. Temp at edge of mixing zone must not exhibit change greater than 8.5 F.
ZELLER, H. D. Environmental Protection Agency 81/01/18 2pp 07500 069

B101300493 Forwards response to NRC B01123 request for confirmation that NUREG-0619 implementation dates will be met. Info justifies continued operation.
MILLER, L. M. Tennessee Valley Authority 81/01/23 3pp 07183 001

Q. Inspection reports, IE Bulletins & correspondence

B101080184 Forwards update to B03104 response to IE Bulletin 79-26 boron loss from BWR control blades. Manpower required for review & preparation approx 20-h.
MILLER, L. M. Tennessee Valley Authority 80/11/25 3pp 03775

B101050588 Forwards IE Info Notice 80-43, "Failures of Continuous Level Monitor for BWR Discharge Val at Dresden Unit 2." No response required.
D'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/12/1p 07391 010

B101140866 Responds to IE Bulletin 80-23 Defective solenoid valves
w/ make & part numbers in Bulletin are not in use at
facilities
MILLS, L M Tennessee Valley Authority 80/12/15 1p 07461 053

B101060153 Forwards IE Info Notice 80-45, "Potential Failure of BWR
Backup Manual Scram Capability." No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/17
1p 07391 275

B101070002 Forwards Suppt 4 to IE Bulletin 80-17, "Failure of 76 of 805
Control Rods to Fully Insert During Scram at BWR." No
written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/18
1p 07417 323

B101050153 Forwards IE Bulletin 80-25, "Operating Problems W/Target
Rods Safety Relief Valves at BWRs." No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/19
2pp 07377 249

B101160252 Forwards response to IE Bulletin 80-07, "BWR Jet Pump
Assembly Failure." Ultrasonic & visual insp of jet pump
beams & assembly showed no problems
MILLS, L M Tennessee Valley Authority 80/12/30 2pp 07470 249

B101160734 Ack receipt of 801205 ltr informing NRC of supplemental
steps taken to correct violations noted in IE Insp Rept
80-260/80-28
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 80/12/31 1p 07472 064

--B101160759 Forwards supplemental response to NRC 801017 ltr re
violations noted in IE Insp Rept 80-260/80-28 Corrective
actions liquid penetrant test performed
MILLS, L M Tennessee Valley Authority 80/12/07 3pp
07472 065

B101210157 Informs that insp program re IE Bulletin 79-14 will not be
completed by 801125 due to delays in planned schedules
Revised insp schedule & Dec 1980 status rept encl
MILLS, L M Tennessee Valley Authority 81/01/05 30pp 07490 010

B101220376 Forwards results of spray sparger insp in response to IE
Bulletin 80-13, "Cracking in Core Spray Spargers"
MILLS, L M Tennessee Valley Authority 81/01/05 2pp 07500 294

B101280505 Forwards response to IE Bulletin 80-24, "Prevention of
Damage Due to Water Leakage (Oct 17, 1980 Indian Point 2
Event)." Components requiring supplemental cooling are
cooled by reactor bldg closed cooling water sys
MILLS, L M Tennessee Valley Authority 81/01/05 5pp 07550 319

B101280527 Forwards results of util analyses on diesel generators &
480 V load shed logic re IE Bulletin 80-06, "Engineered
Safety Feature (ESF) Reset Controls."
MILLS, L M Tennessee Valley Authority 81/01/14 2pp 07550 330

B101290350 Forwards monthly status rept as of B10101 for work re IE
Bulletin 79-14, "Seismic Analysis for As-Built
Safety-Related Piping Sys." Includes description of pipe
support & valve insp
MILLS, L M Tennessee Valley Authority 81/01/15 29pp 07572 327

R. Periodic operating reports & related correspondence

B101130582 Forwards monthly operating repts for Dec 1980
ABERCROMBIE, M Tennessee Valley Authority 81/01/09 1p
07453 215

--B101130588 Monthly operating repts for Dec 1980
THOM, T Tennessee Valley Authority 81/01/04 37pp 07453 236

B101130593 Forwards monthly operating repts for Dec 1980
ABERCROMBIE, M Tennessee Valley Authority 81/01/09 1p
07453 289

--B101130601 Monthly operating repts for Dec 1980
GREEN, H J THOM, T Tennessee Valley Authority 81/01/04 21pp
07453 289

S. Reportable occurrences, LERs & related correspondence

B101130429 Forwards LER 80-056/03L-0
GREEN, H J Tennessee Valley Authority 81/01/06 1p 07454 093

--B101130436 LER 80-056/03L-0 on 801215, reactor water 10
L18-3-56A switch 2 setpoint found outside of Tech Sp
limits Caused by Varway model 4418c setpoint drift S
recalibr & functionally tested for repeatability
* Tennessee Valley Authority 81/01/06 2pp 074

B101160490 Forwards LER 80-035/03L-0
GREEN, H J Tennessee Valley Authority 81/01/06 1p

--B101160498 LER 80-055/03L-0 on 801208, core spray disch
switch, 2-PB-75-16, found set outside Tech Spec limits
by Herco Model DA-700A-R04 setpoint drift. Switch
inspected & recalibr
* Tennessee Valley Authority 81/01/06 2pp 074

B101190490 Forwards LER 80-057/03L-0
GREEN, H J Tennessee Valley Authority 81/01/13 1p

--B101190495 LER 80-057/03L-0 on 801215, pressure switch
& PS-1-B, which monitor main steam line low pressure
found outside Tech Spec limits Caused by setpoint dr
Switches recalibr.
* Tennessee Valley Authority 81/01/13 2pp 074

B101220311 Forwards first interim rept re potential flame
suspended ceiling tile in control rooms in response to
801104 ltr Addl info to be provided by B10211
MILLS, L M Tennessee Valley Authority 81/01/14 3pp

B101220444 Forwards LER 81-001/01T-0
GREEN, H J Tennessee Valley Authority 81/01/15 1p

--B101220449 LER 81-001/01T-0 on 810102, scram discharge
2-LB-85-49A found inoperable & -C & -D found offscal
by one Robert Shaw switch model SL-305-EI-X sticking
setpoint drift stuck switches float chamber back flu
* Tennessee Valley Authority 81/01/15 2pp 075

B101300501 Forwards LER 80-059/03L-0
GREEN, H J Tennessee Valley Authority 81/01/26 1p

--B101300512 LER 80-059/03L-0 on 801230, FR-77-16 observ
during drywell equipment drain sump pump operation. C
shift in model 955 GE transmitter PT77-16 zero adjus
Transmitter recalibr, tested & returned to svc
* Tennessee Valley Authority 81/01/26 2pp 075

DOCKET 50-261 H U ROBINSON PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor pl
& CP applicants Revised radiological emergency respon
plans must be submitted by licensees within 60 days o
B10102 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing 80/11/13 2pp

B101140830 Advises of provisions of 10CFR50, App R, that
to fire protection features of facility, FR notice & s
of staff requirements to resolve open items encl W/O
EISENHUT, D G Division of Licensing 80/11/24, App

B101230058 Releases public version of util evaluation
FELTON, J M Division of Rules and Records 81/01/08
07511 026

--B101230066 Forwards public version of preliminary res
evaluation study for 10-mile emergency planning zon
response to NRC 791129 request Final rept will be a
approval B10201
UTLEY, F E Carolina Power & Light Co 80/12/29

B101210131 Releases public version of util revised emer
FELTON, J M Division of Rules and Records 81/01/13
07491 103

--B101210137 Forwards public version of revised radiolo
response plan, including State of SC emergency plan.
replaces Vol 13 of facility operating manual Cross-
to NUREG-0654 criteria encl W/O revised of SC plan.
UTLEY, F E Carolina Power & Light Co 80/12/30

--B101210144 Public version of revised emergency respon
of SC emergency plan.

B101230600 Requests exemption from App R Requirement III D requiring installation of lube oil collection for fire protection.
UTLEY, E E Carolina Power & Light Co. 01/01/19 2pp 07510 316

Q. Adjudicatory correspondence

B101100646 Forwards revised order for mod of license, correcting refs in 800B29 order Hearing date also revised
EISENHUT, D O Division of Licensing 00/09/19 2pp 07443 150

--B101100654 Revised order amending License DPR-23 info requested by IE Bulletin 79-01B must be submitted to IE by 001101
EISENHUT, D O Division of Licensing 00/09/19 6pp 07443 152

P. Operating license stage documents & correspondence

B101100646 Forwards revised order for mod of license, correcting refs in 800B29 order Hearing date also revised
EISENHUT, D O Division of Licensing 00/09/19 2pp 07443 150

--B101100654 Revised order amending License DPR-23 info requested by IE Bulletin 79-01B must be submitted to IE by 001101
EISENHUT, D O Division of Licensing 00/09/19 6pp 07443 152

B101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under B18 License amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT, D O Division of Licensing 00/11/20 1p

--B101100271 Revised Pages 3/4 7-22 through 20.B 3/4 7-5 & 7-h & 6-17 to B18 snubber inservice insp requirements
* Division of Licensing 00/11/20 10pp

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of 001112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 00/11/26 8pp

B101050110 Forwards interim safety evaluation for auxiliary feedwater sys Tech Specs for plant operation w/inoperable auxiliary feedwater pumps & commitment to meet 020101 date for implementing long-term auxiliary feedwater mod required
VARQA, S A Operating Reactors Branch 1 00/12/02 2pp 07379 265

--B101050113 Safety evaluation supporting util commitment to provide auxiliary feedwater sys reliability
* Division of Licensing 00/12/02 20pp 07379 267

B101210445 Forwards responses to questions on Rule 90.71e, "Periodic Updating of FBARs" & FR notice of final rule. SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame
EISENHUT, D O Division of Licensing 00/12/15 13pp

B101290617 Forwards Amend 54 to License DPR-23 & notice of issuance & availability
VARQA, S A Operating Reactors Branch 1 00/12/10 3pp 07571 317

--B101290622 Amend 94 to License DPR-23, requiring secondary water chemistry program to inhibit steam generator tube degradation
VARQA, S A Operating Reactors Branch 1 00/12/10 2pp 07571 320

--B101290625 Notice of issuance & availability of Amend 54 to License DPR-23
VARQA, S A Operating Reactors Branch 1 00/12/10 2pp 07571 322

B101190355 Forwards list of TLD station locations near facility & proposed route for exchanging TLDs for NRC direct radiation monitoring network w/o encls.
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 00/12/30 2pp 07476 080

B101060453 Forwards "Control Room Habitability Evaluation, HB Robinson Steam Electric Generating Plant (NRC TMI Action Plan Item III D.3.4.)"
UTLEY, E E Carolina Power & Light Co 00/12/31 3pp 07398 223

--B101060457 "Control Room Habitability Evaluation, HB Robinson Steam Electric Generating Plant (NRC TMI Action Plan Item III D.3.4.)"
SLIDER, J E, ARCIERI, W C, NAFT, B. N. NUS Corp. NUS-3696 00/12/31 79pp 07398 226

B101060465 Provides documentation of NUREG-0737 items Submittals re emergency preparedness & control room habitability forthcoming
UTLEY, E E Carolina Power & Light Co 00/12/31 52pp 07398 14

B101150610 Forwards response to outstanding items re NRC interim safety evaluation of auxiliary feedwater sys reliability, per NRC 001202 request
UTLEY, E E Carolina Power & Light Co 01/01/09 8pp 07462 246

B101290345 Forwards request for addl info re adequacy of station electric distribution sys voltages w/n encl
VARQA, S A Operating Reactors Branch 1 01/01/13 1p 07573 31

B101300042 Forwards Amend 55 to License DPR-23, safety evaluation & notice of issuance & availability
VARQA, S A Operating Reactors Branch 1 01/01/16 2pp 07503 14

--B101300050 Amend 55 to License DPR-23, adding operability requirements for boron injection tank heat tracing channels consistent w/other Tech Spec requirements for similar sys
VARQA, S A Operating Reactors Branch 1 01/01/16 4pp 07503 109

--B101300057 Safety evaluation supporting Amend 55 to License DPR-23
* Office of Nuclear Reactor Regulation, Director 01/01/16 07503 013

--B101300065 Notice of issuance & availability of Amend 55 to License DPR-23
VARQA, S A Operating Reactors Branch 1 01/01/16 2pp 07503 015

Q. Inspection reports, IE Bulletins & correspondence

B101050184 Forwards Revision 2 to HB Robinson & Revision 1 to Brunswick 90-day repts w/o Brunswick rept
FURR, B J Carolina Power & Light Co 00/11/21 2pp 07380 001

--B101050194 Revision 2 to "Environ Qualification of Electrical Equipment HB Robinson EQ Plant Unit 2," 90-day rept
* Carolina Power & Light Co 00/11/01 100pp 07380 004

B101050124 Requests existing data, summaries & records of inservice tests of containments w/greased prestressing tendons, DRHL receiving contract to compile & review records of tendons
EISENHUT, D O Division of Licensing 00/11/25 3pp

B101100310 Forwards IE Insp Rept 50-261/00-33 on 001028-30 No noncompliance noted
KEENA, W B Region 2, Atlanta, Safeguards Branch 00/11/26 2pp 07443 233

--B101100320 IE Insp Rept 50-261/00-33 on 001028-30 No noncompliance noted Major areas inspected: cell control & accounting
HODGES, J H, KAHLE, J D Region 2, Atlanta, Safeguards Branch 00/11/26 4pp 07443 233

B101100323 Forwards IE Insp Rept 50-261/00-33 on 001027-31 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/11/28 2pp 07443 239

--B101100326 IE Insp Rept 50-261/00-33 on 001027-31 No noncompliance noted Major areas inspected: general plant operations
BROOKS, E H Region 2, Atlanta, Office of the Director, GUICK, Region 2, Atlanta, Reactor Operations Nuclear Support Branch 00/11/26 4pp 07443 241

B101120289 Suppl response to IE Bulletin 00-15 re emergency notification sys operability following loss of offsite power Test to be performed no later than 010101
FURR, B J Carolina Power & Light Co 00/12/15 2pp 07442 325

B101060233 Forwards IE Info Notice 00-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown" No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 00/12/1p 07391 341

B101220412 Forwards interim response to IE Bulletin 00-24, "Prevention of Damage Due to Water Leakage Inside Containment" Formal response will be provided by 010120, per 001229 telcon w/P Kellogg
FURR, B J Carolina Power & Light Co 01/01/05 12pp 07500 22

8/10100343 Ltr to all power reactor licensees w/plants licensed to 790101 Forwards revised Section 10CFR50.48 & App R re fire protection features in nuclear power plants & lists of requirements for resolution of open issues
EISENHUT.D.O. Division of Licensing 80/11/24 8pp. 07445

8/1010909 Forwards facility emergency planning info to be made publicly available w/o encl
SEUDER, J.L. Division of Rules and Records 80/12/17 1p 07427 359

8/10100745 Requests that encl facility emergency planning info be publicly available w/o encl
SEUDER, J.L. Division of Rules and Records 80/12/31 1p. 07445 130

8/10160028 Responds to 801121 & 29 ltrs requesting ltr of support facility emergency plan NRC will respond as described in encl NUREG-072B in event of facility emergency w/o encl
NEPPLER, J.O. Region 3, Chicago, Office of the Director 81/1/1p. 07467 322

--8/101160034 Requests ltr of support re facility emergency plan attached
HYDSON, G.O. Northern States Power Co 80/11/25 2pp 07445 130

G. Adjudicatory correspondence

8/101300386 Forwards NRC 801113 order modifying license & granting extension of exemption from General Design Criterion 50. Reassessment of containment design for suppression pool by hydrodynamic loading conditions is required.
IPPOLITO, T.A. Operating Reactors Branch 2. 01/01/13 3pp. 07586 352

--8/101300395 Order modifying license & granting extension of exemption from General Design Criterion 50. Reassessment of containment design for suppression pool hydrodynamic loading conditions is required. Mods must be installed by 80Q430.
EISENHUT.D.O. Division of Licensing 81/01/13 7pp. 07586 352

H. General correspondence

8/101100336 Responds to 801021 ltr requesting info re facility requested except for security can be inspected at PDR in Minneapolis, MN
IPPOLITO, T.A. Operating Reactors Branch 2 80/11/17 2pp. 07309 001

8/101290459 Responds to 801203 request for info re emergency preparedness near facilities for response to D Carlson 801101 concerns. FEMA working w/state & local govt to assure that planning & preparedness are completed
DIRKMS, W.J. Office of the Executive Director for Operations 81/01/02 1p 07576 141

--8/101290667 Forwards D Carlson 801101 ltr re emergency planning facilities Requests response
PROXMIER, W. Senate. 80/12/03 3pp 07576 142.

P. Operating license stage documents & correspondence

8/101100254 Ltr to all licensees (except SEP licensees) forward Revision 1 of inservice surveillance requirements for snubbers under STS License amend application adding model Tech Spec to App A should be submitted within 120 days
EISENHUT.D.O. Division of Licensing 80/11/20 1p.

--8/101100271 Revised Pages 3/4 7-22 through 28.B 3/4 7-5 & 7-4 STS snubber inservice insp requirements
Division of Licensing. 80/11/20 10pp

8/101220466 Ltr to all power reactor licensees & applicants for summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT.D.O. Division of Licensing. 80/11/26 8pp

8/101190113 Ltr to all BWR licensees forwarding 801201 generic evaluation re BWR steam discharge sys. Recommends short-term actions necessary to assure safe operation of OE BWRs pending permanent design changes.
EISENHUT.D.O. Division of Licensing. 80/12/09. 2pp.

--8/101190141 Generic safety evaluation re short-term actions to assure continued safe operation of operating BWRs. Continuous operation of plants is acceptable pending permanent design mods. Criteria for implementing design mods encl.
Division of Licensing 80/12/01. 212pp. 07183 001.

8/10100343 Ltr to all power reactor licensees w/plants licensed to 790101 Forwards revised Section 10CFR50.48 & App R re fire protection features in nuclear power plants & lists of requirements for resolution of open issues
EISENHUT.D.O. Division of Licensing 80/11/24 8pp. 07445

8/1010909 Forwards facility emergency planning info to be made publicly available w/o encl
SEUDER, J.L. Division of Rules and Records 80/12/17 1p 07427 359

8/10100745 Requests that encl facility emergency planning info be publicly available w/o encl
SEUDER, J.L. Division of Rules and Records 80/12/31 1p. 07445 130

8/10160028 Responds to 801121 & 29 ltrs requesting ltr of support facility emergency plan NRC will respond as described in encl NUREG-072B in event of facility emergency w/o encl
NEPPLER, J.O. Region 3, Chicago, Office of the Director 81/1/1p. 07467 322

--8/101160034 Requests ltr of support re facility emergency plan attached
HYDSON, G.O. Northern States Power Co 80/11/25 2pp 07445 130

G. Adjudicatory correspondence

8/101300386 Forwards NRC 801113 order modifying license & granting extension of exemption from General Design Criterion 50. Reassessment of containment design for suppression pool by hydrodynamic loading conditions is required.
IPPOLITO, T.A. Operating Reactors Branch 2. 01/01/13 3pp. 07586 352

--8/101300395 Order modifying license & granting extension of exemption from General Design Criterion 50. Reassessment of containment design for suppression pool hydrodynamic loading conditions is required. Mods must be installed by 80Q430.
EISENHUT.D.O. Division of Licensing 81/01/13 7pp. 07586 352

H. General correspondence

8/101100336 Responds to 801021 ltr requesting info re facility requested except for security can be inspected at PDR in Minneapolis, MN
IPPOLITO, T.A. Operating Reactors Branch 2 80/11/17 2pp. 07309 001

8/101290459 Responds to 801203 request for info re emergency preparedness near facilities for response to D Carlson 801101 concerns. FEMA working w/state & local govt to assure that planning & preparedness are completed
DIRKMS, W.J. Office of the Executive Director for Operations 81/01/02 1p 07576 141

--8/101290667 Forwards D Carlson 801101 ltr re emergency planning facilities Requests response
PROXMIER, W. Senate. 80/12/03 3pp 07576 142.

P. Operating license stage documents & correspondence

8/101100254 Ltr to all licensees (except SEP licensees) forward Revision 1 of inservice surveillance requirements for snubbers under STS License amend application adding model Tech Spec to App A should be submitted within 120 days
EISENHUT.D.O. Division of Licensing 80/11/20 1p.

--8/101100271 Revised Pages 3/4 7-22 through 28.B 3/4 7-5 & 7-4 STS snubber inservice insp requirements
Division of Licensing. 80/11/20 10pp

8/101220466 Ltr to all power reactor licensees & applicants for summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT.D.O. Division of Licensing. 80/11/26 8pp

8/101190113 Ltr to all BWR licensees forwarding 801201 generic evaluation re BWR steam discharge sys. Recommends short-term actions necessary to assure safe operation of OE BWRs pending permanent design changes.
EISENHUT.D.O. Division of Licensing. 80/12/09. 2pp.

--8/101190141 Generic safety evaluation re short-term actions to assure continued safe operation of operating BWRs. Continuous operation of plants is acceptable pending permanent design mods. Criteria for implementing design mods encl.
Division of Licensing 80/12/01. 212pp. 07183 001.

0101050278 Forwards commitments to implementation dates specified in NUREG-0737 re hardware, procedural & organizational requirements Remaining submittals re design descriptions & evaluations will be provided by 010201
MAYER, L O Northern States Power Co 00/12/30 19pp 07375 317

0101050190 Forwards IE Bulletin 00-25, "Operating Problems w/Target Rock Safety Relief Valves at NRS" No response required
KEPPLER, J G Region 3, Chicago, Office of the Director 00/12/19
2pp 07377 323

0101120218 Forwards schedule of projected completion dates for Mark I containment long-term program re installation of major plant rods
MAYER, L O Northern States Power Co 01/01/08 2pp 07445 292

0101130118 Responds to Items 1, 2, 3 & 5 of Suppl 4 to IE Bulletin 00-1 re failure of control rods to fully insert during scram at BWR Two unplanned scrams occurred on 000829 & 0904
Procedures revised to include manual check
GILBERTS, D E Northern States Power Co 00/12/23 4pp 07449 24

0101300386 Forwards NRC 010113 order modifying license & granting extension of exemption from General Design Criterion 50 Reassessment of containment design for suppression pool by hydrodynamic loading conditions is required
IPPDLIFF, T A Operating Reactors Branch 2 01/01/13 3pp 07586 352

0101190274 Forwards addl response to IE Bulletin 00-17, Suppl 4, "Failure of 7d of 105 Control Rods to Fully Insert During Scram at BWR" Schematic & instruction manual for scram discharge vol water level monitoring system
GILBERTS, D E Northern States Power Co 00/12/30 2pp 07475 037

--0101300395 Order modifying license & granting extension of exemption from General Design Criterion 50 Reassessment of containment design for suppression pool hydrodynamic loading conditions is required Rods must be installed by 020430
EISENHUT, D O Division of Licensing 01/01/13 7pp 07586 355

0101140156 Informs that commitment to IE Bulletin 79-19 re upgrading training program for maint personnel not met Compliance expected by 010201
GILBERTS, D E Northern States Power Co 00/12/31 1p 07460 334

0 Inspection reports, IE Bulletins & correspondence

0101200170 Responds to IE Bulletin 00-24, "Prevention of Damage Due to Water Leakage Inside Containment (01017 Indian Point 2 Event)" Facility has no open cooling water sys inside containment
GILBERTS, D E Northern States Power Co 01/01/05 2pp 07186 20

0101100340 Forwards IE Insp Rept 50-263/00-16 on 000801-31 & notices of violation, Apps A & B App B withheld (ref 10CFR2 790)
EISENHUT, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 00/10/09 2pp 07443 333

0101230490 Responds to NRC 001229 request for addl info re facility inservice insp program Forwards Revision 1 to NEDO-24197, "Info on Reactor Vessel Matl Surveillance Program"
MAYER, L O Northern States Power Co 01/01/20 6pp 07183 001

--0101100353 Notice of violation App A, from insp on 000801-31
* Region 3, Chicago, Office of the Director 00/10/07 1p 07443 335

--0101230494 "Info on Reactor Vessel Matl Surveillance Program" Revision 1
* General Electric Co NEDO-24197 R1 79/10/31 12pp 07183 001

--0101100361 IE Insp Rept 50-263/00-16 on 000801-31 Noncompliance noted failure to control access to protected areas & failure to follow maint procedures Attachment A withheld (ref 10CFR2 790)
LITTLE, W S, BROWN, C H, MADIBON, A L Region 3, Chicago, Office of the Director 00/10/07 9pp 07443 336

0101260491 Forwards addl info re inservice insp program re ASME Code Section XI, in response to NRC 001229 request Info provided re relief requests from weld exams & estimated man-rem exposures from volumetric exams
MAYER, L O Northern States Power Co 01/01/20 6pp 07950 107

0101090266 Forwards IE Info Notice 00-30, "Cracking in Charging Pump Casing Cladding" No response required
KEPPLER, J G Region 3, Chicago, Office of the Director 00/10/30 2pp 07389 160

R Periodic operating reports & related correspondence

0101100796 Forwards IE Circular 00-23, "Potential Defects in Beloit Power Sys Emergency Generators" No written response required
KEPPLER, J G Region 3, Chicago, Office of the Director 00/10/31 2pp 07444 117

0101130579 Forwards monthly operating rept for Dec 1980
MAYER, L O Northern States Power Co 01/01/09 1p 07309 001

0101060609 Forwards IE Info Notice 00-40, "Excessive Nitrogen Supply Pressure Actuates Safety-Relief Valve Operation to Cause Reactor Depressurization" No written response required
KEPPLER, J G Region 3, Chicago, Office of the Director 00/11/07 2pp 07401 116

--0101130581 Monthly operating rept for Dec 1980
MYRAGU, A L Northern States Power Co 01/01/02 3pp 07309 001

0101060367 Forwards IE Info Notice 00-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1" No response required
KEPPLER, J G Region 3, Chicago, Office of the Director 00/11/10 2pp 07391 067

0101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants, Revised radiological emergency response plans must be submitted by licensees within 60 days of 010102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 00/11/13 2pp

0101140504 Forwards IE Insp Rept 50-263/00-19 on 001001-31, No noncompliance noted
EISENHUT, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 00/12/05 2pp 07461 149

H General correspondence

--0101140510 IE Insp Rept 50-263/00-19 on 001001-31, No noncompliance noted Major areas inspected: routine operations, logs & records housekeeping & routine radiation protection
BROWN, C H, MADIBON, A L, LITTLE, W S Region 3, Chicago, Office of the Director 00/12/03 4pp 07461 151

0101290518 Advises that future correspondence should be addressed to II, Dept of Nuclear Safety, 1035 Outer Park Drive, 5th Floor Springfield, IL 62704
WRIGHT, G H Illinois, State of 01/01/22 1p

0101080038 Forwards IE Info Notice 00-45, "Potential Failure of BWR Backup Manual Scram Capability" No written response required
KEPPLER, J G Region 3, Chicago, Office of the Director 00/12/17 2pp 07419 350

J Insurance & indemnity information

0101090608 Forwards guarantee of payment of deferred premiums for 1980
OSTER, J Commonwealth Edison Co 01/01/05 1p

0101270737 Forwards Endorsement 4 to Binders 00-1, 00-2, 00-3, 00-29, 00-30, 00-42 & 00-43 evidencing secondary financial protection
OSTER, J Commonwealth Edison Co 01/01/21 8pp

P Operating license stage documents & correspondence

B101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for scrubbers under STS License amend application adding rod Tech Specs to App A should be submitted within 120 days
EISENHUT.D G Division of Licensing 80/11/20 1p

--B101100271 Revised Pages 3/4 7-22 through 23.B 3/4 7-5 & 7-6 & 6-17 to STS scrubber inservice insp requirements
* Division of Licensing 80/11/20 10pp

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT.D G Division of Licensing 80/11/26 8pp

B101190113 Ltr to all BWR licensees forwarding B01201 generic safety evaluation re BWR scram discharge sys Recommends short-term actions necessary to assure safe operation of CE BWRs pending permanent design changes
EISENHUT.D G Division of Licensing 80/12/09 2pp

--B101190141 Generic safety evaluation re short-term actions required to assure continued safe operation of operating BWRs Continued operation of plants is acceptable pending permanent design mods Criteria for implementing design mods encl
* Division of Licensing 80/12/01 21pp 07183 001

B101210445 Forwards Responses to questions on Rule 50.71e. "Periodic Updating of FSARs & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame.
EISENHUT.D G Division of Licensing 80/12/15 13pp

B101040376 Submits addl response to NRC B00822 ltr Evaluation of Pratt & Whitney butterfly valve demonstrates that loads imposed & stresses developed in components during valve closure under LOCA event fall within acceptable limits
JANECEK.R F Commonwealth Edison Co 80/12/26 2pp

B101050066 Forwards AMI rept. "Failure Analysis of Cracked Core Spray Piping from Quad Cities Unit 2 BWR"
JANECEK.R F Commonwealth Edison Co 80/12/29 1p 07376 236

--B101050070 Failure Analysis of Cracked Core Spray Piping from Quad Cities Unit 2 BWR
DIERCKH.D R, FRACFL.G M Argonne National Laboratory. 80/07/31 46pp 07376 237

B101050500 Forwards response to NUREG-0737 No response provided for Dresden 1 Unit undergoing extensive mod & decontamination outage Requirements of NUREG-0737 will be addressed prior to startup of unit scheduled for June 1986
ABEL.J S Commonwealth Edison Co. 80/12/31 58pp

B101300154 "Adequacy of Station Electric Distribution Sys Voltages. Quad Cities Units 1 & 2"
UDY.A.C E0610 Idaho, Inc. FIN A-6236 B101300154 80/12/31 9pp 07583 114

B101090001 Forwards Revision 15 pages to CE-1-A QA program topical rept. Revisions reflect Summer 1980 addenda to Section III of ASME code & recent ASME survey for renewal of ASME corporate certifications
ABEL.J S Commonwealth Edison Co. 81/01/02 1p

--B101090005 Revision 15 pages to QA program topical rept
* Commonwealth Edison Co. CE-1-A R15 81/01/02 37pp

B101130237 Submits schedule for completion of torus attached piping sys mods Schedules based upon preliminary engineering analysis completed to date
REED.D C Commonwealth Edison Co 81/01/08 1p

B101300233 Forwards NRC B10113 orders for mod of licenses & granting extension of exemption Licensee must reassess suppression pool hydrodynamic loads & complete mods to meet General Design Criterion 50
PPDOLITO.T.A Operating Reactors Branch 2 81/01/13 3pp

B101200296 Advises that scram discharge sys re-evaluation has been completed. In response to NRC B01001 ltr Necessary mods will be implemented in first refueling outage beginning 223101.
JANECEK.R F Commonwealth Edison Co. 81/01/15 2pp

B101220368 Forwards offsite dose calculation sys description per meteorological data requirements in NUREG-0737 Task
B11 A 2
CELGEORGE.L D Commonwealth Edison Co 81/01/19 1p

--B101220374 "Offsite Dose Calculation Sys Meteorological Monitoring Offsite Dose Calculation Program for Emergency Preparedness at Operating Nuclear Power Plants." Revision 2
GOLDEN.J C Commonwealth Edison Co 80/07/31 130pp

--B101220379 "Study of Low Level Dispersion Over Northern IL"
* Murray & Trettel, Inc 74/06/30 106pp

B101270481 Advises of concurrence w/NUREG-0619 re feedwater nozzles control rod drive return line nozzle cracking. In response to NRC B01113 ltr Results of further evaluations will be submitted by B10220
JANECEK.R F Commonwealth Edison Co 81/01/22 2pp

0 Inspection reports, IE Bulletins & correspondence

B101050249 Forwards IE Info Notice 80-3B. "Cracking in Charging Pump Casing Cladding" No response required
KEPPLER.J G Region 3, Chicago, Office of the Director 80/10/30 2pp

B101050462 Forwards IE Bulletin 80-21. "Valve Yokes Supplied by Melroe Foundry Co, Inc." Written response required
KEPPLER.J G Region 3, Chicago, Office of the Director 80/11/08 2pp

B101100115 Forwards IE Insp Repts 50-254/80-23 & 50-265/80-25 on B00902-03, 18-19, 100B, 15-16 & 1106 No noncompliance noted.
FIORELLI.O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/11/24 2pp 07441 318

--B101100153 IE Insp Repts 50-254/80-23 & 50-265/80-25 No noncompliance noted Major areas inspected: QA/QC program, inservice insp data-torus mod & activities per IE Bulletins 79-03A, 80-08 & 80-13
WARD.K D Region 3, Chicago, Office of the Director.
DANIELSON.D H Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/11/19 11pp 07441 320

B101080079 Forwards IE Insp Repts 50-254/80-23 & 50-265/80-26 on B01020-1124 & notice of violation.
HEISHMAN.R F Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/11/28 2pp 07421 001

--B101080083 Notice of violation from insp on B01020-1124
* Region 3, Chicago, Office of the Director. 80/11/28 1p 07421 003

--B101080092 IE Insp Repts 50-254/80-23 & 50-265/80-26 on B01020-1124 Noncompliance noted: incorrect surveillance performed for inoperable diesel generator Inadequate testing resulted in pump failure
SPESBARO.R.L., CHIRBSOFIMOS.N., DUPONT.B G. Region 3, Chicago, Office of the Director 80/11/28 14pp 07421 004

B101090000 Ack receipt of B01112 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-254/80-20 & 50-265/80-22
KEPPLER.J G Region 3, Chicago, Office of the Director. 80/12/01 07187 001

--B101090810 Responds to NRC B01021 ltr re violations noted in IE Insp Repts 50-254/80-20 & 50-265/80-22 Corrective actions: lead blankets added to piping & ladder by Unit 2 CRD accumulators removed.
ABEL.J S. Commonwealth Edison Co. 80/11/12 10pp 07187 001

B101050530 Forwards IE Info Notice 80-43. "Failures of Continuous W Level Monitor for Scram Discharge Vol at Dresden Unit 2" No response required
KEPPLER.J G Region 3, Chicago, Office of the Director. 80/12/02 2pp

B101090234 Ack receipt of B01201 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-254/80-20 & 50-265/80-24
HEISHMAN.R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/12/09 1p 07423 274

--B101090244 Responds to NRC B01106 ltr re violations noted in IE Insp Repts 50-254/80-22 & 50-265/80-24 Corrective actions: closed charging water isolation valves & resumed control rod blade

8101060073 Responds to IE Bulletin 80-23, "Failures of Solenoid Valves
Mfg. by Valtor Engineering Corp." Valves V70900-21-1 or
V70900-21-3 not used in any safety-related functions. Approx
40 manhours expended in bulletin review.
RAUBCH, T. J. Commonwealth Edison Co. 80/12/12. 1p

8101060060 Forwards IE Info Notice 80-45, "Potential Failure of BWR
Backup Manual Scram Capability." No written response
required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/12/17
2pp.

8101150240 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of Control
Rods to Insert During Scram at BWR." Written response
required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/12/18
1p.

8101290434 Forwards IE Insp Repts 90-254/80-28 & 90-265/80-29 on
801119-20. No noncompliance noted.
PIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/12/18 2pp 07570:325.

--8101290438 IE Insp Repts 90-254/80-28 & 90-265/80-29 on 801119-20 No
noncompliance noted. Major areas inspected. Licensee actions
re IE Bulletin 79-14.
YIN, I. T. Region 3, Chicago, Office of the Director.
DANIELSON, D. H. Region 3, Chicago, Reactor Construction &
Engineering Support Branch 80/12/18 3pp 07570:327

8101050170 Forwards IE Bulletin 80-25, "Operating Problems W/Target
Rock Safety Relief Valves at BWRs." No response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/12/19.
2pp.

8101080093 Responds to NRC 800810 request for monthly status rept re
evaluations in response to IE Bulletin 79-14 Tabulations of
piping sys w/stresses above FSAR levels & below operability
limit encl.
JANECEK, R. F. Commonwealth Edison Co. 80/12/22 5pp

8101130198 Forwards IE Insp Repts 90-254/80-29 & 90-265/80-30 on
801208-12. No noncompliance noted.
HIND, J. A. Region 3, Chicago, Safeguards Branch 80/12/24. 2pp
07452:083.

--8101130206 IE Insp Repts 90-254/80-29 & 90-265/80-30 on 801208-12 No
noncompliance noted. Major areas inspected. security plan &
program audit Details withheld (ref 10CFR2.790).
CHRISTOFFER, G., KNICELEY, J. R. Region 3, Chicago, Office of the
Director HIND, J. A. Region 3, Chicago, Safeguards Branch.
80/12/23. 2pp. 07452:085

8101200135 Forwards addl response to IE Bulletin 79-14, "Seismic
Analysis for As-Built Safety-Related Piping Sys." Revised
initial acceptance allowables for combined piping sys
stresses during BBE event provided.
JANECEK, R. F. Commonwealth Edison Co. 81/01/05. 6pp

8101200155 Forwards response to IE Bulletin 80-24, "Prevention of
Damage Due to Water Leakage Inside Containment (801017
Indian Point 2 Event)." Surveillance procedures, of at least
monthly repetition, will be instituted by 810601.
RAUBCH, T. J. Commonwealth Edison Co. 81/01/05. 6pp.

R Periodic operating reports & related correspondence

8101120153 Forwards "Environ Dose Pathway Study," Spring 1979 through
Summer 1980.
JANECEK, R. F. Commonwealth Edison Co. 80/12/30. 1p. 07446:168

--8101120156 "Environ Dose Pathway Study," Spring 1979 through Summer
1980.
Eberline Instrument Corp. 80/12/30. 44pp. 07446:169.

8101200302 Forwards list of changes, test & experiments completed during
Dec 1980
KALIVIANAKIS, N. Commonwealth Edison Co. 81/01/02 5pp. 07486:262

8101210463 Forwards monthly operating repts for Dec 1980.
KALIVIANAKIS, N. Commonwealth Edison Co. 81/01/02 1p. 07493:107

--8101210465 Monthly operating repts for Dec 1980
TUBBS, R. C. Commonwealth Edison Co. 81/01/01 32pp 07493:108

S Reportable occurrences, LERs & related correspondence

8101060472 Forwards LER 90-033/03L-0
KALIVIANAKIS, N. Commonwealth Edison Co. 80/12/29 1p 07

--8101060482 LER 80-033/03L-0 on 801201. RHR sys 11 supply from
generator alarmed. Caused by blown fuse F11 due to grounded
wire in Unit 2 diesel generator to bus 24-1 circuit
breaker auxiliary contacts. Wire repaired & fuse replaced.
CLARK, D. Commonwealth Edison Co. 80/12/29 2pp 07391

8101060486 Forwards LER 90-036/03L-0
KALIVIANAKIS, N. Commonwealth Edison Co. 80/12/29 1p 07

--8101060492 LER 80-036/03L-0 on 801203. electromagnetic relief va
3D failed to open during reactor pressure rise subsequent
scram. Caused by excessive steam leakage between retainer
plug into vol below main disc Valve replaced.
KOPACZ, J. J. Commonwealth Edison Co. 80/12/29 2pp 073

8101130958 Forwards LER 80-037/03L-0
KALIVIANAKIS, N. Commonwealth Edison Co. 80/12/29 1p 07

--8101130605 LER 80-037/03L-0 on 801207. RHR 2D pump inoperable
excessive leakage of mechanical seal. Caused by normal wear
of O-ring sealing surface. Mechanical seal replaced. Pump
returned to svc & satisfactorily tested.
MENDENHALL, E. E. Commonwealth Edison Co. 80/12/29 2pp
07493:329

8101270740 Forwards LER 80-038/03L-0
KALIVIANAKIS, N. Commonwealth Edison Co. 81/01/07 1p 07

--8101270755 LER 80-058/03L-0 on 801210. series of six trips oc
2A reactor recirculation pump motor generator set field
breaker. Caused by defective tachometer which controls pump
speed Tachometer was replaced on 801231
WYKOFF, D. L. Commonwealth Edison Co. 81/01/07 2pp. 073

DOCKET 90-266 POINT BEACH NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP
& CP applicants. Revised radiological emergency response
plans must be submitted by licensees within 60 days of
810102 & by applicants as part of FSAR
EISENHUT, D. O. Division of Licensing 80/11/13 2pp

8101090110 Releases public version of util preliminary draft e
plan
FELTON, J. M. Division of Rules and Records 80/12/01 1p
07428:001

--8101090113 Forwards public version of preliminary draft emer
FAY, C. W. Wisconsin Electric Power Co. 80/07/25 1p 07

--8101090115 Forwards public version of preliminary draft emer
FAY, C. W. Wisconsin Electric Power Co. 80/07/25 1p 07

--8101090118 Public version of preliminary draft emergency pla
Wisconsin Electric Power Co. 80/07/31. 200pp. 07428

8101090916 Forwards facility emergency planning info to be mad
publicly available W/o encl
SOUDEK, J. L. Division of Rules and Records. 80/12/16 1p
07427:360

8101190297 Forwards request for addl info re 800822 revised sa
contingency plan. Revised plan is acceptable, but approval is
subj to responsibility matrix section mods. Requests response
within 60 days. Request withheld (ref 10CFR2.790)
CLARK, R. A. Operating Reactors Branch 3 80/12/19 2pp 0

8101260340 Requests that completion date for fire protection p
extended to 81117 to provide time required for installation
of portable diesel generator panels w/modified carbon dioxide
extinguishing sys nozzles & light fixture diffusers
FAY, C. W. Wisconsin Electric Power Co. 81/01/20 2pp 075

8101290148 Forwards facility emergency planning info to be mad
publicly available W/o encl
SOUDEK, J. L. Division of Rules and Records 81/01/23 1p.
07575:396

8101220403 Discusses PSC of WI processes for review & assessment of economic & environ impact of proposed alternative actions & of generating replacement power. Forwards application for steam generator replacement
FAY, C W Wisconsin Electric Power Co 81/01/16 4pp 07501 269

--8101220415 Application for authority to replace steam generators at facility. Requests Certificate of Authority per State of WI statutes to acquire, but not install, replacement generators. Certificate of Svc 5 util environ info encl.
MCNEER, C S Wisconsin Electric Power Co 80/12/05 26pp. 07501 289

0 Operating license stage documents & correspondence

8101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for injectors under 51B License amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT, D G Division of Licensing 80/11/20 1p

--8101100271 Revised Pages 3/4 7-22 through 28.9 3/4 7-5 & 7-6 & 6-17 to SFS shutter inservice insp requirements
Division of Licensing 80/11/20 10pp

8101220465 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12. Potential for Low Fracture Toughness & Laminar Tearing on Component Supports.
EISENHUT, D G Division of Licensing 80/11/25 8pp

8101210445 Forwards responses to questions on Rule 50.71e. "Periodic Updating of FSARs" & FR notice of final rule. SEP plants need not comply w/rule until program is complete. Non-SEP plants must comply within specified time frame
EISENHUT, D G Division of Licensing 80/12/15 12pp.

8101100510 Forwards Amends 46 & 51 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability
CLARK, R A Operating Reactors Branch 3 80/12/17 2pp 07445 059.

--8101100527 Amends 46 & 51 to Licensees DPR-24 & DPR-27, respectively, changing Tech Specs to eliminate procedural steps for testing of containment spray additive valves
CLARK, R A Operating Reactors Branch 3 80/12/17 6pp 07445 091

--8101100526 Safety evaluation supporting Amends 46 & 51 to Licensees DPR-24 & DPR-27, respectively
Operating Reactors Branch 3. 80/12/17 2pp 07445:097

--8101100543 Notice of issuance & availability of Amends 46 & 51 to Licensees DPR-24 & DPR-27, respectively
CLARK, R A Operating Reactors Branch 3 80/12/17 2pp. 07445 099

8101100195 Informs that addl duplicate amend fee for B00919 application is still applicable as second unit required addl administrative review. In response to B01114 ltr
MILLER, W D License Fee Management Branch 80/12/19. 1p. 07309 001

8101300175 "Instrument Bus Mods, Point Beach Nuclear Plant, Units 1 & 2"
MAYS, S E. EG&G Idaho, Inc. FIM A-6256 8101300175 80/12/31. 4pp 07583 185.

8101210564 Forwards addl response to NJREQ-0737 re post-TMI requirements for operating plants. Meteorology submittal completed. Control room habitability evaluation will be provided by B1C206
FAY, C W Wisconsin Electric Power Co 81/01/09. 10pp 07489 256

8101160451 Responds to NRC B01219 request for second Class I license amend approval. Fee for B00919 Tech Spec Change Request 6A. No addl administrative effort required for issuance of Tech Spec pages for second unit.
BURSTEIN, B. Wisconsin Electric Power Co 81/01/13. 2pp 07469 397

8101260410 Forwards revised Page 7 to B01223 response to NJREQ-0737, Item II, K 3 12
FAY, C W Wisconsin Electric Power Co 81/01/19 2pp 07522 260.

0 Inspection reports, IE Bulletins & correspondence

8101050225 Forwards IE Info Notice B0-38. "Cracking in Charging Pump Casing Cladding." No response required.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/30 2pp 07389 074

8101050124 Requests existing data, summaries & records of inservice ins tests of containments w/greased prestressing tendons. DRNL receiving contract to compile & review records of tendons.
EISENHUT, D G Division of Licensing 80/11/25 3pp.

8101070263 Forwards list identifying security badge number & clearance level for Region 3 personnel. Badge numbers for personnel identified by asterisks will be provided at later date.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/23 6pp. 07410 353.

8101050378 Forwards IE Info Notice B0-43. "Failures of Continuous Water Level Monitor for Steam Discharge Val at Dresden Unit 2." No response required.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/03 2pp 07309 336

8101150646 Forwards IE Insp Repts 50-266/80-17 & 50-301/80-17 on B01001-31. No noncompliance noted.
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/12/04. 2pp 07465 272

--8101150651 IE Insp Repts 50-266/80-17 & 50-301/80-17 on B01001-31. No noncompliance noted. Major areas inspected: operational safety verification, monthly maint & surveillance & followup on LERs, IE bulletins & circulars.
GULDENHOUT, W O, HARQUE, R L, HARNICK, R F. Region 3, Chicago, Office of the Director 80/12/04. 6pp 07465 274.

8101100174 Forwards IE Insp Repts 50-266/80-21 & 50-301/80-21 on B01107 re NRC evaluation of licensed activity performance.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/10 2pp. 07445 020

--8101100181 IE Insp Repts 50-266/80-21 & 50-301/80-21 re B01107 mgt meeting to discuss regulatory performance of activities at facility. Encl licensee performance evaluation was presented. Performance found adequate.
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/12/09. 10pp. 07445:022

8101070570 Forwards results of re-evaluation of masonry walls in response to IE Bulletin B0-11. Includes schedule for upgrading walls to meet criteria.
FAY, C W Wisconsin Electric Power Co. 80/12/12 4pp. 07415:210

8101070055 Forwards IE Info Notice B0-44. "Actuation of ECCB in Recirculation Mode While in Hot Shutdown." No written response required.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/16 1p 07415 033

8101120201 Suppl B00718 response to IE Bulletin B0-11 re masonry wall design. Wall omitted from first analysis will be reanalyzed using criteria of B01114 ltr.
FAY, C W Wisconsin Electric Power Co 80/12/26. 2pp. 07447 035.

8101200150 Responds to IE Bulletin B0-24 re preventing damage from water leakage inside containment. Facilities have only one open cooling water sys inside containment & have had no significant leakage during plant operations.
FAY, C W Wisconsin Electric Power Co 81/01/05. 12pp. 07187 001.

8101280379 Submits final response to IE Bulletin B0-21. "Valve Yokes Supplied by Malcolm Foundry Co, Inc." Manufacturers did not utilize specified valve parts castings.
BURSTEIN, B. Wisconsin Electric Power Co. 81/01/13. 1p. 07550 06

8101280521 Responds to NRC B010109 request for addl info re IE Bulletin B0-24. "Prevention of Damage Due to Water Leakage Inside Containment (Oct 17, 1980 Indian Point 2 Event)." Info provided re closed cooling water sys experience.
BURSTEIN, B Wisconsin Electric Power Co. 81/01/13 2pp. 07550:328

R Periodic operating reports & related correspondence

B101150517 Forwards monthly operating repts for Dec 1980
FAY, C W Wisconsin Electric Power Co B1/01/12 1p 07463 163

--B101150519 Monthly operating repts for Dec 1980
FAY, C W Wisconsin Electric Power Co. B1/01/07 10pp
07463 164

S Reportable occurrences, LERs & related correspondence

B101300748 PNO-111-B0-219 on B01126, reactor tripped twice. Caused by closure of main feedwater regulating valve, which resulted in low-low level in Steam Generator A Unit will remain down. Refueling outage had been scheduled to begin B01129.
CULDEMOND, W. C., WARNICK, R F., HEISHMAN, R F. Region 3, Chicago, Office of the Director B0/11/28 1p. 07183 001

B101050429 Forwards LER B0-014/01T-0
FAY, C W Wisconsin Electric Power Co B0/12/23 1p 07390 130

--B101050448 LER B0-014/01T-0 on B01211, results of ongoing refueling outage steam generator eddy current insp indicated defective tubes. Eight tubes w/crevice defects taken out of svc. Caused by corrosion. Defects plugged.
FAY, C W Wisconsin Electric Power Co B0/12/23 4pp 07390 131

B101120333 Forwards LER B0-015/01T-0
FAY, C W Wisconsin Electric Power Co B0/12/23 1p. 07447 146.

--B101120367 LER B0-065/01T-0 on B01210, during refueling outage surveillance testing of safety-related shock suppressors, snubber 1-HS-14 found to be inoperable. Caused by low level in reservoir, resulting from piston rod O-ring seal leakage.
FAY, C W Wisconsin Electric Power Co B0/12/23 2pp. 07447 147.

B101300743 PNO-111-B0-219A on B01126, reactor tripped twice. Caused by closure of main feedwater regulating valve. During refueling outage, licensee conducted nondestructive testing of high stress areas of feedwater piping.
CULDEMOND, W. C., WARNICK, R F., HEISHMAN, R F. Region 3, Chicago, Office of the Director B1/01/02 2pp 07183 001.

B101270699 Forwards LER B0-019/01T-1
FAY, C W Wisconsin Electric Power Co B1/01/07 1p. 07549 068.

--B101270710 LER B0-019/01T-1 on B01210, during refueling outage surveillance testing, snubber 1-HS-14 on power operated relief valve header was determined inoperable. Caused by low level in snubber reservoir due to O-ring seal leakage.
FAY, C W Wisconsin Electric Power Co B1/01/07 2pp 07549 069

B101270967 Forwards LER B1-016/03L-0
BURSTEIN, S. Wisconsin Electric Power Co. B1/01/15 1p 07541 135.

--B101270974 LER B1-016/03L-0 on B01217, during testing, emergency diesel generator 4D failed to close on bus. Caused by slippage of flexible shaft coupling on speed sensing frequency generator drive shaft. Coupling secured.
FAY, C W Wisconsin Electric Power Co. B1/01/15 2pp. 07541 136.

B101270960 Forwards LER B1-001/01T-0
FAY, C W Wisconsin Electric Power Co. B1/01/16 1p. 07541 131

--B101270964 LER B1-001/01T-0 on B10102, while performing monthly ventilation sys test, supply breaker for safeguards motor control ctr 1B42 tripped. Caused by dust in instantaneous trip valve on breaker. Breaker cleaned & tested.
FAY, C W Wisconsin Electric Power Co B1/01/16 3pp 07541 132

DOCKET 90-267 FORT ST VRAIN NUCLEAR GENERATING STATION

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR.
EISENHUT, D O. Division of Licensing B0/11/13 2pp.

B101070242 Provides update info re admittance of NRC personnel to facility, per NRC B01107 ltr. Util should train NRC personnel re badge issuance, escort duties & emergency evacuation.
SEYFRIT, K V Region 4, Dallas, Office of the Director B0/12/05 2pp. 07415 238

B101140212 Informs that licensee should conduct emergency exercise within one yr from B003401 or prior to issuance of OL. Schedule of drills should be provided.
SEYFRIT, K V Region 4, Dallas, Office of the Director B0/12/23 1p 07461 257

B101090602 Forwards proposed mods to security plan re elevator security. Mods withheld (ref 10CFR2 790).
FULLER, J K Public Service Co of Colorado B0/12/31 1p 07428 361

P Operating license stage documents & correspondence

B101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of Inservice surveillance requirements for snubbers under STS License amend application adding model Tech Specs to App A should be submitted within 120 days.
EISENHUT, D O Division of Licensing B0/11/20 1p.

--B101100271 Revised Pages 3/4 7-22 through 2B.D 3/4 7-5 & 7-6 & 6-BTS snubber (inservice insp requirements)
* Division of Licensing B0/11/20 10pp

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports".
EISENHUT, D O Division of Licensing B0/11/26 8pp.

B101210445 Forwards responses to questions on Rule 50.71e, "Periodic Updating of FSARs" & FR notice of final rule. SEP plants need not comply w/rule until program is complete. Non-SEP plants must comply within specified time frame.
EISENHUT, D O Division of Licensing B0/12/15 13pp

B101120284 Responds to NRC B00507 ltr re addl TH1-2 related requirements. Reiterates NRC position on reft re ECCS outage, licensee reft & proposed Tech Specs changes. Table re Sys 92 outages for June 1975-Jul 1980 encl.
WAREMBOURG, D. Public Service Co of Colorado B0/12/26 7pp 07439 332

B101120425 Application to amend License DPR-34, changing Tech Specs Sections 4.3.10 & 5.3.3 re boiler feed snubbers & reactor bldg exhaust filter surveillance requirements, respectively. Class II amend fee encl.
LEE, O R Public Service Co of Colorado B0/12/31 2pp 07437 334

--B101120427 Proposed Tech Specs Sections 4.3.10 & 5.3.3 re boiler snubbers & reactor bldg exhaust filter surveillance requirements, respectively.
* Public Service Co of Colorado B0/12/31 11pp 07437 336

B101130369 Application for amend to License DRR-34, proposing change Tech Specs re Class I hydraulic snubbers & reactor bldg exhaust sys.
LEE, O R Public Service Co of Colorado B0/12/31 4pp. 07451 318

--B101130374 Tech Specs LCD 4.3.10, Table 4.3.10-1 & SR 5.3.3 for Class I hydraulic snubbers & reactor exhaust sys.
* Public Service Co of Colorado B0/12/31 9pp 07451 322

B101130393 Forwards application for amend to License DPR-34, Apps A & B Tech Specs. Includes refs, background & reason for proposed revisions, summary of proposed Tech Spec revisions, revisions to App A, proposed App B & final ecological monitoring reft.
LEE, O R Public Service Co of Colorado B1/01/02 3pp 07447 312

--B101130394 Application for amend to Apps A & B Tech Specs of License DPR-34 re environ monitoring. Includes background & reasons for proposed revisions, summary of proposed Tech Specs revisions & proposed revisions to OL.
LEE, O R Public Service Co of Colorado B1/01/02 12pp 07447 315

--B101130396 Proposed revisions to App A Tech Specs Pages 4 B-1 through 4 B-8, inclusive, 5 B-1 & 5 B-2 & 5.9-1 through 5.9-11, inclusive, re environ monitoring.
* Public Service Co of Colorado B1/01/02 22pp 07447 321

--B101130398 Proposed ETS (nonradiological) for facility.
* Public Service Co of Colorado B1/01/02 44pp 07447 321

--B101130460 Final reft, "Ecological Monitoring, Fort St Vrain Generating Station," Jan 1972-Dec 1979. NPDES Permit CU-0001121 encl.
GLOVER, F A, JOHNS, J R, SWANK, F C Thorne Ecological Institute B0/09/26 236pp 07448 012

B101270624 Forwards supplementary info for proposed change to Tech Specs Table 5.1 re B01003 request for extension of fuel element core residence time compatibility w/reactor core refueling intervals
SWART, F E Public Service Co. of Colorado 81/01/21 5pp
07548 103

C Inspection reports, IE Bulletins & correspondence

B101070215 Forwards IE Insp Rept 50-267/80-21 on B01001-31 & notice of violation
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/11/14 2pp 07415 155

--B101070219 Notice of violation from insp on B01001-31
* Region 4, Dallas, Office of the Director. 80/10/13 1p
07415 157

--B101070223 IE Insp Rept 50-267/80-21 on B01001-31 Noncompliance noted:
Failure to seal two valves in position as required per Tech Spec
DICKERSON, M W, COLLINS, R E, WESTERMAN, T F Region 4, Dallas, Office of the Director 80/10/13 5pp 07415 158

B101080085 Responds to IE Bulletin 80-23 re failures of Valcor Engineering Corp solenoid valves No such valves installed at facility
SWART, F E Public Service Co. of Colorado 80/11/21 1p
07421 089

B101090264 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (October 17, 1980 Indian Point 2 Event) Written response required.
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/11/21 1p 07424 031

B101050326 Forwards IE Info Notice 80-42, Effect of Radiation on Hydraulic Snubber Fluid No response required
SEYFRIT, K V Region 4, Dallas, Office of the Director. 80/11/24 1p 07392 055

B101140191 Supply response to IE Bulletin 80-11 re masonry wall design
Eight addl walls identified in followup insp which have potential of affecting Class IE equipment during seismic event
SWART, F E Public Service Co. of Colorado 80/11/25 1p
07461 291

B101060293 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange" No Written response required
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/11/26 1p 07392 031

B101120143 Responds to IE Bulletin 80-21 re valve bolts supplied by Malcolm Foundry Co, Inc No castings purchased from vendor
SWART, F E Public Service Co. of Colorado 80/12/03 1p
07446 337

B101070198 Ack receipt of B01103 & 18 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-267/80-13
SEYFRIT, K V Region 4, Dallas, Office of the Director. 80/12/04 1p 07415 138

--B101070205 Responds to NRC B01008 ltr re violations noted in IE Insp Rept 50-267/80-13 Corrective actions: duties of radiation protection manager assigned to technical svcs section
LEE, D R Public Service Co. of Colorado 80/11/03 2pp
07413 139

--B101070211 Responds to NRC B01008 ltr re violations noted in IE Insp Rept 50-267/80-13 Corrective actions: duties of radiation protection manager assigned to technical svcs dept
WAREMBOURG, D W Public Service Co. of Colorado. 80/11/18 10pp
07415 141

B101120134 Responds to IE Bulletin 80-24 re water leakage inside containment Facility secondary containment not similar to described containment
LEE, D R Public Service Co. of Colorado 80/12/05 1p 07446 353

B101050612 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Scream Discharge Vol at Dresden Unit 2." No response required.
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/12/08 1p 07391 038

B101100067 Forwards IE Insp Rept 50-267/80-17 on B00818-22 & notice of violation. Notice of violation withheld (ref 10CFR2.790)
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/12/18 2pp 07443 015

--B101100074 IE Insp Rept 50-267/80-17 on B00818-22 Noncompliance noted: vital area physical barrier not locked & vital area key available to all personnel using elevator Details withheld (ref 10CFR2.790)
CALCHELL, R A, KELLY, J A Region 4, Dallas, Office of the Director 80/12/18 2pp 07443 017

R Periodic operating reports & related correspondence

B101230187 Final rept, "Ecological Monitoring Fort St Vrain Generating Station for 1972-79"
SCHLEICER, T E Public Service Co. of Colorado. GLOVER, F A, JOHNS, J R Thorne Ecological Institute 80/09/26 220pp
07509 159

B101140486 Forwards monthly operating rept for Dec 1980
WAREMBOURG, D Public Service Co. of Colorado 81/01/09 1p
07458 151

--B101140487 Monthly operating rept for Dec 1980
GAHM, J W Public Service Co. of Colorado 81/01/09 5pp
07458 152

S Reportable occurrences, LERs & related correspondence

B101090192 PM3-IV-B1-01 on B10102, main turbine was tripped at low power conditions to investigate suspected problems w/hot reheat valves Valves failed to fully close following trip Unit will be shut down for approx seven days for repairs
WESTERMAN, T F Region 4, Dallas, Office of the Director 81/01/07 1p 07442 273

B101140625 Forwards LER 80-065/03X-1
WAREMBOURG, D Public Service Co. of Colorado. 81/01/09 1p
07461 103

--B101140630 LER 80-065/03X-1 on B01105, reactor operated in degraded mode. Caused by removal of snubbers for verification of bleed rate snubbers were adjusted & replaced.
GAHM, J W Public Service Co. of Colorado 81/01/09 4pp
07461 104

B101140639 Forwards LER 80-074/03L-0
WAREMBOURG, D Public Service Co. of Colorado 81/01/09 1p
07461 108

--B101140646 LER 80-074/03L-0 on B01210, pilot valve in fired water v. sys resulted in control room alarm Caused by leakage past pilot valve seat due to corrosion & settling of sediment from fire water Corrosion removed.
GAHM, J W Public Service Co. of Colorado 81/01/09 4pp
07461 109

B101210406 Forwards LER 80-075/03L-0
WAREMBOURG, D Public Service Co. of Colorado. 81/01/14 8pp
07493 121

--B101210410 LER 80-075/03L-0 on B01215-31, plant operated w/total p coolant oxidants greater than 10 ppm & average core outlet temp greater than 1200 F on seven occasions. Caused by high moisture in helium storage tanks Tanks purged.
GAHM, J W Public Service Co. of Colorado. 81/01/14 1p
07493 129

B101210480 Forwards LER 80-077/03L-0
WAREMBOURG, D Public Service Co. of Colorado. 81/01/14 1p
07490 152

--B101210468 LER 80-077/03L-0 on B01224, one bearing water makeup pump removed from svc during normal operation. Caused by need to repair valve leak Valves repaired & pump returned to svc.
GAHM, J W Public Service Co. of Colorado. 81/01/14 3pp
07490 153

B101220413 Forwards LER 80-076/03L-0
WAREMBOURG, D Public Service Co. of Colorado 81/01/16 4pp
07505 188

--B101220421 LER 80-076/03L-0 on B01216, results of lab carbon sample analysis of 1A reactor plant exhaust filter showed less radioactive methyl iodine removal capability than required. Caused by normal depletion of activated charcoal adsorber.
GAHM, J W Public Service Co. of Colorado 81/01/16 1p
07505 192

8101300474 Transcript of ACRS Subcommittee for Fort St Vrain Nuclear
Generating Station 810127 meeting in Platteville, CO
Pp 1-271 Viewgraphs & supporting documents encl
* ACRS - Advisory Committee on Reactor Safeguards 81/01/27
346pp 07377:226

V. Operator Examinations

8101060556 Forwards response to 801031 request re TMI action plan
requirements, NUREG-0737, covering shift staffing
requirements, training programs & licensing exams
WAREMBOURG, D W Public Service Co. of Colorado 80/12/20 69pp.
07309:001.

8101060448 Forwards response to NUREG-0737 Item I A 1 1 describing
program for technical advisors.
WAREMBOURG, D W Public Service Co. of Colorado 80/12/30 43pp
07398:264.

8101220548 Forwards revised licensed operator requalification program
WAREMBOURG, D W. Public Service Co. of Colorado 81/01/02 1p
07303:062

--8101220953 Revised licensed operator requalification program
* Public Service Co. of Colorado 80/12/23 11pp 07303:063.

DOCKET 50-269 OCONEE NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP holders
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
810102 & by applicants as part of FBAR
EISENHUT, D O Division of Licensing 00/11/13 2pp.

8101140294 Requests that encl facility planning info be made publicly
available w/o encl
SQUEDER, J L. Division of Rules and Records 80/12/31 1p
07461:262

8101230440 Suppls 810102 & 07 ltrs & crisis mgt plan State of NC
emergency response plan for facility will be provided when
available.
PARKER, W O. Duke Power Co. 81/01/19 1p. 07511:124

8101290594 Releases public version of util emergency plan
FELTON, J M. Division of Rules and Records 81/01/26 1p.
07187:001.

--8101290599 Forwards public version of site-specific radiological
emergency plan, consisting of Part I of State of SC
operational radiological emergency response plan Suppls
810102 submittal.
PARKER, W O. Duke Power Co. 81/01/07 1p. 07187:001

--8101290608 Public version of site-specific radiological emergency
response plan, consisting of Part I of State of SC
operational radiological emergency response plan
* Duke Power Co. 80/12/31. 53pp. 07187:001

I. Financial Information

8101060503 Forwards util submission of guarantee of retrospective
premiums per code requirements & in response to NRC 801219
& 30 requests.
MORROW, N P Duke Power Co. 80/12/30. 1p 07309:001.

--8101060509 Requests that util provide approved guarantee of payment of
deferred premiums for each operating reactor over 100 Mw
per code requirements
BALITMAN, J Utility Finance Branch (formerly Antitrust &
Indemnity) 80/12/19. 1p. 07309:001.

P. Operating license stage documents & correspondence

8101100254 Ltr to all licensees (except BEP licensees) forwarding
Revision 1 of inservice surveillance requirements for
snubbers under STS. License amend application adding model
Tech Specs to App A should be submitted within 120 days
EISENHUT, D O. Division of Licensing. 80/11/20 1p.

* Division of Licensing 80/11/20. 10pp

8101220466 Ltr to all power reactor licensees & applicants forwarding
summary of 801112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

8101090175 Forwards Amends 89.89 & 86 to Licenses DPR-38, DPR-47 &
DPR-55, respectively, safety evaluation & notice of issuance
& availability
REID, R W Operating Reactors Branch 4 80/12/10 2pp 07426:3

--8101090184 Amends 89.89 & 86 to Licenses DPR-38, DPR-47 & DPR-55
respectively, revising Tech Specs to redefine term "operable"
& to add general limiting conditions for operation
REID, R W Operating Reactors Branch 4 80/12/10 11pp
07426:310

--8101090193 Safety evaluation supporting Amends 89.89 & 86 to Lice
DPR-38, DPR-47 & DPR-55, respectively
* Office of Nuclear Reactor Regulation, Director 80/12/10
07426:321

--8101090205 Notice of issuance & availability of Amends 89.89 & 86
Licenses DPR-38, DPR-47 & DPR-55, respectively
REID, R W Operating Reactors Branch 4 80/12/10 2pp
07426:323

8101210445 Forwards responses to questions on Rule 50.71e. "Periodi
Updating of FSARs" & FR notice of final rule. BEP plants need
not comply w/rule until program is complete Non-BEP plants
must comply within specified time frame.
EISENHUT, D O Division of Licensing 80/12/15 13pp

8101200223 Requests amend to license revising Tech Specs re disposa
burned contaminated oil, per 000519 ltr
PARKER, W O. Duke Power Co. 80/12/17 2pp 07487:028

8101070550 Forwards corrected Tech Spec pages (power distribution
curves) to NRC 800222 Cycle & reload license amend
REID, R W Operating Reactors Branch 4 80/12/18 2pp 07404:3

--8101070555 Corrected Tech Spec pages (power distribution curves)
Amend 81 to License DPR-38
REID, R W. Operating Reactors Branch 4 (Pre 800428). 80/12/18
8pp. 07404:359.

8101100440 Forwards Amends 90.90 & 87 to Licenses DPR-38, DPR-47 &
DPR-55, respectively, safety evaluation, EIA & notice of
issuance & availability
REID, R W Operating Reactors Branch 4. 80/12/24 2pp 07444:2

--8101100448 Amends 90.90 & 87 to Licenses DPR-38, DPR-47 & DPR-55,
respectively, allowing increase in spent fuel storage
capacity
NOVAK, T M. Assistant Director for Operating Reactors 80/12/2
7pp 07444:203.

--8101100462 Safety evaluation supporting Amends 90.90 & 87 to Lice
DPR-38, DPR-47 & DPR-55, respectively.
* Office of Nuclear Reactor Regulation, Director 80/12/24
07444:213

--8101100471 EIA supporting Amends 90.90 & 87 to Licenses DPR-38, DPR-
DPR-55, respectively
* Office of Nuclear Reactor Regulation, Director. 80/11/24
07444:222

--8101100479 Notice of issuance & availability of Amends 90.90 & 87
Licenses DPR-38, DPR-47 & DPR-55, respectively & negative
declaration
ERICKSON, P B Operating Reactors Branch 4 80/12/24 2pp
07444:231.

8101050094 Application for amend of Licenses DPR-38, DPR-47 & DPR-55
changing Tech Specs, Section 4 to modify certain surveillance
requirements on annual basis for each refueling outage. Amend
fees encl.
PARKER, W O Duke Power Co. 80/12/29. 3pp 07376:301.

--8101050101 Proposed changes to Tech Specs, Section 4, modifying
surveillance requirements from performance on annual basis
to performance during each refueling outage
* Duke Power Co. 80/12/29 18pp. 07376:304

B101060483 Forwards proposed Tech Specs revision re reactor bldg & containment leakage tests, supplementing B01024 submittal. Containment air lock testing to be submitted upon review completion.
PARKER, W D Duke Power Co 80/12/29 1p 07396 318.

--B101060483 Proposed Tech Specs 3 b & 4.4 revision re reactor bldg & containment leakage tests, respectively. Containment leakage test revision reflects App J requirements.
* Duke Power Co 80/12/29 15pp 07396 319

--B101060491 Test Requirement Bases & Justification for Reverse Director Testing
* Duke Power Co 80/12/29 8pp 07396 334

B101210555 Forwards list of TLD station locations near facility & proposed route for exchanging TLDs for NRC direct radiation monitoring network w/o encls.
BICHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/12/30 2pp 07489 116

B101070269 Forwards response to NUREG-0737, post-TMI requirements, including info re shift technical adviser, short-term accident & procedures review & containment isolation dependability. Central Files version of emergency plan encl.
PARKER, W D Duke Power Co 81/01/02 70pp 07389 012

--B101070286 "Thermal-Mechanical Resp - Effect on HPI on Vessel Integrity for Small Break LOCA Event w/Extended Loss of Feedwater"
Two oversized drawings & responses to NUREG-0737 encl.
* Babcock & Wilcox Co BAH-1648 80/11/30 158pp

B101130404 Provides alternate methods of nondestructive exams for welds to be performed in place of hydrostatic testing, following maint or mod NRC B01107 ltr granted licensee relief from ASME Code requirements re hydrostatic testing.
PARKER, W D Duke Power Co 81/01/07 2pp 07452 111.

B101160366 Advises that response to NRC B01114 ltr requesting addl info re emergency feedwater sys will be ready for submittal by B10302.
PARKER, W D Duke Power Co 81/01/12 1p 07471 148

B101270799 Forwards request for addl info re Cycle & reload NRC assumptions discussed in encl B01028 ltr should be verified as correct & applicable to facility for proposed cycle of operation.
REID, R W Operating Reactors Branch 4 81/01/12 5pp 07549 084

--B101270805 Submits addl comments re planned transfer from TAFV to TACD-2 code for fuel & ECCB analyses.
RUBENSTEIN, L S Assistant Director for Core & Containment Systems 80/10/28 2pp 07549 091

B101210493 Responds to NRC B01001 request for proposed updated Tech Specs for fire protection program. Tech Specs currently under review & will be submitted by B10316.
PARKER, W D Duke Power Co 81/01/15 1p 07489 278

B101220428 Advises of delay of response to NRC B01027 ltr re standby shutdown facility. Response will be provided no later than B10216.
PARKER, W D Duke Power Co 81/01/15 1p 07493 252

D Inspection reports, IE Bulletins & correspondence

B101050124 Requests existing data, summaries & records of inservice insp tests of containments w/created prestressing tendons. ORNL receiving contract to compile & review records of tendons.
EISENHUT, D O Division of Licensing 80/11/25 3pp.

B101080141 Act receipt of B01126 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 90-269/80-32, 90-270/80-28 & 90-287/80-25.
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/12/12 1p 07421 018

--B101080148 Act receipt of IE Insp Repts 90-269/80-32, 90-270/80-28 & 90-287/80-25 on B00902-30. No proprietary info. Corrective actions Tech Specs revised, personnel training reviewed & ltr issued to station manager.
PARKER, W D Duke Power Co 80/11/26 3pp 07421 019

--B101080155 Forwards IE Insp Repts 90-269/80-32, 90-270/80-28 & 90-287/80-25 on B00902-30 & notice of violation.
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/11/03 2pp 07421 022

--B101080161 Notice of violation from insp on B00902-30.
* Region 2, Atlanta, Office of the Director 80/11/03 1p 07421 024

--B101080177 IE Insp Repts 90-269/80-32, 90-270/80-28 & 90-287/80-25 on B00902-30. Noncompliance noted failure to comply w/Tech Spec requirement for processing major procedure change.
JAFEF, F. ORDERS, W. MYERS, D. Region 2, Atlanta, Office of the Director 80/11/03 7pp 07421 025

B101150136 Suppls B00918 ltr re mods to reactor bldg spray sys for facilities. Mods to be installed during next available forced outage of sufficient duration or next refueling outage.
PARKER, W D Duke Power Co 80/12/12 1p 07462 191

B101060225 Forwards IE Info Notice 80-44, "Actuation of ECCB in Recirculation Mode While in Hot Shutdown." No written response required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/12 1p 07391 334

B101160258 Responds to IE Bulletin 80-23 re Valcor Engineering Corp. solenoid valve failure. Util will replace all Valcor solenoid valves w/ARCO solenoid valves as soon as received.
PARKER, W D Duke Power Co 80/12/29 1p 07470 298

B101200575 Forwards response to IE Bulletin 80-24 re prevention of damage due to water leakage inside containment. Tech Specs & station directives ensure reporting of abnormal degradation of primary containment.
PARKER, W D Duke Power Co 81/01/06 11pp 07477 240

B101210213 Forwards supplemental response to IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls." Mods completed on high pressure injection pumps, penetration room exhaust fans, reactor bldg cooling unit fan & Keowee start.
PARKER, W D Duke Power Co 81/01/07 13pp 07488 017.

B101190385 Forwards request for relief from ASME Code Section XI inservice insp requirements re main feedwater sys check valves. Approval requested by B10114.
PARKER, W D Duke Power Co 81/01/13 5pp 07475 332.

R Periodic operating reports & related correspondence

B101210462 Forwards monthly operating repts for Dec 1980.
PARKER, W D Duke Power Co 81/01/15 1p 07493 170.

--B101210464 Monthly operating repts for Dec 1980.
REAVIS, J A Duke Power Co 81/01/15 16pp 07493 171.

S Reportable occurrences, LERs & related correspondence

B101210502 Forwards LER 80-037/03L-0.
PARKER, W D Duke Power Co 81/01/15 2pp 07490 189.

--B101210507 LER 80-037/03L-0: on B01216, CBAST pump delivered no fuel while personnel were attempting sample test & was declared inoperable. Probably caused by low oil level in hydraulic reservoir & clogged pressure gauge line.
JONES, J L Duke Power Co 81/01/15 1p 07490 191.

B101220378 Forwards LER 80-038/03L-0.
PARKER, W D Duke Power Co 81/01/16 3pp 07500 251.

--B101220380 LER 80-038/03L-0: on B01217, during fire protection testing, main transformer automatically isolated from overhead power path. Caused by personnel error. Tech Specs revised to remove overhead path from svc prior to testing.
PHILPOTT, F T Duke Power Co 81/01/16 1p 07500 254

B101230489 Forwards LER 80-039/03L-0.
PARKER, W D Duke Power Co 81/01/19 2pp 07510 288.

--B101230491 LER 80-039/03L-0: on B01220, smoke detector covering 11b & 23a alarmed. Caused by dusty ambient conditions where detector is located. Detector replaced & string returned to svc. Twice weekly preventive maint program implemented.
JONES, J L Duke Power Co 81/01/19 1p 07510 290.

DOCKET 90-270 OCCNEE NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR.
EISENHUT, D O Division of Licensing 80/11/13 2pp

B101140294 Requests that encl facility planning info be made publicly available w/o encl
SOUDER, J L Division of Rules and Records 80/12/31 1p
07461 262

B101230440 Suppls B10102 & 07 ltrs & crisis mgt plan State of NC emergency response plan for facility will be provided when available
PARKER, W O Duke Power Co. 81/01/19 1p. 07511 124.

B101290594 Releases public version of util emergency plan.
FELTON, J M Division of Rules and Records 81/01/26 1p
07187 001.

--B101290599 Forwards public version of site-specific radiological emergency plan, consisting of Part I of State of SC operational radiological emergency response plan Suppl B10102 submittal.
PARKER, W O Duke Power Co. 81/01/07 1p. 07187 001.

--B101290608 Public version of site-specific radiological emergency response plan, consisting of Part I of State of SC operational radiological emergency response plan
* Duke Power Co. 80/12/31 53pp. 07187 001

I Financial information

B101060303 Forwards util submission of guarantee of retrospective premiums per code requirements & in response to NRC 801219 & 30 requests.
MORROW, N P Duke Power Co 80/12/30 1p. 07309 001.

--B101060309 Requests that util provide approved guarantee of payment of deferred premiums for each operating reactor over 100 Mw per code requirements
SALTZMAN, J Utility Finance Branch (formerly Antitrust & Indemnity) 80/12/19 1p 07309 001.

P. Operating license stage documents & correspondence

B101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under STS license amend application adding model Tech Specs to App A should be submitted within 120 days.
EISENHUT, D O Division of Licensing 80/11/20 1p.

--B101100271 Revised Pages 3/4 7-22 through 28.B 3/4 7-5 & 7-6 & 6-17 to STS snubber inservice insp requirements.
* Division of Licensing 80/11/20 10pp

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp.

B101090175 Forwards Amends 89, 89 & 86 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability.
REID, R W Operating Reactors Branch 4 80/12/10 2pp 07426 300.

--B101090184 Amends 89, 89 & 86 to Licenses DPR-38, DPR-47 & DPR-55 respectively, revising Tech Specs to redefine term "operable" & to add general limiting conditions for operation.
REID, R W Operating Reactors Branch 4 80/12/10 11pp
07426 310.

--B101090195 Safety evaluation supporting Amends 89, 89 & 86 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
* Office of Nuclear Reactor Regulation, Director 80/12/10 2pp.
07426 321.

--B101090205 Notice of issuance & availability of Amends 89, 89 & 86 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
REID, R W Operating Reactors Branch 4 80/12/10 2pp.
07426 323.

B101210445 Forwards responses to questions on Rule 50 71e. "Periodic Updating of FSARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame
EISENHUT, D O Division of Licensing 80/12/15 13pp

B101200223 Requests amend to license revising Tech Specs re disposition burned contaminated oil, per 800519 ltr
PARKER, W O Duke Power Co 80/12/17 2pp 07487 028

B101100440 Forwards Amends 90, 90 & 87 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation, EIA & notice of issuance & availability
REID, R W Operating Reactors Branch 4 80/12/24 2pp 07444

--B101100440 Amends 90, 90 & 87 to Licenses DPR-38, DPR-47 & DPR-55, respectively, allowing increase in spent fuel storage capacity
NOVAK, T M Assistant Director for Operating Reactors 80/12/24 2pp 07444 203

--B101100462 Safety evaluation supporting Amends 90, 90 & 87 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
* Office of Nuclear Reactor Regulation, Director 80/12/24 07444 213

--B101100471 EIA supporting Amends 90, 90 & 87 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
* Office of Nuclear Reactor Regulation, Director 80/11/24 07444 222

--B101100479 Notice of issuance & availability of Amends 90, 90 & 87 to Licenses DPR-38, DPR-47 & DPR-55, respectively & negative declaration
ERICKSON, P H Operating Reactors Branch 4 80/12/24 2pp
07444 231

B101050094 Application for amend of Licenses DPR-38, DPR-47 & DPR-55 changing Tech Specs, Section 4 to modify certain surveillance requirements on annual basis for each refueling outage. Amend fees encl
PARKER, W O Duke Power Co 80/12/29 3pp 07376 301.

--B101050101 Proposed changes to Tech Specs, Section 4, modifying surveillance requirements from performance on annual basis to performance during each refueling outage
* Duke Power Co 80/12/29 18pp. 07376 304.

B101050483 Forwards proposed Tech Specs revision re reactor bldg & containment leakage tests, supplementing 801024 submittal. Containment air lock testing to be submitted upon review completion
PARKER, W O Duke Power Co. 80/12/29 1p. 07396 318

--B101060488 Proposed Tech Specs 3 & 4 & 4 revision re reactor bldg & containment leakage tests, respectively. Containment leakage test revision reflects App J requirements
* Duke Power Co 80/12/29 13pp 07396 319.

--B101060491 "Test Requirement Bases & Justification for Reverse Direction Testing"
* Duke Power Co 80/12/29 8pp 07396 334.

B101210565 Forwards list of TLD station locations near facility & proposed route for exchanging TLDs for NRC direct radiation monitoring network w/o encls
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/12/30 2pp 07489 116.

B101070267 Forwards response to NUREG-0737, post-TMI requirements, including info re shift technical adviser, short-term accident & procedures review & containment isolation dependability. Central Files version of emergency plan encl.
PARKER, W O Duke Power Co. 81/01/02 70pp. 95189 012.

--B101070286 "Thermal-Mechanical Rept - Effect on HPI on Vessel In for Small Break LOCA Event w/Extended Loss of Feedwater"
Two oversized drawings & responses to NUREG-0737 encl
* Babcock & Wilcox Co BAW-1648 80/11/30 158pp

B101130404 Provides alternate methods of nondestructive exams for to be performed in place of hydrostatic testing, following maint on mod NRC 801107 ltr granted licensee relief from ASME Code requirements re hydrostatic testing.
PARKER, W O Duke Power Co. 81/01/07 2pp. 07452 111

B101160366 Advises that response to NRC 801114 ltr requesting add re emergency feedwater sys will be ready for submittal by 810302
PARKER, W O Duke Power Co. 81/01/12 1p 07471 148

8101210493 Responds to NRC 801001 request for proposed updated Tech Specs for fire protection program Tech Specs currently under review & will be submitted by 810316
PARKER, W D Duke Power Co 81/01/15 1p 07489 278

8101220428 Advises of delay of response to NRC 801027 ltr re standby shutdown facility. Response will be provided no later than 810216
PARKER, W D Duke Power Co 81/01/15 1p 07493 252

G. Inspection reports, IE Bulletins & correspondence

8101050124 Requests existing data summaries & records of interservice insp tests of containments w/greased prestressing tendons
DRNL receiving contract to compile & review records of tendons
EISENHUT, D O Division of Licensing 80/11/25 3pp

8101080141 Act receipt of 801126 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-269/80-28 & 80-270/80-28 & 80-287/80-23
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/12/12 1p 07421 018

--8101080148 Act receipt of IE Insp Repts 80-269/80-28, 80-270/80-28 & 80-287/80-23 on 800902-30 No proprietary info corrective actions Tech Specs revised, personnel training reviewed & ltr issued to station manager
PARKER, W D Duke Power Co 80/11/26 3pp 07421 019

--8101080155 Forwards IE Insp Repts 80-269/80-28, 80-270/80-28 & 80-287/80-23 on 800902-30 & notice of violation
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/11/03 2pp 07421 022

--8101080161 Notice of violation from insp on 800902-30
e Region 2, Atlanta, Office of the Director 80/11/03 1p 07421 024

--8101080177 IE Insp Repts 80-269/80-28, 80-270/80-28 & 80-287/80-23 on 800902-30 Noncompliance noted failure to comply w/Tech Spec requirement for processing major procedure change
JAFFE, F. ORDERS, W. MYERS, P Region 2, Atlanta, Office of the Director 80/11/03 7pp 07421 025

8101150136 Suppls 800918 ltr re mod to reactor bldg spray sys for facilities Mods to be installed during next available forced outage of sufficient duration or next refueling outage
PARKER, W D Duke Power Co 80/12/12 1p 07462 191

8101060225 Forwards IE Info Notice 80-44, "Actuation of ECCB in Recirculation Mode While in Hot Shutdown" No written response required
D'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/16 1p

8101160258 Responds to IE Bulletin 80-23 re Valcor Engineering Corp solenoid valve failure (U1) will replace all Valcor solenoid valves w/ASCO solenoid valves as soon as received
PARKER, W D Duke Power Co 80/12/29 1p 07470 258

8101200575 Forwards response to IE Bulletin 80-24 re prevention of damage due to water leakage inside containment Tech Specs & station directives ensure reporting of abnormal degradation of primary containment
PARKER, W D Duke Power Co 81/01/06 11pp 07477 240

8101210213 Forwards supplemental response to IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls." Mods completed on high pressure injection pumps, penetration room exhaust fans, reactor bldg cooling unit fan & Redox start
PARKER, W D Duke Power Co 81/01/07 13pp 07488 017

810190385 Forwards request for relief from ASME Code Section XI interservice insp requirements re main feedwater sys check valves Approval requested by 810114
PARKER, W D Duke Power Co 81/01/13 5pp 07475 332

R. Periodic operating reports & related correspondence

8101210462 Forwards monthly operating repts for Dec 1980
PARKER, W D Duke Power Co 81/01/15 1p 07493 170

--8101210464 Monthly operating repts for Dec 1980
REAVIS, J A Duke Power Co 81/01/15 16pp 07493 171

S. Reportable occurrences, LERs & related correspondence

8101300576 Forwards LER 80-021/03L-0
PARKER, W D Duke Power Co 81/01/09 1p 07582 345

--8101300578 LER 80-021/03L-0 on 801210, relay in start circuitry for TDEFH auxiliary oil pump shorted tripping dc breaker Caused by AR-15 relay coil shorting Relay replaced
JONES, J L Duke Power Co 81/01/09 2pp 07582 346

8101270640 Forwards LER 80-026/03L-0
PARKER, W D Duke Power Co 81/01/20 2pp 07548 345

--8101270680 LER 80-026/03L-0 on 801219, concentrated boric acid tank pump declared inoperable because of failure to pump to letdown storage tank Caused by air in hydraulic reservoir & low oil level Oil added & station mod submitted
JONES, J L Duke Power Co 81/01/20 1p 07548 347

DOCKET 80-271 VERMONT YANKEE NUCLEAR POWER STATION

F. Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FEAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

8101100058 Ltr to all power reactor licensees w/plants licensed prior to 790101 Forwards revised Section 10CFR20.48 & App R re fire protection features in nuclear power plants & summary list of requirements for resolution of open issues
EISENHUT, D O Division of Licensing 80/11/24 8pp 07448 224

G. Adjudicatory correspondence

8101070402 Joins VT Yankee Decommissioning Alliance request for full investigation of safety & mgt at facility. Results of investigation should be publicly available
BRCC, C M Affiliation Unknown 80/12/23 1p 07415 299

8101210652 Forwards Director's decision under 10CFR2.206, in response to ltr
STELLO, V Director's Office, Office of Inspection and Enforcement 81/01/08 3pp 07187 001

--8101210655 Forwards Director's decision under 10CFR2.206, denying request for facility shutdown pending public hearings & investigation
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 81/01/08 3pp 07187 001

--8101210658 Forwards Director's decision under 10CFR2.206, denying request for facility shutdown pending public hearings & investigation
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 80/12/30 2pp 07187 001

--8101210660 Forwards Director's decision under 10CFR2.206, in response to ltr
STELLO, V Director's Office, Office of Inspection and Enforcement 81/01/08 1p 07187 001

--8101210661 Forwards Director's decision under 10CFR2.206, in response to ltr
STELLO, V Director's Office, Office of Inspection and Enforcement 81/01/08 1p 07187 001

--8101210663 Forwards Director's decision under 10CFR2.206, in response to City of Holland, VT ltr
STELLO, V Director's Office, Office of Inspection and Enforcement 81/01/08 1p 07187 001

--8101210665 Forwards Director's decision under 10CFR2.206, in response to Ad Hoc Citizens Group for Safety at VT Yankee ltr
STELLO, V Director's Office, Office of Inspection and Enforcement 81/01/08 1p 07308 001

--8101210668 Urges shutdown of facility, pending public investigation of safety & mgt
HILSON, R Affiliation Unknown 81/01/08 1p 07308 001

--B101210469 Notice of issuance of Director's decision under 10CFR2 206. denying VT Yankee Decommissioning Alliance B01127 request for facility shutdown pending public investigation into operation & safety
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 80/12/29 2pp 07308 001

--B101210671 Director's decision under 10CFR2 206. denying VT Yankee Decommissioning Alliance B01127 request for facility shutdown pending public investigation into operation & safety
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 80/12/29 30pp. 07308 001

B101300402 Forwards NRC B10113 order granting extension to exemption from General Design Criterion 50 & requiring licensee to reassess containment design for suppression pool hydrodynamic loading
IPPOLITO, T A Operating Reactors Branch 2 B1/01/13 4pp 07586 244

--B101300411 Order granting extension to exemption from General Design Criterion 50 & requiring licensee to reassess containment design for suppression pool hydrodynamic loading.
EISENHUT, D O Division of Licensing B1/01/13 7pp 07586 248.

B101220014 Order granting extension until B10206 for Commission to decide whether to review Director's decision re Callan & Richardson petition Certificate of Evc encl
CHILK, S J Office of the Secretary of the Commission. B1/01/16 2pp 07501 339

H. General Correspondence

B101070366 Demands full & public investigation into safety & mgt of facility Expresses concern re cracked pipes, worker burnout, stress corrosion, hidden costs & operation w/o water discharge permit.
CAFFERTY, J. Affiliation Unknown. 80/12/28 2pp 07309 001

B101140804 Requests investigation & public hearing re repairs, damage & weaknesses at facility
KIEHN, L. J. Affiliation Unknown. B1/01/04 1p 07308 001

B101140897 Requests investigation re facility safety & mgt.
CHEVAN, J C Affiliation Unknown B1/01/06 2pp 07308 001

B101140906 Expresses concern over safety of facility & requests public investigation into safety & mgt.
WAIT, E. Affiliation Unknown. B1/01/09 1p 07458 261.

B101200208 Urges close look at potential problems at facility.
CARLETON, M Affiliation Unknown B1/01/15 1p 07187 001

P. Operating license stage documents & correspondence

B101100294 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under B1B License amend application adding model Tech Specs to App A should be submitted within 120 days.
EISENHUT, D. O. Division of Licensing. 80/11/20. 1p.

--B101100271 Revised Pages 3/4 7-22 through 28.B 3/4 7-3 & 7-6 & 6-17 to B1B snubber inservice insp requirements
* Division of Licensing 80/11/20. 10pp

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D. O. Division of Licensing. 80/11/26. 8pp.

B101030474 Notifies that until B00912 proposed Tech Specs for TMI Lessons Learned Category A items are unacceptable Tech Specs should contain limiting conditions for operation & actions for primary backup position indicators.
IPPOLITO, T. A. Operating Reactors Branch 2 80/12/01. 3pp. 07390. 049.

B101190113 Ltr to all BWR licensees forwarding B01201 generic safety evaluation re BWR steam discharge sys. Recommends short-term actions necessary to assure safe operation of OE BWRs pending permanent design changes.
EISENHUT, D. O. Division of Licensing. 80/12/09 2pp.

--B101100194 IE Insp Rept 50-271/B0-10 on B00705-0808 Noncompliance noted Major areas inspected logs, records, tours, safety sys operational verification & operational event Followup Portions withheld (ref 10CFR2 790)
RAYMOND, W J, COLLINS, S J, FOLEY, T Region 1, Philadelphia, Office of the Director 80/10/07 34pp 07438 054

B101070414 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs Terry Turbine Steam Inlet Flange " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/11/26 1p 07414 053

B101100493 Forwards IE Insp Rept 50-271/B0-16 on B00929-1003.14-17-31 Ho noncompliance noted
CARLESON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/03 2pp 07444 251

--B101100503 IE Insp Rept 50-271/B0-16 on B00929-1003.14-17 & 27-31 noncompliance noted Major areas inspected. inservice insp program & implementation of testing & esar requirements for refueling outage
SAUDER, W F, MCBEARTY, R A Region 1, Philadelphia, Office of the Director TRIPPL, E E Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/02 9pp 07444 253

B101300092 Revises B00502 response to IE Bulletin 80-17, Suppl 3, "Failure of 76 of 105 Control Rods to Fully Insert During Scram at BWR." Add plant mods changed indications available to control room operator
HEIDER, L H Vermont Yankee Nuclear Power Corp 80/12/03 2pp 07579 332

B101030134 Forwards IE Info Notice 80-43, "Failures of Continuous Level Monitor for Scram Discharge Vol at Dresden Unit 2 " No response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/05 1p 07376 335

B101140913 Responds to IE Bulletin 80-23, "Failures of Solenoid Valves by Valcor Engineering Corp " Valves w/specifed parts not in use at facility
CONWAY, W F Vermont Yankee Nuclear Power Corp 80/12/11. 1p 07458 352

B101160621 Ack receipt of B01113 ltr informing NRC of steps taken correct violations noted in IE Insp Rept 50-271/B0-11. Item 7 remains an item of noncompliance
MARTIN, W O Region 1, Philadelphia, Safeguards Branch 80/12/11 1p 07472 010.

--B101160627 Responds to NRC B01029 ltr re violations noted in IE Rept 50-271/B0-11 Conclusions supporting denial of noncompliance of Item 7 withheld (ref 10CFR2 790).
CONWAY, W F Vermont Yankee Nuclear Power Corp 80/11/13 2p 07472 011

--B101160633 Ack receipt of B01003 ltr informing NRC of steps taken correct violations noted in IE Insp Rept 50-271/B0-11 Response to Item 7 not acceptable Details withheld (ref 10CFR2 790).
MARTIN, W O Region 1, Philadelphia, Safeguards Branch 80/12/11 2pp 07472 013

--B101160640 Responds to NRC B00909 ltr re violations noted in IE Rept 50-271/B0-11 Encl withheld (ref 10CFR2 790).
CONWAY, W F Vermont Yankee Nuclear Power Corp 80/10/03 1p 07472 015

--B101160646 Forwards IE Insp Rept 50-271/B0-11 on B00728-31 & ODO Notice of violation withheld (ref 10CFR2 790)
GRIER, B H Region 1, Philadelphia, Office of the Director 80/09/09 2pp 07472 016

--B101160653 IE Insp Rept 50-271/B0-11 on B00728-31 & ODO Noncompliance noted communications device not tested at required frequency & member of security force not qualified Details withheld (ref 10CFR2 790).
SHEPHERD, R E Region 1, Philadelphia, Office of the Director, DEVLIN, J W Region 1, Philadelphia, Safeguards Branch. 80/09/09. 2pp. 07472 018.

B101060144 Forwards IE Info Notice 80-49, "Potential Failure of Backup Manual Scram Capability." No response required
GRIER, B H Region 1, Philadelphia, Office of the Director. 80/12/17. 1p. 07391 262.

B101070060 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of 76 of 105 Control Rods to Fully Insert During Scram at BWR." No written response required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 80/12/18. 1p. 07414 150

8101210445 Forwards responses to questions on Rule 50.71e. "Periodic Updating of FSARs" & FR notice of final rule. SEP plants need not comply w/rule until program is complete. Non-SEP plants must comply within specified time frame.
EISENHUT, D G Division of Licensing 80/12/15 13pp

8101100712 Forwards Amend 61 to License DPR-28, safety evaluation & notice of issuance & availability
IPPOLITO, T A Operating Reactors Branch 2 80/12/18 3pp
07443 195

--8101100717 Amend 61 to License DPR-28, incorporating limited operating conditions associated w/Cycle 8 operation
IPPOLITO, T A Operating Reactors Branch 2 80/12/18 21pp
07443 198

--8101100727 Safety evaluation supporting Amend 61 to License DPR-28
* Office of Nuclear Reactor Regulation, Director 80/12/18 4pp
07443 219

--8101100731 Notice of issuance & availability of Amend 61 to License DPR-28
IPPOLITO, T A Operating Reactors Branch 2 80/12/18 2pp
07443 223

8101030169 Forwards addl info in response to NRC 800818 questions re adequacy of station electric distribution sys voltages
Includes analysis for unit auxiliary transformer source & analysis w/only one startup transformer available
SMITH, R L Vermont Yankee Nuclear Power Corp 80/12/29 22pp
07377 279

8101210236 Forwards NRC positions re util 77071B, 791206 & 800702 ltrs re degraded grid voltage. Licensees must submit Tech Specs requiring that diesel generator operate for at least 5 minutes while loaded w/emergency loads
IPPOLITO, T A Operating Reactors Branch 2 80/12/29 4pp
07187 331

8101060389 Responds to NUREG-0737, Item 31.K 3 13 Reactor core isolation cooling trip/throttle valve trips on high water level & requires manual resetting at turbine before restart.
Limit torque motor operator will be added for automatic reset.
CONWAY, W F Vermont Yankee Nuclear Power Corp 80/12/30 2pp
07397 358

8101060366 Responds to NUREG-0737, Item 1 C & re guidance for evaluation & development of procedures for transients & accidents. Util has participated in BWR owners group program to develop emergency guidelines. Provides description of submittals.
SMITH, R L Vermont Yankee Nuclear Power Corp 80/12/31 3pp
07393 357

8101080391 Forwards YAE-1234, "Methods for Analysis of BWRs, Steady-State Core Flow Distribution Code (FIDWR)," describing Reload B safety evaluation methods
SMITH, R L Vermont Yankee Nuclear Power Corp 80/12/31 1p
07420 319

--8101080403 "Methods for Analysis of BWRs, Steady-State Core Flow Distribution Code (FIDWR)"
ANSARI, A F., SLIFER, B C., TURNAGE, J C Yankee Atomic Electric Co
YAE-1234 80/12/31 118pp 07420 083

8101080430 Forwards YAE-1232, "Methods for Analysis of BWRs Lattice Physics" Rept describes methods to be used in safety evaluation of Reload B
SMITH, R L Vermont Yankee Nuclear Power Corp 80/12/31 1p
07420 201

--8101080443 "Methods for Analysis of BWRs Lattice Physics"
PILAT, E E., CACCIAPOUTI, A., TURNAGE, J C. Yankee Atomic Electric Co. YAE-1232 80/12/31 108pp 07420 202

8101090006 Forwards YAE-1235, "Methods for Analysis of BWRs, Transient Thermal Margin Analysis Code (MAYUD4-YAEC)," describing methods which will be used to perform safety evaluation of Reload B.
SMITH, R L Vermont Yankee Nuclear Power Corp 80/12/31 1p
07441 200

--8101090009 "Methods for Analysis of BWRs, Transient Thermal Margin Analysis Code (MAYUD4-YAEC)"
BURNS, K J., SLIFER, B C., TURNAGE, J C Yankee Atomic Electric Co. YAE-1235 80/12/30 25pp 07441 201

--8101090039 Tech Spec Table 3.2 & for post-accident ins
Tech Spec 6.10 for integrity of sys outside containment
* Vermont Yankee Nuclear Power Corp 81/01/05 3p

8101160147 Submits info re proposed schedule for remaining
Results of piping analysis will be available by mid-19
Earliest commitment date for completing required mods
be 1983 refueling outage, tentatively scheduled for Apr
HEIDER, L H Vermont Yankee Nuclear Power Corp 81/01
07472 087

8101160379 Forwards response to documentation requirements
NUREG-0737, Item 31 D 3 4 re control room habitability
info will be submitted per schedule in util 801215 ltr
SMITH, R L Vermont Yankee Nuclear Power Corp 81/01
07470 085

8101200249 Forwards info detailing exceptions taken to p
requirements transmitted in NRC 801031 ltr
O'DONNELL, R H Vermont Yankee Nuclear Power Corp 81/01
07486 229

8101300402 Forwards NRC 810113 order granting extension
from General Design Criterion 50 & requiring licensee
reassess containment design for suppression pool
hydrodynamic loading
IPPOLITO, T A Operating Reactors Branch 2 81/01/13
07586 244

--8101300411 Order granting extension to exemption from
Criterion 50 & requiring licensee to reassess contain
design for suppression pool hydrodynamic loading.
EISENHUT, D G Division of Licensing 81/01/13 7p

8101210264 Forwards errata sheets to be included w/ "Meth
Analysis of BWRs, Transient Thermal Margin Analysis Code
(MAYUD4-YAEC)" submitted 801231
SMITH, R L Vermont Yankee Nuclear Power Corp 81/01
07487 186

--8101210367 Errata sheets of matl to be added to "Methods
of BWRs, Transient Thermal Margin Analysis Code
(MAYUD4-YAEC)," submitted 801231
BURNS, K J., SLIFER, B C., TURNAGE, J C Yankee Atomic
YAEC-1235 ENR 81/01/14 2pp 07487 187

8101200388 Clarifies 800928 response to NRC 800312 requ
Info re bypass & reset of engineered safety features &
manual override feature for safety actuation signal de
cause inadvertent bypass of any other actuation signal
SMITH, R L Vermont Yankee Nuclear Power Corp 81/01
07187 001

8101270692 Forwards supplemental info in support of pro
reactor vessel temp/pressure limitation curves. Addl i
describes development of curves
SMITH, R L Vermont Yankee Nuclear Power Corp 81/01
07183 001

8101270746 Forwards revision to util 800919 proposed lo
test program
SMITH, R L Vermont Yankee Nuclear Power Corp 81/01
07545 292

8101300315 Submits results of evaluation of BWR scram d
design in response to NRC 801001 request Sys mods sho
implemented, including installation of two independent
instrument vols & addl coolant boundary valves.
HEIDER, L H Vermont Yankee Nuclear Power Corp 81/0
07586 329

8101300487 Submits proposal to install Class IE protect
end of next refueling outage, as required in NRC 80092
HEIDER, L H Vermont Yankee Nuclear Power Corp 81/0
07587 028

0 Inspection reports, IE Bulletins & correspondence

8101100183 Forwards IE Insp Rept 80-271/80-10 on 800705
noncompliance noted
BRUNNER, E J, Region 1, Philadelphia, Reactor Operati
Support Branch 80/10/15 2pp 07438 032

B101140707 Updates B00919 response to IE Bulletin B0-17, Suppl 1.
"Failure of 76 of 185 Control Rods to Fully Insert During
Scram at BWR." in response to NRC request for more detailed
info re installed level monitoring sys Diagrams encl
CONWAY, W F Vermont Yankee Nuclear Power Corp B0/12/18. 4pp
07461 306

B101130391 Forwards IE Bulletin B0-25. "Operating Problems W/Target
Rock Safety-Relief Valves at BWRs " Written response
required
ORIER, B H Region 1, Philadelphia, Office of the Director.
B0/12/19. 1p 07449 149

B101160054 Ack receipt of B01114 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-271/B0-12.
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch B0/12/19 1p 07469 281

--B101160065 Responds to NRC B01023 ltr re violations noted in IE Insp
Rept 50-271/B0-12 Corrective actions weld data sheet & valve
packing list rewritten from other job associated
documentation
CONWAY, W F Vermont Yankee Nuclear Power Corp B0/11/14 5pp
07469 282

--B101160072 Forwards IE Insp Rept 50-271/B0-12 on B00812-15 & notice of
violation
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch B0/10/23 2pp 07469 287

--B101160077 Notice of violation from insp on B00812-15
* Region 1, Philadelphia, Office of the Director B0/10/14 3pp
07469 289

--B101160087 IE Insp Rept 50-271/B0-12 on B00812-15 Noncompliance noted.
Failure to update valve lineup procedures to include newly
installed instrument air valves
BLUMBERG, N J, RAYMOND, W, COLLINS, B Region 1, Philadelphia,
Office of the Director. B0/10/14 10pp 07469 292

R Periodic operating reports & related correspondence

B101210500 Forwards monthly operating rept for Dec 1980
CONWAY, W F Vermont Yankee Nuclear Power Corp B1/01/14 1p
07490 177

--B101210505 Monthly operating rept for Dec 1980
BERNARD, D Vermont Yankee Nuclear Power Corp. B1/01/13 11pp
07490 178

B Reportable occurrences, LERs & related correspondence

B101050425 Forwards LER B0-040/03L-0
MURPHY, W P. Vermont Yankee Nuclear Power Corp B0/12/24 1p.
07390 128

--B101050433 LER B0-040/03L-0 on B01130, discovered continuous environ air
samples at sample station A12 2 not being drawn. Caused by
main fuse blowing out Entire station replaced & electrical
surge suppressor installed.
MURPHY, W P Vermont Yankee Nuclear Power Corp B0/12/24 1p.
07390 129

B101090224 PNO-I-B0-181 on B01229, while conducting surveillance for
leakage, two through-wall cracks were found in 3-ft straight
section of 4-inch cleanup sys piping Cleanup sys isolated &
power held at 25% pending repair.
GREENHAW, E., BRUNNER, E J Region 1, Philadelphia, Office of the
Director. B0/12/30 2pp. 07442 270

B101080347 Forwards LER B1-001/01P-0
MURPHY, W P. Vermont Yankee Nuclear Power Corp B1/01/02. 1p
07419 345

--B101080352 LER B1-001/01P-0 on B10101, MSIVs B08 & B5A closing time
exceeded Tech Spec limit of 5-s & relay 5A-K3F failed to
de-energize Cause under investigation
MURPHY, W P. Vermont Yankee Nuclear Power Corp B1/01/02 2pp.
07419 346

B101150661 Forwards LER B0-042/03L-0
MURPHY, W P. Vermont Yankee Nuclear Power Corp. B1/01/12 1p.
07463 289

--B101150685 LER B0-042/03L-0 on B01211, control rod block was not
received as required per Tech Spec Caused by arm on GE
limit switch Model CR-1156 working loose & being bent by
platform Arm straightened & tightened
MURPHY, W P Vermont Yankee Nuclear Power Corp B1/01/12 1p
07463 290

B101220459 Forwards LER B0-043/03L-0
MURPHY, W P Vermont Yankee Nuclear Power Corp B1/01/16 1p
07505 202

--B101220462 LER B0-043/03L-0 on B01220, reactor core isolation cool
valve 15 had seat leakage of 1.531 lbm/hr, exceeding Tech
Specs No cause noted Valve seating surfaces lapped & valve
retested
MURPHY, W P Vermont Yankee Nuclear Power Corp B1/01/16 1p
07505 203

V Operator Examinations

B101060416 Responds to HR Denton 791030 ltr & NUREG-0737, Item 1 A
util established program to hire & extensively train group
of engineers Hiring & some training completed w/estimated
completion date remaining B10601
CONWAY, W F Vermont Yankee Nuclear Power Corp B0/12/30 3pp
07399 023

DUCKET 50-272 SALEM NUCLEAR GENERATING STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B101070387 Ltr to all licensees of operating reactor plants, CP hold
& CP applicants. Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B10102 & by applicants as part of PSAR
EISENHUT, D O Division of Licensing B0/11/13 2pp

B101070551 Releases public version of util revised emergency plan
FELTON, J M Division of Rules and Records B0/11/14 1p
07309 001

--B101070557 Forwards public version of util B00930 revisions to
emergency plan
L13R1221, F P Public Service Electric & Gas Co. of New Jersey
B0/10/03 2pp 07309 031

--B101070562 Public version of revisions to emergency plan
* Public Service Electric & Gas Co. of New Jersey B0/09/30
48pp 07309 001

B101130165 Advises of provisions of 10CFR50, App R, that are applica
to fire protection features of facility FR notice & summary
of staff requirements to resolve open items encl No open
items for facility W/o encl
EISENHUT, D O Division of Licensing B0/11/24 3pp 07456 303

B101070533 Releases public version of revision to util emergency p
FELTON, J M Division of Rules and Records B0/12/17 1p
07404 147

--B101070540 Forwards public version of revision to emergency plan
response to NRC request for addl info
L13R1221, F P Public Service Electric & Gas Co. of New Jersey
B0/12/05 1p 07404 149

--B101070543 Public version of revision to emergency plan.
* Public Service Electric & Gas Co. of New Jersey B0/12/05
2pp 07404 154

B101290198 Forwards questions re guard training & qualification p
Requests response within 30 days Questions & comments
withheld (ref 10CFR2 750)
VARONA, S A Operating Reactors Branch 1 B1/01/05 2pp 07575

B101200642 Releases public version of util revised emergency plan
FELTON, J M Division of Rules and Records B1/01/06 1p
07187 001

--B101200644 Forwards public version of revised sections of emerge
ncy plan, in response to NRC request for addl info
UPER172, R A Public Service Electric & Gas Co. of New Jersey
B0/12/19 1p 07187 001

--B101200645 Public version of revised sections of emergency plan
* Public Service Electric & Gas Co. of New Jersey B0/12/19
130pp. 07187 001

B101270616 Requests revised ltr from NRC re-evaluating B00712 evacuation study. Lack of coordination of various NRC divs w/respect to reviewing or issuing ltr re emergency preparedness appears evident.
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey
B1/01/21 1p 07519 067

C. Adjudicatory correspondence

B101100690 Forwards revised order for mod of license, correcting refs in B00629 order. Hearing date also revised.
EISENHUT, D. G. Division of Licensing 80/09/19 2pp. 07443:173

--B101100693 Revised order amending License DPR-70. Info requested by IE Bulletin 79-012 must be submitted to IE by B01101.
EISENHUT, D. G. Division of Licensing 80/09/19 6pp 07443:175

B101070410 Requests to make limited appearance statement at licensing hearing.
NOTERMAN, J. P. Affiliation Unknown 80/12/27 1p 07309:001

B101205277 Findings of fact & conclusions of law in support of B01111 exceptions to AS-3 B01027 initial decision re applicant proposed expansion of fuel storage. Certificate of Svc encl.
COLEMAN, A. C., COLEMAN, E. G. Affiliation Unknown. B1/01/13 26pp 07167 001

B101230647 Order accepting intervenors AC & EQ Colemans late brief. Time for filing remaining briefs shall be computed from B10113 Certificate of Svc encl.
EISENHUT, C. J. Atomic Safety and Licensing Appeal Panel B1/01/19 4pp 07512:290

J. Insurance & indemnity information

B101270735 Forwards Endorsement 5 to NELA Binder ES-60
CORREA, M. A. Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc
Div B1/01/22 2pp 07548 053

B101270738 Forwards Endorsement 42 to NELA Policy NF-230 & Endorsement 34 to MAELU Policy NF-90
CORREA, M. A. Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc
Div B1/01/22 3pp 07548:050

P. Operating license stage documents & correspondence

B101100690 Forwards revised order for mod of license, correcting refs in B00629 order. Hearing date also revised.
EISENHUT, D. G. Division of Licensing. 80/09/19. 2pp 07443:173

--B101100693 Revised order amending License DPR-70. Info requested by IE Bulletin 79-012 must be submitted to IE by B01101.
EISENHUT, D. G. Division of Licensing 80/09/19 6pp 07443:175

B101280294 Releases public version of emergency plan manual implementation procedures for facilities
FELTON, J. M. Division of Rules and Records 80/11/14. 1p. 07421 095

--B101080299 Forwards public version of emergency plan manual implementation procedures for facilities
LIPRIZZI, F. P. Public Service Electric & Gas Co. of New Jersey.
80/10/03 2pp. 07421 076.

--B101080305 Public version of emergency plan manual implementation procedures. Revision 12
ELLERMAN, N. A., STILLMAN, J. L. Public Service Electric & Gas Co. of New Jersey. 80/08/18 170pp. 07421 098.

B101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under STS License amend application. Adding model Tech Specs to App A should be submitted within 120 days.
EISENHUT, D. G. Division of Licensing 80/11/20. 1p

--B101100271 Revised Pages 3/4 7-22 through 28.8 3/4 7-5 & 7-6 & 6-17 to STS snubber inservice insp requirements.
* Division of Licensing 80/11/20 10pp

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports"
EISENHUT, D. G. Division of Licensing. 80/11/26. 8pp

B101100551 Forwards Amend 28 to License DPR-70. safety notice of issuance & availability
VARQA, S. A. Operating Reactors Branch 1 80/12/09

--B101100557 Amend 28 to License DPR-70. revising Tech voltages for individual battery cells, water level in reactor cavity during spent fuel movement & administrative actions
VARQA, S. A. Operating Reactors Branch 1 80/12/09 07440 348

--B101100567 Safety evaluation supporting Amend 28 to * Operating Reactors Branch 1 80/12/09 4pp

--B101100572 Notice of issuance & availability of Amend DPR-70
VARQA, S. A. Operating Reactors Branch 1. 80/12/09 07441 003

B101080104 Requests change in fee determination for ap organizational changes to indicate whether fee is Class II or Class I
B1005, R. M. License Fee Management Branch 80/12/11 07420 347

--B101080114 Forwards ltrs to four licensees requesting for organizational changes. Since facility request similar, requests consideration whether preliminary determination of Class II fee is correct.
B1005, R. M. License Fee Management Branch. 80/11/11 07420 348

B101120022 Forwards Amend 29 to License DPR-70. safety notice of issuance & availability
VARQA, S. A. Operating Reactors Branch 1 80/12/11

--B101120024 Amend 29 to License DPR-70. modifying 5-yr data for sodium hydroxide flow check from spray add through sample line near flow ductors.
VARQA, S. A. Operating Reactors Branch 1. 80/12/11 07446 247.

--B101120026 Safety evaluation supporting Amend 29 to * Office of Nuclear Reactor Regulation, Director. 07446:254

--B101120030 Notice of issuance & availability of Amend DPR-70
VARQA, S. A. Operating Reactors Branch 1 80/12/11 07446:256.

B101210445 Forwards responses to questions on Rule 50. Updating of FSARs & FR notice of final rule SEP plan not comply w/rule until program is complete. Non-BEP must comply within specified time frame.
EISENHUT, D. G. Division of Licensing. 80/12/15. 1p

B101050082 Clarifies inability to comply w/Tech Spec Amend 27. Margin of safety available from charging & injection pumps shown Operation w/tested flow of 10 below Tech Specs does not compromise safety limits
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 80/12/19 5pp. 07376 231.

B101200634 Forwards AEC 680409 ltr. in response to req rate hearing for facility. Licensee initiated 790619 w/NRC.
ROSS, W. J. Operating Reactors Branch 1 80/12/22.

--B101200636 Forwards request for addl info needed to CP application. Includes info re adequacy of QC & procedures, site selection analysis, instrumentation info in FSAR & accident analysis
MORRIS, P. A. Atomic Energy Commission, Directorate 68/04/09 19pp. 07476:282.

B101300427 Forwards Amend 30 to License DPR-70. safety notice of issuance & availability
VARQA, S. A. Operating Reactors Branch 1. 80/12/22.

--B101300433 Amend 30 to License DPR-70. revising Tech flux difference target band.
VARQA, S. A. Operating Reactors Branch 1. 80/12/22 07583 244.

--B101300437 Safety evaluation supporting Amend 30 to * Office of Nuclear Reactor Regulation, Director. 07583 254.

--B01300442 Notice of issuance & availability of Amend 30 to License DPR-70
VARQA, S. A. Operating Reactors Branch 1 80/12/22 2pp 07583 256

B01190794 Forwards summary of B01210 meeting w/util re util mgt reorganization List of attendees encl
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/23 3pp 07473 078

B01160481 Submits info re installation of high density spent fuel racks Evaluation of specific functions in installation process revealed 6 7 man rem occupational exposure
MITTL, R. L. Public Service Electric & Gas Co. of New Jersey. 80/12/31 2pp 07472 137

B01270825 Forwards Amend 31 to License DPR-70, safety evaluation & notice of issuance & availability
VARQA, S. A. Operating Reactors Branch 1 81/01/06 2pp 07549-098

--B01270831 Amend 31 to License DPR-70, revising App A Tech Specs to reflect changes in organization that operates & supports operation of Units 1 & 2
VARQA, S. A. Operating Reactors Branch 1 81/01/06 17pp 07549-100

--B01270836 Safety evaluation supporting Amend 31 to License DPR-70
* Office of Nuclear Reactor Regulation, Director 81/01/06 4pp 07549-116

--B01270842 Notice of issuance & availability of Amend 31 to License DPR-70
VARQA, S. A. Operating Reactors Branch 1 81/01/06 2pp 07549 120

B01150382 Forwards logic diagrams & electrical schematics, per NRC B01208 request. Logic Diagram 239957-B-9646 will be revised to reflect design mod scheduled for completion during next refueling outage. Aperture cards in PDR.
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey 81/01/09 1p. 07462-203

G. Inspection reports, IE Bulletins & correspondence

B01090847 Ack receipt of B01017 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/80-19 & 50-311/80-14
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/11/07 1p. 03893 224

--B01090852 Responds to NRC B00929 ltr re violations noted in IE Insp Repts 50-272/80-19 & 50-311/80-14 Corrective actions, "hold" area established for rejected items & reject tags will be attached to deficient items
SCHNEIDER, F. W. Public Service Electric & Gas Co. of New Jersey. 80/10/17 5pp. 03893-225

--B01090858 Forwards IE Insp Repts 50-272/80-19 & 50-311/80-14 on B00728-0808 & notice of violation
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/29 2pp. 03893-230

--B01090863 Notice of violation from Insp on B00728-0808
* Region 1, Philadelphia, Office of the Director 80/09/25 2pp 03893-232

--B01090888 IE Insp Repts 50-272/80-19 & 50-311/80-14 on B00728-0808. Noncompliance noted. Failure to follow procedures for receipt, handling & storage of safety-related matl.
NAPUDA, O., SIMONETTI, O. Region 1, Philadelphia, Office of the Director. GREENMAN, E. O. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/25 14pp 03893 234

B01060039 Responds to util B01104 ltr revising response to IE Bulletin 80-11, "Masonry Wall Design" & requesting extension until B01203 to complete detailed analysis of masonry walls at facilities. Extension is acceptable
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/11/19 1p. 07392 214

B01140118 Forwards IE Insp Rept 50-272/80-29 on B01105-06. No noncompliance noted.
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/11/20 2pp. 07460-321

--B01140128 IE Insp Rept 50-272/80-29 on B01105-06. No noncompliance noted. Major areas inspected components associated w/ component cooling water sys & reactor coolant pump re IE Bulletin 79-018
PADLINO, R. J. Region 1, Philadelphia, Office of the Director. EDNETER, S. D. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/11/24 4pp 07460-323

B01070418 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Steam Turbine Steam Inlet Flange" No written response required
GRIER, B. H. Region 1, Philadelphia, Office of the Director 80/11/26 1p 07414 047

B01100760 Responds to IE Bulletin 80-23, "Failures of Solenoid Valves by Valcor Engineering Corp." No sub valves used in safety-related function at facilities
SCHNEIDER, F. W. Public Service Electric & Gas Co. of New Jersey 80/12/12 1p 07443 359

B01060816 Forwards IE Info Notice 80-44, "Actuation of ECCB in Recirculation Mode While in Hot Shutdown" No written response required
GRIER, B. H. Region 1, Philadelphia, Office of the Director 80/12/16 1p 07397-045

R. Periodic operating reports & related correspondence

B01210475 Forwards monthly operating rept for Dec 1980
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey 81/01/12 1p 07187 001

--B01210482 Monthly operating rept for Dec 1980
MILLER, L. K. Public Service Electric & Gas Co. of New Jersey. 81/01/12 40pp 07187 001

S. Reportable occurrences, LERs & related correspondence

B01280504 LER 80-056/01X-1 on B01201, review per IE Bulletin 80-11 showed eight masonry wall areas not erected per design. Analysis underway.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey 80/12/01 2pp 07308 001

B01280479 LER 80-062/01P-0 on B01204, observed that auxiliary feed pumps may be tripped from Unit 1 or 2 control consoles if steam generator low-low level condition exists. Cause under investigation.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey. 80/12/09 2pp. 07308 001

B01230350 Summary of B01205 meeting w/util re seismic design deficiencies of masonry walls in recently constructed Bldg A (control facility) & adjoining walkway.
ROSS, W. J. Operating Reactors Branch 1 80/12/30 3pp 07512

B01090643 Forwards LER 80-066/03L-0
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 81/01/02 2pp 07442 183

--B01090651 LER 80-066/03L-0 on B01126, surveillance requirements fire detection instruments not performed. Caused by personnel error. Entry placed in night order log to emphasize importance of completing surveillance tests.
BTEELE, W. J. Public Service Electric & Gas Co. of New Jersey. 81/01/02 2pp. 07442 185

B01090698 Forwards LER 80-062/03L-0
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey 81/01/02 2pp 07442 023

--B01090707 LER 80-062/03L-0 on B01204, during refueling outage, 10 rate of 15 containment isolation valves exceeded Tech Spec limits. Caused by inadequate test equipment. Valves cleaned & internals replaced.
BTEELE, W. J. Public Service Electric & Gas Co. of New Jersey. 81/01/02 1p 07442-025

B01120320 Forwards LER 80-064/03L-0.
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey 81/01/06 3pp 07447 140

--B01120324 LER 80-064/03L-0 on B01207, Tech Spec flow rate not ob for spray additive tank or sodium hydroxide solution. Caused by difference between startup procedure & surveillance procedure. Tech Specs changed
BTEELE, W. J. Public Service Electric & Gas Co. of New Jersey 81/01/06 1p 07447 143

--B01120376 LER 80-067/03L-0 on B01264 valve 115J139 found stuck open, constituting degradation of primary coolant pressure boundary. Caused not stated Valve tapped w/vallet & successfully retested
STEEL, W J Public Service Electric & Gas Co of New Jersey
81/01/08 1p 07447 155

B01203357 Forwards LER 80-069/03L-0
UDERITZ, R A Public Service Electric & Gas Co of New Jersey
81/01/14 2pp 07477 344

--B01203359 LER 80-069/03L-0 on B01223 steam generator 13 channel 11 steam flow failed high Caused by failure of multiplier/divider unit. Hagan Model 112 Unit replaced, calibr & tested
STEEL, W J Public Service Electric & Gas Co of New Jersey
81/01/14 1p 07477 346

B01203386 Forwards LER 80-068/03L-0
UDERITZ, R A Public Service Electric & Gas Co of New Jersey
81/01/14 2pp 07477 335

--B01203391 LER 80-068/03L-0 on B01220 leak rate on 100-foot containment air lock exceeded Tech Spec limit Caused by failure of inner door seals to maintain pressure Seals adjusted & tested.
STEEL, W J Public Service Electric & Gas Co. of New Jersey
81/01/14 1p 07477 337

B01260552 Forwards LER 80-065/03L-0
UDERITZ, R A Public Service Electric & Gas Co of New Jersey
81/01/15 2pp 07531 147

--B01260642 LER 80-065/03L-0 on B01218 steam leak found in pipe tunnel, auxiliary bldg elevation 84 ft Caused by shearing of pipe nipple connecting valve 10V378 w/vent line Letdown isolated & valve removed Remaining pipe nipple capped off
STEEL, W J Public Service Electric & Gas Co. of New Jersey
81/01/15 1p 07531 149

B01260597 Forwards updated LER 80-009/03X-2
UDERITZ, R A Public Service Electric & Gas Co of New Jersey
81/01/15 2pp 07531 150

--B01260650 Updated LER 80-009/03X-2 on B00117 small leak found in telltale train & in spent fuel pit Caused by leaking welded seams Half-round channels welded over leaking voids.
OSUCH, J C Public Service Electric & Gas Co. of New Jersey
81/01/15 1p 07531 152

B01270491 LER 81-007/01T-0 on B01019 during verification of throttle valve position during lineups, it was observed that valves were not operated to verify position where locking devices installed & bench marks aligned Corrective action taken
MIDJRAH, J Public Service Electric & Gas Co. of New Jersey
81/01/20 2pp 07163 601

B01270561 Forwards updated LER 80-054/01X-1
UDERITZ, R A Public Service Electric & Gas Co of New Jersey
81/01/21 3pp 07546 316

--B01270569 Updated LER 80-034/01X-1 on 791016 fire pump diesel 1 destroyed by fire & on 1016 fire pump diesel 2 failed to start Caused by loss of lubrication for pump 1 & faulty voltage regulator for pump 2
STEEL, W J Public Service Electric & Gas Co of New Jersey
81/01/21 1p 07546 319

V Operator Examinations

B01070329 Forwards info requested in NUREG-0737 re shift technical advisor training program performance testing of PWR relief & safety valves containment min pressure setpoint & instrumentation for detection of inadequate core cooling
MITTL, R L Public Service Electric & Gas Co. of New Jersey
80/12/31 140pp 07369 001

B01130322 Provides addl info re training program to qualify degraded engineers as senior reactor operator license candidates, in response to NRC B01031 request Successful licensing of candidates will minimize routine overtime. Related info encl
SCHNEIDER, F W Public Service Electric & Gas Co. of New Jersey
81/01/06 30pp 07447 281

A Application/construction stage documents & correspondence

B01220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lateral Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

B01130389 Recommends denial of B Fleischer B01017 request that Commission issue supplemental EIS re environ consequences of Class 9 accident at facility No evidence presented to warrant reopening environ record
OGLESBY, D A Pacific Gas & Electric Co 81/01/08 2pp 07431 275

B01210555 Forwards environ qualification of Class IE control cable wfg by Continental Wire & Cable Co Requests ack of receipt.
CRANE, P A Pacific Gas & Electric Co. 81/01/16 11pp 07487 266

B01270472 Forwards addl info re QA program per NRC B01007 request info will be incorporated into FSAR
CRANE, P A Pacific Gas & Electric Co. 81/01/22 29pp 07545 193

B01300331 Forwards info addressing issues to be reviewed for full power operation, including operating procedures, control room design, operational & low power testing, auxiliary feedwater sys, containment design & radiation protection
CRANE, P A Pacific Gas & Electric Co. 81/01/26 106pp 07594 174

F Security, medical, emergency & fire protection plans

B01090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B01012 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

B01060312 Requests evaluation of potential complicating factors caused by earthquakes which either initiate or follow initiation of accidents Adequacy review of state & local capabilities re earthquakes requested of FEMA
TEDESCO, R L Assistant Director for Licensing 80/12/16 5pp 07399 048

B01100849 Informs that licensees must conduct emergency exercise within one yr from B010401 or prior to issuance of OL Requests schedule of drills & exercises
ENGELKEN, R H Region 5, San Francisco, Office of the Director, 80/12/19 1p 07442 298

B01300741 Requests that encl facility emergency planning info be made publicly available w/o encl
BOUDER, J L Division of Rules and Records 80/12/31 1p 07445 129

B01100852 Notifies of acceptance of B00711 guard training & qualification plan.
MIRAGLIA, F J Licensing Branch 3 81/01/01 3pp 07442 299

B01120301 Forwards comments re Revision 10 of physical security plan to be resolved prior to license issuance. Comments withheld (ref 10CFR2 790)
MIRAGLIA, F J Licensing Branch 3 81/01/01 5pp 07447 204

B01190696 Requests that encl facility emergency planning info be made publicly available w/o encl B012240129
BOUDER, J L Division of Rules and Records 81/01/09 1p 07472 323

B01190700 Requests that encl facility emergency planning info be made publicly available w/o encl B012290469
BOUDER, J L Division of Rules and Records 81/01/09 1p 07472 321

B01300722 Releases public version of util emergency plan response.
FELTON, J M Division of Rules and Records 81/01/26 1p 07584 159

--B01300728 Forwards public version of response to NRC B00826 request for addl info re site emergency plan, Revision 2 & B00830 request re field property.
CRANE, P A Pacific Gas & Electric Co. 81/01/13 42pp 07584 160

--B01300739 Superior Court order granting land rights to util for implementation of emergency response plans
KIRKPATRICK, R California, State of 80/10/14 3pp 07584 220

DOCKETED ITEMS

G Adjudicatory correspondence

B101030382 Response to joint intervenors' contentions & CA Governor Brown statement on subjs in which he intends to participate Opposes litigating contentions because record is closed & no grounds exist to reopen records
CRANE, P. A., GEHR, A C Pacific Gas & Electric Co GEHR, A C Snell & Wilmer 80/12/18 47pp 07385 099

--B101050388 Advises that FEMA/NRC Bleering Committee has determined that low power testing criteria are not needed Encl position is adequate.
ORIMES, B K Emergency Preparedness Program Office (after B01119 see 18E) RYAN, R Office of State Programs, Director 80/12/18 2pp 07385.146

B101060018 Response to Joint Intervenor's request for directed certification Opposes request because record is closed on all issues & request raises no significant new evidence. Certificate of Svc encl
CHANE, P A., GEHR, A C Pacific Gas & Electric Co GEHR, A C Snell & Wilmer 80/12/18 37pp 07397 066

B101210136 Informs that technical divisions will provide testimony to refute CA Governor Brown B01203 Contentions 1.2.3 & 5 re fuel load/low power license
TEDESCO, R L Assistant Director for Licensing 80/12/31 1p 07489 361

B101090223 Request, identified as proposed findings of fact, that ASLB 790927 partial initial decision be affirmed. Decision concluded that 0.75 g acceleration was appropriate. reanalysis reasonable & Category 1 structures adequate
OLMSTEAD, W J, KETCHEN, E O Hearing Branch 4 81/01/06 88pp 07423 284

B101120459 Certifies svc of NRC proposed findings of fact & conclusions of law in reopened seismic proceedings & response to ASLAB questions on B10106
KETCHEN, E O Hearing Branch 4 81/01/06 3pp 07447 169

B101140877 Requests that WE Martin, Batelle-Columbus Labs, be deleted from svc list.
SMERBER, E B Atomic Safety and Licensing Board Panel 81/01/08 1p 07458 218

B101140949 Joint Intervenor's reply to applicant & NRC responses to statement of contentions. Objections undermined by recent NRC revision of 780620 statement of policy. Adopts Governor Brown contentions. Certificate of Svc encl.
REYNOLDS, J R, OLEISCHAKER, D San Luis Obispo Mothers for Peace REYNOLDS, J R Center for Law in the Public Interest 81/01/08 10pp 07458 227

B101140279 Response to ASLB B01217 order, requesting continued deferral of Joint Intervenor's 790909 motion on Class 9 issues. Emergency planning contentions must be admitted & ASLAB decision on seismic matters issued Certificate of Svc encl
OLMSTEAD, W J Hearing Branch 4 81/01/12 13pp 07498 124

B101140725 Forwards NRC Div of Licensing B10101 ltr to util re Revision 10 to security plan & NRC comments on revision. Comments withheld (ref 10CFR2.790) w/o ltr.
SWARTZ, L L Office of the Executive Legal Director 81/01/12 1p 07458 262

B101160278 Supplement to reply to POME & NRC responses to Joint Intervenor's statement of contentions On Page 3, Line 9, 17 should be deleted & on Line 14, 14, 1B & 20 deleted & 14, 15, 1B, 19 & 24 inserted. Certificate of Svc encl
REYNOLDS, J R San Luis Obispo Mothers for Peace REYNOLDS, J R Center for Law in the Public Interest FLEISCHAKER, D Fleischaker, D B 81/01/12 5pp 07470 279

B101260301 Response opposing Joint Intervenor's & CA Governor Brown B01213 proposed findings re 791015 Imperial Valley earthquake. Certificate of Svc encl
MORTON, B, FURBUSH, M H., GEHR, A C Pacific Gas & Electric Co 81/01/16 32pp 07523 340

B101270739 Brief discussing definition of "several" as used in 10CFR73.1(c)(1). Term "several" means up to & including three attackers
SWARTZ, L L Antitrust Division OLMSTEAD, W J Hearing Branch 4 81/01/19 8pp 07183 001

B101280131 Order scheduling B10128 conference w/ASLB & parties' counsel to be held at 10:30 a.m. re matters discussed in B10128 conference

B101280620 Response to Joint Intervenor's B10108 reply to applicant & NRC responses to contentions. Revised statement of policy. CL1-B0-42, did not change Commission position TH1-related contentions must be denied w/Certificate of Svc
NORTON, B, FURBUSH, M H., GEHR, A C Pacific Gas & Electric Co 81/01/23 13pp 07557 292

H General correspondence

B101120046 Urges rejection of facility license in light of TH1 incident
ROQUINSON, T Affiliation Unknown 79/04/04 1p 07447 085

B101090372 Responds to 790404 postcard re facility NRC has reacted positively to improve safety of all nuclear power plants in operation & under const. Response to concern re proximity of Hosgr's fault to facility encl
MIRAGLIA, F Licensing Branch 3 80/12/11 3pp 07423 268

B101060030 Responds to 790414 ltr expressing concerns re facility safety. Low level radioactivity effects, storage of high level radwaste & ability to withstand severe earthquake poses insignificant level of danger to public
MIRAGLIA, F J Licensing Branch 3 80/12/16 6pp 07399 151

B101090791 Responds to Apr 1979 ltr to President Carter expressing concern re nuclear power safety. NRC currently requires all applicants for new GLs to modify design & operation of nuclear plants to conform to TH1-related requirements
MIRAGLIA, F J Licensing Branch 3 80/12/16 6pp 07309 001

B101120002 Responds to 790402 ltr NRC is presently conducting generic proceeding to reassess degree of confidence in disposal methods to determine disposal availability & to provide storage.
MIRAGLIA, F J Licensing Branch 3 80/12/16 4pp 07447 109

B101120191 Responds to B01208 ltr ASLB considering application for GL authorizing fuel loading & low power testing of Unit 1 ASLAB reviewing portions of ASLB "Partial Initial Decision" re seismic matters & applicant physical security plan.
INGRAM, F L Office of Public Affairs 80/12/16 1p 07309 001

--B101120196 Requests info re status of facility & names of decisionmakers
QANNIS, B Affiliation Unknown 80/12/08 1p 07309 001

B101190128 Ack receipt of B01214 ltr expressing concern re opening of facilities. Ltr will be placed in appropriate public docket file
HANCHETT, J O Region 5, San Francisco, Office of the Director 81/01/02 1p 07475 323

--B101190161 Expresses concern re opening of facilities
HAYES, M Affiliation Unknown 80/12/14 1p 07475 324

B101190284 Ack receipt of B01227 ltr expressing concern re opening of facilities. Ltr will be placed in appropriate public docket file
HANCHETT, J O Region 5, San Francisco, Office of the Director 81/01/02 1p 07476 089

--B101190777 Expresses concern re opening of facilities.
BERRIGAN, S Affiliation Unknown 80/12/27 1p 07476 090

B101200209 Ack receipt of B01227 ltr expressing concern re opening of facilities. Ltr will be placed in appropriate public docket file
HANCHETT, J O Region 5, San Francisco, Office of the Director 81/01/02 1p 07187 001

--B101200126 Expresses concern re opening of facility.
HOFBERG, B J Affiliation Unknown 80/12/27 1p 07187 001

I Inspection reports, IE Bulletins & correspondence

B012290008 Responds to IE Bulletin B0-15, "Possible Loss of Emergency Notification Sys w/Loss of Offsite Power." Administrative Procedure MAP C-11 will be revised to incorporate Item 5 Related correspondence
CRANE, P A Pacific Gas & Electric Co 80/11/25 2pp 07344 201

B101060014 Responds to IE Bulletin B0-19 No CP Core Model H02X-1011 mercury-wetted relay's used in logic matrix at facility
CRANE, P A Pacific Gas & Electric Co 80/11/25 1p 07187 001

--6012160151 Quarterly Financial Rept Sept 1980 & support
 comments
 * General Public Utilities 80/11/14 44pp

P Operating license stage documents & correspondence

B1011G0254 Ltr to all licensees (except SEP licensees) for
Revision 1 of interservice surveillance requirements for
snubbers under STS License amend application adding mod
Tech Specs to App A should be submitted within 120 days
EISENHUT, D O Division of Licensing 80/11/20 1p

--8101100271 Revised Pages 3/4 7-22 through 20, B 3/4 7-9
STB snubber inservice insp requirements
• Division of Licensing 80/11/20 1000

8010220466 Ltr to all power reactor licensees & applicants
summary of 801112 meeting re implementation of guidance
Unresolved Safety Issue A-12. "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D O Division of Licensing. 80/11/26 Bop

B10190113 Ltr to all BWR licensees forwarding B01201 gen
evaluation re BWR scram discharge sys Recommends short-
actions necessary to assure safe operation of OE BWRs
pending permanent design changes
EISENHUT, D O Division of Licensing B0112/09 2pg

--8101190141 Generic safety evaluation re short-term action
assure continued safe operation of operating BWRs. Cont
operation of plants is acceptable pending permanent de
mod Criteria for implementing design mods encl.
* Division of Licensing 80/12/01 212pp. 07183.00

0101210445 Forwards responses to questions on Rule 90.71e.
Updating of FBARS & FR notice of final rule. BEP plants
not comply w/rule until program is complete. Non-BEP plants
must comply within specified time frame.
EIGENHUT.D.O Division of Licensing 80/12/15. 13pp.

B101070466 Responds to util B01126 revised schedule for up position indication sys (acoustic monitors) for Facility Shutdown solely to upgrade sys is unnecessary Unit 2 mod should be completed by B10630
REID.R W Operating Reactors Branch 4 B012/10 200

8101090003 Forwards response to 800907 request re outage d
length of outages for all ECCB for 750101-800901.
DALTROFF,B.L Philadelphia Electric Co. 81/01/05 26p
07309-001

9101130314 Forwards info re plant sys & equipment & engine
evaluating new design stds. in response to NUREG-0737
requests
DALTRDFF, S L Philadelphia Electric Co 01/01/08 93p
07452-011

8101120299 Forwards application to amend License DPR-44 &
MEDD-24229-1, "Peach Bottom Atomic Power Station Units 2
Single Loop Operation"
BRADLEY, E J Philadelphia Electric Co 01/01/09 1p.

--8101120304 Application to amend Licenses DPR-44 & DPR-56
single loop operation beyond 24-h. provided specified
adjustments are implemented Certificate of Gvc & effid
encl.
BAUER, E O , BRADLEY, E J Philadelphia Electric Co. O
6pp 07446 061

--B101120308 Proposed changes to Tech Specs to permit single
operation beyond 24-h
* Philadelphia Electric Co B1/01/09, 20pp, 07446

--8101120309 "Peach Bottom Atomic Power Station Units 2 &
Operation"
MERIKSON, P H General Electric Co. NEDO-24229-1 00
33pp 07446:087

B101230474 Application for amend of License DPR-44 changin
Table 3 2 A to temporarily suspend trip level setting
prescribed for main steam line tunnel exhaust duct high
for five minutes.
COOPER, M. J. Philadelphia Electric Co. 01/01/18 In

8101270728 Submits implemented changes called for by NUREG
Feedwater Nozzle & Control Rod Drive Return Line Nozzle
Cracking." Implementation program includes sys mod, feedw
nozzles, operating procedures, insp & leak testing.
GALLAGHER, J W Philadelphia Electric Co. 81/01/21. 5p
07348 066

tion reports. IE Bulletins & correspondence

Ack receipt of B01105 ltr informing NRC of steps taken to violations noted in IE Insp Repts 90-277/80-28 & 90-278/80-20

E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/11/13 1p 07431 329

211 Responds to NRC B01016 ltr re violations noted in IE Insp Repts 90-277/80-20 & 90-278/80-20 Corrective actions: drywell and re-inspected & reactor startup checklist revised withheld (ref 10CFR2 790).

OFF, B L, Philadelphia Electric Co 80/11/09 3pp 07502 123

218 Forwards IE Insp Repts 90-277/80-20 & 90-278/80-20 on 90-277/80-20 & notice of violation
E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/10/16 3pp 07431 329

224 Notice of violation from insp on B00801-31
Region 1, Philadelphia, Office of the Director 80/10/08 2pp 07502 139

232 Notice of violation from insp on B00801-31 Details withheld (ref 10CFR2 790)
Region 1, Philadelphia, Office of the Director 80/10/08 1p 07414 144

244 IE Insp Repts 90-277/80-20 & 90-278/80-20 on B00801-31 Noncompliance noted failure to follow housekeeping procedures. Failure to positively control designated vehicle. A submittal of LERs Portions withheld (ref 10CFR2 790)
H. A. R., COWILL, C. J., RHOADS, O O Region 1, Philadelphia, Office of the Director 80/10/08 19pp 07431 335

250 Forwards IE Insp Repts 90-277/80-31 & 90-278/80-23 on 1002-03 & 06 No noncompliance noted
E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/11/21 2pp 07500 178

254 IE Insp Repts 90-277/80-31 & 90-278/80-23 on B00930, 1002-03 No noncompliance noted Major areas inspected: QA, QA implementation including auditing, design & changes/

A. Q. Region 1, Philadelphia, Office of the Director
MAN, E. G. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/11/20 11pp 07500 180

263 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Turbine Steam Inlet Flange " No written response
H. Region 1, Philadelphia, Office of the Director 80/11/20 1p 07414 038

269 Forwards IE Info Notice 80-43, "Failures of Continuous Water Monitor for BWR Discharge Vol at Dresden Unit 2 " No response required
H. Region 1, Philadelphia, Office of the Director 80/11/20 1p 07377 245

275 Responds to IE Bulletin 80-23, "Failures of Solenoid Valves Valcor Engineering Corp." Valves w/Parts V70900-21-1 80-21-3 are not in use in safety-related functions at Dresden.
F. B. L. Philadelphia Electric Co. 80/12/10 2pp 07443 360

286 Forwards IE Info Notice 80-40, "Potential Failure of BWR Manual Scram Capability." No response required.
H. Region 1, Philadelphia, Office of the Director 80/11/20 1p 07397 351.

296 Ack receipt of B01204 ltr informing NRC of steps taken to violations noted in IE Insp Repts 90-277/80-08 & 90-278/80-07
E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/12/17 1p 07502 120.

303 Supplements response to Items A & B contained in IE Insp Repts 90-277/80-08 & 90-278/80-07. All site personnel will be trained on "Special Nuclear Plant Rules" for ready ref to improve plant performance.
OFF, B L, Philadelphia Electric Co 80/12/04 1p 07502 121.

314 Ack receipt of B01119 ltr informing NRC of steps taken to violations noted in IE Insp Repts 90-277/80-08 & 90-278/80-07
H. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/12/16 1p 07502 122.

--B01220149 Responds to NRC B01028 ltr re violations noted in IE Insp Repts 90-277/80-08 & 90-278/80-07 Corrective actions fixed damaged seal & reactor work permit area identification mechanisms re located for greater access
DALTROFF, B L Philadelphia Electric Co 80/12/04 4pp 07502 123

--B01220153 Forwards IE Insp Repts 90-277/80-08 & 90-278/80-07 on B00401-30 & notice of violation. Items of Noncompliance A & B are recurring violations
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/10/28 3pp 07502 127

--B01220161 Notice of violation from insp on B00401-30
* Region 1, Philadelphia, Office of the Director 80/10/27 2pp 07502 139

--B01220167 IE Insp Repts 90-277/80-08 & 90-278/80-07 on B00401-30 Noncompliance noted failure to maintain fire retardant seal on electrical cable penetration & failure to follow reactor work permit requirements
COWILL, C. J., BLOUGH, A. R. Region 1, Philadelphia, Office of the Director
GREENMAN, E. O. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/10/27 11pp 07502 132

B01070069 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR " No written response required
GRIER, D. H. Region 1, Philadelphia, Office of the Director 80/12/18 1p 07414 144

B01130075 Forwards IE Bulletin 80-25, "Operating Problems w/Target Rock Safety-Relief Valves at BWRs " Written response required
GRIER, D. H. Region 1, Philadelphia, Office of the Director 80/12/19 1p 07449 154

B01150867 Ack receipt of B01119 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 90-277/80-29 & 90-278/80-21
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/12/23 1p 07464 337

--B01150873 Responds to NRC B01030 ltr re violations noted in IE Insp Repts 90-277/80-29 & 90-278/80-21 Corrective actions employee instructed in correct procedure for maintaining secondary containment App 2 withheld (ref 10CFR2 790)
DALTROFF, B L Philadelphia Electric Co 80/11/19 3pp 07464 338.

--B01150888 Forwards IE Insp Repts 90-277/80-29 & 90-278/80-21 on B00901-30 & notices of violation. App A & B App B withheld (ref 10CFR2 790)
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/10/30 4pp 07464 341

--B01150897 Notices of violation from insp on B00901-30. App A. App B withheld (ref 10CFR2 790)
* Region 1, Philadelphia, Office of the Director 80/10/29 2pp 07464 343

--B01150891 IE Insp Repts 90-277/80-29 & 90-278/80-21 on B00901-30 Noncompliance noted failure to maintain secondary containment & failure to follow escort procedures Details withheld (ref 10CFR2 790)
MCADAM, E. C. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch
BLOUGH, A. R., COWILL, C. J. Region 1, Philadelphia, Office of the Director 80/10/29 15pp 07464 345

B01060789 Addl response to FOIA request for documents re experimental use of DDH NS-1 solvent at Dresden 1 & Peach Bottom Forwards GE rept, "Radiation Level Assessment of Dresden 1 Decontamination Pilot Loop - Final Rept." FELTOW, J. M. Division of Rules and Records. 80/12/29 1p 07400 104

R Periodic operating reports & related correspondence

B010210522 Forwards monthly operating repts for Dec 1980
COONEY, M. J. Philadelphia Electric Co 81/01/09 1p 07490 210.

--B010210528 Monthly operating repts for Dec 1980
ALDEN, W. M. Philadelphia Electric Co 81/01/10 10pp 07490 211

... to ... correspondence ...

... reactor water cleanup ... Tech Spec ...

... pressure switch PS 2-2-134C ...

... while cooling subcritical reactor ...

... A BWR pump room coolers failed ...

... at 100% power during surveillance ...

... at 100% power during surveillance ...

... during subcritical reactor ...

... steel generator EG output breaker to ...

... turbine steam supply high ...

... stand by gas treatment sys manual ...

... reactor core isolation cooling ...

... request to postpone until 810218 ...

... 810217 2pp 07445 311

... engineering studies ...

... 0735

DCCKET 50-278 PEACH BOTTOM: ATOMIC POWER STATION, UNIT 3

F Security, medical, emergency & fire protection plans

810190387 Ltr to all licensees of operating reactor plant & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR EISENHUT.D O Division of Licensing 80/11/13 2pp.

8101090449 Notifies of Commission approval of encl inter suspending previously approved completion dates for fire protection mods Specific schedules for mods will be effective pending publication of final rule EISENHUT.D O Division of Licensing 80/11/18 3pp.

8101230326 Releases public version of util emergency plan FELTON J M Division of Rules and Records 81/01/15 07513 507

--8101230330 Forwards public version of emergency plan for PA disaster operations plan Annex E & York, Lancaster & Chester Counties, PA emergency plans DALTRCFF, S L Philadelphia Electric Co 81/01/02 07513 309

--8101230338 Public version of emergency plan includes PA disaster operations plan Annex E & York, Lancaster & Chester Counties, PA emergency plans Philadelphia Electric Co 80/12/31 600pp 07513 309

I Financial information

8101260144 Forwards BEC Form 10-0, Quarterly Financial Report comments, in response to NRC 790721, 1109 & 800811 requests for info re significant financial developments affecting utility in restart proceeding CCH004, V H General Public Utilities. 80/11/26. 3pp.

--8101260154 Quarterly Financial Rept Sept 1980 & support comments General Public Utilities. 80/11/14. 44pp

P Operating license stage documents & correspondence

8101100254 Ltr to all licensees (except BEP licensees) for Revision 1 of interservice surveillance requirements for snubbers under STB License amend application adding mod Tech Specs to App A should be submitted within 120 days EISENHUT.D O Division of Licensing. 80/11/20. 1p.

--8101100271 Revised Pages 3/4 7-22 through 26.8 3/4 7-5 STB snubber interservice insp requirements Division of Licensing 80/11/20. 10pp

8101220466 Ltr to all power reactor licensees & applicant summary of 801112 meeting re implementation of guidance Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" EISENHUT.D O Division of Licensing. 80/11/26. 6pp.

810190113 Ltr to all BWR licensees forwarding 801201 generic evaluation re BWR screen discharge sys. Recommends short-term actions necessary to assure safe operation of OE BWRs pending permanent design changes. EISENHUT.D O Division of Licensing. 80/12/09 2pp.

--8101190141 Generic safety evaluation re short-term actions to assure continued safe operation of operating BWRs Contingency operation of plants is acceptable pending permanent design mods Criteria for implementing design mods encl. Division of Licensing 80/12/01 212pp. 07183 001

8101210435 Forwards responses to questions on Rule 80.71a. Updating of FSARs & FR notice of final rule. BEP plants must comply w/rule until program is complete. Non-BEP plants must comply within specified time frame EISENHUT.D O. Division of Licensing. 80/12/15 13pp.

8101070466 Responds to util 801126 revised schedule for up position indication sys (acoustic monitors) for facility Shutdown solely to upgrade sys is unnecessary. Unit 2 mod should be completed by 810630. REID, R W Operating Reactors Branch 4 80/12/18. 2pp

810109003 Forwards response to 800507 request re outage dates & length of outages for all ECCS for 790101-800901
DALTROFF, S L Philadelphia Electric Co 81/01/05 26pp
07309 001

8101130314 Forwards info re plant sys & equipment & engineering studies evaluating new design stds. in response to NUREG-0737 requests
DALTROFF, S L Philadelphia Electric Co 81/01/08 53pp.
07452 011.

8101120297 Forwards application to amend Licenses DPR-44 & DPR-56 & NEDC-24229-1. "Peach Bottom Atomic Power Station Units 2 & 3 Single Loop Operation"
BRADLEY, E J Philadelphia Electric Co 81/01/09 1p 07446 060

--8101120304 Application to amend Licenses DPR-44 & DPR-56, permitting single loop operation beyond 24-h, provided specified adjustments are implemented Certificate of Svc & affidavit encl.
BAUER, E O., BRADLEY, E J Philadelphia Electric Co 81/01/09 6pp 07446 061

--8101120308 Proposed changes to Tech Specs to permit single loop operation beyond 24-h
* Philadelphia Electric Co 81/01/09 20pp 07446 067

--8101120309 "Peach Bottom Atomic Power Station Units 2 & 3 Single Loop Operation"
HERIKSON, P H General Electric Co. NEDC-24229-1. 80/05/31 33pp 07446 087

810127028 Submits implemented changes called for by NUREG-0619, "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking." Implementation program includes sys mod, feedwater nozzles, operating procedures, insp & leak testing
GALLAGHER, J W Philadelphia Electric Co 81/01/21 5pp
07540 066

Q Inspection reports, IE Bulletins & correspondence

8101100204 Ack receipt of 801109 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/80-28 & 50-278/80-20
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/11/13 1p 07431 323

--8101100211 Responds to NRC 801016 ltr re violations noted in IE Insp Repts 50-277/80-28 & 50-278/80-20 Corrective actions drywell cleaned & reinspected & reactor startup checklist revised.
App D withheld (ref 10CFR2 790)
DALTROFF, S L Philadelphia Electric Co 80/11/03 3pp.
07431 326.

--8101100218 Forwards IE Insp Repts 50-277/80-28 & 50-278/80-20 on 800801-31 & notice of violation.
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/10/16 3pp 07431 324

--8101100224 Notice of violation from insp on 800801-31
* Region 1, Philadelphia, Office of the Director. 80/10/08 2pp
07431 333

--8101100232 Notice of violation from insp on 800801-31 Details withheld (ref 10CFR2 790).
* Region 1, Philadelphia, Office of the Director 80/10/08 1p
07431 334

--8101100244 IE Insp Repts 50-277/80-28 & 50-278/80-20 on 800801-31 Noncompliance noted failure to follow housekeeping procedures, failure to positively control designated vehicle & late submittal of LERs. Portions withheld (ref 10CFR2 790).
BLOUGH, A R, COWILL, C J, RHODAS, G O Region 1, Philadelphia, Office of the Director. 80/10/08 19pp 07431 335

8101220540 Forwards IE Insp Repts 50-277/80-31 & 50-278/80-23 on 800730, 1002-03 & 06 No noncompliance noted
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/11/21. 2pp 07500 178.

--8101220546 IE Insp Repts 50-277/80-31 & 50-278/80-23 on 800930, 1002-03 & 06 No noncompliance noted. Major areas inspected: QA program implementation including auditing, design & changes/mods.
NAPUZA, G Region 1, Philadelphia, Office of the Director
GREENMAN, E O Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/11/20. 11pp. 07500 180

8101100512 Forwards IE Insp Rept 50-278/80-25 on 801029. No noncompliance noted
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/11/25 2pp 07444 273

--8101100524 IE Insp Rept 50-278/80-25 on 801029 No noncompliance noted
Major areas inspected: motor operated & air operated valves of HPCJ sys re IE Bulletin 79-01B
PAOLINO, R J Region 1, Philadelphia, Office of the Director.
EONETER, S D Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/11/17 3pp 07444 275

8101070423 Forwards Suppl 1 to IE Info Notice 80-29. "Broken Studs of Ferry Turbine Steam Inlet Flange" No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/11/26 1p. 07414 03B.

8101090149 Forwards IE Info Notice 80-43. "Failures of Continuous Water Level Monitor for Scram Discharge Vol at Dresden Unit 2" No response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/05 1p 07377 245

8101100775 Responds to IE Bulletin 80-23. "Failures of Gatevalve Mfg by Valcor Engineering Corp. Valves w/Parts V70903-21-1 or V70900-21-3 are not in use in safety-related functions at facilities"
DALTROFF, S L Philadelphia Electric Co 80/12/10 2pp 07443 3

8101060135 Forwards IE Info Notice 80-45. "Potential Failure of BWR Backup Manual Scram Capability" No response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/17 1p. 07397 331

8101220126 Ack receipt of 801204 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/80-08 & 50-278/80-07
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/12/17 1p 07502 120

--8101220135 Supplements response to Items A & B contained in IE Insp Repts 50-277/80-08 & 50-278/80-07 All site personnel will keep "Special Nuclear Plant Rules" for ready ref to improve compliance
DALTROFF, S L Philadelphia Electric Co 80/12/04 1p
07502 121

--8101220141 Ack receipt of 801119 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/80-08 & 50-278/80-07
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/12/16 1p 07502 122

--8101220149 Responds to NRC 801020 ltr re violations noted in IE Insp Repts 50-277/80-08 & 50-278/80-07 Corrective actions filed damaged seal & reactor work permit area identification mechanisms re located for greater access.
DALTROFF, S L Philadelphia Electric Co 80/12/04 4pp
07502 123

--8101220153 Forwards IE Insp Repts 50-277/80-08 & 50-278/80-07 on 800401-30 & notice of violation Items of Noncompliance A & B are recurring violations
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/10/28 3pp 07502 127

--8101220161 Notice of violation from insp on 800401-30.
* Region 1, Philadelphia, Office of the Director 80/10/27 2p
07502 130

--8101220169 IE Insp Repts 50-277/80-08 & 50-278/80-07 on 800401-30 Noncompliance noted failure to maintain fire retardant seal on electrical cable penetration & failure to follow reactor work permit requirements.
COWILL, C J, BLOUGH, A R Region 1, Philadelphia, Office of the Director. GREENMAN, E O Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/10/27 11pp. 07502 132

8101070069 Forwards Suppl 4 to IE Bulletin 80-17. "Failure of 76 of Control Rods to Fully Insert During Scram at BWR" No written response required.
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/18 1p. 07414 144.

8101130095 Forwards IE Bulletin 80-25. "Operating Problems W/Target Rock Safety-Relief Valves at BWRs" Written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/17 1p 07449 154

8101190867 Adv receipt of 801119 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-277/80-29 & 80-278/80-21
ERUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/12/23 1p 07464 337

--8101190873 Responds to NRC 801030 ltr re violations noted in IE Insp Repts 80-277/80-29 & 80-278/80-21 Corrective actions employee instructed in correct procedure for maintaining secondary containment App B withheld (ref 10CFR2 7901)
DALTROFF, S. L. Philadelphia Electric Co 80/11/19. 3pp 07464 338.

--8101190880 Forwards IE Insp Repts 80-277/80-29 & 80-278/80-21 on 800901-30 & notices of violation App A & B App B withheld (ref 10CFR2 7901)
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/10/30 4pp 07464 341

--8101190897 Notices of violation from Insp on 800901-30 App A App B withheld (ref 10CFR2 7901)
* Region 1, Philadelphia, Office of the Director 80/10/29 2pp 07464 343

--8101190891 IE Insp Repts 80-277/80-29 & 80-278/80-21 on 800901-30 Noncompliance noted failure to maintain secondary containment & failure to follow record procedures Details withheld (ref 10CFR2 7901)
McCABE, E. C. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch BLOUGH, A. R. CONOILL, C. J. Region 1, Philadelphia, Office of the Director 80/10/29 15pp 07464 345

8101140744 Suppls 791217 response to IE Bulletin 79-26, "Baron Loss From DWR Control Blades." Certain blades depleting faster than expected Projections indicate that eight of 185 blades will exceed 34% B-10 depletion prior to Mar 1981 outage
DALTROFF, S. L. Philadelphia Electric Co 80/12/24 2pp 07461 300

8101060785 Addl response to FOIA request for documents re experimental use of DCW NS-1 solvent at Dresden 1 & Peach Bottom Forwards CE rept, "Radiation Level Assessment of Dresden 1 Decontamination Pilot Loop - Final Rept"
FELTON, J. M. Division of Rules and Records 80/12/29 1p.

R. Periodic operating reports & related correspondence

8101210522 Forwards monthly operating repts for Dec 1980
COONEY, M. J. Philadelphia Electric Co. 81/01/09 1p 07490 210.

--8101210528 Monthly operating repts for Dec 1980
ALDEN, W. H. Philadelphia Electric Co 81/01/10 10pp 07490 211

S. Reportable occurrences, LERs & related correspondence

8101280306 LER 80-028/01P-0 on 801203. HPCI declared inoperable because of recurring problems w/HQ-14 valve & valve operator Cause unknown Diagnostics underway to determine cause
ULLRICH, H. T. Philadelphia Electric Co 80/12/04 3pp 07308 001.

8101140519 LER 80-029/03L-0 on 801209. Main steam line radiation monitor C indicated reduced background reading w/trip setpoint greater than Tech Spec Caused by instrument zero drift Monitor recalibr
COONEY, M. J. Philadelphia Electric Co 81/01/08. 1p 07308 001

8101200266 LER 80-030/03L-0 on 801214. Backup nitrogen battle supply to inboard containment isolation valve AQ-3506 found valved out of svc. Pressure regulation adjustment screw missing Cause unknown Backup nitrogen supply restored
COONEY, M. J. Philadelphia Electric Co 81/01/13 1p 07487 014

8101220352 RO 81-031/P on 801113 oil leak of 3-5 gpm discovered on oil supply line to turbine manual/overspeed trip mechanism on HPCI auxiliary oil pump Probably caused by leaking valve or fitting in oil supply line
ULLRICH, H. T. Philadelphia Electric Co 81/01/13 3pp 07309 001

8101220466 LER 81-031/03L-0 on 801218. reactor core isolation cooling inboard steam supply isolation valve did not automatically close Caused by valve closing torque switch on type SM3 Limit torque operator for valve M23-13-15 being open
COONEY, M. J. Philadelphia Electric Co. 81/01/13. 1p. 07505. 204

V. Operator Examinations

8101130314 Forwards info re plant sys & equipment & engineering evaluating new design stds in response to NUREG-0737 requests
DALTROFF, S. L. Philadelphia Electric Co 81/01/08. 53pp

DOCKET 80-280 BERRY POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8101130717 Advises of provisions of 10CFR50 App R, that are applicable to fire protection features of facility. FR notice & summary of staff requirements to resolve open item encl.
EISENHUT, D. O. Division of Licensing 80/11/24 7pp 07454

8101070895 Releases public version of util emergency plan & Commonwealth of VA, Isle of Wight County radiological emergency response plan & York County draft radiological emergency response plan - peacetime
FELTON, J. M. Division of Rules and Records 80/12/01. 1p. 07405 005

--8101070602 Forwards public version of util emergency plan, inc Commonwealth of VA, Isle of Wight County radiological emergency response plan & York County draft radiological emergency response plan - peacetime
BAUM, E. A. Virginia Electric & Power Co 80/06/30 2pp. 07405 006

--8101070607 Public version of emergency plan
* Virginia Electric & Power Co 80/06/16. 200pp 07405 007

--8101070613 Public version of Commonwealth of VA, Isle of Wight County emergency operations plan, Annex V, "Radiological Emergency Response Plan." (Part of util plan)
* Isle of Wight County, VA 79/05/31. 50pp 07405 010.

--8101070622 Public version of Commonwealth of VA, York County emergency operations plan, draft Annex V, Radiological Emergency Response Plan - Peacetime " (Part of util plan)
* York, PA 80/06/30 59pp. 07405 011

8101160599 Forwards Suppl 1 to 790919 fire protection safety evaluation, based on util 801029 & 31 ltrs. Hnds re cable tray covers & fire barriers are not acceptable Review status encl
VAROA, S. A. Operating Reactors Branch 1. 80/12/18 6pp 07490 210.

8101100729 Requests that encl facility emergency planning info publicly available w/o encl.
BOUDER, J. L. Division of Rules and Records. 80/12/31. 1p. 07449 127.

8101140467 Advises that response plan not acceptable in present Supplies, personnel & technical assistance to be provided by State Health Dept in most cases nonexistent.
MOLHEB, M. B. Berry County, VA 80/12/31. 2pp. 07461 277.

8101160493 Releases public version of util emergency plan.
FELTON, J. M. Division of Rules and Records. 81/01/08. 1p. 07466 032

--8101160503 Forwards public version of amended emergency plan facility List of changes & emergency personnel response times encl
BAUM, E. A. Virginia Electric & Power Co. 80/12/31. 4pp. 07466 034.

--8101160511 Public version of amended emergency plan for facility
* Virginia Electric & Power Co. 81/01/02 500pp. 07466 035.

8101270249 Notification of 801119 meeting w/util in Bethesda, MD facility fire protection safe shutdown capability.
NEIGHBOR, D. Operating Reactors Branch 1 81/01/12. 2pp. 07546 017.

8101210618 Approves util 801222 request to be excluded from sub State of NC emergency plan as part of facility emergency plan.
VAROA, S. A. Operating Reactors Branch 1 81/01/13. 2pp 07490 211.

8101290165 Forwards facility emergency planning info to be made publicly available w/o encl.
BOUDER, J. L. Division of Rules and Records 81/01/23 1p 07575 200.

G. Adjudicatory correspondence

B101100363 Forwards revised order for mod of license, correcting refs in 800829 order Hearing date also revised
EISENHUT, D O Division of Licensing 80/09/19 3pp 07442 002

--B101100574 Revised order amending Licenses DPR-37 & DPR-32 info requested by IE Bulletin 79-01B must be submitted to IE by 801101
EISENHUT, D O Division of Licensing 80/09/19 6pp 07442 004

B101130384 Requests extension of license mod hearing request from B10108 to B10216 Hearing may still be requested but until must review environ qualification matter before making final decision re necessity of hearing
CHRISTIAN, J N Hunton & Williams 81/01/07 3pp 07437 020

H. General correspondence

B101050488 Informs that appointment of JI Gatts as senior vice president of power operations, effective 810101, approved on 801219 by VEPCO Board of Directors. Discusses until corporate organization Tech Specs being revised for facilities.
FERGUSON, J H Virginia Electric & Power Co 80/12/31 2pp 07385 268

J. Insurance & indemnity information

B101130357 Forwards Endorsements 2, 5, 4, 4, 24, 9B & 31 to NELIA Policies EB-70, EB-63, EB-2B, EB-27, NB-316, NF-186 & NF-240, respectively
HARRFIELD, K J Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc Div 81/01/09 16pp 07451 333

P. Operating license stage documents & correspondence

B101100563 Forwards revised order for mod of license, correcting refs in 800829 order Hearing date also revised.
EISENHUT, D O Division of Licensing 80/09/19 3pp 07442 002

--B101100574 Revised order amending Licenses DPR-37 & DPR-32 info requested by IE Bulletin 79-01B must be submitted to IE by 801101.
EISENHUT, D O Division of Licensing 80/09/19 6pp 07442 004

B101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under 8FB license amend application adding model Tech Specs to App A should be submitted within 120 days.
EISENHUT, D O Division of Licensing 80/11/20 1p

--B101100271 Revised Pages 3/4 7-22 through 2B, B 3/4 7-9 & 7-6 & 6-17 to 8FB snubber inservice insp requirements
Division of Licensing 80/11/20 10pp

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

B101070553 Notices of preliminary fee review of util B01028 proposed Tech Specs changes. Class IV fee is applicable for Unit 1 NRC is re-evaluating Class III fee re util 800316 application.
DIOGSS, R M License Fee Management Branch 80/12/08 1p 07404 356

B101210445 Forwards responses to questions on Rule 50.71e, "Periodic Updating of FBARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame.
EISENHUT, D O Division of Licensing 80/12/15 13pp

B101130384 Forwards Amends 62 & 62 to Licenses DPR-32 & DPR-37, respectively & notice of issuance & availability
VARQA, S A Operating Reactors Branch 1 80/12/18 3pp 07463 240

--B101150394 Amends 62 & 62 to Licenses DPR-32 & DPR-37, respectively, requiring secondary water chemistry monitoring program to inhibit steam generator tube degradation.
VARQA, S A Operating Reactors Branch 1 80/12/18 4pp 07463 242

--B101150403 Notice of issuance & availability of Amends 62 & 62 to Licenses DPR-32 & DPR-37, respectively
VARQA, S A Operating Reactors Branch 1 80/12/18 2pp 07463 244

B101160562 Forwards safety evaluation on susceptibility of safety-related sys to flooding from failure of non-Category I sys
VARQA, S A Operating Reactors Branch 1 80/12/18 2pp 07471 302

--B101160567 Safety evaluation concluding that added protective measures satisfy guidelines for protection of safety-related sys from flooding due to failure of non-Category I sys
Office of Nuclear Reactor Regulation, Director 80/12/18 2pp 07471 302

--B101160690 "Technical Evaluation of Susceptibility of Safety-Related Sys to Flooding Caused by Failure of Non-Category I Sys for Surry Units 1 & 2"
LATORRE, V R VICTOR, R A Laurence Livermore Laboratory 80/12/31 19pp 07471 304

B101300454 Forwards Amends 63 & 63 to Licenses DPR-32 & DPR-37, respectively & notice of issuance & availability
VARQA, S A Operating Reactors Branch 1 80/12/18 3pp 07583 298

--B101300463 Amends 63 & 63 to Licenses DPR-32 & DPR-37, respectively, adding requirement to follow guard training & qualification plan per 10CFR73.95b within 60 days of Commission approval
VARQA, S A Operating Reactors Branch 1 80/12/18 4pp 07583 296

--B101300473 Notice of issuance & availability of Amends 63 & 63 to Licenses DPR-32 & DPR-37, respectively
VARQA, S A Operating Reactors Branch 1 80/12/18 2pp 07583 298

B101190339 Approves until 801118 request to postpone B10101 install of redundant safety grade reactor coolant sys pressure input to core subcooling monitors Sys will be installed in Unit 1 prior to startup & Unit 2 in May 1981
VARQA, S A Operating Reactors Branch 1 80/12/22 2pp 07476 000

B101190242 Forwards list of TLD station locations near facility & proposed route for exchanging TLDs for NRC direct radiation monitoring network w/o encls.
STOKR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/12/30 2pp 07475 297

B101060308 Forwards response to specified items of NUREG-0737 re shi technical advisor training program & ECCB outage rept of North Anna 1 & 2
SYLVIA, B R Virginia Electric & Power Co 80/12/31 37pp 07396 099

B101190483 Ack receipt of B01208 ltr re license amend application for Check for balance due on Class IV amend to Licenses DPR-32 & DPR-37 submitted
SYLVIA, B R Virginia Electric & Power Co 81/01/09 1p 07475 328

--B101190488 Ack receipt of ltr w/checks to be processed by License Fee Branch
DIOGSS, R M License Fee Management Branch 81/01/15 1p 07475 329

B101200229 Forwards revised VEP-FRD-36, designated VEP-FRD-36A, "Control Rod Reactivity Worth Determination by Rod Swap Technique," per NRC B01107 ltr
THOMAS, W H Virginia Electric & Power Co 81/01/16 2pp 07478 001

--B101200235 "Control Rod Reactivity Worth Determination by Rod Swap Technique"
ROSS, T K, BECK, W C, BOWLING, M L Virginia Electric & Power Co VEP-FRD-36A 80/12/31 61pp 07478 003

B101220354 Forwards response to item III D 3 4 of NUREG-0737. Also forwards "Surry Onsite Toxic Chemical Release Analysis"
SYLVIA, B R Virginia Electric & Power Co 81/01/19 9pp 07500 296

--B101220357 "Surry Onsite Toxic Chemical Release Analysis."
TOTH, K J, JUACH, R J, SCHMIDT, E R NUS Corp NUS-3735 V1 81/01/13 18pp 07500 305

B101300193 Expresses appreciation for B01203 meeting to discuss in-house licensing activities. Physics analysis methodology for reload safety evaluations will be discussed at B10128 meeting
THOMAS, W H Virginia Electric & Power Co 81/01/26 1p 07586 207

U Inspection reports, IE Bulletins & correspondence

B101290301 Forwards IE Insp Repts 50-280/80-36 & 50-281/80-40 on B01020-23 No noncompliance noted
 KENNA, W R Region 2, Atlanta, Safeguards Branch 80/12/12 2pp.
 07575 104

--B101290386 IE Insp Repts 50-280/80-36 & 50-281/80-40 on B01020-23 No noncompliance noted Major areas inspected matl control & accounting
 LEE, T D, MCALPINE, E J Region 2, Atlanta, Safeguards Branch
 80/12/08 3pp 07575 106

B101120120 Revises B01201 completion date for corrective actions for IE Bulletin 80-18 re maint of adequate min flow through centrifugal charging pumps. Surry mode to be completed by B01205 & North Anna by B01203
 SYLVIA, B R Virginia Electric & Power Co 80/12/22 1p
 07446 121

B101120517 Provides estimated schedule for completing masonry wall re-evaluation program required by IE Bulletin 80-11
 Completion dates for Class 1 & II walls are B10315 & 0415, respectively
 SYLVIA, B R Virginia Electric & Power Co. 80/12/26 2pp.
 07447 172

B101160694 Ack receipt of B01217 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/80-39 & 50-281/80-43
 LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 81/01/05 1p 07472 030

--B101160696 Responds to ARC B01125 ltr re violations noted in IE Insp Repts 50-280/80-39 & 50-281/80-43 Corrective actions: maint completed on installed pumps & refueling procedure revised
 SYLVIA, B R Virginia Electric & Power Co 80/12/17 3pp
 07472 031

--B101160699 Forwards IE Insp Repts 50-280/80-39 & 50-281/80-43 on B00902-1003 & notice of violation
 LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/11/25 2pp. 07472 034

--B101160700 Notice of violation from Insp on B00902-1003
 * Region 2, Atlanta, Office of the Director. 80/11/25 1p
 07472 036

--B101160706 IE Insp Repts 50-280/80-39 & 50-281/80-43 on B00902-1003 Noncompliance noted: failure to properly evaluate & document installation of jumper hose & failure to properly seal containment door
 BURKE, D J Region 2, Atlanta, Office of the Director
 KELLER, P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/11/25 10pp 07472 037

B101290396 Forwards response to IE Bulletin 80-24, Prevention of Damage Due to Water Leakage Inside Containment (Oct 17, 1980 Indian Point 2 Event) "No leakage in closed sys at North Anna 1 & 2 Summary of leakage at Surry 1 & 2 encl
 SYLVIA, B R Virginia Electric & Power Co. 81/01/05 9pp
 07575 133

R Periodic operating reports & related correspondence

B101200293 Forwards monthly operating repts for Dec 1980.
 SYLVIA, B R Virginia Electric & Power Co 81/01/14 1p
 07477 180

--B101200297 Monthly operating repts for Dec 1980
 DUNN, S D, CASTELLO, D J Virginia Electric & Power Co 81/01/08 46pp. 07477 181

S Reportable occurrences, LERs & related correspondence

B101050414 Forwards LER 80-072/03L-0
 WILSON, J L Virginia Electric & Power Co 80/12/23 1p.
 07390 118

--B101050423 LER 80-072/03L-0 on B01124, twenty-one improperly sealed fire barrier penetrations in safety-related areas discovered & fire latches not established within 1-h. Caused by erroneous interpretation of requirements
 * Virginia Electric & Power Co 80/12/23 3pp 07390 119

B101090641 Forwards LERs 80-047/03L-0 & 80-073/03L-0
 WILSON, J L Virginia Electric & Power Co 81/01/03 1p.

--B101090682 LER 80-047/03L-0 on B01205, discrepancies discovered in decoupling performance of periodic tests PT-24 SB, 18 4, 17 2 & 17 3 Caused by operations personnel oversight
 Personnel restructured & improved mgt of periodic testing
 WILSON, J L Virginia Electric & Power Co 81/01/05 3pp
 07442 177

--B101090661 LER 80-073/03L-0 on B01205, discrepancies discovered in decoupling performance of periodic tests PT-18 B & 19 1
 Caused by operations personnel oversight Personnel restructured & improved PT mgt sys developed
 * Virginia Electric & Power Co 81/01/05 3pp 07442 180

B101200339 Forwards LERs 80-050/03L-0 & 80-074/03L-0
 WILSON, J L Virginia Electric & Power Co 81/01/15 1p
 07477 234

--B101200343 LER 80-050/03L-0 on B01228, amp reading for circuit 13A injection recirculation to boric acid tank panel B was below acceptance criteria Caused by failure of heat tracing tape due to excessive heat Heat tracing design change initiated.
 WILSON, J L Virginia Electric & Power Co 81/01/15 2pp.
 07477 235

--B101200348 LER 80-074/03L-0 on B01218, power leads to MDV-1067A & discovered to have been reversed Cause undetermined. Power leads returned to normal & valves tested
 * Virginia Electric & Power Co. 81/01/15 3pp 07477 237

B101230605 Forwards LER 80-075/03L-0
 WILSON, J L Virginia Electric & Power Co 81/01/16 1p
 07512 262

--B101230611 LER 80-075/03L-0 on B01223, RM-CC-105 & RM-CC-106 alarm setpoints found to be greater than twice background Caused by decrease in background radiation levels resulting from defueling Alarm setpoints reduced
 * Virginia Electric & Power Co 81/01/16 2pp 07512 263

V Operator Examinations

B101060308 Forwards response to specified items of NUREG-0737 re sh technical advisor training program & ECCB outage rept of North Anna 1 & 2
 SYLVIA, B R Virginia Electric & Power Co 80/12/31 37pp

DOCKET 50-281 SURRY POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP 1010 & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
 EISENHUT, D O, Division of Licensing 80/11/13 2pp

B101130717 Advises of provisions of 10CFR50, App R, that are applicable to fire protection features of facility FR notice & summary of staff requirements to resolve open item encl.
 EISENHUT, D O Division of Licensing. 80/11/24 7pp 07454 045

B101070595 Releases public version of util emergency plan & Commonwealth of VA, Isle of Wight County radiological emergency response plan & York County draft radiological emergency response plan - peacetime
 FELTCH, J H Division of Rules and Records 80/12/01 1p
 07405 005

--B101070602 Forwards public version of util emergency plan, including Commonwealth of VA, Isle of Wight County radiological emergency response plan & York County draft radiological emergency response plan - peacetime
 BALM, E A Virginia Electric & Power Co 80/06/30 2pp
 07405 006

--B101070607 Public version of emergency plan.
 * Virginia Electric & Power Co 80/06/16 200pp. 07405 008

--B101070613 Public version of Commonwealth of VA, Isle of Wight County emergency, operations plan, Annex V, "Radiological Emergency Response Plan." (Part of util plan)
 * Isle of Wight County, VA 79/03/31 50pp. 07405 010

--B101070622 Public version of Commonwealth of VA, York County emergency operations plan, draft Annex U, Radiological Emergency Response Plan - Peacetime " (Part of util plan)
 * York, PA 80/06/30 39pp 07405 011

B101160579 Forwards Suppl 1 to 790919 Fire protection safety evaluation based on util B01029 & 31 ltrs Mods re cable tray covers & fire barriers are not acceptable Review status encl
VAROA.S A Operating Reactors Branch I 80/12/18. 6pp 07471 210

B101100729 Requests that encl facility emergency planning info be made publicly available w/o encl
SOUDEK, J L. Division of Rules and Records 80/12/31 1p
07445 127

B101140467 Advises that response plan not acceptable in present form Supplies, personnel & technical assistance to be provided by State Health Dept in most cases nonexistent
HOLMES, M S Surry County, VA 80/12/31 2pp 07461.277

B101160493 Releases public version of util emergency plan
FELTCH, J M Division of Rules and Records 81/01/08 1p.
07466 032

--B101160503 Forwards public version of amended emergency plan for facility List of changes & emergency personnel response times encl
BAUM, E A Virginia Electric & Power Co 80/12/31 4pp.
07466 034

--B101160511 Public version of amended emergency plan for facility
* Virginia Electric & Power Co. 81/01/02 500pp 07466 038

B101210618 Approves util B01222 request to be excluded from submitting State of NC emergency plan as part of facility emergency plan.
VAROA.S A Operating Reactors Branch I 81/01/13 2pp 07489.238

B101270165 Forwards facility emergency planning info to be made publicly available w/o encl
SOUDEK, J L Division of Rules and Records 81/01/23 1p
07575.200

Q Adjudicatory correspondence

B101100563 Forwards revised order for mod of license, correcting refs in B00829 order Hearing date also revised
EISENHUT, D O Division of Licensing 80/09/19 3pp

--B101100574 Revised order amending Licenses DPR-37 & DPR-32 info requested by IE Bulletin 79-018 must be submitted to IE by B01101
EISENHUT, D O Division of Licensing 80/09/19 6pp

B101130384 Requests extension of license mod hearing request from B10108 to B10216 Hearing may still be requested but util must review environ qualification matter before making final decision re necessity of hearing
CHRISTIAN, J N Hunton & Williams 81/01/07 3pp 07497 020.

H General correspondence

B101090488 Informs that appointment of JI Datts as senior vice president of power operations effective B10101, approved on B01219 by VEPCO Board of Directors. Discusses util corporate organization Tech Specs being revised for facilities.
FERGUSON, J H Virginia Electric & Power Co 80/12/31. 2pp
07383.268

J Insurance & indemnity information

B101130397 Forwards Endorsements 2, 5, 4, 4, 24, 5B & 31 to NELIA Policies EB-70, EB-63, EB-28, EB-27, NS-316, NF-186 & NF-240, respectively
HAIRFIELD, K J Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc Div. 81/01/09. 16pp 07451.333.

P Operating license stage documents & correspondence

B101100363 Forwards revised order for mod of license, correcting refs in B00829 order. Hearing date also revised
EISENHUT, D O Division of Licensing 80/09/19. 3pp. 07442.002.

--B101100574 Revised order amending Licenses DPR-37 & DPR-32 info requested by IE Bulletin 79-018 must be submitted to IE by B01101
EISENHUT, D O Division of Licensing 80/09/19. 6pp. 07442.004

B101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under STS License amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT, D O Division of Licensing 80/11/20 1p

--B101100271 Revised Pages 3/4 7-22 through 28.B 3/4 7-5 & 7-6 & 6-BTS snubber inservice insp requirements
* Division of Licensing 80/11/20 10pp

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

B101070553 Notifies of preliminary fee review of util B01028 proposed Tech Specs changes Class IV fee is applicable for Unit 1 NRC is re-evaluating Class III fee re util B00516 application
DUGGS, R M License Fee Management Branch 80/12/08 1p
07404 356

B101210445 Forwards responses to questions on Rule 50.71e. "Periodic Updating of FSARS" & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame
EISENHUT, D O Division of Licensing 80/12/15 13pp

B101150384 Forwards Amends 62 & 62 to Licenses DPR-32 & DPR-37, respectively & notice of issuance & availability
VAROA.S A Operating Reactors Branch I 80/12/18 3pp 07463

--B101150394 Amends 62 & 62 to Licenses DPR-32 & DPR-37, respectively requiring secondary water chemistry monitoring program to inhibit steam generator tube degradation
VAROA.S A Operating Reactors Branch I 80/12/18 4pp
07463 242

--B101150403 Notice of issuance & availability of Amends 62 & 62 to Licenses DPR-32 & DPR-37, respectively
VAROA.S A Operating Reactors Branch I 80/12/18 2pp
07463 244

B101100562 Forwards safety evaluation on susceptibility of safety-related sys to flooding from failure of non-Category 1 sys
VAROA.S A Operating Reactors Branch I 80/12/18 2pp 07471

--B101160567 Safety evaluation concluding that added protective measures satisfy guidelines for protection of safety-related sys from flooding due to failure of non-Category 1 sys
* Office of Nuclear Reactor Regulation, Director 80/12/18
07471 302

--B101160640 "Technical Evaluation of Susceptibility of Safety-Related Sys to Flooding Caused by Failure of Non-Category 1 Sys for Bury Units 1 & 2"
LATORRE, V R., VICTOR, R A Lawrence Livermore Laboratory 80/12/31 19pp 07471.304

B1011300454 Forwards Amends 63 & 63 to Licenses DPR-32 & DPR-37, respectively & notice of issuance & availability
VAROA.S A Operating Reactors Branch I. 80/12/18 3pp 07583

--B101300463 Amends 63 & 63 to Licenses DPR-32 & DPR-37, respectively adding requirement to follow guard training & qualification plan per 10CFR72.55b within 60 days of Commission approval
VAROA.S A Operating Reactors Branch I 80/12/18 4pp.
07583 296.

--B101300473 Notice of issuance & availability of Amends 63 & 63 to Licenses DPR-32 & DPR-37, respectively
VAROA.S A Operating Reactors Branch I 80/12/18 2pp
07583 298.

B101190359 Approves util B01118 request to postpone B10101 installation of redundant safety grade reactor coolant sys pressure input to core subcooling monitors Sys will be installed in Unit 1 prior to startup & Unit 2 in May 1981
VAROA.S A Operating Reactors Branch I 80/12/22 2pp 07476

B101150242 Forwards list of TLD station locations near facility & proposed route for exchanging TLDs for NRC direct radiation monitoring network w/o encl
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/12/30 2pp 07475.297

Technician 8001501 Training Program & LCCS Outage Rept LT
North Anna 1 & 2
SYLVIA, B R Virginia Electric & Power Co 80/12/31 37pp
07396 099

B101190483 Ack receipt of B01208 ltr re license amend application fee
Check for balance due on Class IV amend to Licenses DFR-32 &
DFR-37 subtitles
SYLVIA, B R Virginia Electric & Power Co. 81/01/09 1p
07475 328

--B101190488 Ack receipt of ltr w/checks to be processed by License Fee
Mgt Branch
DUGES, R M License Fee Management Branch 81/01/15 1p
07475 329

B101200229 Forwards revised VEP-FRD-36, designated VEP-FRD-36A, Control
Rod Reactivity Worth Determination by Rod Swap Technique,"
per NRC 801107 ltr
THOMAS, W H Virginia Electric & Power Co 81/01/16 2pp
07478 001

--B101200235 "Control Rod Reactivity Worth Determination by Rod Swap
Technique"
ROSS, T A, BECK, W C, ROWLING, M L Virginia Electric & Power Co
VEP-FRD-36A 80/12/31 4pp 07478 003

B101220354 Forwards response to Item III D 3 4 of NUREG-0737 Also
forwards Surry Onsite Toxic Chemical Release Analysis."
SYLVIA, B R Virginia Electric & Power Co 81/01/19 9pp
07500 296

--B101220357 "Surry Onsite Toxic Chemical Release Analysis"
TOTH, K J, JUDACH, R J, SCHMIDT, E R NLS Corp NUS-3735 V1
81/01/13 18pp, 07500 305

B101300173 Expresses appreciation for B01203 meeting to discuss
in-house licensing activities Physics analysis methodology
for reload safety evaluations will be discussed at B10128
meeting
THOMAS, W H Virginia Electric & Power Co 81/01/26 1p
07586 207

O Inspection reports, IE Bulletins & correspondence

B101290381 Forwards IE Insp Repts 50-280/80-36 & 50-281/80-40 on
B01020-23 No noncompliance noted
MENNA, W B Region 2, Atlanta, Safeguards Branch, 80/12/12 2pp,
07575 104

--B101290386 IE Insp Repts 50-280/80-36 & 50-281/80-40 on B01020-23. No
noncompliance noted Major areas inspected, mat'l control &
accounting.
LEE, T D, MCALPINE, E J Region 2, Atlanta, Safeguards Branch
80/12/08 3pp 07575 106

B101120120 Revises B01201 completion date for corrective actions for
IE Bulletin 80-18 re maint of adequate min flow through
centrifugal charging pumps Surry mods to be completed by
B01205 & North Anna by B01203
SYLVIA, B R Virginia Electric & Power Co 80/12/22 1p,
07446 121

B101120519 Provides estimated schedule for completing seasonally wall
re-evaluation program required by IE Bulletin 80-11.
Completion dates for Class I & II walls are B10315 & 0415,
respectively.
SYLVIA, B R Virginia Electric & Power Co 80/12/26 2pp
07447 172

B101190357 Responds to IE Bulletin 79-14 re seismic analysis for
safety-related piping sys Support mods installed by B01201
except on 3-inch line in containment bldg. Vendor
verification of valve weights incomplete
SYLVIA, B R Virginia Electric & Power Co 80/12/31 3pp
07474 066

B101160694 Ack receipt of B01217 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-280/80-39 &
50-281/80-43
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 81/01/05 1p, 07472 030

--B101160696 Responds to NRC B01125 ltr re violations noted in IE Insp
Repts 50-280/80-39 & 50-281/80-43 Corrective actions: maint
completed on installed pumps & refueling procedure revised
SYLVIA, B R Virginia Electric & Power Co 80/12/17 3pp
07472 031

B01160694 Ack receipt of B01217 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-280/80-39 &
50-281/80-43
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear
Branch 80/11/25 2pp 07472 034

--B101160700 Notice of violation from insp on B00902-1003
& Region 2, Atlanta, Office of the Director, 80/11/2
07472 036

--B101160706 IE Insp Repts 50-280/80-39 & 50-281/80-43 on
noncompliance noted: failure to properly evaluate & doc
installation of jumper hose & failure to properly seal
containment door
BURKE, D J Region 2, Atlanta, Office of the Director,
KELL009, P J Region 2, Atlanta, Reactor Operations Nu
Branch 80/11/25 10pp 07472 037

B101290396 Forwards response to IE Bulletin 80-24, "Prevent
Damage Due to Water Leakage Inside Containment (Oct 17, 1
Indian Point 2 Event)" No leakage in closed sys at North
Anna 1 & 2 Summary of leakage at Surry 1 & 2 encl.
SYLVIA, B R Virginia Electric & Power Co. 81/01/05 9
07575 133

R Periodic operating reports & related correspondence

B101200295 Forwards monthly operating repts for Dec 1980.
SYLVIA, B R Virginia Electric & Power Co. 81/01/14 1
07477 180

--B101200297 Monthly operating repts for Dec 1980
DUNN, B D, COSTELLO, D J Virginia Electric & Power Co
46pp, 07477 181

S Reportable occurrences, LERs & related correspondence

B101220485 Forwards LER B0-049/03L-0
WILSON, J L Virginia Electric & Power Co. 80/12/31 1
07502 261

--B101220492 LER B0-045/03L-0 on B01207, containment vacuum
found inoperable due to open relay contact. Caused by b
lug on coil lead. Lug was replaced & circuit returned to
normal
WILSON, J L Virginia Electric & Power Co. 80/12/31,
07502 262

B101090474 RD on B01220 at full power, condenser cooling wa
temp exceeded max rate of change per Tech Specs. Cause no
stated Temp decreased when waterbox outlet valves thrott
due to vacuum priming problems
SYLVIA, B R Virginia Electric & Power Co. 81/01/05 1
07442 262

B101090641 Forwards LERs B0-047/03L-0 & B0-073/03L-0.
WILSON, J L Virginia Electric & Power Co. 81/01/05 1
07442 175

--B101090692 LER B0-047/03L-0 on B01205, discrepancies disc
documenting performance of periodic tests PT-24, 5B, 1B,
17 2 & 17 3. Caused by operations personnel oversight.
Personnel retrained & improved mgt of periodic test
WILSON, J L Virginia Electric & Power Co. 81/01/05
07442 177

B101200333 Forwards updated LER B0-003/03L-1 & LER B0-046/
WILSON, J L Virginia Electric & Power Co. 81/01/15 1
07477 229

--B101200335 Updated LER B0-003/03L-1 on B00514, MOV-CW-200
inoperable. Caused by electrical malfunction due to
mechanical repair in progress Redundant water box inlet
valve MOV-CW-2068 was shut
WILSON, J L Virginia Electric & Power Co. 81/01/15,
07477 230

--B101200337 LER B0-045/03L-0 on B01217, breaker feeding MO
open. Caused by coat hung on operating arm of circuit
breaker. Coat removed.
WILSON, J L Virginia Electric & Power Co. 81/01/15,
07477 232

B101200339 Forwards LERs B0-050/03L-0 & B0-074/03L-0.
WILSON, J L Virginia Electric & Power Co. 81/01/15 1
07477 234

injection recirculation to boric acid tank panel B was below acceptance criteria. Caused by failure of heat tracing tape due to excessive heat. Heat tracing design change initiated. WILSON, J. L. Virginia Electric & Power Co. 81/01/15 2pp 07477.235.

V Operator Examinations

B101060308 Forwards response to specified items of NURE0-0737 re shift technical advisor training program & ECCS outage rept of North Anna 1 & 2. SYLVIA, B. R. Virginia Electric & Power Co. 80/12/31. 37pp

DOCKET 90-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B101090287 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR. EISENHUT, D. O. Division of Licensing. 80/11/13 2pp.

B101130124 Advises of provisions of 10CFR50, App R, that are applicable to fire protection features of facility FR notice & summary of staff requirements to resolve open items encl. EISENHUT, D. O. Division of Licensing. 80/11/24 4pp 07449.237.

B101080249 Releases public version of "Evacuation Time Estimates From Areas Near Prairie Island Nuclear Generating Plant." FELTON, J. M. Division of Rules and Records. 80/12/01 1p. 07422.036

--B101080258 Forwards public version of "Evacuation Time Estimates From Areas Near Prairie Island Nuclear Generating Plant." Revision 1. HAYER, L. O. Northern States Power Co. 80/08/25 1p 07422.037

--B101080266 Revision 1 of "Evacuation Time Estimates From Areas Near Prairie Island Nuclear Generating Plant." * Northern States Power Co. 80/08/25 10pp 07422.039

B101060194 Notification of B01112 meeting w/util re draft emergency plan, Trip rept encl. MARTIN, R. E. Operating Reactors Branch 3 80/12/15 2pp 07391.304.

--B101060204 Trip rept of B01113 visit to site re current reviews of draft emergency plans. AXELSON, W. L., PAGLIARO, J. A. Office of Inspection & Enforcement, Office of the Director. 80/12/11 2pp. 07391.306.

B101220176 Forwards Chemical Engineering Branch fire protection safety evaluation for facilities Proposed mods to fire barrier penetration seals, structural member coating & fire dampers are acceptable. Review status encl. CLARK, R. A. Operating Reactors Branch 3 80/12/29. 6pp. 07309.001.

B101300122 Forwards facility emergency planning info for placement in LPDR, W/o B101080283. SQUIDER, J. L. Division of Rules and Records. 81/01/19. 1p. 07583.094.

H General correspondence

B101400336 Responds to B01021 ltr requesting info re facilities. Info requested, except for security, can be inspected at PDR in Minneapolis, MN. IPPOLITO, T. A. Operating Reactors Branch 2 80/11/17. 2pp 07309.001.

B101290659 Responds to B01203 request for info re emergency preparedness near facilities, for response to D Carlson B01101 concerns. FEMA working w/state & local govts to assure that planning & preparedness are completed. DIRCKS, W. J. Office of the Executive Director for Operations. 81/01/02. 1p. 07576.141.

--B101290667 Forwards D Carlson B01101 ltr re emergency planning around facilities. Requests response. PRODMIRE, W. Senate. 80/12/03 3pp. 07576.142

B101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under STS License amend application adding model Tech Specs to App A should be submitted within 120 days. EISENHUT, D. O. Division of Licensing. 80/11/20 1p

--B101100271 Revised Pages 7/4 7-22 through 28.0 3/4 7-5 & 7-6 & STS snubber inservice insp requirements. * Division of Licensing. 80/11/20 10pp

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." EISENHUT, D. O. Division of Licensing. 80/11/26 8pp

B101210444 Forwards responses to questions on Rule 50.71e, "Periodic Updating of FSARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete. Non-SEP plants must comply within specified time frame. EISENHUT, D. O. Division of Licensing. 80/12/15 13pp.

B101120091 Forwards Amends 44 & 38 to Licenses DPR-42 & DPR-60, respectively, safety evaluation & notice of issuance & availability. CLARK, R. Operating Reactors Branch 3 80/12/17 2pp. 07448.037

--B101120056 Amends 44 & 38 to Licenses DPR-42 & DPR-60, respectively, revising common station Tech Specs re current logic for actuation of safety injection & limits for control rods & power distribution. CLARK, R. Operating Reactors Branch 3 80/12/17 25pp. 07448.032.

--B101120099 Safety evaluation supporting Amends 44 & 38 to Licenses DPR-42 & DPR-60, respectively. * Office of Nuclear Reactor Regulation, Director. 80/12/17 07446.017

--B101120062 Notice of issuance & availability of Amends 44 & 38 to Licenses DPR-42 & DPR-60, respectively. CLARK, R. Operating Reactors Branch 3 80/12/17 2pp 07446.033

B101050262 Forwards "Unit 1 Reactor Bldg Integrated Leak Rate Test - Oct 1980." HAYER, L. O. Northern States Power Co. 80/12/22 1p. 07378.250

--B101050267 "Unit 1 Reactor Containment Bldg Integrated Leak Rate Test - Oct 1980." HAUOLAND, P. E. Northern States Power Co. 80/10/31. 32pp. 07378.251

B101050296 Forwards commitments to hardware, procedural & organizational implementation requirements of NURE0-0737 Implementation dependent on equipment availability & firm regulatory position. HAYER, L. O. Northern States Power Co. 80/12/30 36pp 07378.252

B101160445 Forwards supplemental info re B00131 license amend request in response to Auxiliary Sys Branch Questions 1, 3, 4 & 6 & Structural Engineering Branch Questions 1, 2 & 5. HAYER, L. O. Northern States Power Co. 81/01/14 13pp 07472.034

B101200241 Forwards rept of ECCS outages, 1976-80, per NURE0-0737, 11.4.3.17 ECCS outage frequency does not constitute excessive unavailability. No Tech Spec changes are warranted. HAYER, L. O. Northern States Power Co. 81/01/16 2pp. 07486.22

B101270693 Forwards startup physics test rept re Unit 1, Cycle 6. HAYER, L. O. Northern States Power Co. 81/01/22 1p 07345.234

--B101270697 "Prairie Island Startup Physics Test Rept Unit 1 Cycle 6." * Northern States Power Co. 81/01/22 4pp. 07345.235

Q Inspection reports, IE Bulletins & correspondence

B101050266 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No response required. KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/10/2pp. 07389.168

B101100796 Forwards IE Circular 80-23, "Potential Defects in Boiling Water Reactor Emergency Generators." No written response required. KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/10/2pp. 07444.119.

8101060507 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety-Relief Valve Operation to Cause Reactor Depressurization - No written response required. KEPLER, J G Region 3, Chicago, Office of the Director. 80/11/07 2pp. 07401 116

8101060367 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1 " No response required KEPLER, J G Region 3, Chicago, Office of the Director 80/11/10 2pp. 07391:067

8101050565 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Steam Discharge Vn] at Dresden Unit 2 " No response required KEPLER, J G Region 3, Chicago, Office of the Director 80/12/05. 2pp. 07390 337

8101070212 Responds to IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches " Technical problem has prevented repairing of indicating lights for switches to show total circuit continuity GILBERTS, D E Northern States Power Co 80/12/11 1p 07415 244

8101070082 Forwards IE Info Notice 80-44, "Activation of ECCS in Recirculation Mode While in Hot Shutdown " No written response required KEPLER, J G Region 3, Chicago, Office of the Director 80/12/16 1p 07415 044

8101290567 Forwards IE Insp Repts 50-282/80-18 & 50-306/80-18 on 801119-20 No noncompliance noted KEISERMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/12/18 2pp. 07571 331

--8101250573 IE Insp Repts 50-282/80-18 & 50-306/80-18 on 801119-20 No noncompliance noted Major areas inspected control rod drive & position indicator checks, core distribution limits & reactor shutdown margin determination CHVLER, H C, ROBINSON, D L, BREITER, J F Region 3, Chicago, Office of the Director 80/12/11 3pp. 07571:303

8101305276 Forwards IE Insp Repts 50-282/80-19 & 50-306/80-19 on 801001-1130 & notice of deviation KEISERMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/12/19 2pp. 07565 229.

--8101300294 Notice of deviation from insp on 801001-1130 * Region 3, Chicago, Office of the Director. 80/12/19 1p 07565 231

--8101300308 IE Insp Repts 50-282/80-19 & 50-306/80-19 on 801001-1130 Noncompliance noted change to Ispose initial conditions on maint procedures per IE Bulletin 80-12 not incorporated as committed FEIERABEND, C, BURCHES, B L, LITTLE, H S Region 3, Chicago, Office of the Director. 80/12/17 12pp. 07565 232

8101160586 Ack receipt of 801210 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-282/80-17 & 50-306/80-17 HIND, J A Region 3, Chicago, Safeguards Branch 80/12/22 1p 07470 360.

--8101160392 Responds to NRC 801118 ltr re violations noted in IE Insp Repts 50-282/80-17 & 50-306/80-17 Corrective actions withheld (ref 10CFR2 790) GILBERTS, D E Northern States Power Co 80/12/10 1p 07470 361

8101200145 Responds to IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (801017 Indian Point 2 Event) " Procedures for detecting leakage are part of post-accident monitoring instrument monthly check GILBERTS, D E Northern States Power Co 81/01/05. 8pp. 07486 194

8101220398 Advises that util will be unable to test schedule to implement mods re IE Bulletin 80-11, "Masonry Wall Design" by 810115 Full implementation of mods scheduled for completion by 810331 GILBERTS, D E Northern States Power Co. 81/01/08 2pp. 07500 241

8101290742 Forwards Parameter, Inc Rept IE-121, "Metallurgical Analysis, W/Attachment A Stress Analysis of Failed Steam Generator Support Bolts from Prairie Island, Unit 1 " JORDAN, E L Division of Resident & Regional Reactor Inspection 81/01/23 1p 07574 254.

--8101290746 "Metallurgical Analysis, W/Attachment A, Stress Failed Steam Generator Support Bolts from Prairie Island, Unit 1 " FDLEY, W J Parameter, Inc PROFT, T L Technimet Corp. NRC-05-80-251 IE-121 80/12/08. 3pp. 07574 255

--8101290747 "Analysis of Failed Steam Generator Support Northern States Power Co, Prairie Island Nuclear Generating Plant, Unit 1 " Attachment A to Parameter, Inc Rept IE-121 encl PROFT, T L Technimet Corp. NRC-05-80-251 78463 47pp. 07574 258

R Periodic operating reports & related correspondence

8101120294 Forwards monthly operating repts for Dec 1980. HAYER, L D Northern States Power Co 81/01/09 1p.

--8101120297 Monthly operating repts for Dec 1980 HUNSTAD, A A Northern States Power Co. 81/01/02. 8 07442 347

S Reportable occurrences, IERs & related correspondence

8101270635 Forwards IER 80-038/031-0 HAYER, L D Northern States Power Co 81/01/21 1p

--8101270658 IER 80-038/031-0 on 801222, during surveillance steam actuation bistable tripped above Tech limit caused by drift of Foxboro Model 63U-CC-04DR-F bistable Bistable reinspected & recalib. HUNSTAD, A A. Northern States Power Co. 81/01/21. 1

8101290742 Forwards Parameter, Inc Rept IE-121, "Metallurgical W/Attachment A Stress Analysis of Failed Steam Generator Support Bolts from Prairie Island, Unit 1 " JORDAN, E L Division of Resident & Regional Reactor Inspection 81/01/23 1p 07574 254

--8101290746 "Metallurgical Analysis, W/Attachment A, Stress Failed Steam Generator Support Bolts from Prairie Island, Unit 1 " FDLEY, W J Parameter, Inc PROFT, T L Technimet Corp. NRC-05-80-251 IE-121 80/12/08 3pp. 07574 255.

--8101290749 "Analysis of Failed Steam Generator Support Northern States Power Co, Prairie Island Nuclear Generating Plant, Unit 1 " Attachment A to Parameter, Inc Rept IE-121 encl. PROFT, T L Technimet Corp. NRC-05-80-251 78463. 47pp. 07574 258

BCKET 30-285 FORT CALHOUN STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8101090397 Ltr to all licensees of operating reactor plants & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FBAR. EISENHUT, D G Division of Licensing. 80/11/13. 2pp.

8101140476 Notifies of withdrawal of util 790115 & 0629 amend license changing fire protection mod implementation schedules CLARK, R A Operating Reactors Branch 3. 80/12/22 2

8101140209 Informs that licensee should conduct emergency within one yr from 800401 or prior to issuance of OL. Schedule of drills should be provided. SEYFRIT, H V Region 4, Dallas, Office of the Director 1p 07461 235.

J Insurance & indemnity information

8101270731 Forwards Endorsement 42 to MAELU Policy MF-65 48.49 & 50 to NELIA Policy NF-207. PETERSON, H E Omaha Public Power District. 81/01/22. 07548:060

P Operating license stage documents & correspondence

8101100254 Ltr to all licensees (except SEP licensees) Revision 1 of inservice surveillance requirements for snubbers under STS License amend application adding me Tech Specs to App A should be submitted within 120 days EISENHUT, D G Division of Licensing. 80/11/20. 1p

1101070240 Forwards IE Insp Rept 50-285/80-20 on 801001-31 No
 noncompliance noted
 MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support
 Branch 8011/18 2pp 07415:174

--B101070244 IE Insp Rept 50-205/BD-20 on 801001-31 No noncompliance noted Major areas inspected operational safety verification & radwaste shipment
KELLEY, D. L. HUNNICUTT, D M Region 4, Dallas, Office of the Director
EO/11/17 7pp 07415 176

8101120072 Forwards add info on IE Bulletin 79-010 re environ
qualification of Class IE equipment in response to 801113
telcon Info details splice integrity where RTV 3145 used for
splice environ barrier
JONES, W C Omaha Public Power District 80/11/19 4pm 07446-037

0101090278 Forwards IE Bulletin DD-24, "Prevention of Damage Due to Water Leakage Inside Containers (October 19, 1980 Indian Point 2 Event)." Written response required
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/11/21
lc. 07429, 246

0101060336 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid." No response required
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/11/24
lp. 07392 066

B101120131 Forwards response to IE Bulletin 80-23 re failures of
solenoid valves mfg by Valcor Engineering Corp Program
initiated to replace Valcor solenoids w/LOCA qualified ASCO
NP-1 series valves Completion anticipated Fall 1981
JONES, U C Omaha Public Power District 80/11/24 bpd 07446 146

8101130694 Informs that visual insp of RCP studs at Calvert Cliffs
has revealed corrosion problem similar to Ft Colhoun
Insp method should be checked
NOVAK, T M Assistant Director For Operating Reactors 80/11/24
lp 07454-038

DI01050124 Requests existing data, summaries & records of inservice insp
tests of containments w/grounded prestressing tendons
DRILL receiving contract to compile & review records of
tendons
EISENHUT, D O Division of Licensing 80/11/25 App.

0101160942 Forward revisions updating 801031 response to IE Bulletin 77-010, re environ qualification of Class IE equipment File has been established for all documentation supporting qualification of safety-related equipment
JONES, W.C. Omaha Public Power District 80/11/25 8pp 07471 285

0101060307 Forwards Suppl 1 to IE Info Notice 80-24. "Broken Studs on
Terry Turbine Steam Inlet Flange " No written response
required
EYFAR1,K.V Region 4, Dallas. Office of the Director. 80/11/26
In 07392 046

8101120048 Responses to IE Bulletin 80-21 re valve yokes supplied by
Malcolm Foundry Co., Inc. Vendors have verbally verified
Malcolm Foundry not used as subcontractor for any valves
JONES, W.C. Omaha Public Power District 80/12/09 App 07446 260

0101050611 Forwarded IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Broom Discharge Vol at Dresden Unit 2 " No response required
SEYFRIT, K W Region 4, Dallas, Office of the Director 80/12/08.
1p 07391:034

0101070009 Forwards IE Info Notice 80-44. "Actuation of ECCS in Recirculation Mode While in Hot Shutdown " No written response "Required
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 80/12/16.
1p. 07415:039

R. Periodic operating reports & related correspondence

8101160485 Forwards monthly operating rpt for Dec 1980
JONES, W. C Omaha Public Power District 81/01/08. 1p 07471 298

--B101160488 Monthly operating rept for Dec 1980.
PATTERSON, T L Omaha Public Power District. 81/01/08 7pp
07471.259

B Reportable occurrences, LERs & related correspondence

B101060761 Forwards LER 80-031/03L-0.
JOHNS, W C Omaha Public Power District 80/12/17 Ip. 07395.030

--B101060767 LER 80-031/03L-0 on 801207, during normal operation, leak developed in weld connecting demineralized water flush line to discharge manifold of charging pump. Caused by probable piping vibration. Crack repaired & pump returned to svc. TESAREK, J. J. Omaha Public Power District 80/12/17 4pp 07393 031.

B101120300 Forwards LER 80-032/03L-0 JONES, W. C. Omaha Public Power District 80/12/19 1p 07447 125

--B101120348 LER 80-032/03L-0 on 801210, primary heat tracing circuits associated w/piping between sulfuric acid pump discharge & MCV-26B found inoperative. Caused by blown power supply fuses. Fuses replaced. MUELLER, B. Omaha Public Power District 80/12/17 4pp 07447 126

B101130358 Forwards LER 80-030/03L-0 JONES, W. C. Omaha Public Power District 80/12/22 1p 07452-078.

--B101130587 LER 80-030/03L-0 801211, diesel generator 1 failed to start on secondary air sys. Caused by vanes of air motor sticking & preventing motors from turning. Vanes cleaned & motors installed. TESAREK, J. J. Omaha Public Power District 80/12/22 4pp 07452 079

B101300513 Forwards LER B1-001/01T-0 JONES, W. C. Omaha Public Power District 81/01/23 1p. 07584 343

--B101300519 LER B1-001/01T-0 on 810114, discovered that FT-236 changing header flow lacks complete info to qualify for harsh radiation svc required by IE Bulletin 79-01B. Caused by incomplete matls list. Transmitter will be replaced. MEHAFFEY, R. F. Omaha Public Power District 81/01/19 4pp. 07584 344

V. Operator Examinations

B101270127 Advises that until 801030 response to NRC 800731 ltr re shift manning is unacceptable. Provision for addl senior reactor operator for each shift must be implemented by 820701. NOVAK, T. H. Assistant Director for Operating Reactors 81/01/08 3pp 07183 001

DOCKET 80-286 INDIAN POINT STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FBAR. EISENHUT, D. O. Division of Licensing 80/11/13 2pp

B101140827 Advises of provisions of 10CFR50, App R, that are applicable to fire protection features of facility. FR notice & summary of staff requirements to resolve open items encl. No open items for facility. W/o encl. EISENHUT, D. O. Division of Licensing 80/11/24 3pp 07461 017.

B101070250 Requests that encl emergency planning info be made publicly available. W/o encl. BOUDER, J. L. Division of Rules and Records 80/12/17 1p. 07414 297

B101070382 Notifies that meeting w/Div of Safeguards re security plan changes & vital area review has been tentatively rescheduled for wk of 810122, in response to NRC 801209 ltr. HARRINGTON, W. F. Power Authority of the State of New York 80/12/29 1p 07414 109.

B101190692 Requests that encl facility emergency planning info be made publicly available. W/o encl. BOUDER, J. L. Division of Rules and Records 81/01/09 1p 07472 320

B101190709 Requests that encl facility emergency planning info be made publicly available. W/o encl. BOUDER, J. L. Division of Rules and Records 81/01/09 1p. 07472 286

B101300456 Requests 30-day extension to respond to NRC 801030 ltr item re vital areas. LAEL representative will be unavailable before 810202. For vital areas conference w/util & NRC Div of Safeguards. HARRINGTON, W. F. Power Authority of the State of New York 81/01/26 1p. 07581 350

Q. Adjudicatory correspondence

B101100660 Forwards revised order for mod of license, c 800829 order. Hearing date also revised. EISENHUT, D. O. Division of Licensing 80/09/19 3pp

--B101100666 Revised order amending License DPR-64. Info Bulletin 79-01B must be submitted to IE by 801101. EISENHUT, D. O. Division of Licensing 80/09/19

B101160246 Order denying request for reconsideration of 800530 order but directing ASLB to conduct discretionary proceeding using full adjudicatory format. Listed issue be addressed Certificate of Svc encl. CHILK, S. J. Office of the Secretary of the Commission 19pp. 07470 228

B101270319 Requests that public hearings re emergency be rescheduled to earlier date. DELBELLO, A. B. Westchester County, NY 81/01/08 2pp

B101270047 Requests hearing on compaction of spent fuel consequences. HOLT, J. J., AUDIN, L., CORREN, D. Public Interest Research York 81/01/19 2pp. 07547 023.

H. General correspondence

B101260199 Supports shutdown of facilities. AUBREY, C. Affiliation Unknown 81/01/09 1p 075

B101270304 Requests info re B10110 constituent ltr req hearings be held for facilities Ltr encl. WILLIAMS, H. A. Senate 81/01/19 1p 07309 001.

B101280272 Supports shutdown of facility. BELIC, J. Affiliation Unknown 81/01/20 1p. 0730

B101280605 Supports revocation of license. ALABO, A., MCOWILLIGUDDY, C., WILLOUGHBY, R. H. Affiliat 81/01/22 1p 07597 285.

P. Operating license stage documents & correspondence

B101100660 Forwards revised order for mod of license, c 800829 order. Hearing date also revised. EISENHUT, D. O. Division of Licensing 80/09/19 3p

--B101100666 Revised order amending License DPR-64. Info Bulletin 79-01B must be submitted to IE by 801101. EISENHUT, D. O. Division of Licensing 80/09/19

B101220243 "Fracture Toughness of Steam Generator & Re Pump Supports," interim technical evaluation rept. STILWELL, T. C., NOELL, P. N., ALLEN, A. G. Franklin Ins Research Center, NRC-03-79-11B. 8101220243 80/07 07503 263

B101050297 Immediate Action Ltr 80-47 confirming 8011 measures util is taking to assure operability of con fan cooler sys & to detect existence of svc water le inside containment. GRIGER, B. H. Region 1, Philadelphia, Office of the Di 80/11/17 2pp 07389 282.

B101280376 FOIA request for documents re Test Force on Operation of Indian Point submitted to NRC 800601-11. HOLT, R. R. New York Univ. 80/11/17 1p. 07558 062

B101100254 Ltr to all licensees (except SEP licensees) Revision 1 of inservice surveillance requirements for snubbers under STB. License amend application adding Tech Specs to App A should be submitted within 120 d. EISENHUT, D. O. Division of Licensing 80/11/20 1p

--B101100271 Revised Pages 3/4 7-22 through 28, 8 3/4 7 STB snubber inservice insp requirements. Division of Licensing 80/11/20 10pp.

B101220466 Ltr to all power reactor licensees & applic summary of 801112 meeting re implementation of guide Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." EISENHUT, D. O. Division of Licensing 80/11/26 8p

Forwards responses to questions on Rule 50.71e. "Periodic of FSAs" & FR notice of final rule SEP plants need ly w/rule until program is complete. Non-SEP plants ply within specified time frame
D. Q. Division of Licensing 80/12/15 13pp.

Forwards "Rept on 1978-1979 Studies to Evaluate Catch ry of 1 D-m2 Epibenthic Sled." Certificate of Bvc

J. D. Consolidated Edison Co. of New York 80/12/19 3pp.
Q

23 "Rept on 1978-79 Studies to Evaluate Catch Efficiency of Epibenthic Sled."
as Instruments, Inc. 80/09/30. 36pp. 07345.072.

Forwards schedule of implementation of outstanding items re on plan requirements in NUREG-0737 per 801231
Until will not propose Tech Specs re requirements
mission provides addl clarification.
P. Power Authority of the State of New York 80/12/30
7309 001.

Forwards application for amend of License DPR-64, changing es App A to conform w/TMI-2 Lessons Learned Category arents & Westinghouse STS Class III fee encl.
P. Power Authority of the State of New York 80/12/30
420 001

16 Application for amend of License DPR-64, changing Tech Speco per TMI Lessons Learned Category A Items & ghouse STS
J. P. Power Authority of the State of New York 80/12/30
07420 004

26 Proposed changes to Tech Specs App A, Sections 3.4 & 6 re TMI e Learned Category A Items & Westinghouse STS Safety tion encl.
er Authority of the State of New York 80/12/30 20pp
005

Forwards "1970 Yr Class Rept for Multiplant Impact Study n River Estuary." Affidavit of svc encl Rept e in Central Files only.
J. D. Consolidated Edison Co. of New York 81/01/16 4pp.
B

Responds to FOIA request for documents re Task Force on Operation of Indian Point submitted to NRC after
Forwards App A documents App B documents withheld
A Exemption 5)
M. Division of Rules and Records 81/01/21 3pp.
9

81 Forwards draft risk analysis for Facilities Probability of core damage is slight, taking into account
ements made or committed to as of early 1980 W/o encl
ILLA.H. Commissioners 80/06/13. 1p

188 Staff requirements memo re 800626 briefing on endations of facility task force Commission took no
during meeting. Task force rept & other info re ty operation will be reviewed further.
B J. Office of the Secretary of the Commission. 80/06/30.

96 Discusses review of task force rept on interim operation of ties Interim operation poses no undue risk to public &
on health & safety. Facilities should be permitted to use operation during proceedings
E. J. M. Commissioners 80/07/02 1p

102 Provides JM Hendrie comments on order re interim operation ility. Specific language of order should be modified.
on on interim operation depends more heavily on task results.
L. D. F. Commissioners 80/06/22. 1p.

2 Forwards proprietary & nonproprietary update to App A of ltr re IP-3 turbine disc properties. Info derived from tional model accounting for thermal & steam bending s. Portions withheld (ref 10CFR2.790). Affidavit encl
P. Power Authority of the State of New York. 81/01/22
07593:346.

596 Nonproprietary version of "Update to App A of Authority 9 Ltr."
Power Authority of the State of New York. 81/01/22. 37pp.
336.

G Inspection reports, IE Bulletins & correspondence

B101300734 Forwards IE Insp Rept 50-286/80-14 on 800903-04 No noncompliance noted
BHTH, Q H. Region 1, Philadelphia. Fuel Facility & Materials Safety Branch 80/11/10 2pp 07583 336

--B101300740 IE Insp Rept 50-286/80-14 on 800903-04 No noncompliance noted Major areas inspected meteorological monitoring sys including primary & backup measurements programs
BORES, R J. Region 1, Philadelphia. Fuel Facility & Materials Safety Branch JACKSON, T J. Region 1, Philadelphia. Office of the Director. 80/10/24 7pp 07583 338

G101070421 Forwards Suppl 1 to IE Info Notice 80-29. "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required
GRIER, B H. Region 1, Philadelphia. Office of the Director 80/11/26 1p 07414 041

G101060811 Forwards IE Info Notice 80-44. "Actuation of ECCS in Recirculation Mode While in Hot Shutdown." No written response required
GRIER, B H. Region 1, Philadelphia. Office of the Director 80/12/16 1p 07397 049

B101290275 Ack receipt of 801230 payment in full for civil penalties imposed by NRC 801208 order
THOMPSON, D. Enforcement & Investigation Staff 81/01/13 1p
07575 113

R Periodic operating reports & related correspondence

B101140316 Forwards "1977 Yr Class Rept for Multiplant Impact Study of Hudson River Estuary." Certificate of Bvc encl
O'TOOLE, J. D. Consolidated Edison Co. of New York 80/12/19 3pp
07459.001

--B101140326 "1977 Yr Class Rept For Multiplant Impact Study of Hudson River Estuary."
s Texas Instruments, Inc. 80/07/31 709pp 07459 004

B101200287 Forwards monthly operating rept for Dec 1980.
ZULLA, B B. Power Authority of the State of New York 81/01/12 1p.
07477.167

--B101200290 Monthly operating rept for Dec 1980
CONNELL, C. Power Authority of the State of New York 81/01/01 4pp. 07477 160

G101230582 Forwards tabulation of daily record of fish collections for Dec 1980
O'TOOLE, J. D. Consolidated Edison Co. of New York 81/01/15 3pp
07510:279.

G Reportable occurrences, IERs & related correspondence

B101270854 Confirms that during routine review of surveillance test program, determined that safety injection logic channel test for Trains A & B had exceeded required due dates. Testing completed immediately
ZULLA, B B. Power Authority of the State of New York 80/12/23 1p.
07549.124

B101090612 Forwards LER 80-017/01T-0
ZULLA, B S. Power Authority of the State of New York. 81/01/09. 1p.
07430.357

--B101090621 LER 80-017/01T-0 on 801222, review determined that safety injection sys logic test for Train A & B exceeded required due dates Caused by poor communication due to clerical error
GUMBLE, F. W. Power Authority of the State of New York. 81/01/03 1p. 07430 358

B101280416 PND-i-81-04 on B10111, during sampling of vol control tank, inadvertent gaseous release occurred resulting in 82.2 Ci noble gas being released over period of 131 minutes. No personnel exposures involved. Media interest expected.
WHYTE, J. HISTER, H. Region 1, Philadelphia. Office of the Director. 81/01/12. 2pp 07557 099

B101270654 RU on B10111, during planned release of noble gas, magnitude of release exceeded expectations. Insignificant amount of I-131 was also released. Caused by leak in connecting sampling sys. Leaking portion isolated & will be repaired
ZULLA, B B. Power Authority of the State of New York. 81/01/21 2pp. 07948:359

... of the State of New York 8/1/01/22 1p
... during 100% operation, svc water
... for cooler unit rotor coolers had no
... monitoring Cause not stated
... return pipe Follow-up study initiated
... of the State of New York 8/1/01/22
...
... matters
...
... information releasing transcript of 001210
... enforcement action
... of the secretary of the Commission 8/01/2/19
...
... script of 001210 closed discussion of Indian
... 1-77 Supporting documentation
... 02pp
...
... shift technical advisor training
... 1972-1977 Item 1 A 1 113
... of the State of New York 8/1/01/09
...
... LEAH STATION UNIT 3
...
... emergency & fire protection plans
...
... of operating reactor plants, CP holders
... radiological emergency response
... within 60 days of
... of PSAR
... of Licensing 8/01/11/13 2pp
... Requests that only facility planning info be made publicly
...
... Rules and Records 8/01/2/31 1p
...
... 8/01/19 1p 07311 124
... public version of Unit emergency plan
... Rules and Records 8/1/01/26 1p
... public version of site-specific radiological
... Part I of State of SC
... emergency response plan Suppl
...
... Duke Power Co 8/1/01/07 1p 07187 001
... public version of site-specific radiological emergency
... Part I of State of SC
... emergency response plan
... 8/01/2/31 33pp 07187 001
...
...
... Mission of guarantee of retrospective
... in response to NRC 801219
... Duke Power Co 8/12/30 1p 07309 001
... Requests that Unit provide approved guarantee of payment of
... for each operating reactor over 100 due
...
... Finance Branch (formerly Arbitrator &
... 8/12/19 1p 07309 001
...
... documents & correspondence
...
... (except CEP licenses) forwarding
... requirements for
... adding model
... 120 days
... of Licensing 8/11/20 1p

... 8/11/20 10pp
8101220466 Ltr to all power reactor licensees & app
... of 80112 meeting re implementation of g
... Unresolved Safety Issue A-12, "Potential for Low
... Toughness & Lamellar Tearing on Component Support
... Division of Licensing 8/01/11/26
8101090175 Forwards Amends 89.84 & 86 to Licensees
... safety evaluation & notice of
... availability
... Operating Reactors Branch 4 8/01/2/10
--8101090184 Amends 87.89 & 86 to Licensees DPR-38,
... respectively, revising Tech Specs to redefine t
... to add general limiting conditions for operat
... Operating Reactors Branch 4 8/01/2/
07426 310
--8101090195 Safety evaluation supporting Amends 89
... DPR-38, DPR-47 & DPR-35, respectively
... Office of Nuclear Reactor Regulation, Direct
07426 321
--8101090205 Notice of issuance & availability of A
... Licensees DPR-38, DPR-47 & DPR-35, respectively
... Operating Reactors Branch 4, 8/01/2/
07426 323
8101210445 Forwards responses to questions on Rule
... "Updating of FBARs" & FR notice of final rule, SEP
... not comply w/rule until program is complete Non-S
... just comply within specified time frame
... Division of Licensing 8/01/2/15
8101200223 Requests amend to license revising Tech
... burned contaminated oil, per 800519 ltr
... Duke Power Co 8/01/2/17 2pp 07
8101050107 Application to amend License DPR-35, chan
... Section 3.5 re operational & axial power shaping
... operational power imbalance limits & adding Tech
... 3.5.2.9 re operation beyond normal design cycle l
... Duke Power Co. 8/01/2/22 2pp. 073
--8101050112 Proposed change to Tech Specs Section
... axial power shaping rods position limits & oper
... imbalance limits & adding Tech Spec 3.5.2.9 re
... beyond normal design cycle length
... Duke Power Co. 8/01/2/22 11pp 07376 324
8101100440 Forwards Amends 90.90 & 87 to Licensees D
... DPR-35, respectively, safety evaluation, EIA & notic
... issuance & availability
... Operating Reactors Branch 4, 8/01/2/24
--8101100448 Amends 90.90 & 87 to Licensees DPR-38, D
... respectively, allowing increase in spent fuel st
... capacity
... Assistant Director for Operating Re
7pp 07444 203
--8101100462 Safety evaluation supporting Amends 90
... DPR-38, DPR-47 & DPR-35, respectively
... Office of Nuclear Reactor Regulation, Direct
07444 213
--8101100471 EIA supporting Amends 90.90 & 87 to L
... DPR-35, respectively
... Office of Nuclear Reactor Regulation, Direct
07444 222
--8101100479 Notice of issuance & availability of A
... Licensees DPR-38, DPR-47 & DPR-35, respectively &
... declaration
... Operating Reactors Branch 4, 8/0
07444 231
8101050094 Application for amend of Licensees DPR-38
... changing Tech Specs, Section 4 to modify certain s
... requirements on annual basis for each refueling o
... fees encl.
... Duke Power Co. 8/01/2/29, 3pp. 073
--8101050101 Proposed changes to Tech Specs, Section
... surveillance requirements from performance on a
... to performance during each refueling outage
... Duke Power Co 8/01/2/29, 18pp. 07376 304

Forwards proposed Tech Specs revision re reactor bldg &
leakage tests, supplementing B01024 submittal
& air lock testing to be submitted upon review

Duke Power Co 80/12/29 1p 07396 318

Proposed Tech Specs 3.6 & 4.4 revision re reactor bldg &
leakage tests, supplementing B01024 submittal
revision reflects App J requirements

Duke Power Co 80/12/29 15pp 07396 319

"Test Requirement Bases & Justification for Reverse
Engineering Testing"

Duke Power Co 80/12/29 8pp 07396 334

Forwards list of TLD station locations near facility &
route for exchanging TLDs for NRC direct radiation
network w/o encs

Region 2, Atlanta, Fuel Facility & Materials Safety
01/12/30 2pp 07407 116

Forwards response to NUREG-0737, post-TMI requirements,
info re shift technical advisor, short-term
procedures review & containment isolation
Central Files version of emergency plan encl

Duke Power Co 81/01/02 70pp 95189 012

"Thermal-Mechanical Rept - Effect on HPI on Vessel Integrity
& Break LOCA Event W/Extended Loss of Feedwater"
Simplified drawings & response to NUREG-0737 encl

Duke Power Co 80/11/30 158pp

Provides alternate methods of nondestructive exams for welds
formed in place of hydrostatic testing, following
NRC B01107 ltr granted licensee relief from
requirements re hydrostatic testing.

Duke Power Co 81/01/07 2pp 07452 111

Advise that response to NRC B01114 ltr requesting addl info
on feedwater sys will be ready for submittal by

Duke Power Co 81/01/12 1p 07471 148

Forwards Reactor Physics Section evaluation of util
ity to reload for Cycle 5. Proposed changes in
load requirements are acceptable

V. Core Performance Branch 81/01/13 2pp 07549 035

Responds to NRC B01001 request for proposed updated Tech
Specs fire protection program Tech Specs currently
under review & will be submitted by B10316

Duke Power Co 81/01/19 1p 07489 278

Advise of delay of response to NRC B01027 ltr re standby
utility Response will be provided no later than

Duke Power Co 81/01/15 1p 07493 252

on reports, IE Bulletins & correspondence

Requests existing data, summaries & records of inservice insp
containments w/grooved prestressing tendons
involving contract to compile & review records of

Division of Licensing 80/11/29 3pp

With receipt of B01126 ltr informing NRC of steps taken to
address violations noted in IE Insp Repts 50-269/80-32,
50-270/80-28 & 50-287/80-25

Region 2, Atlanta, Reactor Operations Nuclear Support
01/12/32 1p 07421 018

With receipt of IE Insp Repts 50-269/80-32, 50-270/80-28 &
50-29 on B00902-30. No proprietary info. Corrective
Tech Specs revised, personnel training reviewed & ltr
to station manager

Duke Power Co 80/11/26 3pp 07421 019

Forwards IE Insp Repts 50-269/80-32, 50-270/80-28 &
50-29 on B00902-30 & notice of violation
C. Region 2, Atlanta, Reactor Operations Nuclear Support
80/11/03 2pp 07421 022

Notice of violation from Insp on B00902-30
in 2, Atlanta, Office of the Director, 80/11/03 1p
4

--B01080177 IE Insp Repts 50-269/80-32, 50-270/80-28 & 50-287/80-25 on
B00902-30 Noncompliance noted failure to comply w/Tech Spec
requirement for processing major procedure change
JAPC.F., BUDERS.W., MYERS.D. Region 2, Atlanta, Office of the
Director 80/11/03 7pp 07421 025

B010150126 Supplis B00718 ltr re rods to reactor bldg spray sys for
facilities Mods to be installed during next available forced
outage of sufficient duration or next refueling outage
PARKER.W.D. Duke Power Co 80/12/12 1p 07462 191

B010160225 Forwards IE Info Notice 80-44, "Actuation of ECCS in
Recirculation Mode While in Hot Shutdown" No written
response required
O'REILLY.J.P. Region 2, Atlanta, Office of the Director 80/12/16
1p

B010160258 Responds to IE Bulletin 80-23 re Valcor Engineering Corp
solenoid valve failure Util will replace all Valcor
solenoid valves w/ASCO solenoid valves as soon as received
PARKER.W.D. Duke Power Co 80/12/29 1p 07470 258

B0101200575 Forwards response to IE Bulletin 80-24 re prevention of
damage due to water leakage inside containment Tech Specs &
station directives ensure reporting of abnormal degradation
of primary containment
PARKER.W.D. Duke Power Co 81/01/06 11pp 07477 240

B0101210213 Forwards supplemental response to IE Bulletin 80-06,
"Engineered Safety Feature (ESF) Reset Controls" Mode
completed on high pressure injection pumps, penetration room
exhaust fans, reactor bldg cooling unit fan & Keowee start
PARKER.W.D. Duke Power Co 81/01/07 13pp 07488 017

B0101900385 Forwards request for relief from ASME Code Section XI
inservice insp requirements re main feedwater sys check
valves Approval requested by B10114
PARKER.W.D. Duke Power Co 81/01/13 5pp 07475 312

K Periodic operating reports & related correspondence

B0101210462 Forwards monthly operating reports for Dec 1980
PARKER.W.D. Duke Power Co 81/01/15 1p 07493 170

--B0101210464 Monthly operating reports for Dec 1980
REAVIN.J.A. Duke Power Co 81/01/15 16pp 07493 171

H Reportable Occurrences, LERs & related correspondence

B0101050351 Forwards LER 80-018/03L-0
PARKER.W.D. Duke Power Co 80/12/29 2pp 07389 295

--B0101050355 LER 80-018/03L-0 on B01129, oil pump on turbine-driven
emergency feedwater pump was found empty Caused by
misalignment of valves for lube oil purifier, allowing oil
from pump to flow into turbine oil storage tank
JONES.J.L. Duke Power Co 80/12/29 1p 07389 297

B0101070657 Forwards LER 80-020/03L-0
PARKER.W.D. Duke Power Co 81/01/02 2pp 07430 280

--B0101090666 LER 80-020/03L-0 on B01204, fire barrier in Unit 3 cable
room floor forced out of pipe sleeve & into personnel
elevator lobby Caused by operator putting foot on
penetration steel plate welded on top of sleeves
JONES.J.L. Duke Power Co 81/01/02 1p 07430 282

B0101210511 Forwards LER 80-017/03L-0
PARKER.W.D. Duke Power Co 81/01/14 2pp 07490 199

--B0101210516 LER 80-017/03L-0 on B01215, fire detector string B declared
inoperable due to spurious alarms Caused by excessive dust
buildup on detectors, resulting in increased sensitivity Fire
detector B31 replaced & string operability verified
JONES.J.L. Duke Power Co 81/01/14 1p 07490 201

B0101270643 Forwards LER 81-001/01T-0
HINES.A.C. Duke Power Co 81/01/22 2pp 07548 348

--B0101270650 LER 81-001/01T on B10106, polar crane found operating over
fuel transfer canal w/reactor vessel head removed Caused
by personnel error Suspended load directed away from fuel
transfer canal
JONES.J.L. Duke Power Co 81/01/22 1p 07548 350

DOCKET 50-224 THREE MILE NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants. CP holders
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B10102 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing 80/11/13 2pp

B101190786 Forwards NUREG-0746, "Emergency Preparedness Evaluation for
TMI-1" & notice of issuance. W/o NUREG-0746
REID, R W Operating Reactors Branch 4 80/12/10 1p 07473.051

--B101190788 Forwards NUREG-0746, "Emergency Preparedness Evaluation for
TMI-1" Certificate of Svc encl W/o NUREG-0746
GRAY, J R Hearing Branch 1 80/12/10 6pp. 07473.052

--B101190791 Notice of availability of NUREG-0746, "Emergency
Preparedness Evaluation for TMI-1"
REID, R W Operating Reactors Branch 4 80/12/10 2pp
07473.058

B101100497 Forwards errata sheet to NUREG-0746 Certificate of Svc encl
REID, R W Operating Reactors Branch 4 80/12/24 3pp 07445.084.

--B101100508 Errata to EMERGENCY PREPAREDNESS EVALUATION FOR TMI-1
* Office of Inspection & Enforcement, Office of the Director
NUREG-0746 EWR 80/12/24 2pp 07445.087

B101060405 Forwards Revision B to security plan Revision B withheld
(ref 10CFR2.790)
MUKILL, H D Metropolitan Edison Co 80/12/30 1p 07390.078

B101150442 Requests that encl facility emergency planning info be made
publicly available W/o encl 8012190094
SCUDER, J L Division of Rules and Records 80/12/31 1p.
07308.001

B101150447 Requests that encl facility emergency planning info be made
publicly available W/o encl 8012200508
SCUDER, J L Division of Rules and Records 80/12/31 1p
07308.001

B101280092 Forwards emergency planning info for placement in LPR
W/o encl
SCUDER, J L Division of Rules and Records 81/01/08 1p.
07557.083

B101140245 Forwards "Review of PA REP Planning Site-Specific to TMI,"
prepared by FEMA NRC will not be issuing safety evaluation
suppl on adequacy of overall emergency preparedness for TMI
at this time
GRAY, J R Hearing Branch 1. 81/01/12 2pp. 07459.004.

--B101140249 Forwards "Review of PA REP Planning Site-Specific to TMI."
JETT, O W Federal Emergency Management Agency 81/01/06 1p.
07458.086

--B101140252 "Review of PA REP Planning Site-Specific to TMI."
* Federal Emergency Management Agency 81/01/08 19pp.
07458.087.

B101290648 Releases public version of util response to revised
emergency plan comments.
FELTON, J M Division of Rules and Records 81/01/27. 1p
07187.001

--B101290652 Forwards public version of response to NRC 800909 comments
on emergency plan, Revision 2
MUKILL, H D Metropolitan Edison Co. 80/12/29 41pp 07187.001

G. Adjudicatory correspondence

B101060705 Summarizes concepts discussed in 790725 meeting re proposal
to have hearings on TMI-1 restart. Statutorily required
hearing must be held if requested on all elements to suspend
or revoke license
BICKHIT, L Office of the General Counsel 79/07/26 10pp.
07401.061

B101070290 Requests response to Items 3, 4, 5, 6, 7 a, 7, b, B & 9 of NRC
800811 request for addl info NRC must have responses to
complete testimony on financial qualifications issue. Delay
could lead to delay in TMI-1 restart hearing completion.
REID, R W Operating Reactors Branch 4. 80/12/17 4pp. 07413.293

B101120101 Notification of contract execution. Mod 1
for ASLB TMI-1 Restart Hearing " Contractor: Cole &
MEMORANDUM, A Administrative Contracts Branch NRC
80/12/19 1p 07446.118

--B101120104 Mod 1, extending monthly rental for Group
B10371, to "Furnishings for ASLB TMI-1 Restart He
* Cole & Co. LEBO, C D Administrative Contract
NRC-10-80-719. 80/12/19 2pp 07446.119

B101050531 Requests permission to make limited appeal
in NRC restart hearing for facility Requests sched
date & time for appearance
LYNQ, T J Affiliation Unknown 80/12/22 1p 0

B101050458 Notice of withdrawal of intervenor Sholly
14.11 & 6(b) Requests ASLB give intervenors right
Contentions B & 9 or that Board adopt Contentions.
Certificate of Svc encl
SHOLLY, S C Affiliation Unknown 80/12/23 7pp.

B101090021 Notifies Commission of withholding of tra
scheduling info from intervenor Environ Coalition
Nuclear Power & requests Commissioners direct ASLB
written schedule for remaining contentions
JOHNSBRUD, J H. Environmental Coalition on Nuclear
2pp 07423.262

--B101090330 Request that encl transcript of 801203
Johnsbrud & C Kefford re absence of Environ Coali
Nuclear Power representative to cross-examine on
1(d) be included in record Certificate of Svc en
JOHNSBRUD, J H. Environmental Coalition on Nuclear
4pp 07428.263.

B101130049 Requests expedited mailing of transcripts
contents to include noted page numbers on proced
ratters & contentions being addressed by testimony
PULLARD, R O. Chesapeake Energy Alliance 80/12/3

B101080396 Advises that UCS is withdrawing Contention
status panel. Contention 7 re instrumentation to de
inadequate core cooling & Contention 13 re Class 9
in TMI-1 restart hearing. Action due to lack of res
WEISS, E R Sheldon, Harmon & Weiss 81/01/05 1

B101090073 Request by M Lewis to join intervenors' J
opposition to licensee motion for reconsideration.
790702 & 8009 Commission orders Certificate of Svc
LEWIS, M Affiliation Unknown 81/01/03 3pp 0

B101120437 Responses opposing Environ Coalition on N
801215 motions to serve NUREG-0534, to grant exten
compare rept w/NUREG-0746, to file discovery reques
disqualify ASLB Certificate of Svc encl
ZAHLER, R E Metropolitan Edison Co. ZAHLER, R E
Potts & Troubridge 81/01/05 8pp 07442.302.

B101130053 Forwards "Review of TMI-1 Control Room Fr
Viewpoint." Certificate of Svc encl.
BAXTER, T A Metropolitan Edison Co. BAXTER, T A
Potts & Troubridge 81/01/05. 6pp 07448.346

B101090236 Response opposing Environ Coalition on Nu
response to ASLB 801125 memorandum & order, 801204.
801211 memorandum & order Opposes extended discove
reconsideration of 800107 filing Certificate of Svc
SWARTZ, L L. Office of the Executive Legal Director
07424.010.

B101120506 Forwards State of PA response to M Dieck
JF Ahearne
ADLER, R W Pennsylvania, State of. 81/01/06 1p

--B101120511 Response opposing General Public Utils
mod of NRC 790702 & 8009 orders. Expediting issue
to restart are within bounds of 790809 order. W/C
of Svc.
SMITH, D C. Pennsylvania, State of 81/01/06.

B101120508 Brief responding to General Public Utils
mod of 790702 & 8009 orders to allow TMI restart p
hearing completion Interposes no objection if Dire
Nuclear Reactor Regulation & Commission agree.
SWANSON, D T. Hearing Branch 1. COBORGUE, J E. Of
Executive Legal Director 81/01/06. 31pp. 07445

B101120537 Response opposing until Dec 1980 request for Commission reconsideration of 790702 & 0809 orders Ltr was late & lacked factual support for assertions Certificate of Svc encl
WEISS, E R Union of Concerned Scientists WEISS, E R. Schiff, Hardin & Waite B1/01/06 8pp 07445 181.

B101130027 Response opposing General Public Util's request to reconsider 790702 & 0809 orders. Endorses B01210 joint response in opposition to licensee motion Approving restart before proceedings "shatters" NRC credibility W/Certificate of Svc * Chesapeake Energy Alliance B1/01/06 3pp. 07448 295

B101130031 Notice of withdrawal of appearance in proceeding ADLER, T A Three Mile Island Alert ADLER, T A Widoft, Reager, Selkowitz & Adler B1/01/06 2pp 07448 298

B101130042 Forwards H Dieckamp B10106 ltr to NRC BLAKE, E L. Metropolitan Edison Co. BLAKE, E L. Shaw, Pittman, Potts & Trowbridge B1/01/06 2pp. 07448 339.

--B101130045 Responds to allegations that Met Ed has not been diligently pursuing legal & procedural remedies & furnishing info to NRC DIECKAMP, H General Public Utilities B1/01/06 4pp 07448 341

B101140941 Memorandum & order directing all parties, particularly TMI Alert, Antinuclear Group Representing York & Aamodt, to appear on B10109 in Harrisburg, PA if interested in hearing mgt issues schedules. BRITH, T H Atomic Safety and Licensing Board Panel B1/01/06 3pp 07458 244.

B101230083 Informs that contention re filters will be heard as early as 1 PM on B10108 BRITH, T H Atomic Safety and Licensing Board Panel B1/01/06 1p 07511 334.

B101160291 Notice of appearance in proceeding. BRADFORD, L Three Mile Island Alert. B1/01/08 2pp. 07470 247

B101160270 Memorandum forwarding Ahearns B01204 memo explaining why intervenors do not receive mailed copies of transcripts BRITH, T H Atomic Safety and Licensing Board Panel B1/01/09 4pp 07462 199.

B101160242 Response opposing Aamodt B01215 motion for assistance in obtaining expert witnesses. No objection to request for extension of time to file Contention 2 testimony Certificate of Svc encl. SHANBSON, D T. Hearing Branch 1. B1/01/12 7pp. 07498 101.

B101160245 Forwards "Review of PA REP Planning Site-Specific to TMI," prepared by FEMA NRC will not be issuing safety evaluation suppl on adequacy of overall emergency preparedness for TMI at this time GRAY, J R Hearing Branch 1 B1/01/12 2pp. 07490 084.

--B101160249 Forwards "Review of PA REP Planning Site-Specific to TMI " JETT, O W Federal Emergency Management Agency. B1/01/06 1p. 07498 086

B101230068 Requests to make limited appearance statement at restart hearing CHARLES, E R Affiliation Unknown. B1/01/12 1p. 07511 332

B101210594 Submits changes to draft response re TMI-1 restart proceeding financial info. General Public Util currently revising financial forecast, incorporating matl changes & reflecting 1981 spending levels, to be available by B10223 HUKILL, H D. Metropolitan Edison Co. B1/01/13 2pp. 07489 268

B101160167 Response to Met Ed B01223 ten interrogatories on reactor vessel water level. CUTCHIN, J M. Hearing Branch 3 B1/01/14 7pp 07470 006

--B101160175 "Rept on Saint Lucie 1 Natural Circulation Cutdown on B00611." Certificate of Svc encl. INDRD, E V. Director's Office B1/01/14 28pp. 07470 013

B101220008 Memorandum on estimated schedule & sequence of hearing for issues in proceeding Inadequate core cooling begins B10120. ASLB Question 11 possibly before B10127 & Class 9 on B10127, followed by cleanup testimony Certificate of Svc encl. BRITH, T H Atomic Safety and Licensing Board Panel. B1/01/15 7pp. 07501 330.

B101230609 Informs that NRC & licensee plan to file testimony re planning & related contentions on B10209 instead of B10119 Svc list encl ZAHLER, R E Shaw, Pittman, Potts & Trowbridge B1/01/19 4pp 07512 265.

B101230635 Statement of concurrence w/Sholly B10113 memorandum re Dieckamp B10106 ltr Requests that ASLB provide written schedule for filing & cross-examination & withdraw policy of ruling & scheduling from bench Certificate of Svc encl JOHNSRUDD, J H Environmental Coalition on Nuclear Power B1/01/19 2pp 07512 281

B101260261 Statement of objection to placing burden of proof on intervenor re UCB Contention 11 on reaction of zirconium cladding to produce hydrogen Hydrogen control limits waived for Sequoyah W/Certificate of Svc WEISS, E R Union of Concerned Scientists B1/01/15 11pp 07523 318

B101280275 Requests to make limited appearance statement at restart hearing HOCKER, H M. Affiliation Unknown B1/01/19 1p 07308 001

B101200018 Memorandum requesting that Commission disregard Dieckamp B10106 response to motion for reconsideration of 790702 & 0809 orders if ltr is considered, intervenors insist on reasonable time for reply Certificate of Svc encl. BHOULLY, B C Affiliation Unknown * Newberry Township TMI Stead Committee * Three Mile Island Alert B1/01/16 6pp 07477

B101210204 Requests extension until B10209 to file written testimony on onsite emergency preparedness Granting extension will not delay hearing. GRAY, J R. Hearing Branch 1 B1/01/16 2pp. 07490 045

B101210192 Forwards license amend & supporting safety evaluation A involving energy absorbing pipe support snubbers does not appear to relate directly to issues W/o encls GRAY, J R Hearing Branch 1 B1/01/19 1p. 07187 001

B101230219 Response in opposition to Antinuclear Group Representing York B10108 motion to adopt Sholly contentions except Contentions B111(b) & B111(i) Emergency plan will be fully litigated Certificate of Svc encl ZAHLER, R E Metropolitan Edison Co ZAHLER, R E Shaw, Pittman, Potts & Trowbridge B1/01/19 7pp 07512 040

B101230225 Response opposing Environ Coalition on Nuclear Power B1 request for Commission investigation of ECHP failure to receive transcripts & scheduling info Alternatively, request should be referred to ASLB Certificate of Svc encl TROWBRIDGE, O F Metropolitan Edison Co TROWBRIDGE, O F Shaw, Pittman, Potts & Trowbridge B1/01/19 9pp 07512 047

B101280311 Forwards H Dieckamp B10120 ltr to JF Ahearns, replying to B10106 response to Dieckamp B01201 ltr. Svc list also encl. BAXTER, T A Shaw, Pittman, Potts & Trowbridge B1/01/21 4pp 07557 170

--B101280316 Responds to NRC B10106 reply to Dieckamp B01201 ltr re restart pending completion of restart hearings NRC has departed from Commission orders & imposed addl conditions for restart. DIECKAMP, H General Public Utilities - GPU Service Corp B1/01/20 4pp. 07557 174.

B101290722 Forwards W Wegner testimony re licensee mgt capability technical resources, which apply to Issues 1, 2, 4, 5, 6, 7, 10 & 11 of Commission B00306 CLF-B9-5 order. Licensee response re B00627 spill & Certificate of Svc also encl. BERNSTEIN, D L Shaw, Pittman, Potts & Trowbridge. B1/01/26 4 07567 001

--B101290734 Response to ASLB B00812 questions re B00627 10,000 gal spill at TMI-1 Spill caused by operator error. Employees briefed on incident & procedures for transferring inverters revised Spill had no impact on TMI-2 * Metropolitan Edison Co B1/01/26 10pp. 07567 047

--B101290737 Drain down & maintain RCS level between 314 ft 10 in & 315 ft 3 inches Incorporates & supersedes but does not alter safety evaluation of BOP-1-B0-29. Supporting documentation encl SHIPMAN, H B., DULRID, R W., TOLLE, Y Metropolitan Edison Co. B0/03/30 57pp 07567 057.

B101290735 Application for Tech Specs Change Request 98, amending License DPR-30. Certificate of Svc & Class III fee encl HUKILL, H D. Metropolitan Edison Co B1/01/26 3pp. 07576 004

--B01290762 Order authorizing organization of General Public Utility Nuclear Corp as wholly owned subsidiary for mgt & operation of nuclear plants.
F11251M40HS.G Securities & Exchange Commission 80/09/15 3pp
07576 027.

--B01290766 Notice of proposal to organize General Public Utility Nuclear Corp as wholly owned subsidiary for mgt & operation of nuclear plants W/related documentation
F11251M40HS.G Securities & Exchange Commission. 80/06/19 85pp
07576 030

--B01290771 Request that NJ Board of Public Utility dismiss for lack of jurisdiction Util & General Public Utility Nuclear Corp proposed operating agreement in alternative agreement should be approved
BRCKAW.R.D Jersey Central Power & Light Co BRCKAW.R.D
Briarcliff NJ 80/04/11 7pp 07576.120

II. General correspondence

B010150050 Urges restart of TMI-1 to reduce consumption of foreign oil
CRIPPEN.D Affiliation Unknown 80/10/21 2pp 07465-233

B01200243 Urges facility restart due to increasing fuel costs.
DELGINARD.N.H Affiliation Unknown 80/10/21 1p 07187-001

B01090162 Comments that facility should be restarted Reactor operation would reduce costs & save oil.
BACHOFER.M.I. Affiliation Unknown 80/10/22 1p 07309 001.

B01090006 Comments that facility should be restarted Society demands energy supply
HESS.P.W Affiliation Unknown 80/10/23 1p 07442 236.

B01090145 Comments that facility should be restarted due to outstanding operation record for five yrs Energy would be less expensive w/reactor operating Coal endangers environ more than radiation.
STANLEY.M.A Affiliation Unknown 80/10/23 3pp 07309 001

B01090122 Urges facility restart Util has attempted to meet safety stds Electric rates would decrease w/reactor in operation
ZIEGLER.L.J Affiliation Unknown 80/10/27 1p. 07442 233

B01090134 Urges facility restart Util has attempted to meet safety stds Electric rates would decrease w/reactor in operation
ZIEGLER.L.J Affiliation Unknown 80/10/27 1p 07442 232

B01090139 Urges facility restart Util has attempted to meet safety stds Electric rates would decrease w/reactor in operation
ZIEGLER.L.J Affiliation Unknown 80/10/27 1p 07442 288.

B01050310 Urges facility restart Util has tried to meet all safety stds & electric rates would decrease w/reactor in operation
ZIEGLER.L.J Affiliation Unknown. 80/10/27 1p 07465 226

B01090160 Urges facility restart Reactor had one of best safety records in nation Nation needs nuclear power to meet energy crisis
KUNDER.B.A Affiliation Unknown 80/11/10 1p 07309 001.

B01090155 Comments that facility should be restarted Reactor had excellent safety record
JANIB.M Affiliation Unknown 80/11/15 2pp 07309 001

B01090151 Expresses opinion that facility should be put in svc Other energy sources are too expensive
KELLER.D.E Affiliation Unknown 80/11/17 1p 07309 001.

B01090181 Comments that facility should be restarted Local, state & natl economy will benefit
DANIELS.M.A., DANIELS.C.M., DANIELS.D.D Affiliation Unknown.
80/11/10 1p 07309 001

B01090089 Endorses facility return to svc Reactor is safe & could contribute to area economy.
DIFFENDERFER Affiliation Unknown 80/11/19 1p. 07309 001

B01200161 Supports TMI-1 restart based on economic & energy requirements.
ISOLA.S.C Affiliation Unknown 80/12/03 1p 07486 147.

B0100155 Responds to 790911 ltr inquiring why restart late 18 to 24 months ASLR hearing began 801019 Forw NJREG-0680 providing NRC evaluation of licensee com w/concerns as of June 1980 W/o encl
EISENHUT.D.G Division of Licensing 80/12/09 1p

--B01010163 Requests reasoning behind estimate of 18 mths decision on TMI-1 restart Util & patrons must costly replacement power
ANDERSON.P.A Affiliation Unknown 79/09/11. 1p

B01200252 Urges immediate facility restart.
PORTER.W.E Affiliation Unknown 80/12/09 1p.

B01200271 Urges immediate facility restart
TREDALE.J.R., TREDALE.A.A Affiliation Unknown. 80/07/17 001.

B01060036 Responds to 800312 ltr re TMI NRC has amended upgrade requirements for emergency planning Public will determine whether TMI-1 should be operated
SNYDER.B.J TMI Program Office 80/12/12 2pp

B01200257 Urges facility restart because of low cost energy
HERTZICK.R.H Affiliation Unknown 80/12/12. 1p

B01200239 Urges facility restart due to energy problem
LASH.L Affiliation Unknown 80/12/16 1p 07187-001

B01200234 Opposes TMI-1 restart because of proximity to TMI-2 & shared storage pool
KLUGER.M Affiliation Unknown 80/12/17. 1p 07187-001

B01200264 Urges restart of TMI-1 only after ASLR decision
GORMLEY.J.E Affiliation Unknown 80/12/17 1p.

B01200189 Supports facility shutdown
DETULLIO.N Affiliation Unknown 80/12/18 1p.

B01200192 Expresses concerns re TMI-1 restart
SCOTT.P Affiliation Unknown. 80/12/18 1p. 07187-001

B01200194 Opposes facility restart prior to completion of process.
Affiliation Unknown 80/12/18 1p. 07187-001

B01200198 Opposes facility restart prior to completion of process
ROTH.T Affiliation Unknown. 80/12/18. 1p 07187-001

B01200199 Opposes facility restart prior to completion of process
MORR.B Affiliation Unknown 80/12/18. 1p. 07187-001

B01200202 Opposes facility restart
MAGDA.M.S Affiliation Unknown 80/12/18 1p. 07187-001

B01200205 Opposes facility restart
EAEH.S Affiliation Unknown 80/12/18. 1p. 07187-001

B01090165 Urges facility restart Dividend checks for 1980 not been received & value of stock has decreased
RECHITTO.A.J Affiliation Unknown. 80/12/19 1p

B01200261 Opposes facility restart
MAYO.A.S Affiliation Unknown. 80/12/22. 1p 07187-001

B01190630 Responds to 801118 ltr to President Carter re restart Restart hearing commenced on 801015 JA Can 801118 ltr to President. 801006 ltr to util & util response encl
GENTON.H.R Office of Nuclear Reactor Regulation. 80/12/23. 8pp 07476 059

B01060524 Recommends restarting TMI-1 because of excellent record & relatively low cost of nuclear energy
SANDERS.M.I Affiliation Unknown 80/12/24. 1p

--B01060530 Comments that TMI-1 should be restarted
EBY.U. Affiliation Unknown 80/12/24. 1p

0533 Comments that TMI-1 should be restarted for good of country.
 J. R. E. Affiliation Unknown 80/12/21 1p

0538 Forwards ltr from citizen re facility restart TMI-1 should
 be shut down permanently & Congress should emphasize to NRC
 action is not committed irrevocably to nuclear power
 LIND. B House of Rep 80/12/18 2pp

0543 Comments that NRC has delayed too long in granting util
 mission to resume operation
 UR. W. U. Affiliation Unknown 80/12/26 1p

0545 Comments that facility should be restarted Nuclear power is
 necessary to provide energy needs
 ESB. J. J. Affiliation Unknown 80/12/29 1p

0551 Comments that facility should be restarted as shutdown of
 it has driven util to brink of bankruptcy
 EY. J. J. Affiliation Unknown 80/12/24 1p

0554 Comments that facility should be restarted pending
 completion of safe operation
 ER. L. E. Affiliation Unknown 80/12/25 1p

0560 Comments that facility should be restarted.
 CK. J. L. Affiliation Unknown 80/12/16 1p

0563 Comments that facility should be restarted. Shutdown is too
 long
 ER. B. Affiliation Unknown 80/12/29 1p

0568 Comments that facility should be restarted. Nation needs
 many alternatives
 BLAK. H. J. Affiliation Unknown 80/12/30 1p

0575 Responds to 801126 ltr re Lebanon Valley Chamber of Commerce
 ltr to meet w/ Commission to discuss facilities
 issues re Unit 1 are in adjudication Chamber
 and that Commission member could meet re Unit 2 cleanup
 E. J. F. Commissioners. 80/12/24 1p 07462-025

0579 Urges facility restart Util needs to operate reactor to
 be in financial condition
 L. J. Affiliation Unknown 80/12/27 1p 07442-234

0580 Urges restart of TMI-1
 W. J. Affiliation Unknown 80/12/29 1p 07465-229

0581 Opposes facility restart prior to completion of hearing
 on accident
 Affiliation Unknown 80/12/29 1p 07187-001

0585 Responds to FOIA request for seven categories of NRC
 documents. Forwards computer printout indicating pertinent
 documents & other documents published 1977-80 & documents in
 response to request
 J. M. Division of Rules and Records 80/12/31 2pp.

0587 Confirms that encl listed documents responding to FOIA
 requests were received by law firm representative
 J. C. Division of Rules and Records 80/12/18 3pp.

0594 Confirms that encl listed documents responding to FOIA
 requests were received by firm representative
 J. C. Division of Rules and Records 80/12/08 7pp
 6:139

0592 Confirms that encl listed documents responding to FOIA
 requests were received by law firm representative
 J. C. Division of Rules and Records. 80/12/02 3pp

0600 Confirms that listed documents responding to FOIA requests
 received by firm representative
 J. C. Division of Rules and Records 80/11/24 21pp
 6:149.

0605 Confirms that listed documents responding to FOIA requests
 received by firm representative
 J. C. Division of Rules and Records 80/11/10 5pp.
 6:170.

0607 Confirms that listed documents responding to FOIA requests
 received by firm representative
 J. C. Division of Rules and Records 80/11/06 2pp
 6:175

--BIO1260081 Confirms that listed documents responding to FOIA requests
 were received by firm representative Computer printout of
 NUREG-0578 published 1977-80 & 'Std Subj Identification
 Numbering Sys (651NS) Basic Code' & Revision 1 encl
 CARR. J. C. Division of Rules and Records 80/10/31 204pp
 07506-177

BIO1060023 Expresses concern re use of nuclear power Proposes solar
 research & development as alternative energy resource
 VOGLER. T. R. Affiliation Unknown 81/01/02 3pp 07309-001

BIO1090099 Comments that facility should be restarted Reactor is
 relatively safe & nuclear power is needed
 CECOR. I. A. Affiliation Unknown 81/01/02 1p 07309-001

BIO1200172 Urges restart of TMI-1 to reduce dependence on foreign util
 LAGEMANN. A. T. Affiliation Unknown 81/01/03 1p 07187-001

BIO1090056 Comments that facility should be restarted to reduce
 electric bills Marked-up page of NUREG-0578 encl
 TIERNEY. R. E. Affiliation Unknown 81/01/03 3pp 07309-001

BIO1090092 Comments that facility should be restarted Reactor is
 victim of discrimination, because other units are allowed to
 operate while mine are in progress. Restarting plant would
 lower electric bills significantly
 MAYHUE. B. Affiliation Unknown 81/01/05 2pp 07309-001

BIO1150318 Urges facility restart TMI shutdown impacts writer as
 taxpayer, ratepayer & stockholder
 RIDGERS. H. C. Affiliation Unknown 81/01/03 1p 07465-227

BIO1150324 Urges restart of TMI-1 & repair & use of TMI-2
 LAGEMANN. A. T. Affiliation Unknown 81/01/03 1p 07465-228

BIO1150333 Urges restart of TMI-1
 OLEN. F. Affiliation Unknown 81/01/05 1p. 07465-230

BIO1150338 Urges restart of TMI-1, to reduce US dependence on foreign
 energy sources
 OLEN. A. M. Affiliation Unknown 81/01/05 1p 07465-231.

BIO1150345 Urges restart of TMI-1 so customers will receive
 uninterrupted energy supplies & investors will receive fair
 return on capital
 MILROY. H. V. Affiliation Unknown 81/01/05 1p 07465-232

BIO1200179 Urges restart of TMI-1 since facility was undamaged by TMI-2
 accident
 RISK. R. B. Affiliation Unknown 81/01/05 1p. 07486-149

BIO1200255 Urges facility restart Certificate of Svc encl
 OKENS. K. Affiliation Unknown 81/01/05 4pp 07476-350

BIO1150353 Opposes immediate restart of TMI-1. Certificate of Svc encl
 BERTZ. K. Affiliation Unknown 81/01/07 5pp 07465-235

BIO1210293 Responds to encl 800916 ltr to President Carter re effect of
 TMI accident on electricity costs & need for federal
 assistance Resumption of TMI-1 operation is subj of hearing.
 White House 800703 ltr to PA Public Util Commission encl
 BENTON. H. R. Office of Nuclear Reactor Regulation, Director
 81/01/07. 6pp. 07187-001

BIO1210288 Responds to encl 800915 ltr to President Carter re effect of
 TMI accident on electricity costs & need for federal
 assistance Resumption of TMI-1 operation is subj of hearing.
 White House 800703 ltr to PA Public Util Commission encl
 BENTON. H. R. Office of Nuclear Reactor Regulation, Director
 81/01/07 4pp 07484-207

BIO1210309 Responds to encl 800926 ltr to President Carter re effect of
 TMI accident on electricity costs & need for federal
 assistance Resumption of TMI-1 is subj of hearing. White
 House 800703 ltr to PA Public Util Commission encl
 BENTON. H. R. Office of Nuclear Reactor Regulation, Director
 81/01/07 3pp 07484-211

BIO1210310 Responds to encl 800929 ltr to President Carter re effect of
 TMI accident on electricity costs & need for federal
 assistance Resumption of TMI-1 is subj of hearing. White
 House 800703 ltr to PA Public Util Commission encl.
 BENTON. H. R. Office of Nuclear Reactor Regulation, Director
 81/01/07 11pp 07484-214

BIO1200165 Comments on decision not to recognize psychological stress
 as restart issue
 HERMAN. A. A. Affiliation Unknown 81/01/08 1p. 07486-150

--B101200303 Urges restart of TMI-1 due to energy problems.
RACALE, H H Affiliation Unknown B1/12/21. 1p. 07477 228.

B101210581 Notifies of change of address for Citizens for Safe Environ
SCUTTHARD, V Citizens for Safe Environment B1/01/08 1p.
07448 361

B101200183 Urges restart of TMI-1 because of cost to consumers Requests
reimbursement for fuel adjustment costs
WESB, J C Affiliation Unknown B1/01/09. 2pp. 07486 151.

B101230073 Supports facility restart
DECECCO, J V Affiliation Unknown B1/01/09 1p. 07511 333

B101230054 Supports facility restart
OSTERMIER, B Affiliation Unknown B1/01/10. 2pp. 07308 001

B101280219 Supports facility restart
SHIPMAN, C M Affiliation Unknown B1/01/10 1p. 07553 053

B101230158 Supports facility restart Certificate of Svc encl.
DIXON, E H Affiliation Unknown B1/01/12 4pp. 07512 011

B101280521 Responds to B01208 ltr to Chairman Ahearne expressing
concern re delay of TMI restart Resumption of operation is
subj of ASLB hearing NRC committed to fair & thorough
decision
DENTON, M R Office of Nuclear Reactor Regulation, Director
01/01/13 1p. 07550 294

--B101280625 Expresses concern re delay of TMI restart
FAULKNER, R Affiliation Unknown B1/01/13 1p. 07550 295

B101280235 Opposes facility restart
MCKER, M M Affiliation Unknown B1/01/15 1p. 07308 001.

B101230079 Supports facility restart
REINSON, E Affiliation Unknown B1/01/19 1p. 07308 001

B101260238 Opposes facility restart Certificate of Svc encl
FERRMAN, A A Affiliation Unknown B1/01/19 4pp. 07308 001

B101280244 Supports facility restart
ELDHOLL, A B Affiliation Unknown B1/01/19 1p. 07308 001.

B101300695 Responds to B01210 ltr urging TMI-1 restart. Facility is shut
down in accordance w/NRC 790702 order requiring hearing
prior to restart Hearing commenced on B01015 & will be
completed in mid-1981.
DENTON, M R Office of Nuclear Reactor Regulation, Director
B1/01/19 2pp. 07584 149.

I Financial information

B01210144 Forwards SEC Form 10-Q Quarterly Financial Rept & supporting
mgt comments in response to NRC 790921.1109 & B00811
requests for info re significant financial developments
affecting utility in restart proceeding
CANDON, V H. General Public Utilities B0/11/26 3pp.

--B01210154 Quarterly Financial Rept Sept 1980 & supporting mgt
comments.
• General Public Utilities B0/11/14 44pp.

B101070290 Requests response to items 3.4, 5.6, 7, a, 7, b, 8 & 9 of NRC
B00811 request for addl info NRC must have responses to
complete testimony on financial qualifications issue. Delay
could lead to delay in TMI-1 restart hearing completion
REID, R W Operating Reactors Branch 4 B0/12/17. 4pp. 07413 293.

B101210594 Submits changes to draft response re TMI-1 restart
proceeding financial info General Public Util currently
revising financial forecast, incorporating mgt changes &
reflecting 1981 spending levels to be available by B10228
HAKILL, H D. Metropolitan Edison Co B1/01/13 2pp. 07489 260

Proprietary info
HOYLE, J C Office of the Secretary of the Commission
3pp. 07585 348

B101300765 Notice of ACRS B01204-06 meeting in Washing
proposed operation of TMI-1, new safety concepts for
nuclear facilities waste storage & disposal Portions
meeting may be closed to protect proprietary info
HOYLE, J C Office of the Secretary of the Commission
7pp. 07584 242

B101070538 Forwards ACRS B01211 status rept re review
REID, R W Operating Reactors Branch 4 B0/12/18

--B101070946 Submits status rept on facility restart A
meeting on B01204-06, restart was discussed w/ARC, u
General Public Util Nuclear Group Restart was dis
B00131-0201 & 1128-29 subcommittee meetings
PLESSET, M G ACRS - Advisory Committee on Reactor
B0/12/11 4pp. 07403 333

P. Operating license stage documents & correspondence

B101100065 Ack receipt of util B01017 ltr providing re
on-ct-through steam generator auxiliary feedwater no
thermal sleeve/collar weld attachment
BRUNNER, E J. Region 1, Philadelphia, Reactor Operat
Support Branch B0/11/05 1p. 07444 308.

B101100234 Ltr to all licensees (except BEP licensees)
Revision 1 of inservice surveillance requirements for
snubbers under STS License amend application adding
Tech Specs to App A should be submitted within 120 d
EISENHUT, D G Division of Licensing B0/11/20. 1p.

--B101100271 Revised Pages 3/4 7-22 through 28, B 3/4 7
STS snubber inservice insp requirements.
• Division of Licensing B0/11/20 10pp

B101220466 Ltr to all power reactor licensees & applic
summary of B01112 meeting re implementation of guida
Unresolved Safety Issue A-12, "Potential for Low Fra
toughness 5 Lamellar tearing on Component Supports."
EISENHUT, D G Division of Licensing B0/11/26 8p.

B101080007 Discusses license amends re fuel handling b
safety feature & addl storage capacity for low activ
solid radwastes Addl info required for resolution of
items
CAMMILL, W P. Effluent Treatment Systems Branch B0
03891 231

B101210445 Forwards responses to questions on Rule 50
Updating of FSARs" & FR notice of final rule. BEP pla
not comply w/rule until program is complete. Non-BEP
must comply within specified time frame.
EISENHUT, D G Division of Licensing B0/12/15. 13

B101050039 Requests to register as user of Model CNS1
radioactive matl shipping cast.
HOVEY, Q K Metropolitan Edison Co B0/12/18 2pp

B101270580 Evaluates NUREG-0680, Suppl 1 re TMI-1 resta
no significance to waste mgt activities
JOHNSON, T C Low Level Waste Licensing Branch, B0/
07309 001

B101130053 Forwards "Review of TMI-1 Control Room From
Viewpoint " Certificate of Svc encl
BAXTER, T A Metropolitan Edison Co. BAXTER, T A. S
Potts & Frowbridge. B1/01/05. 6pp. 07448 346.

--B101130056 "Review of TMI-1 Control Room From Human
• General Public Utilities. B0/12/31. 155pp. 0

B101300203 Responds to 761230 request for Tech Spec ch
Clarification statement to reporting requirements w/
considered as part of 780508 request for overall rev
App B. Request re change of bases does not require am
REID, R W Operating Reactors Branch 4. B1/01/08.

30027 Notification of B10116 meeting w/utl in Bethesda, MD to discuss implementation of NUREG-0737 items Certificate of encl.
JER, H Operating Reactors Branch 4. 81/01/09 4pp 07463 205

30312 Notification of B10116 meeting between NRC & utl to discuss requirements re NUREG-0737. Response to NUREG will be initiated during wk of B10119
L.H.D. Metropolitan Edison Co 81/01/09 1p 07500 197

0379 Forwards utl B01231 ltr to State of PA requesting waiver permit requirements of Dam Safety Encroachment Act
L.H.D. Metropolitan Edison Co 81/01/13 6pp 07409 044

0587 Forwards addl safety analysis justifying Tech Spec Change Request 90, modifying reactor vessel internal vent surveillance to permit Cycle 5 operation w/o ending of surveillance
L.H.D. Metropolitan Edison Co. 81/01/14 6pp 07489 004

0507 Forwards changes & addition to Tech Spec Change Request 34A graphical errors were noted & corrected. List of tables
L.H.D. Metropolitan Edison Co 81/01/19 2pp 07532 063

260509 Revised proposed Change 34A to Tech Specs. Sections 3.4 & 6, radioactive effluent instrumentation
Metropolitan Edison Co 81/01/19 21pp 07532 065

0992 Documents that actions taken per NUREG-0752, control room on review, are in progress & slated for completion prior to start. Identifies exceptions. Discusses plans re amending General Public Util design review suggestions
L.H.D. Metropolitan Edison Co. 81/01/21 3pp 07548 097

3648 Requests extension to B10915 to submit final rept re third on surveillance test of reactor containment bldg
L.H.D. Metropolitan Edison Co 81/01/21 1p 07183 001

3674 Responds to NRC B00815 ltr re automatic opening of spheric dump valves during failure of nonnuclear instrumentation or integrated control sys Administrative - ois & rods will be completed prior to restart
L.H.D. Metropolitan Edison Co 81/01/21 3pp 07543 224

3593 Forwards response to NRC B01125 request re NUREG-0737 comments. Consists of tabulation addressing items ruled for completion. Procurement factors may impede. Uls Addl info re emergency feedwater sys items encl
D.R.C. Metropolitan Edison Co. 81/01/23 26pp 07573 241

3657 Forwards application for amend of License DPR-50 submitted as Tech Spec Change Request 77
L.H.D. Metropolitan Edison Co 81/01/26 1p 07566 333

90662 Application for amend of License DPR-50 submitted as Tech Spec Change Request 77 revising Tech Specs for fire protection. Certificate of svc encl
L.H.D. Metropolitan Edison Co. 81/01/26 3pp 07566 334

90666 Tech Specs 3 1B & 4 1B re fire protection & fire protection
Metropolitan Edison Co. 81/01/26 10pp 07566 337

755 Application for Tech Specs Change Request 90, amending License DPR-50 Certificate of Svc & Class III fee encl.
L.H.D. Metropolitan Edison Co 81/01/26 3pp 07976 006

90759 Proposed Tech Specs Change 90, amending OL & Apps A & B of License DPR-50 to establish General Public Utility Nuclear as sole entity authorized to operate facility.
Metropolitan Edison Co. 81/01/26 18pp 07576 009

90762 Order authorizing organization of General Public Utility Nuclear Corp as wholly owned subsidiary for mgmt & operation of nuclear plants
SECURITIES & EXCHANGE COMMISSION. 80/09/15 3pp 76:027

--B101290771 Request that NJ Board of Public Utilities dismiss for lack of jurisdiction util & General Public Utility Nuclear Corp proposed operating agreement in alternative agreement should be approved
BROKAW, R O Jersey Central Power & Light Co BROKAW, R O
Brokaw, R O 80/04/11 7pp 07576 130

B101300488 Forwards page inadvertently omitted from B101231 submittal in response to NUREG-0737 requirements
* Metropolitan Edison Co 81/01/29 2pp 07587 030

Q Inspection reports, IE Bulletins & correspondence

B101060632 Forwards Phase 2 submittal responding to Item 26 of IE Bulletin B0-11, "Masonry Wall Design"
HUKILL, H D Metropolitan Edison Co 80/11/17 1p 07399 362

--B101060637 "Re-evaluation of Safety-Related Concrete Masonry Walls."
* General Public Utilities - CPU Service Corp 80/11/17 3pp 07400 001

--B101060641 "Criteria for Re-evaluation of Concrete Masonry Walls"
* Computech Engineering Services, Inc 80/10/31 17pp 07400 007

--B101060652 "Justification for Criteria for Re-evaluation of Concrete Masonry Walls"
* Computech Engineering Services, Inc 80/10/31 32pp 07400 025

--B101060657 "Spec Masonry, SP-9714"
* Gilbert/Commonwealth Cos 69/08/08 15pp 07400 082

B101080103 Forwards Revision 1 to util B01031 response to IE Bulletin 79-01B, "Environmental Qualification of Class IE Equipment"
Calculation to find max temp of vessel for 40-gr svc encl.
HUKILL, H D Metropolitan Edison Co. 80/11/17 3pp 07419 245

B101070428 Forwards Suppl 1 to IE info Notice B0-29, "Broken Studs on Terry Turbine Steam Inlet Flange" No written response required
ORIER, B H Region 1, Philadelphia, Office of the Director.
80/11/26 1p 07414 029

B101150140 Forwards Performance Appraisal Branch Mgt Insp Repts 90-219/79-1B, 90-312/80-15 & 90-289/80-21 IE Performance Appraisal Branch mgt evaluation tree w/users guide for chart, list of licensee recipients of rept & sample ltr encl
ORIER, B H Region 1, Philadelphia, Office of the Director.
80/12/02 2pp 07466 028

--B101150195 Performance Appraisal Branch Mgt Insp Rept 90-289/80-21 on B00707-11, 14-18, 27-31 & 0201. Noncompliance noted: licensee mgt controls were poor re nonlicensed training Attachment A withheld (ref IDCFR2 7401)
CODY, A T Region 1, Philadelphia, Office of the Director
HUNTER, D R Region 3, Chicago, Office of the Director JAF, F
Region 2, Atlanta, Office of the Director 80/10/08 119pp 07308 001

B101150084 Ack receipt of 790626, 0713, 0817 & B00602 ltrs on IE Bulletin 79-13 re feedwater pipe cracks. Feedwater pipe cracks unlikely. Augmented insps per IE Bulletin 79-13 & 79-13. Revision 2, may be discontinued. Safety evaluation encl
REID, R W Operating Reactors Branch 4. 80/12/05 1p 07463 209

--B101150094 Ack receipt of 790626, 0713, 0817 & B00602 ltrs re IE Bulletin 79-13 re feedwater pipe cracks. Feedwater pipe cracks unlikely. Augmented insps per IE Bulletin 79-13 & 79-13. Revision 2, may be discontinued. Safety evaluation encl
REID, R W Operating Reactors Branch 4 80/12/03 4pp 07463 210

--B101150103 Forwards safety evaluation re feedwater pipe cracking & relief from augmented insps for TMI-1
GRAY, J R. Hearing Branch 1. 80/12/05 1p 07463 214

--B101150116 Safety evaluation supporting util actions in response to IE Bulletin 79-13, "Cracking in Feedwater Sys Piping"
* Commissioners 80/12/05 2pp 07463 215

810121021 Forwards IE 11-10 Notice 80-44. "Actuation of ECCS in
Regulation Mode While in Hot Shutdown" No written
response required
GRIER, B. H. Region 1 Philadelphia, Office of the Director
81/01/16 1p 07397 041

810141031 Response to IE Bulletin 80-23 "Failures of Solenoid Valves
Mfg. by Valcor Engineering Corp." No sub. valves used in
safety-related circuits
MALL, H. D. Metropolitan Edison Co. 80/12/17 1p 07308 001

810141042 Response to IE Bulletin 80-23 "Valve Notes Supplied by
Malcolm Foundry Co. Inc." No sub. parts used at facility
MALL, H. D. Metropolitan Edison Co. 80/12/17 1p 07457 104

810121055 Confirms 80107 discussion re interpretation of order re
records related to engine qualification of electrical
equipment IE Bulletin 79-018 records specified to be in
place by 810201 must be in central location by 810201
MALL, H. D. Metropolitan Edison Co. 81/01/21 1p 07349 029

H. Periodic operating reports & related correspondence

810121046 Forwards monthly operating rept for Dec 1980
MALL, H. D. Metropolitan Edison Co. 81/01/15 2pp 07493 232

--810121047 Monthly operating rept for Dec 1980
MITCHELL, D. G. Metropolitan Edison Co. 81/01/15 4pp 07493 234

810121057 Forwards Ichthyological Associate "IMI Aquatic Study Monthly
Rept for Dec 1980
TEIT, T. R. General Public Utilities - GPU Service Corp. 81/01/22
1p 07183 001

--810121058 "IMI Aquatic Study Monthly Rept for Dec 1980" Study
performed for Met Ed
NARDACCI, G. A. RAMEY, E. C. Ichthyological Associates, Inc.
81/01/22 24pp 07183 001

S Reportable occurrences, LERs & related correspondence

810105028 Forwards LER 80-019/03L-0
MALL, H. D. Metropolitan Edison Co. 80/12/24 1p 07383 221

--810105026 LER 80-019/03L-0 on 801126.A & B battery room smoke detector
monthly surveillance test not performed Caused by inadequate
implementation of administrative controls Surveillance
modified
MITCHELL, D. G. Metropolitan Edison Co. 80/12/24 2pp 07383 222

810121033 Interim deficiency rept re electrical component cabinets
where frame is welded to embedded steel angles. Initially
reported 810107 Concrete failure & loss of positive
anchorage possible Review will be completed by 810306
BARBER, M. R. Gilbert/Connecticut Co. 81/01/13 3pp 07487 205

8101250524 PNO-TMI-81-03 on 810116 licensee sentenced planned
activities to raise reactor coolant pressure & temp from
0 psig. 121 F to approx 340 psig & max 195 F Activities
expected to last approx one wk
REKITT, W. HAVERKAMP, D. FASANO, J. A. TMI Program Office 81/01/16
2pp 07557 046

8101250507 PNO-TMI-81-03A on 810118 operational & testing activities
temporarily terminated due to small leak in makeup sys
piping discovered on 810117 RCS depressurized to 45 psig &
being held in that condition
HAVERKAMP, D. R. FASANO, J. A. BARRETT, L. H. TMI Program Office
81/01/19 2pp 07557 051

8101270721 Forwards updated LER 78-001/01T-2
MALL, H. D. Metropolitan Edison Co. 81/01/22 1p 07549 071

--8101270726 Updated LER 78-001/01T-2 on 780106 BSW identified transients
which may result in exceeding DNBR on all/Ft safety limits
caused by positive difference between indicated reactor
power subtracted from actual reactor power
MITCHELL, D. G. Metropolitan Edison Co. 81/01/22 2pp 07549 072

8101270523 LER 80-018 has been cancelled
Metropolitan Edison Co. 81/01/23 2pp 07575 247

T. Hearing transcripts on non-antitrust matters

8101050177 Transcript of 801204 restart hearing in Harrisb.
Pg. 7, 333-7, 533
Atomic Safety and Licensing Board Panel 80/12/04
07379 001

8101050308 Transcript of 801214 hearing in Harrisburg, PA
restart Pg. B.060-B.937
Atomic Safety and Licensing Board Panel. 80/12/19
07387 097

8101050034 Forwards NRC testimony in response to Sholly
Antinuclear Group Representing York Contention 3(c) BSW
801201 testimony re control room design
SWARTZ, L. L. Antitrust Division 80/12/22 1p 0737

--8101050042 Transcript of HQ Ramirez & HE Prince testi
Contention 15 & Antinuclear Group Representing York
Contention 3(c) Prof qualifications & Certification
encl
RAMIREZ, R. O. PRINCE, H. E. Human Factors Engineering
80/12/22 12pp 0737b.009

--8101050049 Forwards NUREQ-0752 "Control Room Design Re
THI-1." & notice of availability Certificate of Bv
encl
REID, R. W. Operating Reactors Branch 4. 80/12/22.
0737b 021

--8101050059 Notice of availability of NUREQ-0752, "Cont
Review Rept for THI-1"
ERICKSON, A. B. Operating Reactors Branch 4 80/12/2
0737b 024

--8101050063 CONTROL ROOM DESIGN REVIEW REPT FOR THI-1
Division of Human Factors Safety. NUREQ-0752 E
0737b 025

8101050081 Testimony of JM Christensen responding to 800306
CL1-80-5, Issue 2, Antinuclear Group Representing York
Contention 4, Sholly Contention 14(b), Aamodt Contention
Chesapeake Energy Alliance Contention 13
CHRISTENSEN, J. Metropolitan Edison Co. 80/12/22. 18

--8101050090 Testimony of PR Clark responding to 800306
Issue 7, Sholly Contention 14(d) & Antinuclear Group
Representing York Contention 4, questioning safety re
& operational advice re THI-1
CLARK, P. R. Metropolitan Edison Co. 80/12/22 12pp

--8101050078 Testimony of EF Gardner responding to 800306
Issue 2, Antinuclear Group Representing York Contention
Sholly Contention 14(b), Aamodt Contention 2 & Chesape
Energy Alliance Contention 13
GARDNER, E. F. Metropolitan Edison Co. 80/12/22 18

--8101050105 Testimony of R Wilson responding to 800306
Issue 11, Sholly Contention 14(b) & Antinuclear Group
Representing York Contention 4 re util ability to su
THI-1 operation w/sufficient technical capability.
WILSON, R. Metropolitan Edison Co. 80/12/22. 25pp.

--8101050111 Testimony of RC Arnold responding to 800306
Issue 1, Antinuclear Group Representing York Contention
Sholly Contention 14(a) re administrative structure
safe operation of THI-1.
ARNOLD, R. C. Metropolitan Edison Co. 80/12/22. 41p

--8101050123 Testimony of FL Kelly responding to 800306
Issue 2, Antinuclear Group Representing York Contention
Sholly Contention 14(b) & Aamodt Contention 2 Prof
qualifications & operator written exam encl
KELLY, F. L. Metropolitan Edison Co. 80/12/22. 36pp

--8101050133 Testimony of MD Huxill, RJ Toole, MJ Ross &
responding to 800306 Order CL1-80-5, Issues 2, 4, 5 & 11, Aamodt C
2, Chesapeake Energy Alliance 13 & Antinuclear Group
Representing York Contention 4 & Sholly Contention
14(a), (b) & (c) re organization & technical resources
HUXILL, M. D. TOOLE, R. J. ROSS, M. J. Metropolitan Ed
80/12/22. 36pp. 07381 194.

--8101050150 Testimony of RL Long, RA Knief, BL Newton &
responding to 800306 Order CL1-80-5, Issues 2, 4, 5 & 11, Aamodt C
2, Chesapeake Energy Alliance 13 & Antinuclear Group
Representing York Contention 4 & Sholly Contentions 14(b) & (c)
LONG, R. L. KNIEF, R. A. NEWTON, B. L. Metropolitan Ed
80/12/22. 56pp 07381 210

0567 Transcript of 801222 hearing in Harrisburg, PA re restart
3,938-9,108
Atomic Safety and Licensing Board Panel 80/12/22 170pp
16 030

0563 Transcript of 801223 hearing in Harrisburg, PA re facility
art Pp 9,310-9,313.
Commissioners. 80/12/23 200pp 07387 296

0558 Transcript of 801224 hearing in Harrisburg, PA re facility
art Pp 9,314-9,390
Atomic Safety and Licensing Board Panel 80/12/24 80pp
17 102

0049 Transcript of 810106 hearing in Harrisburg, PA re restart
0,391-9,529
Atomic Safety and Licensing Board Panel 81/01/06 140pp
7 001

0247 Transcript of 810107 restart hearing in Harrisburg, PA
0,520-9,721
Atomic Safety and Licensing Board Panel 81/01/07 193pp
5:026

0249 Transcript of 810108 restart hearing in Harrisburg, PA
0,722-10,004
Atomic Safety and Licensing Board Panel. 81/01/08 204pp
9:001

0483 Transcript of 810114 hearing in Harrisburg, PA re restart.
0,003-10,215
Atomic Safety and Licensing Board Panel 81/01/14 212pp
9:268

0415 Transcript of 810115 hearing in Harrisburg, PA re restart
0,216-10,446
Atomic Safety and Licensing Board Panel 81/01/15 232pp
5:288

0221 Forwards LE Phillips supplementary testimony to testimony
J on 801201 re reactor water level instrumentation.
HIN:J.M Hearing Branch 3 81/01/16 1p 07490.091

010225 Supplementary testimony of LE Phillips to testimony filed on
1201 re UCB Contention 7, Sholly Contention 6(b) &
Inuclear Group Representing York Contention 3(b)
ILLIPS,L.E Core Performance Branch. 81/01/16 5pp
190.052

0359 Forwards R Long, R Keaton & WS Lee testimonies re licensee
inse to TMI-2 accident per tenth issue identified by
ision B00306 order
E L Shew, Pittman, Potts & Troubridge 81/01/19 3pp
1:042

070361 Transcript of RW Keaton & RL Long testimony re mgt response
TMI-2 accident (CLI-80-9, Issue 10).
TOM,R W , LONG,R L Metropolitan Edison Co. 81/01/19 32pp
144 045

070367 Transcript of WS Lee testimony re mgt response to TMI-2
10ent (CLI-80-9, Issue 10)
J.W.B. Metropolitan Edison Co 81/01/19 14pp 07544 077

405 Transcript of 810120 testimony of B Levy in response to UCB
ntion 13 Pp 1-21, Certificate of Bvc encl
B. Atomic Safety and Licensing Board Panel. 81/01/20. 39pp.
:126

447 Transcript of 810120 hearing in Harrisburg, PA re restart.
0,447-10,614
Atomic Safety and Licensing Board Panel. 81/01/20. 169pp
:273

431 Transcript of 810121 hearing in Harrisburg, PA re restart
0,615-10,825
Atomic Safety and Licensing Board Panel. 81/01/21. 212pp
:216

435 Transcript of 810122 hearing in Harrisburg, PA re restart.
0,826-10,936
Atomic Safety and Licensing Board Panel. 81/01/22. 111pp
:258

--8101270729 Transcript of W Wegner testimony re licensee mgt capital
& technical resources, which apply to Issues 1,2,4,5,6,7,10 &
11 of Commission B00306 CLI-80-5 order & intervenor
contentions
WEGNER,W Basic Energy Technology Associates WEGNER,W
Metropolitan Edison Co 81/01/26 41pp 07567 005

--8101290734 Response to ASLB B00012 questions re B00627 10,000 ga
spill at TMI-1 Spill caused by operator error Employees
briefed on incident & procedures for transferring inverters
revised Spill had no impact on TMI-2
e Metropolitan Edison Co 81/01/26 10pp. 07567 047

--8101240737 Brain down & maintain RCS level between 314 ft 10 incl
315 ft 3 inches Incorporates & supersedes but does not
alter safety evaluation of SGP-1-80-29 Supporting
documentation encl.
SHIPMAN,H R , DULRID,R W , TGOLE,Y Metropolitan Edison Co
80/05/30 59pp 07567 057

8101300371 Transcript of 810127 restart hearing in Harrisburg, PA
Pp 10,937-11,095
e Atomic Safety and Licensing Board Panel 81/01/27 160pp
07576 192

8101300385 Transcript of 810128 restart hearing in Harrisburg, PA
Pp 11,096-11,206
e Atomic Safety and Licensing Board Panel 81/01/28 191pp
07577 091

U Congressional/Executive Correspondence

8101090019 Responds to 801222 ltr requesting views re General Publ
Utils 801201 ltr to NRC urging TMI-1 restart prior to end of
hearings Commission has issued order inviting comments on
issue by 810106 & NRC response will be forwarded
KAMMEIER,C Office of Congressional Affairs 81/01/06 1p
07441 101

--8101090027 Requests views re General Public Utils 801201 ltr to
urging TMI-1 restart prior to end of hearings
WILLIAMS,H A Senate 80/12/22 1p. 07441 182

V Operator Examinations

8101030081 Testimony of JM Christensen responding to B00306 Order
CLI-80-5, Issue 2, Antinuclear Group Representing York
Contention 4, Sholly Contention 14(b), Namdt Contention 2 &
Chesapeake Energy Alliance Contention 13
CHRISTENSEN,J Metropolitan Edison Co 80/12/22 16pp 07381

--8101050137 "Rept of TMI-1 Operator Accelerated Retraining Program
Review Committee"
CHRISTENSEN,J , DARDNER,E F , KIMEL,W R Metropolitan Edison
80/06/01 188pp 07381 270

8101290593 Forwards response to NRC B01125 request re NUREG-0737
requirements consists of tabulation addressing items
scheduled for completion Procurement Factors may impact
schedule Addl info re emergency feedwater sys items encl
ARNOLD,R C Metropolitan Edison Co 81/01/23 26pp 07573 24

DOCKET 90-293 PILORIN NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8101070387 Ltr to all licensees of operating reactor plants, CP hol
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
810102 & by applicants as part of FBAR.
EIBENHUT,D O. Division of Licensing 80/11/13 2pp

8101130139 Advises of provisions of 10CFR50, App R, that are applica
to fire protection Features of facility, FR notice & summary
of staff requirements to resolve open items encl.
EIBENHUT,D O Division of Licensing. 80/11/24 4pp. 07308 00

DOCKETED ITEMS

B10137016a Notifies of receipt of encl 10m of Plymouth, MA B01022 ltr
 1. until objecting to exclusion from local emergency planning
 efforts NRC has requested FEMA review of local planning
 efforts for facility.
 IPPOLITD.T A Operating Reactors Branch 2 80/12/08 4pp
 07414 249

B101065096 Forwards fire protection review Proposed mode re
 items 3 1 19.3 2 4 & 3 2 8 acceptable
 IPPOLITD.T A Operating Reactors Branch 2 80/12/15 6pp
 07373 240

G Adjudicatory correspondence

B101300379 Forwards NRC B01013 order modifying license & granting
 extension of exemption from General Design Criterion 50
 Reassessment of containment design for suppression pool
 hydrodynamic loading conditions is required
 IPPOLITD.T A Operating Reactors Branch 2 81/01/13 3pp
 07586 187

--B101300389 Order modifying license & granting extension of exemption
 from General Design Criterion 50 Reassessment of containment
 design for suppression pool hydrodynamic loading conditions
 is required Mode must be installed by B11031
 EISENHUT.D G Division of Licensing 81/01/13 7pp 07586 190

J Insurance & indemnity information

B101060565 Forwards Endorsements 42 & 53 to MAELU Policy MF-58 & ANI
 Policy MF-188, respectively
 FOULSHAM.P A Boston Edison Co 80/11/14 6pp 07399 160

P Operating license stage documents & correspondence

B101100035 Immediate Action Ltr B0-49 confirming B01117 telcon re
 IMI Task Action Plan Category A requirements Lists actions
 until will implement Requests confirmation
 GRIER.B H Region 1, Philadelphia, Office of the Director
 80/11/18 2pp 07444 303

B101100234 Ltr to all licensees (except SEP licensees) forwarding
 Revision 1 of interview surveillance requirements for
 scrubbers under STS License amend application adding model
 Tech Specs to App A should be submitted within 120 days
 EISENHUT.D G Division of Licensing 80/11/20 1p

--B101100271 Revised Pages 3/4 7-22 through 28.B 3/4 7-9 & 7-a & 6-17 to
 STS scrubber interview insp requirements
 • Division of Licensing 80/11/20 10pp

B101220466 Ltr to all power reactor licensees & applicants forwarding
 summary of B01112 meeting re implementation of guidance for
 Unresolved Safety Issue A-12, "Potential for Low Fracture
 Toughness & Lamellar Tearing on Component Supports."
 EISENHUT.D G Division of Licensing 80/11/26 8pp

B101190113 Ltr to all BWR licensees forwarding B01201 generic safety
 evaluation re BWR scram discharge sys Recommends short-term
 actions necessary to assure safe operation of GE BWRs
 pending permanent design changes
 EISENHUT.D G Division of Licensing 80/12/09 2pp 07183 001

--B101190141 Generic safety evaluation re short-term actions required to
 assure continued safe operation of operating BWRs Continued
 operation of plants is acceptable pending permanent design
 mode Criteria for implementing design mode encl
 • Division of Licensing 80/12/01 212pp 07183 001

B101070162 Forwards request for addl info to complete review of util
 B00327 submittal re containment vent & purge valve
 operability Info required re 20-inch butterfly valve
 assembly mods & seismic qualification
 IPPOLITD.T A Operating Reactors Branch 2 80/12/10 4pp
 07414 245

B101210445 Forwards responses to questions on Rule 50.71a, "Periodic
 Updating of FSARs" & FR notice of final rule SEP plants need
 not comply w/rule until program is complete Non-SEP plants
 must comply within specified time frame
 EISENHUT.D G Division of Licensing 80/12/15 13pp

B101070387 Submits supplemental info to B01015 response to NRC 600731
 ltr Commitments re overtime policy found too restrictive
 MORISL.A V Boston Edison Co 80/12/31 2pg 07410 339

B101090045 Responds to NUREG-0737 Provides info re shift technical
 advisor guidance for evaluation & development of procedures
 for transients & accidents, procedures for feedback of
 operating experience & training for mitigating core damage
 MORISL.A V Boston Edison Co 81/01/05 33pp 07441 082

B101190271 Submits notarized statement omitted from B10105 ltr, per
 ICCFR50 54(f)
 MORISL.A V Boston Edison Co 81/01/09 1p 07473 337

B101300379 Forwards NRC B01013 order modifying license & granting
 extension of exemption from General Design Criterion 50
 Reassessment of containment design for suppression pool
 hydrodynamic loading conditions is required.
 IPPOLITD.T A Operating Reactors Branch 2 81/01/13 3pp
 07586 187

--B101300389 Order modifying license & granting extension of exemption
 from General Design Criterion 50 Reassessment of containment
 design for suppression pool hydrodynamic loading conditions
 is required Mode must be installed by B11031
 EISENHUT.D G Division of Licensing 81/01/13 7pp 07586 190

B101270690 Forwards addl info in response to NUREG-0737 requirements
 re containment isolation dependability, ECCB outage rept &
 auto switchover of reactor core isolation cooling.
 MORISL.A V Boston Edison Co 81/01/22 34pp 07943 018

Q Inspection reports, IE Bulletins & correspondence

B101070390 Forwards Suppl 1 to IE Info Notice B0-29, "Broken Studs
 Terry Turbine Steam Inlet Flange." No written response
 required
 GRIER.B H Region 1, Philadelphia, Office of the Director
 80/11/26 1p 07414 095

B101050140 Forwards IE Info Notice B0-43, "Failures of Continuous Wtr
 Level Monitor For Scram Discharge Vol at Dresden Unit 2." No
 response required
 GRIER.B H Region 1, Philadelphia, Office of the Director
 80/12/05 1p 07377 229

B101100927 Responds to IE Bulletin B0-21, "Valve Yokes Supplied by
 Malcolm Foundry Co. Inc." No subj parts in use or planned for
 use at facility
 MORISL.A V Boston Edison Co 80/12/05 1p 07458 353

B101060131 Forwards IE Info Notice B0-43, "Potential Failure of B45
 Backup Manual Scram Capability." No response required
 GRIER.B H Region 1, Philadelphia, Office of the Director
 80/12/17 1p 07397 345

B101070052 Forwards Suppl 4 to IE Bulletin B0-17, "Failure of 76 of 151
 Control Rods to Fully Insert During Scram at BWR." No
 written response required
 GRIER.B H Region 1, Philadelphia, Office of the Director
 80/12/18 1p 07414 023

B101130097 Forwards IE Bulletin B0-25, "Operating Problems W/Target
 Rock Safety-Relief Valves at BWRs." Written response
 required.
 GRIER.B H Region 1, Philadelphia, Office of the Director
 80/12/19 1p 07449 159

R Periodic operating reports & related correspondence

B101210470 Forwards monthly operating rept for Dec 1980
 MACHON.R D Boston Edison Co 81/01/06 1p 07493 238

--B101210473 Monthly operating rept for Dec 1980.
 WHITNEY.O G Boston Edison Co 81/01/06 8pp 07493 239

S Reportable occurrences, LERs & related correspondence

B101080356 Forwards LER B0-092/03L-0.
 MACHON.R D Boston Edison Co 80/12/29 1p 07420 304

--B101080368 LER B0-092/03L-0 on B01129 reactor water cleanup pumps
 tripped & valve M01201-2 could not be remotely operated.
 Caused by burned-out OE control relay Model CR120A04002AA &
 blown MCC panel fuse for M01201-2 control circuits.
 MCLOUHLIN.M T Boston Edison Co 80/12/29 1p 07420 339

LER 80-093/03L-0 on 801213, Walworth Co reactor water cleanup
and isolation valve MD 1201-9 closed late Cause not
d Valve repacked, stem lubricated & closure retimed
DHLIN, M T Boston Edison Co 81/01/12 1p 07474 059

Forwards LER 80-094/04T-0
R D. Boston Edison Co 81/01/14. 1p. 07471:273

LER 80-094/04T-0 on 801229, lab rept indicated excessive
concentration of I-131 in milk sample collected on 801120
by Chinese weapons test Consumption of milk poses no
threat to health of public
DHLIN, M T Boston Edison Co 81/01/13 1p 07471:274

Forwards LER 80-095/03L-0
R D. Boston Edison Co 81/01/19 1p 07531 140

LER 80-095/03L-0 on 801209, fire brigade not summoned when
fire occurred in security bldg mechanical room
by personnel error Personnel instructed of necessity
follow procedures for summoning brigade.
DHLIN, M T Boston Edison Co 81/01/19 1p 07531 141

Examinations

Responds to NUREG-0737 Provides info re shift technical
guidance for evaluation & development of procedures
prevents & accidents, procedures for feedback of
operating experience & training for mitigating core damage.
A V. Boston Edison Co 81/01/05 33pp. 07441 082

295 ZION NUCLEAR POWER STATION, UNIT 1

cy, medical, emergency & fire protection plans

Ltr to all licensees of operating reactor plants, CP holders
Applicants Revised radiological emergency response
must be submitted by licensees within 60 days of
by applicants as part of FBAR
D O Division of Licensing 80/11/13 2pp

Advise of provisions of 10CFR50, App R, that are applicable
protection features of facility FR notice & summary
requirements to resolve open items encl.
D O Division of Licensing 80/11/24. 6pp 07447 174

Advise of typographical error in effective date of 801124
correct date of 801217 to be published in FR in near
D O Division of Licensing 80/11/25. 1p. 07447:180

atory correspondence

Forwards revised order for mod of license, correcting refs in
order Hearing date also revised
D O Division of Licensing 80/09/19 2pp 07444 135

80 Revised order amending Licenses DPR-39 & DPR-48 Info
requesting by IE Bulletin 79-01B must be submitted to IE
101.
D O Division of Licensing. 80/09/19. 6pp. 07444:137.

correspondence

Responds to Nov 1980 ltr to President Carter re containment
cracks at facilities No cracks that will leak
activity exist.
D O Division of Licensing. 81/01/02. 5pp. 07471:153

ance & indemnity information

Forwards guarantee of payment of deferred premiums for 1980
Commonwealth Edison Co 81/01/05. 1p. 07442:073.

Forwards Endorsements 125 & 126, 65 & 66, 93 & 94, & 13 & 14
Policies NF-43, NF-187, NF-201 & NF-253, respectively
Commonwealth Edison Co 81/01/21. 13pp. 07183:001

Forwards Endorsement 4 to Binders EB-1, EB-2, EB-3, EB-29,
EB-42 & EB-43 evidencing secondary financial
Commonwealth Edison Co 81/01/21. App.

P. Operating license stage documents & correspondence

B101100581 "RELAP4/HOD7 Developmental Checkout Zion," code development
checkout rept
DEVOUR, D T L Idaho National Engineering Laboratory FIN A-6052
8101100581 80/05/31 106pp 07445 220

B101100674 Forwards revised order for mod of license, correcting refs in
800829 order Hearing date also revised
EISENHUT, D O Division of Licensing 80/09/19. 2pp 07444 135

--B101100680 Revised order amending Licenses DPR-39 & DPR-48 Info
requesting by IE Bulletin 79-01B must be submitted to IE
by 801101
EISENHUT, D O Division of Licensing 80/09/19 6pp. 07444:137

B101100254 Ltr to all licensees (except SEP licensees) forwarding
Revision 1 of inservice surveillance requirements for
snubbers under STS License amend application adding model
Tech Spec to App A should be submitted within 120 days.
EISENHUT, D O Division of Licensing 80/11/20. 1p

--B101100271 Revised Pages 3/4 7-22 through 28, B 3/4 7-5 & 7-6 & 6-17 to
STS snubber inservice insp requirements
* Division of Licensing 80/11/20 10pp.

B101220466 Ltr to all power reactor licensees & applicants forwarding
summary of 801112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing. 80/11/26 8pp

B101140849 Requests that util propose Tech Spec changes to require 2 1/2
ft of water above reactor vessel flange to assure fuel
assemblies would be covered at all times during fuel
movement
VARGA, S A Operating Reactors Branch 1. 80/12/12 2pp 07461:332

B101210445 Forwards responses to questions on Rule 50.71e, "Periodic
Updating of FSARs" & FR notice of final rule, SEP plants need
not comply w/rule until program is complete Non-SEP plants
must comply within specified time frame
EISENHUT, D O Division of Licensing. 80/12/15 13pp

B101140523 Forwards review of util evaluation of steady state steam
generator operating level for purpose of maximizing dryout
time w/consideration for overfilling. Current operating level
is justified
VARGA, S A Operating Reactors Branch 1. 80/12/18 7pp. 07472:123

B101090715 Responds to B01126 memo re lack of groundwater monitoring
program at facility. Map of station & elevations above sea
level encl Monitoring not required unless hydraulic gradient
or recharge properties are suitable for contamination
DIRCKS, W J. Office of the Executive Director for Operations.
80/12/23 23pp 07430:304.

B101050500 Forwards response to NUREG-0737 No response provided for
Dresden 1 Unit undergoing extensive mod & decontamination
outage Requirements of NUREG-0737 will be addressed prior
to startup of unit scheduled for June 1986
ABEL, J. S. Commonwealth Edison Co 80/12/31. 55pp.

B101070555 "Adequacy of Station Electric Distribution Bys Voltages,
Zion Station, Unit 1," informal rept.
UDY, A C Idaho National Engineering Laboratory FIN A-6256.
B101070555. 80/12/31. 13pp. 07406:059.

B101220631 "Critique of OPS Risk Study for Zion Nuclear Power Plant,"
informal rept
BUSLIR, A J, BARI, R A Brookhaven National Laboratory.
BNL-NUREG-28790 80/12/31 60pp 07499:158

B101300318 Forwards Amends 59 & 56 to Licenses DPR-39 & DPR-48,
respectively & notice of issuance & availability
VARGA, S A Operating Reactors Branch 1 80/12/31 3pp. 07587 011.

--B101300328 Amends 59 & 56 to Licenses DPR-39 & DPR-48 respectively,
allowing reinjection of four fuel assemblies previously
irradiated in both units back into Unit 1 to irradiate high
burnup fuel for lost cycle.
VARGA, S A Operating Reactors Branch 1. 80/12/31. 7pp
07587:014.

--B101300338 Notice of issuance & availability of Amends 59 & 56 to
Licenses DPR-39 & DPR-48, respectively.
VARGA, S A Operating Reactors Branch 1 80/12/31. 2pp.
07587:021.

81010040 Forwards Revision 19 pages to CE-1-A 0A program topical rept. Revisions reflect Summer 1980 addenda to Section III of AHE code 1 recent AEF survey for renewal of ASME in-service certifications
ARCA, J. S. Commonwealth Edison Co. 81/01/02 1p

--81010050 Revision 19 pages to 3A program topical rept
* Commonwealth Edison Co. CE-1-A 1B 81/01/02 37pp

8101005003 Forwards addl info in response to Section 5.1.1 of ASME N-6512 info superseded 801107 submittal. Detailed review of other sections of ASME N-6512 will be documented in a month's report
TRAHM, T. R. Commonwealth Edison Co. 81/01/02 17pp 07441 065

810100504 Confirms intent to comply w/ rept. "Interim Position for Containment Purge & Vent Valve Operation Pending Resolution of Isolation Valve Operability." Submits temporary plan for use when reactor not in refueling or cold shutdown mode
TRAHM, T. R. Commonwealth Edison Co. 81/01/14 2pp 07183 001

810100507 Supplements Jtl 810114 ltr re plans to use containment purge valves per NRC 791023 guidance. Discusses benefits of conducting containment purging
TRAHM, T. R. Commonwealth Edison Co. 81/01/14 2pp 07183 001

810100753 Forwards Amends 60 & 57 to Licenses DPR-39 & DPR-48, respectively, & notice of issuance & availability
VARGA, S. A. Operating Reactors Branch 1 81/01/14 3pp 07583 191

--810100752 Amends 60 & 57 to Licenses DPR-39 & DPR-48, respectively, deleting surveillance requirements for valves physically installed or removed from facility by plant mode from Tech Spec App A
VARGA, S. A. Operating Reactors Branch 1 81/01/14 12pp 07583 194

--810100754 Notice of issuance & availability of Amends 60 & 57 to Licenses DPR-39 & DPR-48, respectively
VARGA, S. A. Operating Reactors Branch 1 81/01/14 3pp 07583 205

810100759 Approves Jtl 810114 add to commitment to interim position re containment purge contingent on listed elements
VARGA, S. A. Operating Reactors Branch 1 81/01/15 2pp 07575 114

810100761b Forwards Amends 61 & 58 to Licenses DPR-39 & DPR-48, respectively, & notice of issuance & availability
VARGA, S. A. Operating Reactors Branch 1 81/01/15 3pp 07585 240

--810100762 Amends 61 & 58 to Licenses DPR-39 & DPR-48, respectively, approving guard training & qualification plan & combining separate license conditions for security plan, safeguards contingency plan & guard training plan
VARGA, S. A. Operating Reactors Branch 1 81/01/15 4pp 07585 243

--810100767 Notice of issuance & availability of Amends 61 & 58 to Licenses DPR-39 & DPR-48, respectively
VARGA, S. A. Operating Reactors Branch 1 81/01/15 3pp 07585 247

810120358 Forwards offsite dose calculation sys description per meteorological data requirements in NUREG-0737 Task 111 A 2
DELGEMSE, L. D. Commonwealth Edison Co. 81/01/19 1p

--810120374 "Offsite Dose Calculation Sys Meteorological Monitoring, Offsite Dose Calculation Program for Emergency Preparedness at Operating Nuclear Power Plants." Revision 2
GOLDEN, J. C. Commonwealth Edison Co. 80/07/31 130pp

--810120374 "Study of Low Level Dispersion Over Northern IL."
* Murray & Trettel, Inc. 74/06/30 106pp

Q Inspection reports, IE Bulletins & correspondence

8101050249 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/10/30 2pp

8101050462 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/11/06 2pp

8101050124 Requests existing data, summaries & records of in-service ins. tests of containment w/ gressed prestressing tendons
GML receiving contract to compile & review records of tendons
EISENHUT, D. G. Division of Licensing 80/11/25 3pp

8101146091 Forwards IE Insp Repts 50-295/80-20 & 50-304/80-21 on 801001-1114 No noncompliance noted
HEIMANN, R. F. Region 3, Chicago, Reactor Operations Nuclear Safety Branch 80/11/28 2pp 07460 297

--8101146097 IE Insp Repts 50-295/80-20 & 50-304/80-21 on 801001-1114 No noncompliance noted. Major areas inspected: operational safety verification, jumper & lifted lead log & Unit 2 reactor trip
FOHLER, J. E., WATERS, J. R., HEIMANN, R. F. Region 3, Chicago, Office of the Director 80/11/28 14pp 07460 299

8101050530 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Steam Discharge Valve at Dresden Unit 2." No response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/12/05 2pp

8101150628 Forwards IE Insp Repts 50-295/80-22 & 50-304/80-24 on 801117-19 & notice of violation
DAVIS, A. B. Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/12/04 2pp 07465 255

--8101150634 Notice of violation from Insp on 801117-19
DAVIS, A. B. Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/12/04 1p 07465 257

--8101150640 IE Insp Repts 50-295/80-22 & 50-304/80-24 on 801117-19 Noncompliance noted corrective actions contained in Rds 50-295/80-45 & 50-295/80-47 & confirmatory measures
PHILLIPS, M. P., JAYASHA, A. G., PAPERIELLO, C. J. Region 3, Chicago, Office of the Director 80/12/03 8pp 07465 258

8101070214 Responds to IE Bulletin 80-11, "Masonry Wall Design." Data on previous ltr should read 820101, not 80101
RAUSCH, T. J. Commonwealth Edison Co. 80/12/11 1p 07415 243

8101060073 Responds to IE Bulletin 80-23, "Failures of Solenoid Valve Mfg by Valcor Engineering Corp." Valves V70900-21-1 or V70903-21-3 not used in any safety-related functions. Approx 40 manhours expended in bulletin review
RAUSCH, T. J. Commonwealth Edison Co. 80/12/12 1p

8101070105 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown." No written response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/12/16 1p 07415 024

8101080093 Responds to NRC 800818 request for monthly status report re evaluations in response to IE Bulletin 79-14. Tabulations of piping sys w/stresses above FBAR levels & below operability limit encl
JANECEK, R. F. Commonwealth Edison Co. 80/12/22 9pp

8101060285 Forwards IE Insp Repts 50-295/80-23 & 50-304/80-25 on 801117-21 & notice of violation. Notice of violation withheld (ref 10CFR2 790)
HIND, J. A. Region 3, Chicago, Safeguards Branch 80/12/23 2pp 07392 027

--8101060290 IE Insp Repts 50-295/80-23 & 50-304/80-25 on 801117-21 Noncompliance noted. Implementation of security change w/o Commission approval. Details withheld (ref 10CFR2 790)
CHRISTOFFER, G., PIRTLE, O. L. Region 3, Chicago, Office of the Director 80/12/22 2pp 07392 029

8101200155 Forwards response to IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (801017 Indian Point 2 Event)." Surveillance procedures, of at least monthly repetition, will be instituted by 810601.
RAUSCH, T. J. Commonwealth Edison Co. 81/01/09 6pp

8101260675 Ack receipt of 801230 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-295/80-22 & 50-304/80-24
FISHER, W. L. Region 3, Chicago, Fuel Facility & Materials Safety Branch 81/01/12 1p 07531 159

--8101260689 Responds to NRC 801209 ltr re violations noted in IE Insp Repts 50-295/80-22 & 50-304/80-24. Corrective actions: recalibr of all GELI detectors at 1-yr intervals.
ABEL, J. S. Commonwealth Edison Co. 80/12/30 2pp 07531 160

table occurrences. LERs & related correspondence

338 Forwards updated LER 80-091/03X-1
SER, K L Commonwealth Edison Co 80/12/31 1p 07447 156

20343 Updated LER 80-091/03X-1 on 801115, PP zone 2 pressure fell
out Tech Spec requirements & purge exhaust isolation valve
V-RV0004 found leaking at valve seat Caused by valve seat
traction during cold weather
4205, A Commonwealth Edison Co 80/12/31 1p 07447 157

346 Forwards LER 79-096/03L-0
SER, K L Commonwealth Edison Co 80/12/31 1p 07447 163

20349 LER 79-096/03L-0 on 791120, low-low lve comparator ITC4320N
outs found low, exceeding Tech Specs limit Caused by
instrument drift of unknown origin Comparator tested.
slight & returned to svc
44, B Commonwealth Edison Co 80/12/31 1p 07447 166

161 Forwards LER 80-053/03L-0
SER, K L Commonwealth Edison Co 81/01/06 1p 07454 105

10516 LER 80-053/03L-0 on 800825, component cooling liquid rad
tor IRE 0017 did not respond to check source & indicator
at bottom of scale Caused by drift in monitor plateau
seau reset
1, R E Commonwealth Edison Co 81/01/06 1p 07454 106

41 Forwards LER 79-097/03L-0
SER, K L Commonwealth Edison Co 81/01/07 1p 07454 143

10551 LER 79-097/03L-0 on 790724, rad urgent alarm received while
mpting to move shutdown bank C Caused by failure of
er/oscillator card in rad control logic cabinet New card
ined & installed
EMI, W D Commonwealth Edison Co 81/01/07 1p 07454 144

59 Forwards LER 80-054/03L-0
ER, A L Commonwealth Edison Co 81/01/14 1p 07454 103

0536 LER 80-054/03L-0 on 801215, RHM miniflow control valve
-610A switch failed, making RHM pump sys A unable to
orm Caused by faulty micro switch Switch replaced &
libr
008, A Commonwealth Edison Co 81/01/14 1p 07454 104

30 Forwards LER 80-055/03L-0
ER, K L Commonwealth Edison Co 81/01/15 1p 07549 074

0733 LER 80-055/03L-0 on 801216, during normal operation, gas decay
radiation monitor CRT-PRO2B was taken out of svc for
& grab samples were not taken for two shifts Caused by
onnel oversight, Personnel retrained
JRC, J Commonwealth Edison Co 81/01/15 1p 07549 075

for Examinations

71 Requests that WK Joubert be re-examined for senior operator
e during wk of 810112
ER, K L Commonwealth Edison Co 80/12/01 1p 07461 346

3-296 BROWN FERRY NUCLEAR POWER STATION, UNIT 3

ity, medical, emergency & fire protection plans

37 Ltr to all licensees of operating reactor plants, CP holders
licants, Revised radiological emergency response
ust be submitted by licensees within 60 days of
& by applicants as part of FSAR
IT, D G Division of Licensing 80/11/13 2pp

37 Transcript of 801217 briefing on TVA emergency offsite
ies in Washington, DC, pp 1-43
issions: 80/12/17 49pp

& Forwards request for addl info & revisions to 801001 changes
lity guard training & qualification plan, Min passing
or qualifying w/rifle should be stated
G, T A Operating Reactors Branch 2 81/01/14 3pp
79.

1 Releases public version of util revised emergency plan.
J M Division of Rules and Records 81/01/15 1p
33

--8101260519 Forwards public version of revised radiological emergen
plan in response to HRC 801113 ltr Includes State of AL
emergency plan
MILLS, L M Tennessee Valley Authority 80/12/31 1p 07531 23

--8101260634 Public version of revised util radiological emergency pl
a Tennessee Valley Authority 80/12/31 150pp 07531 732

--8101260693 Releases public version of State of AL revised emergency
plan
FELTON, J M Division of Rules and Records 81/01/16 1p
07534 180

--8101260706 Public version of State of AL revised radiological emergen
a Tennessee Valley Authority 80/12/31 300pp 07534 182

8101300356 Forwards revisions to safeguards contingency plan Enc)
withhold (ref 10CFR12.790)
MILLS, L M Tennessee Valley Authority 81/01/23 1p 07586 228

0 Adjudicatory correspondence

8101300467 Order granting extension to exemption from General Design
Criteria 50 & requiring licensee to reassess containment
design for suppression pool hydrodynamic loading
CISENHUT, D O Division of Licensing 81/01/13 7pp 07586 122

8101160226 Petition for leave to intervene & request for hearing on T
license amend requests
PAUL, T W, JOHNS, R W, WALL, M L Affiliation Unknown 81/01/14
4pp 07470 169

8101200070 Motion for leave to intervene in proceeding re license
amends to allow onsite storage of low level radwaste for
five yrs.
CURRITT, D R, CURRITT, U J Affiliation Unknown 81/01/15 3pp
07486 359

8101200091 Petition for leave to intervene in proceeding
MARTIN, J R, BECK, N M, BECK, R W Affiliation Unknown 81/01/16
3pp 07187 001

8101200093 Petition for leave to intervene in proceeding
MUSE, N, FREEMAN, R L, COLCLOCK, A N Affiliation Unknown 81/01/16
4pp 07486 353

8101200214 Petition for leave to intervene & request for hearing on
license amend requests
MARTIN, D L, BROUUGH, D R, PIERSON, M D Affiliation Unknown
81/01/16 3pp 07476 341

8101230107 Requests to make limited appearance statement & to receive
EIS on proposed low level radwaste storage project
YOUNG, F Affiliation Unknown 81/01/21 1p 07107 001

8101300012 Response supporting DR & UJ Curritt, TW Paul, RW Jube, PL Hall)
JL Martin, OR Brough, MD Pierson, D Ely, D Havas, N Muse, RL
Freeman, AN Colcl, JR Martin & NM & RW Beck petitions for
leave to intervene if amended Certificate of Svc encl
LAVERTY, J H Office of the Executive Legal Director 81/01/28
12pp 07582 176

J Insurance & indemnity information

8101040486 Forwards Endorsement 53 to ANI Policy NF-19B for amend to
Condition 2
FIELDER, J Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc
Div 80/12/27 3pp 07442 254

8101090490 Forwards Endorsement 52 to ANI Policy NF-19B for 1981
advances premiums
FIELDER, J Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc
Div 80/12/27 2pp 07442 083

8101090647 Forwards Endorsement 4 to NELIA Binders ED-38, ED-39 &
ED-40 w/o Binders ED-39 & ED-40
FIELDER, J Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc
Div 80/12/29 2pp 07442 060

P Operating license stage documents & correspondence

8101100254 Ltr to all licensees (except SEP licensees) forwarding
Revision 1 of inservice surveillance requirements for
snubbers under B15 License amend application adding model
Tech Specs to App A should be submitted within 120 days
CISENHUT, D O Division of Licensing 80/11/20 1p

--B010100271 Revised Pages 3/4 7-22 through 28; 3/4 7-5 & 7-6 & 6-17 to
SIS snubber inservice insp requirements
* Division of Licensing 80/11/20 10pp

B010220466 Ltr to all power reactor licensees & applicants forwarding
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issue A-12. Potential for Low Fracture
Toughness & Laminar Fracture on Component Supports
EISENHUT, D O Division of Licensing 80/11/26 8pp

B010100030 Requests input sect 4 simulator time re NRC comparison of
RETRAN results w/simulator results for loss of feedwater &
loss of load transients in BWR
IPPOLITO, T A Operating Reactors Branch 2 80/12/02 2pp
07444 299

B010100022 Forwards FR notice of consideration of amends to facility
DLs re util B00731 & 1117 applications for authorization of
onsite low level waste storage for 5-yr period
IPPOLITO, T A Operating Reactors Branch 2 80/12/05 2pp
07445 204

B010190113 Ltr to all BWR licensees forwarding B01201 generic safety
evaluation re BWR scram discharge sys Recommends short-term
actions necessary to assure safe operation of OE BWRs
pending permanent design changes
EISENHUT, D O Division of Licensing 80/12/09 2pp

--B010190141 Generic safety evaluation re short-term actions required to
assure continued safe operation of operating BWRs Continued
operation of plants is acceptable pending permanent design
mods Criteria for implementing design mods encl
* Division of Licensing 80/12/01 212pp 07183 001

B010505610 Forwards geologic rept re suggested graben in Gravelly
Springs, AL area Distance to facilities precludes
significance of structures Related documentation encl
LEFEVRE, H E Geosciences Branch 80/12/11 15pp 03775 001

B010210445 Forwards responses to questions on Rule 50.71e. "Periodic
Updating of FSARs" & FR notice of final rule. SEP plants need
not comply w/rule until program is complete Non-SEP plants
must comply within specified time frame
EISENHUT, D O Division of Licensing 80/12/15 13pp

B010210642 Advises that ATWS issue will be subj of future rulemaking to
determine requirements & schedules for plant mode NRC will
not comment on util B00717 ltr describing program for
resolving issue until rulemaking is finalized
EISENHUT, D O Division of Licensing 80/12/29 2pp 07468 339

B010290033 Forwards Amends 65.61 & 36 to Licenses DPR-33, DPR-52 &
DPR-68, respectively. EIA & notice of issuance & negative
declaration
IPPOLITO, T A Operating Reactors Branch 2 80/12/29 3pp
07309 001

--B010290040 Amends 65.61 & 36 to Licenses DPR-33, DPR-52 & DPR-68,
respectively, changing App B Tech Specs to delete fish
impingement monitoring program
IPPOLITO, T A Operating Reactors Branch 2 80/12/29 12pp
07309 001

--B010290046 EIA supporting Amends 65.63 & 36 to Licenses DPR-33, DPR-52
& DPR-68, respectively. Summary review of fish impingement
encl
* Office of Nuclear Reactor Regulation, Director 80/12/29
32pp 07309 001

--B010290052 Notice of issuance & availability & negative declaration of
Amends 65.61 & 36 to Licenses DPR-33, DPR-52 & DPR-68,
respectively
IPPOLITO, T A Operating Reactors Branch 2 80/12/29 2pp
07309 001

B010190393 Advises that util B00909 response to NRC B00702 generic ltr
re Tech Specs for TMI Lessons Learned Category A items is
inadequate Outstanding items emergency power supply relief
& safety valve position indication
IPPOLITO, T A Operating Reactors Branch 2 81/01/02 2pp
07475 344

B010300467 Order granting extension to exemption from General Design
Criterion 30 & requiring licensee to reassess containment
design for suppression pool hydrodynamic loading
EISENHUT, D O Division of Licensing 81/01/13 7pp 07586 122

B010220411 Requests temporary relief from 5 F thermal rise limit & 100
max reservoir temp rise of 8.5 F be granted until Apr 1981
Temp rise of 8.5 F will sustain 3-unit operation at facility
w/current min hydro releases for navigation
EL-ASHRY, M T Tennessee Valley Authority 81/01/14 3pp
07502 246

B010220297 Grants request for temporary relief from permit conditions
re allowable temp rise within certain conditions Temp at
edge of mixing zone must not exhibit change greater than
8.5 F
ZELLER, H D Environmental Protection Agency 81/01/19 2pp
07500 069

B010300493 Forwards response to NRC B01123 request for confirmation
that NUREG-0619 implementation dates will be met Info
justifies continued operation
MILLS, L M Tennessee Valley Authority 81/01/23 3pp 07161 001

G. Inspection reports, IE Bulletins & correspondence

B010800181 Forwards update to B010104 response to IE Bulletin 79-26 re
boron loss from BWR control blades Manpower required for
review & preparation approx 20-h
MILLS, L M Tennessee Valley Authority 80/11/25 3pp 03775 001

B010450588 Forwards IE Info Notice 80-43, "Failures of Continuous Water
Level Monitor for Scram Discharge Vol at Dresden Unit 2 " No
response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/03
1p 07391 010

B010140866 Responds to IE Bulletin 80-23 Defective solenoid valves
w/rate & part numbers in bulletin are not in use at
facilities
MILLS, L M Tennessee Valley Authority 80/12/19 1p 07461 051

B01060153 Forwards IE Info Notice 80-49, "Potential Failure of BW
Backup Manual Scram Capability " No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/17
1p 07391 275

B010700032 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of 76 of 163
Control Rods to Fully Insert During Scram at BWR " No
written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/18
1p 07413 323

B01050153 Forwards IE Bulletin 80-25, "Operating Problems w/Target
Rock Safety Relief Valves at BWRs " No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/19
2pp 07377 249

B010160252 Forwards response to IE Bulletin 80-07, "BWR Jet Pump
Assembly Failure " Ultrasonic & visual insp of jet pump
beams & assembly showed no problems
MILLS, L M Tennessee Valley Authority 80/12/30 2pp 07470 249

B010210157 Informs that insp program re IE Bulletin 79-14 will not be
completed by B01125 due to delays in planned schedules.
Revised insp schedule & Dec 1980 status rept encl
MILLS, L M Tennessee Valley Authority 81/01/05 30pp 07490 010

B010220376 Forwards results of spray sparger insp in response to IE
Bulletin 80-13, "Cracking in Core Spray Spargers "
MILLS, L M Tennessee Valley Authority 81/01/09 2pp 07583 294

B010280305 Forwards response to IE Bulletin 80-24, "Prevention of
Damage Due to Water Leakage (Oct 17, 1980 Indian Point 2
Event)." Components requiring supplemental cooling are
cooled by reactor bldg closed cooling water sys
MILLS, L M Tennessee Valley Authority 81/01/05 5pp 07550 319

B010280527 Forwards results of util analyses on diesel generators &
480 V load shed logic re IE Bulletin 80-06, "Engineered
Safety Feature (ESF) Reset Controls "
MILLS, L M Tennessee Valley Authority 81/01/14 2pp 07550 336

B010290350 Forwards monthly status rept as of B010101 for work re IE
Bulletin 79-14, "Seismic Analysis for As-Built
Safety-Related Piping Sys " Includes description of pipe
support & valve insp
MILLS, L M Tennessee Valley Authority 81/01/15 29pp 07572 321

R. Periodic operating reports & related correspondence

B01030582 Forwards monthly operating repts for Dec 1980
ABERCROMBIE, H Tennessee Valley Authority 81/01/09 1p
07493 233

120599 Monthly operating repts for Dec 1980
J.M.T. Tennessee Valley Authority 81/01/04 37pp 07453 326

0595 Forwards monthly operating repts for Dec 1980
R.D.H.B.E.H Tennessee Valley Authority 81/01/09 1p
3 288

120601 Monthly operating repts for Dec 1980
J.E.N.D., T.H.M.T Tennessee Valley Authority 81/01/04 21pp
493 289

Portable occurrences. LERs & related correspondence

0469 Forwards LER 80-058/03L-0
J.H.J Tennessee Valley Authority 81/01/06 1p 07454 110

120505 LER 80-058/03L-0 on 801207.MSIV 1-14.1-15.1-26.1-27.1-37 &
JB & 1-51 found leaking Caused by seating surface
degradation due to normal wear Valves repaired
Tennessee Valley Authority 81/01/06 2pp 07454 111

0606 Forwards LER 80-054/01T-0
J.H.J Tennessee Valley Authority. 81/01/08 1p 07475 023

120612 LER 80-054/01T-0 on 801210.eight main steam relief valves
failed to actuate within required 1% of set pressure.Cause
unknown Set pressure reset & proper operation verified
Followup rept will be issued
Tennessee Valley Authority 81/01/08 2pp 07475 024

0476 Forwards "Analysis of Incomplete Control Rod Insertion at
 Browns Ferry 3 "
J.L.M Tennessee Valley Authority 81/01/12 1p 07475 090

120500 "Analysis of Incomplete Control Rod Insertion at Browns
 Ferry 3 "
Nuclear Safety Analysis Center * Institute of Nuclear Power
Operations NSAC-20. 80/12/31. 76pp 07475 091

0311 Forwards first interim rept re potential flammability of
suspended ceiling tile in control rooms in response to
04 ltr.Addl info to be provided by 810211
J.L.M Tennessee Valley Authority. 81/01/14 3pp. 07494 096

0572 Forwards updated LER 80-030/03L-1.
J.H.J Tennessee Valley Authority. 81/01/19 1p 07546 320.

120579 Updated LER 80-030/03L-1 on 800813.Model B2T-A1269 pressure
switches PS-1-B1A & PS-1-91A.Turbine first stage pressure.
Setpoints drifted above Tech Spec limits.Cause not stated.
Switches inspected,recalibr & tested for repeatability
Tennessee Valley Authority 81/01/19 2pp. 07546 321

0668 Forwards updated LER 80-016/03L-1.
J.H.J. Tennessee Valley Authority 81/01/19 1p. 07546 346

120673 Updated LER 80-016/03L-1 on 800513.cooling water flow
determined inadequate on diesel generator heat exchanger 3D.
Caused by apparent restriction in cooling water piping.
Cooling lines flushed
Tennessee Valley Authority. 81/01/19 2pp. 07546 347.

0713 Forwards updated LER 80-036/03L-1.
J.H.J. Tennessee Valley Authority. 81/01/20 1p 07548 071.

120716 Updated LER 80-036/03L-1 on 800715.diesel generator 3A would
not trip to idle speed from loaded condition.Caused by
worn pin on pinion gear to intermediate shaft gear used
for speed adjusting on Woodward governor.Governor replaced.
Tennessee Valley Authority. 81/01/20 2pp 07548 072

0705 Forwards LER 80-040/03L-1
J.H.J. Tennessee Valley Authority. 81/01/21 1p. 07548 081.

120711 LER 80-040/03L-1 on 801010.3EB diesel generator lube oil
circulating pump discovered inoperable.Caused by locked
rubber row ball bearing.Lube oil circulating pump replaced
Tennessee Valley Authority. 81/01/21 2pp. 07548 082

0811 Forwards updated LER 80-015/03L-1.
J.H.J. Tennessee Valley Authority. 81/01/26 1p. 07586 318.

--8101300514 Updated LER 80-015/03L-1 on 800512.RHR pump seal heat
exchanger 3D cooling water flow found inadequate per Tech
Specs Caused by apparent restriction in cooling water piping
upstream 3/4 or downstream from heat exchanger
* Tennessee Valley Authority 81/01/26 2pp 07586 319

8101300632 Forwards LER 80-051/03L-0
GREEN.H.J Tennessee Valley Authority 81/01/26 1p 07586 356

--8101300641 LER 80-061/03L-0 on 801230.SLC pump discharge relief valve
3D would not relieve within Tech Spec Caused by galled valve
disc or disc binding w/valve guide Valve replaced
* Tennessee Valley Authority 81/01/26 2pp 07586 357

8101300504 Forwards updated LER 80-038/03L-1
GREEN.H.J Tennessee Valley Authority 81/01/27 1p 07586 313

--8101300520 Updated LER 80-038/03L-1 on 800907.MSIV 3-FCV-1-26 closed
too fast while running surveillance instruction Caused by
low oil level in hydraulic cylinder Oil added & flow control
valve adjusted
* Tennessee Valley Authority 81/01/27 2pp 07586 314.

8101300611 Forwards LER 80-059/03L-0
GREEN.H.J Tennessee Valley Authority 81/01/27 1p 07586 357.

--8101300615 LER 80-059/03L-0 on 801231.MSIV 1-14.1-15.1-26.1-27.1-37.
1-38 & 1-51 total as-found containment leak rate exceeded
allowable rate Caused by deterioration of valve seating
surfaces Maint & retest effected until rate acceptable.
* Tennessee Valley Authority 81/01/27 2pp. 07586 358

DOCKET 80-298 COOPER NUCLEAR STATION

F. Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants,CP holders
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
810102 & by applicants as part of FBAR
EISENHUT.D.O Division of Licensing 80/11/13 2pp.

8101090405 Ltr to all power reactor licensees w/plants licensed prior
to 790101. Forwards FR notice of revised 10CFR50 AD & App R
re fire protection features in nuclear power plants
EISENHUT.D.O Division of Licensing 80/11/24 3pp. 07387 266

8101140219 Informs that licensee should conduct emergency exercise
within one yr from 800401 or prior to issuance of OL
Schedule of drills should be provided.
SECFRIT.K.V Region 4, Dallas, Office of the Director 80/12/23
1p 07461 258

Q. Adjudicatory correspondence

8101300396 Forwards NRC 810113 order granting extension to exemption
from General Design Criterion 30 & requiring licensee to
reassess containment design for suppression pool
hydrodynamic loading
IPPOLITO.T.A Operating Reactors Branch 2 81/01/13 3pp
07586 197

P. Operating license stage documents & correspondence

8101220637 "Examination of Cracked Turbine Disc From Cooper Nuclear
Power Station," informal rept
CZAJKOWSKI.C.J. Brookhaven National Laboratory FIN A-3106
BNL-NUREO-28724 80/10/31 37pp. 07479 267.

8101100053 Notifies that util 801015 application to amend OL requires
Class III amend fee Application proposed Tech Spec changes
resulting from TMI-2 Lessons Learned requirements.
DIGGS.R.M License Fee Management Branch. 80/11/17 1p
07444 044

8101100254 Ltr to all licensees (except BEP licensees) forwarding
Revision 1 of inservice surveillance requirements for
snubbers under STS license amend application adding model
Tech Specs to App A should be submitted within 120 days.
EISENHUT.D.O Division of Licensing. 80/11/20 1p.

--8101100271 Revised Pages 3/4 7-22 through 28.8 3/4 7-5 & 7-6 & 8-17 to
STS snubber inservice insp requirements
* Division of Licensing. 80/11/20 10pp.

B101070432 Notifies of installation of equipment to meet requirements of NRC B101032 (configuratory, order re monitoring scan discharge vol Ficat-type level switches & ultrasonic equipment installed Description encl)
 PILANT, J M Nebraska Public Power District 80/11/24 4pp
 07415 321

B10120486 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
 EISENHUT, D G Division of Licensing 80/11/26 8pp

B101190113 Ltr to all BWR licensees forwarding B01201 generic safety evaluation re BWR scan discharge sys Recommends short-term actions necessary to assure safe operation of OE BWRs pending permanent design changes
 EISENHUT, D G Division of Licensing 80/12/09 2pp

--B101190141 Generic safety evaluation re short-term actions required to assure continued safe operation of operating BWRs Continued operation of plants is acceptable pending permanent design mods Criteria for implementing design mods encl
 * Division of Licensing 80/12/01 212pp 07183.001

B101210445 Forwards responses to questions on Rule 50.71e, Periodic Updating of FRAs & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame
 EISENHUT, D G Division of Licensing 80/12/15 13pp

B101050466 Forwards status of TMI-related requirements scheduled for implementation prior to B10101 & discussion of requirements scheduled for response between Jan & Jul 1981
 PILANT, J M Nebraska Public Power District 80/12/30 39pp
 07303 224

--B101050473 "Control Room Habitability Study"
 * Stone & Webster Engineering Corp 80/12/12 35pp 07383.262

B101120162 Forwards proposed revision to B01015 Tech Specs addressing areas of valve position indication, shift technical advisor, sys integrity & improved iodine measurements program per TMI-2 Lessons Learned Task Force requirements
 PILANT, J M Nebraska Public Power District 81/01/06 2pp
 07446 212

--B101120167 Proposed revision to B01015 Tech Specs Sections 3.5 & 6 re valve position indication, shift technical advisor, sys integrity & improved iodine measurements program per TMI-2 Lessons Learned Task Force requirements
 * Nebraska Public Power District 81/01/06 4pp 07446 214

B101160448 Responds to NUREG-0619 re feedwater nozzles & control rod drive return line nozzles During spring refueling & maint outage feedwater nozzles inspected & double piston spargers installed No other sys mods necessary
 PILANT, J M Nebraska Public Power District 81/01/07 2pp
 07470 079

B101300396 Forwards NRC B10113 order granting extension to exemption from General Design Criterion 50 & requiring licensee to reassess containment design for suppression pool hydrodynamic loading
 JPMOLIT, T A Operating Reactors Branch 2 81/01/13 3pp
 07506 197

--B101300409 Order granting extension to exemption from General Design Criterion 50 & requiring licensee to reassess containment design for suppression pool hydrodynamic loading
 EISENHUT, D G Division of Licensing 81/01/13 7pp 07586:200

G Inspection reports, IE Bulletins & correspondence

B101100029 Forwards IE Insp Rept 50-298/80-16 on B01021-24 & 29-31. No noncompliance noted
 MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/11/14 2pp 07443 031

--B101100031 IE Insp Rept 50-298/80-16 on B01021-24 & 29-31 No noncompliance noted Major areas inspected followup to previously identified items, IE bulletins & short-term Lessons Learned Category A items
 SPAINGLER, R O, WESTERMAN, T F Region 4, Dallas, Office of the Director 80/11/14 9pp 07443 033

B101090272 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (October 17, 1980 Indian Point 2 event)" Written response required
 SEYFRIT, K V Region 4, Dallas, Office of the Director 80/11/21 1p 07425 242

B101060329 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Chubbet Fluid" No response required
 SEYFRIT, K V Region 4, Dallas, Office of the Director 80/11/24 1p 07392:062

B101080074 Responds to IE Bulletin 80-23 re Valcor Engineering Corp solenoid valve failures No such valves installed at facility
 PILANT, J M Nebraska Public Power District 80/11/24 1p
 07421 068

B101060301 Forwards Suppl 1 to IE Info Notice 80-27, "Broken Studs on Terry Turbine Steam Inlet Flange" No written response required
 SEYFRIT, K V Region 4, Dallas, Office of the Director 80/11/26 1p 07392 043

B101090609 Forwards IE Info Notice 80-43, "Failures of Continuous Wet Level Monitor for Scan Discharge Vol at Dresden Unit 2." No response required
 SEYFRIT, K V Region 4, Dallas, Office of the Director 80/12/05 1p 07391 030

B10120050 Responds to IE Bulletin 80-21 re valve yokes supplied by Malcolm Foundry Co. Inc No response received from valve vendors as yet
 PILANT, J M Nebraska Public Power District 80/12/08 2pp
 07446 262

B101070146 Ack receipt of B01203 & 1016 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-298/80-13
 MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/12/15 1p 07407 031

--B101070155 Responds to NRC B01113 ltr re violations noted in IE Insp Rept 50-298/80-13 Corrective actions time period between requalification exams & grade tests shortened to within 60 days of test date
 PILANT, J M Nebraska Public Power District 80/12/03 2pp
 07409 032

B101120138 Responds to IE Bulletin 80-24 re water leakage inside containment No significant leakages of cooling water inside containment identified
 PILANT, J M Nebraska Public Power District 80/12/15 3pp
 07446 254

A Periodic operating reports & related correspondence

B101130587 Forwards monthly operating rept for Dec 1980.
 LESBOR, L C Nebraska Public Power District 81/01/05 1p
 07453 277

--B101130593 Monthly operating rept for Dec 1980
 BALLINSER, P L Nebraska Public Power District 81/01/05 4pp
 07453 278

B Reportable occurrences, LERs & related correspondence

B101070514 Forwards LER 80-041/03L-0
 LESBOR, L C Nebraska Public Power District 80/11/14 2pp
 07415 111

--B101070521 LER 80-041/03L-0 on B01016, svc water pump C noted vibr excessively. Cause undetermined. Pump disassembled & rotating assembly returned for overhaul. Other components reused.
 BRAW, H F Nebraska Public Power District 80/11/14 1p
 07415 113

B101070507 Forwards LER 80-042/03L-0
 LESBOR, L C Nebraska Public Power District 80/11/18 2pp
 07415 084

--B101070511 LER 80-042/03L-0 on B01020, throttle valve SW-MD-09A on discharge of A RHR heat exchanger would not fully close. Caused by valve stem clamp slipping out of position allowing valve stem to rotate stem clamp keyway enlarged due to wear.
 LAWRENCE, L J Nebraska Public Power District 80/11/18 1p
 07415 086

B101070360 Forwards LER 80-039/03L-0
 LESBOR, L C Nebraska Public Power District 80/11/19 2pp
 07406 344

01070363 LER 80-039/03L-0 on 801023, snubber RH-S-27 discovered inoperable. Caused by work in area damaging snubber. Snubber repaired & protective shield installed
BUNTON, L. F. Nebraska Public Power District 80/11/19. 1p
07406 346

070351 Forwards LER 80-043/03L-0
BBDOR, L. C. Nebraska Public Power District 80/11/20 2pp
406 338

01070353 LER 80-043/03L-0 on 801021, motor operated valve BW-MO-898 failed to open. Caused by broken wire connected to QHMTIE 1000-ohm variable resistor inside valve operator. Broken lead resoldered & circuit checked
BBDOR, L. F. Nebraska Public Power District 80/11/20 1p
07406 340

070355 Forwards LER 80-044/01T-0
BBDOR, L. C. Nebraska Public Power District 80/11/25 2pp
406 341

01070357 LER 80-044/01T-0 on 801115, reactor scram occurred & normal cooldown rate exceeded. Caused by failed card (Westinghouse-Magan 398522) in computer controlled turbine control sys forcing main steam bypass valves to remain open.
BBDOR, P. J. Nebraska Public Power District 80/11/25 1p
07406 343

070489 Forwards LER 80-045/03L-0
BBDOR, L. C. Nebraska Public Power District 80/11/26 2pp
406 356

01070492 LER 80-045/03L-0 on 801102, hydraulic shock suppressor RH-B-43 found inoperable per radiological Tech Spec. Caused by suppressor installed w/reservoir connecting pipe at wrong end of reservoir. Suppressor installed properly
LAWRENCE, L. I. Nebraska Public Power District 80/11/26 1p
07406 358

070477 Forwards LER 80-046/03L-0
BBDOR, L. C. Nebraska Public Power District 80/12/19. 3pp
406 352

01070480 LER 80-046/03L-0 on 801117, isolation valve on discharge line from drywell equipment pump G, RW-AO-94, would not open. Caused by hard & worn U-cup seal in piston air operator. New piston U-cups installed & valve retested
SCHEER, J. L. Nebraska Public Power District 80/12/19. 1p
07406 359

270649 Forwards LER 80-048/03L-0
BBDOR, L. C. Nebraska Public Power District 80/12/16 2pp
546 343

01270653 LER 80-048/03L-0 on 801121, containment oxygen concentration not reduced to less than 4% within 24-h of placing reactor in run mode. Cause unknown. Procedures will be revised to reduce potential for recurrence.
BBDOR, P. J. Nebraska Public Power District 80/12/16 1p
07546 345

270641 Forwards LER 80-049/03L-0
BBDOR, L. C. Nebraska Public Power District 80/12/19. 2pp
546 340

01270645 LER 80-049/03L-0 on 801120, MBIV 68A had slower closure time than Tech Specs allowed. Cause unknown. Closing time adjusted. Further evaluations to be performed
BUNTON, L. F. Nebraska Public Power District 80/12/19. 1p
07546 342

270715 Forwards LER 80-051/03L-0
BBDOR, L. C. Nebraska Public Power District 81/01/13 2pp
549 001

01270719 LER 80-051/03L-0 on 801216, during routine surveillance testing, HPCI turbine stop valve would not open & sys was declared inoperable. Caused by excess teflon seal matl which interfered w/relay valve on hydraulic actuator
FLANNIGAN, R. Nebraska Public Power District 81/01/13. 1p
07183 001

270775 Forwards LER 80-050/03L-0
BBDOR, L. C. Nebraska Public Power District 81/01/14 2pp
549 081

--8101270784 LER 80-050/03L-0 on 801216, during surveillance testing of RHR motor operated valves, RHR-MO-25B, loop B injection line inboard isolation would not open. Caused by installation error. Close torque switch was readjusted
BBDOR, L. F. Nebraska Public Power District 81/01/14 1p
07549 083

BUCKET 80-301 POINT BEACH NUCLEAR PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FBR
EISENHUT, D. O. Division of Licensing 80/11/13 2pp

8101090110 Releases public version of util preliminary draft emergency plan
FELTON, J. M. Division of Rules and Records 80/12/01 1p
07428 001

--8101090113 Forwards public version of preliminary draft emergency plan
FAY, C. W. Wisconsin Electric Power Co 80/07/25. 1p 07428 002

--8101090115 Forwards public version of preliminary draft emergency plan
FAY, C. W. Wisconsin Electric Power Co 80/07/25 1p. 07428 003

--8101090118 Public version of preliminary draft emergency plan
* Wisconsin Electric Power Co 80/07/31. 200pp. 07428 005

8101090716 Forwards facility emergency planning info to be made publicly available w/o encl.
SOUDEK, J. L. Division of Rules and Records 80/12/16 1p
07427 360

8101190297 Forwards request for addl info re 800822 revised safeguards contingency plan. Revised plan is acceptable, but approval is sub j to responsibility matrix section mods. Requests response within 60 days. Request withheld (ref 10CFR2 790)
CLARK, R. A. Operating Reactors Branch 3 80/12/19 2pp. 07476 054

8101260740 Requests that completion date for fire protection mods be extended to 81117 to provide time required for installation of remote diesel generator panels w/modified carbon dioxide extinguishing sys nozzles & tight fixture diffusers
FAY, C. W. Wisconsin Electric Power Co 81/01/20 2pp 07525 140

8101290148 Forwards facility emergency planning info to be made publicly available w/o encl.
SOUDEK, J. L. Division of Rules and Records 81/01/23. 1p.
07525 176

P Operating license stage documents & correspondence

8101100234 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under SIS license amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT, D. O. Division of Licensing 80/11/20. 1p

--8101100271 Revised Pages 3/4 7-22 through 28, B 3/4 7-5 & 7-6 & 6-17
SFB snubber inservice insp requirements
* Division of Licensing 80/11/20 10pp

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D. O. Division of Licensing 80/11/26 8pp

8101210445 Forwards responses to questions on Rule 50.71e, "Periodic Updating of FSARs" & FR notice of final rule. SEP plants need not comply w/rule until program is complete. Non-SEP plants must comply within specified time frame
EISENHUT, D. O. Division of Licensing 80/12/19 13pp

8101100918 Forwards Amends 46 & 51 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability
CLARK, R. A. Operating Reactors Branch 3 80/12/17 2pp 07445 011

--8101100327 Amends 46 & 51 to Licenses DPR-24 & DPR-27, respectively, changing Tech Specs to eliminate procedural steps for testing of containment spray additive valves
CLARK, R. A. Operating Reactors Branch 3 80/12/17. 6pp
07443 091

--B0100536 Safety evaluation supporting Amends 46 & 51 to Licensees
CPR-24 & DPR-27, respectively.
* Operating Reactors Branch 3 80/12/17 2pp 07445 097

--B0100543 Notice of issuance & availability of Amends 46 & 51 to
Licensees DPR-24 & DPR-27, respectively
CLARK, R. A. Operating Reactors Branch 3. 80/12/17 2pp.
07449 099

B01000175 Informs that addl duplicate amend fee for B00919 application
is still applicable as second unit required addl
administrative review in response to B01114 ltr
MILLER, W. O. License Fee Management Branch 80/12/19. 1p
07309 001

B01000175 "Instrument Bus Mnds. Point Beach Nuclear Plant, Units 1 & 2."
MAYB, S. E. EG&G Idaho, Inc. FIN A-6255 B01000175 80/12/31
4pp 07503 189

B01000589 Forwards addl response to NUREG-0737 re post-TMI
requirements for operating plants Meteorology submittal
completed. Control room habitability evaluation will be
provided by B0206
FAY, C. W. Wisconsin Electric Power Co. 81/01/09. 10pp 07489:256

B01004951 Responds to NRC B01219 request for second Class I license
amend approval fee for B00919 Tech Spec Change Request 64
No addl administrative effort required for issuance of
Tech Spec pages for second unit
BURSTEIN, S. Wisconsin Electric Power Co. 81/01/13 2pp
07469 357

B010260410 Forwards revised Page 7 to B01223 response to NUREG-0737.
Item II K 3 12
FAY, C. W. Wisconsin Electric Power Co. 81/01/19 2pp 07522:260

B010270666 Responds to NRC B00905 ltr requesting addl info re adequacy
of electrical distribution sys All safety-related sys
supplied from either 460 volt or 4160 volt sys Electrical
sys diagram encl
FAY, C. W. Wisconsin Electric Power Co. 81/01/21 4pp. 07545:349

G Inspection reports, IE Bulletins & correspondence

B01050225 Forwards IE Info Notice 80-38, "Cracking in Charging Pump
Casing Cladding." No response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/10/20
2pp 07309:074

B01050124 Requests existing data, summaries & records of inservice snap
tests of containments w/greased prestressing tendons
ORNL receiving contract to compile & review records of
tendons
EISENHUT, D. O. Division of Licensing. 80/11/25 3pp.

B01070263 Forwards list identifying security badge number & clearance
level for Region 3 personnel. Badge numbers for personnel
identified by asterisks will be provided at later date
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/11/25
6pp 07410 353

B01050578 Forwards IE Info Notice 80-43, "Failures of Continuous Water
Level Monitor For Steam Discharge Val at Dresden Unit 2." No
response required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/12/05
2pp 07309 336

B01050646 Forwards IE Insp Repts 50-266/80-17 & 50-301/80-17 on
B01001-31. No noncompliance noted.
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support
Branch 80/12/09 2pp 07465 272.

--B01050651 IE Insp Repts 50-266/80-17 & 50-301/80-17 on B01001-31. No
noncompliance noted. Major areas inspected: operational
safety verification, monthly maint & surveillance & followup
on LERs, IE bulletins & circulars
GULDEROND, W. O., HAQUE, R. L., WARRICK, R. F. Region 3, Chicago, Office
of the Director 80/12/04 6pp. 07465:274.

B01000174 Forwards IE Insp Repts 50-266/80-21 & 50-301/80-21 on
B01107 re NRC evaluation of licensed activity performance
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/12/10.
2pp. 07443 020

--B01000101 IE Insp Repts 50-266/80-21 & 50-301/80-21 re B01107 mgt
meeting to discuss regulatory performance of activities at
facility Encl licensee performance evaluation was presented
Performance found adequate.
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear
Support Branch 80/12/09. 10pp 07443:022.

B01070570 Forwards results of re-evaluation of mason
response to IE Bulletin 80-11 Includes schedule for
upgrading calls to meet criteria.
FAY, C. W. Wisconsin Electric Power Co. 80/12/12 4

B01070095 Forwards IE Info Notice 80-44, "Actuation of
Recirculation Mode While in Hot Shutdown." No written
response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director
1p 07415 033

B01020201 Suppl B00718 response to IE Bulletin 80-11
design Hall omitted from first analysis will be rean-
using criteria of B01114 ltr
FAY, C. W. Wisconsin Electric Power Co. 80/12/26 2

B010200150 Responds to IE Bulletin 80-24 re preventing
water leakage inside containment facilities have only
open cooling water sys inside containment & have had
significant leakage during plant operations.
FAY, C. W. Wisconsin Electric Power Co. 81/01/05 1

B010280379 Submits final response to IE Bulletin 80-21
Supplied by Malcolm Foundry Co. Inc. Manufacturers do
utilize specified valve parts castings.
BURSTEIN, S. Wisconsin Electric Power Co. 81/01/13

B010280521 Responds to NRC B01009 request for addl info
80-24, "Prevention of Damage Due to Water Leakage In
Containment (Oct 17, 1980 Indian Point 2 Event)." Info
provided re closed cooling water sys experience.
BURSTEIN, S. Wisconsin Electric Power Co. 81/01/13.
07530 328

R Periodic operating reports & related correspondence

B01050317 Forwards monthly operating repts for Dec 1980
FAY, C. W. Wisconsin Electric Power Co. 81/01/12 1

--B01050519 Monthly operating repts for Dec 1980
FAY, C. W. Wisconsin Electric Power Co. 81/01/07.
07463 164

S Reportable occurrences, LERs & related correspondence

B012170575 Forwards LER 80-010/03L-0.
FAY, C. W. Wisconsin Electric Power Co. 80/12/11. 1

--B012170615 LER 80-010/03L-0 on B01117, safety inject
& pump shaft to coupling keys found to be sheared.
undetermined. Pump & motor checked for damage, keys
pump operability verified.
FAY, C. W. Wisconsin Electric Power Co. 80/12/11

DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3

F Security, medical, emergency & fire protection plans

B01090387 Ltr to all licensees of operating reactor p
& CP applicants. Revised radiological emergency respo
plans must be submitted by licensees within 60 days
B010102 & by applicants as part of FBAR.
EISENHUT, D. O. Division of Licensing. 80/11/13. 2p

B01090453 Notifies of Commission approval of encl rule
previously approved completion dates for fire prote
code. Specific schedules for mods will be effective p
publication of final rule.
EISENHUT, D. O. Division of Licensing 80/11/18. 5p

B01090123 Requests that encl facility emergency plan
publicly available w/o encl.
SQUIDER, J. L. Division of Rules and Records. 81/01/0
07475:322

J. Insurance & indemnity information

B01090456 Forwards Endorsement 46 to NELA Policy NF-
FIELDER, J. Marsh & McLennan, Inc., M & M Nuclear Cor
Div. 80/12/30. 3pp. 07442:035.

B01090475 Forwards Endorsement 49 to ANI Policy NF-19
FIELDER, J. Marsh & McLennan, Inc., M & M Nuclear Cor
Div. 80/12/30. 2pp. 07442:041.

01090561 Forwards Endorsement 4 to ANI Policy ED-39
FIELDER, J. Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc
Div 80/12/30 2pp 07427 349

Advisory Committee on Reactor Safeguards reports & correspondence

010300770 Notice of ACRS Subcommittee on B&W Water Reactors 801031
meeting in Washington, DC re 800226 event at facility
JOYLE, J.C. Office of the Secretary of the Commission 80/10/14
2pp. 07584 251

Operating license stage documents & correspondence

01090739 Corrects typographical errors on Page 3 of 800722 memo re
interim std for probability of severe core damage for
interim reliability evaluation program at facilities.
BERNERD, R.M. Probabilistic Analysis Staff (Pre 801119). 80/07/29
1p 07309 001

0101090745 Submits recommendations re interim reliability evaluation
program & interim action criteria for facilities.
Recommendations include std for corrective action re
potential severe core damage
BERNERD, R.M. Probabilistic Analysis Staff (Pre 801119). 80/07/22
3pp. 07309 001

0101090786 Submits backfit deadlines based on hypothetical interim
acceptable risk numbers.
ROWDSOME, F.H. Probabilistic Analysis Staff (Pre 801119) 80/07/11
9pp. 07309 001.

0101090766 Submits addenda to 800711 memo re backfit deadlines based
upon hypothetical interim acceptable risk numbers.
ROWDSOME, F.H. Probabilistic Analysis Staff (Pre 801119) 80/07/25
2pp. 07309 001.

01000254 Ltr to all licensees (except SEP licensees) forwarding
summary of inservice surveillance requirements for
snubbers under STS License amend application adding model
Tech Specs to App A should be submitted within 120 days
EISENHUT, D.O. Division of Licensing 80/11/20 1p.

010100271 Revised Pages 3/4 7-22 through 28.0 3/4 7-5 & 7-6 & 6-17 to
STS snubber inservice insp requirements
* Division of Licensing 80/11/20 10pp

01020466 Ltr to all power reactor licensees & applicants forwarding
summary of 801112 meeting re implementation of guidance for
Involved Safety Issue A-12. "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D.O. Division of Licensing 80/11/26 6pp

01050167 Forwards "Ofc for Analysis & Evaluation of Operational Data
Actions Re Crystal River 3 Loss of Nonnuclear
Instrumentation & Integrated Control Sys Power on 800226."
response to recommendations will be prepared by 801015.
HICKS, W.J. Office of the Executive Director for Operations.
80/12/11. 1p. 07390 074

01050556 "Ofc for Analysis & Evaluation of Operational Data Actions
Re Crystal River 3 Loss of Nonnuclear Instrumentation &
Integrated Control Sys Power on 800226."
EHNSTEIN, H.L. Director's Office. 80/11/24. 33pp. 07390 075

01050417 Forwards safety evaluation denying until 790523 application
to amend Tech Specs re dc electrical power sys surveillance
requirements
QUAK, T.M. Assistant Director for Operating Reactors. 80/12/11
1pp. 07387 320.

0101030420 Safety evaluation denying until 790523 application to amend
Tech Specs re dc electrical power sys surveillance
requirements.
* Assistant Director for Operating Reactors 80/12/11. 2pp
07389 322

01210445 Forwards responses to questions on Rule 50.71e. "Periodic
padding of FSARs" & FR notice of final rule. SEP plants need
to comply w/rule until program is complete. Non-SEP plants
must comply within specified time frame
EISENHUT, D.O. Division of Licensing 80/12/15 13pp.

01100026 Grants permission to use BUNA-N seal matl in hydraulic
snubbers until next refueling shutdown, in response to until
01219 ltr Seal matl is expected to be replaced w/ethylene
propylene seals during shutdown.
EID, R.W. Operating Reactors Branch 4 80/12/19. 2pp. 07461 223

0101050260 Application for Revision 2 to Tech Spec Change Request
requesting amend to App A of License DPR-72 re emergency
power supply, diverse containment isolation, auxiliary feed
& min shift crew Certificate of Svc encl
BRIGHT, R.M. Florida Power Corp 80/12/31. 4pp. 07389 145

--0101050264 Proposed Revision 2 to Tech Spec Change Request 64
App A of License DPR-72 re emergency power supply, diverse
containment isolation, auto initiation of feedwater, auxiliary
feed flow indication & min shift crew.
* Florida Power Corp 80/12/31 20pp. 07389 149

0101090285 Forwards summary listing of proposed implementation
licensing submittal schedules, in response to NRC 801031 ltr
Drawings on aperture cards in PDR.
GAYNARD, P.Y. Florida Power Corp 80/12/31. 14pp 07379 33

0101070422 Re-requests that Section 3.1 of App B to OL be deleted
Request was based on premise that area was adequately &
appropriately regulated by EPA NPDES & State of FL Dept of
Environment Regulation Permit
BRIGHT, R.M. Florida Power Corp 80/12/31 2pp 07410 331

0101150152 Ack receipt of nuclear safety review task force final
of 800226 event Repl will be compared w/recommendations of
NAREG-0667 & 0737 to identify areas needing improvement
Results of comparison will be provided Jan 1981
EISENHUT, D.O. Division of Licensing 80/12/31 2pp 07463

0 Inspection reports, IE Bulletins & correspondence

0101150024 Requests that until 800722 response to IE Insp Repl
80-302/80-23 be withheld from public disclosure
(ref 10CFR2.790)
BRIGHT, R.M. Florida Power Corp 80/09/22 2pp 07463 004

0101080221 Informs of nonapplicable Page 2-79A transmitted in
ltr responding to IE Bulletin 79-018 re environ
qualification of Class IE equipment Deletion of page
requested.
GAYNARD, P.Y. Florida Power Corp 80/11/17 2pp 07421 360

0101050124 Requests existing data, summaries & records of inserv
tests of containments overgreased prestressing tendons.
ORNL receiving contract to compile & review records of
tendons.
EISENHUT, D.O. Division of Licensing 80/11/29 3pp

0101080052 Forwards safety evaluation re licensee actions taken
response to IE Bulletin 79-13. "Cracking in Feedwater Sys
Piping."
REID, R.W. Operating Reactors Branch 4 80/12/10 2pp 07416 342

--0101080058 Safety evaluation re licensee actions taken in re
IE Bulletin 79-13. "Cracking in Feedwater Sys Piping"
Augmented insps may be discontinued
* Operating Reactors Branch 4 80/12/10 2pp 07416 342

0101150150 Responds to IE Bulletin 80-21 No active valves in u
planned for use in safety-related sys at facility have
valve parts cast by Malcolm Foundry Co. Inc.
GAYNARD, P.Y. Florida Power Corp 80/12/15 1p 07462 172

0101060243 Forwards IE Info Notice 80-44. "Actuation of ECCB i
Recirculation Mode While in Hot Shutdown" No written
response required
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80
1p 07391 349.

0101100015 Provides addl clarification re evaluation of svc co
profiles required by IE Bulletin 79-010 Actual svc
conditions of evaluated equipment were compared w/available
qualification data
GAYNARD, P.Y. Florida Power Corp. 80/12/22 3pp. 07443 33

0101100042 Ack receipt of 800730 & 1022 ltrs informing NRC of
taken to correct violations noted in Health Physics
Appraisal Rept 80-302/80-23
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80
1p 07439 358.

--0101100046 Forwards Health Physics Appraisal Rept 80-302/80-
800616-27, notice of violation & notice of significant
appraisal findings
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
80/09/08. 4pp 07438 001

--0101100048 Notice of violation from insp on 800516-27.
* Region 2, Atlanta, Office of the Director 80/08/05.
07438 005

01011053 IE Health Physics Appraisal Rept 50-302/80-25 on 800616-27
noncompliance noted failure to follow respiratory protection
procedures & failure to perform bioassays & medical
examinations in timely manner
TAMM, M. J. A. P. P. J. J. Region 2, Atlanta, Office of the
Director, OI5504, A. F. Region 2, Atlanta, Fuel Facility &
Materials Safety, Branch 80/08/05 43pp 07438 009

01011052 Forwards response to IE Bulletin 80-24, "Prevention of
Damage Due to Water Leakage Inside Containment (Oct 17, 1980
Insider Point 2 Event) Closed cycle cooling water sys had
leak in reactor coolant Pump 3 oil cooler header inlet
CASHARD, R. A. Florida Power Corp 81/01/02 5pp 07573 352

D Periodic operating reports & related correspondence

01011052 Forwards monthly operating rept for Dec 1980
CASHARD, R. A. Florida Power Corp 81/01/15 1p 07477 174

--01011054 Monthly operating rept for Dec 1980
CULVER, M. W. Florida Power Corp 81/01/05 5pp 07477 175

E Reportable occurrences, LERs & related correspondence

01011053 Forwards LER 80-053/03L-0
HARCOCK, J. A. Florida Power Corp 81/01/05 1p 07442 208

--010109709 LER 80-053/03L-0 on 801208 & 09, containment isolation valve
CAV-3 would not close after sampling pressurizer water
space caused by inadequate closing torque & faulty torque
switch valve stem lubricated Torque switch replaced
HERNANDEZ, V. A. Florida Power Corp 81/01/05 2pp 07442 209

010110514 Forwards LER 80-052/03L-0
HARCOCK, J. A. Florida Power Corp 81/01/05 1p 07442 159

--010109522 LER 80-052/03L-0 on 801208, RCS dose equivalent 1-131
exceeded Tech Spec level caused by leaking fuel pins &
anticipated dose equivalent decline transient following RCS
transient RCS circulated through cleanup & purification sys
HERNANDEZ, V. A. Florida Power Corp 81/01/05 13pp 07442 160

010109590 Forwards LER 80-054/03L-0
HARCOCK, J. A. Florida Power Corp 81/01/06 1p 07442 205

--010109597 LER 80-054/03L-0 on 801210, regulating rod group insertion
limits exceeded caused by anticipated rod movements to
control reactor power burnout Boron added to reactor
coolant
HERNANDEZ, V. A. Florida Power Corp 81/01/06 2pp 07442 206

010110438 Special Rept 80-03 on 801016, during Mode 1 power operation,
fuse in channel P32 blew, actuating ECCS subsystem caused by
failed relay in engineering safeguards cabinet 5B Relay was
replaced & functionally tested
HARCOCK, J. A. POOLE, D. Florida Power Corp 81/01/12 2pp
07472 139

010110556 Forwards LER 80-056/03L-0
HARCOCK, J. A. Florida Power Corp 81/01/12 1p 07471 297

--010110574 LER 80-056/03L-0 on 801219, atmospheric radiation monitor
RM-A5 found inoperable, rendering control complex emergency
ventilation sys inoperable caused by seized sample vacuum
pump due to normal wear spare pump installed & tested
HERNANDEZ, V. A. Florida Power Corp 81/01/12 2pp 07471 298

010110454 Forwards LER 80-055/03L-0
HARCOCK, J. A. Florida Power Corp 81/01/12 1p 07474 055

--010110456 LER 80-055/03L-0 on 801218, load sequence block 3 trip
circuit would not reset following actuation test Cause
isolated to relay 42-27R43 but problem undetermined Relay
reinstalled & surveillance frequency doubled
HERNANDEZ, V. A. Florida Power Corp 81/01/12 2pp 07474 056

010110512 RJ on 801016, Fuse in Channel R32 blew, initiating actuation
of ECCS subsystem Channel 8 during Channel 1 pressure module
test Cause by failed relay in engineering safeguards
cabinet 5B Relay replaced & tested
HARCOCK, J. A. POOLE, D. Florida Power Corp 81/01/12 2pp
07469 279

010110447 Forwards LER 80-057/03L-0
HARCOCK, J. A. Florida Power Corp 81/01/12 1p 07513 034

--0101230455 LER 80-057/03L-0 on 801218, seal matl fabricated
nonapproved matls found installed in approx 13 hydraulic
snubbers caused by failure to identify nonconforming matl
in receiving insp Personnel received training
HERNANDEZ, V. A. Florida Power Corp 81/01/19 2pp 07

010110504 2104 NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

0101090387 Ltr to all licensees of operating reactor plants,
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
810102 & by applicants as part of FSAR
EISENHUT, D. G. Division of Licensing 80/11/13 2pp

0101120535 Advises of provisions of 10CFR50, App R, that are
to fire protection features of facility FR notice & summary
of staff requirements to resolve open items encl
EISENHUT, D. G. Division of Licensing 80/11/24 6pp 07

--0101120542 Advises of typographical error in effective date
ltr correct date of 810217 to be published in FR in near
future
EISENHUT, D. G. Division of Licensing 80/11/25 1p 07

G Adjudicatory correspondence

0101100674 Forwards revised order for mod of license, correct
800829 order Hearing date also revised
EISENHUT, D. G. Division of Licensing 80/09/19 2pp

--0101100680 Revised order amending Licenses DPR-39 & DPR-41
requesting by IE Bulletin 79-018 must be submitted to IE
by 801101
EISENHUT, D. G. Division of Licensing 80/09/19 6pp

H General correspondence

0101100280 Responds to Nov 1980 ltr to President Carter re
structure cracks at facilities No cracks that will leak
radioactivity exist
EISENHUT, D. G. Division of Licensing 81/01/02 5pp 07

J Insurance & indemnity information

0101090608 Forwards guarantee of payment of deferred premium
OSTER, J. Commonwealth Edison Co 81/01/05 1p 07442

0101270737 Forwards Endorsement 4 to Binders EB-1, EB-2, EB-3
EB-30, EB-42 & EB-43 evidencing secondary financial
protection
OSTER, J. Commonwealth Edison Co. 81/01/21 8pp

P Operating license stage documents & correspondence

0101100581 "RELAP4/MOD7 Developmental Checkout Zion," code
checkout rept
DEVONING, T. L. Idaho National Engineering Laboratory, FIN
8101100901 80/05/31 106pp 07445 220

0101100674 Forwards revised order for mod of license, correct
800829 order, Hearing date also revised
EISENHUT, D. G. Division of Licensing 80/09/19 2pp 07

--0101100680 Revised order amending Licenses DPR-39 & DPR-41
requesting by IE Bulletin 79-018 must be submitted to IE
by 801101
EISENHUT, D. G. Division of Licensing 80/09/19 6pp

0101100254 Ltr to all licensees (except SEP licensees) forw
Revision 1 of inservice surveillance requirements for
snubbers under STS License amend application adding model
Tech Specs to App A should be submitted within 120 days
EISENHUT, D. G. Division of Licensing 80/11/20 1p

--0101100271 Revised Pages 3/4 7-22 through 20.B 3/4 7-5 &
BTS snubber inservice insp requirements.
* Division of Licensing 80/11/20 10pp

0101220466 Ltr to all power reactor licensees & applicants
summary of 801112 meeting re implementation of guidance
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D. G. Division of Licensing 80/11/26 8pp

101140849 Requests that util propose Tech Specs changes to require 23 ft of water above reactor vessel flange to assure fuel assemblies could be covered at all times during fuel movement
VARQA.S A Operating Reactors Branch 1 80/12/12 2pp 07461:332

101210445 Forwards responses to questions on Rule 50.71e, "Periodic Updating of FBARs" & FR notice of final rule. SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame
EISENHUT.D G Division of Licensing 80/12/15 13pp

101160523 Forwards review of util evaluation of steady state steam generator operating level for purpose of maximizing drought time w/consideration for overfilling Current operating level is justified.
VARQA.S A Operating Reactors Branch 1 80/12/18 7pp 07472 123

101090715 Responds to 801126 memo re lack of groundwater monitoring program at Facility Map of station & elevations above sea level encl. Monitoring not required unless hydraulic gradient or recharge properties are suitable for contamination.
BIRCKM.J. J. Office of the Executive Director for Operations 80/12/23 23pp. 07430:304

01050500 Forwards response to NUREG-0737. No response provided for Dresden I Unit undergoing extensive mod & decontamination outage Requirements of NUREG-0737 will be addressed prior to startup of unit scheduled for June 1986
ABEL.J.S. Commonwealth Edison Co 80/12/31 53pp

01140673 "Adequacy of Station Electric Distribution Sys Voltages, Zion Station, Unit 2." Informal rept
UDY.A.C. Idaho National Engineering Laboratory FIN A-6296
0101140673 80/12/31 13pp 07461:116

01220631 "Critique of EPS Risk Study for Zion Nuclear Power Plant." Informal rept.
EUSLIK.A.J., BARI.R.A. Brookhaven National Laboratory.
BNL-NUREG-28750. 80/12/31. 60pp. 07499 198

01300318 Forwards Amends 59 & 56 to Licenses DPR-39 & DPR-4B, respectively & notice of issuance & availability
VARQA.S A Operating Reactors Branch 1 80/12/31 3pp 07587 011

0101300328 Amends 59 & 56 to Licenses DPR-39 & DPR-4B, respectively, allowing reinsertion of four fuel assemblies previously irradiated in both units back into Unit 1 to irradiate high burnup fuel for lost cycle
VARQA.S.A Operating Reactors Branch 1. 80/12/31 7pp 07587:014

0101300338 Notice of issuance & availability of Amends 59 & 56 to Licenses DPR-39 & DPR-4B, respectively.
VARQA.S.A Operating Reactors Branch 1 80/12/31 2pp 07587:021

01090001 Forwards Revision 15 pages to CE-1-A-0A program topical rept. Revisions reflect Summer 1980 addenda to Section III of ASME code & recent ASME survey for renewal of ASME corporate certifications.
ABEL.J.S. Commonwealth Edison Co. 81/01/02 1p.

0101090005 Revision 15 pages to 0A program topical rept.
" Commonwealth Edison Co. CE-1-A R19. 81/01/02 57pp.

01090038 Forwards addl info in response to Section 5.1.1 of NUREG-0612. Info supersedes 801107 submittal. Detailed review of other sections of NUREG-0612 will be documented in 6-month rept.
TRAMM.T.R. Commonwealth Edison Co. 81/01/02 17pp. 07441 065.

01270584 Confirms intent to comply w/rept, "Interim Position for Containment Purge & Vent Valve Operation Pending Resolution of Isolation Valve Operability." Submits temporary plan for use when reactor not in refueling or cold shutdown mode
TRAMM.T.R. Commonwealth Edison Co 81/01/14 2pp. 07183.001.

01270617 Supplements util 810114 ltr re plans to use containment purge valves per NRC 791023 guidance. Discusses benefits of conducting containment purging.
TRAMM.T.R. Commonwealth Edison Co. 81/01/14 2pp. 07183.001

01300730 Forwards Amends 60 & 57 to Licenses DPR-39 & DPR-4B, respectively & notice of issuance & availability.
VARQA.S A. Operating Reactors Branch 1. 81/01/14. 3pp. 07583.191.

--8101300752 Amends 60 & 57 to Licenses DPR-39 & DPR-4B, respectively deleting surveillance requirements for valves physically disabled or removed from facility by plant mods from Tech Specs App A
VARQA.S A Operating Reactors Branch 1 81/01/14 12pp 07583 194

--8101300754 Notice of issuance & availability of Amends 60 & 57 to Licenses DPR-39 & DPR-4B, respectively
VARQA.S A Operating Reactors Branch 1 81/01/14 2pp 07583 203

8101290278 Approves util 810114 mod to commitment to interim position re containment purge contingent on listed elements
VARQA.S A Operating Reactors Branch 1 81/01/15 2pp 07575

0101300816 Forwards Amends 61 & 58 to Licenses DPR-39 & DPR-4B, respectively & notice of issuance & availability
VARQA.S A Operating Reactors Branch 1 81/01/15 3pp 07583

--8101300920 Amends 61 & 58 to Licenses DPR-39 & DPR-4B, respectively approving guard training & qualification plan & combining separate license conditions for security plan, safeguards contingency plan & guard training plan
VARQA.S A Operating Reactors Branch 1 81/01/15 4pp 07585 243

--8101300827 Notice of issuance & availability of Amends 61 & 58 to Licenses DPR-39 & DPR-4B, respectively.
VARQA.S A Operating Reactors Branch 1 81/01/15 3pp 07585 247

0101220360 Forwards offsite dose calculation sys description per meteorological data requirements in NUREG-0737 Task III A 2
DELEGEORGE.L.D. Commonwealth Edison Co 81/01/17 1p

--8101220374 "Offsite Dose Calculation Sys Meteorological Monitoring Offsite Dose Calculation Program for Emergency Preparedness at Operating Nuclear Power Plants." Revision 2
GOLDEN.J.C. Commonwealth Edison Co 80/07/31 130pp

--8101220377 "Study of Low Level Dispersion Over Northern IL."
" Murray & Trettel, Inc 74/06/73 106pp

0 Inspection reports, IE Bulletins & correspondence

0101090249 Forwards IE Info Notice 80-30, 'Cracking in Charging Pipe Casing Cladding.' No response required
KEPPLER.J.Q. Region 3, Chicago, Office of the Director 80/10/2pp

0101090462 Forwards IE Bulletin 80-21, 'Valve Yokes Supplied by M. Foundry Co. Inc.' Written response required.
KEPPLER.J.Q. Region 3, Chicago, Office of the Director 80/11/2pp

0101160152 Forwards IE Insp Rept 90-304/80-22 on 801022-23. No noncompliance noted.
HEIGHMAN.R.F. Region 3, Chicago, Reactor Operations Nuclear Sup Branch. 80/11/13 2pp 07469 331

--8101160156 IE Insp Rept 90-304/80-22 on 801022-23. No noncompliance noted. Major areas inspected. Cycle 5 core power distribution limits & control rod worth determination
CHIOULES.N.C. Region 3, Chicago, Office of the Director.
STREETER.J.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/11/13. 4pp. 07469:353

0101090124 Requests existing data, summaries & records of inservice tests of containment w/gressed prestressing tendons.
ORNL receiving contract to compile & review records of tendons.
EISENHUT.D.G. Division of Licensing 80/11/29 3pp

0101140091 Forwards IE Insp Repts 90-295/80-20 & 90-304/80-21 on 801001-1114. No noncompliance noted.
HEIGHMAN.R.F. Region 3, Chicago, Reactor Operations Nuclear Sup Branch. 80/11/28 2pp. 07460.297.

--8101140097 IE Insp Repts 90-295/80-20 & 90-304/80-21 on 801001-1114. No noncompliance noted. Major areas inspected operational safety verification: jumper & lifted lead log & Unit 2 reactor trip.
KOHILER.J.E., WATERG.J.R., REIMANN.F.W. Region 3, Chicago, Office of the Director 80/11/28. 14pp 07460.299

B101050530 Forwards IE Info Notice 80-43. "Failures of Continuous Water Level Monitor for Scan Discharge Val at Dresden Unit 2 " No response required
KEPPLER, J Q Region 3, Chicago, Office of the Director 80/12/05. 2pp

B101150628 Forwards IE Insp Repts 80-295/80-22 & 80-304/80-24 on 801117-19 & notice of violation
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/12/09 2pp 07465 255

--B101150634 Notice of violation from insp on 801117-19
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/12/09 1p 07465 257

--B101150640 IE Insp Repts 80-295/80-22 & 80-304/80-24 on 801117-19 Noncompliance noted corrective actions contained in RAs 80-295/80-45 & 80-295/80-47 & conformity measures
PHILLIPS, M P , JUNUSKA, A Q , PAPERIELLO, C J Region 3, Chicago, Office of the Director 80/12/03 8pp 07465-258

B101070214 Responds to IE Bulletin 80-11. "Masonry Wall Design " Date on previous ltr should read 801016, not 810101
RAUSCH, I J Commonwealth Edison Co 80/12/11 1p 07415 243

B101050073 Responds to IE Bulletin 80-23. "Failures of Bolennoid Valves Mfg by Valcor Engineering Corp " Valves V70903-21-1 or V70903-21-3 not used in any safety-related functions Approx 40 manhours expended in bulletin review
RAUSCH, I J Commonwealth Edison Co 80/12/12. 1p

B101070105 Forwards IE Info Notice 80-44. "Actuation of ECCS in Recirculation Mode While in Hot Shutdown." No written response required.
KEPPLER, J Q Region 3, Chicago, Office of the Director 80/12/16 1p 07415 024

B101080093 Responds to NRC 800818 request for monthly status rept re evaluations in response to IE Bulletin 79-14 Tabulations of piping sys w/stresses above FSAR levels & below operability limit encl
JAMECEA, R F Commonwealth Edison Co. 80/12/22 5pp

B101060283 Forwards IE Insp Repts 80-295/80-23 & 80-304/80-25 on 801117-21 & notice of violation Notice of violation withheld (ref 10CFR2 7901)
HILL, D J A Region 3, Chicago, Safeguards Branch 80/12/23 2pp 07392 027

--B101060290 IE Insp Repts 80-295/80-23 & 80-304/80-25 on 801117-21 Noncompliance noted implementation of security change w/o Commission approval Details withheld (ref 10CFR2 7901)
CHIRISTOFFER, O , PIRTLE, O L Region 3, Chicago, Office of the Director, HIND, J A Region 3, Chicago, Safeguards Branch 80/12/22. 2pp 07392-029

B101200155 Forwards response to IE Bulletin 80-24. "Prevention of Damage Due to Water Leakage Inside Containment (801017 Indian Point 2 Event) " Surveillance procedures of at least monthly repetition will be instituted by 010601
RAUSCH, I J Commonwealth Edison Co. 81/01/09 6pp

B101260675 Ack receipt of 801230 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-295/80-22 & 80-304/80-24
FISHER, W L Region 3, Chicago, Fuel Facility & Materials Safety Branch 81/01/12 1p. 07531:139.

--B101260654 Responds to NRC 801209 ltr re violations noted in IE Insp Repts 80-295/80-22 & 80-304/80-24 Corrective actions. recalibr of all GEL detectors at 1-yr intervals
ABEL, J S. Commonwealth Edison Co 80/12/30 2pp. 07531:160.

6 Replicable occurrences, LERs & related correspondence

B101050340 Forwards LER 80-030/03L-0.
GRAESSER, K L Commonwealth Edison Co. 80/12/24 1p 07385:088.

--B101050345 LER 80-030/03L-0 on 801124, svc water inlet valve. 2NDV-SW0002, failed to stroke to full open position. No cause stated. Valve operator & control circuit repaired
HARWOOD, R Commonwealth Edison Co 80/12/24 1p. 07385:089

B101130550 Forwards LER 80-032/03L-0.
GRAESSER, K L Commonwealth Edison Co 81/01/07 1p. 07454:154

--B101130559 LER 80-032/03L-0 on 801208, during PT-1 rod cluster exercise, rod urgent alarm received Caused by faulty card in rod control logic cabinet Card replaced
KOWAR, K H Commonwealth Edison Co 81/01/07 1p. 07454:157

B101130562 Forwards LER 80-031/03L-0.
GRAESSER, K L Commonwealth Edison Co 81/01/08. 1p. 07454 169

--B101130571 LER 80-031/03L-0 on 801209, engine tripped after running unloaded for 3 minutes, placing auxiliary power sys in degraded mode Caused by loose overspeed trip level C-B part JS-72-22A actuating master shutdown valve.
KRAWCZAK, A T Commonwealth Edison Co. 81/01/08 1p. 07454 170

V Operator Examinations

B101140471 Requests that JK Jousten be re-examined for senior operator license during wk of 810112
GRAESSER, K L Commonwealth Edison Co 80/12/01. 1p. 07461:345

DOCKET 80-305 WEAUWNEE NUCLEAR POWER PLANT

F Security, medical, emergency & fire protection plans

B101090387 ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FOAR.
EISENHUT, D Q. Division of Licensing. 80/11/13 2pp.

B101140841 Advises of provisions of 10CFR50, App R, that are applicable to fire protection features of facility. FR notice & summary of staff requirements to resolve open items encl. No open items for facility W/o encl.
EISENHUT, D. Q. Division of Licensing. 80/11/24 3pp 07461:006

B101290256 Forwards comments re 800924 security guard training & qualification manual. Requests response within 30 days. Further revisions & addl info are necessary. Comments withheld (ref 10CFR2 7901).
VARQA, B A Operating Reactors Branch 1. 81/01/06. 2pp 07373 021

B101210315 Notification of B10115 meeting w/util in Bethesda, MD to discuss facility contingency plan Meeting closed to public.
LICCIARDO, R A. Operating Reactors Branch 1. 81/01/09. 2pp. 07488:229.

B101270947 Notification of B10109 closed meeting w/util in Bethesda, MD re facility contingency plan.
LICCIARDO, R A Operating Reactors Branch 1. 81/01/09. 2pp. 07549:193

Q Adjudicatory correspondence

B101100700 Forwards revised order for mod of license, correcting refs 800829 order. Hearing date also revised.
EISENHUT, D. Q. Division of Licensing. 80/09/19. 2pp. 07443:187

--B101100706 Revised order amending License DPR-43. Info requested by Bulletin 79-01B must be submitted to IE by 801101.
EISENHUT, D Q. Division of Licensing. 80/09/19. 6pp. 07443 189

I Financial information

B101220355 Forwards cash flow for 1979 & cash flow projections for 1980 & 1981 per 10CFR140.21 requirements
MATHENS, E R Wisconsin Public Service Corp. 81/01/13. 2pp. 07496:336

J Insurance & indemnity information

B101210341 Forwards Endorsement 4 to NELIA Policy EB-44 & Endorsement 50 & 51 to NELIA Policy NF-204.
MATHENS, E R. Wisconsin Public Service Corp. 81/01/12. 5pp. 07487:225.

P. Operating license stage documents & correspondence

B101100700 Forwards revised order for mod of license, correcting refs 800829 order. Hearing date also revised.
EISENHUT, D. Q. Division of Licensing. 80/09/19. 2pp. 07443:187

--B101100706 Revised order amending License DPR-43. Info requested by Bulletin 79-01B must be submitted to IE by 801101.
EISENHUT, D. Q. Division of Licensing. 80/09/19. 6pp. 07443:189

8101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under STS license amend application adding model Tech Specs to App A should be submitted within 120 days. EISENHUT, D O Division of Licensing 80/11/20 1p.

--8101100271 Revised Pages 3/4 7-22 through 2B.B 3/4 7-5 & 7-6 & 6-17 to STS snubber inservice insp requirements
• Division of Licensing 80/11/20 10pp

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." EISENHUT, D O Division of Licensing 80/11/26 Bpp.

8101210445 Forwards responses to questions on Rule 50.71e, "Periodic Updating of FBARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete. Non-SEP plants must comply within specified time frame. EISENHUT, D O Division of Licensing 80/12/19 13pp.

8101050047 Confirms 801223 conversation re submittal of response to NUREG-0737 on 810105
SCHROCK, C A Wisconsin Public Service Corp. 80/12/23 1p
07385: 276

8101100388 Responds to 791210 ltr & forwards request for addl info re long-term operability of containment purge & vent valves
VARQA, S A Operating Reactors Branch 1. 80/12/23 9pp. 07464: 277.

8101090329 Forwards responses to NUREG-0737 re post-TMI requirements. Util will meet most implementation dates specified in NUREG-0737. Other dates cannot be committed to w/o evaluating full impact of proposed mods.
MATHEWS, E. R. Wisconsin Public Service Corp. 81/01/03. 64pp.
07429: 277.

8101220034 Forwards info in response to NRC 801014 ltr. Four overseas drawings encl. Aperture cards in PDR
MATHEWS, E. R. Wisconsin Public Service Corp. 81/01/16. 3pp
07500: 019.

8101260379 Requests Tech Specs revision to provide maint for boric acid transfer pumps. Class II amend payment encl.
MATHEWS, E. R. Wisconsin Public Service Corp. 81/01/20. 2pp.
07531: 180.

8101270625 Confirms 810109 telcon re high range radiation monitoring of auxiliary & shield bldg vents. Util implementing mod routing radioactive liquids back to containment. Monitoring & reroute sys scheduled for completion by 811001.
MATHEWS, E. R. Wisconsin Public Service Corp. 81/01/20 3pp.
07548: 100.

3 Inspection reports, IE Bulletins & correspondence

8101100202 Forwards IE Insp Rept 50-305/80-20 on 800901-30. No noncompliance noted
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/10/29. 2pp. 07437: 326

--8101100209 IE Insp Rept 50-305/80-20 on 800901-30. No noncompliance noted. Major areas inspected. Operational safety verification, monthly maint observation & monthly surveillance observation.
MELBON, R. L., FITZPATRICK, B. E., WERNICK, R. F. Region 3, Chicago, Office of the Director. 80/10/28. 6pp. 07437: 328.

8101050232 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/10/30. 2pp. 07389: 088

8101060650 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response is required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/10/31. 1p. 07392: 186.

8101100795 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators." No written response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/10/31. 2pp. 07444: 108

8101060703 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/11/06. 2pp. 07400: 257.

8101090441 Forwards IE Info Notice 80-40, "Excessive Nitrogen Pressure Actuates Safety-Relief Valve Operation to Cause Reactor Depressurization." No written response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/10/29. 2pp. 07442: 146.

8101060381 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/10/29. 2pp. 07391: 079.

8101080355 Forwards IE Insp Rept 50-305/80-23 on 800818-29.0904-05 & notice of violation.
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/10/31. 2pp. 07421: 328

--8101080361 Notice of violation from insp on 800818-29.0904-05 & Region 3, Chicago, Office of the Director. 80/10/31. 4pp. 07421: 330.

--8101080375 IE Insp Rept 50-305 /80-23 on 800818-29.0904-05 & Noncompliance noted. Failure to follow procedures on calibr & surveillance & failure to establish record control accessibility.
BAKER, K. R., JACKIN, I. N., SCHULZ, R. D. Region 3, Chicago, Office of the Director. 80/10/31. 23pp. 07421: 334.

--8101080375 IE Insp Rept 50-305 /80-23 on 800818-22.25-29.0904-05 & Noncompliance noted. Failure to follow procedures on calibr & surveillance & failure to establish record control accessibility.
BAKER, K. R. Region 3, Chicago, Reactor Construction & Engineering Support Branch. GILDER, M. L. Region 3, Chicago, Office of the Director. 80/10/31. 23pp.

8101060505 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Written response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/10/29. 2pp. 07391: 232.

8101070260 Forwards list identifying security badge number & clearance level for Region 3 personnel. Badge numbers for personnel identified by asterisks will be provided at later date.
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/10/29. 6pp. 07410: 359.

8101100524 Forwards IE Insp Rept 50-305/80-21 on 801001-31. No noncompliance noted.
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/11/29. 2pp. 07461: 142.

--8101100531 IE Insp Rept 50-305/80-21 on 801001-31. No noncompliance noted. Major areas inspected. Operational safety verification, monthly maint observation & headquarters requests followup.
MELBON, R. L., FITZPATRICK, B. E., WERNICK, R. F. Region 3, Chicago, Office of the Director. 80/11/21. 9pp. 07461: 144

8101050974 Forwards IE Info Notice 80-43, "Failures of Continuous Level Monitor for Scream Discharge Vol at Dresden Unit 2." No response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/10/29. 2pp. 07386: 045.

8101070650 Responds to IE Bulletin 80-21. No Malcolm Foundry Co parts found at facility.
MATHEWS, E. R. Wisconsin Public Service Corp. 80/12/11. 1p. 07415: 276

8101100188 Forwards IE Insp Rept 50-305/80-27 on 801120 NRC pre results of licensee performance evaluation.
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/10/31. 2pp. 07443: 032.

--8101100193 IE Insp Rept 50-305/80-27 re 801120 mgt meeting & regulatory performance of activities at facility. Encl licensee performance evaluation was presented. Performance found adequate.
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/12/09. 11pp. 07443: 034.

8101070098 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown." No written response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/10/31. 2pp. 07415: 030.

810120315 Responds to IE Bulletin 80-23. "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." No Valcor valves are used at facility.
MATHEWS, E. R. Wisconsin Public Service Corp. 81/01/02 1p
07468 232

8101220389 Responds to IE Bulletin 80-24. "Prevention of Damage Due to Water Leakage Inside Containment." Design change in progress to install differential pressure instrumentation on fan coil units, providing aid in leakage detection.
MATHEWS, E. R. Wisconsin Public Service Corp. 81/01/08 3pp
07500 263

8101220110 Act receipt of 801111 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-305/80-19.
DAVIS, A. B. Region 3, Chicago, Fuel Facility & Materials Safety Branch 81/01/09 1p 07501 360

--8101220114 Responds to NRC 801021 ltr re violations noted in IE Insp Rept 50-305/80-19. Corrective actions addl training for key personnel initiated & emergency preparedness upgraded.
MATHEWS, E. R. Wisconsin Public Service Corp. 80/11/11 2pp.
07501:361

8101300560 Act receipt of 810107 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-305/80-25. Response inadequate Encl withheld (ref 10CFR2 7901).
HIND, J. A. Region 3, Chicago, Safeguards Branch 81/01/21. 2pp
07586 321

--8101300563 Responds to NRC 801212 ltr re violations noted in IE Insp Rept 50-305/80-25. Corrective actions withheld (ref 10CFR2 7901).
MATHEWS, E. R. Wisconsin Public Service Corp. 81/01/07 1p.
07586 323

R. Periodic operating reports & related correspondence

8101130586 Forwards monthly operating rept for Dec 1980
MATHEWS, E. R. Wisconsin Public Service Corp. 81/01/08 1p
07493 272.

--8101130591 Monthly operating rept for Dec 1980
RUTLER, G. H. Wisconsin Public Service Corp. 81/01/02 4pp
07493 273.

S Reportable occurrences, LERs & related correspondence

8101090708 Part 21 rept re fire & bullet resistant doors which may not be in compliance w/applicable requirements. Util seeking labeling &/or specific assurance & proof of fire resistance from manufacturer Exhibits A-H withheld (ref 10CFR2 7901).
MATHEWS, E. R. Wisconsin Public Service Corp. 80/11/20 4pp.
07517 046

8101060555 Forwards LER 80-041/017-0
MATHEWS, E. R. Wisconsin Public Service Corp. 80/12/30 1p
07391:112

--8101060574 LER 80-041/017-0 on 801216, IE Bulletin 79-018 insp revealed three unsealed limit switches subj to failure in submerged condition. Caused by changed requirements since installation. Limit switches will be sealed.
SMOKER, C. S. Wisconsin Public Service Corp. 80/12/30 1p
07391 113

8101130435 Forwards LER 80-042/03L-0
MATHEWS, E. R. Wisconsin Public Service Corp. 81/01/09. 1p.
07494:096

--8101130440 LER 80-042/03L-0 on 801212, during 18 diesel generator testing, air start motors failed to disengage after generator startup & shutdown. Caused by valve stem & disc corrosion. Corroded parts replaced & generator returned to svc.
SMOKER, C. S. Wisconsin Public Service Corp. 81/01/09 1p
07454:097.

8101280518 Forwards LER 80-043/03L-0 & updated LERs 80-042/03K-1 & 80-041/01X-1.
MATHEWS, E. R. Wisconsin Public Service Corp. 81/01/21. 1p.
07597:198

--8101280522 LER 80-043/03L-0 on 801223, boric acid transfer pump motor 1A tripped on overload. Caused by seal degradation from boric acid crystallization in seals during non-use. Pump restarted.
SMOKER, C. S. Wisconsin Public Service Corp. 81/01/22 1p
07597:199

--8101280528 Updated LER 80-042/03X-1 on 801212, diesel generator 1A start motors failed to disengage. Caused by corrosion of valve stem & disc causing valve to stick open. Corroded parts replaced.
SMOKER, C. S. Wisconsin Public Service Corp. 81/01/22 1p
07597 200

--8101280535 Updated LER 80-041/01X-1 on 801216. During IE Bulletin 79-018, identified three limit switches not sealed, therefore susceptible to failure when submerged. Caused by judgement error during installation. Switches to be sealed.
SMOKER, C. S. Wisconsin Public Service Corp. 81/01/22. 1p
07597 201.

DOCKEY 50-306 FRAIRIE ISLAND NUCLEAR STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8101090957 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of F8A9.
EISENHUT, D. Q. Division of Licensing 80/11/13 2pp.

8101130124 Advises of provisions of 10CFR50, App R, that are applicable to fire protection features of facility. FH notice & summary of staff requirements to resolve open items encl.
EISENHUT, D. Q. Division of Licensing 80/11/24 4pp. 07449:237

8101080249 Releases public version of "Evacuation Time Estimates From Areas Near Prairie Island Nuclear Generating Plant."
FELTON, J. M. Division of Rules and Records 80/12/01. 1p
07422 036

--8101080258 Forwards public version of "Evacuation Time Estimates From Areas Near Prairie Island Nuclear Generating Plant."
Revision 1
MAYER, L. O. Northern States Power Co. 80/08/29. 1p. 07422 037

--8101080266 Revision 1 of "Evacuation Time Estimates From Areas Near Prairie Island Nuclear Generating Plant."
Northern States Power Co. 80/08/29. 18pp 07422:039

8101060194 Notification of 801112 meeting w/util re draft emergency plan. Trip rept encl.
MARTIN, R. E. Operating Reactors Branch 3 80/12/15 2pp.
07371 304

--8101060204 Trip rept of 801115 visit to site re current reviews of draft emergency plans.
AXELSON, W. L., PAGLIARD, J. A. Office of Inspection & Enforcement Office of the Director 80/12/11. 2pp. 07391:306

8101220176 Forwards Chemical Engineering Branch fire protection eval for facilities. Proposed mods to fire barrier penetration seals, structural member coating & fire dampers are acceptable. Review status encl.
CLARK, R. A. Operating Reactors Branch 3. 80/12/29. 8pp. 07509

8101300122 Forwards facility emergency planning info for placement LPDR 4/c 8101080283
SOUDER, J. L. Division of Rules and Records. 81/01/19. 1p.
07593:094

H. General correspondence

8101100336 Responds to 801021 ltr requesting info re facilities info requested, except for security, can be inspected at PDR in Minneapolis, MN.
IPPOLITO, T. A. Operating Reactors Branch 2. 80/11/17. 2pp.
07309:001

8101290659 Responds to 801203 request for info re emergency preparedness near facilities, for response to D Carlson 801101 concerns FEMA working w/state & local govts to assure that planning & preparedness are completed.
DIRKSW, W. J. Office of the Executive Director for Operations. 81/01/02 1p. 07576:141

--8101290667 Forwards D Carlson 801101 ltr re emergency planning of facilities. Requests response.
PRXMIERE, W. Senate 80/12/03. 3pp. 07576:142.

P Operating license stage documents & correspondence

B101100254 Ltr to all licensees (except BEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under BTB license amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT, D O Division of Licensing 80/11/20 1p

--B101100271 Revised Pages 3/4 7-22 through 2B, 3/4 7-5 & 7-6 & 6-17 to BTB snubber inservice insp requirements
* Division of Licensing 80/11/20 10pp

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

B101210445 Forwards responses to questions on Rule 50.71c, "Periodic Updating of FBARs" & FR notice of final rule. BEP plants need not comply w/rule until program is complete. Non-BEP plants must comply within specified time frame
EISENHUT, D O Division of Licensing 80/12/15 13pp

B101120051 Forwards Amends 44 & 3B to Licenses DPR-42 & DPR-60, respectively, safety evaluation & notice of issuance & availability.
CLARK, R Operating Reactors Branch 3 80/12/17 2pp 07445.390

--B101120056 Amends 44 & 3B to Licenses DPR-42 & DPR-60, respectively, revising common station Tech Specs re current logic for actuation of safety injection & limits for control rods & power distribution
CLARK, R Operating Reactors Branch 3 80/12/17 29pp 07445.392

--B101120057 Safety evaluation supporting Amends 44 & 3B to Licenses DPR-42 & DPR-60, respectively
* Office of Nuclear Reactor Regulation, Director. 80/12/17 5pp 07446.017

--B101120062 Notice of issuance & availability of Amends 44 & 3B to Licenses DPR-42 & DPR-60, respectively
CLARK, R Operating Reactors Branch 3 80/12/17 2pp 07446.024

B101090266 Forwards commitments to hardware, procedural & organizational implementation requirements of NUREG-0737 Implementation dependent on equipment availability & firm regulatory position
MAYER, L O Northern States Power Co 80/12/30 36pp. 0737B.282

B101160445 Forwards supplemental info re B00131 license amend request, in response to Auxiliary Sys Branch Questions 1.3, 4 & 6 & Structural Engineering Branch Questions 1.2 & 5.
MAYER, L O Northern States Power Co. 81/01/14 13pp. 07472.009

B101200241 Forwards rpt of ECCB outages, 1976-80, per NUREG-0737, Item 11.K.3.17 ECCB outage frequency does not constitute excessive unavailability. No Tech Spec changes are warranted.
MAYER, L O Northern States Power Co. 81/01/16 2pp. 07486.226

Q Inspection reports, IE Bulletins & correspondence

B101090266 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No response required.
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/10/30. 2pp. 07389.16B

B101100776 Forwards IE Circular 80-23, "Potential Defects in Detroit Power Sys Emergency Generators." No written response required.
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/10/31. 2pp. 07444.119

B101060609 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety-Relief Valve Operation to Cause Reactor Depressurization." No written response required.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/07 2pp. 07401.116

B101060367 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/11/10 2pp. 07391.067

B101050565 Forwards IE Info Notice 80-43, "Failures of Continuous Level Monitor for Steam Discharge Vol at Dresden Unit 2." No response required.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/2pp. 07390.337

B101070212 Responds to IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches." Technical problem has prevented rewiring of indicating lights for switches to show total circuit continuity.
OILBERTS, D E Northern States Power Co 80/12/11 1p 07415

B101070082 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown." No written response required.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/1p 07415.044

B101270567 Forwards IE Insp Repts 50-282/80-18 & 50-306/80-18 on B01119-20 No noncompliance noted.
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Safety Branch. 80/12/18. 2pp 07571.301

--B101290573 IE Insp Repts 50-282/80-18 & 50-306/80-18 on B01119-20 noncompliance noted. Major areas inspected control rod drive & position indicator checks, core distribution limits & reactor shutdown margin determination.
CHOLEB, N C, ROBINSON, D L, STREETER, J F Region 3, Chicago, Office of the Director 80/12/11 3pp. 07571.303

B101300276 Forwards IE Insp Repts 50-282/80-19 & 50-306/80-19 on B01001-1130 & notice of deviation.
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Safety Branch. 80/12/19 2pp 07586.229

--B101300294 Notice of deviation from Insp on B01001-1130.
* Region 3, Chicago, Office of the Director 80/12/17 1p 07586.231

--B101300308 IE Insp Repts 50-282/80-19 & 50-306/80-19 on B01001-1130 Noncompliance noted change to impose initial conditions on maintenance procedures per IE Bulletin 80-12 not incorporated as committed.
FEIERABEND, C, BURGES, B L, LITTLE, W G Region 3, Chicago, Office of the Director 80/12/17 12pp. 07586.232

B101160306 Ack receipt of B01210 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-282/80-17 & 50-306/80-17.
HIND, J A Region 3, Chicago, Safeguards Branch. 80/12/22 1p 07470.340

--B101160392 Responds to NRC B01118 ltr re violations noted in IE Insp Repts 50-282/80-17 & 50-306/80-17 Corrective actions withheld (ref 10CFR2.790).
OILBERTS, D E Northern States Power Co 80/12/10. 1p 07470.361

B101200145 Responds to IE Bulletin 80-24, "Prevention of Damage to Water Leakage Inside Containment (B01017 Indian Point 2 Event)." Procedures for detecting leakage are part of post-accident monitoring instrument monthly check.
OILBERTS, D E Northern States Power Co. 81/01/09 8pp. 074

B101220398 Advises that util will be unable to meet schedule to implement mode re IE Bulletin 80-11, "Masonry Wall Design" by B01119. Full implementation of mode scheduled for completion by B10331.
OILBERTS, D E Northern States Power Co 81/01/08 2pp. 075

R Periodic operating reports & related correspondence

B101120294 Forwards monthly operating repts for Dec 1980
MAYER, L O Northern States Power Co 81/01/07 1p 07442.3

--B101120297 Monthly operating repts for Dec 1980
HUNSTAD, A A Northern States Power Co 81/01/02 8pp. 07442.347

DOCKET 50-309 MAINE YANKEE ATOMIC POWER PLANT

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP h & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR.
EISENHUT, D O Division of Licensing 80/11/13 2pp

B010130132 Advises of provisions of 10CFR50, App R, that are applicable to fire protection features of facility FR notice & summary of staff requirements to resolve open items encl.
EISENHUT, D G Division of Licensing 80/11/24 4pp 07308 001

B010705980 Releases public version of util draft emergency plan
FELTON, J M Division of Rules and Records 80/12/03 1p.
07404 210

--B01070584 Forwards public version of draft util emergency plan, Vol 2, in response to NRC 791030 ltr
CHOICE, R H Maine Yankee Atomic Power Co 80/01/31 1p
07404 211

--B01070591 Public version of draft emergency plan, Vol 2
* Maine Yankee Atomic Power Co 80/01/30 77pp 07404 212

B011160610 Informs that review of emergency plan submittal indicates encl addl info necessary before program can meet criteria in NUREG-0654. Revision 1 Revised plan must be submitted
CLARK, R A Operating Reactors Branch 3 80/12/17 27pp
07471 344

B011140315 Requests that encl facility planning info be made publicly available w/o encl
SECURE, J L Division of Rules and Records 80/12/31 1p
07309 001

B011290167 Forwards facility emergency planning info to be made publicly available. W/o encl
SECURE, J L Division of Rules and Records 81/01/23 1p
07575 201

B011300542 Responds to NRC B01224 ltr requesting info on implementation of emergency preparedness exercise requirement. Exercise has been scheduled for B01025
GARRITY, J H Maine Yankee Atomic Power Co 81/01/26 1p
07584 051

G Adjudicatory correspondence

B01090051 Order granting Sensible Maine Power motion for second FR notice of opportunity for hearing due to B00929 license amend application increasing spent fuel storage capacity
AQUO, R M Atomic Safety and Licensing Board Panel 81/01/06 2pp
07426 358

B011290212 Responds to B01204 ltr on behalf of Sensible ME Power, re published remarks by NRC official in support of long-term storage plan at facility Position reflects generic issue documented in NUREG-0575
BENTON, H R Office of Nuclear Reactor Regulation, Director 81/01/13 1p 07309 001

B011280105 Forwards supplemental notice of proposed issuance of amend to facility OL to be published in FR on B01028 per ASLB
B010106 order
MCURREN, H J Hearing Branch 1 81/01/26 1p 07556 084

--B011280114 Supplemental notice of proposed issuance of amend to facility OL, revising Tech Specs to permit expansion of spent fuel storage capacity
CLARK, R A Operating Reactors Branch 3 81/01/13 6pp.
07556 085

H General correspondence

B011120213 Forwards NUREG-0575 for use in committee work w/o encl
REQUA, O Operating Reactors Branch 3 80/12/03 1p. 07446 225.

B011300198 Responds to B01201 ltr re E & R Miller B01110 ltr. EIA will be prepared to consider util proposal to replace existing spent fuel storage racks w/greater strength racks to provide closer storage spacing for increased storage capacity
DIRCKB, W J Office of the Executive Director for Operations 81/01/14 2pp 07183 001

--B011300206 Requests briefing matls for response to encl E & R Miller ltr re util application for onsite nuclear waste storage permit
MITCHELL, O J Senate, Environment & Public Works 80/12/01 3pp
07183 001

P Operating license stage documents & correspondence

B011100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under STB License amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT, D G Division of Licensing 80/11/20 1p

--B011100271 Revised Pages 3/4 7-22 through 28.B 3/4 7-5 & 7-6 & 4-1 STB snubber inservice insp requirements
* Division of Licensing 80/11/20 10pp

B011220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D G Division of Licensing 80/11/26 8pp

B011100139 Forwards Page 5 2-2, Figure 5 2-1, omitted from B01201 Amend 50 to License DPR-36
CLARK, R A Operating Reactors Branch 3 80/12/12 4pp. 07441 3

B01210445 Forwards responses to questions on Rule 50.71e, "Periodic Updating of FBARs" & FR notice of final rule. SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame.
EISENHUT, D G Division of Licensing 80/12/15 13pp

B011140458 Forwards request for addl info re operational QA program
CLARK, R A Operating Reactors Branch 3 80/12/18 7pp. 07461 3

B01060320 Responds to CG Eisenhut B01031 ltr re containment pressure setpoint Setpoint considered adequate. No changes planned.
RANDAZZA, J B Maine Yankee Atomic Power Co 80/12/22 2pp
07399 029

B01300837 "Adequacy of Station Electric Distribution Sys Voltages, Maine Yankee Atomic Power Station," informal rept.
UDY, A C EG&G Idaho, Inc. FIN A-6256 B01300837 80/12/31 15pp 07584 093

B011120210 Forwards ECCB outage rept in response to B01031 ltr to all licensees of operating plants.
RANDAZZA, J B Maine Yankee Atomic Power Co 81/01/07 4pp
07448 256

B011220340 Forwards info re iodine release during nuclear reactor accidents & realistic estimates of reactor accident consequences
GARRITY, J H Maine Yankee Atomic Power Co 81/01/16 3pp
07183 001.

--B011220346 "Realistic Estimates of Consequences of Nuclear Accidents" presented at B01120 AMS conference in Washington, DC.
LEVENSON, M. RAHW, F. Electric Power Research Institute 80/11/30pp 07183 001

B011270368 Responds to NRC B01208 request for addl info re evaluation of radiological aspects of B00929 submittal re spent fuel pin storage. Methods described will allow ALARA objective to be met & minimize need for scarce disposable resources.
GARRITY, J H Maine Yankee Atomic Power Co 81/01/16 5pp
07643 083

B011270667 Responds to NRC position that alternative scheme to mitigate effects of grid degradation fails to comply w/NRC generic position Tech Spec changes re conditions for operation will not provide meaningful enhancement of safety.
CHOICE, R H Maine Yankee Atomic Power Co 81/01/20 4pp.
07349 025.

B011270748 Submits rept on overall safety effect of power operated relief valve isolation sys per B01031 request. Concludes that automatic isolation of power operated relief valves are not necessary & may not be in interest of improved safety.
RANDAZZA, J B Maine Yankee Atomic Power Co 81/01/20 2pp.
07545 305

Q Inspection reports, IE Bulletins & correspondence

B011300026 Forwards IE Insp Rept 80-309/80-14 on B00902-1003 No noncompliance noted
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/11/07 2pp 07582 209.

--B0101300020 IE Insp Rept 50-309/80-14 on B00902-1003 Noncompliance noted Major areas inspected control room, turbine bldg, primary auxiliary bldg, spray bldg & auxiliary feed pump room & followup of IE Bulletin 79-018
MARTIN, T. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch LAZARUS, W. SWETLAND, P. Region 1, Philadelphia, Office of the Director. 80/10/22 14pp 07582 211

B0101060885 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/11/26 1p. 07396 348.

B0101300083 Responds to IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp. " No subj valves used in safety-related functions at facility
RANDAZZA, J. B. Maine Yankee Atomic Power Co 80/12/03 2pp 07579 330

B0101060860 Forwards IE Info Notice 80-44, "Actuation of ECCB in Recirculation Mode While in Hot Shutdown " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director. 80/12/16 1p. 07396 358

B01160101 Ack receipt of B01104 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-309/80-12
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/17 1p. 07469 305.

--B01160114 Responds to NRC B01015 ltr re violations noted in IE Insp Rept 50-309/80-12 Corrective actions surveillance program for nonsafety-related instruments established to monitor limiting conditions.
RANDAZZA, J B Maine Yankee Atomic Power Co. 80/11/04. 2pp. 07469 306

--B01160123 Forwards IE Insp Rept 50-309/80-12 on B00825-29 & notice of violation.
BRUNNER, E J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/10/15 2pp 07469 308

--B01160132 Notice of violation from insp on B00825-29.
* Region 1, Philadelphia, Office of the Director. 80/10/10 1p 07469 310.

--B01160145 IE Insp Rept 50-309/80-12 on B00825-29 Noncompliance noted failure to review & approve documents used for verification of safety-related parameters
BLUMBERG, N. Region 1, Philadelphia, Office of the Director
GREENMAN, E. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/10/10. 12pp. 07469 311

R Periodic operating reports & related correspondence

B01290302 Forwards "Discharge Monitoring Rept, Dec 1980."
GARRITY, J H Maine Yankee Atomic Power Co 81/01/26. 2pp. 07308 001.

--B01290308 "Discharge Monitoring Rept, Dec 1980."
FLANDERS, W. Maine Yankee Atomic Power Co 81/01/26 6pp. 07308 001.

V Operator Examinations

B01120229 Forwards "Shift Technical Advisor Program," per 80 Eisenhower B01031 ltr & NUREG-0737, "Clarification of Post-TMI-2 Requirements."
RANDAZZA, J. B. Maine Yankee Atomic Power Co. 81/01/08 4pp. 07437 347

--B01120233 "Shift Technical Advisor Program: Maine Yankee Atomic Power Co."
* Maine Yankee Atomic Power Co. 81/01/08 6pp. 07437 351.

BOCKET 50-311 SALEM NUCLEAR GENERATING STATION, UNIT 2

E. NRC Safety Evaluation Report (SER), suppl & correspondence

B01090882 Advises that Section 6.2.3.1 of draft Supplemental SER 5 should be examined Facility was granted exemption from requirement of General Design Criteria 57 re closed sys isolation valves.
TEDESCO, R. L. Assistant Director for Licensing. 80/12/17. 1p. 07428 365

B01230298 Forwards NUREG-0517, draft Suppl 5 to SER, proposed OL, T Specs & "Discussion of Environ Effects of U Fuel Cycle Activities Attributable to Operation of Salem Nuclear Generating Station, Unit 2."
DENTON, H R Office of Nuclear Reactor Regulation, Director 80/12/30 1p 07510 033

--B0101230305 DRAFT SUPPLEMENT 5 TO SAFETY EVALUATION REPORT
* Office of Nuclear Reactor Regulation, Director NUREG-0517 85 80/12/29 217pp 07510 034

F. Security, medical, emergency & fire protection plans

B01070551 Releases public version of util revised emergency plan
FELTON, J M Division of Rules and Records 80/11/14 1p 07309 001

--B01070557 Forwards public version of util B00930 revisions to emergency plan
LIBRIZZI, F P Public Service Electric & Gas Co of New Jersey 80/10/03 2pp 07309 001

--B01070562 Public version of revisions to emergency plan
* Public Service Electric & Gas Co of New Jersey 80/09/30 40pp 07309 001.

B01080011 Forwards FR notice of revised Section 10CFR50.48 & App 10CFR50 re fire protection features of nuclear power plants Effective date for Criterion 3 of App A should be 000217 instead of 800219
TEDESCO, R L Assistant Director for Licensing 80/12/04 18p 07309 001

B01070533 Releases public version of revision to util emergency plan
FELTON, J M Division of Rules and Records 80/12/17. 1p 07404 147

--B01070540 Forwards public version of revision to emergency plan in response to NRC request for addl info.
LIBRIZZI, F P Public Service Electric & Gas Co of New Jersey 80/12/03. 1p. 07404 149

--B01070543 Public version of revision to emergency plan
* Public Service Electric & Gas Co of New Jersey 80/12/03 26pp. 07404 154

B01200642 Releases public version of util revised emergency plan
FELTON, J M Division of Rules and Records 81/01/06 1p 07107 001

--B01200644 Forwards public version of revised sections of emergency plan, in response to NRC request for addl info.
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 80/12/19. 1p. 07187 001

--B01290645 Public version of revised sections of emergency plan
* Public Service Electric & Gas Co of New Jersey. 80/12/19 150pp. 07187 001

B01270616 Requests revised ltr from NRC re-evaluating B00712 evacuation study. Lack of coordination of various NRC divs w/ respect to reviewing or issuing ltr re emergency preparedness appears evident.
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 81/01/21. 1p 07549 067

G. Adjudicatory correspondence

B01070410 Requests to make limited appearance statement at licensing hearing.
NOTERMAN, J P Affiliation Unknown. 80/12/27 1p. 07309 001.

J. Insurance & indemnity information

B01210586 Forwards certified Endorsement 3 to NELIA Binder EB-72
CORREA, M A Marsh & McLennan, Inc., M & H Nuclear Consultants, Inc. Div. 81/01/14. 3pp 07489 001

B01270738 Forwards Endorsement 42 to NELIA Policy NF-230 & Endorsement 34 to MAELU Policy MF-90.
CORREA, M A Marsh & McLennan, Inc., M & H Nuclear Consultants, Inc. Div. 81/01/22. 3pp 07548 050.

8101060274 Releases public version of emergency plan manual implementation procedures for facilities
FELTCH, J. M. Division of Rules and Records 80/11/14 1p
07321 095

--8101080259 Forwards public version of emergency plan manual implementation procedures for facilities
LITBRIJZ, F. P. Public Service Electric & Gas Co. of New Jersey
80/10/03 2pp 07421 095

--8101080305 Public version of emergency plan manual implementation procedures, Revision 12
SILVERIO, N. A. STILLMAN, J. L. Public Service Electric & Gas Co. of New Jersey 80/08/18 170pp 07421 098

8101070190 Forwards confirmation that implementation dates in NUREG-0737 will be met, in response to NRC 801031 request
MITTL, R. L. Public Service Electric & Gas Co. of New Jersey 80/12/09 10pp 07414 261

8101060797 Summary of 801120 meeting w/uttl re safety-related masonry walls. No design criteria or QA/QC programs were established for initial const of masonry walls. List of meeting attendees & agenda encl
KERRIGAN, J. Licensing Branch 3. 80/12/11 6pp 07400 106

8101200634 Forwards AEC 680409 ltr. in response to request at 801200 re: hearing for facility. Licensee initiated 790619 meeting w/NRC
ROSS, H. J. Operating Reactors Branch 1. 80/12/22 1p 07476 281

--8101200636 Forwards request for addl info needed to continue review of CP application. Includes info re adequacy of QC & insp procedures, site selection analysis, instrumentation & control info in FBAR & accident analysis
MORRIS, P. A. Atomic Energy Commission, Directorate of Licensing 68/04/09 19pp 07476 282

8101190794 Forwards summary of 801210 meeting w/uttl re util mgt reorganization. List of attendees encl
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 03/12/23 3pp 07473 078

8101230298 Forwards NUREG-0517, draft Suppl 5 to SER, proposed OL Tech Spec & Discussion of Environ Effects of U Fuel Cycle Activities Attributable to Operation of Salem Nuclear Generating Station, Unit 2.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 80/12/30 1p 07510 033

--8101230305 DRAFT SUPPLEMENT 5 TO SAFETY EVALUATION REPORT.
* Office of Nuclear Reactor Regulation, Director NUREG-0517 DRAFT 55 80/12/29 217pp 07510 034

--8101230312 EIB (nonradiological) for facility.
* Office of Nuclear Reactor Regulation, Director 80/12/30 11pp 07510 256

--8101230320 Discussion of Environ Effects of U Fuel Cycle Activities Attributable to Operation of Salem Nuclear Generating Station, Unit 2. Explanatory narrative for Table B-3 encl
* Office of Nuclear Reactor Regulation, Director 80/12/30 93pp 07510 265

8101190586 Forwards request for addl info re masonry walls. Confirms actions util must complete prior to issuance of SER
LEDESCO, R. L. Assistant Director for Licensing 81/01/08 3pp 07472 269

8101180382 Forwards logic diagrams & electrical schematics, per NRC 801208 request. Logic Diagram 239957-B-7646 will be revised to reflect design mod scheduled for completion during next refueling outage. Aperture cards in PDR.
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey 81/01/09 1p 07462 203

8101180635 Forwards verification of previous correspondence as part of OL application
MITTL, R. L. Public Service Electric & Gas Co. of New Jersey 81/01/12 5pp 07462 122

8101150629 Submits info on ECCS outages, per NUREG-0737, Item II, K. 3. 17. Unplanned outages are documented by incident repts. Planned outages are documented in daily log. Failure trends analyzed by review of LER's
MITTL, R. L. Public Service Electric & Gas Co. of New Jersey 81/01/13 1p 07462 121

Westington, CC re full power OL for facility Pr 1-75 Draft Suppl 5 to safety evaluation encl
* Commissioners 81/01/14 77pp 07572 001

--8101290675 Discusses mod of NUREG-0737 requirements for facility full power OL. Facility will be addressed as two units operating as two control rooms after 020701 for senior reactor operator training. Shift training tables encl
HARRAHAN, E. J. Office of Policy Evaluations 81/01/14 3pp 07572 079

8101230441 Advises that overhead annunciator alarm vol has been modified. Results of testing determined that required vol of each annunciator speaker is unacceptably loud. Util proposes to reduce vol of each speaker
MITTL, R. L. Public Service Electric & Gas Co. of New Jersey 81/01/16 2pp 07510 310

Q Inspection reports, IE Bulletins & correspondence

8101090847 Ack receipt of 801017 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-272/80-19 & 80-311/80-14
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/11/07 1p 03893 224

--8101090852 Responds to NRC 800929 ltr re violations noted in IE Insp Repts 80-272/80-19 & 80-311/80-14. Corrective actions "hold" area established for rejected items & reject tags will be attached to deficient items
SCHNEIDER, F. W. Public Service Electric & Gas Co. of New Jersey 80/10/17 5pp 03873 225

--8101090858 Forwards IE Insp Repts 80-272/80-19 & 80-311/80-14 on 800728-0808 & notice of violation
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/27 2pp 03893 230

--8101090863 Notice of violation from Insp on 800728-0808
* Region 1, Philadelphia, Office of the Director 80/09/25 2pp 03893 232

--8101090888 IE Insp Repts 80-272/80-19 & 80-311/80-14 on 800728-0808. Noncompliance noted: Failure to follow procedures for receipt, handling & storage of safety-related mail.
NAPUZA, G. J. SIMONEFFI, G. Region 1, Philadelphia, Office of the Director GREENMAN, E. G. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/25 14pp 03893 234

8101060039 Responds to util 801104 ltr revising response to IE Bulletin 80-11, "Masonry Wall Design" & requesting extension until 801203 to complete detailed analysis of masonry walls at facilities. Extension is acceptable.
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/11/19 1p 07392 214

8101070418 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 80/11/26 1p 07414 047

810100768 Responds to IE Bulletin 80-23, "Failures of Solenoid Valve Mfg by Valcor Engineering Corp." No subj valves used in safety-related function at facilities.
SCHNEIDER, F. W. Public Service Electric & Gas Co. of New Jersey 80/12/12 1p 07443 359

8101060816 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown." No written response required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 80/12/16 1p 07397 045

R Periodic operating reports & related correspondence

8101210435 Forwards monthly operating rept for Dec 1980
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey 81/01/12 1p 07493 156

--8101210458 Monthly operating rept for Dec 1980
MILLER, L. K. Public Service Electric & Gas Co. of New Jersey 81/01/12 8pp 07493 157

transcripts on non-antitrust matters

Unofficial transcript of B10114 public discussion & vote in
ton, DC re full power OL for facility Pp 1-75 Draft
to safety evaluation encl
Commissioners B1/01/14 77pp 07972 001

Discusses mod of NUREG-0737 requirements for facility
power OL Facility will be addressed as two units
ing as two control rooms after B20701 for senior
operator manning Shift manning tables encl.
IAN, E J Office of Policy Evaluations B1/01/14 3pp
079

Examinations

Forwards info requested in NUREG-0737 re shift technical
training program, performance testing of PWR relief &
valves, containment min pressure setpoint &
mentation for detection of inadequate core cooling
L. Public Service Electric & Gas Co of New Jersey.
140pp. 07309 001

Provides addl info re training program to qualify degreed
as senior reactor operator license candidates. In
to NRC B01031 request. Successful licensing of
es will minimize routine overtime. Related info encl.
R. F. H. Public Service Electric & Gas Co of New Jersey.
30pp. 07447 201

312 RANCHO SECO NUCLEAR GENERATING STATION

y, medical, emergency & fire protection plans

Ltr to all licensees of operating reactor plants. CP holders
licants Revised radiological emergency response
et be submitted by licensees within 60 days of
& by applicants as part of FBAN.

D G Division of Licensing 80/11/13 2pp

Releases public version of revision to util draft emergency

M. Division of Rules and Records. 80/12/16 1p

54 Forwards public version of revision to draft emergency plan.
ponse to NRC B01010 request for addl info
DOE, W C Sacramento Municipal Utility District. 80/12/02.
07309: 001

59 Public version of revision to draft emergency plan.
ramento Municipal Utility District 80/11/10 150pp

Informs that licensee must conduct emergency exercise within
from B10401 or prior to issuance of OL Requests
of drills & exercises.
R. H. Region 5, San Francisco. Office of the Director.
1p. 07443: 254

Releases ltr re util compliance w/emergency plan after
info review.

M. Division of Rules and Records. 81/01/08 1p

21 Discusses util compliance w/NRC emergency planning
ements. Emergency plan was originally submitted
. Describes status of state & local govt emergency

, W. K. Sacramento Municipal Utility District. 81/01/02
07495: 196

Forwards facility emergency planning info for placement in
B101070564.

L. Division of Rules and Records 81/01/16. 1p

10.

ing license stage documents & correspondence

Ltr to all licensees (except SEP licensees) forwarding
1 of inservice surveillance requirements for
under STB License amend application adding model
cs to App A should be submitted within 120 days
D. G. Division of Licensing. 80/11/20. 1p.

71 Revised Pages 3/4 7-22 through 38.8 3/4 7-5 & 7-6 & 6-17 to
ubber inservice insp requirements.
ision of Licensing 80/11/20. 10pp.

B101220466 Ltr to all power reactor licensees & applicants forwarding
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issue A-12. "Potential for Low Fracture
Toughness & Laminar Tearing on Component Supports."
EISENHUT, D G Division of Licensing 80/11/26 8pp

B101210445 Forwards responses to questions on Rule 50 71c. "Periodic
Updating of FBARs" & FR notice of final rule SEP plants need
not comply w/rule until program is complete Non-SEP plants
must comply within specified time frame.
EISENHUT, D G Division of Licensing 80/12/15 13pp

B101060946 Submits daily notes for B01223. Status of facilities in five
IE regions encl
DICKER, W J Office of the Executive Director for Operations
80/12/24 3pp 07401 107

B101130303 Advises that util takes exception to necessity of having
classification sys defining specific levels for equipment as
outlined in ANSI N49 2.2 Util program addresses requirements
for packaging based on needs of individual equipment
MATTIMOE, J J Sacramento Municipal Utility District. 81/01/03 1p.
07447: 275

B101270492 Forwards info per B01215 commitments for implementation of
NUREG-0737. "Clarification of TMI Action Plan Requirements"
Includes description of current shift technical advisor
training program & long-term program
MATTIMOE, J J Sacramento Municipal Utility District 81/01/16
6pp 07540 196

G Inspection reports, IE Bulletins & correspondence

B101130675 Forwards IE Info Notice B0-34. "Born Dilution of Reactor
Coolant During Steam Generator Decontamination" No written
response required
ENDELKEN, R H Region 5, San Francisco. Office of the Director
80/09/26 1p 07453 342

B101070656 Responds to IE Bulletin B0-23 No Valcor solenoid valves
mfg by Valcor Engineering Corp found
MATTIMOE, J J Sacramento Municipal Utility District 80/11/24
2pp 07309 001

B101050124 Requests existing data, summaries & records of inservice insp
tests of containments w/greatest prestressing tendons
ORNL receiving contract to compile & review records of
tendons
EISENHUT, D G Division of Licensing 80/11/25 3pp

B101060095 Responds to IE Bulletin B0-21. "Valve Yokes Supplied by
Malcolm Foundry Co. Inc." No Malcolm valve parts used or
planned for use at Facility
WALBRIDGE, W C Sacramento Municipal Utility District 80/12/01
1p 07399 110

B101180140 Forwards Performance Appraisal Branch Mgt Insn Repts
50-219779-18, 50-312/80-15 & 50-289/80-21. IE Performance
Appraisal Branch mgt evaluation tree w/users guide for
chart, list of licensee recipients of rept & sample ltr encl.
CRICK, B H Region 1, Philadelphia. Office of the Director
80/12/02 2pp 07466 020

B101120561 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects
in ABME 8A-312, Type 304 Stainless Steel Pipe" No 8A-312 or
A-312 Type 300 series fusion-welded pipe in use or planned
for use in safety-related sys
MATTIMOE, J J Sacramento Municipal Utility District. 80/12/03 1p.
07447: 196

B101100078 Ack receipt of B01119 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-312/80-26
CREWB, J L Region 5, San Francisco, Reactor Operations Nuclear
Support Branch 80/12/04 1p 07441: 277

--B101100083 Responds to NRC B01107 ltr re violations noted in IE Insp
Rept 50-312/80-26 Corrective actions: air valves SFV 9350J,
SFV53A04 & SFV 93210 will be isolated as required for
bidg integrity.
WALBRIDGE, W C Sacramento Municipal Utility District. 80/11/19
2pp 07441: 278

--B101100086 Ack receipt of B01017 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-312/80-26 Addl
info required.
CREWB, J L Region 5, San Francisco, Reactor Operations Nuclear
Support Branch. 80/11/07. 1p. 07441: 280.

violation
CREWS, J.L. Region 5, San Francisco, Reactor Operations Nuclear
Support Branch 80/09/26 2pp 07441:285

--B101100397 Notice of violation from Insp on 800801-29
* Region 5, San Francisco, Office of the Director. 80/09/25
2pp 07441:287

--B101100103 IE Insp Rept 50-312/80-26 on 800801-29 Noncompliance noted
containment isolation valve design not in accordance
w/DCFR50 App A requirements
CANTER, H.L., D.BRIEN, J. Region 5, San Francisco, Office of the
Director FAULKENBERRY, B. Region 5, San Francisco, Reactor
Operations Nuclear Support Branch 80/09/25 8pp 07441:289

B101030496 Forwards IE Info Notice 80-43, "Failures of Continuous Water
Level Monitor for Steam Discharge Vol at Dresden Unit 2."
No response required
ENDELMEY, R.H. Region 5, San Francisco, Office of the Director
80/12/05 1p 07387:278

B101120553 Suppl response to items 2(i) & 2(d) of IE Bulletin
80-CB, "Elimination of Containment Liner Penetration Welds."
Forwards summary of radiographic test results, for
containment piping penetrations
MATTIMOE, J.J. Sacramento Municipal Utility District. 80/12/05
2pp 07447:189

B101060081 Forwards IE Insp Rept 50-312/80-34 on 801028-1106
CREWS, J.L. Region 5, San Francisco, Reactor Operations Nuclear
Support Branch 80/12/16 2pp 07309:001

--B101060089 IE Insp Rept 50-312/80-34 on 801028-1106 Noncompliance
noted closure of nonperformance repts & monthly repts not
made according to requirements
CANTER, H.L., YOUNG, T., MALMROS, M. Region 5, San Francisco, Office of
the Director 80/12/16 81pp.

B101190827 Forwards IE Info Notice 80-44, "Actuation of ECCB in
Recirculation Mode While in Hot Shutdown." No response
required
ENDELMEY, R.H. Region 5, San Francisco, Office of the Director
80/12/16 1p 07308:001

B101210596 Forwards IE Insp Rept 50-312/80-31 on 801112-19 No
noncompliance noted
CREWS, J.L. Region 5, San Francisco, Reactor Operations Nuclear
Support Branch 80/12/17 2pp 07488:036

--B101210601 IE Insp Rept 50-312/80-31 on 801112-19 No noncompliance
noted Major areas inspected QA program, instrument calibr.
maint program & followup on IE bulletins & circulars
ZWEITIG, G.B. Region 5, San Francisco, Office of the Director
FAULKENBERRY, B. Region 5, San Francisco, Reactor Operations
Nuclear Support Branch. 80/12/16 10pp. 07488:038.

B101100441 Forwards safety evaluation re util 790615, 0727 & 0813
responses to IE Bulletin 79-13, "Cracking in Feedwater Sys
Piping."
REID, R.W. Operating Reactors Branch 4 80/12/24 3pp 07445:063

--B101100449 Safety evaluation re actions taken in response to IE
Bulletin 79-13, "Cracking in Feedwater Sys Piping."
Exemption to bulletin requirements should be granted.
* Operating Reactors Branch 4. 80/12/24. 21pp. 07445:066

B101270523 Forwards response to IE Bulletin 80-24, "Prevention of
Damage Due to Water Leakage Inside Containment (801017
Indian Point 2 Event)." Present liquid level detection sys
provides adequate detection protection
MATTIMOE, J.J. Sacramento Municipal Utility District. 81/01/06.
13pp. 07309:001

B101220303 Forwards Amend 1 to util 801031 response to IE Bulletin
79-01B, "Environ Qualification of Class IE Equipment." Amend
adds info received from vendors since 801101, revises App D &
clarifies basis for interim operation.
MATTIMOE, J.J. Sacramento Municipal Utility District. 81/01/13.
300pp 07494:099

8 Reportable occurrences, LERs & related correspondence

B101120260 Advises that util 790928 ltr re inadvertent
during surveillance testing adequately addresses C
MRC 790921 & 0626 ltr Matter is resolved for facili
REID, R.W. Operating Reactors Branch 4 80/12/19

B101060773 Forwards LER 80-048/03L-0.
MATTIMOE, J.J. Sacramento Municipal Utility District
2pp 07395:027.

--B101060781 LER 80-048/03L-0 on 801201, while review
program & surveillance procedures, two remotely
reactor bldg isolation valves discovered not tes
required by Tech Specs Caused by deletion of qual
* Sacramento Municipal Utility District 80/12/
07395:029

B101130492 Forwards LER 80-047/01T-0.
MATTIMOE, J.J. Sacramento Municipal Utility District
2pp 07454:121

--B101130517 LER 80-047/01T-0 on 801222, IE Bulletin
lack of qualification documentation for flow tra
utilized to establish dilution flow to prevent br
precipitation following LOCA Cause not stated.
COLMBO, R.W. Sacramento Municipal Utility District
1p 07454:123

B101160427 ROs 80-50 & 81-1 re motor starter coils &
reading, respectively. Licensee was informed that fl
Site 3 motor starter coils will not pick up & seal
state during degraded voltage & w/postulated LOCA
DUSRE, R.P. Sacramento Municipal Utility District
07309:001.

B101200221 ROs 80-50 & 81-1, Dechtel advised util the
motor starter coils will not pick up & seal in sta
condition. Second, unrelated occurrence concerns exc
west perimeter TLD monitor reading.
DUSRE, R.P. Sacramento Municipal Utility District
07476:346

B101200281 Forwards LER 80-049/03L-0.
MATTIMOE, J.J. Sacramento Municipal Utility District
2pp 07487:030.

--B101200288 LER 80-049/03L-0 on 801219, during perfo
B diesel generator failed to start Cause not sta
declared operable 801222 after passing applicabl
surveillance test
COLMBO, R.W. Sacramento Municipal Utility District
1p 07487:032

B101230598 Forwards LER 80-050/04T-0.
MATTIMOE, J.J. Sacramento Municipal Utility District
2pp 07512:256.

--B101230602 LER 80-050/04T-0 on 801018, environ TLD
perimeter fence indicated dose rates above Tech
by close proximity to drum storage area. Bulk rad
storage bldg will be constructed.
COLMBO, R.W. Sacramento Municipal Utility District
1p. 07512:258.

B101280297 Forwards LER 81-001/02T-0.
MATTIMOE, J.J. Sacramento Municipal Utility District
2pp. 07308:001.

--B101280302 LER 81-001/02T-0 on 801018, AE notified
control room air conditioner size 3 starter coil
operate at degraded voltage. Caused by design err
mod will be performed during next refueling outa
COLMBO, R.W. Sacramento Municipal Utility District
1p. 07308:001.

DOCKETED ITEMS

Operator Examinations

270492 Forwards info per 801215 commitments for implementation of REG-0737. "Clarification of TMI Action Plan Requirements" includes description of current shift technical advisor training program & long-term program
TRIMBLE, J J Sacramento Municipal Utility District 81/01/16
pp 07540 196

ET 50-313 ARKANSAS NUCLEAR ONE, UNIT 1

security, medical, emergency & fire protection plans

390387 Ltr to all licensees of operating reactor plants, CP holders & P applicants. Revised radiological emergency response info must be submitted by licensees within 60 days of 10CFR2.790 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp 07422 243

370460 Forwards proprietary comments on necessary revisions to & II info, needed re util 800909 revised security training & classification plan. Comments withheld (ref 10CFR2.790)
D, R W Operating Reactors Branch 4 80/12/17 2pp 07415 311

40215 Informs that licensee should conduct emergency exercise within one yr from 800401 or prior to issuance of OL schedule of drills should be provided
FRIT, K V Region 4, Dallas, Office of the Director 80/12/23
07461 256

40595 Forwards response to NRC 801015 ltr requesting info re sponsored vital area analysis of facility info withheld (ref 10CFR2.790).
HUBLE, D C Arkansas Power & Light Co 80/12/31 1p 07427 353

80434 Forwards revisions & proposed changes to industrial security plan. Revisions withheld (ref 10CFR2.790)
HUBLE, D C Arkansas Power & Light Co 81/01/02 2pp 07419 348

00394 Requests that encl facility emergency planning info be made publicly available w/o encl.
DER, J L Division of Rules and Records 81/01/09 1p
06:313

60673 Releases public version of util upgraded emergency plan.
TDM, J M Division of Rules and Records 81/01/16 1p
33:013

1260678 Forwards public version of upgraded emergency plan. Includes state of AR radiological incident response plan & Pope, Johnson, Veil & Logan Counties, AR emergency plans.
TRIMBLE, D C Arkansas Power & Light Co 81/01/02 1p
7533:016

1260683 Public version of upgraded emergency plan. Includes State of AR radiological incident response plan & Pope, Johnson, Veil & Logan Counties, AR emergency plans
Arkansas Power & Light Co 81/01/01 800pp 07533 017

Insurance & indemnity information

70742 Forwards Endorsement CB to NELIA Policy MF-74 & Endorsement to NELIA Policy NF-210.
HUBLE, D C Arkansas Power & Light Co 81/01/21 4pp 07309 001

Operating license stage documents & correspondence

20150 Clarifies intent of plans for position task analysis of several of personnel interview w/personnel in positions. Clear responsibilities will not be complete until 101.
ANAUOH, W Arkansas Power & Light Co 80/11/19 4pp 07446 152

30254 Ltr to all licensees (except SEP licensees) forwarding information of inservice surveillance requirements for operators under BFB. License amend application adding model 1 Spect to App A should be submitted within 120 days.
EISENHUT, D O Division of Licensing 80/11/20 1p 07443 274

1100271 Revised Pages 3/4 7-22 through 28.B 3/4 7-5 & 7-6 & 6-17 to FS snubber inservice insp requirements.
Division of Licensing 80/11/20 10pp 07443 278

8011220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 5pp

801140601 Notifies that Class IV amend fee is required for util 801031 Cycle 5 reload rept.
1808.R M License Fee Management Branch 80/12/08 1p
07462 009

801210445 Forwards responses to questions on Rule 50.71e. "Periodic Updating of FSARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete. Non-SEP plants must comply within specified time frame.
EISENHUT, D O Division of Licensing 80/12/19 13pp 07489 087

801120234 Forwards safety evaluation re final design & implementation of safety-grade anticipatory reactor trip on turbine trip or loss of main feedwater.
REID, R W Operating Reactors Branch 4 80/12/16 2pp 07446 313

--801120239 Safety evaluation re final design & implementation of safety-grade anticipatory reactor trip on turbine trip or loss of main feedwater. Design is acceptable
Operating Reactors Branch 4 80/12/16 5pp 07446 314

801090990 Forwards Amend 49 to License DPR-51, safety evaluation & notice of issuance & availability
REID, R W Operating Reactors Branch 4 80/12/19 2pp 03893 316

--801070953 Amend 49 to License DPR-51, changing power operated relief valve setpoint to 2,450 psig & high pressure reactor trip setpoint to 2,300 psig
REID, R W Operating Reactors Branch 4 80/12/19 10pp
03893 318

--801070956 Safety evaluation supporting Amend 49 to License 51
Office of Nuclear Reactor Regulation, Director 80/12/19 3pp
03893 328

--801090959 Notice of issuance & availability of Amend to License DPR-51
REID, R W Operating Reactors Branch 4 80/12/19 2pp
03893 331

801050418 Advises that NRC 801113 ltr re NUREG-0619, "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking," does not pertain to Facilities Facilities are PHRs. No response action will be taken.
TRIMBLE, D C Arkansas Power & Light Co 80/12/29 1p 07389 324

801050344 Forwards "Thermal-Mechanical Rept Effect of HPI on Vessel Integrity for Break Break LOCA Event W/Extended Loss of Feedwater," in response to NUREG-0737, Item II K 2 13
TRIMBLE, D C Arkansas Power & Light Co 80/12/31 1p 07389 289

801060335 Forwards info re NUREG-0737, in response to NRC 801031 ltr. Includes info re shift technical advisor procedures for transients & accidents, plant shielding & thermal shock rept.
TRIMBLE, D C Arkansas Power & Light Co 80/12/31 9pp 07393 348

801150177 Forwards rept on power operated relief valve opening probability per requirements of NUREG-0737, Items II K 3 2 & II K 3 7
TRIMBLE, D C Arkansas Power & Light Co 81/01/08 17pp
07462 214

801160406 Responds to NUREG-0737, "Reporting Safety Valve & Relief Valve Failures & Challenges." One challenge to electromechanical relief valve occurred at Unit 1 from Apr-Dec 1980. No challenges to primary sys code occurred at Unit 2.
TRIMBLE, D C Arkansas Power & Light Co 81/01/08 1p 07470 167

801200247 Responds to NRC 801208 request for payment for review of licensee 801031 Cycle 5 reload rept. Submittal was preliminary rept Fee will be submitted w/final Cycle 5 reload rept on 80201.
TRIMBLE, D C Arkansas Power & Light Co 81/01/13 1p 07486 228

801230536 Forwards Dames & Moore rept entitled "Task 1 - Analytical Approach, Site-Specific Characteristics at AR Nuclear One." Requests NRC review Rept was formulated as first in series of tasks to assist in implementation of App 2 of NUREG-0654.
TRIMBLE, D C Arkansas Power & Light Co 81/01/13 2pp 07511 16

101010101 Adjudges that Unit 61015 preliminary emergency feedwater upgrade design description is acceptable. Schedule required for add'l design submittals Tech Specs & final implementation.
KELLY, J. A. Assistant Director for Operating Reactors 81/01/15
2pp 07425 271

101010102 Forwards position on recommendations of BAW-1984, "Integrated Control Sys Reliability Analysis," in response to ALE 791127 request.
TRIMBLE, D. C. Arkansas Power & Light Co. 81/01/16 2pp 07495 258

101010103 Forwards revised site specific responses to NRC 800225 questions re Westinghouse low pressure turbine rotor New info results from more sophisticated calculations model. Requests info be withheld (ref 10CFR2 790).
TRIMBLE, D. C. Arkansas Power & Light Co. 81/01/19 1p 07308 001

101010104 Nonproprietary version of "Low Pressure Turbine Disc Info" re Westinghouse Electric Corp. 80/09/22 21pp 07363 001

101010105 Requests clarification of position re Items [I B 1 & I B 4 to 4-10-7377 re reactor coolant sys vents & training for mitigating core damage.
TRIMBLE, D. C. Arkansas Power & Light Co. 81/01/19 3pp 07543 090

2. Inspection reports, IE Bulletins & correspondence

101010106 Responds to IE Bulletin 79-17 re pipe cracks in stagnated torated later sys at PWRs. Cracks discovered in heat affected zones of three welds in reactor oldg spray sys on 800121.
TRIMBLE, D. C. Arkansas Power & Light Co. 80/11/11 4pp 07446 162

81/01/217 Forwards IE Insp Repts 50-313/80-21 & 50-368/80-21 on 800922-1021 & notice of violation.
MAIDEN, G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/11/19 2pp 07431 359

--810101022 Notice of violation from Insp on 800922-1021.
MAIDEN, G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/11/18 2pp 07431 352

--810101023 IE Insp Repts 50-313/80-21 & 50-368/80-21 on 800922-1021. Noncompliance noted inoperability of high pressure safety injection pump & failure to sample reactor coolant sys as required.
JOHN, S. W. D., CALLAN, L. J., HUNTER, D. M. Region 4, Dallas, Office of the Director 80/11/18 7pp 07431 355

810101025 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (October 17, 1980 Indian Point Event)" written response required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 80/11/21 1p 07425 259

8101010318 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Shutter Fluid." No response required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 80/11/24 1p 05873 303

810101035 Responds to IE Bulletin 80-23 re Valcor solenoid valves. No such valves installed at facilities. Three manhours expended.
TRIMBLE, D. C. Arkansas Power & Light Co. 80/11/24 1p 07446 156

8101010324 Requests existing data, summaries & records of inservice insp tests of containments w/greased prestressing tendons. CRMC receiving contract to compile & review records of tendons.
EISENHART, D. C. Division of Licensing 80/11/25 3pp 07378 353

8101010490 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 80/11/26 1p 07391 109

8101010584 Forwards corrected Pages 6 & 7 of IE Insp Repts 50-313/80-21 & 50-368/80-21.
MAIDEN, G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/11/26 1p 07401 050

--8101010687 Corrected Pages 6 & 7
"Region 4, Dallas, Office of the Director 80/11/26 2pp 07401 051

8101090214 Ack receipt of 800924 ltr informing NRC of correct violations noted in IE Insp Repts 50-368/80-21 & 50-313/80-13. Add'l info required within 20 days.
KELLY, J. A. Region 4, Dallas, Office of the Director 2pp 07425 271

--8101090225 Responds to NRC ltr re violations noted in 50-368/80-13 & 50-313/80-13. Corrective actions w/ (ref 10CFR2 790).
TRIMBLE, D. C. Arkansas Power & Light Co. 80/09/24 07425 273

810120044 Informs of progress since 800731 ltr re IE concerning hydromotor actuator deficiencies. Vendor detailing.
TRIMBLE, D. C. Arkansas Power & Light Co. 80/12/01

8101070158 Ack receipt of 801010 & 1112 ltrs informing taken to correct violations noted in IE Insp Repts 50-313/80-16 & 50-368/80-15.
MAIDEN, G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/12/09 1p 07415 119

--8101070164 Responds to NRC 801023 ltr re violations. Repts 50-313/80-16 & 50-368/80-16. Corrective action audit repts will be reviewed by plant safety committee.
TRIMBLE, D. C. Arkansas Power & Light Co. 80/11/11 07415 120

8101050607 Forwards IE Info Notice 80-43, "Failures of Level Monitor for Scram Discharge Vol at Dresden Unit 2." response required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 1p 07391 026

810120174 Responds to IE Bulletin 80-21 re valve gnd Foundry Co., Inc. No valve parts in safety-related sys. Malcolm Foundry Co., Inc.
TRIMBLE, D. C. Arkansas Power & Light Co. 80/12/08

8101050192 Forwards IE Info Notice 80-44, "Actuation, Recirculation Mode While in Hot Shutdown." No writt response required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 1p 07391 300

810100005 Forwards IE Insp Repts 50-313/80-19 & 50-368/80-09 & notice of violation. Notice of violation withheld (ref 10CFR2 790).
KELLY, J. A. Region 4, Dallas, Office of the Director 2pp 07443 057

--810100008 IE Insp Repts 50-313/80-19 & 50-368/80-10. Noncompliance noted: guards w/o continuous communication authorization lists not prepared. Details withheld (ref 10CFR2 790).
EVANS, C. A., KELLY, J. A. Region 4, Dallas, Office of the Director 80/10/31 2pp 07442 059

8101300341 Forwards requests for add'l info re emergency reliability, based on review of licensee 791220 submittal action plan. IE Bulletins 79-05, 05A & 05B & NURE criteria.
REID, R. W. Operating Reactors Branch 4. 81/01/12

R. Periodic operating reports & related correspondence

8101050269 Forwards intake impingement data for Nov 1980.
TRIMBLE, D. C. Arkansas Power & Light Co. 80/12/23

--8101050275 Intake impingement data for Nov 1980.
" Arkansas Power & Light Co. 80/12/19 12pp.

8101210490 Forwards monthly operating rpt for Dec 1980.
TRIMBLE, D. C. Arkansas Power & Light Co. 81/01/15

--8101210494 Monthly operating rpt for Dec 1980.
BRAMLETT, L. B. Arkansas Power & Light Co. 81/01/17 07490 168

8101290536 Forwards results of intake impingement monitoring for Dec 1980 per ETB 4.1.2 1(2).
TRIMBLE, D. C. Arkansas Power & Light Co. 81/01/29

--8101290540 Results of intake impingement monitoring for Dec 1980.
" Arkansas Power & Light Co. 81/01/26 16pp.

portable occurrences, LERs & related correspondence

350320 Forwards revised LER 80-011/03X-B
HBLE.D C Arkansas Power & Light Co 80/12/26 1p 07389 083

31050438 Revised LER 80-011/03X-B on 800401, encl list of 44 hangers declared inoperable per piping sys as-built configuration review required by IE Bulletin 79-14 Caused by defective design Review continuing
HIVELV, C N Arkansas Power & Light Co 80/12/26 2pp
07385 084

350331 Forwards LER 80-041/03L-0
HBLE.D C Arkansas Power & Light Co 80/12/26 1p 07385 086

31050336 LER 80-041/03L-0 on 801128, lead dihydrogen purge supply Pan. 'BF-33A, tripped Caused by blown control fuse due to venturient control power fuse & control transformer increased to accommodate increased load
HIVELV, C N Arkansas Power & Light Co 80/12/26 1p
07385 087

50463 Forwards revised LER 80-011/03X-7
HBLE.D C Arkansas Power & Light Co 80/12/26 1p 07390 196

3050537 Revised LER 80-011/03X-9, on 800401, encl list of 46 hangers declared inoperable per piping sys as-built configuration review required by IE Bulletin 79-14 Caused by defective design Review continuing
HAMLET, L S Arkansas Power & Light Co 80/12/26 2pp
07390 197

30543 Forwards revised LER 80-039/03L-1
HBLE.D C Arkansas Power & Light Co 81/01/08 1p 07454 145

31050546 Revised LER 80-039/03L-1 on 801028, during monthly surveillance on lead H purge sys, exhaust fan VEF-37A tripped Caused by short in control sys which caused actifier to fail & fuse to blow
HAMLET, L S Arkansas Power & Light Co 81/01/08 2pp
07454 146

erator Examinations

50355 Forwards info re NUREG-0737, in response to NRC 801031 ltr ludes info re shift technical advisor procedures for essents & accidents, plant shielding & thermal shock rept
3LE.D C Arkansas Power & Light Co 80/12/31 9pp, 07393 346

30356 Requests clarification of position re items 11 B i & 11 D 4 NUREG-0737, re reactor coolant sys vents & training for getting core damage
3LE.D C Arkansas Power & Light Co. 81/01/17 3pp 07943 090

* 50-315 DONALD C COOK NUCLEAR POWER PLANT, UNIT 1
unity, medical, emergency & fire protection plans

0387 Ltr to all licensees of operating reactor plants, CP holders applicants Revised radiological emergency response is must be submitted by licensees within 60 days of 02 & by applicants as part of FSAR
HUT.D G Division of Licensing 80/11/13 2pp.

0170 Advises of provisions of 10CFR50, App R, that are applicable re protection features of facility, FR notice & summary reFF requirements to resolve open items encl. No open s for facility, W/O encl
HUT.D G Division of Licensing 80/11/24 3pp 07492 150

0461 Requests relief from required 810102 submittal date for ed emergency plan, Delay needed in order to permit mgt ew of state & county emergency plans, final typing & twg Plan will be submitted by 810126
ER, R B Indiana & Michigan Electric Co 80/12/30 2pp.
2:265

0579 Forwards App C to modified amended security plan in response 01031 ltr Plan withheld (ref 10CFR2 790)
ER, R B Indiana & Michigan Electric Co 81/01/20 1p.
1:122

udicatory correspondence

0532 Forwards revised order for mod of license, correcting refs 00829 order Hearing date also revised.
HUT.D G Division of Licensing 80/09/19 3pp 07444 280

--810100549 Revised order amending Licenses DPR-58 & DPR-74 Info requested by IE Bulletin 79-018 must be submitted to IE by 801101
EISENHUT.D G Division of Licensing 80/09/19 6pp 07444 282

P Operating license stage documents & correspondence

810100932 Forwards revised order for mod of license, correcting refs in 800829 order Hearing date also revised
EISENHUT.D G Division of Licensing 80/09/19 3pp 07444 200

--810100549 Revised order amending Licenses DPR-58 & DPR-74 Info requested by IE Bulletin 79-018 must be submitted to IE by 801101
EISENHUT.D G Division of Licensing 80/09/19 6pp 07444 282

810100294 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under STG license amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT.D G Division of Licensing 80/11/20 1p

--810100274 Revised Pages 3/4 7-22 through 28, 8 3/4 7-5 & 7-6 & 6-17 STG snubber inservice insp requirements
4 Division of Licensing 80/11/20 10pp

8101220466 Ltr to all power reactor licensees & applicants forwarding Summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT.D G Division of Licensing 80/11/26 8pp

8101160530 Forwards notification of 801218 meeting w/util to discuss ultimate strength of containment & hydrogen control measures, Util should be prepared to discuss equipment hatch cover & structural analysis Analysis guidelines encl NOVAK, T H Assistant Director for Operating Reactors 80/12/11 4pp 07471 194

8101210445 Forwards responses to questions on Rule 50 71e, "Periodic Updating of FSARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame
EISENHUT.D G Division of Licensing 80/12/15 13pp

8101150368 Summary of 801219 meeting w/util re ultimate strength of containments & hydrogen control measures for containments
MINER, S Operating Reactors Branch 1 81/01/02 5pp 07463 226

8101210242 Forwards House Rept 96-1452, "Twenty-Eighth Rept by Committee on Govt Operations," in response to util 801229 request W/O encl
HEIGHAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 81/01/05 1p 07492 039

8101160021 Confirms plans for 810113 meeting in Glen Ellyn, IL to discuss recent events at facility
KEPPLER, J O Region 3, Chicago, Office of the Director 81/01/06 1p 07467 301

8101130217 Forwards response to NRC 801031 ltr re implementation of post-TMI requirements contained in NUREG-0737
HUNTER, R B Indiana & Michigan Electric Co 81/01/08 34pp 07449 329

8101190512 Forwards "First Quarterly Rept on Hydrogen Issues," per 801007 submittal "Summary of Analyses of DC Cook Containment Response to Hydrogen Transients" encl
HUNTER, R B Indiana & Michigan Electric Co 81/01/12 1p 07183 001

--8101190315 "First Quarterly Rept on Hydrogen Issues,"
* Indiana & Michigan Electric Co 81/01/12 34pp 07183 001

--8101190518 "Summary of Analysis of DC Cook Containment Response to Hydrogen Burn Transients"
* Offshore Power Systems (subs of Westinghouse Electric Corp)
RP26A05 80/12/31 51pp 07183 001

8101230529 Forwards two revised pages correcting administrative errors in 810108 submittal (AEP, ACC398)
HUNTER, R B Indiana & Michigan Electric Co 81/01/16 5pp 07183 001

8101300494 Forwards revised pages correcting errors in 801210 submittal re auxiliary feedwater sys automatic initiation & flow indication
HUNTER, R B Indiana & Michigan Electric Co 81/01/23 4pp 07583 318

D Inspection Reports, IE Bulletins & correspondence

B101050239 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding " No response required.
KEPPLER, J Q Region 3, Chicago, Office of the Director. 80/10/30. 2pp 07389 102

B101060537 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp " No written response is required
KEPPLER, J Q Region 3, Chicago, Office of the Director 80/10/31. 2pp 07401 162

B101050451 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolme Foundry Co. Inc. Written response required
KEPPLER, J Q Region 3, Chicago, Office of the Director 80/11/06 2pp 07389 349

B101060350 Forwards IE Info Notice 80-41, "Failure of Busing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1 " No response required
KEPPLER, J Q Region 3, Chicago, Office of the Director 80/11/10 2pp 07392 073

B101060520 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp " Written response required.
KEPPLER, J Q Region 3, Chicago, Office of the Director. 80/11/14 2pp 07391 241

B101120019 Forwards IE Insp Rept 50-315/80-16 on 801021-22 & 1105-07 & notice of violation
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/11/24 2pp 07446 239

--B101120028 Notice of violation from insp on 801021-22 & 1105-07
" Region 3, Chicago, Office of the Director 80/11/21. 1p 07446 241

--B101120034 IE Insp Rept 50-315/80-16 on 801021-22 & 1105-07
Noncompliance noted failure to follow procedure re calibr of feedwater flow transmitters.
HOPKINS, B. Region 3, Chicago, Office of the Director
STREETER, J F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/11/21 3pp 07446 242

B101050356 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Steam Discharge Vol at Dresden Unit 2." No response required.
KEPPLER, J Q Region 3, Chicago, Office of the Director 80/12/05. 2pp 07390 322.

B101070077 Forwards IE Info Notice 80-44, "Actuation of ECCB in Recirculation Mode While in Hot Shutdown." No written response required
KEPPLER, J Q Region 3, Chicago, Office of the Director. 80/12/16 1p 07415 050

B101220100 Forwards IE Investigation Rept 50-315/80-17 on 800716-30 & 1110
KEPPLER, J Q Region 3, Chicago, Office of the Director 80/12/16 2pp 07183 001.

--B101220102 IE Investigation Rept 50-315/80-17 on 800716-30 & 1110.
Noncompliance noted improper use of plant radiation work permit sys, allowing unauthorized entry into steam generator
WEIL, C H, NDREI, LUS, C E Region 3, Chicago, Office of the Director 80/12/08 47pp 07183 001

B101120268 Informs of review of IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp " No Valcor valves used Total manpower effort was 70 manhours
HUNTER, R S Indiana & Michigan Electric Co. 80/12/17. 1p. 07446 265

B101120315 Responds to IE Bulletin 80-21 re valve yokes supplied by Malcolme Foundry Co. No valves employ yokes mfg by vendor
HUNTER, R S Indiana & Michigan Electric Co. 80/12/17 1p. 07446 264

B101300070 Ack receipt of 801223 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/80-14 & 50-316/80-13.
HIND, J A Region 3, Chicago, Safeguards Branch. 81/01/09 1p. 07583 053

--B101300073 Updates B01022 ltr re IE Insp Repts 50-315/80-14 & 50-316/80-13 Encl withheld (ref 10CFR2 790).
HUNTER, R S Indiana & Michigan Electric Co. 80/12/23 1p 07583 054.

B101280510 Suppls B00710 response to IE Bulletin 80-11, "Masonry Design " Current plant changes being reviewed to verify that all concrete masonry walls were constructed from architectural &/or structural drawings
HUNTER, R S Indiana & Michigan Electric Co. 81/01/14. 2pp 07550 324

S Reportable occurrences, LERs & related correspondence

B101200367 Forwards LER 80-027/03L-0
SHALLER, D V Indiana & Michigan Power Co 81/01/15 1p. 07477 353

--B101200371 LER 80-027/03L-0 on B01218, spent fuel pool, diesel ge room floor & containment spring line peak recording accelerographs found out of calibr Cause unknown Peak recording accelerographs recalibr
DELONG, S Indiana & Michigan Power Co. 81/01/15. 1p 0747

B101290516 Forwards LER 80-028/03L-0
SHALLER, D V. Indiana & Michigan Electric Co. 81/01/23 1p. 07575 244

--B101290521 LER 80-028/03L-0 on B01227, two lower ice condenser door openings exceeded torque spec Caused by slipping insulation around doors due to adhesive bond failure Metal screws added to all lower door insulation.
DELONG, S. Indiana & Michigan Electric Co. 81/01/23 2pp. 07575 245

DOCKET 80-316 DONALD C. COOK NUCLEAR POWER PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP hu & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D Q Division of Licensing. 80/11/13. 2pp.

B101130170 Advises of provisions of 10CFR50 App R, that are applicable to fire protection features of facility, FR notice & summary of staff requirements to resolve open items encl. No open items for Facility, W/O encl.
EISENHUT, D. Q. Division of Licensing. 80/11/24. 3pp 07482 1

B101090461 Requests relief from required B10102 submittal date for revised emergency plan. Delay needed in order to permit mgt review of state & county emergency plans, final typing & printing Plan will be submitted by B10126.
HUNTER, R S Indiana & Michigan Electric Co. 80/12/30. 2pp 07442 263

B101260579 Forwards App C to modified amended security plan in re to B01031 ltr Plan withheld (ref 10CFR2 790).
HUNTER, R S. Indiana & Michigan Electric Co 81/01/20 1p. 07531 122

G Adjudicatory correspondence

B101100532 Forwards revised order for mod of license, correcting r in 800829 order. Hearing date also revised.
EISENHUT, D Q Division of Licensing. 80/09/19. 3pp.

--B101100549 Revised order amending Licenses DPR-5B & DPR-74, info requested by IE Bulletin 79-01D must be submitted to IE by B01101
EISENHUT, D. Q. Division of Licensing 80/09/19. 6pp.

P Operating license stage documents & correspondence

B101100532 Forwards revised order for mod of license, correcting r in 800829 order. Hearing date also revised.
EISENHUT, D Q Division of Licensing. 80/09/19. 3pp. 07444 2

--B101100549 Revised order amending Licenses DPR-5B & DPR-74, info requested by IE Bulletin 79-01D must be submitted to IE by B01101
EISENHUT, D. Q. Division of Licensing 80/09/19. 6pp. 07444

B101100254 Ltr to all licensees (except SEP licensees) Forwarding Revision 1 of inservice surveillance requirements for snubbers under BTS License amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT, D Q Division of Licensing 80/11/20 1p.

--8101100271 Revised Pages 3/4 7-22 through 28.8 3/4 7-5 & 7-6 & 6-17 to
 STS shubber inservice insp requirements
 • Division of Licensing 80/11/20 10pp

8101220466 Ltr to all power reactor licensees & applicants forwarding
 summary of 801112 meeting re implementation of guidance for
 Unresolved Safety Issue A-12, "Potential for Low Fracture
 Toughness & Lamellar Tearing on Component Supports"
 EISENHUT.D O Division of Licensing 80/11/26 8pp

8101160530 Forwards notification of 801218 meeting w/util to discuss
 ultimate strength of containment & hydrogen control
 measures Util should be prepared to discuss equipment hatch
 cover & structural analysis Analysis guidelines encl
 NOVAK, I M Assistant Director for Operating Reactors 80/12/11
 4pp 07471 154

8101050481 Ack receipt of util 780622 ltr forwarding rept. per Condition
 2 C(3)(n) of License DPR-74 Rept is subj to Class III fee
 MILLER.W O - License Fee Management Branch. 80/12/12 1p
 07387 024.

8101210445 Forwards responses to questions on Rule 50.71e. "Periodic
 Updating of FBARS" & PR notice of final rule SEP plants need
 not comply w/rule until program is complete Non-SEP plants
 must comply within specified time frame
 EISENHUT.D O Division of Licensing 80/12/15 13pp

8101150368 Summary of 801219 meeting w/util re ultimate strength of
 containments & hydrogen control measures for containments.
 MINER.S Operating Reactors Branch 1 81/01/02 5pp 07462 226

8101210242 Forwards House Rept 96-1452. "Twenty-Eighth Rept by
 Committee on Govt Operations," in response to util 801229
 request w/o encl
 KEISHMAN.R F Region 3, Chicago, Reactor Operations Nuclear Support
 Branch. 81/01/05 1p. 07492 039

8101160021 Confirms plans for 801113 meeting in Glen Ellyn, IL to
 discuss recent events at facility
 KEPLER.J O Region 3, Chicago, Office of the Director. 81/01/06
 1p 07467 301

8101130217 Forwards response to NRC 801031 ltr re implementation of
 post-TMI requirements contained in NUREG-0737
 HUNTER.R S Indiana & Michigan Electric Co. 81/01/08 34pp.
 07449 320

8101190512 Forwards "First Quarterly Rept on Hydrogen Issues," per
 801007 submittal. "Summary of Analyses of DC Cook
 Containment Response to Hydrogen Transients" encl
 HUNTER.R B Indiana & Michigan Electric Co. 81/01/12 1p
 07183 001.

--8101190515 "First Quarterly Rept on Hydrogen Issues"
 • Indiana & Michigan Electric Co 81/01/12. 34pp. 07183 001

--8101190518 "Summary of Analysis of DC Cook Containment Response to
 Hydrogen Burn Transients"
 • Offshore Power Systems (subs. of Westinghouse Electric Corp.)
 RP36A05. 80/12/31. 51pp. 07183 001

8101230529 Forwards two revised pages correcting administrative errors
 in 810108 submittal (AEP NRC 0039B)
 HUNTER.R S Indiana & Michigan Electric Co. 81/01/16 3pp
 07183 001.

8101270350 Submits Class III fee in response to NRC 801212 ltr re
 processing fee for licensee 780622 submittal. "Westinghouse
 Reactor Protection Sys/Engineered Safety Features Activation
 Sys Setpoint Methodology."
 HUNTER.R B Indiana & Michigan Electric Co 81/01/21 1p
 07343 093.

8101300494 Forwards revised pages correcting errors in 801210 submittal
 re auxiliary feedwater sys automatic initiation & flow
 indication
 HUNTER.R S Indiana & Michigan Electric Co. 81/01/23 4pp
 07583 318

0 Inspection reports, IE Bulletins & correspondence

8101050239 Forwards IE Info Notice 80-30. "Cracking in Charging Pump
 Casing Cladding." No response required
 KEPLER.J O Region 3, Chicago, Office of the Director. 80/10/30
 2pp. 07389 102

8101060537 Forwards IE Info Notice 80-39. "Malfunction of Solenoid
 Valves Mfg by Valcor Engineering Corp." No written response
 is required
 KEPLER.J O Region 3, Chicago, Office of the Director 80/1
 2pp 07401 162

8101050451 Forwards IE Bulletin 80-21. "Valve Yokes Supplied by
 Malcolm Foundry Co. Inc." Written response required
 KEPLER.J O Region 3, Chicago, Office of the Director 80/1
 2pp 07389 319

8101060350 Forwards IE Info Notice 80-41. "Failure of Using Cher
 Valve in Decay Heat Removal Sys at Davis Besse Unit 1" No
 response required
 KEPLER.J O Region 3, Chicago, Office of the Director 80/1
 2pp 07392 073

8101060520 Forwards IE Bulletin 80-23. "Failures of Solenoid Val
 Mfg by Valcor Engineering Corp." Written response required
 KEPLER.J O Region 3, Chicago, Office of the Director. 80/1
 2pp 07391 241

8101050556 Forwards IE Info Notice 80-43. "Failures of Continuous
 Level Monitor for Steam Discharge Vol at Dresden Unit 2" No
 response required
 KEPLER.J O Region 3, Chicago, Office of the Director 80/1
 2pp 07390 322

8101070077 Forwards IE Info Notice 80-44. "Actuation of ECCS in
 Recirculation Mode While in Hot Shutdown" No written
 response required
 KEPLER.J O Region 3, Chicago, Office of the Director 80/1
 1p 07413 050.

8101120268 Informs of review of IE Bulletin 80-23. "Failures of
 Solenoid Valves Mfg by Valcor Engineering Corp." No Valcor
 valves used Total manpower effort was 70 manhours
 HUNTER.R S Indiana & Michigan Electric Co 80/12/17 1p
 07446 265

8101120315 Responds to IE Bulletin 80-21 re valve yokes supplied
 Malcolm Foundry Co. No valves employ yokes mfg by vendor
 HUNTER.R S Indiana & Michigan Electric Co 80/12/17 1p
 07446 264

8101306070 Ack receipt of 801223 ltr informing NRC of steps taken
 correct violations noted in IE Insp Repts 80-315/80-14 &
 80-316/80-13.
 HIND.J A Region 3, Chicago, Safeguards Branch 81/01/09 1
 07583 053

--8101300073 Updates 801022 ltr re IE Insp Repts 80-315/80-14 &
 80-316/80-13 Encl withheld (ref 10CFR2 790)
 HUNTER.R B Indiana & Michigan Electric Co 80/12/23 1p
 07383 054.

8101280510 Suppls 800710 response to IE Bulletin 80-11. "Masonry
 Design" Current plant changes being reviewed to verify that
 all concrete masonry walls were constructed from
 architectural &/or structural drawings
 HUNTER.R S Indiana & Michigan Electric Co 81/01/14. 2pp
 07550 324

8 Reportable occurrences, LERs & related correspondence

8101050356 RD on 801215 spray header isolation valves CT6-124E &
 CT8-128E were discovered sealed & locked closed at 9:30-h.
 Valves reopened, relocked & resealed in correct position
 Followup rept will be submitted by 801226
 BHALLER.D V Indiana & Michigan Electric Co. 80/12/16 1p.
 07376 205

8101050472 Forwards LER 80-033/OIL-O
 SHALLER.D V Indiana & Michigan Electric Co 80/12/22 1p
 07390 203

--8101050946 LER 80-033/OIL-O on 801214 containment upper & lower
 CT8 headers on east train were isolated. Caused by operator
 not performing correct valve lineup. Operating shifts
 retrained
 KEITH.R S Indiana & Michigan Electric Co 80/12/22. 2pp
 07390 204

8101060789 Forwards LER 80-033/OIL-O
 SHALLER.D V Indiana & Michigan Electric Co 80/12/31 1p
 07393 360

--B101060795 LER 80-034/031-0 on 801204, during inservice insp testing, containment isolation valve NCR-252 was not fully seated w/shut indication in control room Cause undetermined Valve stroke adjusted & valve shut completely
WEITH, R S Indiana & Michigan Power Co 80/12/31 2pp
07393 361

B101080384 Forwards LERs 80-035/031-0 & 80-036/031-0
SHALLER, D V Indiana & Michigan Electric Co 81/01/02 1p
07420 348

- B101080397 LER 80-035/031-0 on 801206, rod position identification for control rod N-9 did not respond properly Caused by connector on top of rod position detector assembly that appeared to have been stepped on Cable replaced
RISCH, INC, J Indiana & Michigan Electric Co 80/12/31 1p
07420 309

--B101080406 LER 80-036/031-0 on 801202, discovered that monthly functional test of source range nuclear instrumentation not performed Caused by personnel error Test has been added to surveillance schedule
RISCH, INC, J Indiana & Michigan Electric Co 80/12/31 2pp
07420 310

B101090485 Forwards LER 80-037/031-0
SHALLER, D V Indiana & Michigan Electric Co 81/01/06 1p
07442 018

--B101090672 LER 80-037/031-0 on 801207, transmitter NPP-153 found to have excessive nonconservative drift causing pressurizer pressure high reactor trip setpoint to exceed Tech Spec limits Caused by setpoint drift Transmitter recalibr
RISCH, INC, J Indiana & Michigan Electric Co 81/01/06 2pp
07442 019

B101210443 Forwards LER 80-034/031-1
SHALLER, D V Indiana & Michigan Power Co 81/01/13 1p
07493 193

--B101210451 LER 80-034/031-1 on 801204, containment isolation valve NCR-252 was not fully seated w/shut indication in control room Cause undetermined Valve stroke adjusted & valve shut completely
WEITH, R S Indiana & Michigan Power Co 81/01/08 2pp
07493 154

BUCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 80104 & by applicants as part of FBAR
EISENHUT, D O Division of Licensing 80/11/13 2pp.

B101130136 Advises of provisions of 10CFR50, App R, that are applicable to fire protection features of facility FR notice & summary of staff requirements to resolve open items encl
EISENHUT, D O Division of Licensing 80/11/24 Bpp. 07308 001

B101050437 Provides approach to resolving eight open fire protection items in response to NRC 801124 Ltr re requirements for resolution Fire protection mods will be completed by 801219
LUNDVALL, A E Baltimore Gas & Electric Co 80/12/27 3pp
07399 333

B101140039 Requests that encl facility emergency planning info be made publicly available w/o encl 801220369
SEUDER, J L Division of Rules and Records 80/12/31 1p
07461 225

B101140285 Requests that encl facility planning info be made publicly available w/o encl 8012150057
SEUDER, J L Division of Rules and Records 80/12/31 1p
07461 261

B101290613 Releases public version of utility emergency plan
FELTEN, J M Division of Rules and Records 81/01/27 1p
07187 001

--B101290610 Forwards public version of Attachment J-4 to 801231 emergency response plan.
OLSON, R C Baltimore Gas & Electric Co 81/01/07 1p
07187 001

--B101290621 Public version of Attachment J-4 to emergency response plan.
* Baltimore Gas & Electric Co 80/12/31 1p 07187 001

H General correspondence

B101190164 Forwards updated svc list for correspondence re facility Continuing inconsistency in old svc list has caused delays in receipt of IMC ltrs
OLSON, R C L Baltimore Gas & Electric Co 81/01/12 3pp
07476 042

I Financial information

B101190502 Forwards annual financial rept for 1979 & statement of projected cash flow for twelve months ended 810731.
JINERS, A H Baltimore Gas & Electric Co 81/01/14 5pp.
07473 251

--B101190507 Annual Financial Rept 1979
* Baltimore Gas & Electric Co 80/12/08 40pp 07475 236

J Insurance & indemnity information

B101060571 Forwards Endorsements 3 to NELA Policy EB-52 & MAELU P XR-52
SHIDEMAKER, C L Baltimore Gas & Electric Co 80/12/30 5pp.
07399 166

P Operating license stage documents & correspondence

B101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under STS License amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT, D O Division of Licensing 80/11/20 1p

--B101100271 Revised Pages 3/4 7-22 through 28, 3/4 7-5 & 7-6 & 5/8 snubber inservice insp requirements
* Division of Licensing 80/11/20 10pp.

B101100040 Confirms 801126 mtg meeting in Baltimore, MD to discuss assessment of utility regulatory performance at facility Meeting arrangements were discussed in 801118 telcon Meeting agenda encl
GRIER, D H Region 1, Philadelphia, Office of the Director 80/11/21 2pp. 07444 305

B101220466 Ltr to all power reactor licensees & applicants forward summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D O Division of Licensing 80/11/26 Bpp.

B101090941 Forwards Amend 4B to License DPR-53, safety evaluation & notice of issuance & availability
CLARK, R A Operating Reactors Branch 3 80/12/12 4pp 03071

--B101090943 Amend 4B to License DPR-53, authorizing Cycle 5 operating power level of 2,700 MWt w/increased fuel enrichment, demonstration fuel assemblies, modified guide tubes & new reactor protection sys trip
CLARK, R A Operating Reactors Branch 3 80/12/12 76pp.
03871 252

--B101090945 Safety evaluation supporting Amend 4B to License DPR-53
* Office of Nuclear Reactor Regulation, Director. 80/12/12 50pp. 03871 328

--B101090947 Notice of issuance & availability of Amend 4B to License DPR-53
CLARK, R A Operating Reactors Branch 3 80/12/12 2pp.
03872 016

B101210445 Forwards responses to questions on Rule 50.71e, "Periodic Updating of FBARs" & FR notice of final rule. SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame
EISENHUT, D O Division of Licensing. 80/12/15 13pp.

B101150573 Confirms 801217 telcon revising Tech Spec 3.6.2.1 in response to 801217 telecopy Authorized change will become Amend 49 Tech Specs encl
NOVAH, T M Assistant Director for Operating Reactors. 80/12/10 3pp 07466 006

--B101150875 Revised Tech Spec Section 3/4.6.2 re depressurization cooling sys, containment spray sys
* Assistant Director for Licensing 80/12/18 1p. 07466 000

seismic evaluation program
L1-C Operating Reactors Branch 3 80/12/18 4pp 07464.001.

B01060283 Provides addl info re scope of mod to auxiliary feedwater sys Mods will comply w/Section III of ASME code 1978 Summer Addenda for equipment installation w/exception of final connections to existing sys
ASH, R.F. Baltimore Gas & Electric Co 80/12/30 2pp. 07399 068

B01060333 Forwards response to NRC B01031 request for status of efforts re implementation of YMI Lessons Learned requirements & request for info re NUREG-0737 items
POINDEXTER, C.H. Baltimore Gas & Electric Co 80/12/30 27pp 07392 285

--B01060339 "Control Room Habitability Study for Calvert Cliffs Nuclear Power Station" Responses to NUREG-0737 & NUREG-0578 status info encl
* Bechtel Power Corp (subs of Bechtel Corp.) 80/11/30 47pp 07392 312

B011190416 Forwards request for addl info for review of CEN-119(B)-P re better axial shape selection sys info needed re 18-month fuel cycles
CLARK, R.A. Operating Reactors Branch 3 80/12/30 3pp. 07183:001

B011190320 Application to amend Licenses DPR-53 & DPR-69, changing Tech Specs Sections 3 & 4 to provide for redundancy in decay heat removal capability Class I & III fees encl
LUNDVALL, A.E. Baltimore Gas & Electric Co 81/01/08 2pp 07435 001

--B011190329 Proposed Tech Specs Sections 3 & 4, providing for redundancy in decay heat removal capability
* Baltimore Gas & Electric Co 81/01/08 9pp 07475 003

B011230486 Determines that B01119 request for relief from ASME Code Section VI requirement consists of Class III & I amend per 10CFR170.22 Applicable fees submitted
OLSEN, R.C. Baltimore Gas & Electric Co 81/01/09 1p. 07510:291

B01220434 Submits license fee for Class III amend re seismic qualification of containment spray sys per B01217 request.
OLSEN, R.C.L. Baltimore Gas & Electric Co 81/01/15 1p 07493 251

B01270611 Advises that footnotes will be added to Tech Spec Tables 3-3-3, 3-4 & 4-3-2 to clarify Category A lessons learned requirements.
DAHLQUIST, J.M. Baltimore Gas & Electric Co 81/01/23 1p 07183:001

B01300322 Responds to NRC B01023 request for verification of actions taken in response to NRC 791107 requirements for auxiliary feedwater sys Emergency operating procedures direct operator to start up auxiliary sys if diesel fails.
LUNDVALL, A.E. Baltimore Gas & Electric Co 81/01/26 3pp. 07183 001.

Q Inspection reports, IE Bulletins & correspondence

B01300134 Forwards IE Investigation Rept 50-317/80-18 on B01014-16 No noncompliance noted
CARLSON, R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/11/05 2pp 07583 096

--B01300138 IE Investigation Rept 50-317/80-18 on B01014-16 No noncompliance noted Major areas investigated allegations re pipe support activities performed to comply w/IE Bulletin 79-02
DURR, J.P. Region 1, Philadelphia, Office of the Director.
MATTIA, J.C. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/11/03 7pp 07583 098

B01130694 Informs that visual insp of RCP studs at Calvert Cliffs has revealed corrosion problem similar to Ft Calhoun.
Insp method should be checked
NOVAK, T.M. Assistant Director for Operating Reactors 80/11/24 1p. 07494 038

B01050124 Requests existing data, summaries & records of inservice insp tests of containments w/grouted prestressing tendons
CRNL receiving contract to compile & review records of tendons.
ETSENHUT, D.O. Division of Licensing 80/11/29 3pp 07378 333

CHERRY, G.A. Region 1, Philadelphia, Office of the Director
GRIER, B.H. Region 1, Philadelphia, Office of the Director
80/11/26 1p 07414 092

B01140944 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." No specified parts in use at facilities
LUNDVALL, A.E. Baltimore Gas & Electric Co 80/12/10 1p 07450 360

B01150949 Ack receipt of B01107 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/80-13 & 50-318/80-12
BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/12/10 1p 07464 199

--B01150951 Responds to NRC B01015 ltr re violations noted in IE Insp Repts 50-317/80-13 & 50-318/80-12 Corrective actions entered correct setpoint for 11B RCP seal high temp/pressure into alarm manual
LUNDVALL, A.E. Baltimore Gas & Electric Co 80/11/07 2pp 07464 203

--B01150953 Forwards IE Insp Repts 50-317/80-13 & 50-318/80-12 on B00728-0801 & notice of violation
BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/10/15 2pp 07464 202

--B01150955 Notice of violation from insp on B00728-0801.
* Region 1, Philadelphia, Office of the Director 80/10/06 07464 204

--B01150958 IE Insp Repts 50-317/80-13 & 50-318/80-12 on B00728-0801 Noncompliance noted failure to maintain alarm procedures consistent w/indicated alarm status & failure to properly maintain controlled procedures.
CHUNG, J.W., LUMBERO, N. Region 1, Philadelphia, Office of the Director
GREENMAN, E. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/10/06 16pp 07464 207

B01150562 Ack receipt of B01205 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/80-13 & 50-318/80-14
BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/12/15 1p. 07464 223

--B01150565 Responds to NRC B01107 ltr re violations noted in IE Insp Repts 50-317/80-13 & 50-318/80-14 Corrective actions procedural format set forth by CCI 217, plant mod procedures, approved to measure wall clearance.
LUNDVALL, A.E. Baltimore Gas & Electric Co. 80/12/05 2pp. 07464 224

--B01150568 Forwards IE Insp Repts 50-317/80-13 & 50-318/80-14 on B00901-29 & notice of violation
BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/11/07 2pp 07464 226

--B01150970 Notice of violation from insp on B00901-29
* Region 1, Philadelphia, Office of the Director 80/11/05 07464 228

--B01150973 IE Insp Repts 50-317/80-13 & 50-318/80-14 on B00901-29 Noncompliance noted failure to identify inadequate spacing of storage racks in insp program
ARCHITZEL, R.E., CALLAHAN, C.J. Region 1, Philadelphia, Office of the Director
MCADAM, E.C. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/11/05 13pp. 07464 229

B01060878 Forwards IE Info Notice 80-44, "Activation of ECCS in Recirculation Mode While in Hot Shutdown" No written response required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director 80/12/16 1p 03896 233

B01230937 Forwards proprietary & nonproprietary versions of "End of Cycle 4 Eddy Current Insp Results: Control Element Assemblies (CEA's) Guide Tube Sleeves 1980 Calvert Cliffs 1 Refueling Outage." Proprietary rept withheld (ref 10CFR2.740)
LUNDVALL, A.E. Baltimore Gas & Electric Co 81/01/21 5pp. 07513 001

--B01230541 Nonproprietary version of "End of Cycle 4 Eddy Current Results Control Element Assemblies (CEA's) & Guide Tube Sleeves 1980 Calvert Cliffs 1 Refueling Outage"
* Combustion Engineering, Inc CEN-146(B) HP 80/12/22 11p 07513:006

DOCKETED ITEMS

R Periodic operating reports & related correspondence

8101260530 Forwards monthly operating repts for Dec 1980
PERSON, S B Baltimore Gas & Electric Co 01/01/14 1p 07531 126

--8101260542 Monthly operating repts for Dec 1980.
PERSON, S B Baltimore Gas & Electric Co 01/01/14 10pp
07531 127

S Reportable occurrences, LERs & related correspondence

8101140771 RO 80-65 (U-1) on 001215, during Mode 5 operations, shutdown
cooling flow stopped to perform leak rate test on
penetration 4) w/o verifying that charging pumps were
de-energized or that flow paths were closed
* Baltimore Gas & Electric Co 00/12/16 1p 07308 001

8101050105 Forwards LER 80-065/03L-0.
RUSSELL, L B Baltimore Gas & Electric Co 00/12/29 1p
07382 112

--8101050192 LER 80-065/03L-0 on 001215, charging pumps found running
contrary to Tech Spec surveillance requirement. Caused by
failure of personnel to perform surveillance requirements
after securing shutdown cooling flow. Procedures changed
WENDERLICH, R L Baltimore Gas & Electric Co. 00/12/29 2pp
07382 113

8101090241 PRC-1-80-180 Unit 1 outage has been extended until approx
010111. Outage caused by 001224 discovery of failed main
turbine thrust bearing during initial Cycle 5 startup
McCABE, E C, BRUNNER, E J Region 1, Philadelphia, Office of the
Director 00/12/29 1p 07442 269

8101050399 Forwards LER 80-065/01T-1
RUSSELL, L B Baltimore Gas & Electric Co 00/12/30 1p
07390 111

--8101050403 LER 80-065/01T-1 on 001215, charging pumps discovered running
w/shutdown cooling flow secured. Caused by operator failure
to perform surveillance requirements of Tech Specs
Requirements reviewed w/personnel
WENDERLICH, R L Baltimore Gas & Electric Co 00/12/30 2pp
07390 112

8101050408 Forwards updated LER 80-017/03X-2
RUSSELL, L B Baltimore Gas & Electric Co 00/12/30 1p
07390 116

--8101050413 Updated LER 80-017/03X-2 on 790515, during overspeed testing,
diesel generator 12 auxiliary blower failed. Caused by
thermal growth & subsequent contact between lobes & blower
housing, due to extended overspeed test
LAGIENSKI, J S, UNSTED, J M Baltimore Gas & Electric Co 00/12/30
1p 07390 117

8101130597 Forwards LER 80-070/04X-0
RUSSELL, L B Baltimore Gas & Electric Co 01/01/07 1p
07453 325

--8101130607 LER 80-070/04X-0 on 000624, analysis of oyster samples showed
excessive Ag-110m concentrations. Caused by natural tendency
of oysters to concentrate environ silver
BROBST, O E Baltimore Gas & Electric Co 01/01/07 1p
07453 326

8101130617 Forwards LER 80-068/03L-0.
RUSSELL, L B Baltimore Gas & Electric Co 01/01/09 1p
07453 340

--8101130623 LER 80-068/03L-0 on 001210, control room air conditioning
unit 12 heaters found defective, rendering unit inoperable.
Caused by failure of heating elements. New heating elements
installed & unit returned to svc
LAGIENSKI, J S, PENCE, W B Baltimore Gas & Electric Co 01/01/09
1p 07453 341

8101230538 Forwards LER 80-071/03L-0
RUSSELL, L B Baltimore Gas & Electric Co 01/01/19 1p
07512 228

8101230523 Forwards LER 80-067/03L-0
RUSSELL, L B Baltimore Gas & Electric Co 01/01/20 1p
07513 017

--8101230526 LER 80-067/03L-0 on 001221, reactor protective sys chg
trip units for high power, thermal margin/low pressure &
axial flux offset were bypassed to repair cold input Temp
element 1-TE-122CB failed. Elements replaced w/calibr spaces.
LAGIENSKI, J S, RIZZIO, P O Baltimore Gas & Electric Co 01/01/20
1p 07513 018

8101300523 Forwards LER 80-072/03L-0
RUSSELL, L B Baltimore Gas & Electric Co 01/01/23 1p
07584 348

--8101300530 LER 80-072/03L-0 on 001225, during normal operation, num
component cooling heat exchanger outlet throttle valve
1-S4-5206-CV would not open, rendering heat exchanger
inoperable. Caused by missing operator to stem key.
LAGIENSKI, J S, PENCE, W B Baltimore Gas & Electric Co 01/01/23
2pp 07584 349

V Operator Examinations

8101070379 Responds to NRC 800328 request for mods to licensed oper
training program. Mods include training in heat transfer,
fluid flow & thermodynamics, installed plant sys use to
control core accident damage & emphasis on plant transients
LUNDVALL, A E Baltimore Gas & Electric Co 00/06/10 4pp
07414 134

DOCKET 80-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP holders
& CP applicants. Revised radiological emergency response
plans must be submitted by licensees within 60 days of
010102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 00/11/13 2pp

8101130136 Advises of provisions of 10CFR50, App A, that are applica
to fire protection features of facility. FR notice & summary
of staff requirements to resolve open items encl.
EISENHUT, D O Division of Licensing 00/11/24 8pp 07308 001

8101050437 Provides approach to resolving eight open fire protection
items in response to NRC 001124 ltr re requirements for
resolution. Fire protection mods will be completed by 010219
LUNDVALL, A E Baltimore Gas & Electric Co 00/12/29 3pp
07389 333

8101140039 Requests that encl facility emergency planning info be m
publicly available. W/o encl 0012220369.
EQUIDER, J L Division of Rules and Records 00/12/31 1p
07461 223

8101140285 Requests that encl facility planning info be made public
available. W/o encl 0012190057
EQUIDER, J L Division of Rules and Records 00/12/31 1p
07461 261

8101290613 Releases public version of util emergency plan.
FELTON, J M Division of Rules and Records 01/01/27 1p
07187 001

--8101290618 Forwards public version of Attachment J-4 to 001231
emergency response plan.
OLSON, R C Baltimore Gas & Electric Co 01/01/07 1p
07187 001

--8101290621 Public version of Attachment J-4 to emergency response
* Baltimore Gas & Electric Co 00/12/31 1p 07187 001

H General correspondence

8101190164 Forwards updated svc list for correspondence re facility
Continuing inconsistency in old svc list has caused delays
in receipt of NRC ltrs
OLSON, R C Baltimore Gas & Electric Co 01/01/12 3pp
07476 042

I Financial information

B010190502 Forwards annual financial rept for 1979 & statement of projected cash flow for twelve months ended B10731
INNEB, A H Baltimore Gas & Electric Co B1/01/14 5pp
07475 251

--B010190507 Annual Financial Rept 1979
* Baltimore Gas & Electric Co B0/12/08 40pp. 07475 256

J Insurance & indemnity information

B01060571 Forwards Endorsements 3 to NELIA Policy EB-52 & MAELU Policy 18-93
SHOBEMAKER, C L Baltimore Gas & Electric Co. B0/12/30 5pp.
07399 166

P Operating license stage documents & correspondence

B010100254 Ltr to all licensees (except BEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under STB License amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT, D. G. Division of Licensing B0/11/20 1p

--B010100271 Revised Pages 3/4 7-22 through 28.B 3/4 7-5 & 7-6 & 6-17 to STB snubber inservice insp requirements.
* Division of Licensing B0/11/20 10pp.

B010100040 Confirms B01126 mgt meeting in Baltimore, MD to discuss NRC assessment of util regulatory performance at facility.
Meeting arrangements were discussed in B01118 telcon.
Meeting agenda encl.
GRIER, B H Region 1, Philadelphia, Office of the Director
B0/11/21 2pp 07444:305

B010220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D. G. Division of Licensing B0/11/26. 4pp

B010210445 Forwards responses to questions on Rule 50.71e, "Periodic Updating of FSARs" & FR notice of final rule BEP plants need not comply w/rule until program is complete. Non-BEP plants must comply within specified time frame.
EISENHUT, D. G. Division of Licensing B0/12/15 13pp.

B010150872 Trip rept of B01028 visit to site re auxiliary feedwater sys seismic evaluation program
L.F.C. Operating Reactors Branch 3. B0/12/18 4pp. 07464.001.

B01060283 Provides addl info re scope of mod to auxiliary feedwater sys. Mods will comply w/Section III of ASME code 1978 Summer Addenda for equipment installation w/exception of final connections to existing sys.
ASH, R F Baltimore Gas & Electric Co B0/12/30. 2pp 07399-068

B01060333 Forwards response to NRC B01031 request for status of efforts re implementation of TMI Lessons Learned requirements & request for info re NUREG-0737 items.
PDINDEXTER, C H Baltimore Gas & Electric Co. B0/12/30. 27pp.
07392.285.

--B01060339 "Control Room Habitability Study for Calvert Cliffs Nuclear Power Station." Responses to NUREG-0737 & NUREG-0578 status info encl.
* Bechtel Power Corp. (subs. of Bechtel Corp.). B0/11/30. 47pp.
07392:312

B010190573 Informs of site visit to be scheduled during refueling outage in Jan 1981.
CONNER, E L. Operating Reactors Branch 3. B1/01/05. 2pp.
07474.029

B010190320 Application to amend Licenses DPR-53 & DPR-69, changing Tech Specs Sections 3 & 4 to provide for redundancy in decay heat removal capability Class I & III fees encl.
LUNDVALL, A E Baltimore Gas & Electric Co B1/01/08. 2pp.
07475:001.

--B010190325 Proposed Tech Specs Sections 3 & 4, providing for redundancy in decay heat removal capability.
* Baltimore Gas & Electric Co B1/01/08. 9pp. 07475 003.

B010230406 Determines that B01119 request for relief from ASME Section VI requirement consists of Class III & I amend per 10CFR170.22 Applicable fee submitted
OLESON, R C Baltimore Gas & Electric Co B1/01/09 1p 07

B010220434 Submits license fee for Class III amend re seismic qualification of containment spray sys. per B01217 request
OLESON, R C Baltimore Gas & Electric Co B1/01/15 1p
07493 251

B010270611 Advises that footnotes will be added to Tech Spec T 3 3-3, 3 3-4 & 4 3-2 to clarify Category A lessons learned requirements.
DAHLQUIST, J H Baltimore Gas & Electric Co B1/01/23 1p
07183 001

B010300322 Responds to NRC B01023 request for verification of taken in response to NRC 791107 requirements for auxiliary feedwater sys Emergency operating procedures direct operator to start up auxiliary sys if diesels fail.
LUNDVALL, A E Baltimore Gas & Electric Co. B1/01/26 3pp
07183.001

Q Inspection reports, IE Bulletins & correspondence

B01050124 Requests existing data, summaries & records of inspection tests of containments w/greased prestressing tendons ORNL receiving contract to compile & review records of tendons.
EISENHUT, D. G. Division of Licensing. B0/11/25 3pp

B010670391 Forwards Suppl 1 to IE Info Notice B0-29, "Broken S Terry Turbine Steam Inlet Flange." No written response required.
GRIER, B H Region 1, Philadelphia, Office of the Director
B0/11/26. 1p 07414 072

B010140944 Responds to IE Bulletin B0-21, "Valve Yokes Supplier Malcolm Foundry Co. Inc." No specified parts in use at facilities.
LUNDVALL, A E Baltimore Gas & Electric Co B0/12/10. 1p
07458 360

B010150549 Ack receipt of B01107 ltr informing NRC of steps to correct violations noted in IE Insp Repts 50-317/80-13 & 50-318/80-12
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. B0/12/10 1p 07464:199

--B010150591 Responds to NRC B01015 ltr re violations noted in Repts 50-317/80-13 & 50-318/80-12 Corrective actions enter correct setpoint for 11B RCP seal high temp/pressure into alarm manual.
LUNDVALL, A E Baltimore Gas & Electric Co B0/11/07 2p
07464 200

--B010150593 Forwards IE Insp Repts 50-317/80-13 & 50-318/80-12 800728-0801 & notice of violation
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch B0/10/15 2pp 07464 202

--B010150555 Notice of violation from insp on 800728-0801.
* Region 1, Philadelphia, Office of the Director. B0/10/07464:204

--B010150558 IE Insp Repts 50-317/80-13 & 50-318/80-12 on 800728-0801 Noncompliance noted: failure to maintain alarm procedures consistent w/indicated alarm status & failure to properly maintain controlled procedures.
CHUNG, J W, BLUMBERG, N Region 1, Philadelphia, Office of the Director GREENMAN, E Region 1, Philadelphia, Reactor Operations Nuclear Support Branch B0/10/06 16pp 07464:207.

B010150562 Ack receipt of B01205 ltr informing NRC of steps to correct violations noted in IE Insp Repts 50-317/80-13 & 50-318/80-14.
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch B0/12/15 1p 07464:223

--B010150565 Responds to NRC B01107 ltr re violations noted in Repts 50-317/80-13 & 50-318/80-14 Corrective actions. procedural format set forth by CCI 217, plant mod procedure approved to measure coil clearance.
LUNDVALL, A E Baltimore Gas & Electric Co. B0/12/05. 2p
07464:224.

--B010150568 Forwards IE Insp Repts 50-317/80-13 & 50-318/80-14 800901-29 & notice of violation
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch B0/11/07. 2pp 07464 226

--B101150570 Notice of violation from insp on 800901-29.
* Region 1. Philadelphia. Office of the Director 80/11/05 1p
07464 228

--B101150573 IE Insp Repts 90-317/80-19 & 90-318/80-14 on 800901-29
Noncompliance noted failure to identify inadequate spacing
of storage racks in insp program
ARCHITZEL, R E., CALLAHAN, C J. Region 1. Philadelphia. Office of
the Director MCCABE, E C. Region 1. Philadelphia. Reactor
Operations Nuclear Support Branch 80/11/05 13pp. 07464 229.

B101060873 Forwards IE Info Notice 80-44. 'Actuation of ECCS in
Recirculation Mode While in Hot Shutdown No written
response required
GRIER, B M. Region 1. Philadelphia. Office of the Director.
80/12/16 1p 05096 233

B101260477 Forwards results of sleeved control element assembly guide
tube evaluation. in response to NRC 791119 request insps show
no indication of sleeve wear after two cycles Recommended
insp program encl
LUNDVALL, A E. Baltimore Gas & Electric Co 81/01/21 3pp
07532 035

R Periodic operating reports & related correspondence

B101260530 Forwards monthly operating repts for Dec 1980
MERSON, S D. Baltimore Gas & Electric Co 81/01/14 1p. 07531 126

--B101260542 Monthly operating repts for Dec 1980
MERSON, S. D. Baltimore Gas & Electric Co. 81/01/14 10pp
07531 127

S Reportable occurrences, LERs & related correspondence

B101220388 Forwards LER 80-052/03L-0
RUSSELL, L B. Baltimore Gas & Electric Co 81/01/08 1p.
07505 172

--B101220390 LER 80-052/03L-0 on 801103. CTHT penetration room exhaust fan
discharge damper 22 linkage was found broken Caused by
excessive wear on clevis pin due to inadequate lubrication.
Linkage repaired & restored to svc on 801104
WENDERLICH, R L., PENCE, W B. Baltimore Gas & Electric Co
81/01/08 1p 07505 173

B101130610 Forwards LER 80-055/03L-0.
RUSSELL, L B. Baltimore Gas & Electric Co 81/01/09 1p
07453 338

--B101130615 LER 80-055/03L-0 on 801209. emergency diesel generator 12
developed fuel oil leak Caused by leak at flared type brass
compression fitting Line replaced
WENDERLICH, R L., HUSEBY, D. Baltimore Gas & Electric Co 81/01/09
1p 07453 339.

B101150534 Forwards LER 80-057/03L-0
RUSSELL, L B. Baltimore Gas & Electric Co 81/01/13 1p
07463 184

--B101150543 LER 80-057/03L-0 on 801214. control element assembly 38
dropped to bottom of core. Cause undetermined. Control
element assembly 38 realigned w/group.
LAGIENSKI, J S., RIZZO, P Q. Baltimore Gas & Electric Co 81/01/13
1p. 07463 185

B101230457 Forwards updated LER 79-009/03L-1.
RUSSELL, L B. Baltimore Gas & Electric Co 81/01/20 1p.
07913 031.

--B101230461 Updated LER 79-009/03L-1 on 790226. during test, 21 svc water
heat exchanger saltwater outlet throttle valve failed to
open upon receipt of signal Caused by packing deterioration
& accompanying seizure to shaft Shaft cleaned
CARROLL, J T., PENCE, W B. Baltimore Gas & Electric Co 81/01/20
2pp 07513 032

B101270660 RU B1-005 on 810118 power operated relief valve RC-404-ERV
inadvertently opened Caused by pressure indicating
controller PIC-103-1 failing high Power relief isolation
RC-405-MOV shut, terminating discharge.
* Baltimore Gas & Electric Co. 81/01/20 2pp 07309:001

B101270677 Forwards LER 80-069/03L-0
RUSSELL, L B. Baltimore Gas & Electric Co 81/01/21 1p
07309 001

--B101270684 LER 80-069/03L-0 on 801222. deviation found among chann
engineered safety features actuation sys. Caused by channel
D bistable voltmeter shifting out of tolerance due to maint
activities Distable meter recalibr
LAGIENSKI, J S., RIZZO, P Q. Baltimore Gas & Electric Co 81/01
2pp 07309:001

B101300533 Forwards LER 80-059/03L-0.
RUSSELL, L B. Baltimore Gas & Electric Co 81/01/26 1p.
07308 001

--B101300538 LER 80-059/03L-0 on 801226. while investigating abnormal
containment air particulate & gaseous readings, discovered
that containment atmosphere sample isolation valve was shut
Caused by personnel error Operators instructed.
DAVIS, S M., RIZZO, P Q. Baltimore Gas & Electric Co 81/01/26
2pp 07308:001

V. Operator Examinations

B101070377 Responds to NRC 800328 request for mods to licensed oper
training program Mods include training in heat transfer,
fluid flow & thermodynamics, installed plant sys use to
control core accident damage & emphasis on plant transients.
LUNDVALL, A.E. Baltimore Gas & Electric Co 80/06/18. 4pp
07414 134

DOCKET 80-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP hold
& CP applicants. Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B10102 & by applicants as part of FBAR.
EISENHUT, D O. Division of Licensing 80/11/13. 2pp

B101070265 Releases public version of Commonwealth of PA. Dauphin Co
evacuation plan
FELTON, J M. Division of Rules and Records. 80/12/01. 1p
07309 001

--B101070270 Public version of Commonwealth of PA. Dauphin County
evacuation plan for 1, 2, 3, 5, 10 & 20-mile radius.
HALLON, K. J. Dauphin County, PA 79/04/30. 175pp 07309:001.

B101070322 Releases public version of Commonwealth of PA emergency
plan
FELTON, J M. Division of Rules and Records. 80/12/01. 1p.
07309:001.

--B101070325 Public version of Commonwealth of PA. Dept of Environ
Resources Bureau of Radiological Health plan for nuclear
generating station incidents.
* Pennsylvania, State of. 77/09/30 8pp. 07309:001

B101160331 Releases public version of "PA Disaster Operations Plan, Annex E, Nuclear Incidents (Fixed Facilities)," as part of
util submittal.
FELTON, J. M. Division of Rules and Records. 80/12/01. 1p.
07308:001.

--B101160337 Public version of "PA Disaster Operations Plan, Annex E
Nuclear Incidents (Fixed Facilities)."
* Pennsylvania, State of. 79/03/20. 7pp. 07308:001.

B101050633 Releases public version of "Emergency Planning Around US
Nuclear Power Plants NRC Oversight," fourth rept.
FELTON, J M. Division of Rules and Records. 80/12/19. 1p.
07309:001

--B101050635 Public version of "Emergency Planning Around US Nuclea
Power Plants NRC Oversight," fourth rept.
* House of Rep., Government Operations. 79/08/08 105pp.
07309:001.

B101060405 Forwards Revision 8 to security plan. Revision B withheld
(ref 10CFR2.770)
HAKILL, R D. Metropolitan Edison Co 80/12/30. 1p. 07398 078.

B101150442 Requests that encl facility emergency planning info be m
publicly available. W/o encl 8012190094
BOUDER, J L. Division of Rules and Records. 80/12/31. 1p.
07308:001

07308 001

010190705 Requests that encl facility emergency planning info be made publicly available w/o encl
 SOUDER, J. L. Division of Rules and Records 81/01/08 1p 07472 322

010120708 Requests that encl facility emergency planning info be made publicly available w/o encl
 SOUDER, J. L. Division of Rules and Records 81/01/13 1p 07543 358

0101300117 Forwards facility emergency planning info for placement in LPDR w/o 0101070325
 SOUDER, J. L. Division of Rules and Records 81/01/19 1p 07583 091

0 Adjudicatory correspondence

003100528 Requests info re reasoning behind NRC decision to exempt facility from federal containment regulations covering personnel airlock. Supports revocation of DL Requests info re prospect of NRC action against B&W
 CLARK, D. R. Affiliation Unknown 80/03/12 2pp 95023 073

010100682 Forwards memorandum re 43 cases involving NRC Includes brief description of pending litigation, pending cases & closed cases
 FITZGERALD, J. A. Office of the General Counsel 80/12/09 35pp 07444 320

0101260234 Responds to 801216 ltr request to extend comment period on programmatic DES Comment period extended once & public meetings held in PA & MD re TMI-2 cleanup FES to be issued March 1981 Related correspondence
 SNYDER, B. J. TMI Program Office 81/01/08 2pp 07523 315

--0101260245 Requests extension of period for public review of programmatic EIS Revised draft should be issued, not final revision
 PETERSON, R. W. National Audubon Society, Central Midwest Regional Office 80/12/16 1p 07523 317

0101290762 Order authorizing organization of General Public Utility Nuclear Corp as wholly owned subsidiary for mgt & operation of nuclear plants
 FITZBIBBINS, G. Securities & Exchange Commission 80/09/15 3pp 07576 027

--0101290766 Notice of proposal to organize General Public Utility Nuclear Corp as wholly owned subsidiary for mgt & operation of nuclear plants w/related documentation
 FITZBIBBINS, G. Securities & Exchange Commission 80/06/19 85pp 07576 030

--0101290771 Request that NJ Board of Public Utility dismiss for lack of jurisdiction util & General Public Utility Nuclear Corp proposed operating agreement In alternative, agreement should be approved.
 BROKAW, R. D. Jersey Central Power & Light Co BRDKAW, R. D. Brookaw, R. D. 80/04/11 7pp 07576 130

H General correspondence

0101070084 Expresses opposition to nuclear power & radwaste
 BROWN, C. Affiliation Unknown 80/10/27 1p 07415 247

0101190517 Notifies that nine counties of eastern shore oppose dumping of water from facility, pending appraisal of impact on bay waters.
 WINGATE, W. I. Maryland, State of 80/12/02 1p 07475 357

0101050071 Requests that future correspondence for Chem-Nuclear Sys, Inc re licensed transport costs be forwarded to CP Deltete at Met Ed, instead of RW Howard
 HOVEY, Q. K. Metropolitan Edison Co. 80/12/03 1p 07385 278

0101080330 Responds to 801119 ltr requesting sections of NRC regulations re responsibility for decontamination operations at facility.
 SNYDER, B. J. TMI Program Office 80/12/11 1p 07417 351

--0101080335 Requests sections of NRC regulations re NRC responsibility if util is unable to carry out decontamination operations at facility.
 PETERSON, A. B. Affiliation Unknown 80/11/19 1p 07417 352

0101050064 Notifies of personnel changes in responsibilities for records of licensed transport costs for radioactive materials
 Responsible party for Met Ed on registered users lists should be changed to manager of Process Support Group
 HOVEY, Q. K. Metropolitan Edison Co 80/12/18 1p 07385 277

0101140239 Responds to 801204 ltr requesting info re TMI-2 accident
 Future actions can be taken at site w/o NRC review & approval Human error, plant design & equipment malfunction contributed to accident
 SNYDER, B. J. TMI Program Office 80/12/22 2pp 07461 215

--0101140246 Requests info re TMI-2 accident
 MILLER, A. Affiliation Unknown 80/12/04 2pp 07461 217

0101140705 Responds to 801126 ltr re Lebanon Valley Chamber of Commerce requests to meet w/Commission to discuss facilities situation Issues re Unit 1 are in adjudication Chamber advised that Commission member could meet re Unit 2 cleanup
 NEARNE, J. F. Commissioners 80/12/24 1p 07462 025

0101260025 Responds to FOIA request for seven categories of NRC documents Forwards computer printout indicating pertinent NUREGs & other documents published 1977-80 & documents in response to request
 FELTEN, J. H. Division of Rules and Records 80/12/31 2pp

--0101260031 Confirms that encl listed documents responding to FOIA requests were received by law firm representative
 CARR, J. C. Division of Rules and Records 80/12/18 3pp

--0101260043 Confirms that encl listed documents responding to FOIA requests were received by law firm representative.
 CARR, J. C. Division of Rules and Records 80/12/08 7pp

--0101260052 Confirms that encl listed documents responding to FOIA requests were received by law firm representative
 CARR, J. C. Division of Rules and Records 80/12/02 3pp

--0101260060 Confirms that listed documents responding to FOIA requests were received by law firm representative
 CARR, J. C. Division of Rules and Records 80/11/24 21pp

--0101260065 Confirms that listed documents responding to FOIA requests were received by law firm representative
 CARR, J. C. Division of Rules and Records 80/11/10 5pp

--0101260072 Confirms that listed documents responding to FOIA requests were received by law firm representative
 CARR, J. C. Division of Rules and Records 80/11/06 2pp

--0101260081 Confirms that listed documents responding to FOIA requests were received by law firm representative Computer printout of NUREGs published 1977-80 & 'Std Subj Identification Numbering Sys (SGINS) Basic Code' & Revision 1 encl
 CARR, J. C. Division of Rules and Records 80/10/31 204pp

--0101260091 Forwards schedule of ACRS subcommittee 790915 meeting facility accident implications Subcommittee is unfamiliar w/Michelson rept. Questions have no relevance to Ofc of Inspector & Auditor investigation
 STRICKLER, L. J. Office of Inspector & Auditor 79/09/07 1p 07507 031

--0101260099 Forwards revised tentative schedule for ACRS Ad Hoc Subcommittee 790905 meeting in Washington, DC on facility accident implications
 MAJOR, R. ACRS - Advisory Committee on Reactor Safeguards 79/08/30 3pp 07507 032

0101060023 Expresses concern re use of nuclear power. Proposes safety research & development as alternative energy resource
 VOGLER, T. R. Affiliation Unknown 81/01/02 3pp 07309 001

0101210079 Responds to 800917 ltr to President Carter expressing concern re effect of TMI-2 accident on cost of electricity. No statutory authority provides for direct federal aid for cleanup & recovery costs w/o supporting documents
 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 81/01/07 5pp 07490 222

8101210087 Responds to 800726 ltr to President Carter expressing concern re effect of TMI-2 accident on electricity costs No statutory authority provides for direct federal aid for cleanup & recovery costs w/o supporting documentation
DENTON, H R Office of Nuclear Reactor Regulation, Director.
81/01/07 3pp 07491 06B

8101210095 Responds to 800918 ltr to President Carter expressing concern re effect of TMI-2 accident on electricity costs No statutory authority provides for direct federal aid for cleanup & recovery costs w/o supporting documents
DENTON, H R Office of Nuclear Reactor Regulation, Director
81/01/07 3pp 07491 072

8101210108 Responds to 800918 ltr to President Carter expressing concern re effect of TMI-2 accident on electricity costs No statutory authority provides for direct federal aid for cleanup & recovery costs w/o supporting documentation
DENTON, H R Office of Nuclear Reactor Regulation, Director
81/01/07 3pp 07491 096

8101210253 Responds to encl 800916 ltr to President Carter re effect of TMI accident on electricity costs & need for federal assistance Resumption of TMI-1 operation is subj of hearing White House 800703 ltr to PA Public Util Commission encl
DENTON, H R Office of Nuclear Reactor Regulation, Director
81/01/07 4pp 07187 001

8101210288 Responds to encl 800719 ltr to President Carter re effect of TMI accident on electricity costs & need for federal assistance Resumption of TMI-1 operation is subj of hearing White House 800703 ltr to PA Public Util Commission encl
DENTON, H R Office of Nuclear Reactor Regulation, Director
81/01/07 4pp 0748B 207

8101210309 Responds to encl 800726 ltr to President Carter re effect of TMI accident on electricity costs & need for federal assistance Resumption of TMI-1 is subj of hearing White House 800703 ltr to PA Public Util Commission encl
DENTON, H R Office of Nuclear Reactor Regulation, Director
81/01/07 3pp 0748B 211

8101210310 Responds to encl 800729 ltr to President Carter re effect of TMI accident on electricity costs & need for federal assistance Resumption of TMI-1 is subj of hearing White House 800703 ltr to PA Public Util Commission encl
DENTON, H R Office of Nuclear Reactor Regulation, Director
81/01/07 11pp 0748B 214

8101210594 Notifies of change of address for Citizens for Safe Environ.
SQUINARD, V Citizens for Safe Environment 81/01/08 1p.
0744B 361.

8101270105 Forwards health physics evaluation per NRC 801219 ltr. w/o encl.
LEWIS, S H Hearing Branch 2 81/01/14 1p 07547 040

8101290227 Ack that "a" should be under column "Goats" on line "hair fell out, raw sores" in Table 2 5, Page 9 of NUREG-0738. Error will be corrected on future reprints or revisions
SNYDER, B J TMI Program Office 81/01/16 1p 07575 023.

--8101290240 Informs of discrepancy within NUREG-0738 On Page 7, Table 2 3 problem found w/goats losing hair & developing raw sores On Page 9, in Table 2 3 under "Miscellaneous, Hair Fell Out, Raw Sores" no animal is listed.
BRINK, Y Affiliation Unknown 80/12/17 2pp 07575 024

1 Financial information

8012160144 Forwards SEC Form 10-Q, Quarterly Financial Rept & supporting mgt comments, in response to NRC 790921, 1109 & 800811 requests for info re significant financial developments affecting utility in re-start proceeding
CONDON, V H General Public Utilities 80/11/26 3pp.

--8012160154 Quarterly Financial Rept Sept 1980 & supporting mgt comments
* General Public Utilities 80/11/14 44pp.

J Insurance & indemnity information

8101090496 Forwards 800807 press release announcing premium refunds based on pools' experience during 1969-1979, including TMI incident.
GUATTROCCHI, J American Nuclear Insurers 81/01/06 2pp.
07442:010

O Advisory Committee on Reactor Safeguards reports & correspondence

8101200315 Outlines NRC position re requirements for shutdown & decay heat removal using safety-grade equipment, in response to ACRS 790314 memo
DENTON, H R Office of Nuclear Reactor Regulation, Director.
79/09/07 3pp 07187:001

810126C025 Responds to FOIA request for seven categories of NRC documents Forwards computer printout indicating pertinent NUREGs & other documents published 1979-80 & documents in response to request
FELTON, J H Division of Rules and Records 80/12/31 2pp

P Operating license stage documents & correspondence

8101290203 Forwards EES & FR notice re decontamination & disposal of radwaste from 790328 TMI-2 accident Nonproprietary comments only should be submitted
SNYDER, B J TMI Program Office 80/08/14 1p. 07573 329

--8101290208 Notice of availability of NUREG-0683, OES for decontamination of TMI-2
SNYDER, B J TMI Program Office 80/08/11 2pp. 07573 330.

--8101290214 DRAFT PROGRAMMATIC ENVIRONMENTAL IMPACT STATEMENT RELATIVE TO DECONTAMINATION & DISPOSAL OF RADIOACTIVE WASTES RESULTING FROM MARCH 28, 1979 ACCIDENT, THREE MILE ISLAND NUCLEAR STATION, UNIT 2 Errata.
* Office of Nuclear Reactor Regulation, Director NUREG-0683
80/08/04 4pp. 07573 332

--8101290220 DRAFT PROGRAMMATIC ENVIRONMENTAL IMPACT STATEMENT RELATIVE TO DECONTAMINATION & DISPOSAL OF RADIOACTIVE WASTES RESULTING FROM MARCH 28, 1979, ACCIDENT, THREE MILE ISLAND NUCLEAR STATION, UNIT 2
* Office of Nuclear Reactor Regulation, Director. NUREG-0683.
80/07/31 250pp 07573 336

8101060270 Suggests that radwaste from TMI-2 be buried at DOE facilities, rather than at commercially-licensed burial grounds
AHEARNE, J F Commissioners. 80/10/20 2pp 07397 074.

8101100294 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under STB License amend application adding model Tech Specs to App A should be submitted within 120 days.
EISENHUT, D O Division of Licensing. 80/11/20 1p

--8101100271 Revised Pages 3/4 7-22 through 2B, D 3/4 7-5 & 7-6 & 6-STB snubber inservice insp requirements.
* Division of Licensing. 80/11/20 10pp.

8012120019 Forwards R Codell assessment of groundwater liquid pathway analysis for leakage of water from TMI-2 containment. Final analysis was completed following draft programmatic EIS & contains different results Final statement will be modified.
SNYDER, B J TMI Program Office. 80/11/25 1p. 07231:344.

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lameilar Tearing on Component Supports."
EISENHUT, D O Division of Licensing. 80/11/26 8pp.

8101060764 Notification of contract execution, Mod 1 to "Psychological Stress Response to Venting at TMI." Contractor: Uniform Svcs Univ
HAIRSTON, C A, GLAGOLA, A F. Technical Assistance Contracts Branch FIN B-6892 80/11/28 1p 07400:307.

--8101060770 Mod 1, extending contract period through 810115 w/no additional funding required to "Psychological Stress Response to Venting at TMI"
* Uniformed Services Univ. of the Health Sciences. DOUGHERTY, Technical Assistance Contracts Branch FIN B-6892. 80/11/28. 1p 07400:308

8101090728 Confirms Advisory Panel for Decontamination of TMI-2 8011 meeting to discuss radwaste mgt issues pertinent to decontamination.
TRAVERS, W TMI Program Office. 80/12/09 1p. 07430 338.

8101060955 Grants extension until 810228 to review draft programmatic EIS in response to 801118 request Serious delays re safe cleanup of facilities must be avoided
AHEARNE, J. F. Commissioners. 80/12/12 2pp. 07401:113.

--B10106095s Notifies that Advisory Panel on Decontamination of TMI-2 will be unable to meet B10131 deadline for input to decontamination issue
MINNICH, J. E. Dauphin County, PA 80/11/18 1p 07401 115

B101120159 Forwards Ofc of Stds Development fact sheet, copies of Ofc of Nuclear Reactor Regulation delegations, 791109 FR notice, marked to indicate licensing authority changes & fact sheet re impact of EPA B01120 ltr on TMI programmatic EIS
* Office of Standards Development, Director 80/12/12 3pp.
07436 321

--B101120173 Forwards EPA review of draft EIS Final programmatic EIS should provide more info re amount, nature & disposition of radwastes from TMI-2 decontamination & health effects of various exposure levels (public & occupational)
HEDEMAN, W. H. Environmental Protection Agency, 80/11/20 9pp
07437 002

B101070323 Forwards agenda for NCRP Task Group SC-38 on Disposal of Accident Generated Wastewater for B01218 meeting & site tour TMI Program Ofc has provided Task Group w/DRNL-TM-7448 re decontamination of high activity level water
SNYDER, B. J. TMI Program Office, 80/12/15 10pp

B101210445 Forwards response to questions on Rule 50.71p, "Periodic Updating of FBARS" & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame.
EISENHUT, D. O. Division of Licensing, 80/12/15 13pp.

B101050039 Requests to register as user of Model CNSI LL-50-100 radioactive mail shipping case
HOVEY, O. K. Metropolitan Edison Co 80/12/18 2pp. 07385 273.

B101190640 Provides TMI-2 Advisory Panel w/response to TD Cochran B01202 ltr re potential health effects of cleanup alternatives in programmatic EIS.
SNYDER, B. J. TMI Program Office, 80/12/22 5pp 07474 034

B101140671 Reiterates NRC B00913 request for safety evaluation of SB9 IE Circular B0-18 stated that evaluation should include basis for determining whether unreviewed safety question exists
SNYDER, B. J. TMI Program Office, 80/12/24 1p. 07462 021

B101270706 Notification of contract execution. "Provision of Technical Assistance to Assess Psychological Stress Re Decontamination & Disposal of Radwastes at TMI-2." Awarded to Human Design Group.
LITTLE, M. Administrative Contracts Branch, FIN 11-7938 80/12/30 1p. 07549 125

--B101270723 Contract. "Provision of Technical Assistance to Assess Psychological Stress Re Decontamination & Decontamination & Disposal of Radwastes at TMI-2." Awarded to Human Design Group
PARTNER, A. B. Human Design Group, PERLMAN, J. Administrative Contracts Branch, FIN 11-7938 80/12/30 5pp 07549 126.

B101200545 THE PUBLIC WHOLE BODY COUNTING PROGRAM FOLLOWING THE THREE MILE ISLAND ACCIDENT
OOTCHY, R. L., ROEB, R. J. Region 1, Philadelphia, Office of the Director, NUREG-0636 80/12/31 61pp Available at NTIS.
07476 142

B101260025 Responds to FOIA request for seven categories of NRC documents Forwards computer printout indicating pertinent NUREGs & other documents published 1977-80 & documents in response to request
FELTON, J. H. Division of Rules and Records, 80/12/31 2pp.

--B101260105 Responds to 790731 request re comparison of Michelson rept w/B&W testimony before Presidential TMI Commission Repts are not incompatible
CUMMING, J. J. Office of Inspector & Auditor, 79/08/03 1p 07507 036.

--B101260113 Requests comparison between Michelson rept & B&W testimony before Presidential TMI Commission Related documentation & Columbia Journal Review Article, "At TMI" encl.
GILINSKY, V. Commissioners, 79/07/31 25pp. 07507 037.

--B101260141 Summarizes B&W 790718-20 testimony before President's Commission on TMI Accident. Includes hearing agenda & summary of reporting relationships of witnesses Primary interest was series of memos re safety issues raised by B&W.
KELLEY, C. Office of Inspector & Auditor, 79/07/24 6pp 07507 081.

--B101260151 Informs that W Ward will attest to accuracy of draft of 790529 interview w/RC Jones from B&W WA Post news article encl.
STRICKLER, L. J. Office of Inspector & Auditor 79/07/23 07507 087

B101210237 Forwards request for addl info re contingency plan for transfer & storage of reactor containment bldg sump water
SNYDER, B. J. TMI Program Office 81/01/06 4pp 07492 034.

B101210244 Disapproves B01209 request for relief from inservice requirements of Section XI of ASME Boiler & Pressure Vessel Code Requests mod & resubmission of relief request
SNYDER, B. J. TMI Program Office 81/01/07 2pp 07492 040

B101210657 Responds to B01216 ltr to Chairman Ahearne requesting extension for comment on draft programmatic EIS NRC held series of meetings w/public & local officials in PA & MD to assure adequate public input
SNYDER, B. J. TMI Program Office 81/01/08 3pp 07488 238

B101230623 Responds to B01224 request re submittal of submerged demineralizer sys safety evaluation Review should consider IE Circular B0-18 in 10CFR50.59a criteria spec Anticipates submittal no later than B10206
HOVEY, O. K. Metropolitan Edison Co 81/01/09 1p 07510 311

B101230398 Responds to B00912 ltr re util plans to scale down c activities due to PA Public Util Commission B00918 order denying request for rate relief & NRC action schedule Encl Table 1 lists NRC requirements for safe shutdown
AHEARNE, J. F. Commissioners 81/01/12 4pp 07358 064

--B101260106 Advises of licensee actions being taken re cleanup facility Plan has been revised due to PA Public Util Commission B00918 order denying request for rate relief & NRC action schedule considered in draft programmatic EIS
DIECKAMP, H. General Public Utilities 80/09/12 3pp 07489 217

B101210379 Forwards util B01231 ltr to State of PA requesting w from permit requirements of Dam Safety Encroachment Act
HUGILL, H. D. Metropolitan Edison Co, 81/01/13 4pp. 07489 217

B101210541 Advises of planned licensee actions in response to q raised re use of organic resins in EPICOR-II prefilters Inorganic ion exchange media selected due to stability in radiation field
HOVEY, O. K. Metropolitan Edison Co, 81/01/13 2pp 07489 217

B101290244 Forwards documents in response to B10103 ltr request info to aid NCRP Task Group SC-38 on Disposal of Accident Generated Waste Water. W/o encl
SNYDER, B. J. TMI Program Office 81/01/13 3pp 07375 217

B101210340 Forwards EPICOR-II liner solidification overview sch & overview logic dtd B01210 Re-examination of alternative methods of spent resin stabilization will be conducted per Ahearne B10112 ltr to Dieckamp
HOVEY, O. K. Metropolitan Edison Co 81/01/15 3pp 07489 217

B101230534 Forwards info re disposal of EPICOR II & low activation exchange media in response to NRC B01027 ltr & B01210 telcon EPICOR II linear solidification overview schedule & overview logic encl
HOVEY, O. K. Metropolitan Edison Co 81/01/15 3pp 07308 036

B101230613 Forwards addl info dtd B01231 re util B01205 EPICOR solidification procurement specs.
HOVEY, O. K. Metropolitan Edison Co 81/01/15 20pp. 07510 311

B101290493 Informs that rept re liner module sump contamination originally intended for submittal on B10119 & postponed to B10123, now expected by B10127
HOVEY, O. K. Metropolitan Edison Co 81/01/23 1p 07568 351

B101290755 Application for Tech Specs Change Request 9B, amending License DPR-50, Certificate of SVC & Class III fee encl.
HUKILL, H. D. Metropolitan Edison Co 81/01/26 3pp. 07576: 0

0 Inspection reports, IE Bulletins & correspondence

B101070428 Forwards Suppl 1 to IE Info Notice B0-29, "Broken St Terry Turbine Steam Inlet Flange" No written response required
ORIER, B. H. Region 1, Philadelphia, Office of the Director, 80/11/26 1p. 07414:029.

B01140260 Responds to IE Bulletin 80-23. "Failures of Solenoid Valves
Mfg by Valcor Engineering Corp. No subv valves in use
in safety-related applications at Facility.
HOVEY, G K Metropolitan Edison Co 80/12/12 1p 07461 260

B01140730 Updates B01120 response to IE Bulletin 80-10. "Contamination
of Nonradioactive Sys & Resulting Potential for Unmonitored.
Uncontrolled Release of Radioactivity to Environ. Sls sys
identified w/potential for contamination
HOVEY, G K Metropolitan Edison Co 80/12/16 3pp 07461 297

R Periodic operating reports & related correspondence

B01060105 Forwards NRC TMI Program Ofc Weekly Status Rept for
B01123-120A
CELLINS, J T TMI Program Office 80/12/08 7pp 07359 107

B01090771 Weekly status rept for B01207-13
CELLINS, J T TMI Program Office 80/12/12 5pp 07430 065

B01090972 Forwards NRC TMI Program Ofc Weekly status rept for wk of
B01214-20
BARRETT, L H TMI Program Office 80/12/22 4pp 07430 001

B01140217 Forwards TMI Program Ofc Weekly status rept for wk of
B01214-20
BARRETT, L H TMI Program Office 80/12/22 4pp 07461 211

B01120543 Forwards weekly status rept for wk of B01221-B01003
BARRETT, L H TMI Program Office 81/01/05 6pp 07447 181

B01210264 Forwards NRC TMI Program Ofc weekly status rept for B01221-
B01003
BARRETT, L H TMI Program Office 81/01/05 5pp 07492 052

B01220034 Forwards TMI Program Ofc Weekly status rept for B01004-10
BARRETT, L H TMI Program Office 81/01/12 5pp 07495 220

B01140574 Forwards "TMI Aquatic Study." monthly rept for Nov 1980
Requests that document be made publicly available
HICKEY, C R Environmental Engineering Branch 81/01/13 1p
07460 265

--B01140577 "TMI Aquatic Study." monthly rept for Nov 1980
HARDACCI, G A Ichthyological Associates, Inc. 81/01/13 23pp
07460 266

B01300098 Forwards TMI Program Ofc weekly status rept for B01011-17
BARRETT, L H TMI Program Office 81/01/19 6pp 07579 334

B01270573 Forwards Ichthyological Associate "TMI Aquatic Study Monthly
Rept for Dec 1980
TEITZ, T R General Public Utilities - GPU Service Corp. 81/01/22
1p 07183 001

--B01270578 "TMI Aquatic Study Monthly Rept for Dec 1980." Study
performed for Met Ed
NARDACCI, G A, RANEY, E C Ichthyological Associates, Inc
81/01/22 24pp 07183 001

S Reportable occurrences, LERs & related correspondence

B01090325 Ack receipt of B01006 ltr re notification of overdue LER
Requests that in future, notification be discussed w/senior
resident inspector (SRI) prior to due date of rept
Discussions should include reasons & concurrence of SRI
O'RIER, B H Region 1, Philadelphia, Office of the Director
80/10/30 1p 07417 353

B01140662 RD 80-56/1P on B01212, determined that core flood tank A
had failed. Cause not stated. Details will be included in
follow-up rept
HOVEY, G K Metropolitan Edison Co 80/12/15 1p 07308 001

B01050174 Forwards LER 80-055/03L-0
HOVEY, G K Metropolitan Edison Co 80/12/24 1p 07582 105

--B01050181 LER 80-055/03L-0 on B01127, emergency diesel generator
DF-X-1B failed to start. Caused by inadequate maint of
shutdown ambient temp due to heater failure. Shutdown temp
maintained until replacement parts installed.
CHAPLIN, S D Metropolitan Edison Co 80/12/24 3pp 07382 106

B01050419 LER 80-053/01P-0 on B01223, determined that placing radia-
tion monitor HRP-220 in defeat on B01219 constituted reportable
condition. Caused by instrument malfunction. Repairs
completed
HOVEY, G K Metropolitan Edison Co 80/12/24 2pp 07390 122

B01140650 RD 80-56/1P on B01219, radiation monitor HRP-220 placed in
defeat, causing condition where radiation signal would not
place control room ventilation into recirculate. Caused by
instrument malfunction. Monitor repaired.
HOVEY, G K Metropolitan Edison Co 80/12/24 1p 07462 015

B01190482 Forwards LER 80-056/01L-0
HOVEY, G K Metropolitan Edison Co 81/01/13 1p 07474 075

--B01190486 LER 80-056/01L-0 on B01212, core flood tank A level
instrumentation determined inoperable. Caused by failed
component within containment bldg but exact determination
not made. No action required.
CHAPLIN, S D Metropolitan Edison Co 81/01/12 3pp 07474 0

B01200129 PhD-TMI-B1-01 on B01001, water samples from onsite Well 2
contained trace quantities of Cs-137 & Cs-134. Subsequent
samples on B0100B, 15 & 1105 indicated concentrations at less
than lower limit of detection. Item to be reviewed B01015
SHANAGHY, M, FASANO, A, BARRETT, L TMI Program Office 81/01/13
3pp 07487 033

B01280519 PhD-TMI-B1-02 on B01013, estimated 600 gallons of
concentrated sulfuric acid siphoned from storage tank,
through two valves, & out of 2-inch flange pipe. Valves
inadvertently opened or left open by maint.
BARRETT, L H, SHANAGHY, M, FASANO, A TMI Program Office 81/01/14
2pp 07557 048

B01230594 Advises that interim rept re slight contamination in 31st
storage modules will be submitted B01023
HOVEY, G K Metropolitan Edison Co 81/01/16 1p 07510 314

B01270637 Forwards LER 80-057/03L-0
HOVEY, G K Metropolitan Edison Co 81/01/16 1p 07548 342

--B01270671 LER 80-057/03L-0 on B01217, during surveillance procedure
4203-M10, air intake tunnel chlorine monitor found
inoperable. Caused by dirty probe which reduced sensitivity.
Probe removed, cleaned & returned to svc.
CHAPLIN, S D Metropolitan Edison Co 81/01/16 2pp 07548 3

T Hearing transcripts on non-antitrust matters

B01270250 Unofficial transcript of 790322 public meeting in
Washington, DC re protective order for all TMI records
Pp 1-8.
* Commissioners 79/05/22 9pp 07546 020

B01220261 Unofficial transcript of 790802 public briefing in
Washington, DC re resins from EPICOR-11. Pp 1-32
* Commissioners 79/08/02 33pp 07504 011

B01190554 Transcript of Advisory Council for Decontamination of TMI
B01218 meeting in Harrisburg, PA. Pp 1-92
* Advisory Council for Decontamination of TMI Unit 2 80/12/18
93pp 07473 180

B01190565 Transcript of Advisory Panel for Decontamination of TMI
B01230 meeting in Harrisburg, PA. Pp 1-107
* Advisory Council for Decontamination of TMI Unit 2 80/12/30
11pp 07473 275

U. Congressional/Executive Correspondence

B01140743 Ack receipt of comments on draft programmatic EIS re TMI
decontamination & disposal of radwaste. Comments are being
considered in final programmatic EIS scheduled for Mar 1981
issuance. W/o encl transcript of B01117 public meeting.
ENYBER, B J TMI Program Office 80/12/03 1p 07308 001

B01080279 Responds to B01112 ltr re pace of regulatory review of
cleanup program. General Public Utilities recent cutback in
cleanup operations primarily related to recent PA Public
Utility Commission action. Lists answers to specific questions.
AHEARNE, J F Commissioners 80/12/12 3pp 07422 001

--B01080304 Requests meeting to discuss handling & disposition of
level wastes from facility. Only short-term solution
available for waste removal is transfer to suitable DOE
facilities.
AHEARNE, J F Commissioners 80/10/20 2pp

DOCKETED ITEMS

B101200054 Poses questions re allocation of costs for facility cleanup.
Certificate of Svc encl
MOFFETT, T House of Rep B1/01/06 5pp 07486 317

V. Operator Examinations

B101190344 Confirms telcon re G Kunder B01215 operator license
application Waiver is requested to delete reactor operator
portion of senior reactor operator exam G Kunder is degree-
holding engineer for util
HOVEY, G K Metropolitan Edison Co B1/01/08 1p 07476 086

DOCKET 50-321 EDWIN J HATCH NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders
& CP applicants. Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B10102 & by applicants as part of FSAR.
EISENHUT, D G Division of Licensing 80/11/13 2pp

B101070518 Releases public version of util emergency plan
FELTON, J M Division of Rules and Records 80/12/01 1p.
07403 237

--B101070522 Forwards public version of Revision 3 to emergency plan
WIDNER, W A Georgia Power Co 80/01/31 1p 07403 239

--B101070526 Public version of Revision 3 to emergency plan
* Georgia Power Co 80/01/31 89pp 07403 240

B101260714 Releases public version of util emergency plan
FELTON, J M Division of Rules and Records B1/01/16 1p
07534 027

--B101260718 Forwards public version of emergency plan
WIDNER, W A Georgia Power Co B1/01/02 1p 07534 028

--B101260724 Public version of emergency plan
* Georgia Power Co B1/04/30 100pp 07534 030

J. Insurance & indemnity information

B101090350 Forwards Endorsement 97 to ANF Policy NF-215
FIELDER, J. Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc
Div. 80/12/31 3pp 07427 340.

B101090650 Forwards Endorsement 4 to NELIA Binder EB-81
FIELDER, J. Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc
Div 80/12/31 2pp 07442 050

B101090655 Forwards Endorsement 56 to NELIA Policy NF-215.
FIELDER, J. Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc
Div 80/12/31 2pp 07442 056

B101140233 Forwards Endorsement 4 to NELIA Binder EB-67.
FIELDER, J. Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc.
Div. B1/01/09. 2pp. 07441 271.

P. Operating license stage documents & correspondence

B101100254 Ltr to all licensees (except SEP licensees) forwarding
Revision 1 of inservice surveillance requirements for
snubbers under STS License amend application adding model
Tech Specs to App A should be submitted within 120 days.
EISENHUT, D. G. Division of Licensing. 00/11/20 1p

--B101100271 Revised Pages 3/4 7-22 through 28.B 3/4 7-5 & 7-6 & 6-17 to
STS snubber inservice insp requirements
* Division of Licensing. 80/11/20. 10pp.

B101220466 Ltr to all power reactor licensees & applicants forwarding
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D. G. Division of Licensing. 80/11/26. Bpp.

B101190113 Ltr to all BWR licensees forwarding B01201 generic safety

--B101190141 Generic safety evaluation re short-term actions
assure continued safe operation of operating BWRs Contin
operation of plants is acceptable pending permanent desi
cords Criteria for implementing design mods encl
* Division of Licensing 80/12/01. 212pp 07183 001

B101210445 Forwards responses to questions on Rule 50.71c. "
Updating of FSARs" & FR notice of final rule SEP plants
not comply w/rule until program is complete Non-SEP plants
must comply within specified time frame
EISENHUT, D G Division of Licensing 80/12/15 13pp

B101090970 Forwards request for addl info to complete review
program Shipping damage insps should be implemented &
performed for all safety-related items upon delivery.
REID, R W Operating Reactors Branch 4 80/12/24. 4pp

B101190351 Forwards list of TLD station locations near Facill
proposed route for exchanging TLDs for NRC direct radiatio
monitoring network W/O encl.
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials S
Branch 80/12/30 2pp 07476 083

B101060564 Forwards info for requirements of NUREG-0737, as o
WIDNER, W A Georgia Power Co 80/12/31. 267pp 07395 1

--B101060573 Tech Specs 3/4 & 7 & 3/4 7 2 re chlorine detect
control room environ control sys for Unit 2
* Georgia Power Co 80/12/31 11pp 07396 023

B101220563 Forwards "Operability Review of ECCS at Plant Hat
& 2." in response to NUREG-0737, item 11 K 3 17
WIDNER, W A Georgia Power Co B1/01/16 1p 07503 077

--B101220569 "Operability Review of ECCS at Plant Hatch Unit
* General Physics Corp GP-R-33009 80/12/22 73pp

B101290578 Responds to NUREG-0619, "BWR Feedwater Nozzle & C
Drive Return Line Nozzle Cracking." Mods will be performed
during 1982 refueling outages Feedwater & control rod driv
repts will be submitted within time limits specified.
WIDNER, W A Georgia Power Co B1/01/22 3pp 07575 003

0 Inspection reports, IE Bulletins & correspondence

B012240275 Responds to IE Bulletin 80-17 Ultrasonic transduc
not be installed as previously reported in B00819 ltr
Devices found unreliable in environ. Cause of float failure
under investigation
WIDNER, W A Georgia Power Co 80/11/18 1p 07328 211

B101100682 Forwards IE Insp Repts 90-321/80-43 & 90-366/80-4
B01104-07. No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Eng
Support Branch 80/11/25 2pp 07443 167

--B101100689 IE Insp Repts 90-321/80-43 & 90-366/80-43 on B0
noncompliance noted. Major areas inspected installed
equipment review per IE Bulletin 79-018
O'BROCHS, T D., CONNELL, T E. Region 2, Atlanta, Office of
Director. 80/11/25. 4pp 07443 169.

B101080202 Responds to IE Bulletin 80-21 re valve yokes supp
Malcolm Foundry Co, Inc No such yokes used in facility
Valve documentation indicates other foundries made valve
yokes in use
WIDNER, W A Georgia Power Co 80/11/26 1p 07420 359

B101050602 Forwards IE Info Notice 80-43, "Failures of Cont
Level Monitor for Steam Discharge Vol at Dresden Unit 2."
response required.
O'REILLY, J P. Region 2, Atlanta, Office of the Director.
1p 07391 018

B101070331 Ack receipt of B01008 ltr requesting re-evaluation
dismissal of apparent noncompliance item contained in West
Packaging Insp Repts 90-321/80-32 & 90-366/80-32 item
withdrawn
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials S
Branch 80/12/11 1p 07408 124

--B101070334 Responds to NRC B00917 ltr re violations noted
Packaging Repts 90-321/80-32 & 90-366/80-32 Requests
re-evaluation & dismissal of cited noncompliance All

--B101070336 Forwards Waste Packaging Insp Repts 50-321/80-32 & 50-366/80-32 on 800731 & notice of violation
STONER, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/09/17 2pp 07408 127

--B101070338 Notice of violation from insp on 800731
* Region 2, Atlanta, Office of the Director 80/09/15 1p 07408 129

--B101070342 Waste Packaging Insp Repts 50-321/80-32 & 50-366/80-32 on 800731 Noncompliance noted radwaste shipment not properly placarded
MACARTHUR, T. C. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/09/15 3pp 07408 130

B101060126 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Scram Capability." No response required
D'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/12/17 1p 07397 339

B101070333 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of 76 of 185 Control Rode to Fully Insert During Scram at BWR." No written response required
D'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/12/18 1p 07413 329

B101050159 Forwards IE Bulletin 80-25, "Operating Problems W/Target Rock Safety Relief Valves at BWRs." No response required
D'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/12/19 2pp 07377 259

B101270185 Responds to IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (Oct 17, 1980 Indian Point 2 Event)." Drywell cooling sys composed of six cooling units each w/ two fans. Normally only one fan per unit is operating
WIDNER, W. A. Georgia Power Co. 81/01/05, 7pp. 07569 346

B101290376 Responds to IE Bulletin 80-07, "BWR Jet Pump Assembly Failure." No abnormal wear, stress or failed welds discovered during visual exams of Unit 2 assemblies by remote underwater television cameras. Insp of Unit 1 scheduled
WIDNER, W. A. Georgia Power Co. 81/01/13, 1p. 07375 131

B101290385 Responds to IE Bulletin 80-13, "Cracking in Core Spray Spargers." No cracking of core spray spargers or piping between inlet nozzle & vessel throat was identified in Unit 2 Insp for Unit 1 scheduled during Winter 1981.
WIDNER, W. A. Georgia Power Co. 81/01/13, 1p 07375 132

B101300374 Responds to request for confirmation of response to IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls." Tests will be completed by Feb 1981 & June 1981 for Units 1 & 2, respectively.
WIDNER, W. A. Georgia Power Co. 81/01/26 2pp. 07586 350

R Periodic operating reports & related correspondence

B101260463 Forwards monthly operating rept for Dec 1980.
MANN, R. M. Georgia Power Co. 81/01/10 1p 07524 020

--B101260468 Monthly operating rept for Dec 1980.
KAMISHIAN, J. M. Georgia Power Co. 81/01/10, 9pp 07524 021

B101280189 Forwards monthly operating rept for Dec 1980.
MANN, R. M. Georgia Power Co. 81/01/10 1p 07556 285

--B101280197 Monthly operating rept for Dec 1980.
KAMISHIAN, J. M. Georgia Power Co. 81/01/10, 9pp. 07556 286

G Reportable occurrences, LERs & related correspondence

B101050235 RD on B01213, sprinkler sys providing protection for reactor bldg heating, ventilation & air conditioning room had been inoperable for 14 days. Sys isolated to implement mods for corrective action to open item in IE Rept 50-321/80-02
MANN, R. M. Georgia Power Co. 80/12/19 2pp 07378 324

B101050427 RD on B01213, sprinkler sys providing protection for reactor bldg heating, ventilation & air conditioning had been inoperable for 14 days. Caused by implementation of design mods to bring sys into AFPA code compliance.
MANN, R. M. Georgia Power Co. 80/12/19, 2pp. 07389 326

B101060582 Forwards LER 80-122/01T-0.
MANN, R. M. Georgia Power Co. 80/12/30, 1p. 07391 126

--B101060593 LER 80-122/01T-0 on B01219, QC insp of cable spreading control bldg sprinkler hangers installed in 1978 revealed deficiencies which jeopardize seismic qualification of sprinkler sys. Caused by improper installation
COGGI, C. L. Georgia Power Co. 80/12/30 3pp 07391 127

B101060640 Forwards LER 80-119/03L-0
MANN, R. M. Georgia Power Co. 80/12/30 1p 07392 180

--B101060660 LER 80-119/03L-0 on B01212, routine channel check showed fission product monitors 1011-K631, particulate count & 1011-K633, noble gas count, were out of calibr. Caused by discriminator setpoint drift. Setpoint adjusted
NIX, R. T. Georgia Power Co. 80/12/30 2pp 07392 181

B101060514 Special Rept 1-sp-80-3 on 801206, during routine survey waste oil drums, several areas on ground were found to be contaminated. Caused by storage of previous waste oil drums. Add controls re release of contaminated oil under review
MANN, R. M. Georgia Power Co. 80/12/31, 4pp 07392 189

B101120298 Forwards LER 80-126/03L-0
MANN, R. M. Georgia Power Co. 81/01/06 1p 07447 122

--B101120303 LER 80-126/03L-0 on B01226, dinitrogen storage tank in reduced to below Tech Spec level. Caused by pressure control valve sticking causing tank relief valve to open. Pressure control loop placed in manual control
BAXLEY, S. X. Georgia Power Co. 81/01/06 2pp 07447 123

B101120307 Forwards LER 80-118/03L-0
MANN, R. M. Georgia Power Co. 81/01/06 1p 07447 132

--B101120358 LER 80-118/03L-0 on B01212, IE11-F015D valve, BWR inbo injection, was leaking. Caused by cracks on seating surfaces of valve disc. Valve seats lapped & new disc installed
NIX, R. T. Georgia Power Co. 81/01/06 2pp 07447 133

B101230454 Forwards LER 80-127/03L-0
MANN, R. M. Georgia Power Co. 81/01/13 1p 07308 001

--B101230463 LER 80-127/03L-0 on B01223, w/unit in steady state op research for 9-yr inservice insp rept revealed lack of documentation proving visual insp of 50% of class 1 valve internals. Caused by procedural deficiency
COGGI, C. L. Georgia Power Co. 81/01/13 3pp 07308 001

B101260543 Forwards LER 80-124/03L-0
MANN, R. M. Georgia Power Co. 81/01/13 1p 07531 137

--B101260626 LER B1-124/03L-0 on B01228, control room air intake valve 1741-F012 failed to close in required time. Caused by faulty pilot solenoid operator. Pilot solenoid replaced
NIX, R. T. Georgia Power Co. 81/01/15, 2pp 07531 138

B101260592 Forwards LER B1-001/01T-0
MANN, R. M. Georgia Power Co. 81/01/15 1p 07531 153

--B101260688 LER B1-001/01T-0 on B01228, HPCI steam line pressure IE41-N001a, c.d. actuated outside Tech Specs. Caused by switch setpoint drift. Switches recalibr.
NIX, R. T. Georgia Power Co. 81/01/15 2pp 07531 154

B101260601 Forwards LER 80-123/03L-0
MANN, R. M. Georgia Power Co. 81/01/15, 1p. 07531 156

--B101260614 LER 80-123/03L-0 on B01219 & B01226, turbine trip & valve on reactor core isolation cooling sys failed. Failures caused by gall on valve poppet & body & improper limit switch setting. Gall removed & switch reset.
NIX, R. T. Georgia Power Co. 81/01/15, 2pp. 07531 157

DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & Applicants for summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D. O. Division of Licensing, 80/11/26, 8pp.

B10190379 Requests Class II fee for review of B01126 application extension of completion date in CPBR-95 Application involves

DOCKETED ITEMS

8101130368 Certifies that Amend 28 to license application, consisting of Revision 20 to FSAR (OL stage) was sent by parcel post on 801211
MORIN, J P Long Island Lighting Co 80/12/19 1p 07456-018

8101050109 Forwards response to 801001 info request re environ qualification tests of safety-related equipment
NOVARRO, J P Long Island Lighting Co 80/12/21 App. 07376-225

8101190505 Ltr to all BWR applicants for OL re BWR scram discharge sys safety evaluation & requirements. Rept specifying acceptable basis for continued BWR plant operation & design criteria for scram discharge vol encl
TEDESCO, R L Assistant Director for Licensing. 80/12/22 2pp 07183-001.

--8101190514 Forwards generic safety evaluation re BWR scram discharge sys. Review identified two addl requirements to those proposed by owners group re scram discharge vol designs. Rept should be transmitted to license applicants.
CHECK, P S Assistant Director for Plant Systems 80/12/01 2pp. 07183-001

8101200157 Summary of 801210 meeting w/Mark II owners re status of generic improved chugging load model. Owners requested to justify delay in program & investigate alternatives.
ANDERSON, C J Generic Issues Branch 80/12/22 App. 07486-143

8101140955 Summary of Dec 1980 meeting w/Mark II owners group. OE, BNLL, MIT, B&W, Bechtel & Ebasco Svcs. Inc re suppression pool temp limits. List of attendees & handouts encl
SU, T M. Generic Issues Branch 80/12/30 41pp. 07457-063.

8101270165 Notification of 810113 meeting w/util in Silver Spring, MD re seismic qualification program & current program status
WILSON, J Licensing Branch 1 81/01/06 3pp. 07545-360

8101260470 Forwards Class II amend fee for application to extend CPPR-95 completion date in response to NRC 801218 request.
WALSH, E J Long Island Lighting Co. 81/01/16 1p 07532-033

--8101260473 Forwards util 810116 ltr & Class II amend fee.
DIOGOS, R M License Fee Management Branch. 81/01/22 1p 07532-034.

F. Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants. CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing 80/11/13 2pp

G. Adjudicatory correspondence

8101060001 Forwards 801230 joint motion to accept stipulation & for protective order on security plan info & draft protective order & affidavit.
BORDENICK, B. M. Hearing Branch 4. 80/12/31. 2pp. 07397-053

--8101060002 Joint motion to accept stipulation of relationship between Suffolk County Contention 18 & specific portions of security plan & to issue protective order on security plan info w/ draft order & affidavit of nondisclosure.
EARLEY, A F Long Island Lighting Co. BORDENICK, B M. Hearing Branch 4. DEMPSEY, P A. Suffolk County, NY. 80/12/30. 11pp. 07397-055.

8101070412 Requests NRC institute proceeding & schedule hearings per 10CFR 2.206 & Section 189 of Atomic Energy Act re proposed CPPR-95 extension from 801231 to 830331. More detailed basis for request to be submitted by 810109.
LATHAM, S B. Twomey, Latham & Schmitt 80/12/31. 3pp. 07414-140

8101070465 Advises of Shoreham Opponents Coalition position that CP should be suspended pending requested hearings re revocation. Issues for consideration during hearings will be detailed in 810109 submittal.
LATHAM, S B. Twomey, Latham & Schmitt. 80/12/31. 3p 07414-323

--8101070468 Forwards util request for extension until 830331 to complete facility
BORDENICK, B. M. Hearing Branch 4. 80/11/28. 1p 07414-326

8101200059 Order granting 801231 joint motion to accept stipulation & for protective order on security plan info.

--8101200062 Protective order granting 801231 joint motion on plan info. Permits access to protected info upon listed conditions. Certificate of Gov encl
BOKERS, E S Atomic Safety and Licensing Board Panel 81/01/23 8pp 07486-328

8101270675 Forwards petition of Shoreham Opponents Coalition to institute proceedings on whether good cause exists to extend completion date for CPPR-95
ROOP, J E., LATHAM, S B. Twomey, Latham & Schmitt 81/01/23 075-18 113

--8101270678 Petition for Shoreham Opponents Coalition to institute proceedings on whether good cause exists to extend completion date of CPPR-95
ROOP, J E., LATHAM, S B. Twomey, Latham & Schmitt 81/01/23 075-18 114

--8101270683 'Conservation Alternative to Power Plant at Shoreham Island.'
RASKIN, P D., BIEHALD, B., MCANULTY, D. Energy Systems Research Group, Inc. ESRO 80-31 80/11/30 132pp 07548-147

8101280212 Requests that ASLB accept encl fifth stipulation
EARLEY, A F Hutton & Williams 81/01/23 1p 07556-295

--8101280222 Fifth stipulation that Suffolk County Contentions 11a(iv), 11a(v) & 12(iv) will be dropped. Generic issues 11 8 & 11.5A will not be pursued. Other contentions intended to be dropped. Listed
EARLEY, A F Long Island Lighting Co. BORDENICK, B M. Hearing Branch 4. DEMPSEY, P A. Suffolk County, NY. 81/01/21 3p 07556-296.

X Utility Final Safety Analysis Report (FSAR) & amendments

8101130368 Certifies that Amend 28 to license application, consisting of Revision 20 to FSAR (OL stage) was sent by parcel post on 801211
MORIN, J P Long Island Lighting Co 80/12/19 1p 07456-018

Q Inspection reports, IE Bulletins & correspondence

8101100534 Forwards IE Insp Rept 50-322/80-16 on 800915-1022 Noncompliance noted.
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/11/20 2pp 07444-289.

--8101100542 IE Insp Rept 50-322/80-16 on 800915-1022 Noncompliance noted. Major areas inspected work activities, preoperational testing & plant staff activities.
HIGGINS, J C Region 1, Philadelphia, Office of the Director
KIBLER, H B Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/11/19. 8pp 07444-291

8101070407 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Steam Turbine Inlet Flange." No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/11/26 1p. 07414-065

8101050125 Forwards IE Info Notice 80-43, "Failures of Continuous Level Monitor for Scram Discharge Vol at Dresden Unit 2." No response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/05 1p. 07397-343

8101060129 Forwards IE Info Notice 80-45, "Potential Failure of Backup Manual Scram Capability." No response required.
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/17. 1p 07397-342.

8101070044 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of Control Rods to Fully Insert During Scram at BWR." No written response required.
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/18. 1p 07414-005.

8101190812 Forwards IE Bulletin 80-25, "Operating Problems w/ Rock Safety-Relief Valves at BWRs." No response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/19. 1p. 07464-294

S Reportable occurrences, LERs & related correspondence

B101060485 Forwards preliminary version of "Reactor Bldg Separating Analysis Rept." providing description of analysis performed & including results for reactor bldg primary containment drywell area & B-ft elevation of second containment
MDVARRD, J.P. Long Island Lighting Co 80/12/22 1p 07393 023

--B101060489 Preliminary version of "Reactor Bldg Separation Analysis Rept."
Stone & Webster Engineering Corp 11600 02-158A 80/12/22 75pp 07593 024

B101190319 Ack receipt of util 801120 final deficiency rept re use of inferior lubricant on 480V Nema Size 3 contactors for Square D rotor control ctrs
CARLSON, R. I. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/30 1p 07476 051

--B101190327 Interim deficiency rept re use of inferior lubricant on 480V Nema Size 3 contactors for Square D rotor control ctrs. Initially reported on 801022. Factory representative will repair 15 contactors by Feb 1981
MDVARRD, J.P. Long Island Lighting Co 80/11/20 2pp 07476 052

DOCKET 50-323 DIA3LO CANYON NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B10112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lateral Tearing on Component Supports."
EISENHUT, D. O. Division of Licensing 80/11/26 0pp

B101130339 Recommends denial of D Fleischaker 801017 request that Commission issue supplemental EIS re environ consequences of Class 7 accident at facility. No evidence presented to warrant reopening environ record
MCLEOD, D. A. Pacific Gas & Electric Co 81/01/08 2pp 07451 275

B101210555 Forwards environ qualification of Class 1E control cable mfg by Continental Wire & Cable Co. Requests ack of receipt
CRANE, P. A. Pacific Gas & Electric Co 81/01/16 11pp 07489 266

B101270672 Forwards addl info re QA program per NRC 801007 request. Info will be incorporated into FSAR
CRANE, P. A. Pacific Gas & Electric Co 81/01/22 29pp 07345 193

B101300331 Forwards info addressing issues to be reviewed for full power operation, including operating procedures, control room design, preoperational & low power testing, auxiliary feedwater sys, containment design & radiation protection.
CRANE, P. A. Pacific Gas & Electric Co 81/01/26 106pp 07594 174

F Security, medical, emergency & fire protection plans

B101090337 Ltr to all licensors of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D. O. Division of Licensing 80/11/13 2pp

B101060012 Requests evaluation of potential complicating factors caused by earthquakes which either initiate or follow initiation of accidents. Adequacy review of state & local capabilities re earthquakes requested of FEMA
TEDESCO, R. L. Assistant Director for Licensing 80/12/16 5pp 07399 048

B101100819 Informs that licensees must conduct emergency exercises within one yr from B10101 or prior to issuance of CL. Requests schedule of drills & exercises
ENGELKEN, R. H. Region 9, San Francisco, Office of the Director 80/12/19 1p 07442 290

B101100741 Requests that encl facility emergency planning info be made publicly available w/o encl
SOUDER, J. L. Division of Rules and Records 80/12/31 1p 07445 127

B101100832 Notifies of acceptance of 600711 guard training & qualification plan
MIRAGLIA, F. J. Licensing Branch 3 81/01/01 3pp 07442 299

B101120591 Forwards comments re Revision 10 of physical security plan to be resolved prior to license issuance. Comments withheld (ref 10CFR2 7901)
MIRAGLIA, F. J. Licensing Branch 3 81/01/01 5pp 07447 204

B101190696 Requests that encl facility emergency planning info be made publicly available w/o encl 8012240129
SOUDER, J. L. Division of Rules and Records 81/01/09 1p 07472 323

B101190700 Requests that encl facility emergency planning info be made publicly available w/o encl 8012240469
SOUDER, J. L. Division of Rules and Records 81/01/09 1p 07472 321

B101300722 Releases public version of util emergency plan response.
FELTON, J. M. Division of Rules and Records 81/01/26 1p 07584 159

--B101300728 Forwards public version of response to NRC 800826 request for addl info re site emergency plan, Revision 2 & 800830 request re field property
CRANE, P. A. Pacific Gas & Electric Co 81/01/13 62pp 07584 160

--B101300735 Superior Court order granting land rights to util for implementation of emergency response plans.
MIRKPATRICK, R. California, State of 80/10/14 3pp 07584 2

G Adjudicatory correspondence

B101050382 Response to joint intervenors' contentions & CA Governor Brown statement on subj in which he intends to participate. Opposes litigating contentions because record is closed & no grounds exist to reopen records.
CRANE, P. A., GEHR, A. C. Pacific Gas & Electric Co. GEHR, A. C. Sno Wilner 80/12/18 47pp 07385 099

--B101050388 Advises that FEMA/NRC Steering Committee has determined low power testing criteria are not needed. Encl position is adequate
CRIMES, D. K. Emergency Preparedness Program Office (after B01111 see 16E). RYAN, R. Office of State Programs, Director 80/12/18 2pp 07385 146

B101060018 Response to Joint Intervenors request for directed certification. Opposes request because record is closed on all issues & request raises no significant new evidence. Certificate of Svc encl.
CRANE, P. A., GEHR, A. C. Pacific Gas & Electric Co. GEHR, A. C. Sno Wilner 80/12/18 37pp 07397 066

B101210136 Informs that technical divisions will provide testimony to refute CA Governor Brown B01203 Contentions 1, 2, 3 & 5 re fuel load/low power license.
TEDESCO, R. L. Assistant Director for Licensing 80/12/31 1p 07489 361

B101090223 Request identified as proposed findings of fact, that AB 790927 partial initial decision be affirmed. Decision concluded that 0.75 g acceleration was appropriate, reasonably reasonable & Category 1 structures adequate.
OLMSTEAD, W. J., KETCHEN, E. O. Hearing Branch 4 81/01/06 88pp 07423 284

B101120459 Certifies svc of NRC proposed findings of fact & conclusions of law in reopened seismic proceedings & response to ASLAB questions on B10106.
KETCHEN, E. O. Hearing Branch 4 81/01/06 3pp 07447 169

B101140877 Requests that WC Martin, Datelle-Columbus Labs, be deleted from svc list
BACHERS, E. B. Atomic Safety and Licensing Board Panel 1 81/01/08 07459 218

B101140949 Joint Intervenors' reply to applicant & NRC responses to statement of contentions. Objections undermined by recent NRC revision of 780520 statement of policy. Adopts Governor Brown contentions. Certificate of Svc encl.
REYNOLDS, J. R., OLEISCHAKER, D. San Luis Obispo Mothers for Peace REYNOLDS, J. R. Center for Law in the Public Interest 81/01/08 10pp 07458 227

B101140279 Response to ASLD 801217 order requesting continued deferral of Joint Intervenors 790509 motion on Class 9 issues. Emergency planning contentions must be admitted & ASLAB decision on seismic matters issued. Certificate of Svc encl.
OLMSTEAD, W. J. Hearing Branch 4 81/01/12 15pp 07458 124

8101140925 Forwards NRC Div of Licensing B10101 ltr to util re
Revision 10 to security plan & NRC comments on revision
Comments withheld (ref 10CFR2 790) w/o ltr
SHARTZ, L. L. Office of the Executive Legal Director. 81/01/12. 1p
07458 262

8101160278 Supplement to reply to P&E & NRC responses to Joint
Intervenor's statement of contentions On Page 5, Line 9, 17
should be deleted & on Line 14, 14, 18 & 20 deleted & 14, 15,
18, 19 & 24 inserted Certificate of Svc encl.
REYNOLDS, J. R. San Luis Obispo Mothers for Peace REYNOLDS, J. R.
Center for Law in the Public Interest FLEISCHAKER, D. Fleischaker.
D 8 81/01/12 5pp 07470 279

8101260301 Response opposing Joint Intervenor's & CA Governor Brown
801215 proposed findings re 791015 Imperial Valley
earthquake Certificate of Svc encl
MORTON, B., FURBUSH, M. H., GEHR, A. C. Pacific Gas & Electric Co.
81/01/16. 32pp. 07523 340.

8101270739 Brief discussing definition of "several" as used in
10CFR73.1(a)(1). Term "several" means up to & including three
attackers
SHARTZ, L. L. Antitrust Division DLMSTEAD, W. J. Hearing Branch 4.
81/01/19 8pp. 07183 001.

8101280131 Order scheduling 810128 conference w/ASLB & parties' counsel
in Bethesda, MD re matters discussed in 810121 conference
call Certificate of Svc encl
BOWERS, E. S. Atomic Safety and Licensing Board Panel 81/01/21
7pp. 07556 093

8101280620 Response to Joint Intervenor's 810108 reply to applicant &
NRC responses to contentions Revised statement of policy.
CL1-80-42, did not change Commission position. TMI-related
contentions must be denied w/ Certificate of Svc
MORTON, B., FURBUSH, M. H., GEHR, A. C. Pacific Gas & Electric Co.
81/01/23 13pp 07557 292

H General correspondence

8101120046 Urges rejection of Facility license in light of TMI
incident.
ROBINSON, T. Affiliation Unknown. 79/04/04. 1p 07447 085

8101090372 Responds to 790404 postcard re facility. NRC has reacted
positively to improve safety of all nuclear power plants in
operation & under const. Response to concern re proximity of
Hogri fault to Facility encl
MIRAGLIA, F. Licensing Branch 3 80/12/11. 3pp 07425 268

8101060030 Responds to 790414 ltr expressing concerns re facility
safety. Low level radioactivity effects, storage of high
level radwaste & ability to withstand severe earthquakes
poses insignificant level of danger to public.
MIRAGLIA, F. J. Licensing Branch 3. 80/12/16 6pp. 07399 191.

8101090751 Responds to Apr 1979 ltr to President Carter expressing
concern re nuclear power safety. NRC currently requires all
applicants for new DLs to modify design & operation of
nuclear plants to conform to TMI-related requirements.
MIRAGLIA, F. J. Licensing Branch 3. 80/12/16. 6pp. 07309 001

810120002 Responds to 790402 ltr NRC is presently conducting generic
proceeding to reassess degree of confidence in disposal
methods to determine disposal availability & to provide
storage
MIRAGLIA, F. J. Licensing Branch 3. 80/12/16 4pp. 07447 105.

8101120191 Responds to 801208 ltr ASLB considering application for UL
authorizing fuel loading & low power testing of Unit 1.
ASLB reviewing portions of ASLB "Partial Initial Decision"
re seismic matters & applicant physical security plan
INGRAM, F. L. Office of Public Affairs. 80/12/16 1p. 07309 001.

--8101120196 Requests info re status of facility & names of
decisionmakers.
QANNIS, S. Affiliation Unknown. 80/12/08. 1p. 07309 001.

8101190128 Ack receipt of 801214 ltr expressing concern re opening of
facilities. Ltr will be placed in appropriate public docket
file.
HANCHETT, J. Q. Region 5, San Francisco. Office of the Director.
81/01/02 1p. 07475 323.

--8101190161 Expresses concern re opening of facilities.
HAYS, M. Affiliation Unknown. 80/12/14 1p. 07475 324.

8101190286 Ack receipt of 801227 ltr expressing concern re opening of
facilities. Ltr will be placed in appropriate public docket
file.
HANCHETT, J. Q. Region 5, San Francisco. Office of the Director.
81/01/02 1p 07476 089

--8101190797 Expresses concern re opening of facilities.
BERRIGAN, S. Affiliation Unknown. 80/12/27 1p 07476 090.

8101200209 Ack receipt of 801227 ltr expressing concern re opening of
facilities. Ltr will be placed in appropriate public docket
file.
HANCHETT, J. Q. Region 5, San Francisco. Office of the Director.
81/01/02 1p 07187 001.

--8101260126 Expresses concern re opening of facility
HOFBERG, S. J. Affiliation Unknown. 80/12/27 1p 07187 001

Q Inspection reports, IE Bulletins & correspondence

8101050014 Responds to IE Bulletin 80-19 No CP Clare Model H22x-1011
mercury-wetted relays used in logic matrix at facility
CRANE, P. A. Pacific Gas & Electric Co. 80/11/25. 1p 07187 001

8101130366 Forwards completed response to IE Bulletin 79-02 re pipe
support base plate designs using concrete expansion bolts
CRANE, P. A. Pacific Gas & Electric Co. 80/12/03 11pp 07309 001

8101090504 Forwards IE Info Notice 80-43, "Failures of Continuous Wa
Level Monitor for Steam Discharge Val at Dresden Unit 2 "
No response required
ENGELKEN, R. H. Region 5, San Francisco. Office of the Director
80/12/05 1p 07387 292

8101190822 Forwards IE Info Notice 80-44, "Actuation of ECCS in
Recirculation Mode While in Hot Shutdown " No response
required
ENGELKEN, R. H. Region 5, San Francisco. Office of the Director
80/12/16 1p 07308 001.

8101210145 Forwards IE Insp Repts 50-275/80-22 & 50-323/80-11 on
801202-05 & 10 No noncompliance noted
SPENCER, Q. B. Region 5, San Francisco. Reactor Construction &
Engineering Support Branch 80/12/24 2pp 07490 001

--8101210153 IE Insp Repts 50-275/80-22 & 50-323/80-11 on 801202-05
No noncompliance noted. Major areas inspected. Licensee action
on previous insp findings, QA audits & cleanup crew work
control sys procedures
BODDS, R. T. Region 5, San Francisco. Reactor Construction &
Engineering Support Branch. MIRBCH, D. F. Region 5, San Francisco
Office of the Director. 80/12/23 7pp 07490 003

I Hearing transcripts on non-antitrust matters

8101300364 Transcript of 810128 hearing in Bethesda, MD. Pp 1-206
* Atomic Safety and Licensing Board Panel 81/01/28 210pp
07578 248

DOCKET 50-324 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants. CP holds
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
810102 & by applicants as part of FBAR
EISENHUT, D. G. Division of Licensing 80/11/13 2pp

8101140325 Requests that encl facility emergency planning info be re
publicly available. w/o encl
SHUDER, J. L. Division of Rules and Records 80/12/31. 1p
07458 010

8101230058 Releases public version of util evacuation study
FELTON, J. H. Division of Rules and Records 81/01/08 1p
07511 026

--8101230066 Forwards public version of preliminary results of
evacuation study for 10-mile emergency planning zone, in
response to NRC 791129 request. Final rept will be available
approx 810201
UTLEY, E. E. Carolina Power & Light Co. 80/12/09 6pp. 07511 010

8101260631 Releases public version of util revised emergency plan
FELTON, J. H. Division of Rules and Records. 81/01/16 1p
07524 308.

0637 Forwards public version of revised radiological emergency
w/o State of SC emergency plan Cross-ref against
C-0634 criteria encl
Y.E.E Carolina Power & Light Co 80/12/30 6pp 07524 310

0644 Public version of revised radiological emergency plan w/o
of SC emergency plan.
Carolina Power & Light Co 80/12/31 150pp 07524 316

ling license stage documents & correspondence

54 Ltr to all licensees (except SEP licensees) forwarding
on l of inservice surveillance requirements for
rs under STS License amend application adding model
pers to App A should be submitted within 120 days
UT.D O Division of Licensing 80/11/20 1p

00271 Revised Pages 3/4 7-22 through 28.B 3/4 7-5 & 7-6 & 6-17 to
scrubber inservice insp requirements
Division of Licensing 80/11/20 10pp

66 Ltr to all power reactor licensees & applicants forwarding
y of 801112 meeting re implementation of guidance for
lved Safety Issue A-12. "Potential for Low Fracture
ess & Lateral Tearing on Component Supports"
UT.D O Division of Licensing 80/11/26 6pp

13 Ltr to all BWR licensees forwarding 801201 generic safety
tion re BWR scram discharge sys Recommends short-term
s necessary to assure safe operation of OE BWRs
g permanent design changes
UT.D O Division of Licensing 80/12/09 2pp

0141 Generic safety evaluation re short-term actions required to
re continued safe operation of operating BWRs. Continued
ation of plants is acceptable pending permanent design
Criteria for implementing design mods encl
Division of Licensing 80/12/01 212pp 07183 001

45 Forwards responses to questions on Rule 50.71e. "Periodic
ing Tech Specs & FR notice of final rule SEP plants need
mply w/rule until program is complete Non-SEP plants
mply within specified time frame
UT.D O Division of Licensing 80/12/15 12pp

32 Forwards Amends 33 & 34 to Licenses DPR-71 & DPR-62.
tively, safety evaluation & notice of issuance &
bility
TD.T A Operating Reactors Branch 2 80/12/23 2pp.
162

0539 Amends 33 & 34 to Licenses DPR-71 & DPR-62, respectively.
sing Tech Specs to provide one-time extension of certain
veillance intervals allowing required testing to be
ormed
LT.D.T A Operating Reactors Branch 2 80/12/23 39pp
18 164

0545 Safety evaluation supporting Amends 33 & 34 to Licenses
71 & DPR-62, respectively
Office of Nuclear Reactor Regulation, Director 80/12/23 3pp
088 202

0550 Notice of issuance & availability of Amends 33 & 34 to
enses DPR-71 & DPR-62, respectively
LT.D.T A Operating Reactors Branch 2 80/12/23 2pp.
18 205

043 Forwards Amends 32 & 33 to Licenses DPR-71 & DPR-62.
tively, safety evaluation & notice of issuance &
bility
TD.T A Operating Reactors Branch 2 80/12/29 2pp.
086

0557 Amends 32 & 33 to Licenses DPR-71 & DPR-62, respectively.
sing Tech Specs by adding limiting conditions for
ations w/bases to clarify term operable as applied to
ty sys
LT.D.T A Operating Reactors Branch 2 80/12/29 18pp
18 088

0566 Safety evaluation supporting Amends 32 & 33 to Licenses
71 & DPR-62 respectively
Office of Nuclear Reactor Regulation, Director. 80/12/29 2pp.
18 106

0571 Notice of issuance & availability of Amends 32 & 33 to
ense DPR-71 & DPR-62 respectively
LT.D.T A Operating Reactors Branch 2 80/12/29 2pp
18 108

8101060494 Forwards rept entitled: "Control Room Habitability
Evaluation, Brunswick Steam Electric Generating Plant." Rept
responds to all info requested in NUREG-0737 & NRC 800507
jtr
UTLEY, E E Carolina Power & Light Co 80/12/30 3pp 07393 099.

--8101060494 "Control Room Habitability Evaluation, Brunswick Steam
Electric Generating Plant"
SLIDER, J E., ARCIERI, W C., BROADHURST, R H NUS Corp. NUS-3697
80/12/31 112pp. 07393 102

8101140188 Requests FR publication of encl notice of issuance of
facility QL or amend Referenced documents are available in
PDR w/o encl.
* Operating Reactors Branch 2 80/12/30 1p 07461 208

8101160555 Informs that 801105 application requesting extension of
end dates for performing certain insp & tests requires
Class III fee for one unit & Class I fee for second unit.
1008, R M License Fee Management Branch 80/12/30. 1p.
07471 296

8101060587 Responds to NUREG-0737 re clarification of post-TMI action
plan requirements Items addressed: shift technical
supervisor, training for mitigating core damage, containment
isolation dependability & inplant radiation monitoring.
UTLEY, E E Carolina Power & Light Co 80/12/31 140pp. 07399 175.

8101160442 Provides update re Mark I containment program mods.
Completion scheduled for Jul 1982 Plant unique analysis
experiencing 3-month slippage which will delay completion.
UTLEY, E E Carolina Power & Light Co 81/01/08 1p. 07472 102.

8101190414 Forwards corrected Pages 4-7 & 6-9 to "Control Room
Habitability Evaluation, Brunswick Steam Electric Generating
Plant."
UTLEY, E E Carolina Power & Light Co 81/01/13 1p. 07476 023

--8101190419 Corrected Pages 4-7 & 6-9 to "Control Room Habitability
Evaluation, Brunswick Steam Electric Generating Plant"
SLIDER, J E., ARCIERI, W C., BROADHURST, R H NUS Corp. NUS-3697
ERR 81/01/13 2pp 07476 024

8101190609 Responds to NRC 801209 generic BER re BWR scram discharge
sys Sys mods will be completed prior to completion of next
refueling outage Util will review any scram which occurs
during cycle & verify correct sys function.
UTLEY, E E Carolina Power & Light Co 81/01/13. 2pp. 07475 175.

9 Inspection reports, IE Bulletins & correspondence

8101270873 Informs that corrective actions to IE Insp Repts
50-324/80-24 & 50-325/80-27 will be delayed until 801212
due to manpower requirements resulting from IE Bulletins
79-018 & 80-17
TOLLISON, A C. Carolina Power & Light Co 80/09/18. 1p. 07950 105

8101090184 Forwards Revision 2 to HB Robinson & Revision 1 to
Brunswick 90-day repts w/o Brunswick rept
FURR, B.J Carolina Power & Light Co. 80/11/21. 2pp 07380 001.

8101050597 Forwards IE Info Notice 80-43, "Failures of Continuous Water
Level Monitor for Scram Discharge Val at Dresden Unit 2." No
response required
O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/12/05.
1p 07391 014

8101160264 Forwards IE Insp Repts 50-324/80-35 & 50-325/80-38 on
801001-31. No noncompliance noted.
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support
Branch. 80/12/05. 2pp. 07470 267.

--8101160268 IE Insp Repts 50-324/80-35 & 50-325/80-38 on 801001-31. No
noncompliance noted Major areas inspected: plant logs,
physical security barriers, radiation protection & fire
protection
QUITB, J E Region 2, Atlanta, Office of the Director.
KELLDOG, P. J. Region 2, Atlanta, Reactor Operations Nuclear Support
Branch. 80/12/04. 6pp 07470 269.

8101050638 Forwards supplemental response to IE Bulletin 80-11.
"Masonry Wall Design." All safety-related concrete masonry
walls in diesel generator bldg will maintain structural
integrity during seismic event Three walls will be upgraded.
FURR, B.J Carolina Power & Light Co. 80/12/09. 3pp. 07387 020.

8101070620 Submits supplemental response to IE Bulletin 80-21. "Valve
Yokes Supplied by Malcolm Foundry Co. Inc." Estimated
manpower expended for response was 48-h.
FURR, B.J. Carolina Power & Light Co. 80/12/15. 1p. 07415 318

B01060167 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Scram Capability." No response required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/12/17 1p 07391 281

B01070039 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR." No written response required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/12/18 1p 07413 350

B01050161 Forwards IE Bulletin 80-25, "Operating Problems W/Target Rock Safety Relief Valves at BWRs." No response required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/12/19 2pp 07377 264

B01100831 Confirms corrective actions re Health Physics Appraisal insp on 801208-19 Actions taken established program for determining effectiveness of respirator fit & improved procedures for evaluating uptake of radioactivity
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/12/24 1p 07443 256

B01160005 Responds to IE Bulletin 80-24 re preventing damage from water leakage inside containment Facility does not use any open cooling water sys One leakage from closed cooling water sys caused by mechanical damage
FURR, B. J. Carolina Power & Light Co 80/12/24 2pp 07469 255

B01290220 Provides interim rept in response to IE Bulletins 79-02, 79-07 & 79-14 Several lines exist whose seismic requirements are unclear & which require addl review As-built walkoffs & short-term analyses completed for essential hangers.
TOLLISON, A. C. Carolina Power & Light Co 80/12/31 3pp 07569 354

R Periodic operating reports & related correspondence

B01210405 Forwards monthly operating repts for Dec 1980.
TOLLISON, A. C. Carolina Power & Light Co 81/01/09 1p 07493 108

--B01210408 Monthly operating repts for Dec 1980
WILLIS, E. A. Carolina Power & Light Co 81/01/06 12pp 07493 109

S Reportable occurrences, LERs & related correspondence

B012230491 LER 80-051/03L-0 on B01116, during insp of reactor bldg exhaust ventilation radiation monitor 2-CAC-AT-1264, monitor particulate collector unit found missing two O-rings & misaligned particulate filter support surface
TOLLISON, A. C. Carolina Power & Light Co 80/12/16 2pp 07316 227

B01050033 Nonroutine 30-day radiological environ event rept on B01205, discovered failure to provide 30-day notification of gross beta concentration in Feb 1980 air particulate samples. Caused by computation error in original calculation.
TOLLISON, A. C. Carolina Power & Light Co 80/12/24 1p 07379 333

B01300565 RD on B00222 & 25, during weekly air particulate sampling analysis, gross beta activity exceeded Tech Spec limits Caused by computational error in original calculation
TOLLISON, A. C. Carolina Power & Light Co 80/12/24 1p 07582 362

B01050029 Fourteen-day rept on B01215, failure to install particulate filter holder rendered reactor bldg exhaust monitor inoperable Caused by personnel error. Holder replaced & operating procedures revised to ensure monitor checks
TOLLISON, A. C. Carolina Power & Light Co 80/12/29 1p 07385 272

B01050401 RD 2-B0-106 on B01226, while operating at approx 56% power, reactor scrambled resulting in HPCI trip & isolation on high exhaust pressure. Caused by low level auto initiation signal trip reset. Damaged snubbers repaired
TOLLISON, A. C. Carolina Power & Light Co 80/12/29 2pp 07378 361

B01070370 Forwards LER 80-105/03L-0
TOLLISON, A. C. Carolina Power & Light Co 80/12/30 1p 07406 349

--B01070373 LER 80-105/03L-0 on B01202, TIP machine A found w/o TIP indication which prevented closing of A TIP ball valve. Caused by bent tube guide chafing & extending probe cable until breakage occurred.
TOLLISON, A. C. Carolina Power & Light Co 80/12/30 2pp 07406 350

B01070498 Forwards LER 80-112/01T-0
TOLLISON, A. C. Carolina Power & Light Co 80/12/30 1p

--B01070502 LER 80-112/01T-0 on B01219, determined that sec water pumps for planned maint on 2A nuclear svc water p discharge check valve 2-BW-V24 required rept Caused by Spec misinterpretation Personnel retrained
TOLLISON, A. C. Carolina Power & Light Co 80/12/31 2 07415 076

B01070365 Forwards LER 80-098/03L-0
TOLLISON, A. C. Carolina Power & Light Co 80/12/31 1p

--B01070368 LER 80-098/03L-0 on B01202, valve packing of re isolation cooling steam isolation valve 2-E51-F007 found have failed & allowed leakage of steam condensate Cause packing failure. Valve repacked
TOLLISON, A. C. Carolina Power & Light Co 80/12/31 1 07406 348

B01070491 Forwards LER 80-108/03L-0
TOLLISON, A. C. Carolina Power & Light Co 80/12/31 1p

--B01070493 LER 80-108/03L-0 on B01202, drywell equipment d integrator indicating five gpm w/no pumps running Cause drywell equipment drain square root converter being out of calibr Converter recalibr
TOLLISON, A. C. Carolina Power & Light Co 80/12/31 1 07406 360

B01090511 RD on B01003 during normal reactor startup & heat reactor pressure at 717 psig, safety relief valve B21-F013 lifted, causing feed pump to trip Low level reactor scram resulted Pilot to F0130 replaced
TOLLISON, A. C. Carolina Power & Light Co 81/01/05 2pp 07442 077

B01130548 Forwards LER 80-107/03L-0
TOLLISON, A. C. Carolina Power & Light Co 81/01/07 1p

--B01130554 LER 80-107/03L-0 on B01208, svc water sys prima temp reached 212F Caused by removal of shutdown cooling capability for maint w/access to primary containment open subsequent heatup of primary coolant due to decay heat
POULK, R. M. Carolina Power & Light Co 81/01/07 4pp

B01130561 Forwards LER 80-111/03L-0
TOLLISON, A. C. Carolina Power & Light Co 81/01/07 1p

--B01130568 LER 80-111/03L-0 on B01210, 12 & 1B, reactor cool exceeded Tech Specs Caused by increase in coolant flash product inventory originating from leaking fuel element
PASTVA, M. J. Carolina Power & Light Co 81/01/07 3pp 07454 166

B01140508 Forwards LER 80-110/03L-0
TOLLISON, A. C. Carolina Power & Light Co 81/01/08 1p

--B01140514 LER 80-110/03L-0 on B01212, surveillance require ventilation dampers isolation on fire, toxic gas or high radiation signals not performed Caused by requirements omitted from periodic test during 1979 revision.
PASTVA, M. J. Carolina Power & Light Co 81/01/08 1p

B01200624 Forwards LER 80-102/03L-0
TOLLISON, A. C. Carolina Power & Light Co 81/01/08 1p

--B01200628 LER 80-102/03L-0 on B01212, during reactor start rod 26-35 had to be bypassed in full out position to allow startup to continue. Probably caused by faulty signal from rod position feed switch to rod sequence control sys
PASTVA, M. J. Carolina Power & Light Co 81/01/08 1p

B01130535 Forwards LER 80-113/03L-0
TOLLISON, A. C. Carolina Power & Light Co 81/01/09 1p

--B01130540 LER 80-113/03L-0 on B01211, primary containment control inerting inlet isolation valve 2-CAC-V48 had d open/close position indication Cause unknown Suppl rept be issued following investigation
PASTVA, M. J. Carolina Power & Light Co 81/01/09 1p

B01150532 Forwards LER 80-106/01T-0
TOLLISON, A. C. Carolina Power & Light Co 81/01/09 1p

--B101150538 LER 80-106/01T-0 on B01226.HPCI sys tripped immediately after low level 2 auto-initiation on high steam line exhaust pressure signal Caused by water hammer event in exhaust line HPCI sys trip reset
POULK.R H Carolina Power & Light Co 81/01/09 2pp. 07463 182

B101160524 Forwards LER 80-109/03L-0
TOLLISON.A C Carolina Power & Light Co 81/01/09 1p. 07471 279

--B101160581 LER 80-109/03L-0 on B01215.primary containment atmospheric monitor 2-CAC-AT-1259 tripped due to low sample flow Caused by moisture in monitor pressure regulator & photohelic unit Moisture removed & photohelic unit replaced
TOLLISON.A C Carolina Power & Light Co 81/01/09 2pp. 07471 279

B101220405 Forwards LER 80-115/03L-0
TOLLISON.A C Carolina Power & Light Co 81/01/15 1p. 07494 099

--B101220407 LER 80-115/03L-0 on B01222.reactor vessel conductivity. exceeded 2 umho/cm2 for 27 3-h w/highest measured value at 3 35 umho/cm2 Caused by high conductivity condensate in heater drains sys being concentrated in vessel
POULK.R H Carolina Power & Light Co 81/01/15 1p 07494:070.

B101290386 Special rept while performing periodic test of fire barrier penetration seals.300 seals were found in nonfunctional condition Caused by inadequate sealing during installation Seals identified & mapped for repairs
TOLLISON.A C Carolina Power & Light Co 81/01/15 1p 07526 151

B101270703 Forwards LER 80-114/03L-0
TOLLISON.A C Carolina Power & Light Co 81/01/20 1p 07546 349

--B101270708 LER 80-114/03L-0 on B01229.low level switch 2B21-L16-K031D-3 actuated outside Tech Specs Caused by instrument drift. Switch recalibr
PASTVA.M J Carolina Power & Light Co 81/01/20 1p 07546 350

B101280278 Forwards updated LER 80-080/03L-1
TOLLISON.A C Carolina Power & Light Co 81/01/20 1p 07553 094

--B101280282 Updated LER 80-080/03L-1 on B01019.stuck reactor instrument penetration isolation valve X76-B made containment atmospheric control monitors 1259,1260 & 1261 inoperable Caused by bakelite nipple broken off actuation switch
PASTVA.M J Carolina Power & Light Co 81/01/20 1p 07553 055

B101270688 Forwards LER 80-119/03L-0
TOLLISON.A C Carolina Power & Light Co 81/01/21 1p 07309 001

--B101270675 LER 80-119/03L-0 on B01225.primary containment atmospheric monitor 2-CAC-AT-1263 hydrogen analyzer transmitter had no output signal Caused by dirty contacts on monitor local/remote switch Contacts cleaned & monitor recalibr
PASTVA.M J Carolina Power & Light Co 81/01/21 2pp. 07309 001

B101270788 Forwards LER 80-118/03L-0
TOLLISON.A C Carolina Power & Light Co 81/01/22 1p. 07549 147

--B101270794 LER 80-118/03L-0 on B01231.position indication 38-11 showed superimposed 3 over 8 digit when at position 40 Caused by reed switch problem in rod prototypic inlet piping probe Problem will be corrected during next available outage
PASTVA.M J Carolina Power & Light Co 81/01/22 1p 07549 148

B101270606 Forwards LER 80-117/03L-0.
TOLLISON.A C Carolina Power & Light Co 81/01/23 1p 07546 329

--B101270606 LER 80-117/03L-0 on B01227.BWR sys water pump 2C vibrations exceeded Tech Specs Caused by pump diffuser antirotating pin dislodging from casing & embedding between diffuser vane & pump impeller Pin replaced.
PASTVA.M J Carolina Power & Light Co 81/01/23 2pp. 07546:330

B101270800 Forwards LER 80-116/03L-0
TOLLISON.A C Carolina Power & Light Co 81/01/23 1p 07549 149

--B101270807 LER 80-116/03L-0 on B01231.pressure switch 2-E11-PB-N010A actuated outside Tech Spec limits Caused by instrument drift Switch recalibr
PASTVA.M J Carolina Power & Light Co 81/01/23 1p. 07549 150

BUCKET 50-325 BRUNSWICK STEAM ELECTRIC PLANT. UNIT 1

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plant & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B0102 & by applicants as part of FSAR
EISENHUT.D O Division of Licensing 80/11/13 2pp

B101140325 Requests that encl facility emergency planning publicly available w/o encl.
BOUDER.J L Division of Rules and Records 80/12/31 07458:010

B101230059 Releases public version of util evacuation study
FELTON.J H Division of Rules and Records 81/01/08 07911:026

--B101230046 Forwards public version of preliminary result evaluation study for 10-mile emergency planning zone. response to NRC 791129 request Final rept will be available B10201
UTLEY.E E Carolina Power & Light Co 80/12/29 6p

B101260631 Releases public version of util revised emergency plan
FELTON.J H Division of Rules and Records 81/01/16 07924:308

--B101260637 Forwards public version of revised radiological plan w/o State of SC emergency plan Cross-ref against NUREG-0634 criteria encl.
UTLEY.E E Carolina Power & Light Co 80/12/30 6p

--B101260644 Public version of revised radiological emergency plan
State of SC emergency plan
* Carolina Power & Light Co 80/12/31 150pp. 079

P. Operating license stage documents & correspondence

B101100254 Ltr to all licensees (except SEP licensees) for Revision 1 of inservice surveillance requirements for snubbers under B1S License amend Application adding mod Tech Specs to App A should be submitted within 120 days
EISENHUT.D O Division of Licensing 80/11/20 1p.

--B101100271 Revised Pages 3/4 7-22 through 28.B 3/4 7-5 B1S snubber inservice insp requirements
* Division of Licensing. 80/11/20 10pp

B101220466 Ltr to all power reactor licensees & applicant summary of B01112 meeting re implementation of guidance Unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT.D O Division of Licensing. 80/11/26 8pp.

B101190113 Ltr to all BWR licensees forwarding B01201 gen evaluation re BWR scram discharge sys Recommends short-term actions necessary to assure safe operation of OE BWRs pending permanent design changes
EISENHUT.D O Division of Licensing 80/12/09 2pp.

--B101190141 Generic safety evaluation re short-term actions to assure continued safe operation of operating BWRs Continued operation of plants is acceptable pending permanent design changes.Criteria for implementing design mods encl
* Division of Licensing 80/12/01 212pp. 07183:0

B101210445 Forwards responses to questions on Rule 50.71a Updating of FSARs" & FR notice of final rule.BEP plants not comply w/rule until program is complete Non-BEP plants must comply within specified time frame.
EISENHUT.D O Division of Licensing 80/12/15 13pp

B101210532 Forwards Amends 33 & 34 to Licenses DPR-71 & D respectively.safety evaluation & notice of issuance & availability.
IPPOLITO.T A Operating Reactors Branch 2. 80/12/23. 07488:162

--B101210539 Amends 33 & 34 to Licenses DPR-71 & DPR-62.revising Tech Specs to provide one-time extension of surveillance intervals allowing required testing to be performed.
IPPOLITO.T A Operating Reactors Branch 2. 80/12/23 07488:164.

--B010210945 Safety evaluation supporting Amendments 33 & 34 to Licenses DPR-71 & DPR-62, respectively
* Office of Nuclear Reactor Regulation, Director 80/12/23 3pp
07488 202

--B010210950 Notice of issuance & availability of Amendments 33 & 34 to Licenses DPR-71 & DPR-62, respectively
IPPOL170.T A Operating Reactors Branch 2 80/12/23 2pp.
07488 205.

B010210943 Forwards Amendments 32 & 33 to Licenses DPR-71 & DPR-62, respectively, safety evaluation & notice of issuance & availability
IPPOL170.T A Operating Reactors Branch 2 80/12/29 2pp
07488 086

--B010210957 Amendments 32 & 33 to Licenses DPR-71 & DPR-62, respectively, changing Tech Specs by adding limiting conditions for operations & bases to clarify term operable as applied to safety sys
IPPOL170.T A Operating Reactors Branch 2 80/12/29 18pp
07488 080

--B010210966 Safety evaluation supporting Amendments 32 & 33 to Licenses DPR-71 & DPR-62, respectively
* Office of Nuclear Reactor Regulation, Director 80/12/29 2pp
07488 106

--B010210971 Notice of issuance & availability of Amendments 32 & 33 to License DPR-71 & DPR-62, respectively
IPPOL170.T A Operating Reactors Branch 2 80/12/29 2pp
07488 108

B01060494 Forwards report entitled, "Control Room Habitability Evaluation, Brunswick Steam Electric Generating Plant." Report responds to all info requested in NUREG-0737 & NRC B00507 ltr
UTLEY, E E Carolina Power & Light Co 80/12/30 3pp 07393.099

--B01060498 "Control Room Habitability Evaluation, Brunswick Steam Electric Generating Plant."
SLIDER, J E, ARCIERI, W C, BROADHURST, R H NUS Corp NUS-3697
80/12/31 112pp. 07393 102

B01140188 Requests for publication of encl notice of issuance of facility DL or amend Referenced documents are available in PDR w/o encl
* Operating Reactors Branch 2 80/12/30 1p 07461 208

B01160955 Informs that B01105 application requesting extension of end dates for performing certain insp & tests requires Class III fee for one unit & Class I fee for second unit
DIGGS, R M License Fee Management Branch 80/12/30 1p.
07171-276

B01060987 Responds to NUREG-0737 re clarification of post-TMI action plan requirements. Items addressed shift technical supervisor training for mitigating core damage, containment isolation dependability & inplant radiation monitoring.
UTLEY, E E Carolina Power & Light Co 80/12/31 140pp 07399.175

B01160442 Provides update re Mark I containment program mods. Completion scheduled for Jul 1982 Plant unique analysis experiencing 3-month slippage which will delay completion
UTLEY, E E Carolina Power & Light Co 81/01/00 1p 07472 102.

B01190414 Forwards corrected Pages 4-7 & 6-9 to "Control Room Habitability Evaluation, Brunswick Steam Electric Generating Plant."
UTLEY, E E Carolina Power & Light Co 81/01/13 1p 07476 023.

--B01190419 Corrected Pages 4-7 & 6-9 to "Control Room Habitability Evaluation, Brunswick Steam Electric Generating Plant."
SLIDER, J E, ARCIERI, W C, BROADHURST, R H NUS Corp. NUS-3697
ERR 81/01/13 2pp 07476.024.

B01190609 Responds to NRC B01209 generic BER re BWR scram discharge sys. Sys mods will be completed prior to completion of next refueling outage Util will review any scram which occurs during cycle & verify correct sys function.
UTLEY, E E Carolina Power & Light Co 81/01/13 2pp. 07475 175

0. Inspection reports, IE Bulletins & correspondence

B01270873 Informs that corrective actions to IE Insp Repts 50-324/80-24 & 50-325/80-27 will be delayed until 801212 due to manpower requirements resulting from IE Bulletins 79-018 & 80-17.
TOLLISON, A C. Carolina Power & Light Co. 80/09/18 1p 07550 105.

B01090184 Forwards Revision 2 to HD Robinson & Revision 1 to Brunswick 90-day repts w/o Brunswick rept
FURR, B J Carolina Power & Light Co 80/11/21 2pp 07380 001

B01090597 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Scram Discharge Vol at Dresden Unit 2 " No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/03 1p 07391 014

B01160264 Forwards IE Insp Repts 50-324/80-35 & 50-325/80-38 on B01001-31 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/12/09 2pp 07470 267

--B01160268 IE Insp Repts 50-324/80-35 & 50-325/80-38 on B01001-31 A noncompliance noted Major areas inspected plant logs, physical security barriers, radiation protection & fire protection
O'RTB, J E Region 2, Atlanta, Office of the Director
KELLCOO, P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/12/04 6pp 07470 267

B01090638 Forwards supplemental response to IE Bulletin 80-11, "Masonry Wall Design." All safety-related concrete masonry walls in diesel generator bldg will maintain structural integrity during seismic event Three walls will be upgraded
FURR, B J Carolina Power & Light Co 80/12/09 3pp. 07387 020

B01070620 Submits supplemental response to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co, Inc." Estimated manpower expended for response was 48-h
FURR, B J Carolina Power & Light Co 80/12/15 1p 07415 316

B01060617 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Scram Capability." No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/17 1p. 07371 281

B01070039 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of 76 of 1 Control Rods to Fully Invert During Scram at BWR." No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/10 1p 07413 350.

B01090161 Forwards IE Bulletin 80-25, "Operating Problems w/Target Rack Safety Relief Valves at BWRs." No response required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/15 2pp 07377 264

B01100831 Confirms corrective actions re Health Physics Appraisal insp on B01208-19. Actions taken established program for determining effectiveness of respirator fit & improved procedures for evaluating uptake of radioactivity
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/21 1p 07443 256

B01160005 Responds to IE Bulletin 80-24 re preventing damage from water leakage inside containment Facility does not use any open cooling water sys One leakage from closed cooling water sys caused by mechanical damage
FURR, B J Carolina Power & Light Co. 80/12/24 2pp 07469 255

B01290228 Provides interim rept in response to IE Bulletins 79-02, 79-07 & 79-14 Several lines exist whose seismic requirements are unclear & which require addl review. As-built walkoffs & short-term analyses completed for essential hangers.
TOLLISON, A C. Carolina Power & Light Co 80/12/31 3pp 07569 354

R. Periodic operating reports & related correspondence

B01210405 Forwards monthly operating repts for Dec 1980
TOLLISON, A C. Carolina Power & Light Co 81/01/09 1p 07493 10

--B01210408 Monthly operating repts for Dec 1980
WILLIS, E A. Carolina Power & Light Co. 81/01/06 12pp 07493 109

S. Reportable occurrences, LERs & related correspondence

B01300502 Forwards LER 80-087/03L-0
TOLLISON, A C. Carolina Power & Light Co 80/12/01 1p 07586.3

--B101300507 LER 80-087/03L-0 on 801105 control rods 50-27 & 38-23 exhibited position indication problems. Caused by defective rod position indication reed switches. Corrective maint will be completed during outage
TOLLISON, A C Carolina Power & Light Co 80/12/01 1p 07586 312

B101300568 Forwards LER 80-090/03L-0
TOLLISON, A C Carolina Power & Light Co 80/12/01 1p 07582 348

--B101300572 LER 80-090/03L-0 on 801101 during routine surveillance, containment atmosphere control monitor 1-CAC-AI-1259 was observed indicating downscale. Caused by instrument drift. Monitor recalibr satisfactorily.
TOLLISON, A C Carolina Power & Light Co 80/12/01 2pp 07582 349

B101050033 Nonroutine 30-day radiological environ event rept on 801205 discovered failure to provide 30-day notification of gross beta concentration in Feb 1980 air particulate samples. Caused by computation error in original calculation.
TOLLISON, A C Carolina Power & Light Co 80/12/24 1p 07379 333

B101300565 RD on 800222 & 25 during weekly air particulate sampling analysis, gross beta activity exceeded Tech Spec limits. Caused by computational error in original calculation.
TOLLISON, A C Carolina Power & Light Co 80/12/24 1p 07582 362

B101050029 Fourteen-day rept on 801215 failure to install particulate filter holder rendered reactor bldg exhaust monitor inoperable. Caused by personnel error. Holder replaced & operating procedures revised to ensure monitor checks.
TOLLISON, A C Carolina Power & Light Co 80/12/29 1p 07385 272

B101090511 RD on 810103 during normal reactor startup & heatup w/ reactor pressure at 717 psig, safety relief valve B21-F0130 lifted, causing feed pump to trip. Low level reactor scram resulted. Pilot to F0130 replaced.
TOLLISON, A C Carolina Power & Light Co 81/01/05 2pp 07442 077

B101090667 Forwards LER 80-086/03L-0
TOLLISON, A C Carolina Power & Light Co 81/01/05 1p 07430 283

--B101090676 LER 80-086/03L-0 on 801207 during testing, linear heat generation rate found at 13,359 kW/ft. DD-1 performed & rate exceeded limit. Apparently caused by low power range monitor D drifting w/inlet subcooling.
TOLLISON, A C Carolina Power & Light Co 81/01/05 2pp 07430 284

B101200626 Forwards LER 80-091/03L-0
TOLLISON, A C Carolina Power & Light Co 81/01/08 1p 07477 259

--B101200629 LER 80-091/03L-0 on 801211 rod block monitor B observed indicating downscale. Caused by failed power supply due to defective power supply regulator & zener diode in power supply regulator circuit. Regulator & diode replaced.
PASTVA, M J Carolina Power & Light Co 81/01/08 1p 07477 260

B101220399 Forwards LER 81-001/01T-0
TOLLISON, A C Carolina Power & Light Co 81/01/14 1p 07505 176

--B101220402 LER 81-001/01T-0 on 810103 feed pump tripped on high vessel level due to safety-relief valve B21-F0130, Model 67F, lift. Caused by high second stage & pilot leakage in valve. Pilot valve temporarily replaced until next scheduled outage.
POULK, R M Carolina Power & Light Co 81/01/14 1p 07505 177

B101220393 Forwards LER 80-092/03L-0
TOLLISON, A C Carolina Power & Light Co 81/01/15 1p 07505 174

--B101220396 LER 80-092/03L-0 on 801220 reactor vessel conductivity measured over Tech Spec level. Caused by removal of reactor water cleanup sys from svc for valve maint. Valves repaired & sys returned to svc.
PASTVA, M J Carolina Power & Light Co 81/01/15 1p 07505 175

B101270627 Forwards LER 81-003/03L-0
TOLLISON, A C Carolina Power & Light Co 81/01/20 1p 07546 334

--B101270631 LER 81-003/03L-0 control rod 26-35 on 810103, 18-51 on 810112, 38-31 & 22-15 on 810114 showed inaccurate position indications. Caused by buffer card failure on 26-35, defective reed switches in others. Card replaced, switches repaired.
PASTVA, M J Carolina Power & Light Co 81/01/20 1p 07546 335

B101270587 Forwards LER 80-093/03L-0
TOLLISON, A C Carolina Power & Light Co 81/01/21 1p 07546 327

--B101270595 LER 80-093/03L-0 on 801228 rod worth minimizer insert/withdrawal rod block at rod group 56 when rods were in correct position. Caused by computer rod worth minimizer software problems. Problems corrected.
PASTVA, M J Carolina Power & Light Co 81/01/21 1p

COCKER 50-327 SEQUOYAH NUCLEAR PLANT, UNIT 1

E NRC Safety Evaluation Report (SER), suppl & correspondence

B101120176 Forwards marked-up copy of draft SER, Suppl 4. Comments needed by 801229 to mail draft SER to ACRS members on 801230.
TEDESCO, R L Assistant Director for Licensing 80/12/24 07438 319

B101270078 Forwards final version of Suppl 4 to SER on hydro control. Comments requested by 810115 w/o encl.
TEDESCO, R L Assistant Director for Licensing 81/01/13 07547 208

F Security, medical, emergency & fire protection plans

B101070238 Requests that encl emergency planning info be made available w/o encl.
SOUDER, J L Division of Rules and Records 80/12/17 1p 07414 296

B101090922 Forwards facility emergency planning info to be made publicly available w/o encl.
SOUDER, J L Division of Rules and Records 80/12/17 1p 07427 361

B101210607 Transcript of 801217 briefing on TVA emergency facilities in Washington, DC. Pp 1-45.
* Commissioners. 80/12/17 49pp

B101100724 Requests that encl facility emergency planning info be made publicly available w/o encl.
SOUDER, J L Division of Rules and Records 80/12/31 1p 07445 126

B101200227 Releases public version of util revised emergency plan.
FELTON, J M Division of Rules and Records 81/01/13 1p 07478 066

--B101200233 Forwards public version of revised radiological plan.
MILLS, L M Tennessee Valley Authority 80/12/31 1p

--B101200237 Public version of revised radiological emergency plan, multi-jurisdictional plan encl.
* Tennessee Valley Authority. 80/12/31 475pp 07478 066

B101300115 Forwards facility emergency planning info for plant. LPBR w/o 8101000123.
SOUDER, J L Division of Rules and Records 81/01/16 1p 07583 090

J Insurance & indemnity information

B101140353 Forwards Endorsements 32 & 33 to MAELU Policy NF-10.
FIELDER, J Marsh & McLennan, Inc., M & M Nuclear Consultants Div. 80/11/20 3pp 07457 111

B101090526 Forwards Endorsement 19 to ANI Policy NF-247.
FIELDER, J Marsh & McLennan, Inc., M & M Nuclear Consultants Div. 80/12/28 3pp 07442 280

B101090663 Forwards Endorsement 18 to NELIA Policy NF-247.
FIELDER, J Marsh & McLennan, Inc., M & M Nuclear Consultants Div. 80/12/28 2pp 07442 031

B101090566 Forwards Endorsement 2 to ANI Binder EB-66.
FIELDER, J Marsh & McLennan, Inc., M & M Nuclear Consultants Div. 80/12/30 2pp 07427 347

D Advisory Committee on Reactor Safeguards reports & correspondence

B101280531 Minutes of 242nd ACRS meeting on 800605-07 in Washington. re subcommittee rept on Sequoyah Units 1 & 2 Agenda & appx encl.
* ACRS - Advisory Committee on Reactor Safeguards. 80/11/200pp 07550 332

DOCKETED ITEMS

B01280487 Appx to minutes of 243rd ACRS meeting on B00710-12 in Washington, DC re Sequoyah Units 1 & 2 & FY82 Budget Agenda encl.
* ACRS - Advisory Committee on Reactor Safeguards B011/25
300pp. 07300 001

B01160446 Summarizes B01008-10 ACRS meeting w/NRC & TVA re proposed interim hydrogen control sys Results of analyses & tests support conclusion that distributed ignition sys could improve protection against breach of containment
MARK, J.C. ACRS - Advisory Committee on Reactor Safeguards B1/01/13 1p 07470 081.

B011300814 Concurs w/NRC recommendation to allow operation of interim distributed ignition sys at facilities NRC & util must continue to describe performance characteristics of sys over broader range of conditions
MARK, J.C. ACRS - Advisory Committee on Reactor Safeguards. B1/01/13 1p 07584 316.

B011290209 Forwards ACRS B01013 ltr re interim hydrogen control sys review.
SCHWENCER, A Licensing Branch 2 B1/01/14 2pp. 07575 027

P. Operating license stage documents & correspondence

B01060040 Forwards request for proposed amend to OL to conform w/IE Bulletin B0-18 re adequate min flow through centrifugal charging pumps Requests NRC finding on proposed mods by B01017 w/o encl.
SCHWENCER, A Licensing Branch 2 B0/12/05 1p. 07399 132.

B01060256 Requests info re temp profile for equipment survivability. local detonations & pressure profiles on shell-interior walls; CLABIX modeling of ice bed heat transfer & combustion phenomena; particularly number of ignitors
TEDESCO, R.L. Assistant Director for Licensing B0/12/10 1p 07399:087.

B01100606 Forwards Amend 1 to License DPR-77, safety evaluation & notice of issuance & availability
SCHWENCER, A Licensing Branch 2. B0/12/22 2pp 07443 124.

--B01100614 Amend 1 to License DPR-77, revising Tech Specs re testing of certain valves in different mode of plant operation
SCHWENCER, A Licensing Branch 2. B0/12/22 4pp 07443 126.

--B01100620 Notice of issuance & availability of Amend 1 to License DPR-77
SCHWENCER, A Licensing Branch 2. B0/12/22 2pp 07443 130

--B01100626 Safety evaluation supporting Amend 1 to License DPR-77.
* Licensing Branch 2. B0/12/22. 4pp 07443 132.

B01210642 Advises that ATWS issue will be subj of future rulemaking to determine requirements & schedules for plant mods NRC will not comment on until B00917 ltr describing program for resolving issue until rulemaking is finalized
EISENHUT, D G Division of Licensing. B0/12/29 2pp.

B01090215 Application for revisions to License DPR-77, deleting inappropriate items from license & moving completion date of items originally scheduled for completion from B20101 to Aug 1982
MILLS, L.M. Tennessee Valley Authority. B0/12/30. 3pp 07378 326

--B01090227 Proposed changes to Tech Specs, deleting inappropriate items from license & moving completion date of items originally scheduled B20101 to end of first refueling outage scheduled for Aug 1982.
* Tennessee Valley Authority. B0/12/30 3pp. 07378:329.

B01190420 Advises that util B01009 ltr provided correct interpretation of Tech Spec Section 4.4.3.2.4 surveillance requirement.
TEDESCO, R.L. Assistant Director for Licensing B0/12/30 3pp. 07475:171.

B01090255 Corrects error in util B01219 ltr re submission date for design details of post-accident sampling sys at Facility per NUREG-0737 Details will be provided by B20101 & will apply to both units.
MILLS, L.M. Tennessee Valley Authority B0/12/31 1p 07389:144

B01090434 Forwards analyses re probability of barge collision & of resulting explosion hazard at ERCH intake structure Analyses submitted per Item 2 C(4) of OL requirements
MILLS, L.M. Tennessee Valley Authority B0/12/31 5pp 07369 328

B01120411 Forwards proprietary & nonproprietary versions of summary rept. "Westinghouse Reactor Vessel Level Instrumentation Sys for Monitoring Inadequate Core Cooling (Upper Head Injection)" & application & affidavit for withholding
MILLS, L.M. Tennessee Valley Authority. B1/01/02 9pp 07439 238

B01120331 Forwards revised Page VIII-B to Vol 2 of facility core degradation program, addressing NRC concern re polyurethane foam insulation in ice condenser
CROSS, J.L. Tennessee Valley Authority. B1/01/06 2pp 07447 116

B01160429 Forwards containment purge study for facility, in support of revision to Tech Spec 3.6.1.9 re containment purge limits
MILLS, L.M. Tennessee Valley Authority B1/01/08 6pp 07472 150

B01160494 Forwards info re control room habitability, per NUREG-0737. Operators are adequately protected against effects of accidental release of chemicals Facility can operate safely or shut down under DCA conditions
MILLS, L.M. Tennessee Valley Authority. B1/01/13 3pp 07472 134

B01220291 Advises that mod to containment boundary components will be completed by B01030 Personnel air lock has less yield pressure capacity than structural capability
MILLS, L.M. Tennessee Valley Authority B1/01/15 1p 07494 009

B01270702 Application to amend License DPR-77, removing independent essential raw cooling water sys trains required by Tech Spec 3.7.4 Reasons & justifications for amend encl
CROSS, J.L. Tennessee Valley Authority B1/01/19 4pp 07545 239

B01260416 Forwards upgraded Table 11 to "Electrical Equipment Environment Qualification Rept.," summarizing current interim status of electrical equipment qualification, per NRC request during B01217-19 audit Original rept submitted B01031
CROSS, J.L. Tennessee Valley Authority B1/01/20 1p 07520 161

--B01260420 Updated Table 11 to "Electrical Equipment Environment Qualification Rept."
* Tennessee Valley Authority B1/01/20 5pp 07520 162.

B01270647 Responds to NRC request during B0121 visit. Discussions re short-term thermal effects of hydrogen burn on equipment & assessment of temp curves D & E for equipment survivability evaluations encl
CROSS, J.L. Tennessee Valley Authority B1/01/22. 5pp 07545 263

Q. Inspection reports, IE Bulletins & correspondence

B01140619 Updates licensee corrective actions following NRC B00707-1 Insp of util Div of Engineering Design QA organization restructured to provide sufficient organizational freedom, authority & access to mgt
KIMMONS, G.H. Tennessee Valley Authority. B0/10/08 3pp. 07462:012

B01100351 Forwards IE Insp Rept 50-327/B0-38 on B00901-30 & notice of violation
LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch B0/11/28 2pp. 07443:341

--B01100356 Notice of violation from insp on B00901-30
* Region 2, Atlanta, Office of the Director. B0/11/26. 1p 07443:343

--B01100364 IE Insp Rept 50-327/B0-38 on B00901-30. Noncompliance no improper maint of procedure required by Tech Spec
BUTLER, B.D. Region 2, Atlanta, Office of the Director DANCE, H. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. B0/11/26 8pp 07443 344.

B01090825 Ack receipt of B01121 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-327/B0-39.
LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch B0/12/11 1p. 07430:262.

--B01090834 Responds to NRC B01030 ltr re violations noted in IE Insp

--8101090341 Forwards IE Insp Rept 50-327/80-23 on 800916-19 & notice of violation
LEWIS R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch
80/10/30 2pp 07430 265

--8101090345 Notice of violation from insp on 800916-19
* Region 2, Atlanta, Office of the Director 80/10/29 1p
07430 267

--8101090349 IE Insp Rept 50-327/80-39 on 800916-19 Noncompliance noted
LERs not submitted in accordance w/ Tech Spec time requirements & diesel generator failure repts incomplete
JULIAN C Region 2, Atlanta, Office of the Director DANCE H C
Region 2, Atlanta, Reactor Operations Nuclear Support Branch
80/10/29 5pp 07430:268

8101120240 Forwards response to IE Bulletin 80-20 re Westinghouse Type
W-2 control switches w/spring return to neutral position
Switches used in all facilities except Yellow Creek Lists
sys in which switches are employed
MILLS L M Tennessee Valley Authority 80/12/12 2pp 07447 060

8101150013 Responds to IE Bulletin 80-23 re failures of solenoid valves
w/ by Valitor Engineering Corp Facility does not have valves
w/ make & part numbers described
MILLS L M Tennessee Valley Authority 80/12/15 1p 07462:152

8101160203 Forwards IE Info Notice 80-44, "Activation of ECCB in
Recirculation Mode While in Hot Shutdown" No written
response required
O'REILLY J P Region 2, Atlanta, Office of the Director 80/12/16
1p 07391:312

8101220383 Forwards response to IE Bulletin 80-24, "Prevention of
Damage Due to Water Leakage Inside Containment"
CRDSS J L Tennessee Valley Authority 81/01/06 19pp 07500 274

R Periodic operating reports & related correspondence

8101050241 Forwards essential raw cooling water conduit settlement
monitoring data
MILLS L M Tennessee Valley Authority 80/12/31 1p 07378 318

--8101050250 Essential raw cooling water conduit settlement monitoring
data Oversize Tables 02 B6-1 & 02 B4-1 encl.
* Tennessee Valley Authority 80/12/31 5pp 07378 319

8101160472 Forwards monthly operating rept for Dec 1980
BALLENTINE J M Tennessee Valley Authority 81/01/07 1p
07471:234

--8101160474 Monthly operating rept for Dec 1980
DUPREE D Tennessee Valley Authority 81/01/02 10pp
07471:235

8101220155 Forwards "Environ Radioactivity Levels, Sequoyah Nuclear
Plant, Annual Rept 1979" Monitoring program responsive to US
Fish & Wildlife Svc recommendations & requests.
MILLS L M Tennessee Valley Authority 81/01/15 1p 07496:081

--8101220164 'Environ Radioactivity Levels, Sequoyah Nuclear Plant, Annual
Rept 1979."
* Tennessee Valley Authority RH-00-7-802 80/08/31 53pp
07496 082

S Reportable occurrences, LERs & related correspondence

8011250336 Forwards LER 80-176/03L-0
GREEN H J Tennessee Valley Authority 80/11/21 1p 07056 318

--8011250339 LER 80-176/03L-0 on 801020, lower airlock failed 81-159, i.
overall leakage test Caused by airlock inner door ball
valve leak Valve repaired.
COTTLE W T, KIRK G B Tennessee Valley Authority 80/11/21
2pp 07056 319

8101060466 Forwards LER 80-192/03L-0
GREEN H J Tennessee Valley Authority 80/12/30 1p 07391:080

--8101060477 LER 80-192/03L-0 on 801201, F14 control bank B rod position
indicator deviated by greater than 12 steps from control
bank B demand counter Caused by shift in calibr of control
board indicator Indicator recalibr & returned to svc.
COTTLE W T, WILKEY A M Tennessee Valley Authority 80/12/30
1p 07391:089

8101070374 Forwards LER 80-194/03L-0
GREEN H J Tennessee Valley Authority 80/12/30

--8101070377 LER 80-194/03L-0 on 801201, found circuit
120-volt vital instrument power board 1-11 tripped
radiation monitors 1-RE-90-112/134/141 inoperable
failure of O-RE-90-134 motor Motor replaced.
COTTLE W T, WILKEY A M Tennessee Valley Authority
1p 07414 179

8101130690 Forwards LER 80-198/03L-0
GREEN H J Tennessee Valley Authority 81/01/05

--8101130612 LER 80-198/03L-0 on 801204, containment h
1-W2A1-93-210 failed weekly functional test (81-01)
checked w/4% sample Caused by unauthorized closure
segment air flow rotameter Analyzer returned to svc.
COTTLE W T, WILKEY A M Tennessee Valley Authority
1p 07309 001

8101130457 Forwards LER 80-193/03L-0
GREEN H J Tennessee Valley Authority 81/01/06

--8101130463 LER 80-193/03L-0 on 801208, review identifi
functional test instruction for monitors providing
termination of release did not adequately demonstrate
automatic isolation Caused by inadequate instruct
COTTLE W T, WILKEY A M Tennessee Valley Authority
3pp 07457 015

8101160477 Forwards LER 80-199/03L-0
GREEN H J Tennessee Valley Authority 81/01/07

--8101160483 LER 80-197/03L-0 on 801209, high steam flow
& steam/feedwater flow mismatch bistable found w/
Tech Spec values Caused by low actual differential
produced at flow transmitter Setpoints recalibr.
MCGRIFF J M, WILKEY A M Tennessee Valley Authority
2pp 07471 256

8101210466 RD 80-6 on 801201 & 02 Na-24 was inadvert
turbine bldg sump Caused by inadequate test instruct
poor communications between test directors & radiol
lab personnel
GREEN H J, FRASER D A Tennessee Valley Authority
10pp 07493 221

8101210449 Forwards LER 80-201/03L-0
GREEN H J Tennessee Valley Authority 81/01/14

--8101210454 LER 80-201/03L-0 on 801216, diesel genera
start during test on diesel generator 2A-A Caused
relay flashed in diesel generator control circuit
in blown fuse Relay & fuse replaced
MADDOX S D, MCGRIFF J M Tennessee Valley Authority
3pp 07187 001

8101220311 Forwards first interim rept re potential f
suspended ceiling tile in control rooms in response
801104 ltr Addl info to be provided by 810211
MILLS L M Tennessee Valley Authority 81/01/14

8101220499 Forwards LER 80-204/03L-0
GREEN H J Tennessee Valley Authority 81/01/14

--8101220505 LER 80-204/03L-0 on 801216, axial flux di
target band longer than 1-h Caused by rod stepping
maintain power & blocked borate paths due to low
setting Notice to maintain temp at 200 F put on c
MCGRIFF J M, KIRK G B Tennessee Valley Authority
1p 07501:196

8101220511 Forwards LER 80-203/03L-0
GREEN H J Tennessee Valley Authority 81/01/14

--8101220518 LER 80-203/03L-0 on 801216, during ice co
intermediate deck door under AHU-3A found frozen
Caused by AHU-3A drain line flange leaking Ice re
door, flange gasket replaced & leakage stopped.
MCGRIFF J M, KIRK G B Tennessee Valley Authority
1p 07501:233

8101220523 Forwards LER 80-200/03L-0
GREEN H J Tennessee Valley Authority 81/01/18

--B101220532 LER 80-200/03L-0 on B01217, valves 1-FCV-1-15.16 & 17 found not to have been stroked tested after repacking on B01207
Caused by engineer & craft failure to notify proper personnel Valves tested & personnel instructed.
MCGRIFF, J M , WIRK, O R Tennessee Valley Authority 81/01/15 1p 07497 315

B101220202 Notification of noncompliance w/effluent limitations Three samples collected on B01222 exceeded max permit limitation of 9 O units when valve was inadvertently left open. Plant employees instructed to check all valves
EL-ABHRY, M T Tennessee Valley Authority 81/01/16 2pp 07500 087

B101220318 Informs of mechanical malfunction of water treatment plant flocculator on B01001 Equalization tank sludge built up on hydraulic line & caused crimping which shut down operations
Sludge rerouted to makeup demineralizer sump
EL-ABHRY, M T Tennessee Valley Authority 81/01/19 2pp 07309 001

B101230436 Submits NPDES noncompliance notification Bewage treatment plant operator inexperienced w/varying strengths of commercial sodium hypochlorite solutions, allowed chlorine levels to remain in excess of permit limitations
EL-ABHRY, M T Tennessee Valley Authority 81/01/19 2pp 07510 312

B101300509 Forwards LER 80-206/03L-0
GREEN, H J Tennessee Valley Authority 81/01/22 1p 07586 316

--B101300525 LER 80-206/03L-0 on B01225, refueling water storage tank level indicator 1-LI-63-90 found failing high caused by frozen instrument lines for level transmitter inside cabinet housing lines thawed using heat gun & loop returned to svc
MCGRIFF, J M , WILKEY, A M Tennessee Valley Authority 81/01/22 1p 07586 317

Hearing transcripts on non-antitrust matters

B101090040 Transcript of ACNS Subcommittee on Sequoyah Nuclear Power Plant B10106 meeting in Washington, DC. Pp 1-172 Supporting documents encl
* ACNS - Advisory Committee on Reactor Safeguards 81/01/04 242pp 07425 001

CKET 90-328 SEQUOYAH NUCLEAR PLANT, UNIT 2

Application/construction stage documents & correspondence

B10120466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lameiler Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 0pp

B101090968 Summary of B01208-12 meetings w/caseload forecast panel
Earliest projected fuel load date for facilities is B10601 for Sequoyah Unit 2 & Aug 1982 for Watts Bar Unit 1
KENYON, T J Licensing Branch 2 80/12/16 5pp 07429 336

B101210642 Advises that ATWS issue will be subj of future rulemaking to determine requirements & schedules for plant mode NRC will not comment on util H00917 ltr describing program for resolving issue until rulemaking is finalized
EISENHUT, D O Division of Licensing 80/12/29 2pp

B101090295 Corrects error in util B01219 ltr re submission date for design details of post-accident sampling sys at facility per NUREG-0737 Details will be provided by B02101 & will apply to both units
MILLS, L M Tennessee Valley Authority 80/12/31 1p 07389 144

B101090434 Forwards analyses re probability of barge collision & of resulting explosion hazard at ERCW intake structure. Analyses submitted per Item 2 C(4) of O. requirements
MILLS, L M Tennessee Valley Authority 80/12/31 3pp 07389 328

B101120411 Forwards proprietary & nonproprietary versions of summary rept, "Westinghouse Reactor Vessel Level Instrumentation Sys for Monitoring Inadequate Core Cooling (Upper Head Injection)" & application & Affidavit for withholding.
MILLS, L M Tennessee Valley Authority 81/01/02 9pp 07439 238

B10120287 Forwards clarification of TMI action plan for facility per NUREG-0737 requirements. Discusses operating activity correct performance verification, containment isolation dependability & auto PORV isolation & failure rept
MILLS, L M Tennessee Valley Authority 81/01/07 6pp 07439 326

B101160494 Forwards info re control room habitability per NUREG-0737
Operators are adequately protected against effects of accidental release of chemicals Facility can operate safely or shut down under BHA conditions
MILLS, L M Tennessee Valley Authority 81/01/13 3pp 07472 134

B101220291 Advises that mod to containment boundary components will be completed by B10130 Personnel air lock has less yield pressure capacity than structural capability
MILLS, L M Tennessee Valley Authority 81/01/15 1p 07494 009

B101270662 Advises that fuel load date will be B10415
MILLS, L M Tennessee Valley Authority 81/01/16 1p 07545 284

E NRC Safety Evaluation Report (SER), supp & correspondence

B101120176 Forwards marked-up copy of draft SER, Suppl 4 Comments needed by B01229 to mail draft SER to ACNS members on B01230
TEDESCO, R L Assistant Director for Licensing 80/12/24 45pp 07438 319

B101270078 Forwards final version of Suppl 4 to SER on hydrogen control Comments requested by B10115 w/o encl
TEDESCO, R L Assistant Director for Licensing 81/01/13 1p 07547 208

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

B101070238 Requests that encl emergency planning info be made publicly available w/o encl
BUJDER, J L Division of Rules and Records 80/12/17 1p 07414 296

B101090922 Forwards facility emergency planning info to be made publicly available w/o encl
BUJDER, J L Division of Rules and Records 80/12/17 1p 07427 361

B101210607 Transcript of B01217 briefing on IVA emergency offsite facilities in Washington, DC Pp 1-35
* Commissioners 80/12/17 49pp

B101100724 Requests that encl facility emergency planning info be made publicly available w/o encl
BUJDER, J L Division of Rules and Records 80/12/31 1p 07455 126

B101200827 Releases public version of util revised emergency plan
FELTON, J M Division of Rules and Records 81/01/13 1p 07479 066

--B101200233 Forwards public version of revised radiological emergency plan
MILLS, L M Tennessee Valley Authority 80/12/31 1p 07478 068

--B101200237 Public version of revised radiological emergency plan IN multi-jurisdictional plan encl
* Tennessee Valley Authority 80/12/31 475pp 07478 069

B101300115 Forwards facility emergency planning info for placement in LPR w/o B101080123
BUJDER, J L Division of Rules and Records 81/01/16 1p 07583 090

J Insurance & indemnity information

B101140353 Forwards Endorsements 32 & 33 to MAELU Policy MF-91
FIEDLER, J Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc. Div. 80/11/20 3pp 07457 111

B101090526 Forwards Endorsement 19 to ANI Policy MF-247
FIEDLER, J Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc. Div. 80/12/28 3pp 07442 280

B101090663 Forwards Endorsement 18 to NELIA Policy MF-247
FIEDLER, J Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc. Div 80/12/28 2pp 07442 051

B101090566 Forwards Endorsement 2 to AMI Binder EB-66
FIELDER, J Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc
Div 80/12/30 2pp 07427 347

Q Advisory Committee on Reactor Safeguards reports & correspondence

B101280531 Minutes of 242nd ACRS meeting on B00605-07 in Washington, DC
re subcommittee rept on Sequoyah Units 1 & 2 Agenda &
apps encl
* ACRS - Advisory Committee on Reactor Safeguards 80/11/06
700pp 07553 332

B101280497 Apps to minutes of 243rd ACRS meeting on B00710-12 in
Washington, DC re Sequoyah Units 1 & 2 FY82 budget Agenda
encl.
* ACRS - Advisory Committee on Reactor Safeguards 80/11/25
390pp 07308 001

B101160446 Summaries B10108-10 ACRS meeting w/NRC & TVA re proposed
interim hydrogen control sys. Results of analyses & tests
support conclusion that distributed ignition sys could
improve protection against breach of containment.
MARK, J C ACRS - Advisory Committee on Reactor Safeguards
81/01/13 1p 07470 081

B101300814 Concurs w/NRC recommendation to allow operation of interim
distributed ignition sys at facilities NRC & Util must
continue to describe performance characteristics of sys over
broader range of conditions
MARK, J C ACRS - Advisory Committee on Reactor Safeguards
81/01/13 1p 07584 316

B101250207 Forwards ACRS B10113 ltr re interim hydrogen control sys
review
SCHWENGER, A Licensing Branch 2 81/01/14 2pp 07573 027

Q Inspection reports, IE Bulletins & correspondence

B101140619 Updates licensee corrective actions following NRC B00707-11
insp of util Div of Engineering Design QA organization
restructured to provide sufficient organizational freedom,
authority & access to mgt
KIRKMAN, G H Tennessee Valley Authority 80/10/00 3pp
07462 012

B101120240 Forwards response to IE Bulletin B0-20 re Westinghouse Type
K-2 control switches w/spring return to neutral position
Switches used in all facilities except Yellow Creek Units
sys in which switches are employed.
MILLS, L M Tennessee Valley Authority 80/12/12 2pp 07447:060

B101060203 Forwards IE Info Notice B0-44, "Actuation of ECCB in
Recirculation Mode While in Hot Shutdown No written
response required.
O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/12/16
1p

B101270030 Responds to IE Bulletin B0-23 re Valcor Engineering Corp
solenoid valve failure Valcor solenoid valves V70900-21-1 &
V70900-21-3 not used Util waiting for vendor response on
valves in package components
MILLS, L M Tennessee Valley Authority 80/12/30 1p 07547:021

B101210239 Responds to IE Bulletin B0-23, "Valve Yokes Supplied by
Malcolm Foundry Co, Inc Util is in process of obtaining
assurance from valve suppliers that no Malcolm Foundry
yokes are contained in furnished valves
MILLS, L M Tennessee Valley Authority 81/01/06 1p 07490:057

R Periodic operating reports & related correspondence

B101050241 Forwards essential raw cooling water conduit settlement
monitoring data.
MILLS, L M Tennessee Valley Authority 80/12/31 1p 07378 318

--B101050250 Essential raw cooling water conduit settlement monitoring
data Oversize Tables 02 85-1 & 02 84-1 encl
* Tennessee Valley Authority 80/12/31 5pp 07378 319

B101220155 Forwards "Environ Radioactivity Levels, Sequoyah Nuclear
Plant, Annual Rept 1979" Monitoring program responsive to US
Fish & Wildlife Svc recommendations & requests
MILLS, L M Tennessee Valley Authority 81/01/15 1p 07496 081

--B101220164 "Environ Radioactivity Levels, Sequoyah Nuclear Plant, Annual
Rept 1979"
* Tennessee Valley Authority RH-B0-7-502 80/08/31 33pp
07496 082

S Reportable occurrences, LERs & related correspondence

B101290645 Revised B00403 final deficiency rept, originally submitted
B00303, re control room heating, ventilation/air conditioning
sys Corrective actions described in final rept ineffective
in reducing air leakage Addl corrective actions provided
MILLS, L M Tennessee Valley Authority 80/12/19 2pp 07566 3

B101090405 First interim deficiency rept, originally reported on B01008
re seismic analysis for as-built safety-related piping sys
Caused by discrepancies between sys & design drawings Half
of piping & 25% of hangers already inspected
MILLS, L M Tennessee Valley Authority 80/12/29 2pp 07380 1

B101070429 First interim deficiency rept re stress corrosion cracking
in tubing on reactor coolant pump oil coolers, initially
reported on B01207 Util is considering replacement of 90-10
copper-nickel tubing Next rept will be forwarded by B10203
MILLS, L M Tennessee Valley Authority 81/01/02 2pp 07415 3

B101140635 First interim deficiency rept, originally reported on B01008
re discrepancy in as-built vs as-analyzed piping anchor
location TVA analyzing discrepancy to determine hardware
changes necessary Next rept to be filed by B10220
MILLS, L M Tennessee Valley Authority 81/01/05 2pp 07461 2

B101140405 Second interim deficiency rept initially reported B01008
re seismic analysis of check valves in chemical & vol control
sys Loads from 3-inch check valve are not significant Next
rept will be submitted by B10210
MILLS, L M Tennessee Valley Authority 81/01/06 1p 07461 28

B101260427 Second interim deficiency rept, originally reported on
B01008, re seismic analysis of check valve in chemical &
vol control sys Loads from 3-inch check valve at Bequoyah
insignificant Hardware changes not required
MILLS, L M Tennessee Valley Authority 81/01/06 1p 07531 17

B101140474 First interim deficiency rept re environ qualification of
safety-related electrical equipment Vendor indicated
solenoid valves not qualified for post-accident environ in
annulus Next rept will be submitted by B10212
MILLS, L M Tennessee Valley Authority 81/01/08 2pp 07461 2

B101140616 Final deficiency rept re diesel generator interlock desl
Interlocks will be added to emergency feeder breaker
automatic close circuit before fuel load Originally reported
on B01209
MILLS, L M Tennessee Valley Authority 81/01/09 2pp 07461 1

B101190400 Interim deficiency rept, originally reported on B11210, re
fillet weld misspecification Util in process of evaluating
American Iron & Steel Inst Stds & affected welds Next rept
will be submitted by B10303
MILLS, L M Tennessee Valley Authority 81/01/09 2pp 07475 2

B101190480 Fifth interim deficiency rept re upper head injection
isolation valve accumulator weighing sys, initially reported
B00325 Westinghouse will submit revised drawings so design
changes can be incorporated
MILLS, L M Tennessee Valley Authority 81/01/09 1p 07476:00

B101190485 Third interim deficiency rept re incorrect insulation w
used in piping analysis, initially reported B00424
As-constructed insulation drawings completed Review in
progress
MILLS, L M Tennessee Valley Authority 81/01/09 1p 07475 36

B101190494 First interim deficiency rept re inability to retrieve
manufacturer valve drawings through any documentation sys by
unique identifier Utilizes as-built valve info comparable to
drawing input data to determine impact on seismic analysis
MILLS, L M Tennessee Valley Authority 81/01/12 2pp 07476:0

B101190388 Revised final deficiency rept, initially reported on B004
re environ qualification of Class IE instruments in valve
room Deletes erroneous statement in safety implications
section for B0N EEB B004, item 6.
MILLS, L M Tennessee Valley Authority 81/01/13 5pp 07475 2

B101220311 Forwards first interim rept re potential flammability of
suspended ceiling tile in control rooms in response to
B01104 ltr Addl info to be provided by B10211.
MILLS, L M Tennessee Valley Authority 81/01/14 3pp.

B101220562 Final deficiency rept, initially reported B01216, re environ
qualification of electrical equipment Automatic Switch Co
H183316815 solenoids will be replaced w/Valcor Model
70900-301 valves qualified for calculated accident environ.

DOCKETED ITEMS

B101220202 Notification of noncompliance w/effluent limitations. Three samples collected on B01222 exceeded max permit limitation of 9.0 units when valve was inadvertently left open. Plant employees instructed to check all valves.
EL-ABHRY, M T Tennessee Valley Authority 01/01/16 2pp.
07500-087.

B101220318 Informs of mechanical malfunction of water treatment plant flocculator on B01001 Equalization tank sludge built up on hydraulic line & caused crimping which shut down operations. Sludge rerouted to makeup demineralizer sump.
EL-ABHRY, M T Tennessee Valley Authority 01/01/19 2pp
07309-001

B101230436 Submits NPDES noncompliance notification. Sewage treatment plant operator inexperienced w/varying strengths of commercial sodium hypochlorite solutions, allowed chlorine levels to remain in excess of permit limitations.
EL-ABHRY, M T Tennessee Valley Authority 01/01/19 2pp
07510-312.

B101260436 First interim deficiency rept. originally reported on B01219, re inadequate steel containment penetration assembly. Affected piping will be reanalyzed to determine adequacy of assembly & pipe rupture restraint design.
MILLB, L M Tennessee Valley Authority 01/01/19 2pp. 07531-219

B101270732 Final deficiency rept. originally reported on B00918, re shifting of intermediate pipe break locations w/o notifying NRC. Safety injection & resistance temp device lines have been re-evaluated & no unacceptable interactions found.
MILLB, L M Tennessee Valley Authority 01/01/21 2pp. 07545-290

B101270609 Second interim deficiency rept. originally reported on B01024, re environ. qualification of electrical equipment. Submits list of components w/inadequate documentation to verify qualification. Next rept. will be sent B10217.
MILLB, L M Tennessee Valley Authority 01/01/23 10pp. 07183-001

F. Hearing transcripts on non-antitrust matters

B101090040 Transcript of ACRS Subcommittee on Sequoyah Nuclear Power Plant B10106 meeting in Washington, DC. Pp 1-172. Supporting documents encl.
* ACRS - Advisory Committee on Reactor Safeguards 01/01/06
242pp 07425-001.

DOCKET 50-329 MIDLAND PLANT, UNIT 1

A. Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports".
EISENHUT, D O. Division of Licensing 00/11/26 8pp

B101080345 Confirms plans for B01217 meeting in Glen Ellyn, IL to discuss recently reorganized OA unit. Notice of B01217 significant licensee meeting encl.
KEPPLER, J Q. Region 3, Chicago, Office of the Director 00/12/12
2pp. 07417-349

B101120243 Requests concurrence re util B01126 request that open items related to structural integrity be included for resolution as part of pending structural design audit.
HODD, D. Licensing Branch 3 00/12/19 2pp 07309-001

--B101120250 Requests that open items re NRC audit of safety-related structures be incorporated into FSAR review & SER preparation. Proposed items: external pressure analysis, penetration structural integrity & floor response spectra.
COKK, J W. Consumers Power Co. 00/11/26 2pp 07309-001.

B101100740 Summary of B01205 meeting w/CRC, Bechtel, Weston Geophysical Corp & Structural Mechanics Associates in Bethesda, MD re seismic input parameters.
HODD, D. Licensing Branch 3 00/12/22 7pp. 07187-001

B101150916 Forwards util B01231 rept re reactor vessel support mod at facilities, completing matl necessary for NRC review of revised support concept for Unit 1. Util has requested confirmation of acceptability of Unit 2 studs.
MIRAGLIA, F. Licensing Branch 3 00/12/23 2ppp 07309-001

--B101050132 Forwards public version of Amend B6 to application, containing Revision 31 to FSAR.
COKK, J W. Consumers Power Co 00/12/16 4pp 07375-001

B101100592 Notification of B10120 meeting w/Energy Technology Engineering Ctr, util & Bechtel in Bethesda, MD to resolve differences in bending stresses calculated for underground pipes at facilities.
HODD, D. Licensing Branch 3 00/12/31 5pp 07443-298

B101140815 Summary of B00731 meeting w/util, Bechtel Corp & Bechtel consultants in Bethesda, MD re request for add'l soil borings & tests. List of meeting attendees, agenda, summary & visual aids used during meeting encl.
HODD, D. Licensing Branch 3 01/01/06 35pp 07461-060

B101220109 Updates NRC B01110 ltr granting util request for add'l borings & six std penetration test requirements. Details of relaxation & changed boring locations listed.
TEDESCO, R L. Assistant Director for Licensing 01/01/09
07309-001

--B101220122 Concurs w/NRC B01110 ltr re util request for re-making add'l borings & testings of soil samples from site. Forwards map showing borings in plant fill area & map showing relocated borings on cooling pond dikes.
MCALLISTER, P. Army, Dept of Engineers 00/12/09
07309-001

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR.
EISENHUT, D O. Division of Licensing 00/11/13 2pp

B101070259 Requests that encl emergency planning info be made available w/o encl.
SQUIDER, J L. Division of Rules and Records 00/12/17 1p
07414-299

B101050116 Releases public version of util emergency plan, Rev 1 to FSAR.
FELTON, J M. Division of Rules and Records 00/12/30 1p
07375-001

--B101050132 Forwards public version of Amend B6 to application, containing Revision 31 to FSAR.
COKK, J W. Consumers Power Co 00/12/16 4pp 07375-001

--B101050145 Public version of Revision 31 to FSAR.
* Consumers Power Co 00/11/30 200pp 07375-006.

B101270998 Requests that encl facility emergency planning info be publicly available w/o encl.
SQUIDER, J L. Division of Rules and Records 01/01/13 1p
07548-361

G. Adjudicatory correspondence

B101120444 Response to NRC Interrogatories 1-3 re plant fill & discrepancies in magnitude of loading stress Affidavits encl.
SWANDERO, H. AFIF, S. Consumers Power Co 00/12/16 7pp
07442-310

B101030358 Advises of acceptance as intervenor in NRC hearing continuation of facility const. Also requests time to make presentation at B10120-29 prehearing conference.
MARSHALL, W H. Mapleton Intervenor. 00/12/22 2pp 073

B101030384 Forwards summary of B00730 conversation w/JO Kepp general NRC enforcement issues. Because conversation could be considered ex parte contact in plant proceeding, encl summary should be served on all parties.
GIBSON, T R. Commissioners 00/12/29 2pp. 07375-342.

B101070684 Notice of F. Rinaldi, JO. Keppler, Huang, J. Kane, W. Ott, R. Erickson, J. Branner, Gilray, Shoemaker, H. Singh, A. Cappucci, & P. Chen depositions on B10106, 07-09 & 17-22 re issues set forth in order modifying CPs w/Certificate of Svc.
FARNELL, A S. Consumers Power Co. FARNELL, A S. Isham, L. L.

Certificate of Svc encl
PATON, W.D. Hearing Branch 4 80/12/30 4pp 07390 124

B101050424 Memorandum summarizing B01227 telcon between ASLB, CPC, NRC, Mr. Cherry for intervenor KP Sinclair intervenors B Stamiris & SA Warren & LM Marshall for Rappleton intervenors
BECHHOEFER, C Atomic Safety and Licensing Board Panel 80/12/31 8pp 07387 075

B101070374 Confirms B01229 conversation re B01204 document request Util documents not subj to atty-client privilege b/or work-product privilege will be available by B10119 at Midland Svc Ctr
FARNELL, A.S. Isham, Lincoln & Seale 80/12/31 1p 07415 297

B101090378 Notice of J Matra B10108 deposition in Bethesda, MD re 791206 order modifying CPs & B01024 contentions in app to prehearing conference order ruling on contentions
Certificate of Svc encl
FARNELL, A.S. Consumers Power Co FARNELL, A.S. Isham, Lincoln & Seale 80/12/31 4pp 07425 260

B101050073 Interrogatories directed to licensee requesting info re piping & backfill mail Certificate of Svc encl
PATON, W.D. Hearing Branch 4 81/01/02 12pp 07376 070

B101120515 Forwards JO Kane B01202-04 depositions per B01204 motion for protective order & NRC B01205 ltr w/o encl
JONES, B.W. Hearing Branch 2 81/01/08 1p 07309 001

B101140928 Request for correction of B01231 memorandum re B01229 telephone conference call Certificate of Svc encl
ZAMARIN, R.G. Consumers Power Co ZAMARIN, R.G. Isham, Lincoln & Seale 81/01/09 5pp 07453 251

B101140872 Response opposing intervenor B Stamiris request to receive deposition copies ASLB is w/o authority per Comptroller
General B01203 ltr Certificate of Svc encl
PATON, W.D. Hearing Branch 4 81/01/12 4pp 07458 214

B101140972 Reply opposing NRC B01204 motion for protective order prohibiting further deposition of J Kane NRC should be ordered to pay fees & costs incurred in responding to NRC motion & concluding Kane deposition Certificate of Svc encl
ZAMARIN, R.G. Consumers Power Co ZAMARIN, R.G. Isham, Lincoln & Seale 81/01/12 34pp 07458 262

B101200154 Notice of Keppler & Naider B10116 depositions in Glen Ellyn, IL re 791206 order modifying CPs & contentions in B01024 prehearing conference order app Certificate of Svc encl
FARNELL, A.S. Consumers Power Co FARNELL, A.S. Isham, Lincoln & Seale 81/01/14 4pp 07486 139

B101200210 Request for leave to file response to CPC B10109 reply to NRC B01204 motion for protective order transcripts not available when order was sought & time considerations noted.
Certificate of Svc encl
OLMSTEAD, W.J. Hearing Branch 4 81/01/16 4pp 07476 337

B101260480 Motion to compel K Naider deposition & for order directing NRC to pay util reasonable atty fees & costs Certificate of Svc encl
ZAMARIN, R.G. Consumers Power Co ZAMARIN, R.G. Isham, Lincoln & Seale 81/01/16 5pp 07524 303

B101230164 Notice of Hendon B10127 deposition in Savoy, IL re issues in ASLB 791206 order & contentions of intervenors Stamiris & Warren Certificate of Svc encl
JONES, B.W. Hearing Branch 2 81/01/19 4pp 07512 030

B101260273 Response to intervenor B Stamiris B01204 interrogatories & request for production of documents Ltr to Stamiris, affidavits & Certificate of Svc encl Related correspondence
* Consumers Power Co 81/01/21 12pp 07523 336

B101280149 Order granting NRC B10116 motion to file reply to applicant B10109 response to NRC motion for protective order Reply must be filed & delivered to ASLB & applicant by close of business on B10126 Certificate of Svc encl
BECHHOEFER, C Atomic Safety and Licensing Board Panel 81/01/22 5pp 07556 102

B101270329 Ack receipt of mailgram re free transcripts for intervenor Stamiris under FOIA Request denied per encl ALAD-625
PATON, W.D. Hearing Branch 4 81/01/23 1p 07546 075

summaries. B&W study & NRC policy to be given to LPDR.
PATON, W.D. Hearing Branch 4 81/01/23 2pp 07544:097

B101280299 Motion for order compelling G Fiorelli deposition directing NRC to pay atty fees & costs incurred by util
Certificate of Svc encl
FARNELL, A.S. Consumers Power Co FARNELL, A.S. Isham, Lincoln & Seale 81/01/23 6pp 07557 148

B101290012 Proposed agenda for B10129 prehearing conference conclusion of discovery, further prehearing conferences, motions for summary disposition, filing of testimony, evidentiary hearing & filing of proposed findings of fact.
MILLER, M.I. Consumers Power Co MILLER, M.I. Isham, Lincoln & Seale 81/01/23 2pp 07567 190

--B101290020 Requests order compelling H Thornburg deposition NRC to pay atty fees & costs incurred by util
MILLER, M.I. Consumers Power Co MILLER, M.I. Isham, Lincoln & Seale 81/01/23 5pp 07567 192

--B101290025 Forwards input for Midland order Certificate of Svc encl
SHEWMAKER, R.E. Division of Reactor Construction Inspection 79/11/30 5pp 07567 197

B101280573 Response to CPC B10109 reply to NRC motion for protective order Opposes util claim for expenses Length & method of questioning & Zamarin conduct justify protective order.
Certificate of Svc encl
JONES, B.W. Office of the Executive Legal Director 81/01/22 222

B101280611 Response opposing CPC B10115 motion to compel K Naider deposition Scheduled witnesses are equally knowledgeable in exceptional circumstances exist Certificate of Svc encl
OLMSTEAD, W.J. Hearing Branch 4 81/01/27 6pp 07557 214

H General correspondence

B101050314 Requests exception to NRC B01215 ltr re transcript facility proceedings LPDR is 15 miles from home & personal responsibilities do not allow library use during regular hours.
STAMIRIS, B. Affiliation Unknown 80/12/22 1p 07379 214

A Utility Final Safety Analysis Report (FSAR) & amendments

B101050116 Releases public version of util emergency plan, Revision 32 to FSAR
FELTON, J.M. Division of Rules and Records 80/12/30 1p 07375 006

--B101050132 Forwards public version of Amend B6 to application, containing Revision 31 to FSAR
COCK, J.W. Consumers Power Co 80/12/16 4pp

--B101050145 Public version of Revision 31 to FSAR.
* Consumers Power Co 80/11/30 200pp 07375 006

B101270385 Forwards Amend B7 to DL & CP applications, consisting Revision 32 to FSAR, Vols 1-3.
AULTQUIST, L. Bachtel Associates Professional Corp 81/01/23 120

--B101270590 Revision 32 to FSAR, Vols 1-3
* Consumers Power Co 81/01/21 900pp 07558 121

P Operating license stage documents & correspondence

B101190577 Explains distribution list for two generic ltrs re feedwater nozzle cracking
MIRAGLIA, F.J. Licensing Branch 3 81/01/06 2pp 07477 001

G Inspection reports, IE Bulletins & correspondence

B101090283 Forwards IE Info Notice 80-38, "Cracking in Char Casing Cladding " No response required
KESSLER, J.G. Region 3, Chicago, Office of the Director 2pp 07387 240

B101060713 Forwards IE Bulletin 80-21, "Valve Yokes Supplied Malcolm Foundry Co, Inc " Written response required.
KESSLER, J.G. Region 3, Chicago, Office of the Director 2pp 07400 283

B01060371 Forwards IE Info Notice B0-41. "Failure of Spring Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/11/10
2pp 07391 070

B01070229 Forwards IE Insp Repts 50-329/B0-31 & 50-330/B0-32 on B01001-31 & notice of violation
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/11/19 2pp 07415 163

--B01070233 Notice of violation from Insp on B01001-31
* Region 3, Chicago, Office of the Director 80/11/10 1p
07415:165

--B01070256 IE Insp Repts 50-329/B0-31 & 50-330/B0-32 on B01001-31
Noncompliance noted failure to expedite 10CFR50.55 reportability determinations based on 10CFR21 info re possible defects in engine link rods
COOK, J. W. KNUP, R. C. Region 3, Chicago, Office of the Director 80/11/10 8pp 07415 166

B01000011 Forwards IE Insp Repts 50-329/B0-30 & 50-330/B0-31 on B01007-10 & 15-23 No noncompliance noted
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/11/21 2pp 07441 297

--B01000013 IE Insp Repts 50-329/B0-30 & 50-330/B0-31 on B01007-10 & 15-23 No noncompliance noted Major areas inspected training records, audit activity & personnel air locks
NATDU, K. R., SUTPHIN, R. N., KNUP, R. C. Region 3, Chicago, Office of the Director 80/11/21 19pp 07441 297

B01050524 Forwards IE Info Notice B0-43. "Failures of Continuous Water Level Monitor for Scream Discharge Val at Dresden Unit 2." No response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/12/05
2pp. 07390 292

B01290099 Forwards IE Insp Repts 50-329/B0-27 & 50-330/B0-28 on B00923-24, 1103-04, 12-13 & 19 No noncompliance noted
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/11 2pp. 07567 267.

--B01290122 IE Insp Repts 50-329/B0-27 & 50-330/B0-28 on B00923-24, 1103-04, 12-13 & 19 No noncompliance noted Major areas inspected preservice insp procedures, personnel certifications & data & IE Bulletin B0-0B activities
WARD, K. D. Region 3, Chicago, Office of the Director.
DANIELSON, D. H. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/10 11pp. 07567 269

B01210526 Forwards IE Insp Repts 50-329/B0-34 & 50-330/B0-35 on B01101-30. No noncompliance noted.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/12 2pp. 07408 155.

--B01210533 IE Insp Repts 50-329/B0-34 & 50-330/B0-35 on B01101-30 No noncompliance noted Major areas inspected diesel generator link rods, metal thickness requirements & licensee performance assessment
COOK, J. W., KNUP, R. C. Region 3, Chicago, Office of the Director. 80/12/11 5pp 07408 157.

B01050407 Responds to NRC B00810 ltr & Investigation Repts 50-329/B0-13 & 50-330/B0-14 Util disagrees w/certain aspects of rept. Bechtel memo & ltr to util from B&W encl.
COOK, J. W. Consumers Power Co. 80/12/16 11pp 07379 289

B01070079 Forwards IE Info Notice B0-44. "Actuation of ECCB in Recirculation Mode While in Hot Shutdown." No written response required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/12/16 1p. 07415 047

B01290270 Forwards Mgt Meeting Repts 50-329/B0-35 & 50-330/B0-36 on B01124
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/12/18 2pp. 07575 012.

--B01290283 Mgt Meeting Repts 50-329/B0-35 & 50-329/B0-36 on B01124. Major areas discussed regulatory performance of activities as concluded in systematic assessment of licensee performance program.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/12/18. 7pp 07575 014

B01050595 Ack receipt of B00825 & 1107 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/B0-20 & 50-330/B0-21
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/23 1p 07390 249

--B01050600 Responds to NRC B01008 ltr re violations noted in IE Repts 50-329/B0-20 & 50-330/B0-21 Corrective actions all met through const phase is receipt inspected by UC
COOK, J. W. Consumers Power Co 80/11/07 3pp 07390 250

B01060267 Ack receipt of B01217 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/B0-31 & 50-330/B0-32
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/30 1p 07392 010

--B01060272 Responds to NRC B01119 ltr re violations noted in IE Repts 50-329/B0-31 & 50-330/B0-32 Corrective actions training sessions for key personnel to be conducted re proper handling of Part 21 repts
COOK, J. W. Consumers Power Co 80/12/17 1p. 07392 011

B01160296 Forwards IE Insp Repts 50-329/B0-33 & 50-330/B0-34 on B01201-04 No noncompliance noted
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/30 2pp 07470 251

--B01160299 IE Insp Repts 50-329/B0-33 & 50-330/B0-34 on B01201-04 Noncompliance noted Major areas inspected hardness results of embedded bolts for lateral shudders attached to primary coolant pumps
ERB, C. M. Region 3, Chicago, Office of the Director
DANIELSON, D. H. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/30 5pp 07470 253

B01280591 Responds to IE Bulletin B0-23 Valcor solenoid valves used or planned for use in safety-related functions
COOK, J. W. Consumers Power Co 81/01/06 1p 07557 310

B01200506 Forwards notice of violation & notice of proposed imposition of civil penalties re NRC B00306-0731 investigation
STELLO, V. Director's Office, Office of Inspection and Enforcement 81/01/07 2pp 07477 290

--B01200590 Notice of violation from investigation on B00306-0731
* Director's Office, Office of Inspection and Enforcement 81/01/07 13pp 07477 292

--B01200595 Notice of proposed imposition of civil penalties in of \$30,000 CO for item of violation discovered during investigation on B00306-0731
* Director's Office, Office of Inspection and Enforcement 81/01/07. 1p. 07477 305

R Periodic operating reports & related correspondence

B012310225 Forwards monthly rept per ALAB-106 Bechtel nonconformity repts, Bechtel nonconformance rept log, Bechtel quality action requests, B&W repts of nonconformity, B&W inservice insp nonconformance repts & util nonconformance repts encl
COOK, J. W. Consumers Power Co 80/12/23 350pp 07308 001

B01050365 Forwards Rept 32 for Jan-Mar 1981 per Conditions 2FB of Licenses CPPR-01 & CPPR-02 & 730226 Memorandum & Order ALAB-106
COOK, J. W. Consumers Power Co 80/12/30 24pp 07375 346

B01290580 Forwards ALAB-106 monthly rept for Dec 1980 Bechtel nonconformance repts, quality action requests, mgt corrective action repts, repts of nonconformity, inservice insp nonconformance repts & util nonconformance repts, encl
COOK, J. W. Consumers Power Co 81/01/23 400pp 07309 001

S Reportable occurrences, LERs & related correspondence

B01090513 Interim deficiency rept re overstressed condition in cooler supports Mod being evaluated. Interim or final rept will be submitted on or before B0130.
COOK, J. W. Consumers Power Co 80/12/30 2pp. 07442 285

B01090594 Interim deficiency rept, originally reported on B00327 overstressed condition in letdown cooler supports Mod extent will be determined after analysis of actual nozzle loads & existing supports is completed by AE.
COOK, J. W. Consumers Power Co. 80/12/30 2pp. 07442 012.

B010690185 EN-60-050 en re about B010102 notice of violation & notice of proposed imposition of civil penalties will be issued to util Action based on 56 infractions re major deficiencies in QA program for heating contractor
THRECKETT, T. THOMPSON, D. Office of Inspection & Enforcement, Office of the Director B1/01/02 1p 07442 274

B01140653 Interim Deficiency, Rept 1 re status of low alloy quenched & tempered bolting 1.5 inches & greater in support of safety-related sys Interim or final rept to be provided by B10331 Description of investigation encl
COOK, J.W. Consumers Power Co B1/01/09 14pp. 07308 001

B011236581 Interim deficiency rept re defective sway strut rod ends, initially reported on B01031 Solutions are being investigated & will be coordinated w/all vendors to obtain generic solution Next rept will be forwarded by B01227
COOK, J.W. Consumers Power Co RUTGERS, J.A. Bechtel Power Corp (subs of Bechtel Corp.) B1/01/15 9pp 07911 220

T. Hearing transcripts on non-antitrust matters

B:01050303 Proposed transcript corrections to DS Hood B01229 deposition Certificate of Svc encl
PATON, W.D. Hearing Branch 4 B0/12/29 6pp 03889 289

B011308745 Transcript of ASLB B010108 hearing in Flemington, NJ Pg 1-120.
* Atomic Safety and Licensing Board Panel B1/01/08 121pp 07582 001

DOCKET 50-330 MIDLAND PLANT, UNIT 2

A. Application/construction stage documents & correspondence

B011220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D.G. Division of Licensing, B0/11/26 8pp

B011080345 Confirms plans for B01217 meeting in Glen Ellyn, IL to discuss recently reorganized QA unit Notice of B01217 significant licensee meeting encl
KEPPLER, J.G. Region 3, Chicago, Office of the Director B0/12/12 2pp 07417 349

B01120243 Requests concurrence re util B01126 request that open items related to structural integrity be included for resolution as part of pending structural design audit
HODD, D. Licensing Branch 3 B0/12/19 2pp. 07309 001.

--B01120250 Requests that open items re NRC audit of safety-related structures be incorporated into FSAR review & BER preparation Proposed items external pressure analysis, penetration structural integrity & floor response spectra
COOK, J.W. Consumers Power Co. B0/11/26 2pp 07309.001

B011100740 Summary of B01205 meeting w/CPC, Bechtel, Weston Geophysical Corp & Structural Mechanics Associates in Bethesda, MD re seismic input parameters
HODD, D. Licensing Branch 3. B0/12/22. 7pp. 07187 001

B01150916 Forwards util B01231 rept re reactor vessel support mod at facilities, completing matl necessary for NRC review of revised support concept for Unit 1 Util has requested confirmation of acceptability of Unit 2 studs
MIRAGLIA, F. Licensing Branch 3 B0/12/23 2ppp 07309 001

B01050116 Releases public version of Util emergency plan, Revision 31 to FSAR.
FELTON, J.M. Division of Rules and Records B0/12/30 1p

--B01050132 Forwards public version of Amend B6 to application for CPs & OLS, containing Revision 31 to FSAR
COOK, J.W. Consumers Power Co B0/12/16 4pp

B011100292 Notification of B01120 meeting w/Energy Technology Engineering Ctr, util & Bechtel in Bethesda, MD to resolve differences in bending stresses calculated for underground pipes at facilities
HODD, D. Licensing Branch 3 B0/12/31 9pp. 07443 298.

B01140015 Summary of B00731 meeting w/util, Bechtel Corp & Bechtel consultants in Bethesda, MD re request for addl soil borings & tests List of meeting attendees, agenda, summary & visual aids used during meeting encl.
HODD, D. Licensing Branch 3 B1/01/06. 35pp. 07461 060

B01220109 Updates NRC B01110 ltr granting util request for re addl borings & soil penetration test requirements Detail of relaxation & changed boring locations listed.
TEDESCO, R.L. Assistant Director for Licensing B1/01/08 07309 001

--B01220122 Concurs w/NRC B01110 ltr re util request for re making addl borings & testings of soil samples from site Forwards map showing borings in plant fill area & map showing relocated borings on cooling pond dikes.
MCALLISTER, P. Army, Dept of, Corps of Engineers B0/12/07309 031

B01190604 Forwards info package for independent piping analysis, decay heat removal & core flooding sys info package updates B00612 submittal of piping design package
COOK, J.W. Consumers Power Co B1/01/12 22pp 07475 177

F. Security, medical, emergency & fire protection plans

B010490387 Ltr to all licensees of operating reactor plants, CPs & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B010102 & by applicants as part of FSAR
EISENHUT, D.G. Division of Licensing B0/11/13 2pp.

B01070259 Requests that encl emergency planning info be made available w/o encl.
GOUVER, J.L. Division of Rules and Records B0/12/17. 1p 07414 299

B01050116 Releases public version of util emergency plan, Rev to FSAR
FELTON, J.M. Division of Rules and Records B0/12/30 1p. 07375 001

--B01050132 Forwards public version of Amend B6 to application OLS, containing Revision 31 to FSAR.
COOK, J.W. Consumers Power Co. B0/12/16 4pp 07375.001

--B01050145 Public version of Revision 31 to FSAR
* Consumers Power Co. B0/11/30 200pp. 07375 006

B01270990 Requests that encl facility emergency planning info be publicly available. w/o encl
GOUVER, J.L. Division of Rules and Records. B1/01/13. 1p. 07540 361

G. Adjudicatory correspondence

B01120444 Response to NRC Interrogatories 1-3 re plant fill & discrepancies in magnitude of loading stress Affidavits encl
SWANBERG, N. AFIFI, S. Consumers Power Co. B0/12/16. 7pp. 07442.310.

B01050358 Advises of acceptance as intervenor in NRC hearing continuation of facility const Also requests time to make presentation at B01128-29 prehearing conference.
MARSHALL, W.H. Mapleton Intervenors B0/12/22. 2pp. 07375 001

B01050384 Forwards summary of B00730 conversation w/J0 Keppl general NRC enforcement issues. Because conversation could be considered ex parte contact in plant proceeding, encl summary should be served on all parties.
QIDRON, T.R. Commissioners. B0/12/29 2pp. 07375 342

B01090384 Notice of F Rinaldi, J0 Keppler, Huang, J Kane, W Otto, R Erickson, J Brammer, Gilray, Shoemaker, H Singh, A Cappuchi & P Chen depositions on B0106, 07, 09 & 19-22 re issues set forth in order modifying CPs w/Certificate of Svc.
FARNELL, A.S. Consumers Power Co FARNELL, A.S. Isham, Lin Beale. B0/12/29 4pp 07426 264.

B01050421 Notice of C Gould, RB Peck & MT Davison deposition B0113-14 & 14-15, respectively, re issues set forth in ASLB 791206 order modifying CPs & Stamiris & Warren contentions. Certificate of Svc encl.
PATON, W.D. Hearing Branch 4. B0/12/30 4pp. 07390 124.

B01050624 Memorandum summarizing B01229 telcon between ASLB, Cherry for intervenor HP Sinclair intervenors B Stamiris & SK Warren & WH Marshall for Mapleton intervenors.
BECHHOEFER, C. Atomic Safety and Licensing Board Panel. B0/12/29. 07307 075.

Ctr.
FARNELL, A S Isham, Lincoln & Seale 80/12/31 1p 07415 297

B101090078 Notice of J Matra B10108 deposition in Bethesda, MD re 791206 order modifying CPs & B101024 contentions in app to prehearing conference order ruling on contentions Certificate of Svc encl
FARNELL, A S Consumers Power Co. FARNELL, A S Isham, Lincoln & Seale. 80/12/31 4pp 07426 260

B101090073 Interrogatories directed to licensee requesting info re piping & backfill matl Certificate of Svc encl
PATON, W D Hearing Branch 4 81/01/02 12pp 07376 070.

B101120515 Forwards JD Kane B101202-04 depositions per B101204 motion for protective order & NRC B01205 ltr w/o encl
JONES, B W. Hearing Branch 2 81/01/08 1p. 07309 001

B101140968 Request for correction of B01231 memorandum re B01229 telephone conference call Certificate of Svc encl
ZAMARIN, R O Consumers Power Co. ZAMARIN, R O Isham, Lincoln & Seale. 81/01/09 3pp 07458 251

B101140972 Response opposing intervenor B Stamiris request to receive deposition copies ASLB is w/o authority per Comptroller General B101203 ltr Certificate of Svc encl
PATON, W D Hearing Branch 4 81/01/12 4pp 07458 214

B101140973 Reply opposing NRC B01204 motion for protective order prohibiting further deposition of J Kane NRC should be ordered to pay fees & costs incurred in responding to NRC motion & concluding Kane deposition Certificate of Svc encl
ZAMARIN, R Consumers Power Co. ZAMARIN, R Isham, Lincoln & Seale 81/01/12. 34pp 07458 263

B101200154 Notice of Koppler & Naidor B10116 depositions in Glen Ellyn, IL re 791206 order modifying CPs & contentions in B01024 prehearing conference order app Certificate of Svc encl
FARNELL, A S Consumers Power Co. FARNELL, A S Isham, Lincoln & Seale. 81/01/14 4pp 07406 139

B101200210 Request for leave to file response to CPC B10109 reply to NRC B01204 motion for protective order. Transcripts not available when order was sought & time considerations noted Certificate of Svc encl
OLMSTEAD, W J Hearing Branch 4 81/01/16. 4pp. 07476 337

B101260480 Motion to compel K Naidu deposition & for order directing NRC to pay util reasonable atty fees & costs Certificate of Svc encl
ZAMARIN, R O. Consumers Power Co. ZAMARIN, R O. Isham, Lincoln & Seale 81/01/16. 5pp 07524 303

B101230164 Notice of Hendon B10127 deposition in Savoy, IL re issues in ASLB 791206 order & contentions of intervenors Stamiris & Warren Certificate of Svc encl
JONES, B W. Hearing Branch 2. 81/01/19. 4pp. 07512 030

B101260273 Response to intervenor B Stamiris B01204 interrogatories & request for production of documents, ltr to Stamiris, affidavits & Certificate of Svc encl Related correspondence.
* Consumers Power Co 81/01/21 12pp 07523 336

B101280149 Order granting NRC B10116 motion to file reply to applicant B10109 response to NRC motion for protective order. Reply must be filed & delivered to ASLB & applicant by close of business on B10126. Certificate of Svc encl
DECHHOEFER, C. Atomic Safety and Licensing Board Panel 81/01/22 5pp. 07536 102.

B101270329 Ack receipt of mailgram re free transcripts for intervenor Stamiris under FOIA Request denied per encl ALAB-625
PATON, W D. Hearing Branch 4 81/01/23 1p. 07546 075.

B101270394 Ack agreement re intervenor B Stamiris document request Record of CPC 781107 telcon w/NRC, IE Insp Repts 50-329/77-05 & 50-330/77-08, 790508-11 GA insp rept, meeting summaries, B&W study & NRC policy to be given to LPDR.
PATON, W D. Hearing Branch 4 81/01/23 2pp. 07544 097.

B101280279 Motion for order compelling G Fiorelli deposition & directing NRC to pay atty fees & costs incurred by util. Certificate of Svc encl.
FARNELL, A S Consumers Power Co. FARNELL, A S Isham, Lincoln & Seale. 81/01/23 6pp. 07557 148.

evidentiary hearing & filing of proposed findings of fact
MILLER, M I Consumers Power Co MILLER, M I Isham, Lincoln & Seale 81/01/23. 2pp. 07567 190

--B101290020 Requests order compelling H Thornburg deposit NRC to pay atty fees & costs incurred by util
MILLER, M I Consumers Power Co. MILLER, M I Isham, Lincoln & Seale 81/01/23 3pp. 07567 192

--B101290025 Forwards input for Midland order Certificate of Svc encl
BHEWMAKER, R E. Division of Reactor Construction Inspection 79/11/30. 3pp 07567 197.

B101280593 Response to CPC B10109 reply to LRC motion for protective order. Opposes util claim for expenses Length & method of questioning & Zamarin conduct justify protective order. Certificate of Svc encl.
JONES, B W Office of the Executive Legal Director 81/01/23 07557 222

B101280611 Response opposing CPC B10115 motion to compel K deposition Scheduled witnesses are equally knowledgeable exceptional circumstances exist Certificate of Svc encl
OLMSTEAD, W J Hearing Branch 4. 81/01/27 6pp. 07557 222

H General correspondence

B101050314 Requests exception to NRC B01215 ltr re transfer facility proceedings LPDR is 15 miles from home & personal responsibilities do not allow library use during regular hours
STAMIRIS, B Affiliation Unknown 80/12/22 1p 07379 001

K Utility Final Safety Analysis Report (FSAR) & amendments

B101050116 Releases public version of util emergency plan, ltr to FSAR
FELTON, J M Division of Rules and Records. 80/12/30.

--B101050132 Forwards public version of Amend 06 to application, containing Revision 31 to FSAR
COOK, J W Consumers Power Co 80/12/16 4pp

--B101050145 Public version of Revision 31 to FSAR
* Consumers Power Co 80/11/30 200pp

B101270385 Forwards Amend 07 to OL & CP applications, containing Revision 32 to FSAR, Vols 1-3
AULTQUIST, L Bechtel Associates Professional Corp 81/01/23 07598 120

--B101270390 Revision 32 to FSAR, Vols 1-3.
* Consumers Power Co. 81/01/21 900pp 07598 121

P Operating license stage documents & correspondence

B101190577 Explains distribution list for two generic ltrs Feedwater nozzle cracking.
MIRAOLIA, F J Licensing Branch 3. 81/01/06 2pp. 07474 001

Q Inspection reports, IE Bulletins & correspondence

B101050283 Forwards IE Info Notice 80-30, "Cracking in Casing Cladding." No response required.
KEPPLER, J G Region 3, Chicago, Office of the Director. 2pp 07389 240

B101060713 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required
KEPPLER, J G Region 3, Chicago, Office of the Director. 2pp. 07400 283

B101060371 Forwards IE Info Notice 80-41, "Failure of Swirl Valve in Decay Heat Removal Sys at Davis Besse Unit 1." response required
KEPPLER, J G Region 3, Chicago, Office of the Director. 2pp. 07391 070.

B101070229 Forwards IE Insp Repts 50-329/80-31 & 50-330/80-31, notice of violation.
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/11/19 2pp. 07415 163

-B01070237 Notice of violation from insp on B01001-31
Region 3, Chicago, Office of the Director 80/11/18 1p
07415 169

--B01070236 IE Insp Repts 50-329/80-31 & 50-330/80-32 on B01001-31
noncompliance noted failure to expedite 10CFR30.95
reportability determinations based on 10CFR21 info re
possible defects in engine link rods
COCKA, J. W. Region 3, Chicago, Office of the Director
80/11/18 0pp 07415 169

B01100011 Forwards IE Insp Repts 50-329/80-30 & 50-330/80-31 on
B01007-10 & 15-23 No noncompliance noted
FIGURELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/11/21 2pp 07441 297

--B01100713 IE Insp Repts 50-329/80-30 & 50-330/80-31 on B01007-10 &
15-23 No noncompliance noted Major areas inspected training
records, audit activity & personnel air locks
MAHEU, A. R., SUTPHIN, R. H., KEPLER, J. G. Region 3, Chicago, Office of
the Director 80/11/21 19pp 07441 299

B01050924 Forwards IE Info Notice 80-43, "Failures of Continuous Water
Level Monitor for Scram Discharge Vut at Dresden Unit 2 " No
response required
KEPLER, J. G. Region 3, Chicago, Office of the Director 80/12/05
2pp 07390 292

B01029009 Forwards IE Insp Repts 50-329/80-27 & 50-330/80-28 on
B00923-24, 1103-04, 12-13 & 19 No noncompliance noted.
FIGURELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/12/11 2pp 07567 267

--B01029012 IE Insp Repts 50-329/80-27 & 50-330/80-28 on B00923-24,
1103-04, 12-13 & 19 No noncompliance noted Major areas
inspected preservice insp procedures, personnel
certifications & data & IE Bulletin 00-00 activities
WARD, A. D. Region 3, Chicago, Office of the Director,
DANIELSON, D. H. Region 3, Chicago, Reactor Construction &
Engineering Support Branch 80/12/10 11pp 07567 267

B010210936 Forwards IE Insp Repts 50-329/80-34 & 50-330/80-35 on
B01101-30 No noncompliance noted
FIGURELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/12/12 2pp 07468 155

--B010210533 IE Insp Repts 50-329/80-34 & 50-330/80-35 on B01101-30 No
noncompliance noted Major areas inspected diesel generator
link rods, metal thickness requirements & licensee
performance assessment
COCKA, J. W., KEPLER, J. G. Region 3, Chicago, Office of the Director
80/12/11 5pp 07468 157

B01050407 Responds to NRC B00818 ltr & investigation Repts
50-329/80-13 & 50-330/80-14 Util disagrees w/certain aspects
of rept Bechtel memo & ltr to util from B&W encl
COCKA, J. W. Consumers Power Co 80/12/16 11pp 07379 289

B01070079 Forwards IE Info Notice 80-44, "Actuation of ECCB in
Recirculation Mode While in Hot Shutdown." No written
response required
KEPLER, J. G. Region 3, Chicago, Office of the Director 80/12/16
1p 07415 047.

B010290270 Forwards Mgt Meeting Repts 50-329/80-35 & 50-330/80-36 on
B01124
KEPLER, J. G. Region 3, Chicago, Office of the Director 80/12/18
2pp 07975 012

--B010290283 Mgt Meeting Repts 50-329/80-35 & 50-329/80-36 on B01124.
Major areas discussed regulatory performance of activities
as concluded in systematic assessment of licensee
performance program
FIGURELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/12/18, 7pp 07575 014

B01050595 Ack receipt of B00825 & 1107 ltrs informing NRC of steps
taken to correct violations noted in IE Insp Repts
50-329/80-20 & 50-330/80-21.
FIGURELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/12/22 1p 07390 249

-B01050600 Responds to NRC B01008 ltr re violations noted in IE Insp
Repts 50-329/80-20 & 50-330/80-21 Corrective actions, all
mail through const phase is receipt inspected by GC
COCKA, J. W. Consumers Power Co 80/11/07 3pp 07390 250

B01060269 Ack receipt of B01217 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-329/80-31 &
50-330/80-32
FIGURELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/12/30 1p 07392 010

--B01060272 Responds to NRC B01119 ltr re violations noted in IE Insp
Repts 50-329/80-31 & 50-330/80-32 Corrective actions
training sessions for key personnel to be conducted re
proper handling of Part 21 repts
COCKA, J. W. Consumers Power Co 80/12/17 1p 07392 011

B01100256 Forwards IE Insp Repts 50-329/80-33 & 50-330/80-34 on
B01201-04 No noncompliance noted
FIGURELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/12/30 2pp 07470 251

--B01100259 IE Insp Repts 50-329/80-33 & 50-330/80-34 on B01201-04
noncompliance noted Major areas inspected hardness results
of embedded bolts for lateral snubbers attached to primary
coolant pumps
EHR, C. M. Region 3, Chicago, Office of the Director
DANIELSON, D. H. Region 3, Chicago, Reactor Construction &
Engineering Support Branch 80/12/30 5pp 07470 293

B010200591 Responds to IE Bulletin 80-23 Valcor solenoid valves not
used or planned for use in safety-related functions
COCKA, J. W. Consumers Power Co 81/01/06 1p 07597 310

B010200586 Forwards notice of violation & notice of proposed imposition
of civil penalties re NRC B00306-0731 investigation
STELCO, V. Director's Office, Office of Inspection and Enforcement
81/01/07 2pp 07477 290

--B010200390 Notice of violation from investigation on B00306-0731
Director's Office, Office of Inspection and Enforcement
81/01/07 13pp 07477 292

--B010200595 Notice of proposed imposition of civil penalties in an
amount of \$28,000.00 for item of violation discovered during
investigation on B00306-0731
Director's Office, Office of Inspection and Enforcement
81/01/07 1p 07477 305

R Periodic operating reports & related correspondence

B01080365 Forwards Rept 32 for Jan-Mar 1981 per Conditions 2FB & 2
of Licenses CFP-81 & CFP-82 & 730326 Memorandum & Order
ALAB-106
COCKA, J. W. Consumers Power Co 80/12/30 24pp 07375 346.

B010250580 Forwards ALAB-106 monthly rept for Dec 1980 Bechtel
nonconformance repts, quality action requests, mgt corrective
action repts, repts of nonconformity, inservice insp
nonconformance repts & util nonconformance repts, encl.
COCKA, J. W. Consumers Power Co 81/01/23 400pp 07309 001.

S Reportable occurrences, LERs & related correspondence

B01090513 Interim deficiency rept re overstressed condition in lot
cooler supports Mod being evaluated Interim or final rept
will be submitted on or before 810130
COCKA, J. W. Consumers Power Co 80/12/30 2pp 07442 285

B01090594 Interim deficiency rept, originally reported on B00327, re
overstressed condition in lotdown cooler supports Mod extent
will be determined after analysis of actual nozzle loads &
existing supports is completed by AE.
COCKA, J. W. Consumers Power Co 80/12/30 2pp 07442 012.

B01090185 EN-80-058 on or about B0102, notice of violation & notice
of proposed imposition of civil penalties will be issued to
util Action based on 16 infractions re major deficiencies in
QA program for heating contractor
BROCKETT, T. J., THOMPSON, D. Office of Inspection & Enforcement, Office
of the Director 81/01/02 1p 07442 274.

B01100653 Interim Deficiency Rept 1 re status of low alloy quencher
& tempered bolting 1.5 inches & greater in support of
safety-related sys Interim or final rept to be provided by
B01031, Description of investigation encl.
COCKA, J. W. Consumers Power Co 81/01/09 16pp 07308 001

B010230581 Interim deficiency rept re defective sway strut rod end
initially reported on B01031 Solutions are being
investigated & will be coordinated w/all vendors to obtain
generic solution. Next rept will be forwarded by B01027
COCKA, J. W. Consumers Power Co RUTHERS, J. A. Bechtel Power Corp.
(subs. of Bechtel Corp) 81/01/15 5pp 07511 220

Hearing transcripts on non-antitrust matters

090003 Proposed transcript corrections to DB Head 801229
position Certificate of Svc encl
LTON, W D. Hearing Branch 4 80/12/29 6pp 03889 269

300745 Transcript of A9LB 810108 hearing in Flemington, NJ Pp 1-120
Atomic Safety and Licensing Board Panel. 81/01/08. 121pp
582 001

ET 50-001 DUANE ARNOLD ENERGY CENTER

security, medical, emergency & fire protection plans

090397 Ltr to all licensees of operating reactor plants, CP holders
CP applicants Revised radiological emergency response
ans must be submitted by licensees within 60 days of
0102 & by applicants as part of FSAR
SENHUT, D O Division of Licensing 80/11/13 2pp

140577 Advises that util will receive refund of Class III amend Fee
000425 revision to security plan
LLER, W O License Fee Management Branch 80/12/08 1p
460 291

200458 Releases public version of util emergency plan
LTON, J H Division of Rules and Records 81/01/14. 1p.
484 021

01200466 Forwards public version of emergency plan Includes State of
IA emergency plan & Linn & Benton Counties, IA radiation
emergency response plans
RODT, L D Iowa Electric Light & Power Co 80/12/31. 1p
07484:023

01200475 Public version of emergency plan Includes State of IA
emergency plan & Linn & Benton Counties, IA radiation
emergency response plans
Iowa Electric Light & Power Co 80/07/31 600pp. 07484 024

Judicatory correspondence

000417 Forwards NRC 810113 order granting extension to exemption
on General Design Criteria 50 & requiring licensee to
reassess containment design for suppression pool
hydrodynamic loading
JOLITO, T A Operating Reactors Branch 2 81/01/13 3pp
586:255

01300430 Order granting extension to exemption from General Design
Criteria 50 & requiring licensee to reassess containment
design for suppression pool hydrodynamic loading
EISENHUT, D O Division of Licensing 81/01/13 7pp 07586 258

Insurance & indemnity information

070586 Forwards copy of 801111 util ltr & Natl Rural Util
operative Finance Corp 801031 ltr in response to NRC
1219 ltr requesting guarantee of ability to pay
prospective premiums
LLIAMS, E H Central Iowa Power Cooperative 80/12/29 1p
410 341.

operating license stage documents & correspondence

100254 Ltr to all licensees (except SEP licensees) forwarding
vision 1 of inservice surveillance requirements for
subbers under B7S License amend application adding model
ch Specs to App A should be submitted within 120 days
SENHUT, D O. Division of Licensing 80/11/20 1p

01100271 Revised Pages 3/4 7-22 through 28.B 3/4 7-5 & 7-6 & 6-17 to
B7S snubber inservice insp requirements.
Division of Licensing. 80/11/20. 10pp

050399 Intends to respond to NUREG-0737 requirement II K 3 30.
vised small break LOCA methods to show compliance
CFR50 App K, through GE. Requests schedule & scope of
ations be directed to GE.
DT, L D Iowa Electric Light & Power Co 80/11/29. 1p.
174:023

220466 Ltr to all power reactor licensees & applicants forwarding
summary of 801112 meeting re implementation of guidance for
resolved Safety Issue A-12. "Potential for Low Fracture
ughness & Lamination Tearing on Component Supports."
SENHUT, D O Division of Licensing. 80/11/26 8pp.

8101190113 Ltr to all BWR licensees forwarding 801201 generic safety
evaluation re BWR screen discharge sys. Recommends short-term
actions necessary to assure safe operation of GE BWRs
pending permanent design changes.
EISENHUT, D O Division of Licensing 80/12/09 2pp

--8101190141 Generic safety evaluation re short-term actions required to
assure continued safe operation of operating BWRs Continued
operation of plants is acceptable pending permanent design
mods Criteria for implementing design mods encl
Division of Licensing 80/12/01 212pp. 07183 001

8101210445 Forwards responses to questions on Rule 50 71e. "Periodic
Updating of FSARs" & FR notice of final rule. SEP plants need
not comply w/rule until program is complete Non-SEP plants
must comply within specified time frame
EISENHUT, D O Division of Licensing 80/12/15 13pp

8101050273 Forwards responses to NRC positions re implementation info
required by NUREG-0737. Support info encl.
RODT, L D Iowa Electric Light & Power Co 80/12/31 70pp
07377 159

8101300417 Forwards NRC 810113 order granting extension to exemption
from General Design Criteria 50 & requiring licensee to
reassess containment design for suppression pool
hydrodynamic loading
JPPCLIT, T A. Operating Reactors Branch 2 81/01/13 3p;
07586 255

--8101300430 Order granting extension to exemption from General Design
Criteria 50 & requiring licensee to reassess containment
design for suppression pool hydrodynamic loading
EISENHUT, D O Division of Licensing 81/01/13 7pp 07586 258

8101200300 Forwards re-evaluation of BWR screen sys. in response to NRC
801001 ltr.
RODT, L D Iowa Electric Light & Power Co 81/01/14 4pp
07486:237

8101300849 "Safety Evaluation Rept. Inservice Testing Program Duane
Arnold Energy Ctr."
ROCKWELD, H C. FEHRINGER, J M. EG&G Idaho, Inc FIN A-6258
8101300849 81/01/31 42pp. 07585 002

Q Inspection reports, IE Bulletins & correspondence

8101050270 Forwards IE Info Notice 80-38. "Cracking in Charging Pump
Casing Cladding " No response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/30
2pp 07597 195

8101060552 Forwards IE Circular 80-23. "Potential Defects in Retrofit
Power Sys Emergency Generators " No written response
required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/31
1p 07398 012

8101060658 Forwards IE Info Notice 80-39. "Malfunction of Solenoid
Valves Mfg by Valcor Engineering Corp " No written response
is required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/31
1p 07401 217

8101050545 Forwards IE Info Notice 80-43. "Failures of Continuous Water
Level Monitor for Screen Discharge Vat at Dredgen Unit 2 " No
response required.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/05.
2pp. 07390, 312.

8101290444 Forwards IE Insp Rept 50-331/80-22 on 801101-30 No
noncompliance noted
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support
Branch. 80/12/15 2pp 07570:334.

--8101290449 IE Insp Rept 50-331/80-22 on 801101-30 No noncompliance
noted Major areas inspected plant operations, maint.
procedures & documentation
CHRISTENSEN, W. CLARKE, L S. LITTLE, W S Region 3, Chicago.
Office of the Director. 80/12/12 4pp 07570 336

8101080046 Forwards IE Info Notice 80-45. "Potential Failure of BWR
Backup Manual Screen Capability " No written response
required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/17.
2pp 07419 358

B101130631 Responds to IE Bulletin 80-23 re solenoid valves mfg by Valcor Engineering Corp. No valves mfg by vendor used.
RQDT, L. D. Iowa Electric Light & Power Co. 80/12/18 1p
07453 282

B101150211 Forwards Suppl 4 to IE Bulletin 80-17. "Failure of Control Rods to Insert During Scram at BWR." No written response required.
KEPPLER, J. Q. Region 3, Chicago, Office of the Director 80/12/18
2pp 07462 196

B101050199 Forwards IE Bulletin 80-25. Operating Problems w/Target Rock Safety Relief Valves at GWRs. No response required.
KEPPLER, J. Q. Region 3, Chicago, Office of the Director 80/12/19.
2pp 07377 343

B101220386 Submits response to IE Bulletin 80-24. "Prevention of Damage Due to Water Leakage Inside Containment." Significant closed CVS leakages have not occurred inside drywell.
RQDT, L. D. Iowa Electric Light & Power Co. 81/01/05 8pp
07500 266

R Periodic operating reports & related correspondence

B101200280 Forwards monthly operating rept for Dec 1980
MINECK, D. L. Iowa Electric Light & Power Co. 81/01/14 1p
07477 159.

--B101200284 Monthly operating rept for Dec 1980
VAN BICKEL, J. Iowa Electric Light & Power Co. 81/01/14 7pp
07477 160

S Reportable occurrences, LERs & related correspondence

B101060621 Forwards LER 80-062/01T-0
MINECK, D. L. Iowa Electric Light & Power Co. 80/12/31 1p
07391 136

--B101060627 LER 80-062/01T-0 on 801217, during testing of suppression chamber level transmitters, personnel lowered level below Tech Specs min. Caused by personnel callor error. Responsible individual re-instructed.
RAGER, M. S. Iowa Electric Light & Power Co. 80/12/31 2pp
07391 137

B101120326 Forwards LER 80-063/03L-0
MINECK, D. L. Iowa Electric Light & Power Co. 81/01/06 1p
07447 144

--B101120329 LER 80-063/03L-0 on 801212, solenoid valve in B containment oxygen analyzer failed causing loss of torus sampling.
Caused by faulty solenoid valve coil. Coil replaced & tested successfully.
VAN BICKEL, J. D. Iowa Electric Light & Power Co. 81/01/06 1p.
07447 148.

B101120334 Forwards LER 80-061/03L-0
MINECK, D. L. Iowa Electric Light & Power Co. 81/01/06 1p.
07447: 149

--B101120336 LER 80-061/03L-0 on 801207, drywell pressure & torus water level record PR/LR-4284 began giving erratic & unreliable data. Caused by poor ventilation in recorder cabinet resulting in excessive temp & varied power supply output.
RAGER, M. S. Iowa Electric Light & Power Co. 81/01/06 1p.
07447 150

B101220335 Forwards LER 80-066/03L-0.
MINECK, D. L. Iowa Electric Light & Power Co. 81/01/14. 1p
07500. 123

--B101220343 LER 80-066/03L-0 on 801215, surveillance testing required by Tech Spec 3.5.9.1 when one standby diesel generator is inoperable found not properly completed. Caused by operator error. Operations personnel re-instructed by meeting & memo.
RAGER, M. S. Iowa Electric Light & Power Co. 81/01/14 1p.
07500 124.

B101220381 Forwards LER 80-065/03L-0
MINECK, D. L. Iowa Electric Light & Power Co. 81/01/14 1p.
07505 170

--B101220385 LER 80-065/03L-0 on 801216, suppression chamber purge inlet valve CV-1308 would not cycle. Caused by stuck Miller Fluid Power valve operator piston. Operator cleaned, lubricated & reassembled.
RAGER, M. S. Iowa Electric Light & Power Co. 81/01/14. 1p.
07505: 171

B101220397 Forwards LER 80-064/03L-0
MINECK, D. L. Iowa Electric Light & Power Co. 81/01/14. 1p
07494 091.

--B101220401 LER 80-064/03L-0 on 801125, during surveillance testing standby diesel generator 10-21 failed to start using emergency air start sys. Caused by air start solenoid valve not opening properly. Valve filter cleaned & tested.
RAGER, M. S. Iowa Electric Light & Power Co. 81/01/14 1p
07494 092

B101280550 Forwards LER 80-067/03L-0
MINECK, D. L. Iowa Electric Light & Power Co. 81/01/21 1p
07557: 202

--B101280556 LER 80-067/03L-0 on 801226, reactor water cleanup sys condenser control valve CV-2729 found leaking. Caused by hole in body due to high velocity water flow through valve. Valve body was weld repaired & hydrostatically tested.
RAGER, M. S. Iowa Electric Light & Power Co. 81/01/21. 1p
07557: 203

DOCKET 50-332 BARNWELL REPROCESSING PLANT

Q Adjudicatory correspondence

B101090779 Forwards memos re preliminary estimates of resource needs should "GESMO-type" proceeding be reinstituted. Info derived from discussion during 801201 meeting.
DAVIS, J. Q. Office of Nuclear Material Safety & Safeguards, Director 80/12/03 1p.

--B101090796 Submits estimated resource requirements for completion proceeding Differences in estimates for original GESMO project & estimates to complete proceeding noted.
GUTHNICHAM, R. E. Division of Fuel Cycle & Material Safety 80/09/13 3pp.

--B101160606 Advises that GESMO 1976 study & rept should be revised pending congressional mandate to reopen hearings.
DAVIS, J. Q. Office of Nuclear Material Safety & Safeguards, Director 80/08/08 3pp.

Q. Inspection reports, IE Bulletins & correspondence

B101090790 Forwards IE Insp Rept 50-332/80-03 on 801015-17. No noncompliance noted.
KENNA, W. B. Region 2, Atlanta, Safeguards Branch. 80/11/18 1p
07430 255

--B101090802 IE Insp Rept 50-332/80-03 on 801015-17. No noncompliance noted. Major areas inspected, internal reviews & audits, safety committees, IE bulletins & independent effort.
CORVELL, D. P. Region 1, Philadelphia, Office of the Director
KHALE, B. Region 2, Atlanta, Safeguards Branch. 80/11/18.
07430 256.

B101080189 Ack receipt of IE Insp Rept 50-332/80-03 on 801015-17. No proprietary info.
HOLDEN, R. B. Allied General Nuclear Services. 80/12/10. 1p.
07421: 359

DOCKET 50-333 JAMES A. FITZPATRICK NUCLEAR POWER PLANT

F. Security, medical, emergency & fire protection plans

B002050463 Forwards rept. "Evacuation Time Estimates for Areas Near Sites." in response to NRC 791129 request. Upgraded emergency plan will be provided by B00215.
SCHMEIDER, J. R. Power Authority of the State of New York. 80/01/1p. 01875 111.

--B002050467 "Evacuation Time Estimates for Areas Near Sites." w/ Persons, Brinkerhoff, Guada & Douglas, Inc. 80/01/31. 37pp
01875 112

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR.
EISENHUT, D. O. Division of Licensing. 80/11/13 2pp.

B101100081 Immediate Action Ltr 80-48, confirming agreements reached 801121 meeting w/ utility. Lists actions util will take in areas of radiation protection & emergency planning.
GRIER, D. H. Region 1, Philadelphia, Office of the Director. 80/11/21. 2pp 07445: 001.

O. Adjudicatory correspondence

8101300753 Forwards NRC 810113 order modifying license & granting extension of exemption from General Design Criterion 50 Reassessment of containment design for suppression pool hydrodynamic loading conditions is required
IPFGL170.T A Operating Reactors Branch 2 81/01/13 3pp
07587-035

--8101300757 Order modifying license & granting extension of exemption from General Design Criterion 50 Reassessment of containment design for suppression pool hydrodynamic loading conditions is required Mods must be installed by 81031
EISENHUT.D.O. Division of Licensing 81/01/13 7pp 07587 038

P. Operating license stage documents & correspondence

8101100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under STB License amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT.D.O. Division of Licensing 80/11/20 1p

--8101100271 Revised Pages 3/4 7-22 through 28.B 3/4 7-5 & 7-6 & 6-17 to STB snubber inservice insp requirements.
* Division of Licensing 80/11/20 10pp

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT.D.O. Division of Licensing 80/11/26 8pp.

8101190113 Ltr to all BWR licensees forwarding 801201 generic safety evaluation re BWR scram discharge sys Recommends short-term actions necessary to assure safe operation of GE BWRs pending permanent design changes.
EISENHUT.D.O. Division of Licensing 80/12/09 2pp

--8101190141 Generic safety evaluation re short-term actions required to assure continued safe operation of operating BWRs. Continued operation of plants is acceptable pending permanent design mods. Criteria for implementing design mods encl
* Division of Licensing 80/12/01 212pp. 07183.001

8101210445 Forwards responses to questions on Rule 80.71e. "Periodic Updating of FSARs" & FR notice of final rule. SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame
EISENHUT.D.O. Division of Licensing 80/12/15 13pp.

8101090604 Forwards application for amend to OL & statement of proposed changes to Tech Specs.
BAYNE.J.P. Power Authority of the State of New York 81/01/06 3pp. 07442.111.

--8101090611 Application for amend to License DPR-54, incorporating changes to Tech Specs Safety evaluation supporting proposed Tech Specs encl
BAYNE.J.P. Power Authority of the State of New York 81/01/06 1p. 07442.114

--8101090618 Proposed changes to Tech Specs 2 1.3 2.3 3.3 4.3 6.4 6.3.5 & 4.5 re updating & correcting miscellaneous technical matters.
* Power Authority of the State of New York 81/01/06 9pp
07442.115

--8101090694 Safety evaluation supporting proposed changes to Tech Specs, involving correction & updating of miscellaneous technical matters.
* Power Authority of the State of New York 81/01/06 2pp.
07442.124.

8101120200 Forwards application for amend to License DPR-59, revising App A Tech Specs to correct typographical errors & make editorial improvements & administrative changes. Class II amend fee encl.
BAYNE.J.P. Power Authority of the State of New York 81/01/06 2pp. 07309.001.

--8101120205 Application for amend to License DPR-59, revising App A Tech Specs & to typographical errors & make editorial improvements & administrative changes
BAYNE.J.P. Power Authority of the State of New York 81/01/06 1p. 07309.001

--8101120209 Proposed changes to App A Tech Specs Sections 3 correction of typographical errors & editorial improvements Safety evaluation encl
* Power Authority of the State of New York 81/01/06 07309.001

8101120215 Forwards application for amend to License DPR-59, App A Tech Specs & re scram discharge vol Class II amend fee encl
BAYNE.J.P. Power Authority of the State of New York 81/01/06 2pp 07446.292

--8101120220 Application for amend to License DPR-59, revising Specs re scram discharge vol
BAYNE.J.P. Power Authority of the State of New York 81/01/06 1p 07446.294

--8101120226 Proposed changes to App A Tech Specs Sections 3 discharge vol Provides surveillance requirements for vent drain valves & for reactor protection sys & control rod block SDIV limit switches. Safety evaluation encl
* Power Authority of the State of New York 81/01/06 07446.295

8101130308 Updates Mark I containment program mod schedule M to be completed during Fall 1981 refueling outage due to outstanding load info & attached piping analysis
Installation scheduled for 820601
WILVERDING.O.M. Power Authority of the State of New York 81/01/06 2pp. 07447.276

8101160441 Forwards info re post-TMI requirements listed in 8101160441
BAYNE.J.P. Power Authority of the State of New York 81/01/06 43pp 07308.001

8101160459 Forwards responses to 800718 ltr re NURE0-0737 1b Mods will be delayed until Oct 1981 refueling outage Add'l info to be submitted
BAYNE.J.P. Power Authority of the State of New York 81/01/06 3pp. 07470.001

8101300753 Forwards NRC 810113 order modifying license & granting extension of exemption from General Design Criterion 50 Reassessment of containment design for suppression pool hydrodynamic loading conditions is required
IPFGL170.T A Operating Reactors Branch 2 81/01/13 3p
07587-035

--8101300757 Order modifying license & granting extension of exemption from General Design Criterion 50 Reassessment of containment design for suppression pool hydrodynamic loading conditions is required Mods must be installed by 81031
EISENHUT.D.O. Division of Licensing 81/01/13 7pp

8101260504 Responds to NRC 800924 ltr re plans to upgrade re protection sys power supply Design providing for redundant Class IE protection is being developed. Info re design, proposed Tech Specs & Reload 3 will be submitted in 90 day
BAYNE.J.P. Power Authority of the State of New York 81/01/06 07532.062

8101260117 Forwards info clarifying util 800102 response to Item 2 1.4, in response to concerns of resident inspector re primary containment isolation sys. Nonessential sys automatically isolated upon containment isolation signal.
BAYNE.J.P. Power Authority of the State of New York 81/01/06 19pp 07557-063.

Q. Inspection reports, IE Bulletins & correspondence

8101090878 Forwards IE Insp Rept 50-333/80-18 on 800922-26 N noncompliance noted
HARTIN.W.D. Region 1, Philadelphia, Safeguards Branch. 81/01/06 2pp. 03893.248

--8101090883 IE Insp Rept 50-333/80-18 on 800922-26 No noncompliance noted Major areas inspected: physical security program re contingency security force Details withheld (ref:OCFR2 7)
BAILEY.R.J., SMITH.M. Region 1, Philadelphia, Office of Director, DEVLIN.J.W. Region 1, Philadelphia, Safeguards Branch 80/10/29 1p 03893.250.

8101300068 Ack receipt of 801028 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-333/80-17.
CARLETON.R.T. Region 1, Philadelphia, Reactor Construction Engineering Support Branch. 80/11/17 1p 07383.033

--B101300074 Responds to NRC B01001 Ltr re violations noted in IE Insp Rept 50-333/80-17. Corrective actions, fire doors closed, density tests of sealing matl performed & stop work order issued on electrical penetration sealing work
PASTERNAK, R J. Power Authority of the State of New York
80/10/23 4pp 07583 036

--B101300080 Forwards IE Insp Rept 50-333/80-17 on B00908-11 & notice of violation
CARLSON, R T. Region 1, Philadelphia. Reactor Construction & Engineering Support Branch 80/10/01 2pp 07583 040.

--B101300087 Notice of violation from insp on B00908-11
* Region 1, Philadelphia. Office of the Director. 80/10/01 2pp 07583 042

--B101300107 IE Insp Rept 50-333/80-17 on B00908-11 Noncompliance noted fire doors open & unattended, failure to inspect penetrations requiring permanent tamping & failure to issue work tracking forms on electrical penetration sealing work
KOTAY, P S. Region 1, Philadelphia. Office of the Director
FBNETER, S D. Region 1, Philadelphia. Reactor Construction & Engineering Support Branch 80/10/01. 7pp 07583 044

B101080129 Forwards omitted pages from util B01101 response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment"
PASTERNAK, R J. Power Authority of the State of New York 80/11/21 8pp 07416 352

B101100081 Immediate Action Ltr 80-48, confirming agreements reached at B01121 meeting w/ util lists actions util will take in areas of radiation protection & emergency planning.
GRIER, B H. Region 1, Philadelphia. Office of the Director 80/11/21. 2pp 07445 001

B101070419 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required
GRIER, B H. Region 1, Philadelphia. Office of the Director. 80/11/25 1p 07414 344

B101050142 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Scram Discharge Val at Dresden Unit 2." No response required
GRIER, B H. Region 1, Philadelphia. Office of the Director 80/12/05 1p 07377 233

B101140766 Responds to JE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry, Co. Inc." Review of records will be completed by B10105 No valves w/ specified parts identified to date
PASTERNAK, R J. Power Authority of the State of New York. 80/12/10 1p. 07457 105

B101060116 Forwards IE Info Notice 80-45, "Potential Failure of DWR Backup Manual Scram Capability." No response required.
GRIER, B H. Region 1, Philadelphia. Office of the Director. 80/12/17 1p 07397 323

B101140975 Responds to IE Bulletin 80-23, "Failures of Solenoid Valves Afg by Valcor Engineering Corp." No valves w/ specified parts in use at facility
PASTERNAK, R J. Power Authority of the State of New York 80/12/17. 1p 07457 106

B101070062 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR." No written response required
GRIER, B H. Region 1, Philadelphia. Office of the Director. 80/12/18. 1p. 07414 152.

B101150090 Forwards IE Bulletin 80-25, "Operating Problems w/ Target Rock Safety-Relief Valves at BWRs." Written response required
GRIER, B H. Region 1, Philadelphia. Office of the Director. 80/12/19 1p 07449 144.

R. Periodic operating reports & related correspondence

B101130552 Forwards monthly operating rept for Dec 1980.
PASTERNAK, R J. Power Authority of the State of New York 81/01/07. 1p 07454 158

--B101130558 Monthly operating rept for Dec 1980.
ZUFELT, E. Power Authority of the State of New York. 81/01/07 4pp 07454 159

9. Reportable occurrences, LERs & related correspondence

B101120302 Forwards LER B0-093/03L-0
PASTERNAK, R J. Power Authority of the State of New York 81/01/09 1p 07447 130

--B101120354 LER B0-093/03L-0 on B01212, reactor water level switch 02-3-DP18-101D exhibited erratic setpoint Caused by stripped setpoint lock screw Lock screw replaced & switch recalibr
CHILDS, H V. Power Authority of the State of New York 81/01/07 1p. 07447 131

B101120396 Forwards LER B0-092/03L-0
PASTERNAK, R J. Power Authority of the State of New York 81/01/09. 1p 07447 120

--B101120310 LER B0-092/03L-0 on B01210, heat detector associated w/ fire protection sys for reactor core isolation failed when required to be operable by Tech Spec Caused by internal short Detector replaced
CHILDS, H V. Power Authority of the State of New York. 81/01/09 1p 07447 121

B101160508 Forwards LER B0-066/03X-2
PASTERNAK, R J. Power Authority of the State of New York 81/01/12 1p 07471 271.

--B101160564 LER B0-066/03X-2 on B00805, core spray sys pipe break detection switches 14-DP15-42A & 43B found set above Tech Spec level Caused by instrument drift. Instrument calibr & returned to svc.
CHILDS, H V. Power Authority of the State of New York 81/01/12 1p. 07471 272

B101210492 Forwards LER B0-094/03L-0.
PASTERNAK, R J. Power Authority of the State of New York. 81/01/15 1p 07490 173

--B101210496 LER B0-094/03L-0 on B01216, water level switch 02-3-L18-56 found set outside Tech Specs Caused by instrument drift
CHILDS, H V. Power Authority of the State of New York 81/01/15 1p 07490 174

B101210499 Forwards LER B0-095/03L-0
PASTERNAK, R J. Power Authority of the State of New York. 81/01/15 1p 07490 175

--B101210506 LER B0-095/03L-0 on B01217, reactor core isolation cooling sys high steam flow switch 13-DP18-B4 found set outside Tech Specs Caused by instrument drift Switch recalibr
* Power Authority of the State of New York 81/01/15 1p. 07490 176

B101280136 Re B1-001 on B10117, foreign matl was found in SAV solenoid (pilot) Valve 102-S0V-710) Caused by excess adhesive & O-ring lubricant used by vendor during assembly Insp of remaining nine solenoid valve pairs is in progress.
PASTERNAK, R. Power Authority of the State of New York. 81/01/21 1p. 07187 001.

DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D O. Division of Licensing. 80/11/13 2pp.

B101140836 Advises of provisions of 10CFR50, App R, that are applicable to fire protection features of facility, FR notice & summary of staff requirements to resolve open items encl. W/o encl
EISENHUT, D O. Division of Licensing. 80/11/24 3pp. 07461 032

B101190361 Notifies that util 781211 commitment to install addl hoses hose stations is acceptable for meeting concerns re item 3 C-7 of safety evaluation for Amend 18 to OL
VARQA, S A. Operating Reactors Branch 1. 80/12/23. 2pp. 07476 074

B101100719 Requests that encl facility emergency planning info be made publicly available W/o encl
SOUDEK, J L. Division of Rules and Records. 80/12/31. 1p 07445 125

--801100622 Revised order amending License DPR-66 info requested by IE Bulletin 79-018 must be submitted to IE by 801101
EISENHUT.D O Division of Licensing 80/09/19 6pp 07443 139

P Operating license stage documents & correspondence

801100617 Forwards revised order for mod of license, correcting refs in EC0829 order Hearing date also revised.
EISENHUT.D O Division of Licensing 80/09/19 3pp 07443 136

--801100622 Revised order amending License DPR-66. Info requested by IE Bulletin 79-018 must be submitted to IE by 801101.
EISENHUT.D O Division of Licensing 80/09/19 6pp 07443 139.

801100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under BTS License amend application adding model Tech Specs to App A should be submitted within 120 days.
EISENHUT.D O Division of Licensing 80/11/20 1p

--801100271 Revised Pages 3/4 7-22 through 28.0 3/4 7-5 & 7-6 & 6-17 to BTS snubber inservice insp requirements
* Division of Licensing 80/11/20 10pp

8011220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT.D O Division of Licensing 80/11/26 8pp

801160046 Confirms 801217 mgt meeting to discuss NRC assessment of regulatory performance at facility Agenda encl.
CRIER.B H Region 1, Philadelphia, Office of the Director 80/12/10 2pp 07467 305.

801210445 Forwards responses to questions on Rule 50.71e, "Periodic Updating of FSARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame.
EISENHUT.D O Division of Licensing 80/12/15 13pp

8011050321 Forwards nonproprietary & proprietary versions of "Response to NUREG-0737 " Proprietary version available in Central Files only.
DUNN.C H Duquesne Light Co 80/12/31 2pp 07377 001

--8011090327 Requests that proprietary info submitted as responses to NUREG-0737 re instrumentation for inadequate core cooling be withheld from public disclosure (ref 10CFR2 790) Affidavit encl.
WIEGEMANN.R A Westinghouse Electric Corp 80/12/23 7pp 07377:003.

--8011090330 "Response to NUREG-0537 "
* Duquesne Light Co 80/12/30 200pp 07377 010

801300829 "Adequacy of Station Electric Distribution Sys Voltages. Beaver Valley Power Station, Unit 1," informal rept.
UDV.A.C. EQ&O Idaho, Inc FIN A-6256 801300829 80/12/31 15pp 07584:079.

801300731 Forwards corrections to revised Tech Specs transmitted per Amend 36 to facility OL DPR-66
VARQA.B A Operating Reactors Branch 1 81/01/06 2pp 07583 333

--801300738 Tech Spec 3/4 0 for inservice insp & testing activities surveillance requirements.
* Duquesne Light Co 81/01/06 1p 07583 335

801220571 Submits results of tests performed re util program to reduce leakage from sys outside containment that may contain highly radioactive fluids during transient or accident, per NUREG-0737, Item III.D.1.1 & NUREG-0378
DUNN.C Duquesne Light Co 81/01/15 2pp 07583 153

Q. Inspection reports, IE Bulletins & correspondence

801500059 Forwards IE Insp Rept 50-334/80-26 on 800818-22 No noncompliance noted.
BRUNNER.E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/11/03 2pp 07583 207.

801080126 Submits supplemental response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " NAMCO 700 limit switches will be used inside containment temporarily, until qualified replacements are obtained
DUNN.C H Duquesne Light Co 80/11/21 5pp 07416 347

801060E80 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange " No written response required
CRIER.B H Region 1, Philadelphia, Office of the Director 80/11/26 1p 07396 345

801100781 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co, Inc " Research effort initiated to contact valve suppliers. Extension requested until 801230 to provide info
DUNN.C H Duquesne Light Co 80/12/07 2pp 07444 039

801150933 Forwards supplemental response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment," identifying procedures to provide addl guidance for coping w/environmentally unqualified electrical equipment
DUNN.C H Duquesne Light Co 80/12/12 14pp 07464 165

801100786 Responds to IE Bulletin 80-23, "Failures of Solenoid Valve Mfg by Valcor Engineering Corp." No Valcor solenoid valves in use at facility
DUNN.C H Duquesne Light Co 80/12/15 1p 07444 041.

801060877 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown " No written response required.
CRIER.B H Region 1, Philadelphia, Office of the Director 80/12/16 1p 07396:354

801230356 Summary of 801202 meeting w/util re deficiencies in licensee response to IE Bulletin 79-01 Agenda encl
R05B.W J Operating Reactors Branch 1 80/12/30 4pp 07512:113.

801070518 Responds to IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (801017 Indian Point 2 Event) " Recirculation spray subsystem capable of keeping containment at subatmospheric pressure following accident.
DUNN.C H Duquesne Light Co 81/01/03 3pp 07442 097

R Periodic operating reports & related correspondence

801070436 Forwards NPDES monthly discharge monitoring rept for Nov 1980
M09E.O H Duquesne Light Co 80/12/30 1p 07404 324

--801070439 Discharge NPDES monthly monitoring rept for Nov 1980
* Duquesne Light Co 80/11/30 12pp 07404 325

801160464 Forwards revised operating data rept sheets for Oct & Nov 1980 & monthly operating rept for Dec 1980.
DUNN.C H Duquesne Light Co 81/01/06 1p 07471:225

--801160467 Revised operating data rept sheet for Oct 1980
TIMMO.D R Duquesne Light Co 81/01/06 1p 07471 226.

--801160468 Revised operating data rept sheet for Nov 1980
TIMMO.D R Duquesne Light Co 81/01/06 1p 07471 227

--801160470 Monthly operating rept for Dec 1980
TIMMO.D R Duquesne Light Co 81/01/06 6pp 07471 228

S Reportable occurrences, LERs & related correspondence

801070524 Forwards LER 80-102/03L-0.
MERLING.J A Duquesne Light Co 80/12/26 2pp 07415 115

--801070531 LER 80-102/03L-0 on 801127, all three chlorine detectors noted not dripping Caused by fluid tank being under slight vacuum & clogged wick. Vent & wick cleaned Engineering requested to evaluate.
LACEY.H S Duquesne Light Co 80/12/26 2pp 07415 117

801150421 Forwards LERs 80-104/03L-0, 80-106/03L-0, 80-107/03L-0, 80-108/03L-0 & 80-107/03L-0
MERLING.J A Duquesne Light Co 81/01/09 2pp 07454 050

--B101130425 LER 80-104/03L-0 on B01204.F-47b feed flow protection channel for 1A steam generator failed surveillance test. Cause by bad clock board allowing loop voltage drift on steam flow input clock pulse adjusted
LACEY.W S Duquesne Light Co 81/01/05 2pp 07454 060

--B101130428 LER 80-104/03L-0 on B01205 inner door of containment air lock failed surveillance leakage test per Tech Spec Cause not stated O-rings greased & valves tightened
LACEY.W S Duquesne Light Co 81/01/05 2pp 07454 062

- B101130432 LER 80-107/03L-0 on B01206 electrolyte for detectors 101A & 101B found not dripping. Cause by clogged wick & glass orifice. Wick & orifice cleaned & top vent filter loosened
LACEY.W S Duquesne Light Co 81/01/05 2pp 07454 064

--B101130438 LER 80-108/03L-0 during maint surveillance procedure for calibr of hydrogen analyzer H2-HV-1003. failed function circuit card found. Cause by electronic circuit card failure. Function card replaced
LACEY.W S Duquesne Light Co 81/01/05 2pp 07454 066

--B101130443 LER 80-107/03L-0 on B01205 axial flux difference increased above target band. Cause by high initial second fuel cycle 100% target flux value. Target flux value lowered
LACEY.W S Duquesne Light Co 81/01/05 2pp 07454 068

B101130508 Forwards LER 80-105/03L-0
MERLING.J A Duquesne Light Co 81/01/05 2pp 07454 124

--B101130515 LER 80-105/03L-0 on B01205 thermocouple readings indicated temps below Tech Spec level around boron injection tank outlet isolation valves. Cause by thermocouples not in full contact w/pipes. Heat tracing sys study is being conducted
LACEY.W S Duquesne Light Co 81/01/05 2pp 07454 126

B101130531 LER 81-001/01P-0 on B10106 IE Bulletin 79-14 evaluation & reanalysis of piping & supports revealed H-162, H-164 & H-166 to be less conservative than original design. Cause by QA breakdown
MERLING.J A Duquesne Light Co 81/01/07 3pp 07309 001

B101190467 Forwards LER 80-111/03L-0
MERLING.J A Duquesne Light Co 81/01/09 2pp 07474 060

--B101190470 LER 80-111/03L-0 on B01211 steam generator feed pump suction pressure low alarm was received. Cause by control rod insertion. Rods partially borated back out of core. restoring delta flux to within target band
LACEY.W S Duquesne Light Co 81/01/09 2pp 07474 062

B101190474 Forwards LER 80-112/03L-0
MERLING.J A Duquesne Light Co 81/01/12 2pp 07474 064

--B101190477 LER 80-112/03L-0 on B01213 sample pump for containment atmospheric gaseous & particulate radiation monitors failed. Cause not stated. Sample pump motor & drive pulley replaced
LACEY.W S Duquesne Light Co 81/01/12 2pp 07474 066

B101220382 Forwards LER 80-113/03L-0, 80-114/03L-0 & 80-118/03L-0
MERLING.J A Duquesne Light Co 81/01/14 2pp 07500 243

--B101220384 LER 80-113/03L-0 on B01214 during surveillance testing, several penetration fire barriers found lacking seals. Cause not stated. Fire watch posted & openings sealed
LACEY.W S Duquesne Light Co 81/01/15 2pp 07500 245

--B101220387 LER 80-114/03L-0 on B01215 during shift channel check of refueling water storage tank, channel C level indicator found reading high. Cause by transmitter zero drift. Transmitter recalibr & returned to svc
LACEY.W S Duquesne Light Co 81/01/14 2pp 07500 247

--B101220392 LER 80-118/03L-0 on B01217 during chlorine detection sys surveillance test, 101A, B & C detectors electrolyte found not dripping. Cause by vacuum in fluid tanks & clogged glass orifices. Wicks replaced & orifices cleaned
LACEY.W S Duquesne Light Co 81/01/14 2pp 07500 249

B101230465 Forwards LER 80-116/03L-0 & 80-117/03L-0
MERLING.J A Duquesne Light Co 81/01/15 2pp 07513 025

--B101230471 LER 80-116/03L-0 on B01217 degassifier A recovery heat exchanger BR-E-12A2 steam leak found to be cracked weld. Cause unknown. Exchanger isolated & stained weld ground out & temporary mod to seal weld performed
LACEY.W S Duquesne Light Co 81/01/15 2pp 07513 027

--B101230473 LER 80-117/03L-0 on B01218 during physics testing, delta flux left low side of target band when power decreased rapidly. Cause by rapid insertion of control rods during power decrease. Rods partially borated out of core
LACEY.W S Duquesne Light Co 81/01/15 2pp 07513 029

B101230475 Forwards LER 80-120/03L-0
MERLING.J A Duquesne Light Co 81/01/19 2pp 07513 031

--B101230478 LER 80-120/03L-0 on B01218 during hot standby, containment air lock outer door failed seal leakage surveillance test. Cause untested. Seals inspected, cleaned & greased
LACEY.W S Duquesne Light Co 81/01/19 2pp 07513 033

B101260548 Forwards LER 81-001/01T-0
MERLING.J A Duquesne Light Co 81/01/20 2pp 07531 142

--B101260634 LER 81-001/01T-0 on B10106 supports H-162, H-164 & H-166 reported not modified per IE Bulletin 79-14. Cause by loss of pertinent drawings. Work on supports completed
LACEY.W S Duquesne Light Co 81/01/20 3pp 07531 144

B101270590 Forwards LER 81-002/01T-0
MERLING.J A Duquesne Light Co 81/01/21 2pp 07548 334

--B101270593 LER 81-002/01T-0 on B10107 during shutdown, seal flow dropped below min on IC reactor coolant pump. Cause by sensitive valving. Pump restarted within 20 minutes
LACEY.W S Duquesne Light Co 81/01/21 2pp 07548 336

DOCKET 90-339 ST. LUCIE PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

B101090287 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR.
EISENHUT.D O Division of Licensing 80/11/13 2pp

B101130134 Advice of provisions of 10CFR90, App R, that are applicable to fire protection features of facility. FR notice & summary of staff requirements to resolve open items encl
EISENHUT.D O Division of Licensing 80/11/24 9pp 07308 001

B101080133 Releases public version of util draft emergency plan.
FELTON.J H Division of Rules and Records 80/12/01 1p 07419 113

--B101080137 Forwards public version of draft emergency plan
HARRIO.R E Florida Power & Light Co 80/07/23 1p 07419 114

--B101080142 Public version of draft emergency plan
* Florida Power & Light Co 80/07/19 129pp 07419 115

B101190377 Requests response to encl comments from NRC review of util security plan Encl withheld (ref 10CFR2 7901)
CLARK.R A Operating Reactors Branch 3 80/12/12 2pp 07474 280

B101100484 Forwards request for addl info re util 800723 emergency plan Areas re assignment of responsibility, onsite emergency organization & emergency response support & resources must be clarified per NUREG-0654 criteria.
CLARK.R A Operating Reactors Branch 3 80/12/18 10pp 07445 068

B101050402 Disagrees w/items contained in Encl 2 to NRC 801124 ltr re requirements to resolve open items concerning fire protection. Response to items will be submitted B10130.
HARRIO.R E Florida Power & Light Co 80/12/30 1p 07375 340

B101210085 Releases public version of util revised emergency plan.
FELTON.J H Division of Rules and Records 81/01/08 1p 07490 225

--B101210092 Forwards public version of revised emergency plan. State of FL draft radiological emergency plan encl
HARRIO.R E Florida Power & Light Co 81/01/02 1p 07490 226

--B101210098 Public version of revised emergency plan. State of FL draft radiological emergency plan encl.
* Florida Power & Light Co 81/01/02 200pp 07490 227

CHILSON, V. F. Florida Power & Light Co 8/10/10 10pp 07437 137

8101210445 Forwards monthly operating repts for Dec 1980
SCHMIDT, A. D. Florida Power & Light Co 8/10/10 1p 07493 126

--8101210429 Monthly operating repts for Dec 1980
CHILSON, V. F. Florida Power & Light Co 8/10/10 9pp 07493 127

E. Reportable occurrences, LERs & related correspondence

8101050360 Forwards LER 80-044/03L-0
SCHMIDT, A. D. Florida Power & Light Co 8/11/28 1p 07379 301

--8101050349 LER 80-044/03L-0 on 801030 during normal operation, turbine control sys malfunction caused unexpected load decrease resulting in reactor cold leg temp briefly exceeding Tech Spec limit. No cause determined. Feedback re-established.
PACE, P. L. Florida Power & Light Co 8/11/28 1p 07379 302

8101050444 Forwards LER 80-053/03T-0
SCHMIDT, A. D. Florida Power & Light Co 8/12/05 1p 07390 135

--8101050447 LER 80-053/03T-0 on 801107, drifting pressure indication for C pressurizer pressure channel was noted & channel bypassed. Caused by faulty pressure signal transmitter on pressure sensing instrument. Transmitter replaced & channel recalibrated.
PACE, P. L. Florida Power & Light Co 8/12/05 1p 07390 136

8101130341 Forwards LER 80-057/01T-0
SCHMIDT, A. D. Florida Power & Light Co 8/12/15 1p 07451 350

--8101130355 LER 80-067/01T-0 on 801120, some reactor trip breakers found not to trip on under voltage. Caused by inoperable under voltage device in breaker device armature realigned.
PACE, P. L. Florida Power & Light Co 8/12/15 1p 07451 361

8101130345 Forwards LER 80-065/03L-0
SCHMIDT, A. D. Florida Power & Light Co 8/12/19 1p 07452 064

--8101130372 LER 80-065/03L-0 on 801121, containment fire protection zone 14A went into invalid alarm state. Caused by one detector shorting out due to condensation. Detector removed.
PACE, P. L. Florida Power & Light Co 8/12/19 1p 07452 065

V. Operator Examinations

8101060374 Forwards repts on NUREG-0737 items in response to NRC 801031 ltr. Includes info re shift technical advisor, auxiliary feedwater sys evaluation & auxiliary feedwater sys initiation & flow.
WARRIOR, R. E. Florida Power & Light Co 8/10/02 28pp 07393 215

8101130333 Forwards 800801 revision to facility Administrative Procedure 0005720, licensed operator requalification program. Requirement re instructor qualifications unattainable. Instruction to be supervised by licensed personnel.
WARRIOR, R. E. Florida Power & Light Co 8/10/06 1p 07308 001

--8101130339 "Licensed Operator Requalification Program," Revision 8, Administrative Procedure 0005720
* Florida Power & Light Co 8/08/21 16pp 07308 001

BECKETT 50-036 MILLSTONE NUCLEAR POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR.
EISENHUT, D. O. Division of Licensing 8/11/13 2pp

810120405 Releases public version of emergency plan.
FELTON, J. M. Division of Rules and Records 8/11/19 1p 07437 011

--810120413 Forwards public version of draft Revision 7 to emergency plan.
COUNSELL, W. G. Northeast Nuclear Energy Co (subs. of Northeast Utilities) 8/10/14 3pp 07437 013

8101090304 Discusses utility commitments re emergency plans. Revised emergency plans addressing Revision 1 to NUREG-0654/FEMA-REP-1, App E to 10CFR30, will be submitted by 810216.
COUNSELL, W. G. Connecticut Yankee Atomic Power Co (subs. of Northeast Nuclear Energy Co) 8/12/31 4pp 07442 247

8101100734 Requests that encl facility emergency planning info be made publicly available w/o encl.
SOUVER, J. L. Division of Rules and Records 8/12/31 1p 07445 128

8101270712 Responds to NRC 801124 ltr re fire protection features. Protection equivalent to NRC seismic criteria provided by backfitting of seismic qualification of reactor coolant pump lubrication oil sys.
COUNSELL, W. G. Connecticut Yankee Atomic Power Co (subs. of Northeast Nuclear Energy Co) 8/10/13 4pp 07545 269

8101290163 Forwards facility emergency planning info to be made publicly available w/o encl.
SOUVER, J. L. Division of Rules and Records 8/10/23 1p 07575 199

J. Insurance & indemnity information

8101270736 Forwards Endorsement 4 to NELA Binders EU-15 & EU-16.
IFFLAND, R. R. Northeast Utilities 8/10/22 3pp 07548 035

8101270744 Forwards Endorsements 65 & 66 to NELA Policy NF-173.
IFFLAND, R. R. Northeast Utilities 8/10/22 4pp 07548 046

P. Operating license stage documents & correspondence

8101100294 Ltr to all licensees (except BEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under STB license amend application adding model Tech Specs to App A should be submitted within 120 days.
EISENHUT, D. O. Division of Licensing 8/11/20 1p

--8101100271 Revised Pages 3/4 7-22 through 20, B 3/4 7-5 & 7-6 & 6-17 to STB snubber inservice insp requirements.
* Division of Licensing 8/11/20 10pp

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 80112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D. O. Division of Licensing 8/11/26 8pp

8101210445 Forwards responses to questions on Rule 50.71e, "Periodic Updating of FSARs" & FR notice of final rule. BEP plants need not comply w/rule until program is complete. Non-BEP plants must comply within specified time frame.
EISENHUT, D. O. Division of Licensing 8/12/19 13pp

8101160029 Notification of 801218 meeting w/BEP owners group in Bethesda, MD re BEP program, schedule for licensee topic completion & assignment of lead topics to plants.
RUSSELL, W. T. Technical Support Branch 8/12/16 2pp

8101050468 Forwards facility electric distribution sys voltage info per TM Novak 800625 request.
COUNSELL, W. G. Northeast Utilities 8/12/19 1p 07389 163

--8101050476 "Millstone Nuclear Power Station 2 Electric Distribution Sys Voltages"
* Northeast Utilities 8/12/31 21pp 07389 164

8101060746 Submits daily notes for 801223 Status of facilities in five IE regions encl.
DIRCKS, W. J. Office of the Executive Director for Operations 8/12/24 3pp

8101050076 Provides refts to FSAR to assist NRC in obtaining info to support containment sump evaluation program in response to 801106 request. Also submits info re insulation utilized within containment.
COUNSELL, W. G. Northeast Nuclear Energy Co (subs. of Northeast Utilities) 8/12/29 3pp 07376 290

B01140238 Forwards rept on post-TMI requirements in response to NUREG-0737 & NRC B01031 ltr
COUNCIL, W. O. Connecticut Yankee Atomic Power Co. COUNCIL, W. O.
Northeast Nuclear Energy Co. (subs. of Northeast Utilities)
80/12/31 300pp 07468 014

B01150624 Submits info re justification of measurement uncertainty values for axial shape index, pressure, temp, flow & power, in response to NRC B01006 request
COUNCIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 81/01/08 2pp 07462-116

B01290799 Forwards Amend 63 to license DPR-65, safety evaluation & notice of issuance & availability
MGAVAK, T. M. Assistant Director for Operating Reactors. 81/01/14 4pp 07568 075

--B01290802 Amend 63 to License DPR-65, adding operability, trip setpoint & surveillance requirements for automatic initiation of auxiliary feedwater sys
CLARK, R. A. Operating Reactors Branch 3 81/01/14. 21pp 07568 081.

--B01290804 Safety evaluation supporting Amend 63 to License DPR-65
* Office of Nuclear Reactor Regulation, Director 81/01/14 14pp. 07568 103.

--B01290807 Notice of issuance & availability of Amend 63 to License DPR-65
CLARK, R. A. Operating Reactors Branch 3 81/01/14 2pp 07568 117

B01200293 Requests review of util basic safety rept so that potential for 10CFR50.59 reload for Cycle 5 can be realized at facility Request originally made on B00306. NRC B01006 response did not accept rept as ref document
COUNCIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 81/01/16 2pp 07486 238

0 Inspection reports, IE Bulletins & correspondence

B01050124 Requests existing data, summaries & records of inservice insp tests of containments w/greased prestressing tendons.
ORNL receiving contract to compile & review records of tendons.
EISENHUT, D. O. Division of Licensing. 80/11/25. 3pp.

B01070425 Forwards Suppl 1 to IE Info Notice B0-29, "Broken Studs on Terry Turbine Steam Inlet Flange " No written response required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director 80/11/26 1p 07414 035.

B01140718 Updates B00716 response to IE Bulletins 79-02 & 79-14 re as-built safety-related piping sys & pipe supports using concrete expansion anchor bolts, respectively No sys found to have loss of function as result of as-built deviations.
COUNCIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/12/02 2pp. 07457 107.

B01150028 Responds to IE Bulletin B0-23, "Failures of Solenoid Valves Hfg by Valcor Engineering Corp. " No valves w/specified part numbers in use at facilities
COUNCIL, W. O. Connecticut Yankee Atomic Power Co. COUNCIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/12/03 1p. 07462-205

B01100789 Responds to IE Bulletin B0-23, "Failures of Solenoid Valves Hfg by Valcor Engineering Corp. " No subj valves in use at facilities
COUNCIL, W. O. Connecticut Yankee Atomic Power Co. COUNCIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 80/12/05 1p 07444 042

B01060836 Forwards IE Info Notice B0-44, "Actuation of ECCB in Recirculation Mode While in Hot Shutdown " No written response required
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 80/12/16. 1p. 07397-025

B01150936 Act receipt of B01016 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-245/80-11 & 50-336/80-07. Item E now considered as single item of noncompliance.
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/12/16. 1p. 07464-180.

--B01150540 Responds to NRC B00922 ltr re violations noted in IE Repts 50-245/80-11 & 50-336/80-09 Corrective actions advised personnel that partial sys lineups will be conducted following maint where appropriate
COUNCIL, W. O. , FEE, W. F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 80/10/16 4pp 07464 181

--B01150542 Forwards IE Insp Repts 50-245/80-11 & 50-336/80-09 B00706-0802 & notice of violation
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/22 2pp 07464 185

--B01150544 Notice of violation from insp on B00706-0802
* Region 1, Philadelphia, Office of the Director 80/09/16 07464 187

--B01150546 IE Insp Repts 50-245/80-11 & 50-336/80-09 on B00706-0802 Noncompliance noted requires to require restoration of equipment following maint & failure to require radiation work permit in accordance w/procedures
SHELDON, J. T. , ZIMMERMAN, W. P. Region 1, Philadelphia, Office of the Director KEIMIO, R. R. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/16 10pp 07464

B01290776 Summary of B01212 meeting w/util re facility steam gen insp results. List of attendees & vignographs encl
CONNER, E. L. Operating Reactors Branch 3 81/01/08 42pp 07569 276

R Periodic operating reports & related correspondence

B01230411 Forwards monthly operating rept for Dec 1980
MROCKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 81/01/15. 1p 07512 134

--B01230413 Monthly operating rept for Dec 1980
HONLETT, G. H. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 81/01/12. 5pp 07512 125

B Reportable occurrences, LERs & related correspondence

B01030339 PNO-1-B0-17B on B01222, Chen Nuclear reactor trailer c low level radiaste from util was involved in traffic accident near Bordentown, NJ no visible damage to cask detected Shipment proceeded to Barnwell, SC
CAMPELLO, M. , KINNEHAN, J. Region 1, Philadelphia, Office of the Director 80/12/23 2pp 07379-038

B01120351 Forwards LER B0-040/03L-0
MROCKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 80/12/31 1p 07447 167

--B01120355 LER B0-040/03L-0 on B01226, control element assembly dropped to zero steps from 180 steps Cause not stated Power reduced & CEA realigned
HEBETAR, J. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/12/31 1p 07447 168

B01270707 PNO-1-B1-001 on B0102, power lost to one AC shutdown when turbine generator tripped after inadvertent opening of 125 volt DC breaker Caused by loss of spray flow from one loop when associated reactor coolant pump was secured
MCCANN, J. F. Director's Office, Office of Inspection and Enforcement BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 81/01/02 2pp 07550 112

B01160519 Forwards LER B0-041/03L-0
MROCKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 81/01/08 1p 07471-293

--B01160624 LER B0-041/03L-0 on B01210, HPB1 injection MVV 2-S1 overtravelled 0.25 inch cause unknown Valve stroked five times & traveled to correct position each time
BECKER, J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 81/01/08 1p 07471 294

B01280426 PNO-1-B1-02 on B0107, during startup for restart, event occurred which resulted in introduction of reactor coolant into nitrogen gas supply sys Caused by two open valves in nitrogen supply line to RCS Valves left open during maint
KEIMIO, R. , BRUNNER, E. J. Region 1, Philadelphia, Office of the Director 81/01/09 2pp. 07557 053

B01210592 RO on B01209, inservice insp revealed that required w/operability tests not performed during third calendar quarter 1980. Valves successfully tested Action taken to assure timely review of valve test data
MROCKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 81/01/13 2pp 07489 266

CLCPE1 50-538 NORTH ANNA POWER STATION, UNIT 1

F. Security, residual, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FBAR EISENHUT, D G Division of Licensing 80/11/13 2pp

B101070434 Releases public version of util emergency plan FELTON, J M Division of Rules and Records 80/12/02 1p 07415 346

--B101070440 Forwards public version of Revision 2 to emergency plan. List of changes encl BAUM, E A Virginia Electric & Power Co 80/06/20 2pp 07415 347

--B101070443 Public version of Revision 2 to emergency plan * Virginia Electric & Power Co 80/06/18 28pp 07415 349

B101070452 Releases public version of util emergency plan FELTON, J M Division of Rules and Records 80/12/02 1p 07416 014

--B101070454 Forwards public version of Revision 3 to emergency plan BAUM, E A Virginia Electric & Power Co 80/06/25 1p 07416 015

--B101070457 Public version of Revision 3 to emergency plan * Virginia Electric & Power Co 80/06/25 22pp 07416 016

B101120457 Releases public version of util emergency plan FELTON, J M Division of Rules and Records 80/12/02 1p 07417 204

--B101120490 Forwards public version of Revision 1 to util emergency plan State of VA 800920 confirmation ltr & list of changes encl BAUM, E A Virginia Electric & Power Co 80/06/06 5pp 07417 205

--B101120495 Public version of Revision 1 to util emergency plan * Virginia Electric & Power Co 80/06/09 106pp 07417 210

B101060415 Requests that encl emergency planning info be made publicly available. W/o encl SJOJER, J L Division of Rules and Records 80/12/17 1p 07419 399

B101090146 Requests that encl emergency planning info be made publicly available W/o encl SJOJER, J L Division of Rules and Records 80/12/17 1p 07419 248

B101120280 Requests exclusion from submitting State of MD emergency plan, since zone intrudes only 12 miles into area w/sparse population & Farming Wind welder blows toward area & radiation levels would be minimal BAUM, E A Virginia Electric & Power Co 81/01/08 2pp 07447:113

G Adjudicatory correspondence

B101130384 Requests extension of license mod hearing request from B10108 to B10126 Hearing may still be requested but util must review environ qualification matter before making final decision re necessity of hearing. CHRISTMAN, J H. Hutton & Williams 81/01/07 3pp 07457 020

B101230103 Forwards "Turbine Missile Rept (HP296-LP281-LP281)," per NRC request Rept section of info package to be submitted per B01106 ltr Related correspondence * Hutton & Williams 81/01/14 1p 07511 341

--B101230109 "Turbine Missile Rept (HP296-LP281-LP281)," CT-24821 Revision 0 Related correspondence * Westinghouse Electric Corp. HP296-LP281-LP281 80/08/31 26pp 07511 342

H General correspondence

B101050488 Informs that appointment of JI Datta as senior vice president of power operations, effective B10101, approved on B01219 by VEPCO Board of Directors Discusses util corporate organization Tech Specs being revised for facilities PERCUSO, J M Virginia Electric & Power Co 80/12/31 2pp 07385:268

J. Insurance & indemnity information

B101130357 Forwards Endorsements 2, 3, 4, 4A, 5B & 31 to NELA Policy FB-70, ED-63, EB-28, EG-27, HS-316, NF-186 & NF-240, respectively WARFIELD, K J Marsh & McLennan, Inc. M & M Nuclear Consultants, Div. 81/01/09 16pp 07451 333

P Operating license stage documents & correspondence

B101100254 Ltr to all licensees (except BEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under STS License amend application adding model Tech Specs to App A should be submitted within 120 days EISENHUT, D O Division of Licensing 80/11/20 1p

--B101100271 Revised Pages 3/4 7-22 through 28.B 3/4 7-5 & 7-6 & 6- STS snubber inservice insp requirements * Division of Licensing 80/11/20 10pp

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports." EISENHUT, D O Division of Licensing 80/11/26 8pp

B101070129 Forwards Amend 22 to License NPF-4, safety evaluation & notice of issuance & availability CLARK, R A. Operating Reactors Branch 3 80/12/10 3pp 07419

--B101070134 Amend 22 to License NPF-4, changing axial power distribution surveillance turn-on power & part power axial flux difference limits. CLARK, R A. Operating Reactors Branch 3 80/12/10 17pp 07415 061

--B101070138 Safety evaluation supporting Amend 22 to License NPF-4 * Office of Nuclear Reactor Regulation, Director 80/12/10 07415 071

--B101070143 Notice of issuance & availability of Amend 22 to License NPF-4 CLARK, R A. Operating Reactors Branch 3 80/12/10 2pp 07415:073

B101210445 Forwards responses to questions on Rule 80 71e, "Periodic Updating of FBARs" & FR notice of final rule. BEP plants need not comply w/rule until program is complete. Non-BEP plants must comply within specified time frame EISENHUT, D O Division of Licensing 80/12/15 13pp

B101150892 Updates developments in turbine missile issue at facilities Based on conservatism for calculation of critical crack ratio, continued operation until B01229 is justified. Licensees will meet w/NRC on B01229 to present add'l justification MUHAM, T M Assistant Director for Operating Reactors 80/12/23 3pp 07398:001

B101060349 Forwards rept, "Evaluation of Direct Measurement of Differential Settlement Across Svc Water Lines Expansion Joints," in response to NRC B00912 request. SYLVIA, B R. Virginia Electric & Power Co 80/12/29 20pp 07393 006

B101050352 Forwards response to item 111.D.3.4 of NUREG-0737 Review control room habitability conclude that requirements of Reg Guide 1.7B & 1.95 & SRP Sections 2.2.1-2.2.2 & 2.2.3 have been met. SYLVIA, B R. Virginia Electric & Power Co 80/12/30 12pp 07376 206

B101190408 Forwards Amends 23 & 3 to Licenses NPF-4 & NPF-7, respectively & notice of issuance. CLARK, R A. Operating Reactors Branch 3. YOUNGBLOOD, B J. License Branch 1 80/12/30 3pp 07183:001

--B101190617 Amends 23 & 3 to Licenses NPF-4 & NPF-7, respectively, deleting water quality requirements for Unit 1 & adding environ protection plan for Units 1 & 2 CLARK, R A. Operating Reactors Branch 3 80/12/30 85pp 07183:001

--B101190621 Notice of issuance of Amends 23 & 3 to Licensee NPF-4 & NPF-7, respectively
CLARK, R A Operating Reactors Branch 3 80/12/30 2pp
07183 001

B101060308 Forwards response to specified items of NUREG-0737 re shift technical advisor training program & ECCS outage rept of North Anna 1 & 2
SVLVIA, B R Virginia Electric & Power Co 80/12/31 37pp
07396 099

B101190379 Forwards safety evaluation supporting mechanical operability of purge & vent valves
CLARK, R A Operating Reactors Branch 3 81/01/06 2pp 07474 031

--B101190584 Safety evaluation supporting mechanical operability of purge & vent valves. Containment isolation capability of valves in closed position acceptable
• Office of Nuclear Reactor Regulation, Director 81/01/06 1p
07474 033

B101300024 Informs of transfer of licensing mgt responsibilities. Responsibilities for Unit 2 will fall under Assistant Director for Operating Reactors. Div of Licensing Licensing project manager for both units will be L Engle.
EISENHUT, D O Division of Licensing 81/01/13 2pp. 07308 001.

B101200218 Advises that data from pump tests will be used to determine if 340 gpm would be delivered to steam generator, per B01226 ltr. Results from final calculations will be forwarded.
SVLVIA, B R Virginia Electric & Power Co 81/01/19 1p
07467 027

B101200229 Forwards revised VEP-FRD-36, designated VEP-FRD-36A, "Control Rod Reactivity Worth Determination by Rod Swap Technique," per NRC B01107 ltr
THOMAS, W N Virginia Electric & Power Co 81/01/16 2pp
07478 001

--B101200235 "Control Rod Reactivity Worth Determination by Rod Swap Technique."
ROBB, T K, BECK, W C, BOWLING, M L Virginia Electric & Power Co VEP-FRD-36A 80/12/31. 61pp 07470 003

B101220328 Forwards Revision 0 to CT-24821, "Turbine Missile Rept (HP296-LP281-LP281)"
SVLVIA, B R Virginia Electric & Power Co 81/01/19 1p.
07500 123.

--B101220333 "Turbine Missile Rept (HP296-LP281-LP281)"
• Westinghouse Electric Corp. CT-24821 R0 80/08/31. 26pp
07500 126.

B101290757 Forwards info re containment base mat amplified response spectra per NRC verbal request Evaluation of safety-related components described in B01107 submittal completed for smooth ground response spectra w/o design mode
SVLVIA, B R Virginia Electric & Power Co 81/01/23 7pp
07309 001

B101300193 Expresses Appreciation for B01203 meeting to discuss in-house licensing activities. Physics analysis methodology for reload safety evaluations will be discussed at B10128 meeting
THOMAS, W N Virginia Electric & Power Co 81/01/26 1p
07586 207.

B101300188 Advises of plans for Cycle 3 reload core. Verification of reload core will be performed through startup physics testing program
THOMAS, W N Virginia Electric & Power Co. 81/01/27. 1p.
07586 208.

0. Inspection reports, IE Bulletins & correspondence

B101070294 Forwards supplemental response to violations noted in IE Insp Rept 50-338/79-47 Corrective actions. Welder performance qualifications involving combined processes show separate thicknesses for each process of combined process weld.
SVLVIA, B R Virginia Electric & Power Co. 80/10/14. 2pp
07413 297.

--B101070303 Forwards supplemental response to violations noted in IE Insp Rept 50-338/79-47 Corrective action determined that no multiple process procedures used to complete repairs since startup Welding processes performed per weld manual.
SVLVIA, B R Virginia Electric & Power Co. 80/10/02. 2pp
07413 299

--B101070309 Forwards response to violations noted in IE Insp Rept 50-338/79-47 Corrective action welding procedures involving combination processes will be amended to include weld metal thickness range as deposited by each individual process
SVLVIA, B R Virginia Electric & Power Co 80/09/17 2pp
07413 301

B101150114 Responds to request for addl info re reply to IE Bulletin 79-02, "Pipe Support Baseplate Designs Using Concrete Expansion Anchor Bolts" for facility Sample calculations for typical baseplates & BSW review procedure NA-EM 1 encl
SVLVIA, B R Virginia Electric & Power Co 80/12/17 22pp
07308 001

B101120120 Revises B01201 completion date for corrective actions F IE Bulletin 80-18 re maint of adequate min flow through centrifugal charging pumps Surry mods to be completed by B01203 & North Anna by B01203
SVLVIA, B R Virginia Electric & Power Co 80/12/22 1p
07446 121

B101120519 Provides estimated schedule for completing masonry wall re-evaluation program required by IE Bulletin 80-11. Completion dates for Class I & II walls are B10315 & 0415, respectively
SVLVIA, B R Virginia Electric & Power Co 80/12/26. 2pp
07447 172

B101290396 Forwards response to IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (Oct 17, 1980 Indian Point 2 Event)" No leakage in closed sys at North Anna 1 & 2 Summary of leakage at Surry 1 & 2 encl
SVLVIA, B R Virginia Electric & Power Co 81/01/09 9pp
07575 133.

R Periodic operating reports & related correspondence

B101200278 Forwards monthly operating repts for Dec 1980 & revised 1 monthly operating rept for Nov 1980.
SVLVIA, B R Virginia Electric & Power Co 81/01/15 1p
07477 146

--B101200285 Revised monthly operating rept for Nov 1980
ROGERS, L L Virginia Electric & Power Co. 80/12/26 2pp
07477 147

--B101200287 Monthly operating repts for Dec 1980
ROGERS, L L Virginia Electric & Power Co 81/01/05. 10pp
07477 149.

S Reportable occurrences, LERs & related correspondence

B101060567 Forwards LER 80-104/99T-0
CARTWRIGHT, W R Virginia Electric & Power Co 81/01/02 1p.
07391 120

--B101060599 LER 80-104/99T-0 on B01223, environ telemetry channel air temp found out of tolerance high during calibr. Caused by printed circuit card failure in transmitter multiplexer. Card removed & sent to manufacturer for repairs.
CARTWRIGHT, W R Virginia Electric & Power Co 81/01/02 2pp
07391 121

B101130454 Forwards LER 80-105/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co. 81/01/06 1p
07454 100

--B101130342 LER 80-105/03L-0 on B01218, level in IC safety injection accumulator dropped below Tech Spec 3.5.1 min level. Caused by operator error during filling operation. Level restored.
CARTWRIGHT, W R Virginia Electric & Power Co. 81/01/06 2pp
07454 101

B101120341 Forwards LER 80-102/03L-0.
CARTWRIGHT, W R Virginia Electric & Power Co 81/01/07 1p.
07447 160.

--B101120365 LER 80-102/3L-0 on B01211, auto stop oil pressure switch calibr procedure would allow lower min valve than Tech Spec. Caused by incorrect procedure. Calibr procedure changed.
CARTWRIGHT, W R Virginia Electric & Power Co 81/01/07. 2pp
07447 161

B101200362 Forwards LER 80-106/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co. 81/01/14 1p.
07477 347

--B101200344 LER 80-105/03L-0 on B01221 fire door S94-6 found to be nonfunctional. Caused by hole in door & misaligned hardware. Cover plate installed over hole & hardware adjusted. CARTWRIGHT, W R Virginia Electric & Power Co. B1/01/14 2pp 07477 348

B101200431 Forwards LER 80-107/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co. B1/01/14 1p 07476 331

--B101200437 LER 80-107/03L-0 on B01226 while operating at 59% power, steam generator ID steam pressure channel #1 observed indicating high, resulting in channel being locked in. Caused by sensing line for pressure transmitter 14B1 freezing. CARTWRIGHT, W R Virginia Electric & Power Co. B1/01/14 2pp 07476 332

B101201439 Forwards LER 80-109/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co. B1/01/15 1p 07493 150

--B101201446 LER 80-109/03L-0 on B01230, steam generator water level low-low reactor trip setpoint found at 15% narrow range instrument span on all generators rather than 18% level. Caused by oversight by administrative personnel. CARTWRIGHT, W R Virginia Electric & Power Co. B1/01/15 2pp 07493 151

B101220452 Forwards LER B1-002/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co. B1/01/15 1p 07503 194

--B101220456 LER B1-002/03L-0 on B01231, pressurizer power operated relief valve declared inoperable because of low nitrogen gas supply tank pressure in J-ON-TAK-1A. Caused by excessive usage of nitrogen to cycle relief valves to reduce RCS pressure. CARTWRIGHT, W R Virginia Electric & Power Co. B1/01/15 3pp 07505 200

B101270582 Forwards LER 80-108/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co. B1/01/21 1p 07546 323

--B101270588 LER 80-108/03L-0 on B01227, tests showed primary identified leakage was 12.73 gpm & primary unidentified leakage was 2.37 gpm. Caused by excessive leakage of RCP A seal 2. Seal will be replaced. CARTWRIGHT, W R Virginia Electric & Power Co. B1/01/21 3pp 07546 324

V. Operator Examinations

B101000308 Forwards response to specified items of NUREG-0737 re shift technical advisor training program & ECCS outage report of North Anna 1 & 2.
SULVIA, G R Virginia Electric & Power Co. 80/12/31 37pp

DOCKET 80-039 NORTH ANNA POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

B101070434 Releases public version of utility emergency plan.
FELTON, J M Division of Rules and Records 80/12/02 1p 07415 346

--B101070446 Forwards public version of Revision 2 to emergency plan. List of changes encl.
BAUM, E A Virginia Electric & Power Co. 80/06/20 2pp. 07415 347

--B101070442 Public version of Revision 2 to emergency plan.
* Virginia Electric & Power Co. 80/06/18 28pp. 07415 349.

B101070152 Releases public version of utility emergency plan.
FELTON, J M Division of Rules and Records 80/12/02 1p 07416 014

--B101070454 Forwards public version of Revision 3 to emergency plan.
BAUM, E A Virginia Electric & Power Co. 80/06/25 1p 07416 015

--B101070457 Public version of Revision 3 to emergency plan.
* Virginia Electric & Power Co. 80/06/25 22pp 07416 016

B101120489 Releases public version of utility emergency plan.
FELTON, J M Division of Rules and Records. 80/12/02 1p 07437 204

--B101120490 Forwards public version of Revision 1 to utility emergency plan. State of VA B00520 confirmation ltr & list of changes encl.
BAUM, E A Virginia Electric & Power Co. 80/06/08 5pp 07437 205

--B101120495 Public version of Revision 1 to utility emergency plan.
* Virginia Electric & Power Co. 80/06/09 106pp 07437

B101066615 Requests that utility emergency planning info be made publicly available. W/O encl.
SCUDER, J L Division of Rules and Records 80/12/17 1p 07399 359

B101090146 Requests that utility emergency planning info be made available. W/O encl.
SCUDER, J L Division of Rules and Records 80/12/17 1p 07419 248

B101120280 Requests exclusion from submitting State of MD emergency plan, since zone intrudes only 12 miles into area w/ sparse population & farming. Wind seldom blows toward area & radiation levels would be minimal.
BAUM, E A Virginia Electric & Power Co. B1/01/09 2pp.

G. Adjudicatory correspondence

B101130384 Requests extension of license mod hearing request. B10108 to B10216. Hearing may still be requested but utility must review environmental qualification matter before making final decision re necessity of hearing.
CHRISTIAN, J N Hinton & Williams B1/01/07 3pp

B101230103 Forwards "Turbine Missile Rept (HP296-LP261-LP281) request Rept section of info package to be submitted per B01106 ltr. Related correspondence.
* Hinton & Williams B1/01/14 1p 07511 341

H. General correspondence

B101050489 Informs that appointment of JJ Datta as senior vice president of power operations, effective B10101, approved on B01219 by WEPCO Board of Directors. Discusses utility corporate organization Tech Specs being revised for facilities.
FEQULESON, J H Virginia Electric & Power Co. 80/12/31 2p

J. Insurance & indemnity information

B101130357 Forwards Endorsements 2.5, 4, 4.24, 5B & 31 to NELA ED-70, ED-63, EB-28, ED-27, NS-316 NF-186 & NF-240, respectively.
HARRFIELD, A J Marsh & McLennan, Inc. M & M Nuclear Consulting Div. B1/01/07 16pp.

P. Operating license stage documents & correspondence

B012300480 Forwards addl info re B01101 NUREG-0508 on safety electrical equipment environment qualification per NRC B01202-0 audit request. Response to Statement 10 to be submitted separately. Encl available in Central Files only.
SULVIA, B R Virginia Electric & Power Co. 80/12/23 2pp 07346 132

B101150892 Updates developments in turbine missile issue at Based on conservatism for calculation of critical crack ratio, continued operation until B01229 is justified. License will meet w/NRC on B01229 to present addl justification.
NEVAK, T M Assistant Director for Operating Reactors 80/12/31 07308 001

B101040349 Forwards rept. "Evaluation of Direct Measurement Differential Settlement Across Svc Water Lines Expansion Joints," in response to NRC B00912 request.
SULVIA, B R Virginia Electric & Power Co. 80/12/29 20pp 07393 006

B101160417 Forwards Amend 2 to License NPF-7, FR notice & safety evaluation. No action taken on item re implementation date. Condition 2 C 21, Item J.
YOUNGBL000, B J Licensing Branch 1 80/12/29 2pp 07416 014

--B101160421 Amend 2 to License NPF-7, changing implementation certain post-TMI requirements & revising implementation mode re IE Bulletin 79-27.
ETSEBOUT, D O Division of Licensing 80/12/29 4pp

--B101160423 Notice of issuance of Amend 2 to License NPF-7.
YOUNGBL000, B J Licensing Branch 1 80/12/29 2pp 07416 014

--B101160424 Safety evaluation supporting Amend 2 to License NPF-7
 * Office of Nuclear Reactor Regulation, Director 80/12/29
 1app 07471 009

B101050352 Forwards response to Item III D 3 4 of NUREG-0737 Reviews of control room habitability conclude that requirements of Reg Guide 1.78 & 1.95 & SRP Sections 2.2 1-2 2.2 & 2.2 3 have been met
 SYLVIA.B.R Virginia Electric & Power Co 80/12/30 12pp 07376 206

B101190608 Forwards Amds 23 & 3 to Licenses NPF-4 & NPF-7, respectively & notice of issuance
 CLARK.R.A Operating Reactors Branch 3. YOUNGBLOND.B.J Licensing Branch 1 80/12/30 3pp 07183 001

--B101190617 Amds 23 & 3 to Licenses NPF-4 & NPF-7, respectively, deleting water quality requirements for Unit 1 & adding environ protection plan for Units 1 & 2
 CLARK.R.A Operating Reactors Branch 3 80/12/30 85pp 07183 001

--B101190621 Notice of issuance of Amds 23 & 3 to Licenses NPF-4 & NPF-7, respectively
 CLARK.R.A Operating Reactors Branch 3 80/12/30 2pp 07183 001

B101060308 Forwards response to specified items of NUREG-0737 re shift technical advisor training program & ECCS outage rept of North Anna 1 & 2
 SYLVIA.B.R Virginia Electric & Power Co 80/12/31 37pp

B101090588 Responds to Statement 10 of NRC B01202-04 audit of utility NUREG-0588 review Program developed to re-evaluate equipment qualification folders Outline of missing data will be prepared by B10107
 SYLVIA.B.R Virginia Electric & Power Co 81/01/02 2pp 07427 351

B101160436 Application for amend to License NPF-7, allowing 90-day extension for completion of piping reanalysis, including seismic amplified response spectra evaluation, Class III Fee encl
 FERROUSON.J.H Virginia Electric & Power Co 81/01/09 3pp 07472 141

B101290478 Summary of B10107 meeting w/utility in Bethesda, MD re load testing of RCS isolation valves Tech Spec Page 3/4 4-1B encl
 DRUMERICK.A.W Licensing Branch 1 81/01/12 9pp 07975 147

--B101290482 Tech Spec Page 3/4 4-1B, Section 4.4 & 2.2 re RCS surveillance requirements
 * Licensing Branch 1 81/01/12 1p 07975 152

B101300024 Informs of transfer of licensing mgt responsibilities Responsibilities for Unit 2 will fall under Assistant Director for Operating Reactors, Div of Licensing Licensing project manager for both units will be L. Engle
 EISENHUT.D.O Division of Licensing 81/01/13 2pp. 07308 001

B101200229 Forwards revised VEP-FRD-36, designated VEP-FRD-36A, "Control Rod Reactivity Worth Determination by Rod Swap Technique," per NRC B01107 ltr
 THOMAS.W.N Virginia Electric & Power Co 81/01/16 2pp

--B101200235 "Control Rod Reactivity Worth Determination by Rod Swap Technique"
 ROSS.T.K Virginia Electric & Power Co VEP-FRD-36A 80/12/31 61pp

B101220369 Forwards VEP-FRD-39, "North Anna Unit 2, Cycle 1 Startup Physics Test Rept"
 THOMAS.W.N Virginia Electric & Power Co 81/01/16 1p 07309 001

--B101220370 "North Anna Unit 2, Cycle 1 Startup Physics Test Rept"
 ROTELLA.T.S., KUNSITIS.T.J., LOZITO.E.J Virginia Electric & Power Co VEP-FRD-39 80/12/31 125pp 07309 001

B101220328 Forwards Revision 0 to CT-24821, "Turbine Missile Rept (HP296-LP281-LP281)"
 SYLVIA.B.R. Virginia Electric & Power Co 81/01/19. 1p. 07500: 125

--B101220333 "Turbine Missile Rept (HP296-LP281-LP281)"
 * Westinghouse Electric Corp CT-24821 RO 80/08/31. 26pp 07500. 126

B101230465 Advises that containment sump level processors move to nonhazardous environment has been completed Change will be reflected in B10201 submittal for NUREG-0588 review
 SYLVIA.B.R Virginia Electric & Power Co 81/01/19 2pp 07510 308

B101290757 Forwards info re containment base mat amplified response spectra per NRC verbal request Evaluation of safety-related components described in B01107 submittal completed for smooth ground response spectra w/o design mods
 SYLVIA.B.R Virginia Electric & Power Co 81/01/23 7pp 07309 001

B101300193 Expresses appreciation for B01203 meeting to discuss in-house licensing activities Physics analysis methodology for reload safety evaluations will be discussed at B01208 meeting
 THOMAS.W.N Virginia Electric & Power Co 81/01/26 1p

0 Inspection reports, IE Bulletins & correspondence

B101120120 Revises B01201 completion date for corrective actions for IE Bulletin 80-18 re maint of adequate min flow through centrifugal charging pumps Surry mods to be completed by B01203 & North Anna by B01203
 SYLVIA.B.R Virginia Electric & Power Co 80/12/22 1p.

B101120519 Provides estimated schedule for completing reason well re-evaluation program required by IE Bulletin 80-11 Completion dates for Class I & II wells are B10315 & 0415, respectively
 SYLVIA.B.R. Virginia Electric & Power Co 80/12/26 2pp

B101290396 Forwards response to IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (Oct 17, 1980 Indian Point 2 Event)" No leakage in closed sys at North Anna 1 & 2 Summary of leakage at Surry 1 & 2 encl
 SYLVIA.B.R Virginia Electric & Power Co 81/01/05 9pp

R Periodic operating reports & related correspondence

B101200378 Forwards monthly operating rept for Dec 1980 & revised Unit 1 monthly operating rept for Nov 1980
 SYLVIA.B.R Virginia Electric & Power Co 81/01/15 1p 07477 146

--B101200389 Monthly operating repts for Dec 1980
 ROBERS.L.L. Virginia Electric & Power Co. 81/01/05 10pp 07477 149

8 Reportable occurrences, LERs & related correspondence

B101090630 Forwards LER 80-101/03L-0
 CARTWRIGHT.W.R Virginia Electric & Power Co 81/01/02 1p 07430 359

--B101090639 LER 80-101/03L-0 on B01211, nonconservative constants found entered on B01127 into FO survey program used to verify FZ within limits Caused by computer technician error after disc changeout. Correction made
 CARTWRIGHT.W.R. Virginia Electric & Power Co 81/01/02 2pp 07430 360

B101130468 Forwards LER 80-098/03L-0
 CARTWRIGHT.W.R Virginia Electric & Power Co. 81/01/06 1p 07454 107

--B101130480 LER 80-098/03L-0 on B01208, individual rod position indication for rod J-7 in shutdown bank B deviated from demand position by more than 12 steps Caused by instrument drift Rod position indicator channel recaliber
 CARTWRIGHT.W.R Virginia Electric & Power Co 81/01/06 2pp 07454 108

B101300475 Forwards LER 80-097/03L-0
 CARTWRIGHT.W.R Virginia Electric & Power Co 81/01/06. 1p 07454 115

--B101130488 LER 80-097/03L-0 on B01209 & 10, containment penetration conductor for polar crane energized in mode for which breaker overload protection not qualified. Caused by closing breaker 231-2A3 for insp & work completion
 CARTWRIGHT.W.R. Virginia Electric & Power Co 81/01/06 2pp 07454 116

B101130493 Forwards LER 80-099/03L-0
 CARTWRIGHT.W.R. Virginia Electric & Power Co 81/01/06 1p 07453 285

--B101130528 LER 80-099/03L-0 on 801210, overspeed trip of steam driven auxiliary feedwater pump occurred during post-maint testing. Probably caused by governor malfunction due to air entrapped. Air purged from governor oil.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 81/01/06 2pp
07453.286

B101130534 Forwards LER 80-096/03L-0
CARTWRIGHT, W.R. Virginia Electric & Power Co. 81/01/06 1p
07454.136

--B101130539 LER 80-096/03L-0 on 801208, power supply to PG-2475 in steam generator 1A steam pressure channel (TI reading low) caused by instrument drift. Power supply recalibrated.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 81/01/06 2pp
07454.137

B101300582 Forwards LER 80-100/03L-0
CARTWRIGHT, W.R. Virginia Electric & Power Co. 81/01/09 1p
07582.342

--B101300597 LER 80-100/03L-0 on 801211, with unit in Mode 3, RC Loop A gave protection annunciator locked in actual lube indicating 347 F & protective Channel 1A lube (TI-2412D) indicating 344 F. Cause unknown. Channel 1A recalibrated.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 81/01/09 2pp
07582.343

B101200353 Forwards LER 80-102/03L-0
CARTWRIGHT, W.R. Virginia Electric & Power Co. 81/01/14 1p
07477.341

--B101200359 LER 80-102/03L-0 on 801218, axial flux difference deviated above target caused by increasing reactor power during startup w/ effects of xenon burnout. Rods banded out to restore axial flux difference to within target band.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 81/01/14 2pp
07477.342

B101200375 Forwards LER 80-103/03L-0
CARTWRIGHT, W.R. Virginia Electric & Power Co. 81/01/14 1p
07477.352

--B101200383 LER 80-103/03L-0 on 801220, refueling water storage tank level transmitters LT-08-2000, C & D froze caused by cold outside temp along w/ improperly adjusted setpoint pots on heat tracing circuits. Transmitters thawed & pots adjusted.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 81/01/14 2pp
07477.353

B101200444 Forwards LER 80-104/03L-0
CARTWRIGHT, W.R. Virginia Electric & Power Co. 81/01/14 1p
07476.334

--B101200452 LER 80-104/03L-0 on 801218, w/ unit in Mode 1, water was found leaking from weld joint connecting vent valve 2-CH-P-185 to piping into suction line of charging pump 2-CH-P-1B. Caused by leak from weld at base of valve. Weld repaired.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 81/01/14 2pp
07476.335

B101230593 Forwards LER 81-001/03L-0
CARTWRIGHT, W.R. Virginia Electric & Power Co. 81/01/15 1p
07512.252

--B101230601 LER 81-001/03L-0 on 810101, average RCS temp outside Tech Specs on two occasions. First caused by vol control tank being overbored; second by overcooling primary steam generator blowdown secured, rods withdrawn & RCS diluted.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 81/01/15 3pp
07512.253

B101300706 Forwards LER 81-007/03L-0
CARTWRIGHT, W.R. Virginia Electric & Power Co. 81/01/26 1p
07183.001

--B101300714 LER 81-007/03L-0 on 801230, boron concentration in boron acid storage tank C & boron injection tank below Tech Spec. Probably caused by inletage of unknown source. Boric acid transferred to tank C. Investigation of leak underway.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 81/01/26 3pp
07183.001

V Operator Examinations

B101050308 Forwards response to specified items of NUREG-0737 re shift technical advisor training program & ECCS outage rept of North Anna 1 & 2
SYLVIA, B.R. Virginia Electric & Power Co. 80/12/31 37pp.

B101130240 Advises that four licensed reactor operators will not complete annual written exam by end of CY80, due to extensive startup test program, outages & training & operator licensing requirements. Exam will be completed by 810331.
SYLVIA, B.R. Virginia Electric & Power Co. 81/01/08 1p
07457.024

DOCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D.O. Division of Licensing 80/11/26 6pp

B101190505 Ltr to all BWR applicants for OL re BWR scram discharge w/ safety evaluation & requirements Rept specifying acceptable basis for continued BWR plant operation & design criteria for scram discharge vol encl.
TEDESCO, R.L. Assistant Director for Licensing 80/12/22 2pp
07183.001

--B101190514 Forwards generic safety evaluation re BWR scram discharge w/ Review identified two add'l requirements to those proposed by owners group re scram discharge vol designs Rept should be transmitted to license applicants.
CHECK, P.S. Assistant Director for Plant Systems 80/12/01 2p
07183.001

B101140942 Summary of 801209 meeting w/ Bechtel in Gaithersburg, MD re review.
KINTNER, L.L. Licensing Branch 2 80/12/30 3pp 07461.021

B101050077 Forwards Amend 32 to amended & substituted application for licenses, consisting of additions & mods to FSAR.
THOMAS, B. LeBoeuf, Lamb, Leiby & MacRae 80/12/31 1p
07380.191

--B101050080 Amend 32 to amended & substituted application for licenses, consisting of additions & mods to FSAR.
HEIDEL, C.M. Detroit Edison Co. 80/12/30 1p 07380.192

B101200316 Confirms 810115 meeting w/ util in Glen Ellyn, IL to discuss status of project & topics re const activities.
HEPPLER, J.O. Region 3, Chicago, Office of the Director 81/01/12 1p 07487.024

B101210083 Informs that 801205 memo re meeting summary for Fermi 2 should read Farley 2. Copies of memo should be destroyed.
KINTNER, L.L. Licensing Branch 2 81/01/13 2pp 07489.322

B101210588 Forwards Certificate of Bwr re Amend 32 to amended & substituted application for licenses.
MATERA, B.R. Detroit Edison Co. 81/01/14 3pp 07489.010

B101290472 Summary of 801223 meeting w/ util re scope & schedule for completion of facility OL application review.
KINTNER, L.L. Licensing Branch 2 81/01/14 5pp 07571.037

B101300219 Requests commitment to special low power test program for facility to comply w/ TMI last action item I.O. 1. PWR test re simulated loss of ac power is feasible & should be performed on BWRs.
TEDESCO, R.L. Assistant Director for Licensing 81/01/14 3pp
07582.138

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR.
EISENHUT, D.O. Division of Licensing 80/11/13 2pp

K Utility Final Safety Analysis Report (FSAR) & amendments

B101050077 Forwards Amend 32 to amended & substituted application for licenses, consisting of additions & mods to FSAR.
THOMAS, B. LeBoeuf, Lamb, Leiby & MacRae 80/12/31 1p
07380.191

--B101050080 Amend 32 to amended & substituted application for licenses, consisting of additions & mods to FSAR.
HEIDEL, C.M. Detroit Edison Co. 80/12/30 1p 07380.192

--B101090089 Amend 32 to Enrico Fermi Unit 2 FSAR
* Detroit Edison Co 80/12/30 131pp 07380 193

G. Inspection reports, IE Bulletins & correspondence

B101050274 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding " No response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/30 2pp. 07389 209.

B101050590 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Bscm Discharge Vol at Dresden Unit 2 " No response required.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/05 2pp. 07390 317

B101210656 Forwards IE Insp Rept 50-341/80-20 on 801112-14 & notice of violation
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/09 2pp 07408 147

--B101210699 Notice of violation from insp on 801112-14
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/09 2pp 07488 149

--B101210662 IE Insp Rept 50-341/80-20 on 801112-14 Noncompliance noted: permitting cable installation activities to continue w/known inadequacy & not performing actual audits on electrical activities in plant
BARRETT, P A , KNOP, R C Region 3, Chicago, Office of the Director 80/12/09 4pp 07480 151

B101150810 Forwards IE Insp Rept 50-341/80-21 on 801119-21 No noncompliance noted.
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/12/11 2pp 07464 287.

--B101150819 IE Insp Rept 50-341/80-21 on 801119-21 No noncompliance noted Major areas inspected radiation protection program
HUETER, L J Region 3, Chicago, Office of the Director
FISHER, H L Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/12/09 3pp. 07464 289

B101080041 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Bscm Capability " No written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/17 2pp. 07419 354.

B101150220 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Bscm at BWR " No written response required.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/10 2pp 07465 332.

B101050193 Forwards IE Bulletin 80-25, "Operating Problems W/Target Rock Safety Relief Valves at BWRs." No response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/19 2pp. 07377 331

B101290768 Ack receipt of 801119 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-341/80-11.
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 81/01/14 1p 07568 330

--B101290770 Responds to NRC 801008 ltr re violations noted in IE Insp Rept 50-341/80-11. Corrective actions program instituted to assure design documents in use reflect current design status.
HINEB, E Detroit Edison Co 80/11/19 4pp 07568 331.

B. Reportable occurrences, LERs & related correspondence

B101290006 Interim deficiency rept re defective micro switches initially reported 801203 Six switch failures found out of 130 switches tested Caused by crushed internal parts Final rept will follow by 810310
HINEB, E Detroit Edison Co. 80/12/23 1p 07568 339.

DOCKET 50-344 TROJAN NUCLEAR PLANT, PORTLAND GENERAL ELECTRIC

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR.
EISENHUT, D O Division of Licensing 80/11/13 2pp

B101100661 Ltr to all power reactor licensees w/plants to 790101 Forwards revised Section 10 CFR 50.48 & App fire protection features in nuclear power plants & 1 requirements for resolution of open issues
EISENHUT, D O Division of Licensing 80/11/24 20

B101140454 Responds to utsl 801023 ltr re need to exist area boundary at facility during & after const of to support ctr Changes will not decrease safeguards effectiveness & do not require prior Commission approval
CLARK, R A Operating Reactors Branch 3 80/12/17

B101100840 Informs that licensee must conduct emergency one yr from 810401 or prior to issuance of GL Request schedule of drills & exercises
FENSELKEN, R H Region 5, San Francisco, Office of the 80/12/19 1p 07443 255

B101080440 Discusses emergency plan revision re effect eruptions from Mount St Helens FEPA has been request NRC to consider effects of earthquake eruptions on communication networks & evacuation plans in site area
CHAVEZ, M V Federal Emergency Management Agency, B 07420 336

G. Adjudicatory correspondence

B101120502 Order granting licensee & State of OR 80122 reopen record & receive stipulation & other documents modify License Condition 2 C(12) Appeal moot & dismiss Certificate of Bwc Encl
BISHOP, C J Atomic Safety and Licensing Appeal Panel 8pp 07447 213

H. General correspondence

B101140762 Responds to 801016 ltr re CA Snow 801007 ltr concerns about Mount St Helens & facility Util report finding little mud in plant intake structure Should have been more massive, plant could have shut down so DIRCKS, W J Office of the Executive Director for Ops 80/12/03 4pp 07461 302

B101210318 Expresses concern re possible pyroclastic flow facility resulting from Mt St Helens volcanic eruption Comments requested Search Technical Svcs evaluation newspaper article encl
STEINHART, K Physicians for Social Responsibility, 07490 133

J. Insurance & indemnity information

B101140218 Forwards Endorsement 42 to ANI Policy NF-22 36 & 35 to MAELU Policy NF-66 Endorsement 36 amendments of Endorsement 35
WILSON, F R Portland General Electric Co 80/12/04 07461 273

P. Operating license stage documents & correspondence

B101100254 Ltr to all licensees (except SEP licensees) Revision 1 of inservice surveillance requirements for snubbers under BTR license amend application adding Tech Specs to App A should be submitted within 120 d
EISENHUT, D O Division of Licensing 80/11/20 1p

--B101100271 Revised Pages 3/4 7-22 through 28 B 3/4 7 BTR snubber inservice insp requirements
* Division of Licensing 80/11/20 10pp

B101220466 Ltr to all power reactor licensees & applicants summary of 801112 meeting re implementation of guide Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports " EISENHUT, D O Division of Licensing 80/11/26 8p

B101090745 Forwards Amend 93 to License NPF-1 & notice availability.
CLARK, R A Operating Reactors Branch 3 80/12/11

--B101090753 Amend 53 to License NPF-1, clarifying definition of "operable."
CLARK, R A Operating Reactors Branch 3 80/12/11 07430 342

--B101090760 Notice of issuance & availability of Amend NPF-1.
CLARK, R A Operating Reactors Branch 3 80/12/11 07430 352

0101060435 Forwards Amend 54 to License NPF-1 & notice of issuance & availability
CLARK, R A Operating Reactors Branch 3 80/12/11 3pp 03893 292

--0101060928 Amend 54 to License NPF-1 restricting containment purge/exhaust fan operation & correcting error on min water level maint over reactor vessel during refueling
CLARK, R A Operating Reactors Branch 3 80/12/11 19pp 03893 295

--0101070939 Notice of issuance & availability of Amend 54 to License NPF-1
CLARK, R A Operating Reactors Branch 3 80/12/11 2pp 03893 313

0101050441 Notifies that until 801029 application to amend license, clarifying term "operation" requires Class III fee
EISENHUT, D G License Fee Management Branch 80/12/15 1p 07389 347

010101210445 Forwards responses to questions on Rule 30.71e. "Periodic Updating of FSARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame
EISENHUT, D G Division of Licensing 80/12/15 13pp

0101000590 Technical Evaluation Rept. Degraded Grid Protection for Class IE Power Sys. Trojan Nuclear Plant. technical evaluation rept
CLEVELAND, C W Idaho National Engineering Laboratory FIN A-6256
80/12/31 13pp 07431 110

0101070346 Forwards supplemental info to 801223 response to NUREG-0737 re post-TMI action items includes info re shift technical advisor, auxiliary feedwater sys automatic initiation & flow indication Aperture card in PDR
WITHERS, B D Portland General Electric Co. 81/01/02 37pp 07414 332

01010100271 Forwards Class III license amend fee in response to LRC 801215 ltr re util 801027 application
WITHERS, B D Portland General Electric Co 81/01/06 2pp 07447 221

0101290773 Summary of 801217 meeting w/Util & Westinghouse re final conclusions & lab examination results of steam generator row 1 U-bend tube samples removed from facility. List of attendees & photographs encl
TRAMMELL, C M Operating Reactors Branch 3 81/01/06 11pp 07569 187

0101210293 Forwards addl clarifying info re FIS in support of 800722 License Change Application 63 for amend of License NPF-1
WITHERS, B D Portland General Electric Co 81/01/13 5pp 07492 060

0101220270 Forwards proprietary & nonproprietary versions of "Improved BCL, HZP, Power Distribution Prediction," per 801118 request Requests Withholding (ref 10CFR2 790)
WITHERS, B D Portland General Electric Co 81/01/13 2pp 07495 174

--0101220274 Nonproprietary version of "Improved BCL, HZP Power Distribution Prediction"
Portland General Electric Co. 81/01/13 8pp 07495 176

--0101220279 Requests that util startup & power escalation testing rept be withheld from public disclosure per 10CFR2 790 Original Affidavit AW-76-31 dtd 760703 encl
WIESEFANN, R A Westinghouse Electric Corp 81/01/07 10pp 07495 184

0101270503 Suppls 801112 License Change Application 67 requesting changes to Tech Specs re emergency bus undervoltage protection sys actuation logic Primary & secondary sys will consist of four solid state definite time delay relays
WITHERS, B D Portland General Electric Co. 81/01/21 4pp 07543 012

0 Inspection reports, IF Bulletins & correspondence

0101050124 Requests existing data, summaries & records of inservice insp tests of containments w/greased prestressing tendons ORNL receiving contract to compile & review records of tendons
EISENHUT, D G Division of Licensing 80/11/25 3pp

0101210520 Forwards IE Insp Rept 50-344/80-28 on 801103-07 No noncompliance noted
SPENCER, D S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/11/28 2pp 07488 068

--0101210624 IE Insp Rept 50-344/80-28 on 801103-07 No noncompliance noted Major areas inspected facility mod activities & followup on previously identified items
HARBUTT, P P Region 5, San Francisco, Office of the Director
DOBBS, R T Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/11/28 8pp 07488 070

0101060028 Responds to IE Bulletin 80-23 No Valcor Engineering Corp solenoid valves used at facility
WITHERS, B D Portland General Electric Co 80/12/02 1p 07399 157

0101050496 Forwards IE Info Notice 80-43, "Failures of Continuous W Level Monitor for Scram Discharge Vol at Dresden Unit 2"
No response required
EISENHUT, D G Region 5, San Francisco, Office of the Director 80/12/05 1p 07387 282

0101120567 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co, Inc." No subj valve yokes in use at facility
WITHERS, B D Portland General Electric Co 80/12/10 1p 07309 001

0101060033 Forwards IE Insp Rept 50-344/80-23 on 801020-24, 28 & 29 noncompliance noted Major areas inspected activities re physical protection program against industrial sabotage & theft of S&I Insp rept withheld (ref 10CFR2 790)
MORROW, L R Region 5, San Francisco, Safeguards Branch 83/12/19 1p 07399 150

0101150829 Forwards IE Info Notice 80-41, "Actuation of ECCB in Recirculation Mode While in Hot Shutdown" No response required
EISENHUT, D G Region 5, San Francisco, Office of the Director 80/12/16 1p 07308 001

0101270453 Responds to IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (801017 Indian Point 2 Event)" Safety-grade containment water level monitoring sys will be installed during next refueling outage.
WITHERS, B D Portland General Electric Co 81/01/06 1p 07549 059

0101270657 Responds to NRC 801125 ltr requesting info re inservice of containment structure ungrouted (greased) prestressing tendons Third surveillance program now being performed at plant & expected to continue through Mar 1981
WITHERS, B D Portland General Electric Co 81/01/21 5pp 07549 001

R Periodic operating reports & related correspondence

0101130564 Forwards monthly operating rept for Dec 1980.
YUNDT, C P Portland General Electric Co. 81/01/02 1p. 07493

--0101130572 Monthly operating rept for Dec 1980
YUNDT, C P Portland General Electric Co. 81/01/02 5pp 07495 209

B Reportable occurrences, LERs & related correspondence

0101050311 Discusses fire suppression sys inoperability caused by in hydrant branch line due to excavation for technical support ctr Design completed shortening header branch line & relocating fire hydrant. Completion scheduled for 801224
YUNDT, C P Portland General Electric Co. 80/12/17 1p. 07385

0101190443 Forwards LER 81-001/03L-0
YUNDT, C P Portland General Electric Co. 81/01/09 2pp. 07474 049

--0101190445 LER 81-001/03L-0 on 801212, blown fuse was found in br control power circuit for vent supply fan to turbine-driven auxiliary feedwater pump room Cause unknown Fuse replaced.
YUNDT, C P Portland General Electric Co. 81/01/09 2pp 07474 051

0101290730 Part 21 rept re failure to provide proper Control Comp Int'l valves supplying 2 gpm flow when in closed position. Caused by valve failure. Affected licensees notified & selection of alternative method underway.
TAYLOR, J H Babcock & Wilcox Co 81/01/09 2pp. 07308 001.

8101280539 Forwards updated LER 80-020/017-1
YUNDT, C P Portland General Electric Co 81/01/22 3pp
07308 001

--8101280546 Updated LER 80-020/017-1 on 801003 auxiliary feedwater pumps
Failed to respond to automatic start signal from 10-10 steam
generator water level following reactor trip Caused by
wiring error Procedure mod instituted
SCHMITT, R P Portland General Electric Co 81/01/22 1p
07308 001

DOCKET 80-346 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP holders
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
810102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

8101080101 Releases public version of util emergency plan
FELTON, J M Division of Rules and Records 80/12/03 1p
07309 001

--8101080107 Forwards public version of util emergency plan in response
to 730710 request
MULLER, D R Atomic Energy Commission, Directorate of Licensing
73/07/24 2pp 07309 001

--8101080110 Public version of util emergency plan
* Toledo Edison Co 73/07/24 10pp 07309 001

8101070469 Forwards comments on util 800815 revised emergency plan Plan
was evaluated using criteria in NUREG-0634 Comments must be
resolved by 810102
REID, R W Operating Reactors Branch 4 80/12/17 7pp. 07415-248

8101160616 Requests that encl facility emergency planning info be made
publicly available w/o encl
SODER, J L Division of Rules and Records 81/01/07 1p
07471-221

J. Insurance & indemnity information

8101220351 Forwards Endorsements 33 & 34 to NELIA Policy NF-236 &
Endorsement 4 to Binder ED-61
CORREA, C Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc Div.
81/01/15 3pp 07496 351

P. Operating license stage documents & correspondence

8101070173 Forwards questions & comments & request for addl info re
inservice testing program Comments will form basis for
working session to be held at facility on 80119-21
REID, R W Operating Reactors Branch 4 80/11/14 13pp 07414 293

8101100254 Ltr to all licensees (except SEP licensees) forwarding
Revision 1 of inservice surveillance requirements for
snubbers under BTB License amend application adding model
Tech Specs to App A should be submitted within 120 days
EISENHUT, D O Division of Licensing 80/11/20 1p

--8101100271 Revised Pages 3/4 7-22 through 28, B 3/4 7-5 & 7-6 & 6-17 to
BTB snubber inservice insp requirements
* Division of Licensing. 80/11/20 10pp.

8101220466 Ltr to all power reactor licensees & applicants forwarding
summary of 801112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing. 80/11/26 8pp.

8101210445 Forwards responses to questions on Rule 50.71e. "Periodic
Updating of FBARs" & FR notice of final rule, SEP plants need
not comply w/rule until program is complete Non-SEP plants
must comply within specified time frame
EISENHUT, D O. Division of Licensing. 80/12/15. 13pp

8101100184 Discusses 801205 inadvertent safety features actuation sys
Level 1, 2, 3 & 5 actuation while licensee & vendor were
attempting to isolate electrical fault in sys IE & Ofc of
Nuclear Reactor Regulation followup should suffice
CHIRWAL, M. Director's Office 80/12/19 2pp. 07444.166

8101060581 Forwards application for amend to License NPF-
Tech Specs re fire detection sys, decay heat removal
capabilities, low temp RCS overpressure event, axial power
shaping rod insertion limits & util reorganization
CROUSE, R P Toledo Edison Co 80/12/26 2pp 07395

--8101060584 Application for amend of License NPF-3 change
re fire detection sys, decay heat removal capabilities
temp RCS overpressure event, axial power shaping rod
insertion limits & util reorganization
CROUSE, R P Toledo Edison Co 80/12/26 1p 07395

--8101060597 Proposed Tech Specs 3.3.3.8.4.3.3.8.2.3.7
Tables 3.3-14.3.7-4 & 3.7.5 re fire detection & fire
suppression sys
* Toledo Edison Co. 80/12/26 16pp 07395 075

--8101060673 Proposed Tech Specs 3.4.1.1.3.4.1.2.3.9.8.1.
re decay heat removal capability Safety evaluation encl
* Toledo Edison Co 80/12/26. 10pp 07395 091

--8101060610 Proposed Tech Specs 3.5.3.3.4.2.4.4.2.Figure
3.4-2b.3.bases re decay heat removal sys relief valv
Modes 4 & 5 Safety evaluation encl
* Toledo Edison Co 80/12/26 11pp 07395 101

--8101060614 Proposed Tech Specs 4.1.3.9 re axial power s
insertion limits Safety evaluation encl
* Toledo Edison Co 80/12/26 5pp 07395 112

--8101060624 Proposed Tech Specs 6.5.1 re administrative
* Toledo Edison Co 80/12/26 1p 07395 119

8101060473 Responds to NUREG-0737 Util working w/OM State
feasibility evaluation of long-term program to phase out
need for shift technical advisor Commitment supersedes
previous commitments
CROUSE, R P Toledo Edison Co. 80/12/30 17pp 07390

8101120253 Notification of 810105 meeting w/util in Bathe
discuss proposed Tech Spec change re defeat of automatic
switchover of ECCS supply from borated water storage tank
recirculation mode from containment sump
DIAMANT, D C Operating Reactors Branch 4 80/12/30
07435 359

8101070378 Forwards "Addendum 1 to Analyses of Adequacy of
Nuclear Power Station Onsite Electrical Auxiliary
Distribution Power Sys Voltages." in response to addl N
801114 questions
* Toledo Edison Co. 81/01/02 1p 07414 110

--8101070383 "Addendum 1 to Analyses of Adequacy of Davis
Power Station Onsite Electrical Auxiliary Distribution
Power Sys Voltages"
* Toledo Edison Co 80/12/30 12pp 07414 111

8101090027 Application to amend License NPF-3, changing Tech
Sections 3.1.3.3.3.3.4.3.4.5.2.4.6 re borated water source
limiting condition for operation, surveillance requirements
& bases W/Class 111 amend fee
CROUSE, R P Toledo Edison Co 81/01/05 3pp 07441

--8101090029 Proposed Tech Spec Sections 3.1.3.3.3.4.3.
changing borated water sources limiting conditions for
operation, surveillance requirements & bases
* Toledo Edison Co. 81/01/05 17pp 07441 161

8101160090 Forwards Amend 35 to License NPF-3, safety eval
notice of issuance & availability
REID, R W Operating Reactors Branch 4 81/01/05 2pp

--8101160057 Amend 35 to License NPF-3, revising Tech Specs
continuous plant operation during first test following
refueling outage on pressure transmitters for contain
high pressure channels
REID, R W Operating Reactors Branch 4 81/01/05 9
07469 273

--8101160051 Safety evaluation supporting Amend 35 to Lic
* Office of Nuclear Reactor Regulation, Director B
07469 277

--8101160061 Notice of issuance & availability of Amend 3
NPF-3
REID, R W Operating Reactors Branch 4 81/01/05 2
07469 279

8101220242 Forwards application to amend License NPF-3, marked-up Tech Spec changes & proposed procedure mods Encl available in Central Files only
 CROUSE, R P Toledo Edison Co 81/01/09 2pp 07517 036

810160461 Forwards marked-up electrical drawings as update to 810105 request to deautomate Incident Level 5 of safety features actuation sys Procedure mod details, license amend request & safety evaluation will follow 1/20 encl
 CROUSE, R P Toledo Edison Co 81/01/09 3pp 07469 359

810190503 Application to amend License NPF-3, changing Tech Specs to permit deautomation of valve shifts caused by Incident Level 5 of safety features actuation sys
 CROUSE, R P Toledo Edison Co 81/01/15 3pp 07475 075

810190509 Proposed Tech Specs Sections 3 & 4, to permit deautomation of valve shifts caused by Incident Level 5 of safety features actuation sys Draft emergency & sys operating procedures & functional description encl
 Toledo Edison Co 81/01/15 10pp 07475 078

8101205075 Forwards application for amend of License NPF-3 re proposal to deautomate valve shifts caused by Incident Level 5 of safety features actuation sys
 CROUSE, R P Toledo Edison Co 81/01/15 2pp 07502 270

8101205082 Application for amend of License NPF-3, changing Tech Specs Sections 3.4 & 4 re proposal to deautomate valve shifts caused by Incident Level 5 of safety features actuation sys Draft proposed mods to operating procedures encl
 ROULES, W C, CROUSE, R P Toledo Edison Co 81/01/15 12pp 07502 272

8101260467 Revision to 810105 application to amend License NPF-3, changing Tech Specs Sections 3.4 & 4 to support deautomation of Incident Level 5 of safety features actuation sys
 CROUSE, R P Toledo Edison Co 81/01/15 3pp 07502 038

8101260493 Proposed Tech Specs Sections 3.4 & 4 to support deautomation of Incident Level 5 of safety features actuation sys Description of electrical mods, safety evaluation & draft proposed emergency & sys operating procedures encl
 Toledo Edison Co 81/01/15 20pp 07532 041

8101230495 Forwards response to NRC questions re util 810115 ltr re deautomation of Incident Level 5 of safety features actuation sys & long-term post LOCA core cooling manual action proposals
 CROUSE, R P Toledo Edison Co 81/01/19 16pp 07511 130

8101270576 Forwards revision to Attachment C of 810119 ltr re present circuit configuration Calculation methodology for min contained vol discussed Approval of proposed Tech Spec changes re addl surveillance requested by 810123
 CROUSE, R P Toledo Edison Co 81/01/22 4pp 07548 093

8101300605 Responds to NRC safety evaluation requiring installation of addl 100% capacity auxiliary feedwater sys Proposes risk reduction comparison to provide evaluation of acceptable alternatives
 CROUSE, R P Toledo Edison Co 81/01/23 3pp

8101500404 Forwards amend fee for 801226 request for Tech Specs change re fire protection, decay heat removal capabilities, low temp RCS overpressure event, axial power shaping rods insertion limits & reorganization
 CROUSE, R P Toledo Edison Co 81/01/26 1p 07587 067

0 Inspection reports, IE Bulletins & correspondence

8101050218 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding " No response required
 KEPLER, J G Region 3, Chicago, Office of the Director 80/10/30 2pp 07399 060

8101050402 Forwards IE Bulletin 80-21, Valve Yokes Supplied by Malcolm Foundry Co, Inc " Written response required
 KEPLER, J G Region 3, Chicago, Office of the Director 80/11/06 2pp 07390 264

8101080170 Responds to IE Bulletin 80-23 re Valve solenoid valves in safety-related functions No such valves used, Ten hours of manpower expended
 CROUSE, R P Toledo Edison Co 80/11/25 1p 07420 358

8101050581 Forwards IE Info Notice 80-43, "Failures of Continuous Main Level Monitor for Steam Discharge Vol at Dresden Unit 2 " No response required
 KEPLER, J G Region 3, Chicago, Office of the Director 80/12/05 2pp 07399 341

8101500626 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co, Inc " Specified valves are not installed at facility
 CROUSE, R P Toledo Edison Co 80/12/05 1p 07391 063

8101290536 IE Investigation Rept 50-346/80-28 on 800929-1001 No noncompliance noted Major areas investigated allegations re improper welder qualification & welding documentation by personnel
 FOSTER, J E, SCHAPIER, J F, MORELIUS, C E Region 3, Chicago, Office of the Director 80/12/09 7pp 07573 339

8101260720 Forwards IE Insp Rept 50-346/80-31 on 801105-07 No noncompliance noted
 DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/12/10 2pp 07531 162

8101260729 IE Insp Rept 50-346/80-31 on 801105-07 No noncompliance noted Major areas inspected emergency exercise w/13 NRC representatives observing key functions & locations Exercise scenario encl
 AXELSON, W L Region 3, Chicago, Fuel Facility & Materials Safety Branch, MICHAELSON, N A, PAPERIELLO, C J Region 3, Chicago, Office of the Director 80/12/09 13pp 07531 164

8101070200 Provides anticipated schedule for completion of pipe support/anchor mods required inside & outside containment by IE Bulletins 79-02 & 79-14 All IE Bulletin 79-02 mods inside containment completed
 CROUSE, R P Toledo Edison Co 80/12/12 2pp 07415 245

8101060496 Forwards revision to 800515 inservice insp program Changes reflect results of 801119 & 20 meetings w/NRC onsite re lower head joint insp & requirements in 1977 edition through summer 1978 addenda of Boiler & Pressure Vessel Code
 CROUSE, R P Toledo Edison Co 80/12/19 2pp 07396 209

8101060457 Revision 1 to inservice insp program
 Toledo Edison Co 80/11/30 60pp 07396 211

8101070074 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown " No written response required
 KEPLER, J G Region 3, Chicago, Office of the Director 80/12/16 1p 07415 033

8101210650 Forwards IE Insp Rept 50-346/80-30 on 801112-14 & notice of violation
 HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/12/19 2pp 07488 140

8101210651 Notice of violation from insp on 801112-14
 HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/12/18 1p 07488 142

8101210654 IE Insp Rept 50-346/80-30 on 801112-14 Noncompliance noted strip chart recorders not calibr for rod drop time tests
 CHOULES, N C, ROBINSON, D L Region 3, Chicago, Office of the Director, STREETER, J F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/12/17 4pp 07488 143

8101290499 Forwards IE Investigation Rept 50-346/80-28 on 800929-1001 No noncompliance noted
 KEPLER, J G Region 3, Chicago, Office of the Director 80/12/19 2pp 07573 337

8101290506 IE Investigation Rept 50-346/80-28 on 800929-1001 No noncompliance noted Major areas investigated allegations re improper welder qualification & welding documentation by personnel
 FOSTER, J E Region 3, Chicago, Office of the Director, DANIELSON, D Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/09 7pp

8101210643 Forwards IE Insp Rept 50-346/80-29 on 801020-1126 & 1201-0 & notice of violation
 HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/12/23 2pp 07488 129

8101210646 Notice of violation from insp on 801020-1126 & 1201-05
 Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/12/23 1p 07488 131

--B101210548 IE Insp Rept 50-346/80-29 on 801020-1126 & 1201-05
Noncompliance noted containment pressure transmitters not
exercised during functional test
HEYEB, L. A., ROGERS, W. C., WARNICK, R. F. Region 3, Chicago, Office of
the Director 80/12/18 8pp 07489 132

B101160579 Forwards list of NRC & contractor personnel for whom
nonemployees, no escort required, picture badges are required
for health physics appraisal beginning 810117
KEPPLER, J. C. Region 3, Chicago, Office of the Director 80/12/29
3pp. 07471 204

B101200185 Forwards response to IE Bulletin 80-24, "Prevention of
Damage Due to Water Leakage Inside Containment (801017
Indian Point 2 Event)." Containment vessel contains one open
cooling water sys Insp is performed during each startup
CROUSE, R. P. Toledo Edison Co 81/01/05 12pp 07486 214

B101280348 Forwards revision to 801125 response to IE Bulletin 80-06,
"Engineered Safety Feature (ESF) Reset Controls." Valves
which were not tested have safety feature actuation sys
logic identical to valves which were tested
CROUSE, R. P. Toledo Edison Co 81/01/09 5pp 07598 052

B101280348 Forwards revision to 801125 response to IE Bulletin 80-06,
"Engineered Safety Feature (ESF) Reset Controls." Valves
which were not tested have safety feature actuation sys
logic identical to valves which were tested
CROUSE, R. P. Toledo Edison Co 81/01/09 5pp

B101300551 Ack receipt of 810109 ltr informing NRC of steps taken to
correct violation noted in IE Insp Rept 50-346/80-30
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support
Branch 81/01/21 1p 07585 250

--B101300554 Responds to NRC 801219 ltr re violations noted in IE Insp
Rept 50-346/80-30 Corrective actions mod added requiring
brush recorder chart speed to be checked prior to control
rod drop test
CROUSE, R. P. Toledo Edison Co 81/01/07 3pp 07583 231

B101300566 Ack receipt of 801110 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-346/80-25
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support
Branch 81/01/21 1p 07586 324

--B101300571 Responds to NRC 801015 ltr re violations noted in IE Insp
Rept 50-346/80-25 Corrective actions current revisions of
operating procedures will be used
CROUSE, R. P. Toledo Edison Co. 80/11/10 2pp 07586 325

R Periodic operating reports & related correspondence

B101130521 Forwards monthly operating rept for Dec 1980.
MURRAY, T. D. Toledo Edison Co 81/01/08 1p 07454 130.

--B101130526 Monthly operating rept for Dec 1980
BARBOUR, B. Toledo Edison Co 81/01/08 5pp 07454 131

S Reportable occurrences, LERs & related correspondence

B101060667 Forwards LER 80-086/03L-0
MURRAY, T. D. Toledo Edison Co 81/01/02 1p. 07395 050

--B101060680 LER 80-086/03L-0 on 801203, while performing BT 8030.12,
alligator clip slipped off terminal studs 3 & 4 causing
short circuit. Caused by design error. BT 8030.12
modified & F101 fuse replaced.
WERNER, B. J. Toledo Edison Co. 81/01/02 3pp 07395 051.

B101060685 Forwards LER 80-089/03L-0.
MURRAY, T. D. Toledo Edison Co. 81/01/02 1p. 07395 045.

--B101060692 LER 80-089/03L-0 on 801203, following reactor trip, RCB sample
revealed dose equivalent 1-131 level was greater than Tech
Specs. Caused by gas leakage through fuel cladding. Levels
monitored to ensure that gas decayed to below limits.
ESHELMAN, D., BYOTZ, J. Toledo Edison Co 81/01/02 4p.
07395 046

B101060698 Forwards LER 80-087/03L-0.
MURRAY, T. D. Toledo Edison Co. 81/01/02 1p 07395 038.

--B101060705 LER 80-087/03L-0 on 801206, while troubleshooting, control
room operator could not stroke valve CV5006 Valve declared
inoperable. Cause unknown. Corrective action will be conducted
under maint work order IC-814-80 during next outage.
ISLEY, T. Toledo Edison Co 81/01/02 2pp. 07395 039

B101060733 Forwards LER 80-069/03L-0
MURRAY, T. D. Toledo Edison Co 81/01/02 1p 07395 041

--B101060745 LER 80-068/03L-0 on 801205, while troubleshooting for gro
problems in safety features actuation sys channel 3 cabinet.
Station experienced channel 1/3 simultaneous actuation of
levels 1, 2, 3 & 5 Caused by component failure PS-07 replaced
ISLEY, T. Toledo Edison Co 81/01/02 3pp. 07395 042

B101060749 Forwards LER 80-090/03L-0
MURRAY, T. D. Toledo Edison Co 81/01/02 1p 07395 035.

--B101060757 LER 80-090/03L-0 on 801205, during surveillance testing,
setpoint for borated water storage tank low level bistables
BA312 & BA707 found out of tolerance Caused by component
failure Bistables recalibr
ISLEY, T. Toledo Edison Co 81/01/02 2pp 07395 036

B101130415 Forwards LER 80-091/01T-0
MURRAY, T. D. Toledo Edison Co 81/01/06 1p 07454 052

--B101130417 LER 80-091/01T-0 on 801223, during analysis per IE Bulletin
80-11, design for block wall between control room & stairway
A2-1 found to be less conservative than assumed in FSAR
Caused by outdated analytical const methods
MEKEL, C. Toledo Edison Co 81/01/06 3pp 07454 053

B101220424 Forwards LER 80-092/03L-0
MURRAY, T. D. Toledo Edison Co 81/01/16 1p 07505 193

--B101220429 LER 80-092/03L-0 on 801219, isolation valve from main steam
line to auxiliary feed pump turbine failed to close
unrecirculated low pressure Caused by failed couch relay R1
New relay installed
FROMME, R. Toledo Edison Co 81/01/16 2pp 07505 194

B101220435 Forwards LER 80-093/03L-0
MURRAY, T. D. Toledo Edison Co 81/01/16 1p 07505 196

--B101220440 LER 80-093/03L-0 on 801219, demineralized water contained
isolation valve DM66318 did not close in required time
Caused by dump solenoid orifice too small to allow adequate
bleedoff flow Solenoid to be replaced
TRAUTMAN, D. Toledo Edison Co 81/01/16 2pp 07505 197

B101270689 Forwards LER 81-001/01T-0
MURRAY, T. D. Toledo Edison Co 81/01/20 1p. 07545 228

--B101270701 LER 81-001/01T-0 on 810107, analysis determined that
reportable condition had existed on 801204 when several pipe
supports or fuel lines to emergency diesel generators found
disassembled Caused by outside contractor personnel error
DIETERICH, W. Toledo Edison Co. 81/01/20 3pp 07545 229

B101270634 Forwards LER 80-094/03L-0
MURRAY, T. D. Toledo Edison Co 81/01/21 1p 07546 336

--B101270636 LER 80-094/03L-0 on 801226, data from test performed on
auxiliary feed pump 1-2 indicated high bearing temp on
turbine outboard bearing Caused by low oil level Procedures
modified per M-4578 to provide direction on oil levels
JOHNSON, J. Toledo Edison Co 81/01/21 3pp 07546 337

V Operator Examinations

B101060473 Responds to NUREG-0737 Util Working w/OH State Univ on
feasibility evaluation of long-term program to phase out
need for shift technical advisor Commitment supersedes all
previous commitments
CROUSE, R. P. Toledo Edison Co 80/12/30 17pp.

BUCKET 50-348 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

B101260350 Forwards proposed changes to Table 2 3-10 of FSAR, reflecting
current instrumentation on meteorological tower Proposed
change will be incorporated into next amend to FSAR
CLAYTON, F. L. Alabama Power Co 81/01/20 3pp 07525 142.

B01002 & by applicants as part of REAR
EISENHUT.D G Division of Licensing 80/11/13 2pp 07422 243

B01010822 Advises of provisions of 10CFR50 App R that are applicable to fire protection features of facility. FR notice & summary of staff requirements to resolve open items encl W/O encl
EISENHUT.D G Division of Licensing 80/11/24 3pp 07461 013

B01010201 Requests that encl facility emergency planning info be made publicly available W/O encl
SOUDEB J L Division of Rules and Records 80/12/31 1p
07461 263

G Adjudicatory correspondence

B010100507 Forwards revised order for mod of license, correcting refs in B00829 order. Hearing date also revised
EISENHUT.D G Division of Licensing 80/09/19 3pp 07443 258

--B010100595 Revised order attending License NPF-2 info requested by IE Bulletin 79-018 must be submitted to IE by 801101
EISENHUT.D G Division of Licensing 80/09/19 6pp 07443 260

J Insurance & indemnity information

B010107001 Forwards Endorsement 4 to NELA Binder EO-62
FIELDER, J Marsh & McLennan, Inc., H & M Nuclear Consultants, Inc
Div 80/12/30 2pp 07442 071

B01220545 Forwards Endorsements 30 & 31 to NELA Policy NF-238
JUCA, J R Marsh & McLennan, Inc., H & M Nuclear Consultants, Inc. Div.
81/01/16 4pp 07502 058

P Operating license stage documents & correspondence

B010100587 Forwards revised order for mod of license, correcting refs in B00829 order. Hearing date also revised
EISENHUT.D G Division of Licensing 80/09/19 3pp 07443 258

--B010100595 Revised order attending License NPF-2 info requested by IE Bulletin 79-018 must be submitted to IE by 801101
EISENHUT.D G Division of Licensing 80/09/19 6pp 07443 260

B010100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under STS License amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT.D G Division of Licensing 80/11/20 1p 07443 274

--B010100271 Revised Pages 3/4 7-22 through 28.B 3/4 7-9 & 7-6 & 6-17 to STS snubber inservice insp requirements
* Division of Licensing 80/11/20 10pp 07443 278

B010220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports."
EISENHUT.D G Division of Licensing 80/11/26 8pp

B01020228 Forwards Amend 17 to License NPF-2, safety evaluation & notice of issuance & availability
VARQA.S A Operating Reactors Branch I 80/12/10 3pp 07447 041

--B010120252 Amend 17 to License NPF-2, revising administrative controls Tech Specs for high radiation area entry & adding feedwater control sys bypass valves response times to Tech Specs.
VARQA.S A Operating Reactors Branch I 80/12/10 10pp
07447 344

--B010120235 Safety evaluation supporting Amend 17 to License NPF-2
* Office of Nuclear Reactor Regulation, Director 80/12/10 3pp
07447 054

--B010102039 Notice of issuance & availability of Amend 17 to License NPF-2
* Office of Nuclear Reactor Regulation, Director 80/12/10 1p
07447 059

B010106831 Forwards request for addl info re calculations of fuel rod bow penalty
VARQA.S A Operating Reactors Branch I 80/12/12 3pp 07461 327

B01210445 Forwards responses to questions on Rule 50.71e. "Periodic Updating of FSARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame
EISENHUT.D G Division of Licensing 80/12/15 13pp 07489 0

B01050021 Forwards cross ref between Category A model spec provisions & sections in existing & proposed B01215 Tech Specs which show compliance Proposed Tech Spec Section 3.4.6.3 not required License condition re iodine monitoring encl
CLAYTON.F L Alabama Power Co 80/12/23 4pp 07379 340

B01010507 Forwards response to NRC B01212 request for addl info re facility rod bow penalty. Fuel rod bowing reduces value of DN3 ratio. Sufficient credit exists to offset reduction.
CLAYTON.F L Alabama Power Co 81/01/05 9pp 07462 064

B01210402 Discusses containment purge valve operability at facility including use of solenoid valves & air actuators. Interim use of solenoid valves is acceptable. Actuator seal kits will be replaced on regular basis
CLAYTON.F L Alabama Power Co 81/01/05 2pp 07489 080

B01220359 Forwards proposed changes to Tech Specs 3.4.9 & 4.4.9 re heatup & cooldown limit curves necessary as result of Capsule Y analysis. Plant Operations Review Committee & Nuclear Operations Review Board safety evaluation encl.
CLAYTON.F L Alabama Power Co 81/01/09 2pp 07496 358

--B010220363 Safety evaluation supporting proposed changes to Tech Specs 3.4.9 & 4.4.9 re heatup & cooldown limit curves
* Alabama Power Co 81/01/09 2pp 07496 360

--B010220365 Proposed changes to Tech Specs 3.4.9 & 4.4.9 re heatup & cooldown limit curves
* Alabama Power Co 81/01/09 13pp 07497 001

B01260350 Forwards response to NUREG-0737, in response to NRC B01011r items requiring followup by Unit 2 & corresponding SER are included in action item for requirement.
CLAYTON.F L Alabama Power Co 81/01/14 9pp 07529 147

B01230425 Forwards proprietary & nonproprietary versions of low pressure turbine disc info for facility. Proprietary printout withheld (ref 10CFR2 7901 Affidavit & application for withholding encl.
CLAYTON.F L Alabama Power Co 81/01/20 29pp 07308 001

B01270696 Comments on draft SER re auxiliary feedwater control system. Auxiliary feedwater sys design will be modified to remove power source dependence
CLAYTON.F L Alabama Power Co 81/01/22 2pp 07543 016

B01270750 Submits info in clarification of multiple rod drop analysis per Unit 1 B01212 ltr & B01016 telcon. Outlines policy to be implemented when Unit 1 returned to power & subsequent to exceeding 5% power for Unit 2
CLAYTON.F L Alabama Power Co 81/01/22 1p 07548 045

B01270514 Forwards WCAP-BB10, "Reactor Vessel Radiation Program" WCAP-9717, "Analysis of Capsule Y From AL Power Co Farley Unit 1 Reactor Vessel Radiation Surveillance Program," in response to NRC request.
CLAYTON.F L Alabama Power Co 81/01/23 1p 07541 009

--B01270519 "Reactor Vessel Radiation Surveillance Program" DAVIDSON, J A, PHILLIPS, J H, YANICHKO, S E Westinghouse Electric Corp. WCAP-BB10 76/12/31 40pp 07541 010

--B01270526 "Analysis of Capsule Y From AL Power Co Farley Unit 1 Reactor Vessel Radiation Surveillance Program" YANICHKO, S E, ANDERSON, S L, KAISER, W T Westinghouse Electric Corp. WCAP-9717 80/06/30 78pp 07541 050

O Inspection reports, IE Bulletins & correspondence

B01290086 Submits amended response to IE Insp Repts 50-348/80-16 50-364/80-19. Contact made w/vendors to determine required installation torques for concrete expansion anchor bolts.
CLAYTON.F L Alabama Power Co 80/10/07 6pp 07567 234

B101220419 Forwards IE Insp Repts 50-348/80-35 & 50-364/80-46 on B01001-31 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch, 80/12/04 2pp 07500 213

--B101220427 IE Insp Repts 50-348/80-35 & 50-364/80-46 on B01001-31 No noncompliance noted Major areas inspected plant tours, pre-operational testing, open items & task action items
BRADFORD, W H, NULKEY, J P, MARTIN, R D Region 2, Atlanta, Office of the Director 80/12/05 11pp 07500 215

B101060239 Forwards IE Info Notice 80-44, "Actuation of ECCB in Recirculation Mode While in Hot Shutdown " No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/16 1p 07391 345

B101100308 Ack receipt of B01210 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/80-31 & 50-364/80-42
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/12/22 1p 07443 313

--B101100319 Responds to NRC B01114 ltr re violations noted in IE Insp Repts 50-348/80-31 & 50-364/80-42 Corrective actions comprehensive QA audit of fire protection const program initiated No proprietary info
CLAYTON, F L Alabama Power Co 80/12/10 2pp 07443 314

--B101100331 Forwards IE Insp Repts 50-348/80-31 & 50-364/80-42 on B01014-17 & notice of deviation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/14 2pp 07443 316

--B101100337 Notice of deviation from insp on B01014-17, * Region 2, Atlanta, Office of the Director, 80/11/12 1p 07443 318

--B101100343 IE Insp Repts 50-348/80-31 & 50-364/80-42 on B01014-17 Noncompliance noted inadequate fire protection QA program
MILLER, W H Region 2, Atlanta, Office of the Director
CONLON, T E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/12 7pp 07443 319

B101210226 Requests description of insps on turbine discs NRC is concerned that low pressure turbine disc cracks might result in rupture of more turbine discs Info should be provided 30 days prior to restart
VARGA, S A Operating Reactors Branch 1 81/01/09 2pp 07491 358

B101290363 Requests extension until B10115 to respond to IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (Oct 17, 1980 Indian Point 2 Event) " Extension necessitated by licensing & refueling activities
CLAYTON, F L Alabama Power Co 81/01/09 1p 07575 129

B101140554 Forwards "Low Pressure Disc Ultrasonic Insp Rept," in response to NRC B10105 request for results of insp conducted at facility Cracks were discovered in some discs. Refurbished rotors will be installed.
CLAYTON, F L Alabama Power Co. 81/01/12 2pp 07461 350.

--B101140559 "Low Pressure Disc Ultrasonic Insp Rept " * Alabama Power Co 81/01/08 13pp 07461 352

B101270406 Summarizes B10109 conference call re licensee evaluation of IE Bulletin 80-11, "Masonry Wall Design " Licensee should be requested to provide description of deficiencies. Bechtel wall evaluation & commitment to modify walls
REEVES, E Operating Reactors Branch 1, KINTNER, L, Operating Reactors Branch 2, 81/01/13 3pp 07546 181

B101290334 Forwards response to IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (Oct 17, 1980 Indian Point 2 Event) " Bvc water sys is open sys supplying cooling water inside containment.
CLAYTON, F L Alabama Power Co. 81/01/15 8pp 07575 220

B101290728 Responds to IE Bulletin 80-11, "Masonry Wall Design." Required vertical reinforcing missing from both unit walls. Wall w/safety-related equipment should conform w/requirements before criticality.
CLAYTON, F L Alabama Power Co. 81/01/15 2pp 07309 001

--B101210521 Monthly operating rept for Dec 1980
HAIRSTON, W G Alabama Power Co 81/01/01 7pp 07490 203

S Reportable occurrences, LERs & related correspondence

B101130602 Forwards LER 80-077/03L-0.
CLAYTON, F L Alabama Power Co 81/01/06 1p 07453 336

--B101130608 LER 80-077/03L-0 on B01128, loop suction valve for A train RHR closed, resulting in A train RHR being inoperable Caused by dirty contacts on circuitry card for pressure transmitter Card cleaned
HAIRSTON, W G Alabama Power Co. 81/01/06 1p 07453 337

B101300580 RC on B01227, one tube in steam generator 1C satisfactorily plugged Defective tube located by pressurizing secondary side & performing visual insp for leaks Tube plugging reported per Tech Spec 4.4.5.5 a
CLAYTON, F L Alabama Power Co 81/01/12 1p 07582 363

B101210426 Forwards LER 80-070/03L-0
CLAYTON, F L Alabama Power Co 81/01/13 1p 07493 146

--B101210430 LER 80-070/03L-0 on B01207, fusible links found missing Fire dampers between 139-ft & 121-ft penetration rooms Cause unknown Fusible links installed & dampers operational
HAIRSTON, W G Alabama Power Co 81/01/13 1p 07493 147

B101280268 Forwards LERs 80-077/03L-0 & 80-058/03L-1
CLAYTON, F L Alabama Power Co 81/01/23 1p 07557 144

--B101280291 LER 80-058/03L-1 on B01007, per discussion w/NRC, three-containment tendon surveillance revealed tendon liftoff forces & record discrepancies Spring 1901 surveillance to be performed Rams calibr is suspected as primary cause
HAIRSTON, W G Alabama Power Co 81/01/23 2pp 07557 145

--B101280295 LER 80-077/03L-0 on B01108, main steam safety valve B10110108 failed to meet Tech Spec 11F1 setting requirements Caused by setpoint drift Valve adjusted
HAIRSTON, W G Alabama Power Co 81/01/23 1p 07557 147

V Operator Examinations

B101260740 Forwards response to AUREG-0737, in response to NRC B0103 ltr Items requiring followup by Unit 2 & corresponding SER are included in action item for requirement
CLAYTON, F L Alabama Power Co 81/01/14 99pp 07525 147

DOCKET 50-392 LIPERICK GENERATING STATION, UNIT 1

A Application/construction stage documents & correspondence

B101220486 Ltr to all power reactor licensees & applicants forwarded summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports " EBERHART, D G Division of Licensing, 80/11/26 8pp

B101190505 Ltr to all BWR applicants for OL re BWR scram discharge safety evaluation & requirements Rept specifying acceptable basis for continued BWR plant operation & design criteria for scram discharge vol encl
TEDESCO, R L Assistant Director for Licensing 80/12/22 2pp

--B101190514 Forwards generic safety evaluation re BWR scram discharge Review identified two addl requirements to those proposed by owners group re scram discharge vol designs. Rept should be transmitted to license applicants.
CHECK, P S Assistant Director for Plant Systems 80/12/01 07183 001

B101200157 Summary of B01210 meeting w/Mark II owners re status of generic improved chugging load model Owners requested to justify delay in program & investigate alternatives
ANDERSON, C J Generic Issues Branch 80/12/22 4pp 07486 14

B101140955 Summary of Dec 1980 meeting w/Mark II owners group. Q&A MIT, E&H, Bechtel & Ebasco Svcs, Inc re suppression pool temp limits List of attendees & handouts encl
SU, T M Generic Issues Branch 80/12/30 41pp 07457 063

B10116037 Requests substantial of risk assessment study final rept for
NRC to commence review of FSAR Areas for discussion should
include emergency preparedness re special institutions &
cooling water supply
TEDESCO, R. L. Assistant Director for Licensing 81/01/03 2pp
07471 161

B101306037 Summary of B01209 meeting w/uttl in Pottstown, PA re risk
evaluation study for facility
SELLS, D. Licensing Branch 2 81/01/14 4pp. 07583 001.

B101300144 Requests review of Amend 24 to PSAR
SELLS, D. Licensing Branch 2 81/01/14. 1p 07582 122

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B10102 & by applicants as part of FSAR
EISENHUT, D. G. Division of Licensing 80/11/13 2pp

G Adjudicatory correspondence

B101160211 Forwards City Council of Philadelphia B00529 Resolution 169
demanding const on facility be halted CLs should be refused
due to water shortage & lack of safety guarantee.
COHEN, D. Philadelphia, PA 81/01/03 3pp 07470 063.

H General correspondence

B101060999 Responds to B01215 ltr re preparation of EIS for facility
Applicants for CL must submit environ rept prior to OL
issuance
HANSLER, Q. M. Assistant Director for Licensing 80/12/16. 2pp
07401 086

B101050059 Expresses gratitude for hearing arranged onsite & urges Div
of Licensing not to grant license as plant constitutes
health & safety hazard Editorials encl
ANTHONY, R. L. Friends of the Earth. 80/12/23 6pp 07376 282

B101070621 Responds to B01029 ltr re leakage of river water into unit
containment Long-term generic actions described in encl IE
Bulletin B0-24 will be taken to preclude recurrence at other
plants
EISENHUT, D. G. Division of Licensing. 80/12/23 1p. 07414 157

B101070372 Requests that OL be denied
WEILER, J. Affiliation Unknown 81/01/01 1p 07309 001

B101306021 Responds to B01121 ltr forwarding B Irvine & J Williams
B00528 ltr opposing Point Pleasant Diversion Project pumping
station & operation of facilities. Responsibility for DE
River water matters is vested in DE River Basin Commission
DIRKS, W. J. Office of the Executive Director for Operations
81/01/06 3pp 07579 310.

--B101300033 Forwards J Williams & B Irvine B00528 ltr opposing operation
of facilities, originally forwarded by B00707 ltr Requests
response
WILLIAMS, H. A. Senate. 80/11/21. 2pp. 07579. 323

I Financial information

B012160144 Forwards SEC Form 10-Q, Quarterly Financial Rept & supporting
mgmt comments, in response to NRC 790921, 1109 & B00011
requests for info re significant financial developments
affecting utility in respect proceeding
CONDOU, V. H. General Public Utilities 80/11/26. 3pp

--B012160154 Quarterly Financial Rept Sept 1980 & supporting mgmt
comments
* General Public Utilities 80/11/14. 44pp.

Q Inspection reports, IE Bulletins & correspondence

B101070398 Forwards Suppl 1 to IE Info Notice B0-29, "Broken Studs on
Terry Turbine Steam Inlet Flange" No written response
required
GRIER, B. H. Region 1, Philadelphia, Office of the Director
80/11/26 1p 07414 080

B101050118 Forwards IE Info Notice B0-43, "Failures of Con-
Level Monitor for Scram Discharge Val at Dresden Unit 2
Response required
GRIER, B. H. Region 1, Philadelphia, Office of the Director
80/12/05 1p 07376 335

B101060123 Forwards IE Info Notice B0-45, "Potential Failure
Backup Manual Scram Capability" No response required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
80/12/17 1p 07397 332

B101070055 Forwards Suppl 4 to IE Bulletin B0-17, "Failure
Control Rods to Fully Insert During Scram at BWR." No
written response required
GRIER, B. H. Region 1, Philadelphia, Office of the Director
80/12/18 1p 07414 029.

B101190820 Forwards IE Bulletin B0-25, "Operating Problems
Rock Safety-Relief Valves at BWRs." No response required
GRIER, B. H. Region 1, Philadelphia, Office of the Director
80/12/19 1p 07469 317

B101210210 Responds to IE Bulletin B0-23, "Failures of Bol-
Mfg by Valcor Engineering Corp." No Valcor valves used, &
safety-related function OE review of NSSS sys has not been
completed Response will be delayed until B10228
KEMPER, J. B. Philadelphia Electric Co 80/12/26. 1p.

S. Reportable occurrences, LERs & related correspondence

B101070369 Final deficiency rept, originally reported on B0-
bolts, nuts & studs obtained from unapproved sources. Cause
by lack of proper QA review. Unacceptable bolting matl to
replaced
KEMPER, J. B. Philadelphia Electric Co. 80/12/30 3pp.

B101230434 Deficiency Rept 29 re metal potential loss of s
grounding of flexible metal conduit, preventing reactor
protection sys proper operation. OE rept encl. Flexible
conduit to be properly grounded per OE instructions.
KEMPER, J. B. Philadelphia Electric Co 81/01/13. 3pp.

B101260500 Interim deficiency rept re Deficiency 27, improv
reactor pressure vessel safe ends, initially reported B01
OE evaluating weld acceptability. Final rept will be
submitted by B10415
KEMPER, J. B. Philadelphia Electric Co. 81/01/16. 2pp.

T Hearing transcripts on non-antitrust matters

B101070324 Forwards B01209 transcripts of public meeting &
technical presentation of facility risk assessment. Also
forwards B01209 viewpoints re technical presentation.
SELLS, D. E. Operating Reactors Branch 2. 81/01/03. 3pp

--B101070327 Transcript of B01209 afternoon technical pres
Pottstown, PA Presents facility risk assessment study b
util Pg 1-123.
* Commissioners. 80/12/09 127pp. 07411: 190.

--B101070332 Transcript of B01209 evening public meeting f
Pg 1-122.
* Commissioners. 80/12/09. 124pp. 07412: 020.

DOCKET 90-333 LIMERICK GENERATING STATION, UNIT 2

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants
summary of B01112 meeting re implementation of guidance
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D. G. Division of Licensing 80/11/26. 8pp.

B101220157 Summary of B01210 meeting w/Hark II owners re s
generic improved chugging load model. Owners requested to
justify delay in program & investigate alternatives.
ANDERSON, C. J. Generic Issues Branch. 80/12/22. 4pp.

B101140955 Summary of Dec 1980 meeting w/Hark II owners gr
MIT, S&W, Bechtel & Ebasco Svcs, Inc re suppression pool te
limits. List of attendees & handouts encl.
SU, T. H. Generic Issues Branch. 80/12/30. 41pp. 07457

37 Requests submittal of risk assessment study final rept for commence review of FSAR Areas for discussion should emergency preparedness re special institutions & water supply
O.R.L. Assistant Director for Licensing. 81/01/05 2pp.
161.

37 Summary of 801209 meeting w/util in Pottstown, PA re risk study for facility
D. Licensing Branch 2 81/01/14 4pp 07583 001

44 Requests review of Amend 24 to PSAR.
D. Licensing Branch 2 81/01/14 1p. 07582.122

ity, medical, emergency & fire protection plans

87 Ltr to all licensees of operating reactor plants, CP holders applicants. Revised radiological emergency response must be submitted by licensees within 60 days of & by applicants as part of FSAR.
UT, D.O. Division of Licensing 80/11/13 2pp.

icatory correspondence

11 Forwards City Council of Philadelphia 800529 Resolution 169 ing const on facility be halted DLs should be refused water shortage & lack of safety guarantee.
D. Philadelphia, PA. 81/01/08. 5pp 07470-063

al correspondence

09 Responds to 801215 ltr re preparation of E18 for facility. ants for DL must submit environ rept prior to DL
R.Q.M. Assistant Director for Licensing 80/12/16 2pp
086

59 Expresses gratitude for hearing arranged onsite & urges Div ending not to grant license as plant constitutes & safety hazard Editorials encl.
V.R.L. Friends of the Earth. 80/12/23 6pp. 07376 282

72 Requests that DL be denied.
J. Affiliation Unknown 81/01/01 1p. 07309.001

21 Responds to 801121 ltr forwarding B Irvine & J Williams ltr opposing Point Pleasant Diversion Project pumping n & operation of facilities. Responsibility for DE water matters is vested in DE River Basin Commission W.J. Office of the Executive Director for Operations
06. 5pp 07379 318

0033 Forwards J Williams & B Irvine 800328 ltr opposing operation facilities. originally forwarded by 800707 ltr. Requests on-site
JAMS, H.A. Senate. 80/11/21. 2pp. 07379:323

cial information

44 Forwards SEC Form 10-Q. Quarterly Financial Rept & supporting ments. in response to NRC 790921, 1109 & 800811 ts for info re significant financial developments ing utils in restart proceeding
V.H. General Public Utilities. 80/11/26. 3pp.

0154 Quarterly Financial Rept Sept 1980 & supporting mgt ents.
General Public Utilities. 80/11/14 44pp.

ction reports, IE Bulletins & correspondence

98 Forwards Suppl 1 to IE Info Notice 80-29. "Broken Studs on Turbine Steam Inlet Flange." No written response
B.H. Region 1, Philadelphia, Office of the Director
26. 1p. 07414-080.

18 Forwards IE Info Notice 80-43. "Failures of Continuous Water Monitor for Scram Discharge Val at Dresden Unit 2 " No response required.
B.H. Region 1, Philadelphia, Office of the Director.
05 1p. 07376-335

23 Forwards IE Info Notice 80-45. "Potential Failure of BWR Manual Scram Capability." No response required
B.H. Region 1, Philadelphia, Office of the Director
17. 1p. 07397:332

8101070055 Forwards Suppl 4 to IE Bulletin 80-17. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR " No written response required
GRIER, B.H. Region 1, Philadelphia, Office of the Director
80/12/18. 1p 07414 023

8101150800 Forwards IE Bulletin 80-25. "Operating Problems W/Target Rock Safety-Relief Valves at BWRs." No response required
GRIER, B.H. Region 1, Philadelphia, Office of the Director
80/12/19 1p 07465:317

8101210210 Responds to IE Bulletin 80-23. "Failures of Solenoid Valves Hfg by Valcor Engineering Corp." No Valcor valves used in safety-related function GE review of NSSG sys has not been completed Response will be delayed until 810228.
KEMPER, J.S. Philadelphia Electric Co 80/12/26. 1p 07468 329

S Reportable occurrences, LEAs & related correspondence

8101070369 Final deficiency rept. originally reported on 800826, re ASME bolts, nuts & studs obtained from unapproved sources Caused by lack of proper QA review Unacceptable bolting matl to be replaced
KEMPER, J.S. Philadelphia Electric Co 80/12/30 5pp. 07414 127

8101230434 Deficiency Rept 29 re metal potential loss of solid metallic grounding of flexible metal conduit, preventing reactor protection sys proper operation GE rept encl Flexible conduit to be properly grounded per GE instructions
KEMPER, J.S. Philadelphia Electric Co. 81/01/13 3pp. 07308 001

8101260500 Interim deficiency rept re Deficiency 27, improper welding of reactor pressure vessel safe ends, initially reported 801218. GE evaluating weld acceptability. Final rept will be submitted by 810415
KEMPER, T.S. Philadelphia Electric Co. 81/01/16 2pp. 07308 001

T Hearing transcripts on non-antitrust matters

8101070324 Forwards 801209 transcripts of public meeting & util technical presentation of facility risk assessment Also forwards 801209 viewgraphs re technical presentation.
SELLS, D.E. Operating Reactors Branch 2 81/01/05 3pp. 07411 187

--8101070327 Transcript of 801209 afternoon technical presentation in Pottstown, PA Presents facility risk assessment study by util Pp 1-125
* Commissioners 80/12/09 127pp 07411.190

--8101070332 Transcript of 801209 evening public meeting in Pottstown, PA Pp 1-122
* Commissioners 80/12/09 124pp 07412-020

DOCKET 50-334 HOPE CREEK NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D.O. Division of Licensing. 80/11/26 8pp

8101190794 Forwards summary of 801210 meeting w/util re util mgt reorganization List of attendees encl.
CARLEBON, R.Y. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/23 3pp 07473-078.

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR
EISENHUT, D.O. Division of Licensing. 80/11/13 2pp

J Insurance & indemnity information

8101270738 Forwards Endorsement 42 to NELIA Policy NF-230 & Endorsement 34 to MAELU Policy NF-90
CORREA, M.A. Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc
Div 81/01/22 3pp 07548 050

O Inspection reports, IE Bulletins & correspondence

B010270779 Ack receipt of B01014 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-354/79-04
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/11/23 1p 07368 335

--B010290781 Suppls response to NRC B003821 ltr re violations noted in IE Insp Rept 50-354/79-04 Corrective actions weld buildups being evaluated to determine required measures
MARTIN, T J Public Service Electric & Gas Co. of New Jersey 80/10/14 1p 07560 336

B010700396 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange " No written response required
CRIER, B H Region 1, Philadelphia, Office of the Director 80/12/26 1p 07414 083

B01050121 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Scram Discharge Vpl at Dresden Unit 2 " No response required
CRIER, B H Region 1, Philadelphia, Office of the Director 80/12/05 1p 07376 339

B01060145 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Scram Capability " No response required
CRIER, B H Region 1, Philadelphia, Office of the Director 80/12/17 1p 07391 265

B01070050 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of 76 of 105 Control Rods to Fully Insert During Scram at BWR " No written response required
CRIER, B H Region 1, Philadelphia, Office of the Director 80/12/18 1p 07414 017

B01050795 Forwards IE Bulletin 80-25, "Operating Problems W/Target Rock Safety-Relief Valves at BWRs " No response required
CRIER, B H Region 1, Philadelphia, Office of the Director 80/12/19 1p 07465 312

R Periodic operating reports & related correspondence

B012190521 Forwards rept entitled "Monitoring of Liquefied Natural Gas & Liquefied Petroleum Gas Shipping & Const Activities on DE River"
MITTL, R L Public Service Electric & Gas Co. of New Jersey 80/12/15 2pp 07285 322

--B012190528 "Monitoring of Liquefied Natural Gas & Liquefied Petroleum Gas Shipping & Const Activities on DE River "
Public Service Electric & Gas Co. of New Jersey 80/11/30 36pp 07285 324

E Reportable occurrences, LERs & related correspondence

B01050491 Ack receipt of util B01024 interim deficiency rept re primary containment relief valves at facility
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/11/07 1p 07387 275

--B01050497 Interim deficiency rept re primary containment relief valves at facility, initially reported on B00326 Expected conclusion of investigation has been postponed until B01205
MARTIN, T J Public Service Electric & Gas Co. of New Jersey 80/10/24 2pp 07387 276

B01060480 Significant deficiency rept, originally reported on B00326, re primary containment vacuum relief valves Concludes that subj bolting is designed within appropriate stress allowances & conforms w/spec 10855-M-150101
MARTIN, T J Public Service Electric & Gas Co. of New Jersey 80/12/03 2pp 07396 316

DOCKET 50-355 HOPE CREEK NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

B010220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports "
EISENHUT, D G Division of Licensing 80/11/26 0pp

B010190794 Forwards summary of B01210 meeting w/util re util mgt reorganization List of attendees encl
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/23 3pp

F Security, medical, emergency & fire protection plans

B01090387 Ltr to all licensees of operating reactor plants, CP hold & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B01012 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing 80/11/13 2pp

J Insurance & indemnity information

B01070738 Forwards Endorsement 42 to NELIA Policy NF-230 & Endorsement 34 to MALLU Policy MF-90
CORREA, M A Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 81/01/22 3pp

O Inspection reports, IE Bulletins & correspondence

B010700396 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange " No written response required
CRIER, B H Region 1, Philadelphia, Office of the Director 80/11/26 1p 07414 083

B01050121 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Scram Discharge Vpl at Dresden Unit 2 " No response required
CRIER, B H Region 1, Philadelphia, Office of the Director 80/12/05 1p 07376 339

B01060145 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Scram Capability " No response required
CRIER, B H Region 1, Philadelphia, Office of the Director 80/12/17 1p 07391 265

B01070050 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of 76 of 105 Control Rods to Fully Insert During Scram at BWR " No written response required
CRIER, B H Region 1, Philadelphia, Office of the Director 80/12/18 1p 07414 017

B01050795 Forwards IE Bulletin 80-25, "Operating Problems W/Target Rock Safety-Relief Valves at BWRs " No response required
CRIER, B H Region 1, Philadelphia, Office of the Director 80/12/19 1p 07465 312

R Periodic operating reports & related correspondence

B012190521 Forwards rept entitled "Monitoring of Liquefied Natural Gas & Liquefied Petroleum Gas Shipping & Const Activities on DE River."
MITTL, R L Public Service Electric & Gas Co. of New Jersey 80/12/15 2pp 07285 322

--B012190528 "Monitoring of Liquefied Natural Gas & Liquefied Petroleum Gas Shipping & Const Activities on DE River."
Public Service Electric & Gas Co. of New Jersey 80/11/30 36pp 07285 324

E Reportable occurrences, LERs & related correspondence

B01050491 Ack receipt of util B01024 interim deficiency rept re primary containment relief valves at facility
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/11/07 1p 07387 275

--B01050497 Interim deficiency rept re primary containment relief valves at facility, initially reported on B00326 Expected conclusion of investigation has been postponed until B01205
MARTIN, T J Public Service Electric & Gas Co. of New Jersey 80/10/24 2pp 07387 276

DOCKET 50-356 UNIV OF ILLINOIS LOPRA RESEARCH REACTOR

O Inspection reports, IE Bulletins & correspondence

B01060368 Forwards IE Insp Repts 50-151/80-03 & 50-356/80-03 on B01117-19 & notice of violation
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Supp Branch 80/12/10 2pp 07470 352

--B01060374 Notice of violation from insp on B01117-19
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/12/09 1p 07470 354

--B01150382 IE Insp Repts 90-191/80-03 & 50-756/80-03 on 801117-19
Noncompliance noted nuclear reactor committee meetings
exceeded specified frequency
RIGGMAN, W R . BOONE, J M Region 3, Chicago, Office of the
Director 80YD, D C Region 3, Chicago, Reactor Operations Nuclear
Support Branch 80/12/07 5pp 07470 359

CKET 50-350 WILLIAM H ZIMMER NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

BC08110130 Notification of B0C806-07 meeting w/OE owners group, LaSalle
& Zimmer owners group representative & GE in Bethesda, MD
for briefing on basis for symptom-oriented guidelines &
applicability in evaluating event procedures.
SIEGEL, B L Procedures & Test Review Branch 80/07/28 2pp
06278 117

B01220466 Ltr to all power reactor licensees & applicants forwarding
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp.

B01050549 Confirms B01216 meeting in Cincinnati, OH to discuss
evaluation of util regulatory performance re facility
KEPPLER, J G Region 3, Chicago, Office of the Director 80/12/10
1p 07387 177.

B01190503 Ltr to all BWR applicants for OL re BWR scram discharge sys
safety evaluation & requirements Rept specifying acceptable
basis for continued BWR plant operation & design criteria
for scram discharge vol encl.
TEDESCO, R L Assistant Director for Licensing 80/12/22 2pp

--B01190514 Forwards generic safety evaluation re BWR scram discharge
sys Review identified two addl requirements to those
proposed by owners group re scram discharge vol designs Rept.
should be transmitted to licensee applicants
CHECK, P S Assistant Director for Plant Systems 80/12/01 2pp
07183 001

B01200157 Summary of B01210 meeting w/Mark II owners re status of
generic improved chugging load model Owners requested to
justify delay in program & investigate alternatives
ANDERSON, C J Generic Issues Branch 80/12/22 4pp 07486 143

B01140955 Summary of Dec 1980 meeting w/Mark II owners group, GE, ENL,
MIT, S&W, Bechtel & Babco Svcs, Inc re suppression pool temp
limits. List of attendees & handouts encl
BU, T M Generic Issues Branch 80/12/30 41pp

B01120197 Advises of scheduled B10030 fuel load data, per ARC telcon
BORGMANN, E A Cincinnati Gas & Electric Co. 81/01/07 1p.
07445 261.

B01140272 Forwards proprietary & nonproprietary versions of "Environ
Qualification of Safety-Related Electrical Equipment." Vols
1-3 Affidavit for withholding encl. Proprietary info withheld
(ref 10CFR2 7901)
BORGMANN, E A Cincinnati Gas & Electric Co 81/01/07. 4pp.
07537 164.

--B01140276 Nonproprietary version of "Environ Qualification of
Safety-Related Electrical Equipment." Vol 1-3
* Cincinnati Gas & Electric Co. 81/01/07. 1000pp. 07537 16B

B01210625 Forwards House Rept 96-1452, "Evaluating Nuclear Util's
Performance: NRC Oversight." W/o encl.
HEISHMAN, R F. Region 3, Chicago, Reactor Operations Nuclear Support
Branch. 81/01/08 1p 07489 249

B01270821 Forwards NRC position re toxic chemical traffic on US Route
32 near facility site. Position based on evaluation that
Revision 60 to FSAR is inadequate
TEDESCO, R L Assistant Director for Licensing 81/01/14. 4pp.
07549 094.

B01300602 Forwards request for addl info for NRC review of facility
water cleanup & condensate cleanup sys against Revision 1 of
Reg Guide 1.56, "Maint of Water Purity in BWRs."
TEDESCO, R L Assistant Director for Licensing. 81/01/14. 3pp
07584 355.

B01300751 Requests commitment to special low power test program for
facility to comply w/THJ task action item f Q.1. PWR test re
simulated loss of ac power is feasible & should be
performed on BWRs.
TEDESCO, R L Assistant Director for Licensing. 81/01/14. 3pp
07587 032

B01270642 Forwards supplemental info re seismic qualification of
equipment
BERGMANN, E A Cincinnati Gas & Electric Co 81/01/20 1p.
07544 099

--B01270646 "Equipment Qualification"
* Sargent & Lundy, Inc 81/01/20 375pp 07544 100

--B01270651 "Zimmer Seismic Qualification Review Team Evaluation/
Qualification Status Rept"
BROCATO, V J, MCCORMACHY, W J Nuclear Technology, Inc (Nutech)
CGE-03-144 80/12/10 29pp 07545 105

--B01270655 "Nuclear Safety-Related Equipment List for Zimmer Nuclear
Generating Station"
BROCATO, V J, MCCORMACHY, W J, RICCARDELLA, P Nuclear Technology,
Inc (Nutech) CGE-03-087 80/04/15 98pp 07545 134

F Security, medical, emergency & fire protection plans

B01090387 Ltr to all licensees of operating reactor plants, CP holders
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B01062 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13. 2pp

B01070515 Releases public version of "Preliminary Evaluation Time
Study of Plume Exposure Emergency Planning Zone Around
WM Zimmer Nuclear Power Station, Unit 1"
FELTON, J M Division of Rules and Records 80/12/01. 1p
07309 001

--B01070529 Forwards public version of "Preliminary Evaluation Time
Study of Plume Exposure Emergency Planning Zone Around
WM Zimmer Nuclear Power Station, Unit 1"
FELTON, J M Cincinnati Gas & Electric Co 80/08/18 1p
07309 001

--B01070536 Public version of "Preliminary Evaluation Time Study of
Plume Exposure Emergency Planning Zone Around WM Zimmer
Nuclear Power Station, Unit 1"
* Stone & Webster Engineering Corp 80/08/31. 30pp 07309 001

G Adjudicatory correspondence

B01060913 Order granting applicant B01224 motion for extension until
B01026 to file answers or objections to NRC B01209 second
interrogatories. NRC raised no objection
BECHHOEFER, C Atomic Safety and Licensing Board Panel 80/12/30
2pp 07401 090

B01230148 Order granting extension until 810120 to answer
interrogatories on Contention 13 Intervenor Miami Valley
Power Project shall hand deliver answer & notify applicants
of identity of witnesses by telephone w/ Certificate of Svc
BECHHOEFER, C Atomic Safety and Licensing Board Panel 81/01/16
4pp 07512 022

B01290726 Answers of Miami Valley Power Project to applicant seventh
set of interrogatories re witnesses & decommissioning costs
Analysis of decommissioning & premature shutdown costs of
plants & certification of svc encl Related correspondence
FELDMAN, J H Miami Valley Power Project 81/01/20 47pp
07567 117

B01280062 Forwards applicant responses to NRC second set of
interrogatories re evacuation time study. Offers to meet
w/NRC to discuss emergency plan or any other questions.
CONNOR, T B Connor, Moore & Corber. 81/01/23 1p 07555 117

--B01280077 Response to NRC second set of interrogatories re B&W
evacuation time study Prof qualifications & Certificate of
Svc encl
WEISS, L S Stone & Webster Engineering Corp WEISS, L S
Cincinnati Gas & Electric Co 81/01/23 21pp. 07555 11B

B01290740 Confirms agreement re potential witnesses R Estes & T Hernan
depositions to be given in Cincinnati, OH on B010204. Witness
prof qualifications & other documents to be provided. Related
correspondence
WETTERHAM, M J Connor, Moore & Corber 81/01/27. 2pp. 07567 348

B101070616 Forwards request for additional financial info to expedite public hearing. Util should provide detailed itemized estimate of cost of constructing & installing items resulting from TMI accident.
TEDESCO, R L Assistant Director for Licensing 80/12/19 3pp
07419 315

B101290272 Forwards responses to financial questions per B01219 ltr BORGMANN, E A Cincinnati Gas & Electric Co 81/01/26 7pp
07567 164

3. Inspection reports, IE Bulletins & correspondence

B101050289 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No response required.
KEPPLER, J G Region 3, Chicago, Office of the Director 80/10/30 2pp 07389 268

B101060125 Forwards IE Circular 80-23, "Potential Defects in Delmit Power Sys Emergency Generators." No written response required.
KEPPLER, J G Region 3, Chicago, Office of the Director 80/10/31 1p 07397 335

B101060554 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response is required.
KEPPLER, J G Region 3, Chicago, Office of the Director 80/10/31 2pp 07401 173

B101060356 Forwards IE Info Notice 80-41, "Failure of Suing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required.
KEPPLER, J G Region 3, Chicago, Office of the Director. 80/11/10 2pp 07392 076

B10120066 Forwards IE Insp Rept 50-358/80-23 on B01001-24. No non-compliance noted.
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/11/13 2pp 07446 026

--B101120070 IE Insp Rept 50-358/80-23 on B01001-24. No noncompliance noted. Major areas inspected previously identified items, bulletin & circular followup & maint procedures review.
DANIELS, F T, GWYNN, T P, WERNICK, R F Region 3, Chicago, Office of the Director. 80/11/10 5pp 07446 028

B101060497 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Written response required.
KEPPLER, J G Region 3, Chicago, Office of the Director 80/11/14 2pp 07391 226

B101050557 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Bcrum Discharge Vol at Dresden Unit 2." No response required.
KEPPLER, J G Region 3, Chicago, Office of the Director. 80/12/05 2pp 07390 327

B101290558 Forwards IE Insp Rept 50-358/80-24 on B01103-07, 12-14, 17-21, 24-26 & 28. No noncompliance noted.
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/12/16 2pp 07575 278

--B101290563 IE Insp Rept 50-358/80-24 on B01103-07, 12-14, 17-21, 24-26 & 28. No noncompliance noted. Major areas inspected: fuel receipt & storage, design control & preoperational test program implementation controls.
DANIELS, F T, GWYNN, T P, WERNICK, R F Region 3, Chicago, Office of the Director. 80/12/10. 6pp. 07575 280.

entire Failure of BWR response
the Director. 80/12/17.

ure of Control
nse
or 80/12/18

ms W/Target
ed
r 80/12/19.

approval is obtained
KEPPLER, J G Region 3, Chicago, Office of the Director 80/12/24 2pp 07443 245

B101150901 Responds to IE Bulletin 80-21 re valve yokes supplied by Malcolm Foundry Co. Inc. Interim responses from vendors indicate no mat'l from Malcolm Foundry Co. Inc. was used at facility.
BORGMANN, E A Cincinnati Gas & Electric Co 80/12/29 1p 07464 143

B101150908 Responds to IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (Oct 17, 1980 Indian Point 2 Event)." Facility does not have open cooling water sys inside containment.
BORGMANN, E A Cincinnati Gas & Electric Co 80/12/29 1p 07464 144

B101060278 Ack receipt of B01126 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-358/80-22.
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/30 1p. 07392 017

--B101060281 Responds to NRC B01031 ltr re violations noted in IE Insp Rept 50-358/80-22. Corrective actions INX support implementation schedule established.
BORGMANN, E A Cincinnati Gas & Electric Co. 80/11/26 4pp. 07392 018

B101210635 Ack receipt of B01204 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-358/80-16. Requests schedule of anticipated completion of review & mod of procedures.
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch. 81/01/07 2pp 07488 114.

--B101210630 Updates response to IE Insp Rept 50-358/80-16. Twelve procedures scheduled for revision completed & ready for issuance. All revisions will be completed by B10115.
BORGMANN, E A Cincinnati Gas & Electric Co. 80/12/04. 2pp 07400 116.

5 Reportable occurrences, LERs & related correspondence

B101210214 Ack receipt of util B00919 ltr informing of corrective actions taken in response to NRC B00904 immediate action ltr re mat'l mfg by Tech-Sil, Inc. Confirms B01218 telcon authorizing resumption of work involving mat'l at facility.
KEPPLER, J G Region 3, Chicago, Office of the Director 81/01/09 2pp 07488 333

B101230476 Interim deficiency rept re use of 1-inch diameter Hilti nut-bolt anchors. Forty-four supports identified as utilizing 1-inch expansion anchors w/embedded lengths of B0. Review will be completed by mid-Mar. w/final rept by B10331.
BORGMANN, E A Cincinnati Gas & Electric Co 81/01/12. 1p. 07511 129

Docket 50-361 BAW DOWDFRE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

B101280466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D O. Division of Licensing. 80/11/26. 8pp

B101070232 Requests addl info re util B01027 application for review of proposed license for new fuel storage. Util should describe controls used to ensure conformance w/fuel storage pattern & that subcritical conditions will be maintained.
STEVENSCH, R L Uranium Fuel Licensing Branch. 80/12/17. 1p. 07414 295

B101140227 Approves B00903 request to withhold proprietary version CEN-135 (s) -P (ref 10CFR2.790).
MIRAOLIA, F Licensing Branch 3. 80/12/31 2pp. 07309 001

B101140234 Approves B01118 request to withhold proprietary version CEN-140(S)-P, "Data Transmittal for Southern CA Edison Fuel Audit Analysis." (ref 10CFR2.790).
MIRAOLIA, F Licensing Branch 3. 80/12/31. 2pp. 07308 001.

B101160024 Forwards safety evaluation & notice of issuance & availability of SER, NUREG-0712.
MIRAOLIA, F. Licensing Branch 3. 80/12/31. 4pp. 07469 138.

--B101160030 Notice of issuance & availability of SER re geologic & seismic aspects, NUREG-0712
BUCKLEY, B Licensing Branch 3 80/12/31 1p. 07469 142

B101190280 Approves 800913 request to withhold CEN-127(S)-P (ref 10CFR2 790) Document contains trade secrets, confidential, commercial & financial info
MIRAGLIA, F Licensing Branch 3 81/01/06 2pp 07476 091

B101130093 Forwards responses to numerous open items & questions identified in NRC 801107 ltr & meetings w/NRC during wk of 801215 Direct distribution will be made as part of Amend 23 distribution per svc list provided in utl 801029 ltr.
BASKIN, K P. Southern California Edison Co 81/01/09 200pp 07456 022.

B101200102 Notification of 810115 meeting w/util, C-E & Dechtel in Bethesda, MD to discuss explosion probabilities
RADD, H Licensing Branch 3 81/01/09 3pp. 07486 357

B101160110 Forwards responses to open items & questions which will become part of Amend 23 distribution, per 801107 ltr
BASKIN, K P. Southern California Edison Co 81/01/14 54pp 07470 104

B101210621 Recommends that meeting w/util be held in mid-Mar 1981 to discuss licensee qualification
TEDESCO, R L Assistant Director for Licensing 81/01/14 1p 07489 240

--B101210630 Recommends review of util mgt & use of consultants in improving performance in areas of regulatory difficulty
MOSELEY, H C. Division of Reactor Operations Inspections 80/12/31 2pp 07489 241.

B101220187 Forwards proprietary version of CEN-148(S)-P, "Functional Design Spec for Control Element Assembly Calculator" Rept withheld (ref 10CFR2 790) Affidavit for withholding encl
BASKIN, K P. Southern California Edison Co 81/01/19 6pp. 07500 022

B101220180 Forwards responses to open items & questions in NRC 801107 ltr re reactor internals analyses, preservice & inservice insps, sump vortex test, snubber insp & engineered safety features & auxiliary feedwater fracture toughness
BASKIN, K P. Southern California Edison Co 81/01/20 58pp. 07495 284

C. Utility Environmental Report (ER), amends & correspondence

B101130235 Forwards affidavit attesting to fact that direct distribution of Amend 6 to environ rept is per modified svc list Bvc list modified to include two members of ASLD.
Affidavit of Bvc encl.
BASKIN, K P. Southern California Edison Co 81/01/06 6pp. 07491 247

D. NRC Draft/Final Environmental Statements, suppl & correspondence

B101270130 Forwards notice of availability of suppl to DEB for facilities Requests FR publication.
* Office of Nuclear Reactor Regulation, Director. 81/01/16 1p 07575 190

--B101290134 Notice of availability of suppl to DEB for facilities
MIRAGLIA, F J. Licensing Branch 3 81/01/16 3pp. 07575 191

B101270591 Verifies official filing of EIS for facility FR notice of availability scheduled for B10123 Public review period will terminate on 810309
WILSON, K L. Environmental Protection Agency. 81/01/21 1p 07549 064.

B101300408 Responds to NRC 810116 request for comments on OES suppl. No significant impacts found to electric power, natural gas & oil pipeline industries
HEINEMANN, J M. Federal Energy Regulatory Commission. 81/01/23 1p 07582 354.

B101290455 SUPPLEMENT TO DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF SAN ONOFRE NUCLEAR GENERATING STATION, UNITS 2 & 3
* Office of Nuclear Reactor Regulation, Director. NUREG-0490. 81/01/31 37pp

E. NRC Safety Evaluation Report (SER), suppl & correspondence

B101060131 Informs of full power SER to be issued in Feb 1981
Geosciences Branch input scheduled for 801203 Competing priorities for reviewers & mgt have caused delays in completing facility input
RADD, H Licensing Branch 3 80/12/08 5pp 07391 254.

B101200514 Forwards draft SER for facilities re non-TMI related Outstanding items include seawall design & classification, high energy line break, load combination methods & independent piping analysis (W/O encl)
TEDESCO, R L. Division of Licensing 81/01/08 3pp 07486 357

B101140516 Forwards Revision 1 to listing of SER open items & open items resolved as of 810112
BASKIN, K P. Southern California Edison Co 81/01/12 13pp 07309 601

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR
EISENHUT, D G. Division of Licensing 80/11/13 2pp

B101100075 Requests evaluation of potential effects of earthquake emergency responses, including earthquakes which either initiate or follow initiation of accidents First instance should be included in revised emergency plan
TEDESCO, R L Assistant Director for Licensing 80/12/17 07309 001

B101100838 Informs that licensee must conduct emergency exercise one yr from 810401 or prior to issuance of D. Requests schedule of drills & exercises
EMMETT, R H Region 3, San Francisco, Office of the Director 80/12/19 1p 07443 257.

B101290173 Forwards facility emergency planning info to be made publicly available W/O encl
SCUDER, J L Division of Rules and Records 81/01/23 1p 07575 202

G. Adjudicatory correspondence

B101140038 Forwards Commission 801210 memorandum & order & statement of policy re litigation on TMI-2 issues in CL proceedings
CHANDLER, L J Hearing Branch 1. 80/12/29 1p 07460 234

--B101140046 Memorandum & order amending encl 800620 statement "Further Commission Guidance for Power Reactor CLs"
CHILK, S J Office of the Secretary of the Commission 81/01/16 3pp 07460 235

--B101140053 "Further Commission Guidance for Power Reactor CLs" statement of policy Ahearn dissenting views encl.
CHILK, S J Office of the Secretary of the Commission 81/01/16 14pp 07460 238

B101230128 Notice of CP Buckley 810212 deposition in Rosemead seismology & geology of site
PIGOTT, D R Southern California Edison Co PIGOTT, D R & Gregory 81/01/15 2pp 07512 015

--B101230137 Notice of J Drue 810209 deposition in San Diego seismology & geology of site Certificate of Svc encl.
PIGOTT, D R Southern California Edison Co PIGOTT, D R Chickering & Gregory 81/01/15 3pp 07512 017

H. General correspondence

B101090742 Requests reopening of safety licensing hearings & in light of TMI incident
REICHENBERG, B Affiliation Unknown 79/04/02 2pp 07486 357

B101300256 Responds to EK Johnson ltr re location of facility Earthquake hazards are being re-reviewed in connection w/D applications for Units 2 & 3 Facilities meet NRC siting criteria
DIRKSH, W J Office of the Executive Director for Operations 81/01/15 3pp 07586 129.

X Utility Final Safety Analysis Report (FSAR) & amends

8101070525 Forwards affidavit of svc of Amend 22 to FSAR & Amend 4 to fire hazards analysis per encl svc list
BASKIN, K P Southern California Edison Co 80/12/30 3pp
07442 068

O Advisory Committee on Reactor Safeguards reports & correspondence

8101149574 Forwards SER re geology & seismology for review & comment
Review will allow ASLD hearing to proceed w/o encl
TELEFIO, R L Assistant Director for Licensing 80/12/31 1p
07476 115

P Operating license stage documents & correspondence

8101160524 Notification of 801218 meeting w/SEP owners group in
Bethesda MD re SEP program, schedule for licensee topic
completion & assignment of lead topics to plants
ROUSELL, W T Technical Support Branch 80/12/16 2pp

Q Inspection reports, IE Bulletins & correspondence

8101050454 Forwards IE Info Notice 80-43, "Failures of Continuous Water
Level Monitor for Steam Discharge Vol at Dresden Unit 2"
No response required
ENGELKEN, R H Region 5, San Francisco, Office of the Director
80/12/05 1p 07387 271

8101210626 Forwards IE Insp Rept 50-361/80-20 on 801103-07 No
noncompliance noted
SCED, H E Region 5, San Francisco, Fuel Facility & Materials Safety
Branch 80/12/12 2pp 07488 078

--8101210527 IE Insp Rept 50-361/80-20 on 801103-07 No noncompliance
noted Major areas inspected licensee action on previous insp
findings & preoperational testing procedures
FISHER, R F, CHILDS, M., WENSLAWSKI, F A Region 5, San Francisco,
Office of the Director 80/12/12 6pp 07468 080

8101150832 Forwards IE Info Notice 80-44, "Actuation of ECCS in
Recirculation Mode While in Hot Shutdown" No response
required
ENGELKEN, R H Region 5, San Francisco, Office of the Director
80/12/16 1p 07308 001

8101270517 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by
Malcolm Foundry Co. Inc." NRC will be notified if suspect
yokes were utilized upon written confirmation from
subvendor
BASKIN, K P Southern California Edison Co 81/01/05 1p
07543 352

8101300756 Ack receipt of 801223 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-361/80-18 &
50-362/80-11
SPENCER, Q S Region 5, San Francisco, Reactor Construction &
Engineering Support Branch 81/01/14 1p 07308 001

--8101300757 Responds to NRC 801202 ltr re violations noted in IE Insp
Repts 50-361/80-18 & 50-362/80-11 Corrective actions work
plan procedure/OC Instruction 400 has been revised to
strengthen procedural controls
ARENAL, A Southern California Edison Co 80/12/23 4pp
07308 001

--8101300763 Forwards IE Insp Repts 50-361/80-18 & 50-362/80-11 on
800923-26 & notice of violation
SPENCER, Q S Region 5, San Francisco, Reactor Construction &
Engineering Support Branch 80/12/02 2pp 07308 001

--8101300766 Notice of violation from insp on 800923-26.
SPENCER, Q S Region 5, San Francisco, Reactor Construction &
Engineering Support Branch 80/12/02 1p 07308 001

--8101300771 IE Insp Repts 50-361/80-18 & 50-362/80-11 on 800923-26
Noncompliance noted stainless steel piping Spools 25-81-045
& 046 of safety injection sys insulated despite residue on
external surfaces of piping
ECKHARDT, J H., HERNANDEZ, C Region 5, San Francisco, Office of the
Director MAYNES, R C Region 5, San Francisco, Reactor
Construction & Engineering Support Branch 80/12/01 7pp
07308 001

8101220180 Forwards responses to open items & questions in NRC 801107
ltr re reactor internals analyses, preserve & inservice
insps, sump vortex test, snubber insp & engineered safety
features & auxiliary feedwater fracture toughness.
BASKIN, K P Southern California Edison Co 81/01/20 58pp.
07495 284

S Reportable occurrences, IERs & related correspondence

8101210394 Final deficiency rept re ITE-0904d 480 V air circuit
breakers w/damaged trip coil wiring. Initially reported on
801219 Licensee will tie-wrap wires near gear reducer or put
wires inside spiral wiring harness
PAPAY, L T Southern California Edison Co 81/01/12 3pp
07489 074

8101270507 Final deficiency rept, originally reported on 801226, re
inadequate design of fuel transfer tube Multiple
longitudinal stiffener plates added between interface &
adjacent circumferential interface stiffener rings
PAPAY, L T Southern California Edison Co 81/01/16 3pp.
07566 326

V Operator Examinations

8101050376 Submits addl info re description of shift technical advisor
training program & plans for requalification training per
791031 request
MAYNES, J O Southern California Edison Co 80/12/30 4pp
07385 285

8101060313 Forwards "Shift Technical Advisor Training & Requalification
Program" & related info. in response to NRC 801031 ltr re
TMI action plan requirement
MAYNES, J O Southern California Edison Co 80/12/30 5pp.
07396 040

--8101060523 "Shift Technical Advisor Training & Requalification
Program"
Southern California Edison Co. 80/12/31 31pp 07396 049.

DOCKET 50-362 SAN JOSE NUCLEAR STATION, UNIT 3

A Application/construction stage documents & correspondence

810120446 Ltr to all power reactor licensees & applicants forwarding
summary of 801112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 0pp.

8101070232 Requests addl info re util 801027 application for revision
of proposed license for new fuel storage Util should
describe controls used to ensure conformance w/fuel storage
pattern & that subcritical conditions will be maintained.
STEVENSON, R L Uranium Fuel Licensing Branch 80/12/17 1p.
07414 295

8101140227 Approves 800903 request to withhold proprietary version of
CEN-125 (s) -P (ref 10CFR2.790).
MIRAGLIA, F. Licensing Branch 3 80/12/31 2pp 07309:001.

8101140234 Approves 801118 request to withhold proprietary version of
CEN-140(B)-P, "Data Transmittal for Southern CA Edison Fuel
Audit Analysis." (ref 10CFR2.790).
MIRAGLIA, F. Licensing Branch 3 80/12/31 2pp 07308:001

8101160024 Forwards safety evaluation & notice of issuance &
availability of SER, NUREG-0712
MIRAGLIA, F. Licensing Branch 3 80/12/31 4pp 07469:138

--8101160030 Notice of issuance & availability of SER re geologic &
seismic aspects, NUREG-0712.
BUCKLEY, B. Licensing Branch 3 80/12/31 1p. 07469:142.

8101190280 Approves 800813 request to withhold CEN-127(B)-P
(ref 10CFR2.790) Document contains trade secrets,
confidential, commercial & financial info
MIRAGLIA, F. Licensing Branch 3 81/01/06 2pp. 07476:091.

8101130093 Forwards responses to numerous open items & questions
identified in NRC 801107 ltr & meetings w/NRC during wk of
801215 Direct distribution will be made as part of Amend 23
distribution per svc list provided in util 801029 ltr.
BASKIN, K P Southern California Edison Co 81/01/09 200pp.
07456:022

010200102 Notification of B10115 meeting w/uttl, C-E & Bechtel in Bethesda, MD to discuss explosion probabilities
RODD, H Licensing Branch 3 B1/01/09 3pp 07486 352

010160110 Forwards responses to open items & questions which will become part of Amend 23 distribution, per B10107 ltr
BASKIN, K P Southern California Edison Co B1/01/14 34pp
07470 104

010210621 Recommends that meeting w/uttl be held in mid-Mar 1981 to discuss licensee qualification
TEDESCO, R L Assistant Director for Licensing B1/01/14 1p
07489 240

-010210630 Recommends review of util mgt & use of consultants in improving performance in areas of regulatory difficulty
MOSELEY, H C Division of Reactor Operations Inspections
80/12/31 2pp 07489 241

010220187 Forwards proprietary version of CEN-148(B)-P, "Functional Design Spec for Control Element Assembly Calculator " Rept withheld (ref JOCFR2 770) Affidavit for withholding encl
BASKIN, K P Southern California Edison Co B1/01/19 6pp
07500 022

010220180 Forwards responses to open items & questions in NRC B01107 ltr re reactor internals analyses, preservice & inservice
insp, pump vortex test, snubber insp & engineered safety features & auxiliary feedwater fracture toughness
BASKIN, K P Southern California Edison Co B1/01/20 58pp
07495 284

Utility Environmental Report (ER), amends & correspondence

010130235 Forwards affidavit attesting to fact that direct distribution of Amend 6 to environ rept is per modified svc list. Svc list modified to include two members of ASLB
Affidavit of Svc encl
BASKIN, K P Southern California Edison Co B1/01/06 6pp
07451 247

NRC Draft/Final Environmental Statements, supplis & correspondence

010290130 Forwards notice of availability of suppl to DEB for facilities. Requests FR publication
* Office of Nuclear Reactor Regulation, Director B1/01/16 1p
07575 190

-010290134 Notice of availability of suppl to DEB for facilities.
MIRALIA, F J Licensing Branch 3 B1/01/16 3pp 07575 191

010270591 Verifies official filing of EIS for facility FR notice of availability scheduled for B10123. Public review period will terminate on B10309
WILSON, K L Environmental Protection Agency B1/01/21 1p
07349 064

010300408 Responds to NRC B10116 request for comments on DEB suppl. No significant impacts found to electric power, natural gas & oil pipeline industries.
HEINEHANN, J M Federal Energy Regulatory Commission B1/01/20 1p
07582 354

010290455 SUPPLEMENT TO DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF SAN ONOFRE NUCLEAR GENERATING STATION, UNIT 2 & 3
* Office of Nuclear Reactor Regulation, Director NUREG-0490, B1/01/31 37pp.

NRC Safety Evaluation Report (SER), supplis & correspondence

01060141 Informs of full power SER to be issued in Feb 1981. Final Geosciences Branch input scheduled for B01208. Competing priorities for reviewers & mgt have caused delays in completing Facility input
RODD, H Licensing Branch 3 B0/12/08 3pp 07091 254

010200514 Forwards draft SER for facilities re non-TMI related issues. Outstanding items include seawall design & classification, high energy line break, load combination methods & independent piping analysis. W/o encl.
TEDESCO, R L Division of Licensing B1/01/08 3pp 07487 048

010140516 Forwards Revision 1 to listing of SER open items identifying open items resolved as of B10112
BASKIN, K P Southern California Edison Co B1/01/12 13pp
07309 001

F Security, medical, emergency & fire protection plans

0101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing B0/11/13 2pp

010160075 Requests evaluation of potential effects of earthquakes on emergency responses, including earthquakes which either initiate or follow initiation of accidents. First instance should be included in revised emergency plan
TEDESCO, R L Assistant Director for Licensing B0/12/17 4pp
07309 001

010160839 Informs that licensee must conduct emergency exercise within one yr from B10401 or prior to issuance of EL. Requests schedule of drills & exercises
ENGELKEN, R H Region 5, San Francisco, Office of the Director B0/12/19 1p 07443 257

0101290173 Forwards facility emergency planning info to be made publicly available. W/o encl
SOUDEK, J L Division of Rules and Records B1/01/23 1p
07575 202

G Adjudicatory correspondence

0101140038 Forwards Commission B01218 memorandum & order & revised statement of policy re litigation on TMI-2 issues in UL proceedings
CHANDLER, L J Hearing Branch 1 B0/12/24 1p 07460 234

0101290128 Notice of CP Buckley B10212 deposition in Rosemead, CA re seismology & geology of site
PIGOTT, D R Southern California Edison Co PIGOTT, D R Chickering & Gregory B1/01/13 2pp 07512 015

--0101230137 Notice of J Brune B10209 deposition in San Diego, CA re seismology & geology of site. Certificate of Svc encl
PIGOTT, D R Southern California Edison Co PIGOTT, D R Chickering & Gregory B1/01/15 5pp 07512 017

H General correspondence

0101090742 Requests reopening of safety licensing hearings for Facility in light of TMI incident.
REICHENBERG, G Affiliation Unknown 79/04/02 2pp 07429 360

0101300256 Responds to EA Johnson ltr re location of facilities. Earthquake hazards are being re-reviewed in connection w/D. applications for Units 2 & 3. Facilities meet NRC siting criteria.
DIRCKS, W J Office of the Executive Director for Operations B1/01/15 3pp 07586 129

K Utility Final Safety Analysis Report (FSAR) & amends

0101090625 Forwards affidavit of svc of Amend 22 to FSAR & Amend 4 to fire hazards analysis per encl svc list.
BASKIN, K P Southern California Edison Co B0/12/30 3pp
07442 060

O Advisory Committee on Reactor Safeguards reports & correspondence

0101190734 Forwards SER re geology & seismology for review & comment. Review will allow ASLB hearing to proceed. W/o encl
TEDESCO, R L Assistant Director for Licensing B0/12/31 1p
07476 119

P Operating license stage documents & correspondence

0101600029 Notification of B01218 meeting w/SEP owners group in Bethesda, MD re SEP program, schedule for licensee topic completion & assignment of lead topics to plants
RUSSELL, W T Technical Support Branch B0/12/16 2pp

Q Inspection reports, IE Bulletins & correspondence

0101050489 Forwards IE Info Notice B0-43, "Failures of Continuous Water Level Monitor for Steam Discharge Val at Dresden Unit 2."
No response required
ENGELKEN, R H Region 5, San Francisco, Office of the Director B0/12/05 1p 07387 271

B0115CB32 Forwards IE Info Notice B0-44. "Actuation of ECCS in Recirculation Mode While in Hot Shutdown " No response required
EISENHUT, R H Region 5, San Francisco, Office of the Director
B01/2/16 1p 07308 001

B0127C517 Responds to IE Bulletin B0-21. "Valve Yokes Supplied by Malcolm Foundry Co. Inc " NRC will be notified if suspect yokes were utilized upon written confirmation from subvondor
BASKIN, K P Southern California Edison Co B1/01/05 1p
07943 352

B01300756 Ack receipt of B01223 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-361/B0-1B & 50-362/B0-11.
SPENCER, D S Region 5, San Francisco, Reactor Construction & Engineering Support Branch B1/01/14 1p 07308 001

--B01300759 Responds to IAC B01202 ltr re violations noted in IE Insp Repts 50-361/B0-1B & 50-362/B0-11 Corrective actions work plan procedure/GC instruction 400 has been revised to strengthen procedural controls
ARENAL, A Southern California Edison Co B0/12/23 4pp
07300 001

--B01300763 Forwards IE Insp Repts 50-361/B0-1B & 50-362/B0-11 on B00923-26 & notice of violation
SPENCER, D S Region 5, San Francisco, Reactor Construction & Engineering Support Branch B0/12/02 2pp 07308 001

--B01300766 Notice of violation from insp on B00923-26.
SPENCER, D S Region 5, San Francisco, Reactor Construction & Engineering Support Branch B0/12/02 1p 07308 001

--B01300771 IE Insp Repts 50-361/B0-1B & 50-362/B0-11 on B00923-26 Noncompliance noted stainless steel piping Spools 28-B1-045 & 046 of safety injection sys insulated despite residue on external surfaces of piping
EICHARDT, J H, HERNANDEZ, C Region 5, San Francisco, Office of the Director HAYNES, R C Region 5, San Francisco, Reactor Construction & Engineering Support Branch B0/12/01 7pp
07308 001.

B012201B0 Forwards responses to open items & questions in NRC B01107 ltr re reactor internals analyses, preservice & inservice insps, sump vortex test, snubber insp & engineered safety features & auxiliary feedwater fracture toughness
BASKIN, K P Southern California Edison Co B1/01/20 50pp

G Reportable occurrences, LERs & related correspondence

B01210384 Final deficiency rept re ITE-0b015 480 V air circuit breakers w/damaged trip coil wiring, initially reported on B01219 licensee will tie-wrap wires near gear reducer or put wires inside spiral wiring harness
PAPAY, L T Southern California Edison Co B1/01/12 3pp
07489 074

B01296507 Final deficiency rept, originally reported on B01226, re inadequate design of fuel transfer tube Multiple longitudinal stiffener plates added between interface & adjacent circumferential interface stiffener rings
PAPAY, L T Southern California Edison Co B1/01/16 3pp.
07566 326

V. Operator Examinations

B01050376 Submits addl info re description of shift technical advisor training program & plans for requalification training per 791031 request
HAYNES, J O Southern California Edison Co B0/12/30 4pp.
07389: 285

B010460513 Forwards "Shift Technical Advisor Training & Requalification Program," & related info. in response to NRC B01031 ltr re TMI action plan requirement
HAYNES, J O Southern California Edison Co B0/12/30 3pp.
07396 040

--B010460523 "Shift Technical Advisor Training & Requalification Program "
* Southern California Edison Co B0/12/31 31pp. 07396.045.

CLC/ET 50-363 FORKED RIVER NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

B01220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports "
EISENHUT, D O Division of Licensing B0/11/26 8pp

F Security, medical, emergency & fire protection plans

B01090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B0102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing B0/11/13 2pp

I Financial information

B012160144 Forwards SEC Form 10-Q, Quarterly Financial Rept & supporting mgt comments in response to NRC 790921, 1109 & B00811 requests for info re significant financial developments affecting utility in restart proceeding
CONDEEN, V H General Public Utilities B0/11/26 3pp

--B012160154 Quarterly Financial Rept Sept 1980 & supporting mgt comments
* General Public Utilities B0/11/14 44pp

O Inspection reports, IE Bulletins & correspondence

B01070409 Forwards Suppl 1 to IE Info Notice B0-29, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director.
B0/11/26 1p 07414 062

B01060830 Forwards IE Info Notice B0-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director.
B0/12/16 1p 07397 021

DOCKET 50-364 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

B01090020 Forwards for review: "Radiation Control & Protection Procedure FNP-O-RCP-000, Mobile Cement Solidification Operation (Hittman) "
CLAYTON, F L Alabama Power Co B1/01/06 2pp. 07424 211

--B01090030 "Radiation Control & Protection Procedure FNP-O-RCP-000 Mobile Cement Solidification Operation (Hittman). "
* Alabama Power Co B0/12/15 30pp 07424 213.

--B01070032 "Process Control Program for Sample Collection, Analysis, Test Solidification Using Cement. "
* Alabama Power Co B0/11/28 11pp 07424 242.

B01160017 Notification of B0107-09 meeting w/util at site to audit records on environ qualification of selected safety-related equipment
WINTNER, L L Licensing Branch 2 B1/01/07 4pp. 07469: 257

B010300054 Summary of B01022 meeting w/util to review design of flow control valves in auxiliary feedwater systems part of OL review
WINTNER, L L Licensing Branch 2 B1/01/14 15pp. 07883: 017.

B01260350 Forwards proposed changes to Table 2.3-10 of FSAR, reflect current instrumentation on meteorological tower. Proposed change will be incorporated into next amend to FSAR
CLAYTON, F L Alabama Power Co B1/01/20 3pp 07525.142.

F Security, medical, emergency & fire protection plans

B01140301 Requests that encl facility emergency planning info be made publicly available w/o encl.
SOUDER, J L Division of Rules and Records B0/12/31 1p.
07461 263

DOCKETED ITEMS

J Insurance & indemnity information

8101090501 Forwards Endorsement 4 to NELIA Binder EB-62
FIELDER, J. Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc
Div 80/12/30 2pp 07442 071

8101220345 Forwards Endorsements 30 & 31 to NELIA Policy NF-230
DUCK, J R Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc Div
81/01/16 4pp 07503 098

P Operating license stage documents & correspondence

8101120106 Forwards Amend 1 to License NPF-B, safety evaluation & notice
of issuance & availability
SCHWENCER, A Licensing Branch 2 80/12/24 2pp 07446-122

--8101120111 Amend 1 to License NPF-B, granting relief from diesel
generator surveillance Requirements 4.8.1.1.2 C.7 & part of
4.8.1.2 from initial fuel loading to initial criticality.
SCHWENCER, A Licensing Branch 2 80/12/24 7pp 07446 125

--8101120114 Notice of issuance & availability of Amend 1 to License
NPF-B
SCHWENCER, A Licensing Branch 2 80/12/24 2pp 07446 132

--8101120116 Safety evaluation supporting Amend 1 to License NPF-B
* Office of Nuclear Reactor Regulation, Director 80/12/24 3pp
07446 134

8101190101 Application to amend License NPF-B, granting temporary relief
from certain Tech Spec items in order to perform augmented
low power testing program
CLAYTON, F L Alabama Power Co 81/01/05 2pp 07476 004

8101210402 Discusses containment purge valve operability at facility,
including use of solenoid valves & air actuators Interim use
of solenoid valves is acceptable. Actuator seal kits will be
replaced on regular basis
CLAYTON, F L Alabama Power Co 81/01/05 2pp 07409-080

8101270179 Notification of 810112 meeting w/utl in Gaithersburg, MD re
identifying specific info for piping sys that penetrate
containments, as part of OL review
KINTNER, L L Licensing Branch 2 81/01/09 2pp. 07946-001

8101210411 Responds to 801230 request for addl info re NRC Position
040 15E on external control power for primary & backup
breakers associated w/reactor coolant pumps Postulated
failure analyses & control power sources provided.
CLAYTON, F L Alabama Power Co 81/01/12 5pp 07489-082

8101210083 Informs that 801205 memo re meeting summary for Fermi 2
should read Farley 2 Copies of memo should be destroyed.
KINTNER, L L Licensing Branch 2 81/01/13 2pp. 07489-322

8101260360 Forwards response to NUREG-0737, in response to NRC 801031
ltr items requiring followup by Unit 2 & corresponding BER
are included in action item for requirement.
CLAYTON, F L Alabama Power Co. 81/01/14 99pp 07525-147

8101220344 Forwards Westinghouse "Special Low Power Tests, Safety
Evaluation." Revision 2, providing justification for
performing Tests 4 & 5 re natural circulation & forced
circulation, respectively
CLAYTON, F L Alabama Power Co. 81/01/16 1p. 07496-347

--8101220349 Revision 2 to "Farley Unit 2 Special Low Power Tests, Safety
Evaluation."
* Westinghouse Electric Corp. 81/01/31 3pp 07496 348

8101270696 Comments on draft BER re auxiliary feedwater control sys
Auxiliary feedwater sys design will be modified to remove
power source dependence.
CLAYTON, F L Alabama Power Co. 81/01/22 2pp. 07543-016

8101270790 Submits info in clarification of multiple rad drop analysis,
per utl 801212 ltr & 810116 telcon Outlines policy to be
implemented when Unit 1 returned to power & subsequent to
exceeding 5% power for Unit 2
CLAYTON, F L Alabama Power Co. 81/01/22 1p. 07548-045

8101280164 Forwards list of radioactive liquids, resins & Hitman sys
bags which must be processed for facility process control
program info suppld utl 801203 & 810106 ltrs. End product
bags will be in compliance w/requirements.

Q Inspection reports, IE Bulletins & correspondence

8101290086 Submits amended response to IE Insp Repts 80-348/80-16 &
80-364/80-19 Contact made w/vendors to determine required
installation torques for concrete expansion anchor bolts
CLAYTON, F L Alabama Power Co 80/10/07 6pp 07567 234

8101050124 Requests existing data, summaries & records of inservice
tests of containments w/gressed prestressing tendons
DRNL receiving contract to compile & review records of
tendons
EISENHART, D O Division of Licensing 80/11/25 3pp

8101220419 Forwards IE Insp Repts 80-348/80-35 & 80-364/80-46 on
801091-31 Ho noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support
Branch. 80/12/04 2pp 07560 213

--8101220427 IE Insp Repts 80-348/80-35 & 80-364/80-46 on 801091-31
noncompliance noted Major areas inspected plant tours,
pre-operational testing, open items & task action items
BRADFORD, W H, MURKEY, J P, MARTIN, R D Region 2, Atlanta, Office
of the Director 80/12/05 11pp 07503 215

8101070856 Confirms 801209 telcon advising of design deviations in
2 auxiliary bldg concrete block walls discovered as result
of evaluations required by IE Bulletin 80-11, "Masonry Wall
Design"
HARRINGTON, G O Alabama Power Co 80/12/09 1p. 07428 358

8101100036 Submits 801210 daily staff notes IE informs of concrete
block wall deviations at Farley 2 & breach of radwaste
package integrity at Turkey Point 3 & 4 Plant status encl
DIRKSB, W J Office of the Executive Director for Operations
80/12/11 3pp

8101060239 Forwards IE Info Notice 80-44, "Actuation of ECCS in
Recirculation Mode While in Hot Shutdown." No written
response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/11
1p 07391 345

8101100308 Ack receipt of 801210 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 80-348/80-31 &
80-364/80-42
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 80/12/22 1p 07443 313

--8101100319 Responds to NRC 801114 ltr re violations noted in IE Insp
Repts 80-348/80-31 & 80-364/80-42 Corrective actions
comprehensive QA audit of fire protection const program
initiated No proprietary info
CLAYTON, F L Alabama Power Co 80/12/10 2pp 07443 314

--8101100331 Forwards IE Insp Repts 80-348/80-31 & 80-364/80-42 on
801014-17 & notice of deviation.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch. 80/11/14 2pp 07443-316

--8101100337 Notice of deviation from insp on 801014-17
* Region 2, Atlanta, Office of the Director 80/11/12 1p.
07443-318

--8101100343 IE Insp Repts 80-348/80-31 & 80-364/80-42 on 801014-17
Noncompliance noted inadequate fire protection QA program
MILLER, W H Region 2, Atlanta, Office of the Director
CONLON, T E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 80/11/12 7pp 07443-319

8101290363 Requests attention until 810115 to respond to IE Bulletin
80-24, "Prevention of Damage Due to Water Leakage Inside
Containment (Oct 17, 1980 Indian Point 2 Event)." Extension
necessitated by licensing & refueling activities
CLAYTON, F L Alabama Power Co 81/01/05 1p 07575 129

8101270406 Summarizes 810109 conference call re licensee evaluation
IE Bulletin 80-11, "Masonry Wall Design." Licensee should be
requested to provide description of deficiencies, Bechtel
wall evaluation & commitment to modify walls.
REEVER, E Operating Reactors Branch 1 KINTNER, L Operating
Reactors Branch 2 81/01/13 3pp. 07946 181

8101300062 Summary of 801205 meeting w/utl in Gaithersburg, MD to
review drawings & other design info re piping sys that
penetrate containments, as part of OL review
KINTNER, L L Licensing Branch 2 81/01/14 4pp. 07583 032

01290334 Forwards response to IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (Oct 17, 1980 Indian Point 2 Event)." Swr water sys is open sys supplying cooling water inside containment
CLAYTON, F L Alabama Power Co 81/01/15 3pp 07575 220

8101290328 Responds to IE Bulletin 80-11, "Masonry Wall Design" Required vertical reinforcing missing from both unit walls. Wall safety-related equipment should conform w/requirements before criticality
CLAYTON, F L Alabama Power Co 81/01/15 2pp 07309 001

P. Periodic operating reports & related correspondence

8101210481 Forwards monthly operating rpt for Dec 1980
CLAYTON, F L Alabama Power Co 81/01/14 1p 07490 156

--8101210465 Monthly operating rpt for Dec 1980
HARRISON, W G Alabama Power Co 81/01/01 4pp 07490 197

Q. Reportable occurrences, LERs & related correspondence

8101300589 RD on 801227, one tube in steam generator IC satisfactorily plugged. Defective tube located by pressurizing secondary side & performing visual insp for leaks. Tube plugging reported per Tech Specs 4.4.3.5.a
CLAYTON, F L Alabama Power Co 81/01/12 1p 07582 263

R. Temperature Examinations

8101260360 Forwards response to NUREG-0737, in response to IIRC 801031 for items requiring followup by Unit 2 & corresponding SER are included in action item for requirement
CLAYTON, F L Alabama Power Co 81/01/14 7pp

8101260365 Forwards addl info re shift technical advisor per NUREG-0737
CLAYTON, F L Alabama Power Co 81/01/20 6pp 07325 216

S. Security, medical, emergency & fire protection plans

8101090397 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing 80/11/13 2pp

8101070518 Releases public version of util emergency plan
FELTON, J M Division of Rules and Records 80/12/01 1p 07403 237

--8101070522 Forwards public version of Revision 3 to emergency plan
WIDNER, W A Georgia Power Co 80/01/31 1p 07403 239

--8101070526 Public version of Revision 3 to emergency plan
* Georgia Power Co 80/01/31 8pp 07403 240

8101140251 Requests to be relieved of constraint to install sprinkler sys for facility recirculation pumps due to recently issued App B to 10CFR50. Forwards proposed revision to fire protection evaluation rpt for NRC review & approval
WIDNER, W A Georgia Power Co 80/12/29 3pp 07462 003

8101260714 Releases public version of util emergency plan
FELTON, J M Division of Rules and Records 81/01/16 1p 07534 027

--8101260718 Forwards public version of emergency plan
WIDNER, W A Georgia Power Co 81/01/02 1p 07534 028

--8101260724 Public version of emergency plan
* Georgia Power Co 81/04/30 100pp 07534 030

T. Insurance & indemnity information

8101090550 Forwards Endorsement 97 to ANF Policy NF-215
FIELDER, J Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc
Div 80/12/31 3pp 07442 050

8101090630 Forwards Endorsement 4 to NELA Binder EB-51
FIELDER, J Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc
Div 80/12/31 2pp 07442 058

P. Operating license stage documents & correspondence

8101000254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under SIS License amend application adding model Tech Specs to App A should be submitted within 120 days.
EISENHUT, D G Division of Licensing 80/11/20 1p

--810100271 Revised Pages 3/4 7-22 through 28, B 3/4 7-5 & 7-6 & 6-17 to SIS snubber inservice insp requirements
* Division of Licensing 80/11/20 10pp

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D G Division of Licensing 80/11/26 8pp

8101190113 Ltr to all BWR licensees forwarding 801201 generic safety evaluation re BWR scram discharge sys. Recommends short-term actions necessary to assure safe operation of OE BWRs pending permanent design changes
EISENHUT, D G Division of Licensing 80/12/09 2pp

--8101190141 Generic safety evaluation re short-term actions required to assure continued safe operation of operating BWRs. Continued operation of plants is acceptable pending permanent design rods. Criteria for implementing design mods uncl.
* Division of Licensing 80/12/01 212pp 07103 001

8101210445 Forwards responses to questions on Rule 50.71a, "Periodic Updating of PSAs" & FH notice of final rule SEP plants need not comply w/rule until program is complete. Non-SEP plants must comply within specified time frame.
EISENHUT, D G Division of Licensing 80/12/15 13pp

8101090970 Forwards request for addl info to complete review of QA program. Shipping damage insps should be implemented & performed for all safety-related items upon delivery.
REID, R W Operating Reactors Branch 4 80/12/24 4pp 07442 026

8101190351 Forwards list of TLD station locations near facility & proposed route for exchanging TLDs for NRC direct radiation monitoring network w/o encls.
BIDLER, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/12/30 2pp 07476 083

8101060564 Forwards info for requirements of NUREG-0737, as of 810101.
WIDNER, W A Georgia Power Co 80/12/31 267pp 07393 120

--8101060973 Tech Specs 3/4 6.7 & 3/4.7.2 re chlorine detectors & main control room environ control sys for Unit 2
* Georgia Power Co 80/12/31 11pp 07396 023

8101220563 Forwards "Operability Review of ECCS at Plant Hatch Unit 1 & 2," in response to NUREG-0737, item II K 3.17.
WIDNER, W A Georgia Power Co 81/01/16 1p 07503 077

--8101220569 "Operability Review of ECCS at Plant Hatch Units 1 & 2"
* General Physics Corp GP-R-33009 80/12/22 75pp 07503 070

8101290570 Responds to NUREG-0619, "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking." Mods will be performed during 1982 refueling outages. Feedwater & control rod drive repts will be submitted within time limits specified.
WIDNER, W A Georgia Power Co 81/01/22 3pp 07575 003

U. Inspection reports, IE Bulletins & correspondence

8012240275 Responds to IE Bulletin 80-17 Ultrasonic transducers will not be installed as previously reported in 800819 ltr. Devices found unreliable in environ. Cause of float failures under investigation.
WIDNER, W A Georgia Power Co 80/11/18 1p 07328 211

8101100682 Forwards IE Insp Repts 80-321/80-43 & 80-366/80-43 on 801104-07 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/25 2pp 07443 167

--B01100689 IE Insp Repts 80-321/80-43 & 80-366/80-43 on 801104-07 No noncompliance noted Major areas inspected installed equipment review per IE Bulletin 79-018
O'DONNELL, D. J. CONLON, T. E. Region 2, Atlanta, Office of the Director 80/11/25 4pp 07443 169

B01080202 Responds to IE Bulletin 80-21 re valve yokes supplied by Malcolm Foundry Co. Inc No such yokes used in facility Valve documentation indicates other foundries made valve yokes in use
WIDNER, W. A. Georgia Power Co. 80/11/26 1p 07420 359

B01090602 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Scram Discharge Val at Dresden Unit 2 " No response required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/12/05 1p 07391 018

B01070331 Ack receipt of B01008 ltr requesting re-evaluation & dismissal of apparent noncompliance ltr contained in Waste Packaging Insp Repts 80-321/80-32 & 80-366/80-32. Item withdrawn
STCHAR, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/12/11 1p 07408 124

--B01070334 Responds to NRC 800917 ltr re violations noted in Waste Packaging Repts 80-321/80-32 & 80-366/80-32 Requests re-evaluation & dismissal of cited noncompliance All shipment regulations properly followed
WIDNER, W. A. Georgia Power Co. 80/10/08 2pp 07408 129

--B01070336 Forwards Waste Packaging Insp Repts 80-321/80-32 & 80-366/80-32 on 800731 & notice of violation
STCHAR, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/09/17 2pp 07408 127

--B01070338 Notice of violation from Insp on 800731
* Region 2, Atlanta, Office of the Director 80/09/15 1p 07408 129

--B01070342 Waste Packaging Insp Repts 80-321/80-32 & 80-366/80-32 on 800731 Noncompliance noted radwaste shipment not properly placarded
MACARTHUR, T. C. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/09/15 3pp 07408 130

B01060126 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Scram Capability " No response required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/12/17 1p 07397 339

B01070033 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of 76 of 189 Control Rods to Fully Insert During Scram at BWR " No written response required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/12/10 1p 07413 329

B01090159 Forwards IE Bulletin 80-25, "Operating Problems W/Target Rock Safety Relief Valves at BWRs " No response required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/12/19 2pp 07377 259

B01290185 Responds to IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (Oct 17, 1980 Indian Point 2 Event) " Drywell cooling sys composed of six cooling units each w/ two fans Normally only one fan per unit is operating
WIDNER, W. A. Georgia Power Co. 81/01/05 7pp 07569 346

B01290376 Responds to IE Bulletin 80-07, "BWR Jet Pump Assembly Failure. " No abnormal wear, stress or failed welds discovered during visual exams of Unit 2 assemblies by remote underwater television cameras Insp of Unit 1 scheduled
WIDNER, W. A. Georgia Power Co. 81/01/13 1p 07575 131

B01290385 Responds to IE Bulletin 80-13, "Cracking in Core Spray Spargers. " No cracking of core spray spargers or piping between inlet nozzle & vessel shroud was identified in Unit 2. Insp for Unit 1 scheduled during Winter 1981.
WIDNER, W. A. Georgia Power Co. 81/01/13 1p 07575 132

B01300374 Responds to request for confirmation of response to IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Tests will be completed by Feb 1981 & June 1981 for Units 1 & 2, respectively
WIDNER, W. A. Georgia Power Co. 81/01/26 2pp 07586 350

R Periodic operating reports & related correspondence

B01260525 Forwards monthly operating rept for Dec 1980.
MANN, M. Georgia Power Co. 81/01/10 1p 07529 257

--B01260527 Monthly operating rept for Dec 1980
MANN, M. Georgia Power Co. 81/01/10 1pp 07529

S Reportable occurrences, LERs & related correspondence

B01050455 Forwards LER 80-163/01T-1
MANN, M. Georgia Power Co. 80/12/23 1p 07390 193

--B01060460 LER 80-163/01T-1 on 801215, until notified that react lead insulation structure did not conform to seismic Class I requirements Caused by failure to incorporate rods during const. Insulation structure will be modified
COGGI, H. C. L. Georgia Power Co. 80/12/23 2pp 07390 194

B01060559 Forwards LER 80-164/03L-0
MANN, M. Georgia Power Co. 80/12/30 1p 07391 114

--B01060566 LER 80-164/03L-0 on 801210, attempt to pressurize dr equipment drain sump to radwaste discharge piping failed due to excessive leakage past outdoor isolation valve 2011-F004. Caused by valve gate not seating properly Gate lapped
COGGI, H. C. L. Georgia Power Co. 80/12/30 2pp 07391 115

B01060572 Forwards LER 80-162/03L-0
MANN, M. Georgia Power Co. 80/12/30 1p 07391 123

--B01060579 LER 80-162/03L-0 on 801209, review of 801203 local 1 test revealed leakage for vent purge outlet isolation valve 2148-F318 would have exceeded Tech Specs Cause unknown Valve will be repaired prior to startup
COGGI, H. C. L. Georgia Power Co. 80/12/30 2pp 07391 124

B01060648 Forwards LER 80-121/03L-0.
MANN, M. Georgia Power Co. 80/12/30 1p 07392 183

--B01060669 LER 80-121/03L-0 on 801211, all points of 1147-RU11, temp recorder, were reading higher than redundant recorder 1147-R612 Caused by faulty slide wire contacts & pinthead mechanism New parts installed
NIX, R. T. Georgia Power Co. 80/12/30 2pp 07392 184

B01060514 Special Rept 1-sp-80-3 on 801206, during routine survey waste oil drums, several areas on ground were found to be contaminated Caused by storage of previous waste oil drums Addl controls re release of contaminated oil under review
MANN, M. Georgia Power Co. 80/12/31 4pp 07392 189

B01120312 Forwards LER 80-157/03L-0
MANN, M. Georgia Power Co. 81/01/06 1p 07447 135

--B01120364 LER 80-157/03L-0 on 801223, control rod removed & f pool for Insp Monorail hoist used w/c performing hoist operability Caused by inadequate procedure Procedure revised
BARTLEY, S. X. Georgia Power Co. 81/01/06 2pp 07447 136

B01230466 Forwards LER 80-160/03L-0
MANN, M. Georgia Power Co. 81/01/13 1p 07511 126

--B01230469 LER 80-160/03L-0 on 801216, during refueling, local 1 test performed on fire protection isolation valve 2143-F159 revealed leakage would have exceeded acceptance criteria since test val could not be pressurized
COGGI, H. C. L. Georgia Power Co. 81/01/13 2pp 07511 127

DOCKET 80-367 BAILLY GENERATING STATION

A Application/construction stage documents & correspondence

B01220466 Ltr to all power reactor licensees & applicants for summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports "
EISENHUT, D. Q. Division of Licensing, 80/11/26 8pp

B01090389 Forwards final panel rept, "Effects of Dewatering on Dunes Natl Lakeshore "
WHITEHOUSE, J. R. Interior, Dept of, National Park Service 80/12/17 1p 07378 358

B01070317 Notification of contract execution "Div of Engineering Review Support on Bailly Pile Foundations." awarded to M Davidson
FLEENOR, C. M. Administrative Contracts Branch FIN 8-7936 80/12/17 1p 07415 217

--B101070319 Contract "Div of Engineering Review Support on Bailly Pile Foundations. awarded to MT Davison
DAVISSON, M T Davison, M T PERLMAN, J Administrative Contracts
Branch File # 7536 80/12/17 3pp 07415 218

B101050428 Forwards response to questions to aid in evaluation of CP extension request, per B01121 ltr Certificate of Svc encl
SHORR, E M Northern Indiana Public Service Co. 80/12/18 5pp
07380 128

B101050079 Forwards records of three wells in IN Dunes Natl Lakeshore, near facility Wells 26, D-7A & 23-A were pumped w/hand pump to develop wells All three wells are open to aquifer in which they are screened
WATSON, L R Interior, Dept of 80/12/22 7pp 07376 292

B101200157 Summary of 801210 meeting w/Mark II owners re status of generic improved chugging load model Owners requested to justify delay in program & investigate alternatives
ANDERSON, C J Generic Issues Branch 80/12/22 4pp.

B101140955 Summary of Dec 1980 meeting w/Mark II owners group, GE, BNL, MIT, S&W, Bechtel & Ebasco Svcs. Inc re suppression pool temp limits List of attendees & handouts encl
SU, T M Generic Issues Branch 80/12/30 41pp.

B101060470 Comments on Natl Park Svc rept. "Effects of Dewatering on IN Dunes Natl Lakeshore." USGS prediction of groundwater changes are urgent & unreliable (ref B01120 ltr & encl B01208 ltr to members of wetlands panel)
SHORR, E M Northern Indiana Public Service Co 80/12/31 18pp
07398 146

B101090720 Responds to B01212 transmittal of Wetland ecologists "Effects of Dewatering on IN Dunes Natl Lakeshore" Rept provides no useful info to NRC preparation of EIA re request for CP extension Certificate of Svc encl
SHORR, E M Northern Indiana Public Service Co. 80/12/31 20pp
07142 126

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

G Adjudicatory correspondence

B101100049 Forwards correspondence w/City of Gary, IN re requests for action under 10CFR2 206, in response to B01031 request Util will be notified of meeting w/o encls.
DIRCKS, W J Office of the Executive Director for Operations 80/12/12 1p 07442 291.

--B101100091 Forwards draft response to util B01031 ltr re requests for action concerning facility Requests Blind copy of final version of response.
MOUNT, R Rulemaking & Enforcement Division. 80/11/17. 3pp
07442 292

--B101100095 Requests that util be furnished on contemporaneous basis w/all correspondence between NRC & parties to extension proceeding &/or petitioners under 10CFR2 206
SHORR, E M Northern Indiana Public Service Co. 80/10/31. 3pp
07442 295

B101050004 Responds to B01212 request for NRC response to B01202 ltr from RE Dickinson, Natl Park Svc. Copy will be forwarded when available
GOLDBERG, S C Hearing Branch 2 80/12/30 1p. 07377 340

B101060629 Informs that Director's decision under 10CFR2 206 re State of IL & City of Gary B01231 request is unachievable by B01231 Determination anticipated in early Jan 1981.
GOLDBERG, S C Hearing Branch 2 80/12/31 1p 07387 263

B101090102 Motion for extension until B10109 to file responses to ASLB B01224 memorandum & order Intervenor believes order contains misunderstandings of law & misconceptions re position Certificate of Svc encl
CHILKIN, S J Isaac Walton League of America, Porter County Chapter 80/12/31 4pp 07426 294

B101130606 Requests response by B10119 that Commissioners will insure adequate emergency planning for potential accidents at site before further const permitted
MCFEET, T House of Rep. Government Operations 81/01/03 1p
07453 331

--B101130613 Extract of staff requirements memo advising that Director of Nuclear Reactor Regulation must hold action on 10CFR2 206 requests by State of IL & City of Gary until further notice from Commission Certificate of Svc encl
CHILKIN, S J Office of the Secretary of the Commission. 81/01/09 4pp. 07453 332

B101120449 Order granting extension until B10128 for Commission to review ALAB-619 Certificate of Svc encl.
CHILKIN, S J Office of the Secretary of the Commission. 81/01/07. 4pp 07442 317

B101120232 Motion for extension until B10116 to respond to ASLB B01224 memorandum & order Certificate of Svc encl
FAHNER, T C, RAPKIN, A, MURRAY, M J Illinois, State of 81/01/08 4pp 07458 097

B101150008 Order granting extension until B10109 for any party to file pleadings pursuant to ASLB B01224 Memorandum & order. Certificate of Svc encl
GROSSMAN, H Atomic Safety and Licensing Board Panel. 81/01/09. 4pp. 07462 137.

B101160242 Response in opposition re admissibility of newly filed & short piling contentions in issues to ASLB Certificate of Svc encl
VOLLEN, R J Isaac Walton League of America, Porter County Chapter. VOLLEN, R J Vollen, R J 81/01/09 12pp. 07470 216

B101140230 Forwards HR Denton B01230 ltr to RE Dickenson in response B01202 ltr to J Ahearn
GOLDBERG, S C Hearing Branch 2 81/01/12. 1p. 07309 001.

--B101140237 Advises that Ahearns response to B01202 ltr re dewatering procedure would be inappropriate since subj is similar to contention admitted by ASLB. Proposed plan constitutes reasonable approach w/one exception.
DEUTON, H R Office of Nuclear Reactor Regulation, Director. 80/12/30 2pp 07309 001

B101260216 Requests notification of any proceedings re facility
DOUGHERTY, M R Affiliation Unknown. 81/01/12 1p. 07523 307

--B101260224 Memorandum & order denying Porter County Chapter intervenor B01017 motion to compel MD Lynch deposition in Chicago Deposition to be restricted to Bethesda, MD or metropolitan Washington, DC area Certificate of Svc encl
GROSSMAN, H Atomic Safety and Licensing Board Panel. 81/01/19. 3pp 07523 308

B101160726 Order granting another extension until B10116 for any party to file pleading re ASLB B01224 memorandum & order. Certificate of Svc encl
GROSSMAN, H Atomic Safety and Licensing Board Panel. 81/01/14. 4pp 07472 057

B101200046 Objections to ASLB B01224 memorandum & order. Requests revision of order or certification to ASLB of admissibility of short piling contentions. Certificate of Svc encl.
RAPKIN, A, FAHNER, T C, MURRAY, M J Illinois, State of. 81/01/14 8pp. 07477 322

B101216200 Informs that EIA will not completed by B10115 as B01030 ltr advised NRC will inform ASLB & parties when realistic date for EIA issuance is known
GOLDBERG, S C Hearing Branch 2 81/01/16 1p. 07490 044.

B101230432 Advises that util will respond to Porter County Chapter Intervenor's B10109 objections to ASLB B01224 memorandum & order & to B10109 motion for certification or referral. Certificate of Svc encl.
SHEA, K H Lowenstein, Newman, Reis, Aselrad & Toll. 81/01/16. 3pp. 07512 130.

B101280031 Order granting extension until B10206 for Commission to review ALAB-619 Certificate of Svc encl
CHILKIN, S J Office of the Secretary of the Commission 81/01/22 4pp. 07555 111

B101270378 Informs that Director of Nuclear Reactor Regulation instructed not to act on State of IL & City of Gary 10CFR2 206 request until further advised
GOLDBERG, S C Hearing Branch 2 81/01/26. 1p 07544 096.

8101280641 Response opposing Porter County Chapter of Izaak Walton League of America, Inc 801224 motion for reconsideration & admission of denied contentions or certification to ASLAP Certificate of Svc encl
SHEA, K H Northern Indiana Public Service Co. SHEA, K H
Lovenstein, Neuman, Reis, Aselrad & Toll Eichhorn, Eichhorn & Link
81/01/26 10pp 07550 216

0 Inspection reports, IE Bulletins & correspondence

8101090206 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding " No response required.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/30
2pp 07389 013.

8101060662 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp " No written response is required
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/10/31.
1p 07401 129

8101100785 Forwards IE Circular 80-23, "Potential Defects in Beloit Power Sys Emergency Generators " No written response required
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/10/31
2pp. 07444:075

8101090479 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co, Inc " Written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/06
2pp 07390 061

8101060623 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety-Relief Valve Operation to Cause Reactor Depressurization." No written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/07.
1p 07400 161

8101060362 Forwards IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1 " No response required.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/10
2pp. 07391:064

8101060525 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp " Written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/11/14.
2pp. 07391 244

8101070576 Responds to IE Bulletin 80-23 No Valcor solenoid valves.
V709000-21-1 or V709000-21-3, used in safety-related sys at facility Complete response will be provided by 820129
SHORR, E M Northern Indiana Public Service Co. 80/12/04 1p.
07415:277

8101030568 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor For Scram Discharge Vol at Dresden Unit 2 " No response required
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/12/05
2pp 07388 359

8101080048 Forwards IE Info Notice 80-49, "Potential Failure of BWR Backup Manual Scram Capability " No written response required.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/17
2pp. 07420:317

8101150225 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BWR " No written response required.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/18
2pp. 07465:340

8101050210 Forwards IE Bulletin 80-25, "Operating Problems W/Target Rock Safety Relief Valves at BWRs." No response required.
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/17
2pp. 07389 007

R. Periodic operating reports & related correspondence

8101050395 Forwards well charts for 801210-1217 & Bailey Wells w/o recorders, pond levels, pneumatic pressure transducers, water meter readings & USGS wells for 801217.
BOHN, R J Northern Indiana Public Service Co 80/12/24 33pp
07380:335

8101050336 Forwards well charts for 801217-14 & Bailey Wells w/o recorders, pond levels, pneumatic pressure transducers & water meter readings for 801224 Well readings for 518 & 558 unavailable
BOHN, R J Northern Indiana Public Service Co 80/12/31 32pp.
07430 016.

8101120459 Forwards Well charts for 801224-31, Bailey Wells w/o recorders, pond levels, pneumatic pressure transducers, water meter readings & USGS wells for 801231 Well 518 float froze
BOHN, R J Northern Indiana Public Service Co 81/01/09 32pp
07452 113

8101210320 Forwards Well charts for 801230-810107 & Bailey wells w/o recorders, pond levels, pneumatic pressure transducers, water meter readings & USGS wells for 810107 Clock on Wells 14 & 57C stopped float on Well 35B froze
BOHN, R J Northern Indiana Public Service Co 81/01/16 32pp
07107 001

8101230552 Forwards well charts for 810107-14, Bailey Wells w/o recorders, pond levels, pneumatic pressure transducers, water meter readings & USGS wells for 800114 & rainfall data for 801101-1230 Head hung up on Well 14
BOHN, R J Northern Indiana Public Service Co 81/01/20 33pp
07511 167

U Congressional/Executive Correspondence

8101130606 Requests response by 810119 that Commissioners will ins adequate emergency planning for potential accidents at site before further const permitted.
MEFFETT, T House of Rep , Government Operations 81/01/03. 1p
07453 331

--8101130613 Extract of staff requirements memo advising that Dir of Nuclear Reactor Regulation must hold action on 10CFR2 206 requests by State of IL & City of Gary until further notice from Commission Certificate of Svc encl
CHILK, R J Office of the Secretary of the Commission. 81/01/4pp. 07453:332.

DOCKET 90-368 ARKANSAS NUCLEAR ONE, UNIT 2

F. Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP hol & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

8101130142 Advises of provisions of 10CFR50, App R, that are applica to fire protection features of facility FR notice & summary of staff requirements to resolve open items encl
EISENHUT, D O Division of Licensing 80/11/24 7pp 07308 09

8101070460 Forwards proprietary comments on necessary revisions to add info needed re util 800909 revised security training & qualification plan. Comments withheld (ref 10CFR2 790).
REID, R W Operating Reactors Branch 4 80/12/17 2pp. 07415.

8101140215 Informa that licensee should conduct emergency exercise within one yr from 800401 or prior to issuance of DL.
Schedule of drills should be provided
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/12/21p 07461 256

8101080343 Forwards revisions & proposed changes to industrial sec plan Revisions withheld (ref 10CFR2 790)
TRIMBLE, D C Arkansas Power & Light Co 81/01/02 2pp 07415

8101200394 Requests that encl facility emergency planning info be publicly available w/o encl.
SOUDER, J L Division of Rules and Records. 81/01/09. 1p
07486 313

8101260673 Releases public version of util upgraded emergency plan
FELTON, J M Division of Rules and Records 81/01/16 1p
07533 015

--8101260678 Forwards public version of upgraded emergency plan in State of AR radiological incident response plan & Popp.
Johnson, Yell & Logan Counties, AR emergency plans
TRIMBLE, D C Arkansas Power & Light Co 81/01/02. 1p.
07533 016

--B01020693 Public version of upgraded emergency plan Includes State of AR radiological incident response plan & Papp, Johnson, Yell & Logan Counties. AR emergency plans
Arkansas Power & Light Co B1/01/01 800pp 07533 017.

J Insurance & indemnity information

B01020742 Forwards Endorsement 3B to RELIA Policy MF-74 & Endorsement 43 to RELIA Policy MF-210
TRIMBLE, D C Arkansas Power & Light Co B1/01/21 4pp 07369 001

P Operating license stage documents & correspondence

B01020150 Clarifies intent of plans for position task analysis of general ofc personnel interviews w/personnel in positions w/nuclear responsibilities will not be complete until
B010101
CAVANAUUGH, W Arkansas Power & Light Co 08/11/19 4pp 07446 152

B010100254 Ltr to all licensees (except SEP licensees) forwarding Revision 1 of inservice surveillance requirements for snubbers under BTS license amend application adding model Tech Specs to App A should be submitted within 120 days
EISENHUT, D O Division of Licensing 08/11/20 1p

--B010100227: Revised Pages 3/4 7-22 through 28; B 3/4 1-5 & 7-6 & 6-17 to BTS snubber inservice insp requirements
Division of Licensing 08/11/20 10pp

B01020465 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12. "Potential for LCA Fracture Toughness & Laminar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 08/11/26 8pp

B01020445 Forwards responses to questions on Rule 50.71e. "Periodic Updating of FSARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame
EISENHUT, D O Division of Licensing 08/12/15 13pp

B010100246 Informs that B00911 application for changes to Tech Specs re containment cooling sys svc water requirements only requires Class II, not Class III Fee as permitted Refund will be made
MILLER, W D License Fee Management Branch 08/12/22 1p 07145 219.

B0105041B Advises that NRC B01113 ltr re NUREG-0519, "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking," does not pertain to Facilities Facilities are PHRs No response action will be taken
TRIMBLE, D C Arkansas Power & Light Co 08/12/29 1p 07389:329

B01060255 Forwards info re NUREG-0737, in response to NRC B01031 ltr Includes info re shift technical advisor procedures for transients & accidents, plant shielding & thermal shock rept
TRIMBLE, D C Arkansas Power & Light Co. 08/12/31 9pp 07393:340

B01060406 Responds to NUREG-0737, "Reporting Safety Valve & Relief Valve Failures & Challenges " One challenge to automatic relief valve occurred at Unit 1 from Apr-Dec 1980 No challenges to primary sys code occurred at Unit 2
TRIMBLE, D C Arkansas Power & Light Co. B1/01/08 1p 07470 167

B010220414 Forwards CEN-143(A)-P & CEN-143(A)-NP, proprietary & nonproprietary versions, respectively of "CPC/CEAC Software Mods for AR Nuclear One-Unit 2 " Requests withholding of CEN-143(A)-P (ref 10CFR2 790). Affidavit encl
TRIMBLE, D C Arkansas Power & Light Co B1/01/09 5pp 07493 233

--B010220417 Nonproprietary version of "CPC/CEAC Software Mods for AR Nuclear One-Unit 2 "
Corbustion Engineering, Inc CEN-143(A)-NP 08/12/31 109pp. 07493 259

B010200298 Forwards evaluation of HPS1 pump operability w/o svc water cooling.
TRIMBLE, D C Arkansas Power & Light Co. B1/01/13 13pp 07486 242

B010200256 Forwards detailed plan, discussed in B01217 meeting w/NRC, describing proposed analysis method to demonstrate adequate fracture toughness characteristics for snubber attachment lug to reactor coolant pump, in response to NRC B00805 ltr
TRIMBLE, D C Arkansas Power & Light Co B1/01/15 2pp 07486 233

Q Inspection reports, IE Bulletins & correspondence

B010120166 Responds to IE Bulletin 79-17 re pipe cracks in stagnated torated water sys at PHRs Cracks discovered in heat affected zones of three welds in reactor bldg spray sys on B00121
TRIMBLE, D C Arkansas Power & Light Co 08/11/11 4pp 07446 162

B010100217 Forwards IE Insp Repts 50-313/80-21 & 50-360/80-21 on B00922-1021 & notice of violation
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 08/11/19 2pp 07431 350

--B010100225 Notice of violation from Insp on B00922-1021
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 08/11/18 3pp 07431:352

--B010100236 IE Insp Repts 50-313/80-21 & 50-360/80-21 on B00922-1021 Noncompliance noted inoperability of high pressure safety injection pump & failure to sample reactor coolant sys as required
JOHNSON, W D, CALLAN, L J, HUNN/CUTT, D M Region 4, Dallas, Office of the Director 08/11/18 7pp 07431:355

B01090285 Forwards IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (October 17, 1980 Indian Point Event)" Written response required.
SEYFRIT, W V Region 4, Dallas, Office of the Director 08/11/21 1p 07425 250

B01060318 Forwards IE Info Notice 80-42, "Effect of Radiation on Hydraulic Snubber Fluid " No response required
SEYFRIT, W V Region 4, Dallas, Office of the Director 08/11/24 1p. 03996 308

B010120155 Responds to IE Bulletin 80-23 re Valcor solenoid valves No such valves installed at Facilities Three manhours expended
TRIMBLE, D C Arkansas Power & Light Co 08/11/24 1p. 07446:156

B010604090 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange " No written response required
SEYFRIT, W V Region 4, Dallas, Office of the Director. 08/11/24 1p 07391 109

B01060084 Forwards corrected Pages 6 & 7 of IE Insp Repts 50-313/80-21 & 50-360/80-21
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch. 08/11/26 1p 07401:050

--B01060587 Corrected Pages 6 & 7.
Region 4, Dallas, Office of the Director 08/11/26 2pp 07401 051

B01090214 Ack receipt of B00924 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-360/80-13 & 50-313/80-13 Addl info required within 20 days.
KELLY, J A Region 4, Dallas, Office of the Director. 08/11/20 3pp 07425 271

--B01090225 Responds to NRC ltr re violations noted in IE Insp Repts 50-360/80-13 & 50-313/80-13 Corrective actions withheld (ref 10CFR2 790).
TRIMBLE, D C Arkansas Power & Light Co 08/09/24 1p. 07425 273

B01020044 Informs of progress since B00731 ltr re IE Bulletin 80-09 concerning hydrcmotor actuator deficiencies. Vendor repts detailed
TRIMBLE, D C Arkansas Power & Light Co. 08/12/04 3pp. 07446:23

B0107015B Ack receipt of B01010 & 1112 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/80-16 & 50-360/80-16
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 08/12/05 1p. 07415 119

--B01070164 Responds to NRC B01023 ltr re violations noted in IE Insp Repts 50-313/80-16 & 50-360/80-16 Corrective actions: site QA audit repts will be reviewed by plant safety committee.
TRIMBLE, D C Arkansas Power & Light Co. 08/11/12 2pp 07415:120

8101050607 Forwards IE Info Notice 80-43. "Failures of Continuous Water Level Monitor for Steam Discharge Vol at Dresden Unit 2 " No response required
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/12/08
Ip 07391 026

810120174 Responds to IE Bulletin 80-21 re valve yokes cast by Malcolm Foundry Co, Inc No valve parts in safety-related sys cast by Malcolm Foundry Co, Inc
TRIMBLE, D C Arkansas Power & Light Co 80/12/08 Ip 07446 167

8101060192 Forwards IE Info Notice 80-44. "Actuation of ECCS in Recirculation Mode While in Hot Shutdown " No written response required
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/12/16
Ip 07391 300

810100005 Forwards IE Insp Repts 50-313/80-19 & 50-368/80-19 on 801006-09 & notice of violation Notice of violation withheld (ref 10CFR2 790)
KELLY, J A Region 4, Dallas, Office of the Director 80/12/19
2pp 07443 057

--810100008 IE Insp Repts 50-313/80-19 & 50-368/80-19 on 801006-09 Noncompliance noted: guards w/o continuous communication & access authorization lists not prepared Details withheld (ref 10CFR2 790)
EVANS, C A , KELLY, J A Region 4, Dallas, Office of the Director 80/10/31 2pp 07443 059

A Periodic operating reports & related correspondence

8101210509 Forwards monthly operating rept for Dec 1980
TRIMBLE, D C Arkansas Power & Light Co 81/01/15 Ip 07490 192.

--8101210514 Monthly operating rept for Dec 1980
PENDERGRAFT, R Arkansas Power & Light Co 81/01/15 5pp
07490 193

B Reportable occurrences, LERs & related correspondence

8101070399 RD 80-91 on 801220, channel checks on refueling water tank level indication revealed that Channels A, C & D indicated 100% & Channel B 82% Caused by frozen refueling water tank level transmitters
D'IANLON, J P Arkansas Power & Light Co 80/12/22 Ip 07415 298

8101030361 Forwards LER 80-088/03L-0
TRIMBLE, D C Arkansas Power & Light Co 80/12/26 Ip 07305 092

--8101050367 LER 80-089/03L-0 on 801201, core protection computer A & CEAC 1 failed CEAC 2 & PPS channels B, C & D were inoperable Caused by maint personnel working on 2F1-8224-1 in cabinet 2033. Sigma indicators will be replaced
PENDERGRAFT, R Arkansas Power & Light Co 80/12/26 2pp
07385 093.

8101050373 Forwards LER 80-087/03L-0
TRIMBLE, D C Arkansas Power & Light Co 80/12/26 Ip 07385 095

--8101050377 LER 80-087/03L-0 on 801229, high pressure safety injection valve 2CV-5056 failed to close Caused by control circuit Fuse failure Fuse replaced, valve stroked & declared operable
SHIVELY, C N Arkansas Power & Light Co 80/12/26 Ip
07385 096

8101050381 Forwards revised LER 80-064/03X-1.
TRIMBLE, D C Arkansas Power & Light Co 80/12/26 Ip 07385 097.

--8101050387 Revised LER 80-064/03X-1 on 800810, high containment pressure trip delayed from PPS A & D On 801203, steam generator B low level trip circuit for PPS A was inoperable Caused by bistable comparator card power supply failures
SHIVELY, C N Arkansas Power & Light Co 80/12/26 Ip
07385 098

8101050422 Forwards LER 80-091/01T-0
TRIMBLE, D C Arkansas Power & Light Co 80/12/26 Ip 07390 189

--8101050501 LER 80-091/01T-0 on 801220, Channel B instruments indicated low refueling water tank level Caused by frozen level transmitters Replaced fuse
SHIVELY, C N Arkansas Power & Light Co 80/12/26 3pp
07390 186

8101050440 Forwards LER 80-090/03L-0
TRIMBLE, D C Arkansas Power & Light Co 80/12/26 Ip 07390 191

--8101050509 LER 80-090/03L-0 on 801205, increased accumulation of wastes found in waste tanks Caused by vibration induced cracking on charging pump suction header at junction of reactor makeup water tank supply Pipe spool piece replaced
SHIVELY, C N Arkansas Power & Light Co 80/12/26 Ip
07390 192

8101050452 Forwards LER 80-089/03L-0
TRIMBLE, D C Arkansas Power & Light Co 80/12/26 Ip 07390 193

--8101050519 LER 80-089/03L-0 on 801205, steam generator levels dropping loss of feedwater flow found in electric driven emergency feedwater pump 2P7H. Caused by radial & thrust bearing failure in pump shaft Pump assembly rebuilt
SHIVELY, C N Arkansas Power & Light Co 80/12/26 Ip
07390 235.

8101120344 Forwards updated LER 80-060/03X-2
TRIMBLE, D C Arkansas Power & Light Co 81/01/07 Ip 07447 164

--8101120389 Updated LER 80-060/03X-2 800730 & 1202, D core protection calculator failed C core protection calculator failed on 801120 Watchdog timer timed out preventing console communications Core protection calculator sys reinitialized
BRAMLETT, L S Arkansas Power & Light Co 81/01/07 Ip
07447 164

8101130474 Forwards updated LER 80-081/03L-1
TRIMBLE, D C Arkansas Power & Light Co 81/01/07 Ip 07454 313

--8101130484 Updated LER 80-081/03L-1 on 801030 & 1212, during rework, fire barrier not maintained Caused by inadequate instructions Contractor instructed to maintain firewatch when penetrations are open & to seal penetrations quickly
BRAMLETT, L S Arkansas Power & Light Co 81/01/07 Ip
07454 313

8101130439 Forwards updated LER 80-056/03X-1
TRIMBLE, D C Arkansas Power & Light Co 81/01/09 Ip 07454 099

--8101130452 Updated LER 80-056/03X-1 on 800720, A core protection calculator received three auto restarts & on 801218, calculator C failed causing BDDR/LPD trip Probably caused by malfunction of normal room cooler increasing air temp.
BRAMLETT, L S Arkansas Power & Light Co 81/01/09 Ip
07454 099

8101190448 Forwards updated LER 80-060/03X-3
TRIMBLE, D C Arkansas Power & Light Co 81/01/13 Ip 07474 053

--8101190498 Updated LER 80-060/03X-3 on 800730, core protection calculator channel failed, causing trip sequence Cause under investigation Watch dog timer timed out, rendering channel inoperable Sys reinitialized & bypasses removed
SHIVELY, C N Arkansas Power & Light Co 81/01/13 2pp
07474 053

8101200411 Forwards LER 80-092/03L-0
TRIMBLE, D C Arkansas Power & Light Co 81/01/14 Ip 07487 038

--8101200416 LER 80-092/03L-0 on 801222, emergency control room 2VE-1A compressor failed to start, Caused by frozen migration due to cold ambient temp affect on sys Had being evaluated to add time delay on interlocks to allow low temp starts
SHIVELY, C N Arkansas Power & Light Co 81/01/14 Ip
07487 038

8101200399 Forwards LER 80-093/03L-0
TRIMBLE, D C Arkansas Power & Light Co 81/01/15 Ip 07477 361

--8101200406 LER 80-093/03L-0 on 801220, emergency diesel generator tripped on reverse power on breaker closure Caused by operator applying manual generator load increase too slowly Operators instructed on importance of applying load quickly
SHIVELY, C N Arkansas Power & Light Co 81/01/15 Ip
07477 361

8101270577 Forwards updated LER 80-039/03X-1
TRIMBLE, D C Arkansas Power & Light Co 81/01/19 Ip 07541 139

--8101270585 Updated LER 80-037/03X-1 on 800727 & 1231, during M operation, core operating limits supervisory sys declared inoperable Caused by integrated detector flux array becoming altered on 800727 & disc input/output failure on 801231
SHIVELY, C N Arkansas Power & Light Co 81/01/19 Ip
07541 139

V Operator Examinations

8101060355 Forwards info re NUREG-0737, in response to NRC 801031 ltr includes info re shift technical advisor procedures for transients & accidents, plant shielding & thermal shock rept TRIMBLE, D C Arkansas Power & Light Co. 80/12/31 9pp

8101270356 Requests clarification of position re Items II B 1 & II B 4 to NUREG-0737, re reactor coolant sys vents & training for mitigating core damage TRIMBLE, D C Arkansas Power & Light Co 81/01/19 3pp

DSCKET 50-369 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unsolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports" EISENHUT, B G Division of Licensing 80/11/26 8pp

8101050107 Forwards nonradiological environ protection plan for Facility Certain portions of plan revised to comply w/NRC efforts to standardize environ programs YOUNG, C L Licensing Branch 1 80/12/10 3pp 07379 207

--8101050105 Environ protection plan (nonradiological) for Facility
• Commissioners 80/12/10 11pp 07379 310

8101070624 Ack receipt of 801117 re hydrogen control measures Addl info requested re all recently developed info pertinent to evaluation of hydrogen control measure TERESCO, H L Assistant Director for Licensing 80/12/19 2pp 07414 179

810120271 Forwards summary of 801217 meeting w/util in Bethesda, MD re auxiliary feedwater sys reliability evaluation YOUNG, C L Licensing Branch 1 80/12/27 2pp 07446 319

--8101060350 Summary of 801217 meeting w/util in Bethesda, MD re improving reliability of auxiliary feedwater sys PARKER, W D Auxiliary Systems Branch 80/12/19 3pp 07446:321

8101190220 Forwards list of 1LD station locations near facility & proposed route for exchanging 1LDs for ARC direct radiation monitoring network W/o encls SINGER, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/12/30 2pp 07475 309

8101150711 Notification of 810103 meeting w/util in Bethesda, MD to discuss surveillance requirements for piping sys snubbers & exemption request (waived) from mechanical snubber requirements. BIRKEL, R A Licensing Branch 1 81/01/02 3pp 07464 360

8101220133 Forwards "Analysis of Hydrogen Control Measures at McGuire Nuclear Station," Vol 1 PARKER, W D Duke Power Co 81/01/05 1p 07474:010

--8101220138 "Analysis of Hydrogen Control Measures at McGuire Nuclear Station," Vol 3
• Duke Power Co 81/01/05 78pp 07474:011

8101230493 Forwards proposed Tech Specs, changing explosive gas mixtures in tanks w/radioactive effluents & deleting hydrogen monitor requirement for waste gas holdup sys PARKER, W D Duke Power Co 81/01/12 1p 07511 149

--8101230496 Proposed Tech Specs Sections 3 & 4 changing explosive gas mixtures in tanks w/radioactive effluents & deleting requirement for hydrogen monitor in waste gas holdup sys
• Duke Power Co 81/01/12 5pp 07511 150

8101300150 Requests amend to License NPF-9, changing wording of Section 2 C. (12). Design of engineered safety features sys provides that all safety-related equipment will remain in emergency mode when actuations signal is reset PARKER, W D Duke Power Co 81/01/27 1p 07309:001

E NRC Safety Evaluation Report (SER), supp & correspondence

8101270931 SAFETY EVALUATION REPORT RELATED TO OPERATION OF MCGUIRE NUCLEAR STATION, UNITS 1 AND 2
• Office of Nuclear Reactor Regulation, Director NUREG-0422 504 81/01/31 100pp Available at NTIS \$6.00 07541:232

F Security, medical, emergency & fire protection plans

8101090287 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of EAR EISENHUT, B G Division of Licensing 80/11/13 2pp

8101150169 Forwards safeguards contingency plan, Revision 1 Revision withheld (ref 10CFR2 790) PARKER, W D Duke Power Co 80/12/17 1p 07462 213

8101100753 Requests that encl facility emergency planning info be made publicly available W/o encl SINGER, J L Division of Rules and Records 80/12/31 1p 07443:357

8101150462 Informs that NRC approved guard training & qualification plan will be implemented Security plan revision deleting all commitments not included Approved plan will be submitted PARKER, W D Duke Power Co 81/01/02 1p 07463 003

8101160443 Outlines util actions & schedule for implementing amended NRC fire protection regulations NRC consideration of proposed schedule as license condition or Unit 1 requested Schedule will be incorporated into Unit 2 const schedule PARKER, W D Duke Power Co 81/01/09 2pp 07470 002

8101190699 Requests that encl facility emergency planning info be made publicly available W/o encl SINGER, J L Division of Rules and Records 81/01/09 1p 07472 319

8101290159 Forwards facility emergency planning info to be made publicly available W/o encl EISENHUT, B G Division of Rules and Records 81/01/23 1p 07575:198

8101300436 Advises that util purchased Class 350 file cabinets & flammable liquid storage cabinets for use in interior rooms of control room area Class C doors installed Additions should provide 1 1/2-h fire rating PARKER, W D Duke Power Co 81/01/27 1p 07382 333

G Adjudicatory correspondence

8101050072 Request, submitted by Board of Commissioners, to participate as official observer in reopened hearings re Facility Pertinent documents requested FOX, C D Mecklenburg County, NC 80/12/23 1p 07376 289

8101090062 Notice of JL Riley 810114 deposition in Charlotte, NC to ascertain extent of Carolina Environ Study Group case re upcoming administrative hearing Certificate of Evc encl POLYMER, W L Duke Power Co 80/12/31 2pp 07427:303

8101090341 Notice of ASLAB constitution AS Rosenthal, chairman & Jrl & RS Galician, members TCMPEKINS, B A Atomic Safety and Licensing Appeal Panel 81/01/05 1p 07423 203

8101090261 Memorandum & order concluding stay of ASLB 801125 order re warranted, affirming order to extent reviewed & advising Commission that order raises no issues requiring prompt policy guidance BISHOP, C J Administrative Branch 81/01/06 4pp 07424 035

8101205395 Responds to Intervenor Carolina Environ Study Group 80112 1201:28 & 810108 interrogatories & requests for documents Certificate of Evc encl ISRAEL, S Reliability & Risk Assessment Branch JOHNSTON, W V Performance Branch CURTISS, J R Regulations Division 81/01/16 38pp 07486 276

8101090485 Informs of retainment as co-counsel w/JL Riley for intervenor Carolina Environ Study Group Requests all documents re hearings Appointment should enable advancement of intervenors position Affirmation of svc encl BLUM, S Blum, S 81/01/07 2pp 07309:001

8101140968 Motion to suppl 801107 Contentions 5 & 6 w/memorandum of law, No objection to extension for reply Certificate of Evc encl COHN, D B Public Citizen Litigation Group COHN, D B Carolina Environmental Study Group 81/01/08 4pp 07458:247

B101220210 Requests participation as interested govt body due to involvement in emergency planning
KJRE, Charlotte, NC B1/01/13 1p 07503 250

B101220910 Refuses request for addl documents Atty not retained by Carolina Environ Study Group, as previously stated & group has been furnished documents w/o encl of Comptroller General decision re procedural assistance
METCHEN, E O Hearing Branch 4 B1/01/16 1p 07501 337

B101260209 Response to Mecklenburg County Board of Commissioners & City of Charlotte B01231 & B01113 requests to participate
Applicant has no objection Certificate of Svc encl
FORTER, W L, MCCABRY, J M Duke Power Co B1/01/19 3pp
07523 304

B101260311 Memorandum supporting Carolina Environ Study Group Motion to add Contentions 5 & 6 advanced in B01107 reply to applicant motion for summary disposition Notice of appearance & Certificate of Svc encl
COMAN, D B Carolina Environmental Study Group B1/01/21 23pp
07536 034

H General correspondence

B101050371 Expresses concern that containment bldg at facility does not have enough strength to hold pressure during accident akin to that of TMI Mock evacuation needed in Charlotte, NC
SIELEDS, J Affiliation Unknown B0/12/15 2pp 07309 001

B101100119 Responds to B00930 ltr expressing concern re implementation of emergency plan for facility Plans are currently under review & must meet NRC criteria prior to issuance of PL
METCHEN, E O Hearing Branch 4 B0/12/15 1p 07445 013

B101230629 Responds to B01002 ltr re emergency & evacuation plans for facility DL hearings will address issue of emergency plans
NRC will determine if evacuation plans meet requirements
METCHEN, E O Hearing Branch 4 B0/12/15 1p 07512 275

B101050378 Expresses concern re water problems generated by facility urges NRC to reopen licensing hearings
ELLIS, B Affiliation Unknown B0/12/20 2pp 07309 001

B101090680 Demands licensing hearing be reopened Cites NRC B00626 rept. SECY-B0-107, showing facility containment pressure stds to be less stringent than TMI stds
WEBB, S P, HODGES, J M Affiliation Unknown B1/01/01 1p
07442 067

B101090680 Comments that facility is not safe, since hydrogen pressure equal to that of TMI accident could not be held by containment walls Certificate of Svc encl
UNDERWOOD, M A Affiliation Unknown B1/01/01 3pp 07309 001

B101090514 Requests that public hearings re facility licensing be reopened Until containment integrity is inadequate for withstanding hydrogen pressure event similar to TMI incident
UNDERWOOD, M A Affiliation Unknown B1/01/07 1p 07309 001

B101220216 Requests that licensing hearings be reopened to resolve health & safety issues Certificate of Svc encl
GUYTON, W M Affiliation Unknown B1/01/11 3pp 07503 251

J Insurance & indemnity information

B101290419 Confirms increase in liability limit under Policy NF-248 under EB-67 providing coverage under secondary financial protection policy has been executed & becomes effective on licensing date
HAINES, H American Nuclear Insurers B1/01/23 1p 07309 001

B101290591 Confirms MAELU Policy MF-101 coverage
ROBERTS, D Duke Power Co B1/01/23 1p 07183 001

Q Inspection reports, IE Bulletins & correspondence

B101070320 Forwards supplemental responses to NRC B01016 ltr re violations noted in IE Insp Repts 50-369/B0-08, 50-370/B0-05, 50-413/B0-09, 50-414/B0-09, 50-491/B0-02, 50-492/B0-06 & 50-493/B0-06 Final rept to be submitted by B10131
PARKER, W O Duke Power Co B0/11/11 2pp 07413 305

B101150015 Forwards IE Insp Rept 50-369/B0-34 on B01103-06 No noncompliance noted
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch, B0/12/05 2pp 07462 153

B101150017 IE Insp Rept 50-369/B0-24 on B01103-06 No noncompliance noted Major areas inspected radioactive mgt, radiation protection & ALARA considerations.
TRUMP, G L Region 2, Atlanta, Office of the Director B1B5
Region 2, Atlanta, Fuel Facility & Materials Safety Branch
B0/12/03 5pp 07452 155

B101070145 Ack receipt of IE Insp Rept 50-369/B0-24 on B00804-07 proprietary info
PARKER, W O Duke Power Co B0/12/11 1p 07469 020

--B101070152 Forwards IE Insp Rept 50-369/B0-24 on B00804-0730 No noncompliance noted
LEWIS, H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch, B0/11/21 2pp 07409 021

--B101070159 IE Insp Rept 50-369/B0-24 on B00804-0730 No noncompliance noted Major areas inspected preoperational test witnessing, procedure review & previous insp findings followup
DUMAT, J J, SMYLECKA, M B, SKINNER, P Region 2, Atlanta, Office of the Director B0/11/20 8pp 07409 023

B101060225 Forwards IE Info Notice B0-44, "Activation of ECCS in Recirculation Mode While in Hot Shutdown" No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director B0/11/20 3pp 07391 034

B101150907 Forwards Revision 4 of response to IE Bulletin 79-02, documenting commitment to complete necessary repairs prior to fuel load
PARKER, W O Duke Power Co B0/12/16 6pp 07465 001

B101150765 Ack receipt of IE Insp Rept 50-369/B0-36 on B01103 No noncompliance noted
PARKER, W O Duke Power Co B0/12/23 1p 07465 300

--B101150769 Forwards IE Insp Rept 50-369/B0-36 on B01103 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch, B0/12/05 2pp 07465 301

--B101150773 IE Insp Rept 50-369/B0-36 on B01103-06 No noncompliance noted Major areas inspected preservice insp data review & evaluation
ECCHEMOS, N Region 2, Atlanta, Office of the Director, HEAR
Region 2, Atlanta, Reactor Construction & Engineering Support Branch, B0/11/24 4pp 07465 303

B101160725 Ack receipt of IE Insp Repts 50-369/B0-33 & 50-370/B0-1B
B01104-07 No proprietary info
PARKER, W O Duke Power Co B0/12/31 1p 07472 047

--B101160728 Forwards IE Insp Repts 50-369/B0-33 & 50-370/B0-1B
B01104-07 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch, B0/12/12 2pp 07472 048

--B101160734 IE Insp Repts 50-369/B0-33 & 50-370/B0-1B on B01104-07 noncompliance noted Major areas inspected IE bulletins & licensee identified items
MCFARLAND, C R Region 2, Atlanta, Office of the Director
BRYAN, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch, B0/12/11 7pp 07472 050

B101290404 Responds to IE Bulletin B0-21, "Valve Yokes Supplied Malcolm Foundry Co, Inc." No valves have been identified from Malcolm Foundry Co manufacturer has not responded
PARKER, W O Duke Power Co B1/01/05 1p 07573 357

B101290492 Ack receipt of IE Insp Rept 50-369/B0-34 No proprietary info
PARKER, W O Duke Power Co B1/01/08 1p 07575 169

S Reportable occurrences, LERs & related correspondence

B101260513 Suppl 1 to Significant Deficiency Repts 50-369/B0-21 B0-16 re failure to consider containment vessel dynamic movements due to postulated LOCA, initially reported B01126 Analysis revised
PARKER, W O Duke Power Co B1/01/09 3pp 07529 238

DOCKETED TO THE ATTORNEY GENERAL'S OFFICE NUCLEAR DIVISION UNIT 2

A. Application documents, stage documents & correspondence

BIO121111 Ltr to all power reactor licensees & applicants forwarding summary of BIO1211 meeting re implementation of guidance for unresolved direct, issue A-12 Potential for Low Fracture Toughness & Lateral Leaking in Component Supports
BIO121111 G Division of Licensing 80/11/26 8pp

BIO121102 Forwards nonradiological environ protection plan for facility certain portions of plan revised to comply w/NRC requests for standardize emission programs
BIO121102 G Licensing Branch 1 80/12/10 3pp 07379 307

BIO121066 Envrn protection plan (nonradiological) for facility
BIO121066 G Licensing Branch 1 80/12/10 11pp 07379 310

BIO121044 Ack receipt of BIO1117 re hydrogen control measures Addl info requested re all recently developed info pertinent to evaluation of hydrogen control measure
BIO121044 G Assistant Director for Licensing 80/12/19 2pp 07414 173

BIO1210071 Forwards summary of BIO1217 meeting w/utl in Bethesda, MD re auxiliary, feedwater sys reliability evaluation
BIO1210071 G Licensing Branch 1 80/12/29 2pp 07446 319

BIO1210055 Summary of BIO1217 meeting w/utl in Bethesda, MD re improving reliability of auxiliary feedwater sys
BIO1210055 G Auxiliary Systems Branch 80/12/19 3pp 07446 321

BIO1210020 Forwards list of TLD station locations near facility & proposed route for exchanging TLDs for NRC direct radiation monitoring network w/o encl
BIO1210020 G Region C: Atlanta Fuel Facility & Materials Safety Branch 80/12/30 2pp 07475 309

BIO1210071 Notification of BIO102 meeting w/utl in Bethesda, MD to discuss surveillance requirements for piping sys snubbers & exemption request (valves) from mechanical snubber requirements
BIO1210071 G Licensing Branch 1 81/01/02 3pp 07464 360

BIO1220137 Forwards Analysis of Hydrogen Control Measures at McGuire Nuclear Station, Vol 3
BIO1220137 G Duke Power Co 81/01/05 1p 07494 010

BIO1220138 Analysis of Hydrogen Control Measures at McGuire Nuclear Station, Vol 3
BIO1220138 G Duke Power Co 81/01/05 78pp 07494 011

BIO1230193 Forwards proposed Tech Specs. changing explosive gas mixtures in tanks w/radioactive effluents & deleting hydrogen monitor requirement for waste gas holdup sys
BIO1230193 G Duke Power Co 81/01/12 1p 07511 149

BIO1230496 Proposed Tech Specs Sections 3 & 4 changing explosive gas mixtures in tanks w/radioactive effluents & deleting requirement for hydrogen monitor in waste gas holdup sys
BIO1230496 G Duke Power Co 81/01/12 2pp 07511 150

F. NRC Safety Evaluation Report (SER), supp's & correspondence

BIO1270731 SAFETY EVALUATION REPORT RELATED TO OPERATION OF MCGUIRE NUCLEAR STATION, UNITS 1 AND 2
BIO1270731 G Office of Nuclear Reactor Regulation, Director NUREG-0422 504 81/01/31 100pp Available at NTIS 96 00 07541 252

F. Security, medical, emergency & fire protection plans

BIO1260357 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of BIO1262 & by applicants as part of FSAR
BIO1260357 G Division of Licensing 80/11/13 2pp

BIO1253168 Forwards safeguards contingency plan, Revision 1 Revision withold (ref 10CFR2 790)
BIO1253168 G Duke Power Co 80/12/17 1p 07452 213

BIO1260753 Requests that encl facility emergency planning info be made publicly available w/o encl
BIO1260753 G Division of Rules and Records 80/12/31 1p

BIO1260753 Informs that NRC approved guard training & qualification plan will be implemented Security plan revision deleting all commitments not included Approved plan will be submitted
BIO1260753 G Duke Power Co 81/01/02 1p 07463 003

BIO1260443 Outlines util actions & schedule for implementing amended NRC fire protection regulations NRC consideration of proposed schedule as license condition of Unit 1 requested Schedule will be incorporated into Unit 2 const schedule
BIO1260443 G Duke Power Co 81/01/07 2pp 07470 082

BIO1260650 Requests that encl facility emergency planning info be made publicly available w/o encl
BIO1260650 G Division of Rules and Records 81/01/09 1p 07472 319

BIO1290158 Forwards facility emergency planning info to be made publicly available w/o encl
BIO1290158 G Division of Rules and Records 81/01/23 1p 07575 158

BIO1260436 Advises that util purchased Class 150 fire cabinets & flammable liquid storage cabinets for use in interior rooms of control room area Class C doors installed Additions should provide 1 1/2-h fire rating
BIO1260436 G Duke Power Co 81/01/27 1p 07582 353

G. Adjudicatory correspondence

BIO1050072 Request, submitted by Board of Commissioners, to participate as official observer in reopened hearings re facility. Pertinent documents requested
BIO1050072 G Mecklenburg County, NC 80/12/23 1p 07376 289

BIO1070062 Notice of JL Riley BIO114 deposition in Charlotte, NC to ascertain extent of Carolina Environ Study Group case re upcoming administrative hearing Certificate of Rev encl
BIO1070062 G Duke Power Co 80/12/31 2pp 07427 303

BIO1090331 Notice of AELAS constitution AS Rosenthal, chairman & JH Buck & RG Salzman, members
BIO1090331 G Atomic Safety and Licensing Appeal Panel 81/01/05 1p 07483 283

BIO1090268 Memorandum of order concluding stay of AELAS BIO1125 order not warranted, affirming order to extent reviewed & advising Commission that order raises no issues requiring prompt policy guidance
BIO1090268 G Administrative Branch 81/01/06 4pp 07424 035

BIO1200385 Responds to Intervenor Carolina Environ Study Group BIO1129, 1201.28 & BIO108 interrogatories & requests for documents. Certificate of Svc encl
BIO1200385 G ISRAEL, S Reliability & Risk Assessment Branch, JOHNSON, W V Core Performance Branch, CURTIS, J R Regulations Division 81/01/16 36pp 07486 276

BIO1090485 Informs of retainer as co-counsel w/JL Riley for intervenor Carolina Environ Study Group Requests all documents re hearings Appointment should enable advancement of intervenors position Affirmation of svc encl
BIO1090485 G Blum, S Blum, S 81/01/07 2pp 07309 001

BIO1140788 Motion to suppl BIO107 Contentions 5 & 6 w/memorandum of law in objection to extension for reply Certificate of Svc encl
BIO1140788 G Public Citizen Litigation Group, CONN, D B Carolina Environmental Study Group 81/01/08 4pp 07458 247

BIO1220210 Requests participation as interested govt body due to involvement in emergency planning
BIO1220210 G Charlotte, NC 81/01/13 1p 07503 250

BIO1220610 Refuses request for addl documents Atty not retained by Carolina Environ Study Group, as previously stated & group has been furnished documents w/o encl of Comptroller General decision re procedural assistance
BIO1220610 G Hearing Branch 4 81/01/16 1p 07501 337

BIO1260209 Response to Mecklenburg County Board of Commissioners & City of Charlotte BIO1231 & BIO113 requests to participate Applicant has no objection Certificate of Svc encl
BIO1260209 G PORTER, W L - MCCARRY, J M Duke Power Co 81/01/19 3pp 07523 304

DOCKETED ITEMS

0101260311 Memorandum supporting Carolina Environ Study Group Motion to add Contention 5 & 6 advanced in 011107 reply to applicant motion for summary disposition Notice of appearance & Certificate of Svc encl
CHAMBERS, D. B. Carolina Environmental Study Group 01/01/21 23pp
07536-034

H General correspondence

0101050371 Expresses concern that containment bldg at facility does not have enough strength to hold pressure during accident akin to that of TMI Mock evacuation needed in Charlotte, NC
SMITH, D. S. Affiliation Unknown 00/12/15 2pp 07309 001

010100117 Responds to 000930 ltr expressing concern re implementation of emergency plan for facility Plans are currently under review & must meet NRC criteria prior to issuance of OL
VETCHEM, E. G. Hearing Branch 4 00/12/15 1p 07445 019

0101230629 Responds to 010102 ltr re emergency & evacuation plans for facility OL hearings will address issue of emergency plans NRC will determine if evacuation plans meet requirements
VETCHEM, E. G. Hearing Branch 4 00/12/15 1p 07512 275

010103037B Expresses concern re water problems generated by facility Urges NRC to reopen licensing hearings
ELLS, B. Affiliation Unknown 00/12/20 2pp 07309 001

0101090680 Demands licensing hearing be reopened Cites NRC 000626 reprob. 6ECY-00-107, showing facility containment pressure stds to be less stringent than TMI stds
WEST, S. P., HODGES, J. M. Affiliation Unknown 01/01/01 1p 07442 067

0101090680 Comments that facility is not safe, since hydrogen pressure equal to that of TMI accident could not be held by containment walls Certificate of Svc encl
UNDERWOOD, M. A. Affiliation Unknown 01/01/01 3pp 07309 001

0101090514 Requests that public hearings re facility licensing be reopened. Util containment integrity is inadequate for withstanding hydrogen pressure event similar to TMI incident
UNDERWOOD, M. A. Affiliation Unknown 01/01/07 1p 07309 001

0101220216 Requests that licensing hearings be reopened to resolve health & safety issues Certificate of Svc encl
CUPTON, W. H. Affiliation Unknown 01/01/11 3pp 07503 251

J Insurance & indemnity information

0101290419 Confirms increase in liability limit under Policy NF-248 Binder EB-69 providing coverage under secondary financial protection policy has been executed & becomes effective on licensing date
WAINES, H. American Nuclear Insurers 01/01/23 1p 07309 001

0101290591 Confirms MAELU Policy MF-101 coverage.
ROBERTS, D. Duke Power Co. 01/01/23 1p 07183 001.

Q Inspection reports, IE Bulletins & correspondence

0101070320 Forwards supplemental responses to NRC 001016 ltr re violations noted in IE Insp Repts 50-369/80-08, 50-370/80-03, 50-413/80-07, 50-414/80-09, 50-491/80-02, 50-492/80-06 & 50-493/80-06. Final rept to be submitted by 010131
PARKER, W. D. Duke Power Co. 00/11/11 2pp 07413 305.

0101060225 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown." No written response required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 00/12/16 1p 07391-334

0101150907 Forwards Revision 4 of response to IE Bulletin 79-02, documenting commitment to complete necessary repairs prior to fuel load.
PARKER, W. D. Duke Power Co. 00/12/16 5pp 07465 001

0101160724 Ack receipt of IE Insp Repts 50-369/80-33 & 50-370/80-18 on 011104-07 No proprietary info
PARKER, W. D. Duke Power Co. 00/12/31 1p 07472-047.

--0101160728 Forwards IE Insp Repts 50-369/80-33 & 50-370/80-18 on 011104-07. No noncompliance noted
BURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering

0101150734 IE Insp Repts 50-369/80-33 & 50-370/80-18 on 011104-07. Noncompliance noted. Major areas inspected IE bulletins & licensee identified items
McFARLAND, R. Region 2, Atlanta, Office of the Director
BRAY, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/12/11 7pp 07472 050

0101290404 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." No valves have been identified from Malcolm Foundry Co. manufacturer has not responded
PARKER, W. D. Duke Power Co. 01/01/05 1p 07573 357

S Reportable occurrences, LFRs & related correspondence

0101260513 Suppl 1 to Significant Deficiency Repts SD 369/80-21 & SD 369/80-16 re failure to consider containment vessel dynamic movements due to postulated LOCA. Initially reported 011126 Analysis revised
PARKER, W. D. Duke Power Co. 01/01/09 3pp 07529 238

DOCKET 00-073 LASALLE COUNTY STATION, UNIT 1

A Application/construction stage documents & correspondence

0101300297 Forwards "LaSalle County Units 1 & 2 Equipment Qualification, Vols 1-3 & "LaSalle 1 & 2 NSSS Safety-Related Equipment List." Revision 1 Repts available in Central Files only
SINKAPANI, J. Sargent & Lundy, Inc. 00/10/30 1p 07183 001

0101220466 Ltr to all power reactor licensees & applicants forwarding summary of 011112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
TEDESCO, R. L. Division of Licensing 00/11/26 0pp

0101190505 Ltr to all BWR applicants for CL re BWR screen discharge safety evaluation & requirements Rept specifying acceptable basis for continued BWR plant operation & design criteria for screen discharge vol encl
TEDESCO, R. L. Assistant Director for Licensing 00/12/22 2pp

--0101190514 Forwards generic safety evaluation re BWR screen discharge sys Review identified two addl requirements to those proposed by owners group re screen discharge vol designs Rept should be transmitted to license applicants
CHECK, P. S. Assistant Director for Plant Systems 00/12/01 2p 07183 001.

0101200157 Summary of 010120 meeting w/Mark II owners re status of generic improved chugging load model Owners requested to justify delay in program & investigate alternatives
ANDERSON, C. J. Generic Issues Branch 00/12/22 4pp

0101100263 Forwards trip rept of 010124-31 site visit to perform drawing review
BOURINIA, A. Licensing Branch 1 00/12/29 3pp 07444 233

0101140955 Summary of Dec 1980 meeting w/Mark II owners group, GE, BN, MIT, ESW, Bechtel & Babcock & Wilcox Svcs. Inc re suppression pool temp limits List of attendees & handouts encl
EUT, H. Generic Issues Branch 00/12/30 41pp

0101140512 Forwards suppl info re valve discharge case design basis Frequency range & air clearing load assessment per 011120 telcon
DELGECRE, L. O. Commonwealth Edison Co. 01/01/08 5pp 07461 1

0101200245 Forwards Licensing Topical Rept NEDD-24057A, "Assessment of Reactor Internals Vibration in BWR/4 & BWR/5 Plants." & NRC evaluation
DELGECRE, L. O. Commonwealth Edison Co. 01/01/15 2pp 07487 0

0101290394 Forwards floodplain aspects Plant structures will have negligible effect on post-onset water levels during flood
YOUNGBLOOD, B. J. Licensing Branch 1. 01/01/16 4pp 07569 001

0101300818 Requests commitments to special low power test program for facility & augmented operator training for compliance w/TMI test action item 1 G 1.
TEDESCO, R. L. Assistant Director for Licensing 01/01/16 3pp 07183 001

010122036B Forwards offsite dose calculation sys description per meteorological data requirements in NUREG-0737 Task 111 A 2
DELGECRE, L. O. Commonwealth Edison Co. 01/01/19 1p

- B10123374 Offsite Dose Calculation Sys Meteorological Monitoring
Diffsite Dose Calculation Program For Emergency Preparedness
at Operating Nuclear Power Plants. Revision 2
COMMONWEALTH Edison Co 80/07/31 120pp

--B10123379 Study of Low Level Dispersion Over Northern IL
Murray S. Trettel, Inc 74/06/30 106pp

F. Security, medical, emergency & fire protection plans

B101090257 Ltr to all licensees of operating reactor plants, CP holders
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B10102 & by applicants as part of FSAR
BELGEORGE, L. D. Commonwealth Edison Co 80/11/12 2pp

J. Insurance & security information

B101270614 Forwards Enforcements 125 & 126.65 & 66.93 & 94. & 13 & 14
to MELIA Policies NF-43, NF-107, NF-201 & NF-253, respectively
OSTER, J. Commonwealth Edison Co 81/01/21 13pp

K. Utility Final Safety Analysis Report (FSAR) & amendments

B101190352 Forwards affidavit stating that distribution of FSAR
Amend 53 has been made
BELGEORGE, L. D. Commonwealth Edison Co 80/12/30 2pp 07476 027

P. Operating license stage documents & correspondence

B101090601 Forwards Revision 15 pages to CE-1-A-04 program topical
rept Revisions reflect Surber 1980 addenda to Section III of
ASME code & recent ASME survey for renewal of ASME
corporate certifications
ABEL, J. S. Commonwealth Edison Co 81/01/02 1p

- B101090605 Revision 15 pages to QA program topical rept
Commonwealth Edison Co CE-1-A R15 81/01/02 57pp

Q. Inspection reports, IE Bulletins & correspondence

B101090749 Forwards IE Info Notice 80-18, "Cracking in Charging Pump
Casing Cladding." No response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/10/30
2pp

B101090462 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm
Foundry Co. Inc." Written response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/11/06
2pp

B101130574 Forwards IE Insp Rept 50-373/80-43 on 800915-1020 & notice
of violation
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support
Branch 80/11/12 2pp 07453 214

--B101130593 Notice of violation from insp on 800915-1020
Region 3, Chicago, Office of the Director 80/11/10 1p
07453 216

--B101130592 IE Insp Rept 50-373/80-43 on 800915-1020 Noncompliance
noted, failure to notify NRC of each design & const
deficiency
WALKER, R. D., SHEPLEY, S. E., SPESSARD, R. L. Region 3, Chicago, Office
of the Director 80/11/10 13pp 07453 217

B101140847 Forwards IE Insp Repts 50-373/80-47 & 50-374/80-29 on
801027-31 No noncompliance noted
DAVIS, A. B. Region 3, Chicago, Fuel Facility & Materials Safety
Branch 80/12/04 2pp 07461 040

--B101140853 IE Insp Repts 50-373/80-47 & 50-374/80-29 on 801027-31 No
noncompliance noted Major areas inspected emergency
planning, coordination w/ offsite agencies & emergency
planning exercise discussion
BERTMAN, H. J., AIFLSEN, W., PAPERIELLO, C. J. Region 3, Chicago,
Office of the Director 80/12/05 9pp 07461 042

B101090930 Forwards IE Info Notice 80-43, "Failures of Continuous Water
Level Monitor for Scram Discharge Val at Dresden Unit 2." No
response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/12/05
2pp

B101150779 Forwards IE Insp Rept 50-373/80-51 on 801125-26 No
noncompliance noted
DAVIS, A. B. Region 3, Chicago, Fuel Facility & Materials Safety
Branch 80/12/09 2pp 07465 307

- B101150787 IE Insp Rept 50-373/80-51 on 801125-26 No noncompliance
noted Major areas inspected radwaste mgmt program & FSAR
commitment conformance
LOVEHDALE, P. C. Region 3, Chicago, Office of the Director
FISHER, W. L. Region 3, Chicago, Fuel Facility & Materials Safety
Branch 80/12/08 3pp 07465 309

B101150654 Forwards IE Insp Repts 50-373/80-50 & 50-374/80-31 on
801119-21 & notice of violation
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support
Branch 80/12/12 2pp 07465 280

--B101150658 Notice of violation from insp on 801119-21
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear
Support Branch 80/12/11 2pp 07465 282

--B101150653 IE Insp Repts 50-373/80-50 & 50-374/80-31 on 801119-21
Noncompliance noted various fire fighting hose mounts
unstructed by const. matls, several mounts damaged or
improperly made up & several isolation valves inoperable
DUPOUIT, S. G., SPESSARD, R. L. Region 3, Chicago, Office of the
Director 80/12/11 5pp 07465 284

B101080360 Forwards IE Info Notice 80-45, "Potential Failure of BWR
Startup Manual Scram Capability." No written response
required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/12/17
2pp

B101150230 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of Control
Rods to Insert During Scram at BWR." No Written response
required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/12/18
2pp 07465 345

B101090186 Forwards IE Bulletin 80-25, "Operating Problems W/Target
Roll Safety Relief Valves at BWRs." No response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/12/17
2pp 07377 319

B101130667 Responds to 801114 ltr re IE Bulletin 80-23 No Valcor
solenoid valves V70900-21-1 or V70900-21-3 are in use at
LaSalle County Station Rept addressing affected valves at
Byron & Braidwood Stations to be submitted by 810212
RAUSCH, H. J. Commonwealth Edison Co 80/12/29 2pp 07454 033

B101200528 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by
Malcolm Foundry Co. Inc." LaSalle County Station contains 138
safety-related valves cast by Malcolm & mfg by Anchor-
Darling Valve Co Valves will be replaced
HAUSCH, T. J. Commonwealth Edison Co 81/01/06 2pp 07487 046

B101270851 Ack receipt of 801215 ltr in response to item of
noncompliance noted in IE Insp Rept 50-373/80-43 Improper
lugging wiring on Control Room Panel H13-P603 must be
reported as significant deficiency per 10CFR50.55(e)
KEPPLER, J. G. Region 3, Chicago, Office of the Director 81/01/07
2pp 07549 122

B101290339 Forwards request for addl info re 800708 response to IE
Bulletin 80-11, "Masonry Wall Design." Info is needed on how
loads are transferred from walls to columns & design
adequacy of walls w/o relying on tensile stresses
TEDESCO, R. L. Assistant Director for Licensing 81/01/19 4pp
07575 228

S. Reportable occurrences, IERs & related correspondence

B101050415 Provides 30-day notification of possible deficiency re
incorrect suppression pool water vol in FSAR, initially
reported 801126 Caused by diffused responsibility for
calculation Pool temp transient will be reanalyzed
BELGEORGE, L. D. Commonwealth Edison Co 80/12/24 2pp 07379 28

B101230417 Final deficiency rept re electrical termination lug design
Insp of control room panels & replacement of improper lugs
completed
ABEL, J. S. Commonwealth Edison Co 81/01/19 2pp 07511 118

B101230433 Final deficiency rept re valve yoke matl in Anchor/Darling
Valves, initially reported on 801218 Schedule has been
established for shipment of 138 new yokes between 810227 &
0424 Defective yokes will be replaced & destroyed
BELGEORGE, L. D. Commonwealth Edison Co 81/01/19 2pp 07511 118

V Operator Examinations

B010300818 Requests commitments to special low power test program for facility & augmented operator training for compliance w/THI task action item 1 G 1
TEDESCO, R L Assistant Director for Licensing B1/01/16 3pp
07183 C01

DOCKEY 50-374 LASALLE COUNTY STATION, UNIT 2

A Application/construction stage documents & correspondence

B010300297 Forwards "LaSalle County Units 1 & 2 Equipment Qualification," Vols 1-3 & "LaSalle 1 & 2 N585 Safety-Related Equipment List," Revision 1 Repts available in Central Files only
SINRAPAN, J Barget & Lundy, Inc B0/10/30 1p 07183 C01

B010220464 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing B0/11/26 8pp

B010200157 Summary of B01210 meeting w/Mark II owners re status of generic improved chugging load model. Owners requested to justify delay in program & investigate alternatives
ANDERSON, C J Generic Issues Branch B0/12/22 4pp

B010100263 Forwards trip rept of B01024-31 site visit to perform drawing review
BOURNIA, A Licensing Branch 1 B0/12/27 3pp 07444 233

B010100955 Summary of Dec 1980 meeting w/Mark II owners group, OE, BNL, MIT, GE, Westinghouse & Esasco Bvcs, Inc re suppression pool temp limits List of attendees & handouts encl
EU, T M Generic Issues Branch B0/12/30 41pp

B010100512 Forwards suppl info re valve discharge case design basic frequency range & air clearing load assessment per B01120 telcon
DELDORGE, L D Commonwealth Edison Co B1/01/08 3pp 07461 162

B010200245 Forwards Licensing Topical Rept NEDU-24057A, "Assessment of Reactor Internals Vibration in BWR/4 & BWR/5 Plants," & HRC evaluation
DELDORGE, L D Commonwealth Edison Co B1/01/15 2pp 07487 C01

B010200394 Forwards floodplain aspects Plant structures will have negligible effect on post-cons water levels during flood
YOUNGBLOOD, B J Licensing Branch 1 B1/01/16 4pp 07969 C01

B010300818 Requests commitments to special low power test program for facility & augmented operator training for compliance w/THI task action item 1 G 1
TEDESCO, R L Assistant Director for Licensing B1/01/16 3pp
07183 C01

B010220368 Forwards offsite dose calculation sys description per meteorological data requirements in NUREG-0737 Task III, A 2
DELDORGE, L D Commonwealth Edison Co B1/01/19 1p

--B010220374 "Offsite Dose Calculation Sys Meteorological Monitoring, Offsite Dose Calculation Program for Emergency Preparedness at Operating Nuclear Power Plants," Revision 2
GOLDEN, J C Commonwealth Edison Co B0/07/31 130pp

--B010220379 "Study of Low Level Dispersion Over Northern IL"
Murray & Trettel, Inc 74/06/30 106pp

F Security, medical, emergency & fire protection plans

B01090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B010102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing B0/11/13 2pp

X Utility Final Safety Analysis Report (FSAR) & amendments

B010190352 Forwards affidavit stating that distribution of FSAR Amend 53 has been made
DELDORGE, L D Commonwealth Edison Co B0/12/30 2pp 07476 027

F Operating license stage documents & correspondence

B01090001 Forwards Revision 15 pages to CE-1-A, QA program topical rept. Revisions reflect Summer 1980 addenda to Section III of ASME code & recent ASME survey for renewal of ASME corporate certifications
ASSEL, J S Commonwealth Edison Co B1/01/02 1p

--B01090005 Revision 15 pages to QA program topical rept
Commonwealth Edison Co CE-1-A R15 B1/01/02 37pp

G Inspection reports, IF Bulletins & correspondence

B01050249 Forwards IE Info Notice B0-38, "Cracking in Charging Pump Casing Cladding." No response required
KEPLER, J G Region 3, Chicago, Office of the Director B0/10/30 2pp

B01050462 Forwards IE Bulletin B0-21, "Valve Vokes Supplied by Mall Foundry Co, Inc." Written response required
KEPLER, J G Region 3, Chicago, Office of the Director B0/11/00 2pp

B01040847 Forwards IE Insp Repts 50-373/B0-47 & 50-374/B0-24 on B01029-31 No noncompliance noted
DAVIS, A D Region 3, Chicago, Fuel Facility & Materials Safety Branch B0/12/04 2pp 07461 C40

--B01040858 IE Insp Repts 50-373/B0-47 & 50-374/B0-29 on B01029-31 Noncompliance noted. Major areas inspected: emergency planning, coordination w/offsite agencies & emergency planning exercise discussion
CEBTHAIN, H J, AXELSON, W, PAPERIELLO, C J Region 3, Chicago, Office of the Director B0/12/05 7pp 07461 C42

B01050530 Forwards IE Info Notice B0-43, "Failures of Continuous Level Monitor for Scram Discharge Val at Dresden Unit 2." No response required
KEPLER, J G Region 3, Chicago, Office of the Director B0/12/00 2pp

B01050651 Forwards IE Insp Repts 50-373/B0-50 & 50-374/B0-31 on B01019-21 & notice of violation.
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch B0/12/12 2pp 07465 280

--B01050658 Notice of violation from insp on B01019-21
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch B0/12/11 2pp 07465 282

--B01050663 IE Insp Repts 50-373/B0-50 & 50-374/B0-31 on B01019-21 Noncompliance noted. Various fire fighting hose mounts obstructed by const. mtl's, several mounts damaged or improperly rated up & several isolation valves inoperable
DUPONT, S O, SPRESSARD, R L Region 3, Chicago, Office of the Director B0/12/11 3pp 07465 284

B010230678 Forwards IE Insp Rept 50-374/B0-32 on B01017-20 No noncompliance noted
FIGIELLO, G Region 3, Chicago, Reactor Construction & Engineering Support Branch B0/12/12 2pp 07512 353

--B010230687 IE Insp Rept 50-374/B0-32 on B01017-20 No noncompliance noted. Major areas inspected: work activities & nondestructive testing, records & control of equipment & mtl re installation & welding of safety-related piping
KEY, W J Region 3, Chicago, Office of the Director DANIELSON, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch B0/12/10 7pp 07512 355

B01090060 Forwards IE Info Notice B0-45, "Potential Failure of UW Backup Manual Scram Capability." No written response required
KEPLER, J G Region 3, Chicago, Office of the Director B0/12/00 2pp

B01050230 Forwards Suppl 4 to IE Bulletin B0-17, "Failure of Cont Rods to Insert During Scram at BWR." No written response required
KEPLER, J G Region 3, Chicago, Office of the Director B0/12/00 2pp 07465 345

B01050106 Forwards IE Bulletin B0-25, "Operating Problems w/Target Rock Safety Relief Valves at BWRs." No response required.
KEPLER, J G Region 3, Chicago, Office of the Director B0/12/00 07377 319

B101130667 Response to B01114 ltr re IE Bulletin B0-23 No Valcor solenoid valves V70900-21-1 or V70930-21-3 are in use at LaSalle County Station Rept addressing affected valves at Byron B Braidwood Stations to be submitted by B10212 RAUSCH, T J Commonwealth Edison Co B0/12/29 2pp 07454 033

B101203528 Response to IE Bulletin B0-21. Valve Yokes Supplied by Malcolm Foundry Co. Inc. LaSalle County Station contains 138 safety-related valves cast by Malcolm & mfg by Anchor-Darling Valve Co Valves will be replaced RAUSCH, T J Commonwealth Edison Co B1/01/06 2pp 07467 046

B101270337 Forwards request for addl info re B00768 response to IE Bulletin B0-11. "Masson, Wall Design." Info is needed on how loads are transferred from walls to columns & design adequacy of walls w/o relying on tensile stresses TEDESCO, R L Assistant Director for Licensing B1/01/19 4pp 07575 228

H Reportable occurrences, LTRs & related correspondence

B101050415 Provides 30-day notification of possible deficiency re incorrect suppression pool water vol in PSAR, initially reported B01126 Caused by diffused responsibility for calculation Pool temp transient will be reanalyzed DELGEORGE, L D Commonwealth Edison Co B0/12/24 2pp 07379 287

B101230417 Final deficiency rept re electrical termination lug design Insp of control room panels & replacement of improper lugs completed ABEL, J S Commonwealth Edison Co B1/01/19 2pp 07511 118

B101230433 Final deficiency rept re valve yoke matl in Anchor/Darling Valves, initially reported on B01218 Schedule has been established for shipment of 138 new yokes between B01227 & Q424 Defective yokes will be replaced & destroyed. DELGEORGE, L D Commonwealth Edison Co B1/01/19 2pp 07511 122

V Operator Examinations

B101300818 Requests commitments to special low power test program for facility & augmented operator training for compliance w/FMI task action item 1 Q 1 TEDESCO, R L Assistant Director for Licensing B1/01/16 3pp

BUCKET 30-376 NORTH COAST NUCLEAR PLANT

G Adjudicatory correspondence

B101050632 Response to ASLB B01216 order, supporting applicant B00911 motion for termination of proceeding & withdrawal of application w/o prejudice, Notice of appearance & Certificate of Svc encl GUTIERREZ, J H Hearing Branch 3 B0/12/31 14pp 07397 093

B101090094 Reply to intervenor B01203 submittal stating withdrawal application should be dismissed w/prejudice Accusation of hidden, deceitful action is unsubstantiated Proceeding should be terminated w/o prejudice W/Certificate of Svc AXELRAD, M Puerto Rico Electric Power Authority, AXELRAD, M Lewenstein, Newman, Reis, Axelrad & Toll B0/12/31 22pp 07426 271

BUCKET 30-382 WATERFORD GENERATING STATION, UNIT 3

A Application/construction stage documents & correspondence

B101720465 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" EISENHUT, D O Division of Licensing B0/11/26 8pp

B101060728 Notification of changed room assignment for B01223 meeting w/C-E in Bethesda, MD to receive presentation on proposed demonstration irradiation of experimental test assemblies for H1-burnup TAKAR, M Core Performance Branch B0/12/19 2pp 07401 104

B101070359 Responds to DG Eisenhower B01001 ltr re environ qualification of safety-related equipment Listing of identified class IE equipment for which qualification testing has not been completed encl MAURIN, L V Louisiana Power & Light Co B0/12/26 3pp 07410 336

B101160025 Notification of B01113-15 meeting w/util in Taft, LA re performance of caseload forecast to determine priorities for allocating NRC manpower. Proposed agenda encl KEOUSEK, S Licensing Branch 2 B1/01/05 6pp 07469 262

B101270413 Summary of B01223 meeting w/util & C-E in Bethesda, MD to discuss demonstration fuel assemblies NRC encourages use of small numbers of assemblies w/experimental fuel designs Recommends exam to yield info re safety analysis PCKERS, D A Core Performance Branch B1/01/14 3pp 07549 039

B101220532 Concurs w/Oct 1982 fuel load data as determined at NRC B10113-15 case load forecast panel meeting Applicant advocates status rept approach to SER, fire protection & structural engineering reviews WYATT, J H Louisiana Power & Light Co B1/01/19 2pp 07502 265

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of PSAR EISENHUT, D O Division of Licensing B0/11/13 2pp

B101100034 Amended notification of B10107 meeting w/util in Bethesda, MD to discuss physical security plan & operator training NAME, W F Licensing Branch 2 B0/12/24 3pp 07443 028

B101140473 Notification of B10107 meeting w/util in Bethesda, MD to discuss physical security plan NAME, W F Licensing Branch 2 B0/12/24 3pp 07458 144

M Antitrust correspondence

B101140593 Requests that files on util activities be made available to NRC for OL antitrust review RUTBEND, J Antitrust Division B1/01/09 1p 07308 001

Q Inspection reports, IE Bulletins & correspondence

B101070257 Forwards IE Mgt Meeting Rept 90-382/B0-29 on B01027. SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch B0/11/14 1p 07415 108

--B101070261 IE Mgt Meeting Rept 90-382/B0-29 on B01027 Major area discussed licensee performance evaluation. SEYFRIT, K V, CROSSMAN, W A Region 4, Dallas, Office of the Director, SEIDLE, W C, Region 4, Dallas, Reactor Construction & Engineering Support Branch B0/11/07 9pp 07415 189

B101070247 Forwards IE Insp Rept 90-382/B0-25 on B00916-1015 No noncompliance noted MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch B0/11/19 2pp 07415 183

--B101070252 IE Insp Rept 90-382/B0-25 on B00916-1015 No noncompliance noted Major areas inspected operational staffing, overall preoperational test program & plant tours CONSTABLE, Q E, DUBOIS, D L, WESTERMAN, R F Region 4, Dallas, Office of the Director B0/11/18 3pp 07415 185

B101120093 Forwards IE Insp Rept 90-382/B0-28 on B01021-24 No noncompliance noted. SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch B0/11/24 2pp 07446 052

--B101120096 IE Insp Rept 90-382/B0-28 on B01021-24 No noncompliance noted Major areas inspected safety-related const activities pertaining to electrical cable installation, Insp & documentation JOHNSON, A R Region 4, Dallas, Reactor Construction & Engineering Support Branch MARTIN, L E, STEWART, R C Region 4, Dallas, Office of the Director B0/11/21 6pp 07446 054

B101140495 Forwards IE Insp Rept 90-382/B0-31 on B01117-20 No noncompliance noted. SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch B0/12/05 2pp 07461 282

--B101140500 IE Insp Rept 90-382/B0-31 on B01117-20 No noncompliance noted Major areas inspected safety-related electrical cable & penetration assembly installation const activities. MARTIN, L E, STEWART, R C, CROSSMAN, W A Region 4, Dallas, Office of the Director B0/12/05 4pp 07461 284

B101050621 Forwards IE Info Notice B0-43, "Failures of Continuous Water Level Monitor for Scram Discharge Vol at Dresden Unit 2." No response required. SEYFRIT, K V Region 4, Dallas, Office of the Director B0/12/08 1p 07391 055

8101209502 Forwards IE Investigation Rept 50-382/80-17 on 800731-0801, 21.0918 & 1119-21 No noncompliance noted
SEIDLE, W. C. Region 4, Dallas. Reactor Construction & Engineering Support Branch 80/12/09 2pp 07477 330

--8101200508 IE Investigation Rept 50-382/80-17 on 800731-0801, 21.0918 & 1119-21 No noncompliance noted Major areas investigated
allegations re possible const deficiencies
STENHART, R. C. CHROSMAN, W. A. Region 4, Dallas. Office of the Director 10th INSON, D. P. Region 4, Dallas. Reactor Construction & Engineering Support Branch 80/12/09 9pp 07477 332

--8101200508 IE Investigation Rept 50-382/80-17 on 800731-0801, 21.0918 & 1119-21 No noncompliance noted Major areas investigated
allegations re possible const deficiencies
STENHART, R. C. Region 4, Dallas. Office of the Director HALL, R. E. Region 4, Dallas. Reactor Construction & Engineering Support Branch 80/12/09 9pp

8101060187 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown." No written response required
SEYFRIT, K. V. Region 4, Dallas. Office of the Director 80/12/16 1p 07391 296

8101100748 Ack receipt of 801128 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 90-382/80-26
SEIDLE, W. C. Region 4, Dallas. Reactor Construction & Engineering Support Branch 80/12/23 1p 07444 130

--8101100752 Responds to NRC 801031 ltr re violations noted in IE Insp Rept 50-382/80-26 Corrective actions lines blown out w/air & valves capped off
ASWELL, D. L. Louisiana Power & Light Co 80/11/28 3pp 07444 131

S Reportable occurrences, LERs & related correspondence

8101070384 Final Significant Const Deficiency Repts 6 & 10 re emergency diesel generator defective shafts & springs & defective emergency diesel generator roller pins, initially reported 780725 & 1103, respectively Shafts replaced & pins repaired
ASWELL, D. L. Louisiana Power & Light Co 80/09/23 7pp 07414 099

8101090500 Interim rept of Significant Const Deficiency 20 re inadequate design & review of instrumentation seismic support drawings Results of review & analysis of drawings provided. Design change or field change request issued
MCLENDEN, G. D., MILHISER, R. J., WILLIS, J. Louisiana Power & Light Co 81/01/09 4pp 07442 079

V. Operator Examinations

8101100034 Amended notification of 810107 meeting w/util in Bethesda, MD to discuss physical security plan & operator training
KAINE, W. F. Licensing Branch 2 80/12/24 3pp 07443 020

DOCKET 90-367 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1

A. Application/construction stage documents & correspondence

8101090067 Releases public version of util emergency plan
FELTDN, J. M. Division of Rules and Records 80/11/13 1p 07440 001

--8101090071 Forwards public version of request for Amend 25 to application for DL, consisting of Revision 2 to emergency plan
CURTIS, N. W. Pennsylvania Power & Light Co. 80/10/31 1p 07440:003

--8101090075 Public version of Amend 25 to application for DL, consisting of Revision 2 to util emergency plan
CURTIS, N. W. Pennsylvania Power & Light Co. 80/10/31 1p 07440:004

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D. O. Division of Licensing 80/11/26 8pp

8101220669 Notification of rescheduling of 810127-29 meeting to 810303-05 w/util in Allentown, PA re agt structure & technical resources.
STARKE, R. H. Licensing Branch 1 80/12/16 3pp 07502 007

8101090902 Forwards request for addl info per review of DL application power sys area & in procedures & test review branches
TEDESCO, R. L. Assistant Director for Licensing 80/12/22 15pp 07593 266

8101190505 Ltr to all BWR applicants for DL re BWR scram discharge safety evaluation & requirements Rept specifying acceptable basis for continued BWR plant operation & design criteria for scram discharge vol entl
TEDESCO, R. L. Assistant Director for Licensing 80/12/22 2pp

--8101190514 Forwards generic safety evaluation re BWR scram discharge Review identified two addl requirements to those proposed by owners group re scram discharge vol designs Rept should be transmitted to license applicants
CHECK, P. S. Assistant Director for Plant Systems 80/12/01 2 07183 001

8101200157 Summary of 801210 meeting w/Mark II owners re status of generic improved chugging load model Owners requested to justify delay in program & investigate alternatives
ANDERSON, C. J. Generic Issues Branch 80/12/22 4pp

8101080196 Notification of 810115 meeting w/util in Bethesda, MD to discuss applicant responses to NRC questions & positions concerning initial test program
STARKE, R. H. Licensing Branch 1 80/12/23 3pp 07421 032

8101210297 Summary of 801110-19 meeting w/PN&L in Bethesda, MD re control room habitability
KRUOG, H. E. Accident Evaluation Branch 80/12/24 4pp 07493 001

8101140955 Summary of Dec 1980 meeting w/Mark II owners group, GE, BN, MIT, SSW, Jochel & Ebasco Svcs, Inc re suppression pool temp limits list of attendees & handouts encl
EART, M. Generic Issues Branch 80/12/30 41pp

8101130466 Forwards slides presented during 801218 meeting
CURTIS, N. W. Pennsylvania Power & Light Co 81/01/02 1p 07308 001

8101130320 Forwards info re fish impingement & entrainment in response to ALE request concerning input to FEG Final & operations phase NPDES permit encl
CURTIS, N. W. Pennsylvania Power & Light Co 81/01/05 44pp 07308 001

8101270482 Submits info re facility operations during low river flow conditions, in response to NRC request Util plans to replace water taken from Susquehanna River during low flow by using water from existing reservoir or Pond Hill Reservoir
CURTIS, N. W. Pennsylvania Power & Light Co 81/01/07 1p 07349 063

8101120189 Forwards Amend 27 to util 790731 application for DLs, containing Revision 19 to FSAR
CURTIS, N. W. Pennsylvania Power & Light Co. 81/01/09 2pp 07436 001

8101190387 Forwards "Seismic Category I Essential Components for Susquehanna 1 & 2 NBSB Equipment Only," supplementing 801216 equipment qualification info package
CURTIS, N. W. Pennsylvania Power & Light Co 81/01/09 1p 07474 185

--8101190390 "Seismic Category I Essential Components for Susquehanna 1 & 2 NBSB Equipment Only"
Pennsylvania Power & Light Co 81/01/09 88pp 07474 186

8101300825 Requests commitments to special low power test program facility & augmented operator training, for compliance w/THI task action item 1.0
TEDESCO, R. L. Assistant Director for Licensing 81/01/16 3pp 07183 001

8101260370 Forwards util response to NUREG-0737 THI-related requirements Meeting to discuss response requested
CURTIS, N. W. Pennsylvania Power & Light Co 81/01/22 87pp 07525 252

8101280151 Forwards application for amend of CPPR-101 & CPPR-102, to extend const completion dates, Class I & Class II fees encl
SNAPP, R. A. Pennsylvania Power & Light Co 81/01/23 2pp 07558 042

--8101280158 Application for amend of CPPR-101 & CPPR-102 to extend completion dates to 820231 for CPPR-101 & 840331 for CPPR-102
CURTIS, N. W. Pennsylvania Power & Light Co 81/01/23 3pp 07558 014

8101030500 Submits update on farm survey in vicinity of facility
CURTIS, N W Pennsylvania Power & Light Co 81/01/27 2pp
07587 072

D NRC Draft/Final Environmental Statements, suppis & correspondence

8101130370 Forwards info re fish impingement & entrainment in response
to ARL request concerning input to FES Final & operations
phase 3 PDES permit encl
CURTIS, N W Pennsylvania Power & Light Co 81/01/05 44pp
07308 001

F NRC Safety Evaluation Report (SER), suppis & correspondence

8101050502 Requests schedule of completion for organizational changes
at facility prior to proposed NRC 810127-29 visit re SER
preparation
EISENHUT, D G Division of Licensing 80/12/15 2pp 07337 286

F Security, medical, emergency & fire protection plans

8101050507 Releases public version of util emergency plan
FELTON, J M Division of Rules and Records 80/11/13 1p
07440 001

--8101090071 Forwards public version of request for Amend 25 to
application for DL consisting of Revision 2 to emergency
plan
CURTIS, N W Pennsylvania Power & Light Co 80/10/31 1p
07440 003

---8101090079 Public version of Amend 25 to application for DL consisting
of Revision 2 to util emergency plan
CURTIS, N W Pennsylvania Power & Light Co 80/10/31 1p
07440 004

--8101090080 Public version of util emergency plan, Revision 2
w Pennsylvania Power & Light Co 80/10/31 150pp 07440 005

8101070087 Ltr to all licensees of operating reactor plants, CP holders
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
810102 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing 80/11/13 2pp

8101140801 Forwards applicant emergency plan per request w/o encl.
Related correspondence.
SNAPP, B A Pennsylvania Power & Light Co 81/01/08 1p
07458 213

8101290146 Notification of 810121 meeting w/util in Bethesda, MD re
facilities emergency, offsite facilities design & applicable
NRC requirements
STARK, R M Licensing Branch 1 81/01/08 3pp 07567 331

8101210649 Forwards Chemical Engineering Branch request for addl info
re fire protection
TEJESCB, R L Assistant Director for Licensing 81/01/13 12pp
07448 348

8101290154 Forwards facility emergency planning info to be made
publicly available w/o encl.
SOUGER, J L Division of Rules and Records 81/01/23 1p
07575 197

G Adjudicatory correspondence

8101120225 Forwards statement of qualifications & affidavit of
CL Miller re Contention 16 Prof qualifications encl
KREGER, W E Assistant Director for Radiation Protection 80/12/04
6pp 07446 137

8101140900 Requests to make limited appearance statement at licensing
hearings Certificate of Svc encl
NOTERMANN, J P Affiliation Unknown 80/12/27 3pp 07458 219

8101050620 Order granting NRC 801224 motion for extension until 810109
to respond to applicants' motion for partial summary
disposition of Contention 17
BECHHOEFER, C Atomic Safety and Licensing Board Panel 80/12/30
2pp 07387 073

8101070202 Notice of RW Adler appearance in & KW Carter notice of
withdrawal from proceeding Certificate of Svc encl
ADLER, R W, CARTER, K W Pennsylvania State of 80/12/30 4pp
07415 151

8101070527 Order granting intervenor Susanheanne Environ Advocates
801213 motion for extension until 810223 to respond to
Contention & discovery requests
BECHHOEFER, C Atomic Safety and Licensing Board Panel 81/01/0
3pp 07496 361

8101090033 Requests time to make limited appearance statement at
hearing in Berwick, PA Certificate of Svc encl
MCLELLAN, M Affiliation Unknown 81/01/09 1p 07441 178

8101140561 Forwards applicant emergency plan per request w/o encl.
Related correspondence
SNAPP, B A Pennsylvania Power & Light Co 81/01/08 1p
07458 213

8101140311 Response to applicants' 801208 motion for partial summary
disposition of Contention 17 Motion should be granted except
for part re human health effects of electric fields Suppl to
applicants' statement of mat facts encl
LAVERY, J H Hearing Branch 1 81/01/09 12pp 07309 001

--8101140317 Affidavit re likely levels & potential impact of aud
noise possibly resulting from transmission lines associated
w/facility Potential for speech interference & activity
interference very low
LEHR, J C Environmental Engineering Branch 81/01/07 9pp
07309 001

--8101140328 Affidavit re radio & television interference, shock &
flashover, magnetic field & electric field effects on human
health Magnetic fields will not cause adverse biological
effects Certificate of Svc encl
GEARS, G Environmental Engineering Branch 81/01/08 9pp
07309 001

8101200023 Requests that ASLD formally recognize withdrawal of
Contention 13 C Marsh expressly withdrew contention on Page
11 of 790720 answers to NRC first round interrogatories
LAVERY, J H Office of the Executive Legal Director 81/01/14
2pp 07477 314

8101280628 Informs that action on encl 801216 application for SMC
license expected by Jan 1981 Submittal supercedes 801016
application
LAVERY, J H Office of the Executive Legal Director 81/01/14
2pp 07107 001

8101220004 Memorandum & order stating no formal request received
withdraw Marsh Contention 13 Parties may reply by 810130 to
NRC 810109 response to applicants' motion for partial
summary disposition of Contention 17 w/Certificate of Svc
BECHHOEFER, C Atomic Safety and Licensing Board Panel 81/01/
4pp 07501 315

8101270298 Response stating that NRC & applicant interrogatories
burdensome & that intervenor lacks resources to reply
Requests GE Reud repl Certificate of Svc encl
JOHNERUD, J H Environmental Coalition on Nuclear Power 81/01/
3pp 07546 063

H General correspondence

8101090703 Notifies that on 810108 telephone prefix 821 replaced
for all util general ofc complex telephone numbers. Prefix
change will not affect 4-digit extension numbers.
CURTIS, N W Pennsylvania Power & Light Co 81/01/02 1p
07424 350

K Utility Final Safety Analysis Report (FSAR) & amends

8101120169 Forwards Amend 27 to util 790731 application for DLs
containing Revision 17 to FSAR
CURTIS, N W Pennsylvania Power & Light Co 81/01/09 2pp
07436 001

--8101120194 Amend 19 to FSAR
w Pennsylvania Power & Light Co 81/02/09 175pp 07436 0

O Inspection reports, IE Bulletins & correspondence

8101090553 Ack receipt of 800910 ltr informing NRC of steps taken
correct violations noted in IE Insp Rpt 50-387/80-14
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 80/11/10 1p 07430 225

0101090857 Responds to NRC 800818 ltr re violations noted in IE Insp Rept 50-387/80-14 Corrective actions, procedures replaced w/procedures having proper approval signature
CURTIS, N W Pennsylvania Power & Light Co 80/09/10 5pp
07439, 226

0101090862 Forwards IE Insp Rept 50-387/80-14 on 800602-27 & notice of violation
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/08/18 2pp 07430, 231

0101090865 Notice of violation from insp on 800602-27
* Region 1, Philadelphia, Office of the Director 80/08/18 2pp
07430, 233

0101090869 IE Insp Rept 50-367/80-14 on 800602-27 Noncompliance noted use of unapproved plant maint procedure MT-64-003 & failure to follow approved procedures for reporting nonconforming items
GALLD.R H, RHODAS, G C Region 1, Philadelphia, Office of the Director MCCABE, E C Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/08/18 10pp 07430, 235

12310383 Responds to IE Bulletin 80-03, "Loss of Charcoal from Std Type 11, Two-Inch Tray Adsorber Cells " One type of cell is used Insp rept results showed no signs of screen casing separation Rept encl
CURTIS, N W Pennsylvania Power & Light Co 80/11/19 2pp

01070400 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/11/26 1p 07414, 077

01050120 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Scram Discharge Vol at Dresden Unit 2 " No response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/05 1p 07376, 331

01150841 Ack receipt of 801202 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-387/80-24
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/12/10 1p 07464, 315

0101190846 Responds to NRC 801103 ltr re violations noted in IE Insp Rept 50-387/80-24 Corrective actions Preoperational Test Procedure PIC 1, Revision 1, Test Review Board approval rescinded for procedure revision
CURTIS, N W Pennsylvania Power & Light Co 80/12/02 2pp
07464, 316

0101150850 Forwards IE Insp Rept 50-387/80-24 on 800708-1010 & notice of violation
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/11/03 2pp 07464, 318

0101150854 Notice of violation from insp on 800908-1010
* Region 1, Philadelphia, Office of the Director 80/10/30 1p
07464, 320

0101190861 IE Insp Rept 50-387/80-24 on 800908-1010 Noncompliance noted PIC 1, Revision 1 reviewed & approved w/o resolution of comments made by util fire protection engineer
GALLD.R H, RHODAS, G C Region 1, Philadelphia, Office of the Director MCCABE, E C Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/10/30 16pp 07464, 321

01140824 Forwards results of independent teardown analysis/insp of nine samples of cable w/o encl
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/11 2pp 07461, 325

01060138 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Scram Capability " No response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/17 1p 07397, 354

01070058 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/18 1p 07415, 008

01190835 Forwards IE Bulletin 80-25, "Operating Problems W/Target Rod Safety-Relief Valves at BWRs " No response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/19 1p 07465, 322

V Reportable occurrences, LERs & related correspondence

8010100071 Ack receipt of 801020 ltr forwarding interim deficiency rept re excessive voltage drops in ac motor operated valve control circuits Rept will be reviewed & evaluated
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/11/13 1p 07444, 316

--8010100076 Interim deficiency rept re excessive voltage drops in ac motor operated valve control circuits, initially reported on 800918 Util is evaluating alternatives to determine course of action Final rept will be provided in Jan 1981
CURTIS, N W Pennsylvania Power & Light Co 80/10/20 2pp
07444, 317

8010100113 Ack receipt of 801026 deficiency rept re loose contact modules on GE Type CR 2940 selector switches
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/11/25 1p 07503, 016

8010100374 Ack receipt of util 801121 interim deficiency rept re separation criteria for electrical equipment Matter will be reviewed following receipt of final rept
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/09 1p 07337, 311

8010100398 Ack receipt of util 801121 final deficiency rept re Hilti shell-type expansion anchors Matter will be reviewed during subsequent insp
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/11 1p 07387, 314

8010100616 Ack receipt of 801121 ltr forwarding final rept re Limiting torque switch deficiencies
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/17 1p 07309, 031

8010100332 Revised final deficiency rept re improper stading of piping & tubing lines for GE instrumentation Lines will be installed with slope 1/2 inch per ft
CURTIS, N W Pennsylvania Power & Light Co 80/12/20 3pp
07399, 285

8010160550 Ack receipt of util 801117 interim deficiency rept re excessive voltage drops in power supplies to dc motor-operated valves Matter will be reviewed following receipt of final rept
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/23 1p 07471, 101

8010160553 Ack receipt of util 801119 final deficiency rept re Limiting torque switch rotors Matter will be reviewed during subsequent insp
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/24 1p 07471, 101

8010190779 Ack receipt of util 801209 interim deficiency rept re shimming of base plates
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/24 1p 07473, 044

--8010190783 Interim deficiency rept re use of pipe shims around and between equipment floors & equipment base plates, initially reported on 801107 Evaluation underway to determine scope of problem & resolution, including removal of pipe shims
CURTIS, N W Pennsylvania Power & Light Co 80/12/09 6pp
07473, 045

8010120362 Interim deficiency rept re use of improperly grounded flexible conduit on safety-related circuits, initially reported on 801210 Caused by manufacturer failure to remove paint from termination module Next rept by Apr 1981
CURTIS, N W Pennsylvania Power & Light Co 81/01/14 4pp
07493, 079

80101270425 Final deficiency rept re unauthorized welding of pipe hanger to reactor pressure vessel, initially reported on 800201 All necessary rework has been completed Reactor pressure vessel is in acceptable state
CURTIS, N W Pennsylvania Power & Light Co 81/01/22 6pp
07549, 044

V Operator Examinations

8010300825 Requests commitments to special low power test program for facility & augmented operator training for compliance w/MI test action item 1 Q.1
TEDESCO, R T Assistant Director for Licensing 81/01/16 3pp
07183, 001

4101260370 Forwards util response to NUREG-0737 TMI-related requirements Meeting to discuss response requested
CURTIS, N W Pennsylvania Power & Light Co 01/01/22 07pp
07525 252

DOCKET 50-268 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2

A Application/construction stage documents & correspondence

0101090067 Releases public version of util emergency plan
FELTCH, J H Division of Rules and Records 00/11/13 1p.

--0101090071 Forwards public version of request for Amend 25 to application for OL consisting of Revision 2 to emergency plan
CURTIS, N W Pennsylvania Power & Light Co 00/10/31 1p

--0101090075 Public version of Amend 25 to application for OL consisting of Revision 2 to util emergency plan
CURTIS, N W Pennsylvania Power & Light Co 00/10/31 1p.

01220466 Ltr to all power reactor licensees & applicants forwarding summary of 001112 meeting re implementation of guidance for Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Corrosion Fatigue on Component Supports"
EISENHUT, D G Division of Licensing 00/11/26 8pp

0101220069 Notification of rescheduling of 010127-29 meeting to 010303-05 w/util in Allentown, PA re mgt structure & technical resources
STARKE, R M Licensing Branch 1 00/12/16 3pp 07502 007

0101090032 Forwards request for addl info per review of OL application in power sys area & in procedures & test review branches
TEDESCO, R L Assistant Director for Licensing 00/12/22 19pp.
03893 266

0101200157 Summary of 001210 meeting w/Mark II owners re status of generic improved chugging load model Owners requested to justify delay in program & investigate alternatives
WIDENSEN, C J Generic Issues Branch 00/12/22 4pp

0101080176 Notification of 010113 meeting w/util in Bethesda, MD to discuss applicant responses to NRC questions & positions concerning initial test program
STARKE, R M Licensing Branch 1 00/12/23 3pp 07421 032

0101210247 Summary of 001118-19 meeting w/PNHL in Bethesda, MD re control room habitability
MRUC, H F Accident Evaluation Branch 00/12/29 6pp. 07493 088

010107055 Summary of Dec 1989 meeting w/Mark II owners group, GE, BNH, HTR, BWH, Bechtel & Babcock & Wilcox, Inc re suppression pool temp limits List of attendees & handouts encl
SUTK, Generic Issues Branch 00/12/30 41pp

010130466 Forwards slides presented during 001218 meeting
CURTIS, N W Pennsylvania Power & Light Co 01/01/02 1p
07308 001

010130320 Forwards info re fish impingement & entrainment in response to ANL request concerning input to FES Final & operations phase NPDES permit encl
CURTIS, N W Pennsylvania Power & Light Co 01/01/05 44pp.
07308 001

0101270482 Submits info re facility operations during low river flow conditions in response to NRC request Util plants to replace water taken from Susquehanna River during low flow by using water from existing reservoir or Pond Hill Reservoir
CURTIS, N W Pennsylvania Power & Light Co 01/01/07 1p
07549 063

010120189 Forwards proposed Amend 27 to util 790731 application for OLs, containing Revision 17 to FBAR
CURTIS, N W Pennsylvania Power & Light Co 01/01/09 2pp

01010387 Forwards "Seismic Category I Essential Components for Susquehanna 1 & 2 NSSS Equipment Only," supplementing 001216 equipment qualification info package.
CURTIS, N W Pennsylvania Power & Light Co 01/01/09 1p
07474 185

0101190390 "Seismic Category I Essential Components for Susquehanna 1 & 2 NSSS Equipment Only"
* Pennsylvania Power & Light Co 01/01/07 88pp 07474: 186

0101300825 Requests commitments to special low power test program facility & augmented operator training for compliance w/TMI last action item 1 C 1
TEDESCO, R L Assistant Director for Licensing 01/01/16 3pp
07183 001

0101260370 Forwards util response to NUREG-0737 TMI-related requirements Meeting to discuss response requested
CURTIS, N W Pennsylvania Power & Light Co 01/01/22 07pp
07525 252

0101280151 Forwards application for amend of CPPR-101 & CPPR-102 to extend const completion dates Class I & Class II fees encl
SHAPP, R A Pennsylvania Power & Light Co 01/01/23 2pp
07558 042

--0101200158 Application for amend of CPPR-101 & CPPR-102 to extend completion dates to 020231 for CPPR-101 & 040331 for CPPR-102
CURTIS, N W Pennsylvania Power & Light Co 01/01/23 3pp
07558 044

0101300500 Submits update on farm survey in vicinity of facility
CURTIS, N W Pennsylvania Power & Light Co 01/01/27 2pp
07587 072

D NRC Draft/Final Environmental Statements, supp & correspondence

010130320 Forwards info re fish impingement & entrainment in response to ANL request concerning input to FES Final & operations phase NPDES permit encl
CURTIS, N W Pennsylvania Power & Light Co 01/01/05 44pp
07308 001

E NRC Safety Evaluation Report (SER), supp & correspondence

0101050502 Requests schedule of completion for organizational changes at facility prior to proposed NRC 010127-29 visit re SER preparation
EISENHUT, D G Division of Licensing 00/12/19 2pp. 07387 284

F Security, medical, emergency & fire protection plans

0101090067 Releases public version of util emergency plan
FELTCH, J H Division of Rules and Records 00/11/13 1p
07440 001

--0101090071 Forwards public version of request for Amend 25 to application for OL consisting of Revision 2 to emergency plan
CURTIS, N W Pennsylvania Power & Light Co 00/10/31 1p
07440 003

--0101090075 Public version of Amend 25 to application for OL consisting of Revision 2 to util emergency plan
CURTIS, N W Pennsylvania Power & Light Co 00/10/31 1p
07440 004

--0101090080 Public version of util emergency plan, Revision 2
* Pennsylvania Power & Light Co 00/10/31 150pp. 07440 001

0101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 010102 & by applicants as part of FBAR.
EISENHUT, D G Division of Licensing 00/11/13 2pp

0101140861 Forwards applicant emergency plan per request. W/o encl
Related correspondence
SHAPP, R A Pennsylvania Power & Light Co 01/01/08 1p.
07458 213

0101290146 Notification of 010121 meeting w/util in Bethesda, MD re facilities emergency offsite facilities design & applicable MLC requirements.
STARKE, R M Licensing Branch 1 01/01/08 3pp. 07567 351

0101210649 Forwards Chemical Engineering Branch request for addl info re fire protection.
TEDESCO, R L Assistant Director for Licensing 01/01/13 12pp
07448 348

0101290154 Forwards facility emergency planning info to be made publicly available w/o encl.
BOUDER, J L Division of Rules and Records 01/01/23 1p.
07575 197

C Adjudicatory correspondence

B101120225 Forwards statement of qualifications & affidavit of CL Miller re Contention 16 Prof qualifications encl.
KREGER, W E Assistant Director for Radiation Protection. 80/12/04
6pp 07446:137

B101140900 Requests to make limited appearance statement at licensing hearings Certificate of Svc encl
NOTERMAN, J P Affiliation Unknown. 80/12/27. 3pp 07450:219

B101050620 Order granting NRC B01224 motion for extension until B10109 to respond to applicants' motion for partial summary disposition of Contention 17
BECHHOEFER, C Atomic Safety and Licensing Board Panel. 80/12/30
2pp 07387:073

B101070202 Notice of RW Adler appearance in & KW Carter notice of withdrawal from proceeding Certificate of Svc encl
ADLER, R W, CARTER, K W Pennsylvania, State of. 80/12/30 4pp
07415:151

B101070527 Order granting intervenor Susquehanna Environ Advocates B01213 motion for extension until B10223 to respond to Contention & discovery requests.
BECHHOEFER, C Atomic Safety and Licensing Board Panel. 81/01/02.
2pp 07406:361.

B101090033 Requests time to make limited appearance statement at hearing in Berwick, PA Certificate of Svc encl.
MOWELL, R M Affiliation Unknown. 81/01/03. 1p 07441:178

B101140861 Forwards applicant emergency plan per request, W/o encl
Related correspondence
SNARP, B A Pennsylvania Power & Light Co. 81/01/08 1p
07458:213.

B101140011 Response to applicants' B01208 motion for partial summary disposition of Contention 17 Motion should be granted except for part re human health effects of electric fields Suppl to applicants' statement of mat facts encl
LAVERY, J. H. Hearing Branch 1. 81/01/09 12pp 07309:001.

--B101140017 Affidavit re likely levels & potential impact of audible noise possibly resulting from transmission lines associated w/facility Potential for speech interference & activity interference very low
LEHR, J C Environmental Engineering Branch. 81/01/07 9pp
07309:001

--B101140028 Affidavit re radio & television interference, shock from flashover, magnetic field & electric field effects on human health Magnetic fields will not cause adverse biological health Certificate of Svc encl.
GEARS, Q Environmental Engineering Branch. 81/01/08. 9pp
07309:001.

B101200023 Requests that ASLB formally recognize withdrawal of Contention 13 C Marsh expressly withdrew contention on Page 11 of 790720 answers to NRC first round interrogatories
LAVERY, J. H. Office of the Executive Legal Director. 81/01/14
2pp 07477:314.

B101280628 Informs that action on encl B01216 application for BNH license expected by Jan 1981 Submittal supercedes B01016 application
LAVERY, J. H. Office of the Executive Legal Director. 81/01/14.
2pp. 07187:001.

B101220004 Memorandum & order stating no formal request received to withdraw Marsh Contention 13 Parties may reply by B10130 to NRC B10109 response to applicants' motion for partial summary disposition of Contention 17. W/Certificate of Svc.
BECHHOEFER, C Atomic Safety and Licensing Board Panel. 81/01/15.
4pp. 07501:313.

B101270298 Response stating that NRC & applicant interrogatories are burdensome & that intervenor lacks resources to reply.
Requests OE Reed rept. Certificate of Svc encl.
JOHNSBRUD, J H Environmental Coalition on Nuclear Power. 81/01/13
3pp. 07546:063

H General correspondence

B101090703 Notifies that on B10108 telephone prefix B21 replaced by 770
For all util general ofc complex telephone numbers. Prefix change will not affect 4-digit extension numbers.
CURTIS, N H Pennsylvania Power & Light Co. 81/01/02 1p.
07424:362

K Utility Final Safety Analysis Report (FSAR) & amends

B101130164 Forwards Amend 27 to util 790731 application for OLR containing Revision 19 to FSAR
CURTIS, N H Pennsylvania Power & Light Co. 81/01/09 2pp
07436:001

--B10120174 Amend 19 to FSAR
" Pennsylvania Power & Light Co. 81/02/07 175pp 0743

Q Inspection reports, IE Bulletins & correspondence

B101070409 Forwards Suppl 1 to IE Info Notice B0-29, "Broken 9 Terry Turbine Steam Inlet Flange " No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/11/26 1p 07414:077

B101050130 Forwards IE Info Notice B0-43, "Failures of Continuous Level Monitor for Scram Discharge Vol at Dresden Unit 2 " No response required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/12/03 1p 07376:351

B101140824 Forwards results of independent teardown analysis/nine samples of cable W/o encl
CARLSCH, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/12/11. 2pp 07461:323

B101060138 Forwards IE Info Notice B0-45, "Potential Failure of Backup Manual Scram Capability " No response required.
GRIER, B H Region 1, Philadelphia, Office of the Director
80/12/17. 1p 07397:354.

B101070058 Forwards Suppl 4 to IE Bulletin B0-17, "Failure of Control Rods to Fully Insert During Scram at BWR " No written response required.
GRIER, B H Region 1, Philadelphia Office of the Director.
80/12/18 1p 07415:008.

B101150805 Forwards IE Bulletin B0-29, "Operating Problems W/ React Safety-Relief Valves at BWRs." No response required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/12/19 1p 07465:323

S Reportable occurrences, LERs & related correspondence

B10100071 Ack receipt of B01020 ltr forwarding interim deficit re excessive voltage drops in ac motor operated valve control circuits Rept will be reviewed & evaluated
CARLSCH, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/11/13 1p. 07444:316

--B10100076 Interim deficiency rept re excessive voltage drop motor operated valve control circuits. Initially reported on 800710 Util is evaluating alternatives to determine course of action Final rept will be provided in Jan 1981.
CURTIS, N H Pennsylvania Power & Light Co. 80/10/20 2p
07444:317

B101300113 Ack receipt of B01028 deficiency rept re loose control modules on GE Type CR 2940 selector switches.
CARLSCH, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/11/23. 1p 07583:086

B101050394 Ack receipt of util B01121 interim deficiency rept re separation criteria for electrical equipment Matter will be reviewed following receipt of final rept
CARLSCH, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/12/09 1p. 07389:311

B101050390 Ack receipt of util B01121 final deficiency rept re shell-type expansion anchors Matter will be reviewed during subsequent insp
CARLSCH, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/12/11 1p 07389:314

B101090416 Ack receipt of B01121 ltr forwarding final rept re Limitorque torque switch deficiencies
CARLSCH, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/12/17 1p 07309:001

B101050332 Revised final deficiency rept re improper sloping of piping & tubing lines for GE instrumentation Lines will be installed which slope 1/2 inch per ft
CURTIS, N H Pennsylvania Power & Light Co. 80/12/23 5pp
07389:226

B10112058 Ack receipt of util B01117 interim deficiency rept re excessive voltage drops in power supplies to dc motor-operated valves Matter will be reviewed following receipt of final rept
CARLSON R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/23 1p 07471 183

B10112059 Ack receipt of util B01119 final deficiency rept re lightning limit switch rotors Matter will be reviewed during subsequent insp
CARLSON R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/24 1p 07471 181

B101190779 Ack receipt of util B01209 interim deficiency rept re shimming of base plates
CARLSON R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/24 1p 07473 044

-B101190785 Interim deficiency rept re use of pipe shims around anchors between equipment floors & equipment base plates. Initially reported on B01107 Evaluation underway to determine scope of problem & resolution, including removal of pipe shims
CURTIS M W Pennsylvania Power & Light Co 80/12/09 6pp 07473 045

B10120362 Interim deficiency rept re use of improperly grounded flexible conduit on safety-related circuits. Initially reported on B01210 Caused by manufacturer failure to remove part from termination module Next rept by Apr 1981
CURTIS M W Pennsylvania Power & Light Co 80/01/14 4pp 07473 079

B10270425 Final deficiency rept re unauthorized welding of pipe rammer to reactor pressure vessel. Initially reported on B02201 All necessary repairs have been completed Reactor pressure vessel is in acceptable state
CURTIS M W Pennsylvania Power & Light Co 80/01/22 6pp 07549 044

Operator Examinations

B1020825 Requests commitments to special low power test program for Facility 1, augmented operator training, for compliance w/INEL action item 1 G 1
TEFFESCO R L Assistant Director for Licensing 81/01/16 3pp

B1260370 Forwards Util response to NUREG-0737 INEL-related requirements Meeting to discuss response requested
CURTIS M W Pennsylvania Power & Light Co 80/01/22 87pp

INEL 50-389 ST. LUCIE PLANT, UNIT 2

Security, medical, emergency & fire protection plans

H090387 Ltr to all licensees of operating reactor plants, CP holders, CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 110102 & by applicants as part of FSAR
EISENHUT D O Division of Licensing 80/11/13 2pp

Adjudicatory correspondence

1190036 Order granting extension until B10115 for Commission to review Director's decision DD-BD-33 Certificate of Svc encl
HILK S J Office of the Secretary of the Commission 81/01/09 pp 07462 134

1140956 Response to Commission B01212 memorandum & order recommends affirmation of ALAB-603 & acceptance of ASLAB certification SRP Section 2 2 3 should not be used to determine DOE Certificate of Svc encl
HSTEAD W J Hearing Branch 4 81/01/12 11pp 07458 302

160217 Response recommending Commission affirm ALAB-603 & accept certification of ASLAB ASLAB requirements re station actout are appropriate pending completion of Task Action an A-44
HSTEAD W J Hearing Branch 4 81/01/12 11pp 07470 068

160261 Response opposing B01212 Commission memorandum & order, 1-B0-41, announcing sua sponte review of B00730 ALAB-603 Commission letter jurisdiction Certificate of Svc encl
HSEAR M A, COLLINS A Florida Power & Light Co BAUSER M A Weinstein, Newman, Reis, Atsired & Toll 81/01/12 8pp 07470 239

B101260321 Informs that time for Commission to act to review Director's decision DD-BD-33, has expired Commissioner Dillinsky in voting for no review stated Class 9 accidents should be considered in suppl to CP review Certificate of Svc encl
HILK S J Office of the Secretary of the Commission 81/01/21 4pp 07529 250

J Insurance & indemnity information

B101090457 Forwards Endorsement 4 to NELA Binder EB-59
FIELDER J Marsh & McLennan, Inc, H & M Nuclear Consultants, Inc Div 80/12/30 2pp 07430 048

B101090464 Forwards Endorsement 38 to NELA Policy NF-227
FIELDER J Marsh & McLennan, Inc, H & M Nuclear Consultants, Inc Div 80/12/30 3pp 07442 032

B101090556 Forwards Endorsement 37 to ANI Policy NF-227
FIELDER J Marsh & McLennan, Inc, H & M Nuclear Consultants, Inc Div 80/12/30 2pp 07427 343

M Antitrust correspondence

B101140915 Order scheduling B10202 prehearing conference in Bethesda, MD re joint motion to approve & authorize implementation of settlement agreement Certificate of Svc encl
LADON R M Atomic Safety and Licensing Board Panel 81/01/07 5pp 07458 236

B101090348 FL Cities motion to file encl reply to applicant B01203 brief which raises new questions & new statements of law
JABLON R A Affiliation Unknown JABLON R A Spiegel & McDiarmid 81/01/08 2pp 07424 039

--B101090360 FL Cities reply brief to applicant B01203 response to FL Cities answer to joint motion Supports prehearing conference & contends license condition clause contrary to public policy Certificate of Svc encl
JABLON R A Affiliation Unknown JABLON R A Spiegel & McDiarmid 81/01/08 173pp 07424 041

B101280599 Answer opposing intervening Cities B10108 reply to util DDJ & NRC B00712 joint motion intervenors arguments re liability provisions & settlement license conditions Certificate of Svc & supportive documentation encl
DYH M, BOUWMEESTER J A Florida Power & Light Co DYH M, Covington & Butling 81/01/27 32pp 07557 233

P Operating license stage documents & correspondence

B101250466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lateral Tearing on Component Supports."
EISENHUT D O Division of Licensing 80/11/26 8pp

Q Inspection reports, IE Bulletins & correspondence

B012160019 Forwards IE Info Notice 80-37, "Containment Cooler Leaks & Reactor Cavity Flooding At Indian Point Unit 2" No written response required
O'REILLY J P Region 2, Atlanta, Office of the Director 80/10/24 1p

B101290365 Forwards IE Insp Rept 80-389/80-16 on B01118-20. No noncompliance noted
MURPHY C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/12/15 2pp 07571 356

--B101290367 IE Insp Rept 80-389/80-16 on B01118-20. No noncompliance noted Major areas inspected followup items, licensees identified items & IE bulletins, circulars & info notices.
MCFARLAND C R Region 2, Atlanta, Office of the Director BRYANT J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/12/15 4pp 07571 358

B101270008 Responds to IE Bulletin 80-23 re Valcor Engineering Corp solenoid valve failure Util will fully respond to bulletin by B10116
UMRIG R E Florida Power & Light Co 80/12/29 1p 07547 019

B101270043 Responds to IE Bulletin 80-21 re Malcolm Foundry Co valve yokes Util waiting for vendor response
UMRIG R E Florida Power & Light Co 80/12/30 1p 07547 022

810150590 Ack receipt of 801215 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-389/80-13
HARRPH, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 81/01/06 1p 07464 284

--810150595 Responds to RAC 801010 ltr re violations noted in IE Insp Rept 50-389/80-13 Corrective actions Quality Procedure B re storage & distribution of welding filler metal revised.
WIRIG, R E Florida Power & Light Co 80/12/15 2pp 07464 285

R Periodic operating reports & related correspondence

8101220172 Forwards monthly status rept of const/startup progress for Dec 1980
WIRIG, R E Florida Power & Light Co 81/01/14 2pp 07495 282

DECKET 90-099 WATTS BAR NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports"
EISENHUT, D G Division of Licensing 80/11/26 8pp

810150552 Forwards requests for clarification of responses to questions re containment vessel bldg analysis
TEDESCO, R L Assistant Director for Licensing 80/12/09 4pp 07387 178

8101207068 Summary of 801200-12 meetings w/caseload forecast panel Earliest projected fuel load date for facilities is 810601 for Sequoyah Unit 2 & Aug 1982 for Watts Bar Unit 1
KENYON, T J Licensing Branch 2 80/12/16 5pp 07429 356

8101140810 Requests ultimate capacity analysis of ice condenser containments, re NRC review of effects of hydrogen evolving from postulated accidents Analysis guidelines encl
TEDESCO, R L Assistant Director for Licensing 80/12/10 3pp 07461 316

8101210642 Advises that ATWS issue will be subj of future rulemaking to determine requirements & schedules for plant mode NRC will not comment on util 800917 ltr describing program for resolving issue until rulemaking is finalized
EISENHUT, D G Division of Licensing 80/12/29 2pp

8101190228 Forwards list of TLD station locations near facility & proposed route for exchanging TLDs for NRC direct radiation monitoring network w/o encls
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch, 80/12/30 2pp 07475 305

8101160418 Responds to NRC 800924 request for results of preliminary design review of control room Results encl
MILLS, L M Tennessee Valley Authority 81/01/13 9pp 07470 158

8101290497 Summary of 801208 meeting w/util & ANL at site re safety & relief valve piping of primary coolant sys List of attendees encl
KENYON, T Operating Reactors Branch 2 81/01/15 4pp 07575 170

8101300097 Notification of contract execution Mod 3 to "Evaluation of Buckling Stress Criteria for Steel Containment of Watts Bar" Contractor Intl Structural Engineers
FLENDOR, C M Administrative Contracts Branch, FIN B-6581 81/01/26 1p 07583 077

--8101300104 Mod 3, extending period of performance to 810630 to "Evaluation of Buckling Stress Criteria for Steel Containment of Watts Bar"
MOSEBERG, B A International Structural Engineers, Inc PERLMAN, J Administrative Contracts Branch, FIN B-6581 81/01/26 1p 07583 078

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR.
EISENHUT, D G Division of Licensing, 80/11/13 2pp

8101210607 Transcript of 801217 briefing on TVA emergency offsite facilities in Washington, DC Pp 1-45
* Commissioners 80/12/17 49pp.

8101300620 Forwards request for addl info & revisions to util 801000 training & qualification program Section 1.3 must be revised to correct to physical exam within 30-day period preceding demonstration of physical fitness
TEDESCO, R L Assistant Director for Licensing 81/01/15 4pp 07582 141

J Insurance & indemnity information

8101070555 Forwards Encorsement 11 to ANJ Policy NF-256
FIELDER, J Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 80/12/29 2pp 07427 335

8101090658 Forwards Endorsement 12 to HELIA Policy NF-256
FIELDER, J Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 80/12/29 3pp 07442 053

O Inspection reports, IE Bulletins & correspondence

8101140619 Updates licensee corrective actions following NRC 800701 Insp of util Div of Engineering Design QA organization restructured to provide sufficient organizational freedom, authority & access to mgmt
KIMMINS, G H Tennessee Valley Authority 80/10/08 3pp 07462 012

8101290373 Forwards IE Insp Repts 50-370/80-34 & 50-391/80-27 on 81020-31 No non-compliance noted.
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/12/09 2pp 07572 336

--8101290378 IE Insp Repts 50-390/80-34 & 50-391/80-27 on 81020-31 non-compliance noted Major areas inspected SNM license amend & licensee action on previous insp findings
MCEDMUND, J A Region 2, Atlanta, Office of the Director DANCE, H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/12/09 3pp 07572 398

8101120240 Forwards response to IE Bulletin 80-20 re Westinghouse W-2 control switches w/spring return to neutral position Switches used in all facilities except Yellow Creek Lists sys in which switches are employed
MILLS, L M Tennessee Valley Authority 80/12/12 2pp 07447 6

8101060203 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown" No written response required
O'RILEY, J P Region 2, Atlanta, Office of the Director 80/12/12 1p

8101270030 Responds to IE Bulletin 80-23 re Valcor Engineering Corp solenoid valve failure Valcor solenoid valves V70900-21-1 & V70900-21-3 not used Util waiting for vendor response on valves in package components
MILLS, L M Tennessee Valley Authority 80/12/30 1p 07547 0

8101210239 Responds to IE Bulletin 80-71, "Valve Yokes Supplied by Malcolm Foundry Co, Inc" Util is in process of obtaining assurance from valve suppliers that no Malcolm Foundry yokes are contained in furnished valves
MILLS, L M Tennessee Valley Authority 81/01/06 1p 07490 0

8101230468 Responds to NRC 801121 ltr re violations noted in IE Insp Repts 50-390/80-30 & 50-391/80-23 Corrective action util has met all reporting requirements of 10CFR90.55(e) & is in full compliance
MILLS, L M Tennessee Valley Authority 81/01/14 5pp 07510 1

S Reportable occurrences, LERs & related correspondence

8101090439 Final interim deficiency rept, originally reported on 80 re unacceptable welds on duct supports in auxiliary bldg Program implemented to re-inspect welds on duct supports in auxiliary bldg Welds to be repaired
MILLS, L M Tennessee Valley Authority 80/12/31 2pp 07380

8101070432 First interim deficiency rept re design of self-drilling expansion anchors, initially reported on 80/12/04 Util is evaluating adequacy of design to determine impact of error Next rept will be forwarded by 810308
MILLS, L M Tennessee Valley Authority 81/01/02 2pp 07415

8101140485 Second interim deficiency rept initially reported 80100 seismic analysis of check valves in chemical & vol control sys Loads from 3-inch check valve are not significant Next rept will be submitted by 810210
MILLS, L M Tennessee Valley Authority, 81/01/06 1p 07461 2

B010140592 Fifth interim deficiency rept. originally reported on B00325.
 re upper head injection hydraulic isolation valve
 accumulator weighing sys Westinghouse agreed to submit
 revised drawings. Next rept will be submitted by B10310
 MILLS, L M Tennessee Valley Authority B1/01/06 1p 07461 235

B010260427 Second interim deficiency rept. originally reported on
 B00302. re seismic analysis of check valve in chemical &
 vol control sys. Loads from 3-inch check valve at Sequoyah
 insignificant. Hard-ware changes not required.
 MILLS, L M Tennessee Valley Authority B1/01/06 1p 07531 175

B010140618 Final interim deficiency rept. originally reported on B00818.
 re discrepancy in two PM-71 embedded plates. Plates
 reanalyzed for related loads assuming none of embedment
 anchors are double studed. Embedded plates acceptable.
 MILLS, L M Tennessee Valley Authority B1/01/08 2pp 07461 236

B010270245 Part 21 rept re discovery of surface indications in loop 1
 steam generator. Caused by delayed hydrogen cracking. Due to
 welding surface indications removed by grinding.
 MILLS, L M Tennessee Valley Authority B1/01/08 3pp 07547 114

B010140616 Final deficiency rept re diesel generator interlock design.
 Interlocks will be added to emergency feeder breaker
 automatic close circuit before fuel load. Originally reported on
 B01209.
 MILLS, L M Tennessee Valley Authority B1/01/09 2pp 07461 120

B010360462 Final deficiency rept. originally reported B01027 re
 interaction areas in reactor bldg annulus not covered by
 automatic fixed water spray sys. Fire protection sys is being
 modified to encompass addl interaction areas identified.
 MILLS, L M Tennessee Valley Authority B1/01/09 2pp 07471 223

B010190405 Interim deficiency rept. originally reported on B11210 re
 fillet weld misspecification. Util in process of evaluating
 American Iron & Steel Inst Stds. Next rept will be sent
 B10303.
 MILLS, L M Tennessee Valley Authority B1/01/09 2pp 07475 249

B010190391 First interim deficiency rept. initially reported on B01212.
 re nonrandom testing of expansion anchor bolts. Deficiency
 under investigation to determine corrective action.
 MILLS, L M Consumers Power Co. B1/01/12 2pp 07475 245.

B010210421 Second interim deficiency rept re valve accelerations for
 piping analysis. Initially reported on B01002. Util is still
 evaluating interpretation of design criteria re valve
 seismic accelerations. Addl info will be provided by B10220.
 MILLS, L M Tennessee Valley Authority B1/01/13 1p 07448 362

B010260409 Second interim deficiency rept. first reported on B01002. re
 valve accelerations for piping analysis. Design criteria
 interpretation re valve seismic accelerations being
 evaluated. Addl info scheduled for B10220.
 MILLS, L M Tennessee Valley Authority B1/01/13 1p 07531 216

B010290311 Forwards first interim rept re potential flammability of
 suspended ceiling tile in control room in response to
 B01104 ltr. Addl info to be provided by B10211.
 MILLS, L M Tennessee Valley Authority B1/01/14 3pp

B010230542 Fourth interim deficiency rept. initially submitted B00501. re
 safety injection sys B flow deficient. No further testing
 performed. Further info to be provided by B10314.
 MILLS, L M Tennessee Valley Authority B1/01/15 1p 07308 001

B010230553 First interim deficiency rept. originally reported B01216. re
 loose electrical terminations on diesel generator control
 panels. Investigation committee formed to evaluate
 deficiency. Loose terminations tightened.
 MILLS, L M Tennessee Valley Authority B1/01/15 2pp 07510 286

B010230608 Sixth interim deficiency rept. originally submitted 790906. re
 steam generator water level ref column error. Microprocessors
 provide temp compensation for errors caused by water density
 changes. Addl info to be submitted B10515.
 MILLS, L M Tennessee Valley Authority B1/01/15 1p 07308 001

B010260438 Final deficiency rept. originally reported on B01217. re
 spring from ITI actuator rfg from incorrect matl.
 Investigation revealed Post-Seal uses NH 90 series
 hydroliners. Post-Seal verified safe performance of actuator.
 MILLS, L M Tennessee Valley Authority B1/01/15 2pp 07531 221

B010260418 First interim deficiency rept. originally reported on B01219.
 re current control problems w/diesel generators 1A-A & 1B-B
 caused by incorrect wiring of voltage regulator wiring
 corrected. A preoperational testing complete.
 MILLS, L M Tennessee Valley Authority B1/01/19 3pp 07531 217

B010260436 First interim deficiency rept. originally reported on B01219.
 re inadequate steel containment penetration assembly.
 Affected piping will be reanalyzed to determine adequacy of
 assembly & pipe rupture restraint design.
 MILLS, L M Tennessee Valley Authority B1/01/19 2pp 07531 219

B010270732 Final deficiency rept. originally reported on B00918. re
 shifting of intermediate pipe break locations w/o notifying
 NRC. Safety injection & resistance temp device lines have
 been re-evaluated & no unacceptable interactions found.
 MILLS, L M Tennessee Valley Authority B1/01/21 2pp 07545 290

B010300483 Final deficiency rept. originally reported on B01030. re
 improper weld attachment of shear lugs. Caused by improper
 design & installation. Lugs will be removed & reinstalled
 w/1/4 inch fillet weld. Mods to be completed by May 1982.
 MILLS, L M Tennessee Valley Authority B1/01/26 2pp 07586 103

DOCKET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2
 A Application/construction stage documents & correspondence

B010220466 Ltr to all power reactor licensees & applicants forwarding
 summary of B01112 meeting re implementation of guidance for
 Unresolved Safety Issue A-12, "Potential for Low Fracture
 Toughness & Lamellar Tearing on Component Supports."
 EISENHUT, D Q Division of Licensing B01/1/26 8pp

B010500552 Forwards requests for clarification of responses to
 questions re containment vessel bldg analysis.
 TEDESCO, R L Assistant Director for Licensing B01/2/05 4pp
 07387 178

B010909668 Summary of B01208-12 meetings w/caseload forecast panel.
 Earliest projected fuel load date for facilities is B10601
 for Sequoyah Unit 2 & Aug 1982 for Watts Bar Unit 1.
 KENYON, T J Licensing Branch 2 B01/2/16 5pp 07429 356.

B010140810 Requests ultimate capacity analysis of ice condenser
 containments. re NRC review of effects of hydrogen evolving
 from postulated accidents. Analysis guidelines encl.
 TEDESCO, R L Assistant Director for Licensing B01/2/18 3pp.
 07461 316

B010210642 Advises that ATWS issue will be subj of future rulemaking to
 determine requirements & schedules for plant mods. NRC will
 not comment on util B00917 ltr describing program for
 resolving issue until rulemaking is finalized.
 EISENHUT, D Q Division of Licensing B01/2/29 2pp

B010190228 Forwards list of TLD station locations near facility &
 proposed route for exchanging TLDs for NRC direct radiation
 monitoring network w/o encls.
 STOKER, J P Region 2, Atlanta, Fuel Facility & Materials Safety
 Branch B01/2/30 2pp 07475 305.

B010160418 Responds to NRC B00924 request for results of preliminary
 design review of control room. Results encl.
 MILLS, L M Tennessee Valley Authority B1/01/13 9pp 07470 158.

B010290497 Summary of B01208 meeting w/util & ANL at site re safety &
 relief valve piping of primary coolant sys. List of attendees
 encl.
 KENYON, T Operating Reactors Branch 2 B1/01/15 4pp 07575 170

B010300097 Notification of contract execution. Mod 3 to "Evaluation of
 Buckling Stress Criteria for Steel Containment of Watts
 Bar." Contractor Intl Structural Engineers
 FLEENOR, C M Administrative Contracts Branch. FIN B-6581.
 B1/01/26 1p 07583 077

--B010300104 Mod 3, extending period of performance to B10630 to
 "Evaluation of Buckling Stress Criteria for Steel
 Containment of Watts Bar."
 MCSB300.3 A International Structural Engineers, Inc. PERLMAN, J
 Administrative Contracts Branch. FIN B-6581. B1/01/26 1p.
 07583 078

F Security, medical, emergency & fire protection plans

B010909387 Ltr to all licensees of operating reactor plants. CP holders
 & CP applicants. Revised radiological emergency response
 plans must be submitted by licensees within 60 days of
 B0102 & by applicants as part of FSAR.
 EISENHUT, D Q Division of Licensing B01/1/13 2pp.

B010210607 Transcript of B01217 briefing on TVA emergency offsite
 facilities in Washington, DC. Pp 1-45
 & Commissioners B01/2/17 49pp

8101300230 Forwards request for Addl info & revisions to util 801001 guard training & qualification program Section 1.3 must be revised to permit to physical exam within 30-day period preceding demonstration of physical fitness
TECECO, R L Assistant Director for Licensing 81/01/15 4pp
07382 141

J Insurance & indemnity information

8101070535 Forwards Endorsement 11 to ANI Policy NF-296
FIELDER, J Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc
Div 80/12/29 2pp 07427 339

8101090658 Forwards Endorsement 12 to HELIA Policy NF-296
FIELDER, J Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc
Div 80/12/29 3pp 07442 093

K Inspection reports, IE Bulletins & correspondence

8101140619 Updates licensee corrective actions following NRC 800707-11 insp of util Div of Engineering Design QA organization restructured to provide sufficient organizational freedom, authority & access to mgr
XIMONS, O H Tennessee Valley Authority 80/10/08 3pp

8101290373 Forwards IE Insp Rpts 90-390/80-34 & 90-391/80-27 on 801020-31 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/12/09 2pp 07572 336

--8101290378 IE Insp Rpts 90-390/80-34 & 90-391/80-27 on 801020-31 No noncompliance noted Major areas inspected BHM licensee amend & licensee action on previous insp findings
MCGRWALD, J A Region 2, Atlanta, Office of the Director
DAVCE, H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/12/09 3pp 07572 350

8101120210 Forwards response to IE Bulletin 80-20 re Westinghouse Type W-2 control switches w/spring return to neutral position
Switches used in all facilities except Yellow Creek Lists
s/s in which switches are employed
MILLS, L M Tennessee Valley Authority 80/12/12 2pp

8101060203 Forwards IE Info Notice 80-44, "Actuation of ECCB in Recirculation Mode While in Hot Shutdown - No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/12/16 1p

8101270030 Responds to IE Bulletin 80-23 re Valcor Engineering Corp solenoid valve failure Valcor solenoid valves V70900-21-1 & V70900-21-3 not used Util waiting for vendor response on valves in package components.
MILLS, L M Tennessee Valley Authority 80/12/30 1p 07547 021

8101210239 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co., Inc." Util is in process of obtaining assurance from valve suppliers that no Malcolm Foundry yokes are contained in furnished valves
MILLS, L M Tennessee Valley Authority 81/01/06 1p 07490 057

8101230468 Responds to NRC 801121 ltr re violations noted in IE Insp Rpts 90-390/80-30 & 90-391/80-23 Corrective action util has met all reporting requirements of 10CFR50.55(a) & is in full compliance
MILLS, L M Tennessee Valley Authority 81/01/14 5pp 07510 303

L Reportable occurrences, LERs & related correspondence

8101050439 Final interim deficiency rept. originally reported on 801201, re unacceptable welds on duct supports in auxiliary bldg. Program implemented to re-inspect welds on duct supports in auxiliary bldg welds to be repaired
MILLS, L M Tennessee Valley Authority 80/12/31 2pp 07380 186

8101070432 First interim deficiency rept re design of self-drilling expansion anchors, initially reported on 801204 Util is evaluating adequacy of design to determine impact of error. Next rept will be forwarded by 810308
MILLS, L M Tennessee Valley Authority 81/01/02 2pp 07415 306

8101140485 Second interim deficiency rept initially reported 801002 re seismic analysis of check valves in chemical & vol control s/s Loads from 3-inch check valve are not significant Next rept will be submitted by 810210
MILLS, L M Tennessee Valley Authority. 81/01/06 1p 07461 281

8101140593 Fifth interim deficiency rept. originally reported on 800325, re upper head injection hydraulic isolation valve accumulator weighing s/s Westinghouse agreed to submit revised drawings Next rept will be submitted by 810310
MILLS, L M Tennessee Valley Authority 81/01/06 1p 07461 235

8101260427 Second interim deficiency rept. originally reported on 801002, re seismic analysis of check valve in chemical & vol control s/s Loads from 3-inch check valve at Sequoyah insignificant Hardware changes not required
MILLS, L M Tennessee Valley Authority 81/01/06 1p 07531 179

8101140618 Final interim deficiency rept. originally reported on 800818, re discrepancy in two MA-71 embedded plates Plates reanalyzed for related loads assuming none of embedment anchors are double studied Embedded plates acceptable
MILLS, L M Tennessee Valley Authority 81/01/08 2pp 07461 236

8101290672 Final deficiency rept. originally reported on 800818, re discrepancy in two MA-71 embedded plates Caused by lack of double studied anchors & insufficient number of horizontal rows Embedded plates replaced & ultrasonically tested
MILLS, L M Tennessee Valley Authority 81/01/08 2pp 07565 329

8101140616 Final deficiency rept re diesel generator interlock design Interlocks will be added to emergency feeder breaker automatic close circuit before fuel load Originally reported on 801209
MILLS, L M Tennessee Valley Authority 81/01/09 2pp 07461 128

8101160462 Final deficiency rept originally reported 801027 re interaction areas in reactor bldg annulus not covered by automatic fixed water spray s/s Fire protection s/s is being modified to encompass addl interaction areas identified
MILLS, L M Tennessee Valley Authority 81/01/09 2pp 07471 223

8101190405 Interim deficiency rept. originally reported on 811210 re fillet weld misspecification Util in process of evaluating American Iron & Steel Inst Stds Next rept will be sent
810303
MILLS, L M Tennessee Valley Authority 81/01/09 2pp 07475 249

8101190391 First interim deficiency rept. initially reported on 801212, re nonrandom testing of expansion anchor bolts Deficiency under investigation to determine corrective action
MILLS, L M Consumers Power Co 81/01/12 2pp 07475 245

8101230296 Final Part 21 rept re installation of compression type terminals on single-phase static inverters, first reported 801212 insufficient number of or improper crimps made Vendor approval for mod obtained Mods to be completed 810201
MILLS, L M Tennessee Valley Authority 81/01/12 3pp 07187 001

8101210421 Second interim deficiency rept re valve accelerations for piping analysis, initially reported on 801002 Util is still evaluating interpretation of design criteria re valve seismic accelerations Addl info will be provided by 810220
MILLS, L M Tennessee Valley Authority 81/01/13 1p 07448 362

8101260405 Second interim deficiency rept. first reported on 801002, re valve accelerations for piping analysis Design criteria interpretation re valve seismic accelerations being evaluated Addl info scheduled for 810220
MILLS, L M Tennessee Valley Authority 81/01/13 1p 07531 216

8101220311 Forwards first interim rept re potential flammability of suspended ceiling tile in control rooms in response to 801104 ltr Addl info to be provided by 810211
MILLS, L M Tennessee Valley Authority 81/01/14 3pp

8101230593 First interim deficiency rept. originally reported 801216, re loose electrical terminations on diesel generator control panels Investigation committee formed to evaluate deficiency Loose terminations tightened
MILLS, L M Tennessee Valley Authority 81/01/15 2pp 07510 286

8101230608 Sixth interim deficiency rept. originally submitted 790906, re steam generator water level ref column error Microprocessors provide temp compensation for errors caused by water density changes Addl info to be submitted 810515
MILLS, L M Tennessee Valley Authority 81/01/15 1p 07308 001

8101260438 Final deficiency rept. originally reported on 801217, re spring from ITT actuator w/4 from incorrect matl Investigation revealed Posi-Seal uses NM 90 series hydramtors Posi-Seal verified safe performance of actuator
MILLS, L M Tennessee Valley Authority 81/01/15 2pp 07531 221

8101260436 First interin deficiency rept. originally reported on 801219. re inadequate steel containment penetration assembly. Affected piping will be re-analyzed to determine adequacy of assembly & pipe rupture restraint design
MILLS, L. M. Tennessee Valley Authority 81/01/19 2pp 07531 217

8101270732 Final deficiency rept. originally reported on 800918. re shifting of intermediate pipe break locations w/o notifying NRC Safety Injection & resistance temp device lines have been re-evaluated & no unacceptable interactions found
MILLS, L. M. Tennessee Valley Authority 81/01/21 2pp 07543 290

8101350463 Final deficiency rept. originally reported on 801030. re improper weld attachment of shear lugs caused by improper design & installation lugs will be removed & reinstalled w/1/4 inch fillet weld. Work to be completed by May 1982
MILLS, L. M. Tennessee Valley Authority 81/01/26 2pp 07586 103.

BUCKET 50-052 CHOCOMAN POWER REACTOR

B Reportable occurrences, LERs & related correspondence

8101290672 Final deficiency rept. originally reported on 800818. re discrepancy in two MA-71 embedded plates caused by lack of double studed anchors & insufficient number of horizontal rows. Embedded plates replaced & ultrasonically tested
MILLS, L. M. Tennessee Valley Authority 81/01/08 2pp 07566 329

BUCKET 50-375 VIRGIL C SUMMER NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8101140251 Advises that branch will review adequacy of cable separation inside Westinghouse 7300 series process control cabinet during 801112-14 site visit. Review conducted in response to 801029 memo
SATTENFIELD, E. Instrumentation & Control Systems Branch 80/11/06 1p 07461 259

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unsolved Safety Issue A-12. "Potential for Low Fracture Toughness & Latent Failure on Component Supports"
EISENHUT, D. O. Division of Licensing 80/11/26 8pp

8101050149 Requests addl info by 801219 re RCS vents.
TEDESCO, R. L. Assistant Director for Licensing 80/12/05 0pp 07399 678

8101080644 Forwards request for addl info re identification of high strength welds joining component parts & provision of impact energy data necessary to demonstrate fracture toughness adequacy
TEDESCO, R. L. Assistant Director for Licensing 80/12/22 3pp 07421 085

8101090315 Forwards response to questions re containment sump & effect on long term cooling following LOCA full flow testing performed as part of startup testing procedures. Alden Lab proposal concerning model test encl
NICHOLS, T. C. South Carolina Electric & Gas Co 80/12/29 28pp 07399 001

8101050337 Forwards proprietary & nonproprietary "Summary Rept. Westinghouse Reactor Vessel Level Instrumentation Sys for Monitoring Inadequate Core Cooling (7300 Sys)." dtd Dec 1980 in response to NUREC-0737, Part II F. 2
NICHOLS, T. C. South Carolina Electric & Gas Co 80/12/30 2pp 07394 159

--8101050347 Requests "Summary Rept. Westinghouse Reactor Vessel Level Instrumentation Sys for Monitoring Inadequate Core Cooling (7300 Sys)." dtd Dec 1980 be withheld (ref 10CFR2.790) per previously submitted application AM-77-18 approved 771028
WIESEMAN, R. A. Westinghouse Electric Corp 80/12/23 7pp 07354 161

8101060577 Responds to NRC request for updated info re occurrence of earthquakes similar to 1884 event in Charleston, SC. Similar earthquakes have potential to occur in vicinity. Seismic engineering parameters should be carefully considered
DEVINE, J. Interior Dept. of Geological Survey 80/12/30 4pp 07399 171

8101090234 Forwards list of TLD station locations near facility & proposed route for exchanging TLDs for NRC direct radiation monitoring network w/o encls
STONER, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/12/30 2pp 07475 301

8101270219 Notification of 810107 meeting w/Util in Bethesda, MD re outstanding issues in Instrumentation & Control Sys Branch safety evaluation
NICHOLS, T. C. Licensing Branch 2 80/12/31 3pp 07546 016

8101080417 Requests authorization to utilize Code Case N-282 during re-stamping of sys Code reviewed by NRC & will be included in revision to Reg Guide 1.84
NICHOLS, T. C. South Carolina Electric & Gas Co 81/01/02 2pp 07420 313

8101090503 Advises that estimated fuel load readiness date is Aug. Projection is based on engineering, preoperational testing & const work remaining
NICHOLS, T. C. Southern California Edison Co 81/01/06 1p 07426 362

8101130102 Forwards "Separation Audit of Class IE Electric Equipment & Circuits Rept." & "Procedure to Audit Separation of Class IE Electric Equipment & Circuits." Results indicate FSAR separation criteria effectively implemented
NICHOLS, T. C. South Carolina Electric & Gas Co 81/01/06 1p 07449 174

--8101130107 "Separation Audit of Class IE Electric Equipment & Circuits"
* Gilbert/Commonwealth Cos 81/01/06 10pp 07449 175

--8101130112 "Procedure to Audit Separation of Class IE Electric Equipment & Circuits." List of audited Class IE & associated circuits & equipment & summary of discrepancy types encl
POAHL, D. J., THOMAS, W. D., DELP, G. A. South Carolina Electric & Gas Co 80/09/22 33pp 07449 185

8101130121 Responds to NUREC-0737, Items II K 2 & II K 3. Westinghouse owners group is performing blind post-test predictions of LOFT Experiment L3-6
NICHOLS, T. C. South Carolina Electric & Gas Co 81/01/06 4pp 07449 230

8101130126 Forwards revised data for Tech Spec Table 3.4-1 & disc leak tight integrity of primary coolant sys pressure isolation valves
NICHOLS, T. C. South Carolina Electric & Gas Co 81/01/06 3pp 07449 234

8101200582 Authorizes use of bellows assembly not in full accordance w/ASME code requirements in response to 801031 request. Assembly will replace damaged assembly in reactor bldg steam generator blowdown penetration
TEDESCO, R. L. Assistant Director for Licensing 81/01/07 3pp 07477 287

8101130089 Responds to Question 211 133 re reactor vessel vent system removes noncondensable gases from reactor vessel head. Info will be incorporated into FSAR Amend 23
NICHOLS, T. C. South Carolina Electric & Gas Co 81/01/09 10pp 07456 001

8101130293 Forwards "Comparison of Mgt/Technical Resources to Regulatory Guidance"
NICHOLS, T. C. South Carolina Electric & Gas Co 81/01/09 1p 07447 225

--8101130296 "Comparison of Mgt/Technical Resources to Regulatory Guidance"
* South Carolina Electric & Gas Co 81/01/31 49pp 07447

8101150103 Forwards design review of plant shielding & environmental qualification of equipment for spaces/sys which may be used in post-accident operations outside reactor bldg. Info will be incorporated in Amend 23 of FSAR
NICHOLS, T. C. South Carolina Electric & Gas Co 81/01/09 46pp 07308 001

8101160290 Submits info addressing NUREC-0737, II K 3.17, "Rept on Outage of ECCS Licensee Rept. & Proposed Tech Specs Changes." Administrative Procedure AP-217 written establishing program for equipment removal from & restoration to svc
NICHOLS, T. C. South Carolina Electric & Gas Co 81/01/12 2pp 07470 169

8101160395 Informs that licensee has submitted electrical schematic for acoustic leak monitor to NRC project manager W Kane, per requirements of IMJ Item II D 3
NICHOLS, T. C. South Carolina Electric & Gas Co 81/01/13 1p 07470 168

101220262 Forwards human factors engineering evaluation & improvement of control room Rept describes backfits being implemented to correct discrepancies noted in NRC audit & Essex preliminary evaluation
NICHOLS, T C South Carolina Electric & Gas Co 01/01/15 1p
07496 131

-101220265 Human Factors Engineering Evaluation & Improvement of VC Summer Nuclear Station Control Room, Phase 1 - Prepared for util
JEORLING, D H, STEELE, E H, VERDI, A P Essex Corp 01/01/31
214pp 07496 132

101230405 Forwards proprietary & nonproprietary versions of Revision 1 to 'Environ Qualification of Safety-Related Electrical Equipment/MUREQ-0500' Proprietary version withheld (ref 10CFR2 790) Westinghouse affidavit encl
NICHOLS, T C South Carolina Electric & Gas Co 01/01/15 9pp
07536 093

-101230410 Nonproprietary version of Revision 1 to 'Environ Qualification of Safety-Related Electrical Equipment/MUREQ-0500'
* South Carolina Electric & Gas Co 01/01/15 303pp 07536 092

101290775 Forwards summary of major points of Instrumentation & Control Sys Branch 001112-14 audit drawing review Addl info requested to complete evaluation Site visit summary & list of attendees encl
TEDESCO, R L Assistant Director for Licensing 01/01/15 17pp
07338 001

101200258 Provides proposed survey program for verification of svc water intake line location & structural integrity, in response to NRC request at 801119 meeting.
NICHOLS, T C South Carolina Electric & Gas Co 01/01/16 3pp
07486 235

101280119 Responds to comments received at 810107 meeting in Bethesda, MD re NRC 801112-14 site visit Manual closure capability to effect valve closure w/accumulator air source to be provided in control room Reset capability to be added to panels
NICHOLS, T C South Carolina Electric & Gas Co. 01/01/23 3pp
07358 039

NRC Draft/Final Environmental Statements, supp's & correspondence

101090017 Forwards NABA comments on draft EIS for facility Questions why wind rose data was not taken into account in determining probability of total population exposure. Ten copies of final EIS requested
MINK, R T Commerce, Dept of 00/12/24 2pp 07379 344

101060474 Forwards responses to questions re Section 7 of DES, per IFC 801201 telecopy request
NICHOLS, T C South Carolina Electric & Gas Co 00/12/31 6pp
07398 122

101090497 Ack receipt of 801110 ltr transmitting suppl to draft EIS Provides detailed comments on sections re groundwater & uncertainties Finding of Lewis Rept w/respect to uncertainty in risk of reactor accidents should be discussed in FES
RATHLEBERGER Interior, Dept of 01/01/05 2pp 07427 333

101210590 Applauds NRC decision to prepare suppl to DES for evaluation of environ impacts from different LUR accident scenarios including Class 9 accidents. Technical comments on DES encl
HAYMER, R W Environmental Protection Agency 01/01/12 3pp
07409 253

101260593 Comments on DES for facility re possible impacts of Class 9 accidents, in response to NRC request. Discussion of probabilities of occurrence, magnitude of consequences & risk considerations should be given separate attention.
MILLS, W A Environmental Protection Agency. 01/01/17 2pp
07532 087

101270743 Comments on DES suppl to facility operation. Exposure area of 500 miles is not required by NRC policy statement. Practically all health-related exposures would occur within 50-mile radius.
BUCHEV, Q D Washington Public Power Supply System 01/01/19 1p
07548: 273

Security, medical, emergency & fire protection plans

101070387 Ltr to all licensees of operating reactor plants. CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing 00/11/13 2pp

8101090123 Releases public version of util radiation emergency plan
FELTON, J H Division of Rules and Records 00/12/01 1p
07428 226.

--8101090125 Forwards public version of radiation emergency plan, Revision 2
NICHOLS, T C South Carolina Electric & Gas Co 00/10/13 1p
07428 227.

--6101090127 Public version of radiation emergency plan, Revision 2
* South Carolina Electric & Gas Co 00/10/31 150pp 07428 228

8101200001 Forwards request for addl info & comments re 790820 training & qualification plan & 790621 safeguards contingency plan Encl withheld (ref 10CFR2 790)
TEDESCO, R L Assistant Director for Licensing 00/12/19 2pp
07487 025

8101140332 Requests that encl facility emergency planning info be made publicly available w/o encl
SHOUBER, J L Division of Rules and Records 00/12/31 1p
07308 001

8101270965 Forwards request for addl info, resulting from review of v 810113 emergency plan. Revised plan due by 810116
TEDESCO, R L Assistant Director for Licensing 01/01/14 10pp
07183 001

8101300857 Forwards facility emergency planning info to be made publicly available w/o encl
SHOUBER, J L Division of Rules and Records 01/01/23 1p
07587 027.

8101590129 Forwards Revision 1 to safeguards contingency plan Plan withheld (ref 10CFR2 790)
NICHOLS, T C South Carolina Electric & Gas Co 01/01/26 1p
07566 363

0 Adjudicatory correspondence

8101070010 Memorandum R. order following 801125 third prehearing conference Reaffirms that intervenor must submit final list of intended witnesses, documents & summaries of testimonies by 810131
GROSSMAN, H Atomic Safety and Licensing Board Panel 00/12/30 8pp 07413 307

--8101070017 Directs DFC of Secretary & NRC staff to cease using FYB funds for procedural assistance program, per encl Comptroller General, 801203 ltr
ANFARKE, J Commissioners 00/12/04 1p 07413 315

8101060431 Forwards addl financial qualifications requested in 801201 ltr
NICHOLS, T C South Carolina Electric & Gas Co 00/12/31 14pp
07394 001

--8101060438 Order by Public Svc Commission of SC approving util req for adjustments in electric rates & charges.
YONCE, H Q South Carolina Electric & Gas Co STILL, J H South California Edison Co 00/06/30 94pp 07394 105

1 Financial information

8101060431 Forwards addl financial qualifications requested in 801201 ltr
NICHOLS, T C South Carolina Electric & Gas Co. 00/12/31 14pp
07394 001

--8101060434 Annual Rept 1979
* South Carolina Electric & Gas Co 00/02/00 140pp 07394 0

--8101060438 Order by Public Svc Commission of SC approving util req for adjustments in electric rates & charges.
YONCE, H Q South Carolina Electric & Gas Co STILL, J H South California Edison Co 00/06/30 94pp 07394 105.

--8101060441 Direct testimony of OS Wooten supporting util request for rate relief
WOOTEN, O S South Carolina Electric & Gas Co 79/08/31 22pp
07394 199

--8101060445 Rate of return testimony of SF Sherwin on 790831 Financial statements encl
SHERWIN, S F South Carolina Electric & Gas Co. SHERWIN, S F Foster Associates, Inc 79/08/31 195pp 07394 221

J Insurance & indemnity information

B101090463 Forwards Endorsement 14 to HELIA Policy NR-252
FIELDER, J Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc
Div 80/12/31 2pp 07442 030

B101090542 Forwards Endorsement 15 to Axl Policy MF-252
FIELDER, J Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc
Div 80/12/31 2pp 07427 337

K Utility Final Safety Analysis Report (FSAR) & amends

B101090487 Forwards revised pages to FSAR, reflecting seismic monitoring
program status, in response to NRC request changes will be
incorporated in Amend 23 by late Jan 1981
NICHOLS, T C South Carolina Electric & Gas Co 81/01/07 3pp
07427 328

B101210351 Forwards Amend 23 to FSAR, addressing NUREG-0737 criteria
NICHOLS, T C South Carolina Electric & Gas Co 81/01/19 2pp
07472 071

--B101210350 Amend 23 to FSAR, addressing NUREG-0737 criteria
South Carolina Electric & Gas Co 81/01/31 700pp 07492 073

M Antitrust correspondence

B101190458 Forwards joint sys coordination & integration agreement
between SC Public Svc Authority & Central Electric Power
Cooperative, Inc Certificate of Svc encl
MORRISON, H P Cahill, Gordon & Reindel 81/01/14 99pp.
07473 061

B101200082 Order scheduling filing of comments from Central Electric
Cooperative, SC Public Svc Authority & SC Electric & Gas Co
by 810123, from DOJ by 810130 & from AEC by 810205
Certificate of Svc encl
MORRISON, J C Office of the Secretary of the Commission 81/01/15
4pp 07538 116

B101210349 Response to Commission B10115 order requesting comments on
effect of agreement between Central Electric Power
Cooperative, Inc & PSC of SC Antitrust review should be
ordered Certificate of Svc & supportive documents encl
BRAHD, W E , HALL, E E , BEENE, S T Central Electric Power
Cooperative, Inc 81/01/23 47pp 07546 351

B101280161 Response to B10115 order for comment on agreement between
SC Public Svc Authority & Central Electric Cooperative Addl
antitrust review unnecessary Petition for significant change
finding should be denied W/Certificate of Svc
MORRISON, H D South Carolina Public Service Authority 81/01/23
14pp 07556 106

B101280331 Comments in response to B10115 order re agreement between
SC Public Svc Authority & Central Electric Power
Cooperative No further antitrust review warranted
Certificate of Svc encl
MORRISON, J B South Carolina Electric & Gas Co, KNOTT, J B
Debevoise & Liberman 81/01/23 12pp 07557 186

Q. Inspection reports, IE Bulletins & correspondence

B101060196 Forwards IE Info Notice 80-44, "Actuation of ECCB in
Recirculation Mode While in Hot Shutdown." No written
response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/16
1p 07391 308

B101060212 Forwards IE Info Notice 80-44, "Actuation of ECCB in
Recirculation Mode While in Hot Shutdown." No written
response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/16
1p 07391 317

B101080217 Ack receipt of B01124 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-395/80-25
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 80/12/16 1p 07421 041

--B101080227 Responds to NRC B01006 ltr re violations noted in IE Insp
Rept 50-395/80-25 Corrective actions issued special
instructions re valve lineup operations.
NICHOLS, T C South Carolina Electric & Gas Co 80/11/24 3pp
07421 042

--B101080233 Forwards IE Insp Rept 50-395/80-25 on B00721-0831 & notes
of violation
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 80/10/06 2pp 07421 045

--B101080239 Notice of violation from Insp on B00721-0831
Region 2, Atlanta, Office of the Director 80/10/06 1p
07421 047

--B101080248 IE Insp Rept 50-395/80-25 on B00721-0831 Noncompliance
noted failure to follow procedure re valve lineup
SMOLDS, J L Region 2, Atlanta, Office of the Director
KELLDON, P J Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 80/10/06 13pp 07421 048

B101090385 Responds to IE Bulletin 80-23 No Valcor solenoid valves,
V70900-21-1 or 3 used Twenty manhours expended on bulletin
review
NICHOLS, S. I C Southern California Edison Co 80/12/29 1p
07378 360

B101270011 Responds to IE Bulletin 80-23 re Valcor Engineering Corp
solenoid valve failure Valcor solenoid valves V70900-21-1 &
V70900-23-3 not used
NICHOLS, T C South Carolina Electric & Gas Co 80/12/29 1p
07547 020

B101290194 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by
Malcolm Foundry Co, Inc." No active valves supplied w/Malcolm
Foundry yokes Westinghouse is conducting generic review
Study will not be complete until mid Feb 1981
NICHOLS, T C South Carolina Electric & Gas Co 80/12/31 1p
07567 353

B101220091 Forwards IE Insp Rept 50-395/80-36 on B01119-21 No
noncompliance noted
KENNA, W B Region 2, Atlanta, Safeguards Branch 81/01/02 2pp.
07502 001

--B101220095 IE Insp Rept 50-395/80-36 on B01119-21 No noncompliance
noted Major areas inspected preoperational status of
physical security program Details withheld (ref 10CFR2 790)
PERNEY, C D , HILL, A O Region 2, Atlanta, Office of the Director
MCQUIRE, D R Region 2, Atlanta, Safeguards Branch 80/12/31
07502 003

B101130093 Responds to IE Bulletin 80-06 All engineering safety
features control circuits will be reviewed re deficiencies
in bypass, override & reset of engineering safety features
action Deviations from criteria will be corrected
NICHOLS, T C South Carolina Electric & Gas Co 81/01/09 1p
07497 022

S Reportable occurrences, LERs & related correspondence

B101220559 Final deficiency rept re unauthorized hanger work, initially
reported on B01216 Caused by human error & lack of knowledge
of program requirements Insp program is being performed to
monitor installed hangers
NICHOLS, T C South Carolina Electric & Gas Co 81/01/13 3pp
07503 074

B101260491 Deficiency rept re presence of Train A red cable in Channel
IV yellow protection control cabinet No credible fault of
failure exists which could degrade min degree of channel or
train redundancy Westinghouse evaluation encl
NICHOLS, T C South Carolina Electric & Gas Co 81/01/16 6pp
07529 215

B101260607 Interim deficiency rept, originally reported on B01024, re
advert boron dilution event at shutdown conditions on RHR
sys Final rept will be issued after Westinghouse completes
investigation & long-term solution has been evaluated.
NICHOLS, T C South Carolina Electric & Gas Co 81/01/16 2pp.
07531 225

B101260643 Final interim deficiency rept, originally reported on B00124,
re violation of Westinghouse separation criteria, for
separation of field run protection & control circuits
Thirty-four circuits routed in cable trays.
NICHOLS, T C South Carolina Electric & Gas Co 81/01/16 3pp.
07531 227

B101280257 Final deficiency rept re failure to install insulation on
pipes of penetration assemblies, initially reported in B01224
telcon Insulation omission found not reportable condition.
NICHOLS, T C South Carolina Electric & Gas Co 81/01/23 2pp.
07558 002

T Hearing transcripts on non-antitrust matters

B101060431 Forwards addl financial qualifications requested in B01208 ltr
NICHOLB, T C South Carolina Electric & Gas Co 80/12/31 14pp
07394 001

--B101060441 Direct testimony of OS Hooten supporting util request for rate relief
HOOTEN, O S South Carolina Electric & Gas Co 79/08/31 22pp
07394 199

--B101060445 Rate of return testimony of SF Sherwin on 790831 Financial statements encl
SHERWIN, S F South Carolina Electric & Gas Co SHERWIN, S F
Foster Associates, Inc 79/08/31 199pp 07394 221

V Operator Examinations

B101060380 Forwards 5-yr projection of licensed operators at plant, per FJ Williams of Licensee Qualification Branch request
NICHOLB, T C South Carolina Electric & Gas Co 80/12/30 14pp
07392 079.

B101090013 Discusses util position on TMI items re training & qualifications for shift technical advisors & independent safety engineering group
NICHOLB, T C South Carolina Electric & Gas Co 81/01/02 2pp
07442 237.

B101270496 Forwards revised Attachment V re total licensed operators vs required licensed operators, per B01230 ltr Fifth shift to be added in June 1982
NICHOLB, T C South Carolina Electric & Gas Co 81/01/22 3pp
07543 007.

DOCKET 50-396 UNIV OF VIRGINIA CAVALIER REACTOR

R. Periodic operating reports & related correspondence

B101300382 Submits annual operating rept for 1980, per Section 4.7.e of Tech Specs
FARRAR, J D Virginia, Univ of 81/01/09 14pp. 07591 236

DOCKET 50-397 WPPSS NUCLEAR PROJECT, UNIT 2

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

B101190505 Ltr to all BWR applicants for OL re BWR scram discharge sys safety evaluation & requirements Rept specifying acceptable basis for continued BWR plant operation & design criteria for scram discharge val encl
TEDESCO, R L Assistant Director for Licensing 80/12/22 2pp

--B101190514 Forwards generic safety evaluation re BWR scram discharge sys. Review identified two addl requirements to those proposed by owners group re scram discharge val designs Rept should be transmitted to license applicants.
CHECK, P B Assistant Director for Plant Systems 80/12/01 2pp
07183 001.

B101200157 Summary of B01210 meeting w/Mark II owners re status of generic improved chugging load model Owners requested to justify delay in program & investigate alternatives
ANDERSON, C J Generic Issues Branch 80/12/22 4pp.

B101140959 Summary of Dec 1980 meeting w/Mark II owners group, QE, BN, L, MIT, B&W, Bechtel & Ebasco Svcs, Inc re suppression pool temp limits List of attendees & handouts encl
SU, T M Generic Issues Branch 80/12/30 4pp

B101190423 Forwards Instrumentation & Control Sys Branch addl Round 2 questions Applicant required to describe liquid level measuring sys within containment used to initiate safety-related actions
TEDESCO, R L Assistant Director for Licensing 80/12/30 7pp
07475 164

B101190347 Responds to NRC B00421 ltr requesting info on use of Category I masonry walls No Category I masonry walls exist at facility
BOUCHEY, O D Washington Public Power Supply System 81/01/08
07476 085

B101190346 Advises that updated QA const program description will be issued as amend to FSAR to reflect project organization changes Meeting to discuss changes tentatively scheduled for 810225
BOUCHEY, O D Washington Public Power Supply System 81/01/08
07475 330

B101210561 Notifies that util confirms request for meeting w/Maille Branch on B10121 to discuss review of Unit 2 sacrificial shield wall, per telcon w/MD Lynch of LRC
BOUCHEY, O D Washington Public Power Supply System 81/01/12
07489 297

B101230511 Notification of B10121 meeting w/util in Bethesda, MD re geological investigation program being conducted on faulting on Oable Mountain
LYNCH, M D Licensing Branch 1 81/01/12 3pp 07512 206

B101230512 Notification of B10121 meeting w/util in Bethesda, MD re developments by util in defining pool dynamic loads
LYNCH, M D Licensing Branch 1 81/01/12 3pp 07512 209

B101270669 Forwards summary of facility geology program in support of B10121 meeting w/NRC in Bethesda, MD
BOUCHEY, O D Washington Public Power Supply System 81/01/21
12pp 07543 073

F Security, medical, emergency & fire protection plans

B101070287 Ltr to all licensees of operating reactor plants, CP hold & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & b; applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

G Inspection reports, IE Bulletins & correspondence

B101050510 Forwards IE Info Notice 80-43, "Failures of Continuous Level Monitor for Scram Discharge Val at Dresden Unit 2"
No response required
ENGELKEN, R H Region 5, San Francisco, Office of the Director
80/12/05 1p 07390 277

B101290643 Forwards IE Insp Rept 50-397/80-18 on B01001-31 No noncompliance noted
SPENCER, G B Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/12/16 2pp 07566 131

--B101290646 IE Insp Rept 50-397/80-18 on B01001-31 No noncompliance noted Major areas inspected licensee & contractor activities to re-evaluate & improve methods of installing safety-related equipment
TOTH, A D Region 5, San Francisco, Office of the Director
HAYNES, R C Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/12/11 10pp 07566 133

B101130110 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Scram Capability." No response required
ENGELKEN, R H Region 5, San Francisco, Office of the Director
80/12/17 1p 07449 223.

B101090784 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of 76 Control Rods to Fully Insert During Scram at BWR." No written response required
ENGELKEN, R H Region 5, San Francisco, Office of the Director
80/12/18 1p 07430 253

B101050164 Forwards IE Bulletin 80-25, "Operating Problems W/Target Rod Safety Relief Valves at BWRs." No response required
ENGELKEN, R H Region 5, San Francisco, Office of the Director
80/12/19 2pp 07377 269

B101210110 Forwards IE Insp Rept 50-397/80-21 on B01202-04 No noncompliance noted
CREW, J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/12/24 2pp 07489 350

--B101210119 IE Insp Rept 50-397/80-21 on B01202-04 No noncompliance noted Major areas inspected: low pressure core spray preoperational test, flushing program & results of control rod hydraulic sys flush.
STEINBERG, D M Region 5, San Francisco, Reactor Operations Nuclear Support Branch CARLSON, J D Region 5, San Francisco, Office of the Director 80/12/23 3pp 07489 352

Amend 2 Amend includes drawing A table changes reflective of as-built conditions & description of mechanized equipment used for examination of reactor pressure vessel
BOUCHER, D D Washington Public Power Supply System 80/12/31 2pp
07517 549

-B101040021 "Preservice Insp Program Plan & Revisions, Amend 2
Washington Public Power Supply System 80/12/18 300pp
07517 051

B101270464 Responds to IE Bulletin 80-23, "Failures of Solenoid Valves
Mfg by Valcor Engineering Corp Specified valves are not
used at Facility
MAZUR, D H Washington Public Power Supply System 80/12/31 1p
07549 061

B101276505 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by
Malcolm Foundry Co. Inc " Manufacturers have been contacted
Supplemental rept will be sent during Feb 1981
MATLOCK, R G Washington Public Power Supply System 81/01/02 2pp
07549 349

B101270459 Confirms 801223 telcon approving 30-day extension to respond
to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm
Foundry Co. Inc
MAZUR, D H Washington Public Power Supply System 81/01/06 1p
07543 348

5 Reportable occurrences, IERs & related correspondence

B101140518 Final deficiency rept re fuel pool boiling prevention.
Initially reported 770818 Addl cooling coils will not be
placed in standby gas treatment sys Corrective action
fuel pool cooling sys upgraded to safety grade status
MATLOCK, R G Washington Public Power Supply System 80/12/03 2pp
07452 053

B101050013 Interim deficiency rept originally reported on B01114 re
overloads on supports for spray pond piping Caused by
hardware design error Review of original design margins to
be completed by B01212
MATLOCK, R G Washington Public Power Supply System 80/12/15 2pp
07385 274

B101050089 Interim deficiency rept re nonseismic Class 1 const &
installation of control room cabinet for digital electro-
hydraulic turbine generator Failure during seismic event
could cause damage to safety-related equipment
MATLOCK, R G Washington Public Power Supply System 80/12/15 2pp
07376 229

B101140497 Interim deficiency rept re wiring interfaces on motor
operators Conflict discovered between electrical const
drawings & info provided by subcontractor Followup rept to
be submitted by B10316
MATLOCK, R G Washington Public Power Supply System 81/01/07 3pp
07461 157

B101230730 Part 2) rept re failure to provide proper Control Components
Intl valves supplying 2 gpm flow when in closed position
Caused by valve Failure Affected licensees notified &
selection of alternative method underway
TAYLOR, J H Babcock & Wilcox Co 81/01/09 2pp 07308-001

DOCKET 50-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Laminar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

B101050325 Informs of Unit 1 const schedule revision, changing
commercial operation date from Mar to Sept 1985 New schedule
requires timely DL issuance for Dec 1984 fuel loading Future
FSAR amend will reflect const change Other units unchanged.
JOHNS, J A Carolina Power & Light Co 80/12/30 1p 07385.279

3 Inspection reports, IE Bulletins & correspondence

B101060233 Forwards IE Info Notice 80-44, "Actuation of ECCS in
Recirculation Mode While in Hot Shutdown " No written
response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/
1p 07391 341

B101140200 Responds to IE Bulletin 80-23 re Failures of solenoid
mfg by Valcor Engineering Corp No valves mfg by vendor used
MCUFFIE, M A Carolina Power & Light Co 80/12/24 1p 074

B101210217 Responds to IE Bulletin 80-21, "Valve Yokes Supplied
Malcolm Foundry Co. Inc " Any valve parts having properties
not in accordance w/ASTM matl spec will be replaced by
affected vendor
MCUFFIE, M A Carolina Power & Light Co 81/01/05 2pp
07493 047

B101270353 Ack receipt of 801223 ltr forwarding revised response
Insp Repts 50-400/80-13, 50-401/80-13, 50-402/80-13 &
50-403/80-13
KUNRATH, C E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 81/01/13 1p 07571 355

5 Reportable occurrences, LERs & related correspondence

B101070437 Interim deficiency rept re deficiencies in procurement
fabrication & insp of engineered plates for safety-related
load concrete embedment & support Addl ultrasonic exams
being performed Re-evaluation/correction completion B10301
CHIANQI, H J Carolina Power & Light Co 80/12/30 1p 0741

B101130225 Interim deficiency rept re welding of cadwell sleeve
nonqualified procedures originally reported on B01205
Procedures have been qualified Requests extension to B10202
for evaluation
CHIANQI, H J Carolina Power & Light Co 81/01/05 2pp 075

DOCKET 50-401 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Laminar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

B101050325 Informs of Unit 1 const schedule revision, changing
commercial operation date from Mar to Sept 1985 New schedule
requires timely DL issuance for Dec 1984 fuel loading Future
FSAR amend will reflect const change Other units unchanged.
JOHNS, J A Carolina Power & Light Co 80/12/30 1p 07385

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B10102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

3 Inspection reports, IE Bulletins & correspondence

B101060233 Forwards IE Info Notice 80-44, "Actuation of ECCS in
Recirculation Mode While in Hot Shutdown " No written
response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/
1p 07391 341

B101140200 Responds to IE Bulletin 80-23 re Failures of solenoid
mfg by Valcor Engineering Corp No valves mfg by vendor used
MCUFFIE, M A Carolina Power & Light Co 80/12/24 1p 07

00FFIE.M.A. Carolina Power & Light Co. B1/01/05 2pp
490 047

290353 Ack receipt of B01223 ltr forwarding revised response to IE
asp Repts 50-400/80-15, 50-401/80-13, 50-402/80-13 &
50-403/80-13
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering
Support Branch B1/01/13 1p 07571 359

Reportable occurrences, LERs & related correspondence

070437 Interim deficiency rept re deficiencies in procurement
fabrication & insp of engineered plates for safety-related
as concrete embedment & support Addl ultrasonic exams
being performed. Re-evaluation/correction completion B10301
CHIANZI, H.J. Carolina Power & Light Co. B0/12/30 1p 07414 143

DOCKET 50-402 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 3

Application/construction stage documents & correspondence

220466 Ltr to all power reactor licensees & applicants forwarding
summary of B01112 meeting re implementation of guidance for
resolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
GENHUT, D.G. Division of Licensing B0/11/26 Bpp

050325 Inform of Unit 1 const schedule revision, changing
commercial operation date from Mar to Sept 1985 New schedule
requires timely OL issuance for Dec 1984 fuel loading Future
LAR amend will reflect const change Other units unchanged
NEB, J.A. Carolina Power & Light Co. B0/12/30 1p 07285 279

Security, medical, emergency & fire protection plans

090387 Ltr to all licensees of operating reactor plants, CP holders
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B10102 & by applicants as part of FSAR
GENHUT, D.G. Division of Licensing B0/11/13 2pp

Inspection reports, IE Bulletins & correspondence

060233 Forwards IE Info Notice 80-44, "Actuation of ECCB in
Recirculation Mode While in Hot Shutdown" No written
response required
O'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/12/16

140200 Responds to IE Bulletin 80-23 re failures of solenoid valves
mfg by Valcor Engineering Corp No valves mfg by vendor used
DUFFIE, M.A. Carolina Power & Light Co. B0/12/24 1p 07461 252

210217 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by
Malcolm Foundry Co. Inc." Any valve parts having properties
not in accordance w/ASTM matl spec will be replaced by
affected vendor
DUFFIE, M.A. Carolina Power & Light Co. B1/01/05 2pp
490 047

290353 Ack receipt of B01223 ltr forwarding revised response to IE
asp Repts 50-400/80-15, 50-401/80-13, 50-402/80-13 &
50-403/80-13
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering
Support Branch B1/01/13 1p 07571 359

Reportable occurrences, LERs & related correspondence

070437 Interim deficiency rept re deficiencies in procurement
fabrication & insp of engineered plates for safety-related
as concrete embedment & support Addl ultrasonic exams
being performed. Re-evaluation/correction completion B10301
CHIANZI, H.J. Carolina Power & Light Co. B0/12/30 1p 07414 143

DOCKET 50-403 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 4

Application/construction stage documents & correspondence

220466 Ltr to all power reactor licensees & applicants forwarding
summary of B01112 meeting re implementation of guidance for
resolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
GENHUT, D.G. Division of Licensing B0/11/26 Bpp

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B10102 & by applicants as part of FSAR
EISENHUT, D.G. Division of Licensing B0/11/13 2pp

Inspection reports, IF Bulletins & correspondence

B101040233 Forwards IE Info Notice 80-44, "Actuation of ECCB in
Recirculation Mode While in Hot Shutdown" No written
response required
O'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/12/16
1p

B101140200 Responds to IE Bulletin 80-23 re failures of solenoid valves
mfg by Valcor Engineering Corp No valves mfg by vendor used
DUFFIE, M.A. Carolina Power & Light Co. B0/12/24 1p

B101210217 Responds to IF Bulletin 80-21, "Valve Yokes Supplied by
Malcolm Foundry Co. Inc." Any valve parts having properties
not in accordance w/ASTM matl spec will be replaced by
affected vendor
DUFFIE, M.A. Carolina Power & Light Co. B1/01/05 2pp

B101290353 Ack receipt of B01223 ltr forwarding revised response to IE
asp Repts 50-400/80-15, 50-401/80-13, 50-402/80-13 &
50-403/80-13
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering
Support Branch B1/01/13 1p

S. Reportable occurrences, LERs & related correspondence

B101070437 Interim deficiency rept re deficiencies in procurement
fabrication & insp of engineered plates for safety-related
load concrete embedment & support Addl ultrasonic exams
being performed. Re-evaluation/correction completion B10301
CHIANZI, H.J. Carolina Power & Light Co. B0/12/30 1p

DOCKET 50-404 NORTH ANNA POWER STATION, UNIT 3

F Security, medical, emergency & fire protection plans

B101060615 Requests that encl emergency planning info be made
publicly available w/o encl
SOUDER, J.L. Division of Rules and Records B0/12/17 1p
07399 399

B101080146 Requests that encl emergency planning info be made publicly
available w/o encl
SOUDER, J.L. Division of Rules and Records B0/12/17 1p
07419 248

J Insurance & indemnity information

B101130357 Forwards Endorsements 2, 5, 4, 4, 24, 5B & 31 to NELA Policies
EB-70, EB-63, EB-28, EB-27, NS-316, NF-186 & NF-240, respectively.
HAIRFIELD, D.K. J. Marsh & McLennan, Inc. & M & M Nuclear Consultants, Inc.
Div. B1/01/09 1app

S Reportable occurrences, LERs & related correspondence

B101270707 Interim deficiency rept re apparent disparity between B&W
mathematical model of upper steam generator support sys &
actual hardware. Initially reported B01223 Caused by manner
in which forces were reported Final rept expected by B10223
SPENCER, W.C. Virginia Electric & Power Co. B1/01/22 6pp
07545 243

DOCKET 50-405 NORTH ANNA POWER STATION, UNIT 4

F Security, medical, emergency & fire protection plans

B101060615 Requests that encl emergency planning info be made
publicly available w/o encl
SOUDER, J.L. Division of Rules and Records B0/12/17 1p

B101CB0146 Requests that encl emergency planning info be made publicly available W/O encl
SQUER, J L Division of Rules and Records 80/12/17 1p

J Insurance & indemnity information

B101130357 Forwards Endorsements 2, 5, 4, 4, 24, 98 & 31 to NCLIA Policies EB-70, EB-63, EB-28, EB-27, NS-316, NF-186 & NF-240, respectively
HAIRFIELD, K J Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc
Div 81/01/09 16pp

DOCKET 50-409 LA CROSSE BOILING WATER REACTOR

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSA9
EISENHUT, D G Division of Licensing 80/11/13 2pp

B101050326 Forwards revisions to physical security plan for facility Revisions withheld (ref 10CFR2 790)
LINDER, F Dairyland Power Cooperative 80/12/29 2pp 07389 284

B101220025 Forwards training & qualification plan revisions Plan withheld (ref 10CFR2 790)
LINDER, F Dairyland Power Cooperative 81/01/15 3pp 07501 343.

G Adjudicatory correspondence

B101120524 Prehearing conference memorandum from 801217 hearing which established proposed findings & conclusions schedule & SSE phase discovery schedule
DECHHOEFER, C Atomic Safety and Licensing Board Panel 81/01/06 3pp 07445 176

--B101120528 Supports nuclear power Certificate of Bvc encl.
VASLOW, C Affiliation Unknown 80/12/16 3pp 07445 178

B101140983 Order granting extension until 810123 for Commission to review ALAB-61B
CHILK, S J Office of the Secretary of the Commission 81/01/09 3pp 07456 299

B101280044 Motion that listed corrections be made to transcript of 801216-17 evidentiary hearing in LaCrosse, WI Certificate of Bvc encl
BURNS, S G Rule-making & Enforcement Division 81/01/26 10pp 07555 093

H General correspondence

B101090577 Comments that nation needs nuclear power for economic political & moral reasons
VASLOW, C Affiliation Unknown 80/12/16 1p 07428 353

B101050307 Comments by WXEN-TV/NDM-TV on ASLB review of facility. Power supplied by plant is necessary for station to perform per FCC license requirements Recommends that NRC approve continued operation of facility
PESCHAU, D F Affiliation Unknown 80/12/19 1p 07379 306

J Insurance & indemnity information

B101140225 Forwards Endorsements 38 & 39 to NCLIA Policy NF-217
PAULY, S A Hobbs Brook Agency, Inc 81/01/06 4pp 07461 267

P. Operating license stage documents & correspondence

B011190112 Submits list of topics that should be added to 791116 listing for deletion from SEP review Revised list of DBE accident & transient groups applicable to BWRs encl.
CRUTCHFIELD, D Operating Reactors Branch 5 80/09/26 5pp

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01111 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D G Division of Licensing 80/11/26 5pp.

060896 Requests invoice be sent to licensee for review of route proposal
LLER, W G License Fee Management Branch 80/12/08 1p 400 127.

--B101060361 Forwards data re tests & manpower incurred in review of licensee request for route approval
MCCORRALD, W Physical Security Licensing Branch PARTLOW, J O Material Control Licensing Branch 80/11/03 2pp 07400 120

B101190113 Ltr to all BWR licensees forwarding B01201 generic safety evaluation re BWR steam discharge sys Recommends short-term actions necessary to assure safe operation of GE BWRs pending permanent design changes
EISENHUT, D G Division of Licensing 80/12/09 2pp

--B101190141 Generic safety evaluation re short-term actions required assure continued safe operation of operating BWRs Continued operation of plants is acceptable pending permanent design mods. Criteria for implementing design mods encl
* Division of Licensing 80/12/01 212pp. 07183 001.

B101140277 Requests info re SEP Topic IV-2, reactivity control sys design & protection against single failures Info should be provided within 90 days of receipt of ltr
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/15 4pp 07458 189

B101216322 Ltr for all SEP licensees forwarding guidelines for performing soil-structure interaction reviews for SEP facilities & simplified analytical approach for evaluating soil-structure interaction using lumped parameter model.
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/15 2pp 07491 348

B101210445 Forwards responses to questions on Rule 50.71e, "Periodic Updating of FBARs" & FR notice of final rule SEP plants need not comply w/rule until program is complete Non-SEP plants must comply within specified time frame.
EISENHUT, D G Division of Licensing 80/12/15 13pp

B101270130 Forwards safety evaluation of SEP Topic II-2.A, "Severe weather Phenomena" & TX Tech Univ rept, "Tornado & Straight Wind Hazard Probability for LaCrosse Nuclear Power Reactor Site, WI"
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/15 7pp 07547 221

--B101270141 "Tornado & Straight Wind Hazard Probability for LaCrosse Nuclear Power Reactor Site, WI"
MCDONALD, J R Texas Tech Univ NRC-04-76-345 80/05/31 26pp 07567 228

B101160029 Notification of 801218 meeting w/SEP owners group in Bethesda, MD re SEP program schedule for licensee topic completion & assignment of lead topics to plants.
RUESSELL, W T Technical Support Branch 80/12/16 2pp.

B101080099 Informs of 24-h load test performed 801127 on emergency Diesel Generator 13 at connected load of 300 kW in accordance w/resident inspector request & IE Bulletin 79-23.
LINDER, F Dairyland Power Cooperative 80/12/17 2pp 07420 34

B101230343 Forwards listing of all SEP correspondence re facility per SEP owners group B01202 meeting List provides basis upon which to determine plant status Review & comments requested.
W/O encl
CRUTCHFIELD, D Operating Reactors Branch 5 80/12/22 2pp 07512 104

B101090042 Provides extended schedule for response to NUREG-0737 requirements Delay due to refueling outage & ASLB hearings on site liquefaction Extensions do not represent delays in completion of mods
LINDER, F Dairyland Power Cooperative 80/12/31 2pp 07442 28

B101100804 Adequacy of Station Electric Distribution Sys Voltages, LACBWR, informal preliminary rept
UDY, A C Idaho National Engineering Laboratory B101100804 80/12/31 14pp 07444 045

B101300508 Advises that evaluation of SEP Topic V-10 A, "RHR Sys Heat Exchanger Tube Failures," is considered complete since until did not comment on NRC 790111 draft evaluation.
CRUTCHFIELD, D Operating Reactors Branch 5 81/01/07 2pp. 07586 268

B101300181 Forwards info re NUREG-0737 clarification items requested in NRC 801031 ltr. Comparison of facility shift technical advisor program to Institute of Nuclear Power Operations program encl
LINDER, F Dairyland Power Cooperative 81/01/16 18pp. 07586:2

8101270345 Submits info re injection of grout into voids under turbine
bldg that two 94 lb bags of cement used instead of two 49 lb
bags as stated in 801126 ltr
LINDER, F Dairyland Power Cooperative 81/01/21 1p 07543 094

9 Inspection reports, IE Bulletins & correspondence

8101030279 Forwards IE Info Notice 80-38, "Cracking in Charging Pump
Casing Cladding " No response required
KEPPLER, J Q Region 3, Chicago, Office of the Director 80/10/30
2pp 07389 223

8101060109 Forwards IE Circular 80-23, "Potential Defects in Beloit
Power Sys Emergency Generators " No written response
required
KEPPLER, J Q Region 3, Chicago, Office of the Director 80/10/31
1p 07397 320

8101060522 Forwards IE Info Notice 80-37, "Malfunction of Solenoid
Valves Mfg by Valcor Engineering Corp " No written response
is required
KEPPLER, J Q Region 3, Chicago, Office of the Director 80/10/31
2pp 07401 195

8101050471 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by
Malcolm Foundry Co. Inc " Written response required
KEPPLER, J Q Region 3, Chicago, Office of the Director 80/11/06
2pp 07390 032

8101060631 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply
Pressure Actuates Safety-Relief Valve Operation to Cause
Reactor Depressurization " No written response required
KEPPLER, J Q Region 3, Chicago, Office of the Director 80/11/07
2pp 07392 170

8101060390 Forwards IE Info Notice 80-41, "Failure of Spring Check
Valve in Decay Heat Removal Sys at Davis Besse Unit 1 " No
response required
KEPPLER, J Q Region 3, Chicago, Office of the Director 80/11/10
2pp 07391 085

8101060495 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves
Mfg by Valcor Engineering Corp " Written response required
KEPPLER, J Q Region 3, Chicago, Office of the Director 80/11/14
2pp 07391 223

8101050520 Forwards IE Info Notice 80-43, "Failures of Continuous Water
Level Monitor for Scram Discharge Vol at Dresden Unit 2 " No
response required
KEPPLER, J Q Region 3, Chicago, Office of the Director 80/12/05
2pp 07390 287

8101230667 Forwards IE Insp Rept 50-409/80-16 on 801202 No
noncompliance noted
FICRELLI, Q Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/12/11 2pp 07512 346

--8101230672 IE Insp Rept 50-409/80-16 on 801202 No noncompliance noted
Major areas inspected review of inservice procedures, work
activities, personnel certification & data & IE Bulletins
79-Q3A & 80-Q0 activities
WARD, K D Region 3, Chicago, Office of the Director
DANIELSON, D H Region 3, Chicago, Reactor Construction &
Engineering Support Branch 80/12/10 5pp 07512 348

8101210640 Forwards IE Insp Rept 50-409/80-13 on 801001-31 & notice of
violation
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support
Branch 80/12/16 2pp 07488 118

--8101210641 Notice of violation from insp on 801001-31.
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear
Support Branch 80/12/12 2pp 07488 120

--8101210643 IE Insp Rept 50-409/80-13 on 801001-31 Noncompliance noted:
use of unqualified guard as armed responder & failure of
shift supervisor to make required tours
FORNEY, W L, BRANCH, M W, RIDGWAY, K R Region 3, Chicago, Office
of the Director 80/12/12 7pp 07488 122

8101070627 Forwards IE Info Notice 80-45, "Potential Failure of BWR
Backup Manual Scram Capability " No written response
required
KEPPLER, J Q Region 3, Chicago, Office of the Director 80/12/17
2pp 07414 172

8101080099 Informs of 24-h load test performed 801127 on emergency
Diesel Generator 1B at connected load of 300 kW in
accordance w/resident inspector request & IE Bulletin 79-23
LINDER, F Dairyland Power Cooperative 80/12/17 2pp 07420 345

8101050182 Forwards IE Bulletin 80-25, "Operating Problems w/Target
Rock Safety Relief Valves at 3WRs " No response required
KEPPLER, J Q Region 3, Chicago, Office of the Director 80/12/19
2pp 07377 313

8101080109 Responds to IE Bulletin 80-21 re valve yokes supplied by
Malcolm Foundry Co. Inc No valves in safety-related sys have
parts cast by manufacturer Total manpower expended was 46-h
LINDER, F Dairyland Power Cooperative 80/12/19 1p 07420 359

8101300636 Responds to IE Bulletin 80-25, "Operating Problems w/Target
Rock Safety-Relief Valves at 3WRs " Pneumatic operated
safety valves not used or planned for use at facility
LINDER, F Dairyland Power Cooperative 80/12/31 3pp 07587 077

8101200178 Responds to IE Bulletin 80-24, "Prevention of Damage Due to
Water Leakage Inside Containment (801017 Indian Point 2
Event) " Facility has no open cooling water sys in operation
inside containment matching bulletin description
LINDER, F Dairyland Power Cooperative 81/01/06 4pp 07486 210

8101280515 Responds to IE Bulletin 80-13, "Cracking in Core Spray
Spargers " Facility does not utilize core spray spargers of
type in which cracks were detected No indication of defects
found in inspected components
LINDER, F Dairyland Power Cooperative 81/01/13 2pp 07590 326

R Periodic operating reports & related correspondence

8101140491 Forwards monthly operating rept for Dec 1980
LINDER, F Dairyland Power Cooperative 81/01/09 1p 07458 157

--8101140494 Monthly operating rept for Dec 1980
GODSMAN, L S Dairyland Power Cooperative 81/01/09 12pp
07458 158

B Reportable occurrences, IERs & related correspondence

8101050374 Forwards IER 80-013/03L-0
LINDER, F Dairyland Power Cooperative 80/12/22 2pp 07389 300

--8101050380 IER 80-013/03L-0 on 801127 during periodic leakage rate
testing, electrical penetration unit 6 was determined to
exceed Tech Spec limits Caused by cracked gland on
individual penetration 298 Gland was soldered
GODSMAN, L S Dairyland Power Cooperative 80/12/22 2pp
07389 302

8101050383 Forwards IER 80-012/03L-0
LINDER, F Dairyland Power Cooperative 80/12/26 6pp 07389 304

--8101050391 IER 80-012/03L-0 on 801124 soil sample under feedwater
heater area of turbine bldg found slightly contaminated
Caused by drilling hole in bldg floor or when floor was
washed prior to grouting Surveillance program established.
GODSMAN, L S Dairyland Power Cooperative 80/12/23 1p
07389 310

8101060561 Forwards IER 80-017/01T-0
LINDER, F Dairyland Power Cooperative 80/12/30 2pp 07391 117

--8101060563 IER 80-017/01T-0 on 801216 crane reactor cavity purge ch
valve & 253B reactor vent header valve found leaking Caused
by rust & debris Valves replaced.
GODSMAN, L S Dairyland Power Cooperative 80/12/30 1p
07391 119

8101160433 Special rept on 801201 during refueling outage high pressu
svc water diesel pump 1B was removed from normal standby
condition to perform 5-yr preventative maint program &
remained inoperable for 8 days Pump returned to svc 801209
LINDER, F Dairyland Power Cooperative 81/01/06 2pp 07472 147

T Hearing transcripts on non-antitrust matters

8101280320 Proposed corrections to transcript of 801216-17 evidential
hearing in La Crosse, WI Certificate of Svc encl
HEISHMAN, R F Dairyland Power Cooperative 81/01/15 11pp
07557 179

V Operator Examinations

8101300181 Forwards info re NUREG-0737 clarification items requested
in NRC 801031 ltr Comparison of facility shift technical
advisor program to Institute of Nuclear Power Operations
program encl
LINDER, F Dairyland Power Cooperative 81/01/16 18pp 07506 200

Application/construction stage documents & correspondence

101200465 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." EISENHUT.D.C. Division of Licensing 80/11/26 8pp

101200157 Summary of B01210 meeting w/Mark II owners re status of generic improved chugging load model. Owners requested to justify delay in program & investigate alternatives. ANDERSON.C.J. Generic Issues Branch 80/12/22 4pp

101140955 Summary of Dec 1980 meeting w/Mark II owners group. CE.B.H. MIT.S.W. (Rechts) & Ebasco Svcs. Inc re suppression pool temp limits list of attendees & handouts encl. SMITH.M. Generic Issues Branch 80/12/30 41pp

101140590 Responses to Util 790403 & 0908 ltr requesting approval of design change to main steam isolation valves. Licensee may proceed w/procurement & installation, but should reserve space to provide for potential backfitting. TEDESCHI.R.L. Assistant Director for Licensing 81/01/02 3pp 07471 207

101130239 Responses to NRC E00610 ltr requesting info re jet pump supports. Beam design used at facility operates at peak stress less than BWR/3 beams. Preload on beams will be reduced from 30,000 to 25,000 lbs. RHOE.G.W. Niagara Mohawk Power Corp 81/01/09 1p 07457 028

Security, medical, emergency & fire protection plans

101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FEAR. EISENHUT.D.C. Division of Licensing 80/11/13 2pp

Inspection reports, IE Bulletins & correspondence

101070403 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Turbine Turbine Steam Inlet Flange." No written response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director 80/11/26 1p 07414 074

101050128 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Scram Discharge Val at Dresden Unit 2." No response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director 80/12/05 1p 07376 347

101060142 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Scram Capability." No response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director 80/12/17 1p 07391 259

101070047 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of 76 of 189 Control Rods to Fully Insert During Scram at BWR." No written response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director 80/12/18 1p 07414 011

101130838 Forwards IE Bulletin 80-25, "Operating Problems w/Target Rod Safety-Relief Valves at BWRs." No response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director 80/12/19 1p 07458 327

Reportable occurrences, LERs & related correspondence

101190336 Ack receipt of Util B01201 interim deficiency rept re spent fuel pool cooling water heat exchangers. Matter will be reviewed pending receipt of final rept. CARLSOHN.R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/18 1p 0747A 034

152 Final interim deficiency rept. originally reported on B01205, a & rigging of safety-related equipment. Site to implement requirements for handling & rigging related equipment inadequate. Niagara Mohawk Power Corp 81/01/26 3pp 07586 094

Application/construction stage documents & correspondence

B101200465 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." EISENHUT.D.C. Division of Licensing 80/11/26 8pp

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FEAR. EISENHUT.D.C. Division of Licensing 80/11/13 2pp

B101105717 Requests that encl facility emergency planning info be made publicly available. U/o encl. SULLIVER.J.L. Division of Rules and Records 80/12/31 1p 07445 125

A. Inspection reports, IE Bulletins & correspondence

B101070411 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Turbine Turbine Steam Inlet Flange." No written response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director 80/11/26 1p 07414 059

B101060324 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown." No written response required. GRIER.B.H. Region 1, Philadelphia, Office of the Director 80/12/16 1p 07397 037

B. Reportable occurrences, LERs & related correspondence

B101200109 Ack receipt of B01114 Significant Deficiency Rept 80-08 re inferior welds on cable tray fittings. CARLSOHN.R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/11/25 1p 07583 082

B101050404 Interim Rept 3 re Significant Deficiency 80-03 concerning linear indications in girth gasket welds in reactor vessel structural support. Support will be repaired at B&W Mt Vernon, Ill facility. WOODLIVER.E.J. Duquesne Light Co. 80/12/12 2pp 07389 316

B101190272 Ack receipt of B01120 interim deficiency rept re 3-inch motor operated valves in safety injection & chemical & vol control sys. CARLSOHN.R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/18 1p 07475 063

--B101190279 Interim deficiency rept re failure of Westinghouse 3-inch motor operated valves in safety injection & chemical & vol control sys. Initially reported on B01029. Corrective action is under investigation. WOODLIVER.E.J. Duquesne Light Co. 80/11/20 4pp 07475 064

B101070350 Ack receipt of B01120 ltr forwarding interim rept re 3-inch gate valves in safety injection & chemical & vol control sys. CARLSOHN.R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/12/24 1p 07414 180

B101060458 Initial interim deficiency rept re seismic calculations for Category I structures. Calculations, drawings & other design considerations will be corrected as required. Next interim rept will be issued by B10622. WOODLIVER.E.J. Duquesne Light Co. 81/01/02 2pp 07396 088

DOCKET 90-413 CATAWBA NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

B101200465 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports." EISENHUT.D.C. Division of Licensing 80/11/26 8pp

8101120265 Requests util perform ultimate capacity analysis of Mark III containment for NRC generic review re effects of hydrogen evolving from postulated accident
TEDESCO, R L Assistant Director for Licensing 80/12/19 4pp
07446 273

8101150163 Forwards Amend 1 to CPPR-116, safety evaluation, EIA, negative declaration & notice of issuance & availability
EISENHUT, D O Division of Licensing 80/12/23 5pp 07300:001

--8101150171 Amend 1 to CPPR-116, adding NC Electric Membership Corporation & Saluda River Electric Cooperative, Inc as co-owners of facility
EISENHUT, D O Division of Licensing 80/12/23 1p 07300 001

--8101150176 Safety evaluation supporting Amend 1 to CPPR-116.
TEDESCO, R L Assistant Director for Licensing 80/12/23 10pp
07308 031

--8101150180 EIA supporting Amend 1 to CPPR-116
• Division of Licensing 80/12/23 2pp 07308 001

--8101150186 Negative declaration re Amend 1 to CPPR-116
MIRAGLIA, F J Licensing Branch 3 80/12/23 2pp 07303 001

--8101150189 Notice of issuance & availability to Amend 1 to CPPR-116
MIRAGLIA, F J Licensing Branch 3 80/12/23 2pp 07308 001

8101300836 Forwards test plan for next series of tests re Commission-directed electrical connector test program Requests review
FEIT, R Qualification Testing Evaluation Review Group 81/01/14 2pp 07986 021

--8101300841 Forwards Draft 3 of 'Connector Assembly Test Plan for Duke Power, Catawba 1 & 2 Connectors'
BUCKALEW, W H Sandia Laboratories. 80/12/22 16pp 07986 023

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

Q Adjudicatory correspondence

8101290011 Forwards Director's decision under 10CFR2 206 denying 790128 petition for reopening safety phases of licensing proceeding & notice of issuance
DENTON, H R Office of Nuclear Reactor Regulation, Director 81/01/09 3pp 07573 295

--8101290017 Director's decision under 10CFR2 206, denying Carolina Environ Study Group 790128 petition for reopening safety phases of licensing proceeding
DENTON, H R Office of Nuclear Reactor Regulation, Director 81/01/09 28pp 07573 298

--8101290022 Notice of issuance of 800107 Director's decision under 10CFR2 206, denying Carolina Environ Study Group 790128 petition for reopening safety phases of licensing proceeding.
CASE, E O Office of Nuclear Reactor Regulation, Director 81/01/09 2pp

M Antitrust correspondence

8101120503 Response opposing 801215 HQ Ayers antitrust hearing request Ltr fails to establish standing or satisfy antitrust criteria Discretionary intervention not warranted
Certificate of Svc encl
CHANANIA, F D Antitrust Division 81/01/09 18pp 07440 325.

8101160189 Notice of ASLB constitution ME Miller, chairman & PB Cotter & RM Lazo, members Certificate of Svc encl
COTTER, B P Atomic Safety and Licensing Board Panel 81/01/09 4pp 07470 044

8101160220 Response of Duke Power Co, NC Electric Membership Corp & Saluda River Electric Cooperative in opposition to HQ Ayers 801215 ltr request to intervene & for antitrust proceeding
Certificate of Svc encl
PORTER, W L Duke Power Co, MCARRY, J M Debevoise & Liberman 81/01/12 9pp 07470 171.

8101160741 Mergrandia & order denying HQ Ayers 801215 request for antitrust hearing Also grants Ayers leave to file amended petition for leave to intervene & request for antitrust hearing by 810131 Certificate of Svc encl
MILLER, M E, LAZO, R M, COTTER, B P Atomic Safety and Licensing Board Panel 81/01/12 12pp 07472 048

Q Inspection reports, IE Bulletins & correspondence

8101070320 Forwards supplemental responses to NRC 801016 ltr re violations noted in IE Insp Repts 50-413/80-08, 50-370/80-05, 50-413/80-09, 50-414/80-09, 50-491/80-02, 50-492/80-06 & 50-493/80-06 Final rept to be submitted by 810131
PARKER, W D Duke Power Co 80/11/11 2pp 07413 305

8101070313 Responds further to NRC 801010 ltr re violations noted Insp Repts 50-413/80-16 & 50-414/80-16 Corrective action all cable tray installation drawings showing proper weld symbols revised & released
PARKER, W D Duke Power Co 80/12/03 1p 07413 303

--8101070316 Responds further to NRC 801010 ltr re violations noted Insp Repts 50-413/80-16 & 50-414/80-16 Corrective action all cable tray installation drawings will be reviewed, revised & released as required by 801201
PARKER, W D Duke Power Co 80/10/22 1p 07413 309.

8101060225 Forwards IE Info Notice 80-41, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown" No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/11/1p

8101160662 Ack receipt of 801218 ltr informing NRC of steps taken correct violations noted in IE Insp Repts 50-413/80-33 & 50-414/80-33
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 81/01/02 1p 07472 020

--8101160668 Responds to NRC 801210 ltr re violations noted in IE Repts 50-413/80-33 & 50-414/80-33 Corrective actions engineers involved will be retrained in requirements of procedure.
PARKER, W D Duke Power Co 80/12/18 2pp 07472 021

--8101160671 Forwards IE Insp Repts 50-413/80-33 & 50-414/80-33 801027-31 & notice of violation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/12/02 2pp 07472 023

--8101160679 Notice of violation from Insp on 801027-31
• Region 2, Atlanta, Office of the Director 80/12/02 1p 07472 025

--8101160684 IE Insp Repts 50-413/80-33 & 50-414/80-33 on 801027 Noncompliance noted failure to follow procedure for reporting cracks in auxiliary bldg concrete
HARRIS, J R Region 2, Atlanta, Office of the Director
COLLON, T E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/12/02 4pp 07472 026

8101290400 Responds to IE Bulletin 80-21, "Valve Yokes Supplied Malcolm Foundry Co, Inc" No active valves cast by Malcolm Foundry are in use at facilities
PARKER, W D Duke Power Co 81/01/05 1p 07573 358

S Reportable occurrences, LERs & related correspondence

8101140600 Final deficiency rept SD-413/414/80-08 originally rep on 800617, re inadequate min flow through centrifugal charging pump. Util will implement Westinghouse interim Mod 2 transmitted on 800714
PARKER, W D Duke Power Co 81/01/07 2pp 07461 245

DOCKET 80-414 CATAWBA NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8101290466 Ltr to all power reactor licensees & applicants for summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

8101120265 Requests util perform ultimate capacity analysis of containment for NRC generic review re effects of hydrogen evolving from postulated accident
TEDESCO, R L Assistant Director for Licensing 80/12/19 4pp 07446 273.

B10100636 Forwards test plan for next series of tests re Commission-directed electrical connector test program Requests review
FEITH, Qualification Testing Evaluation Review Group. 81/01/14
2pp 07585 021

--B10137084: Forwards Draft 3 of Connector Assembly Test Plan for Duke Power Cataula 1 & 2 Connectors
BUCKALEW, W. H. Sardia Laboratories 80/12/22 16pp 07586 023.

F. Security, medical, emergency & fire protection plans

B101090357 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FBAR
EISENHUT, D. O. Division of Licensing 80/11/13 2pp

G. Adjudication, correspondence

B101290011 Forwards Director's decision under 10CFR2 206 denying 790128 petition for reopening safety phases of licensing proceeding & notice of issuance
DEITHOLM, R. Office of Nuclear Reactor Regulation, Director 81/01/09 3pp 07573 295

--B101290017 Director's decision under 10CFR2 206 denying Carolina Environ Study Group 790128 petition for reopening safety phases of licensing proceeding
DEITHOLM, R. Office of Nuclear Reactor Regulation, Director 81/01/09 28pp 07573 298

--B101290022 Notice of issuance of B00109 Director's decision under 10CFR2 206 denying Carolina Environ Study Group 790128 petition for reopening safety phases of licensing proceeding
CASE, F. G. Office of Nuclear Reactor Regulation, Director 81/01/09 2pp

H. Antitrust correspondence

B101160109 Notice of ASLB constitution RE Miller, chairman & PB Cotter & RM Lato, members Certificate of Svc encl
COTTER, B. P. Atomic Safety and Licensing Board Panel 81/01/09 4pp 07470 044

B101160741 Memorandum & order denying HQ Ayers B01215 request for antitrust hearing Also grants Ayers leave to file amended petition for leave to intervene & request for antitrust hearing by B10131 Certificate of Svc encl
MILLER, M. E., LAZO, R. M., COTTER, B. P. Atomic Safety and Licensing Board Panel 81/01/13 12pp 07472 068

I. Inspection reports, IE Bulletins & correspondence

B101070320 Forwards supplemental responses to NRC B01016 ltr re violations noted in IE Insp Repts 50-413/80-08, 50-370/80-05, 50-413/80-09, 50-414/80-09, 50-471/80-02, 50-492/80-06 & 50-493/80-06 Final rept to be submitted by B10131.
PARKER, W. O. Duke Power Co 80/11/11 2pp.

B101070313 Responds further to NRC B01010 ltr re violations noted in IE Insp Repts 50-413/80-16 & 50-414/80-16, Corrective action all cable tray installation drawings showing proper weld symbols revised & released
PARKER, W. O. Duke Power Co 80/12/03 1p 07413 303.

--B101070316 Responds further to NRC B01010 ltr re violations noted in IE Insp Repts 50-413/80-16 & 50-414/80-16, Corrective action all cable tray installation drawings will be reviewed, revised & released as required by B101201
PARKER, W. O. Duke Power Co 80/10/22 1p. 07413 304

B101060225 Forwards IE Info Notice B0-44, "Actuation of ECCB in Recirculation Mode While in Hot Shutdown." No written response required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/12/16 1p

B101160662 Act receipt of B01218 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/80-33 & 50-414/80-33
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 81/01/02 1p 07472: 020

--B101160668 Responds to NRC B01210 ltr re violations noted in IE Insp

--B101160671 Forwards IE Insp Repts 50-413/80-33 & 50-414/80-33 on B1027-31 & notice of violation
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/12/02 2pp 07472 023

--B101160679 Notice of violation from insp on B01027-31
* Region 2, Atlanta, Office of the Director 80/12/02. 1p 07472 025

--B101160684 IE Insp Repts 50-413/80-33 & 50-414/80-33 on B01027-31 Noncompliance noted failure to follow procedure for reporting cracks in auxiliary bldg concrete
HARRIS, J. R. Region 2, Atlanta, Office of the Director
CONLON, T. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/12/02 4pp 07472 026

B101290408 Responds to IE Bulletin B0-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." No active valves cast by Malcolm Foundry are in use at facilities
PARKER, W. O. Duke Power Co 81/01/05 1p 07573 358

S. Reportable occurrences, LERs & related correspondence

B101140600 Final deficiency rept 50-413/414/80-08 originally reported on B00617, re inadequate min flow through centrifugal charging pump until will implement Westinghouse Interim Mod 2 transmitted on B00714
PARKER, W. O. Duke Power Co 81/01/07 2pp 07461 245

DOCKET 50-416 GRAND OULF NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D. O. Division of Licensing. 80/11/26. 8pp

B101060907 Informs that more appropriate date for control room visit will be wk of B10309, rather than wk of B10109 Info requested in B01204 ltr should be provided by B10206.
MARTORE, J. A. Licensing Branch 3 80/12/12 2pp. 07401: 084

B101060020 Provides guidance re determination of acceptability of O-list for facilities Reviewers should identify safety-related structures, sys & components within areas of responsibility
HAASB, W. P. Quality Assurance Branch MARTORE, J. A. Licensing Branch 3 80/12/18 3pp 07445 201

B101070456 Requests postponement until B10309-13 re Human Factors Engineering Branch visit to control room at facility.
MIRAGLIA, F. J. Licensing Branch 3. 80/12/19. 1p. 07415 310.

B101120257 Requests util perform ultimate capacity analysis of Mark II containment for NRC generic review re effects of hydrogen evolving from postulated accident. Test description encl
TEDESCO, R. L. Assistant Director for Licensing. 80/12/19 4pp. 07446 266

B101190505 Ltr to all BWR applicants for DL re BWR scram discharge sys safety evaluation & requirements Rept specifying acceptable basis for continued BWR plant operation & design criteria for scram discharge vol encl
TEDESCO, R. L. Assistant Director for Licensing. 80/12/22 2pp.

--B101190514 Forwards generic safety evaluation re BWR scram discharge sys Review identified two addl requirements to those proposed by owners group re scram discharge vol designs. Rept should be transmitted to license applicants
CHECK, P. S. Assistant Director for Plant Systems. 80/12/01. 2pp 07183 001

B101090100 Submits results of reanalysis of cooling tower drift
DALE, L. F. Mississippi Power & Light Co. 80/12/23. 2pp. 07375: 31

B101060433 Forwards Essex Corp human factors design engineering evaluation of control room per NUREG-0660, Task I, D.1. Review conducted from B00617-1001, using criteria from NUREG-1580, "Human Engineering Guide to Control Room Evaluation."
DALE, L. F. Mississippi Power & Light Co. 80/12/29. 2pp. 07309: 00

--B101060442 "Human Factors Engineering Evaluation of Grand Gulf Unit Control Room"

B101030329 Forwards amend to application for CL submitted as Amend 43 to FSAR & revised P&ID Aperture cards available in PDR only
MCOAUGHY, J P Mississippi Power & Light Co 80/12/31 1p
07383 297

--B101050335 Amend to application for DL submitted as Amend 45 to FSAR
MCOAUGHY, J P Mississippi Power & Light Co 80/12/31 2pp.
07303 298

B101070445 Reiterates B00926 request that requirements re sediment
tasks be deleted from environ protection plan Sediment
tasks adequately regulated by NPDES Permit MS0029521.
MCOAUGHY, J P Mississippi Power & Light Co 80/12/31 2pp
07403 360

B10140222 Approves B01125 request to withhold rept entitled
"Containment Bldg Response Spectra, 85E, 7% Dumping, North-
South-East-West Vertical Mass Points 7, 14, 15, 21 & 23;
Containment Structure Mathematical Model;" (ref 10CFR2 7901
MIRAGLIA, F Licensing Branch 3 80/12/31 (rpp 07309:001

B101130226 Forwards informal comparison between constituent sys of
facility & generic design plant described in CESSAR-II
Designs fundamentally similar though not identical Designs
differ in area of instrumentation
DALE, L F Mississippi Power & Light Co 81/01/09 3pp. 07449 357

B101150499 Advises that review of archaeological survey rept re
R Braswell transmission line route shows no cultural sites
eligible for listing on Natl Register of Historic Places
will be affected.
KILLIARD, E R Mississippi, State of 81/01/12 1p. 07463 153.

B101220294 Forwards addl info re INEL structural audit action items per
NRC request Remaining items will be submitted in Feb 1981
DALE, L F Mississippi Power & Light Co 81/01/16 49pp
07495 126

B101220337 Provides revised fuel load & commercial operation dates. Unit
1 fuel load & commercial operation dates are Dec 1981 & Aug
1982, respectively Unit 2 fuel load & commercial operation
dates are Aug 1985 & Apr 1986, respectively
DALE, L F Mississippi Power & Light Co 81/01/16 1p 07494 093.

B101230493 Forwards updated Unit 1 const network info for period ending
B01221 Unit 2 const was halted on 7/12/81 Projected fuel load
dates for Units 1 & 2 are Dec 1981 & Aug 1985, respectively
DALE, L F Mississippi Power & Light Co 81/01/16 8pp. 07511 193

B101290491 Forwards proprietary info re NRC/INEL audit action items,
based on NRC B00317-21 structural audit of facilities info
available in Central Files
ZACCARIA, A Bechtel Power Corp (subs of Bechtel Corp.) 81/01/19
1p 07573 361.

B101270843 Responds to NRC B01219 request for Mark III containment
analysis. Containment analysis does not consider dynamic
pressure effects due to design criteria which prohibit
conditions leading to hydrogen explosion
MCOAUGHY, J P Mississippi Power & Light Co 81/01/21 2pp
07545:281

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants. CP holders
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B10102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

K Utility Final Safety Analysis Report (FSAR) & amends

B101050329 Forwards amend to application for DL submitted as Amend 43
to FSAR & revised P&ID Aperture cards available in PDR only
MCOAUGHY, J P Mississippi Power & Light Co 80/12/31 1p
07383 297.

--B101050335 Amend to application for DL submitted as Amend 45 to FSAR
MCOAUGHY, J P Mississippi Power & Light Co 80/12/31 2pp.
07383:298.

--B101050341 Amend 45 to FSAR
* Mississippi Power & Light Co. 80/12/31. 250pp 07383 300.

B101150639 Forwards affidavit of svc re Amend 45 to FSAR.
DALE, L F Mississippi Power & Light Co 81/01/09. 2pp 07462 127

U. Inspection reports, IE Bulletins & correspondence

B101050603 Forwards IE Info Notice B0-43. "Failures of Contain-
ment Level Monitor for Scram Discharge Vol at Dresden Unit 2 " No
response required
O'REILLY, J P Region 2, Atlanta, Office of the Director
1p 07391 022

B101060365 Requests addl info for licensing review Responses
Bulletin 79-27 & B0-06 re instrument bus failures &
engineered safety feature controls, respectively, are
required.
TEDESCO, R L Assistant Director for Licensing 80/12/12
07422 233

B101120039 Suppl B00206 response to IE Bulletin 79-28 Thirte
switches identified by Bechtel. Eight sub j switches exposed
to temps above 175 F during LOCA Util repairing all eight
switches
DALE, L F Mississippi Power & Light Co 80/12/12 3pp

B101060162 Forwards IE Info Notice B0-45. "Potential Failure
Backup Manual Scram Capability " No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director
1p 07391 278

B101070037 Forwards Suppl 4 to IE Bulletin B0-17. "Failure of
Control Rods to Fully Insert During Scram at BWR " No
written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director
1p 07413 344

B101050156 Forwards IE Bulletin B0-25. "Operating Problems W/
Rod Safety Relief Valves at BWRs " No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director
2pp 07377:254

B101120125 Responds to IE Bulletin B0-16 re potential misappl
of Resonant Inc pressure transmitters Ten such transmitter
used in safety-related applications. Of working w/out] to
correct problem prior to fuel loading.
DALE, L F Mississippi Power & Light Co 80/12/19. 3pp

B101120074 Act receipt of B01215 ltr informing NRC of steps to
correct violations noted in IE Insp Repts B0-416/B0-25 &
90-417/B0-15
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engi
Support Branch. 80/12/24 1p 07446 037.

--B101120077 Responds to NRC B01121 ltr re violations noted i
Repts B0-416/B0-25 & 90-417/B0-15 Corrective actions: safe
evaluation implemented to determine reportability of
nonconformance
MCOAUGHY, J P Mississippi Power & Light Co 80/12/19
07446 038

--B101120081 Forwards IE Insp Repts 90-416/B0-25 & 90-417/B0-
01028-31, notice of violation & notice of deviation
MURPHY, C E Region 2, Atlanta, Reactor Construction & En
Support Branch 80/11/21 2pp 07446 040

--B101120084 Notice of violation from insp on B01028-31
* Region 2, Atlanta, Office of the Director 80/11/20
07446:042

--B101120086 Notice of deviation from Insp on B01028-31
* Region 2, Atlanta, Office of the Director. 80/11/20.
07446 043

--B101120090 IE Insp Repts 90-416/B0-25 & 90-417/B0-15 on B01
Noncompliance noted subsl fire damper installation Power
supply for electric fire pump not designed for locked rot
current.
MILLER, V H Region 2, Atlanta, Office of the Director
CONLON, T E Region 2, Atlanta, Reactor Construction & En
Support Branch 80/11/20 8pp 07446 044

B101290367 Requests 60-day extension in responding to IE Bull
B0-21. "Valve Yokes Supplied by Malcolm Foundry Co. Inc "
Time needed to contact suppliers
DALE, L F Mississippi Power & Light Co. 81/01/05 1p 0

B101220474 Submits addl info re IE Bulletin B0-07. "BWR Jet P
Assembly Failure." in response to NRC request Describes
actions to preclude occurrence of jet pump cracking &
commitment for long-term solution
DALE, L F Mississippi Power & Light Co 81/01/14 3pp

on inlet desper. Initially reported on 800730 Caused by failure to set actuator Cans properly Manufacturer notified Final rept will be issued by 810517
MCGAUGHY, J P Mississippi Power & Light Co 80/12/19 2pp
07578 001

B101050239 Status Rept B re Potential Reportable Deficiency 79/05 concerning discrepancies in design documentation for power generation control complex panels Corrective actions by supplier are not finalized Final rept scheduled by 810324
MCGAUGHY, J P Mississippi Power & Light Co 80/12/30 2pp
07389 291

B101050346 Status Rept 4 re Potential Reportable Deficiency 80/04 concerning loss of site power on red position indication & rebus monitoring Matter is under review Determination of reportability & final rept due by 810421
MCGAUGHY, J P Mississippi Power & Light Co 80/12/30 2pp
07399 243

B101260519 Interim Deficiency Rept 2 re standby svc water basin fans. Initially reported 800826 Fan pillow block bearings failed after 320-h of operation Constructor & supplier conducting evaluations Final rept will be filed by 810422
MCGAUGHY, J P Mississippi Power & Light Co 81/01/06 2pp
07529 248

B101270088 Part 21 rept re failure of pillow block bearings on standby svc water cooling tower fans. Initially reported on 800826 Cause unknown Replacement of damaged bearings recommended Final rept will be available on 810422
MCGAUGHY, J P Mississippi Power & Light Co 81/01/06 3pp
07183 001

B101190147 Final rept for Potentially Reportable Deficiency 80/53 re oil level indicator lines outside missile barriers Missile shielding of exposed oil lines has been coordinated w/ Ceramic Cooling Tower Co for completion by 810421
MCGAUGHY, J P Mississippi Power & Light Co 81/01/07 2pp
07479 217

B101270341 Deficiency Status Rept 1 re loss of solid metallic grounding of flexible conduit used in power generation control complex equipment Ground to be attached at both ends of conduit Final rept to be issued by 810319
MCGAUGHY, J P Mississippi Power & Light Co 81/01/09 2pp
07505 168

B101270104 Part 21 rept. Initially reported on 791205, re failure to provide seismically & environ qualified instruments for use in nuclear safety sys in ROP control complex Caused by GE misinterpretation of Bachtel requirements
MCGAUGHY, J P Mississippi Power & Light Co 81/01/09 6pp
07183 001

B101230539 Interim deficiency rept. originally reported on 800909, re seismic hangers w/ incomplete welds at member connection joints Insp to be completed by 810227 Final rept expected by 810528
MCGAUGHY, J P Mississippi Power & Light Co 81/01/13 2pp
07510 024

B101230599 Interim Deficiency Rept 1, originally reported on 800319, re pipe hanger nonconformances Nonconformances attributed to failure of const to follow installation instructions & proper insp procedures Insp program initiated
MCGAUGHY, J P Mississippi Power & Light Co. 81/01/15 4pp
07510 028

B101230607 Interim deficiency rept. originally reported on 801216, re unapproved mods to control room fire dangers Caused by A/E error Vendor investigation re possible effects on UL classification & air flow testing in progress.
MCGAUGHY, J P Mississippi Power & Light Co 81/01/15 2pp
07510 031

B101230482 Final deficiency rept. originally reported on 800314, re limiter valve operator malfunctions Testing results determined that problem was isolated incident on nonsafety related equipment & not reportable per 10CFR50.53(e).
MCGAUGHY, J P Mississippi Power & Light Co 81/01/16 2pp
07510 015

B101300388 Interim deficiency rept. first reported on 800912, re incorrectly ordered throttling valves for RHRS sys Four valves suitable w/ mods by manufacturer Constructor evaluation to be reviewed to determine corrective action
MCGAUGHY, J P Mississippi Power & Light Co 81/01/23 3pp
07580 358

MCGAUGHY, J P Mississippi Power & Light Co 81/01/23 3pp
07586 089

B101300455 Interim deficiency rept. originally reported on 800912, re nonconforming Reactor Controls. Inc seismic piping supports Contractor QA manual approval pending & all future work will conform to revised QA program
MCGAUGHY, J P Mississippi Power & Light Co 81/01/23 4pp.
07586 097

B101300475 Second interim deficiency rept. originally reported on 800806, re inadequate control of supplier drawing revision notices program Nonconforming conditions under scrutiny & procedural controls being revised
MCGAUGHY, J P Mississippi Power & Light Co 81/01/23 2pp
07586 101

CECKET 50-417 GRAND OULF NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports"
EISFIMUT, D O Division of Licensing 80/11/26 8pp.

B101060907 Informs that more appropriate date for control room visit will be wk of 810309, rather than wk of 810105 Info requested in 801204 ltr should be provided by 810206
MARTORE, J A Licensing Branch 3 80/12/12 2pp 07401 084

B101100020 Provides guidance re determination of acceptability of Q-list for Facilities Reviewers should identify safety-related structures, sys & components within areas of responsibility
HANSSE, W P Quality Assurance Branch MARTORE, J A Licensing Branch 3 80/12/18 3pp 07445 201

B101070456 Requests postponement until 810309-13 re Human Factors Engineering Branch visit to control room at facility
MIRACLIA, F J Licensing Branch 3 80/12/19 1p 07415 310

B101120257 Requests util perform ultimate capacity analysis of Mark containment for NRC generic review re effects of hydrogen evolving from postulated accident Test description encl
TEDESCO, R L Assistant Director for Licensing 80/12/19 4pp
07446 266

B101050100 Submits results of reanalysis of cooling tower drift
DALE, L F Mississippi Power & Light Co. 80/12/23 2pp 07375 3

B101050329 Forwards amend to application for DL submitted as Amend 4 to FSAR & revised P&ID
MCGAUGHY, J P Mississippi Power & Light Co 80/12/31 1p

--B101050335 Amend to application for DL submitted as Amend 45 to FSAR
MCGAUGHY, J P Mississippi Power & Light Co 80/12/31 2pp

B101070445 Reiterates 800926 request that requirements re sediment basins be deleted from environ protection plan Sediment basins adequately regulated by NPDES Permit MS0027921.
MCGAUGHY, J P Mississippi Power & Light Co. 80/12/31 2pp.
07403 360

B101140222 Approves 801125 request to withhold rept entitled "Containment Bldg Response Spectra, SSE, 7% Dumping, North-South-East-West Vertical Mass Points 7, 14, 15, 21 & 23" Containment Structure Mathematical Model." (ref 10CFR2 790).
MIRACLIA, F J Licensing Branch 3 80/12/31 2pp 07309 001.

B101130226 Forwards informal comparison between constituent sys of facility & generic design plant described in CESSAR-II Designs fundamentally similar, though not identical Designs differ in area of instrumentation
DALE, L F Mississippi Power & Light Co 81/01/09 3pp. 07449:

B101150499 Advises that review of archaeological survey rept re R Braswell transmission line route shows no cultural sites eligible for listing on Natl Register of Historic Places will be affected
HILLIARD, E R Mississippi, State of 81/01/12 1p. 07463 153

DOCKETED ITEMS

B101220294 Forwards addl info re INEL structural audit action items per NRC request. Remaining items will be submitted in Feb 1981.
DALE L F Mississippi Power & Light Co 01/01/16 49pp
07493 126

B101220337 Provides revised fuel load & commercial operation dates Unit 1 fuel load & commercial operation dates are Dec 1981 & Aug 1982, respectively. Unit 2 fuel load & commercial operation dates are Aug 1985 & Apr 1986, respectively.
DALE L F Mississippi Power & Light Co 01/01/16 1p 07494 093

B101230498 Forwards updated Unit 1 const network info for period ending B01231. Unit 2 const was halted on 7/12/81. Projected fuel load dates for Units 1 & 2 are Dec 1981 & Aug 1985, respectively.
DALE L F Mississippi Power & Light Co 01/01/16 8pp 07511 159

B101290451 Forwards proprietary info re NRC/INEL audit action items based on NRC B00317-21 structural audit of facilities info available in Central Files.
ZACCARIA A Bechtel Power Corp (subs of Bechtel Corp) 01/01/19 1p 07573 361

B101270843 Responds to NRC B01219 request for Marx III containment analysis. Containment analysis does not consider dynamic pressure effects due to design criteria which prohibit conditions leading to hydrogen explosion.
MCGAUGHY J P Mississippi Power & Light Co 01/01/21 2pp
07543 281

F Security, medical, emergency & fire protection plans

B101090307 Ltr to all licensees of operating reactor plants. CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR.
ETSEHUT D O Division of Licensing 00/11/13 2pp

A Utility Final Safety Analysis Report (FSAR) & amendments

B101050329 Forwards amend to application for CL submitted as Amend 45 to FSAR & revised PAID Aperture cards available in PDR only.
MCGAUGHY J P Mississippi Power & Light Co 00/12/31 1p
07383 297

--B101050335 Amend to application for CL submitted as Amend 45 to FSAR.
MCGAUGHY J P Mississippi Power & Light Co 00/12/31 2pp
07383 298

--B101050341 Amend 45 to FSAR
* Mississippi Power & Light Co 00/12/31 250pp 07383 300

B101150639 Forwards affidavit of svc re Amend 45 to FSAR.
DALE L F Mississippi Power & Light Co 01/01/09 2pp 07462 127

Q Inspection reports, IE Bulletins & correspondence

B101050503 Forwards IE Info Notice B0-43, "Failures of Continuous Water Level Monitor for Steam Discharge Val at Dresden Unit 2." No response required.
O'REILLY J P Region 2, Atlanta, Office of the Director 00/12/09 1p 07391 022

B101080066 Requests addl info for licensing review. Responses to IE Bulletin 79-27 & B0-06 re instrument bus failures & engineered safety feature controls, respectively, are required.
TEDECO R L Assistant Director for Licensing 00/12/12 7pp
07422 233

B101120009 Suppls B00206 response to IE Bulletin 79-20 Thirteen NAMCO switches identified by Bechtel. Eight subg switches exposed to temps above 175 F during LOCA Util repairing all eight switches.
DALE L F Mississippi Power & Light Co 00/12/12 3pp 07447 095

B101060162 Forwards IE Info Notice B0-45, "Potential Failure of BWR Backup Manual Scram Capability." No response required.
O'REILLY J P Region 2, Atlanta, Office of the Director 00/12/17 1p 07391 278

B101050156 Forwards IE Bulletin B0-25, "Operating Problems w/Target Rock Safety Relief Valves at 30Ps." No response required.
O'REILLY J P Region 2, Atlanta, Office of the Director 00/12/24 2pp 07377 254

B10120125 Responds to IE Bulletin B0-16 re potential misapplication of Rosemount, Inc. pressure transmitters. For such transmitters used in safety-related applications OE working w/Util to correct problem prior to fuel loading.
DALE L F Mississippi Power & Light Co 00/12/19 3pp 07445

B101120074 Ack receipt of B01215 ltr informing NRC of steps taken correct violations noted in IE Insp Repts 50-416/B0-25 & 50-417/B0-15.
MURPHY C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/12/24 1p 07446 037

--B101120077 Responds to NRC B01215 ltr re violations noted in IE Repts 50-416/B0-25 & 50-417/B0-15. Corrective actions safety evaluation implemented to determine reportability of nonconformance.
MCGAUGHY J P Mississippi Power & Light Co 00/12/15 2pp
07446 038

--B101120091 Forwards IE Insp Repts 50-416/B0-25 & 50-417/B0-15 on B101028-31. Notice of violation & notice of deviation.
MURPHY C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/11/21 2pp 07446 040

--B101120094 Notice of violation from insp on B01028-31
* Region 2, Atlanta, Office of the Director 00/11/20 1p
07446 042

--B101120086 Notice of deviation from insp on B01028-31
* Region 2, Atlanta, Office of the Director 00/11/20 1p
07446 043

--B101120090 IE Insp Repts 50-416/B0-25 & 50-417/B0-15 on B01028-31. Noncompliance noted subst fire damper installation. Power supply for electric fire pump not designed for locked rotor current.
MILLER W H Region 2, Atlanta, Office of the Director
CHILCH T E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 00/11/20 8pp 07446 044

B101290367 Requests 60-day extension in responding to IE Bulletin B0-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Time needed to contact suppliers.
DALE L F Mississippi Power & Light Co 01/01/05 1p 07575

B101220474 Submits addl info re IE Bulletin B0-07, "BWR Jet Pump Assembly Failure." In response to NRC request Describes actions to preclude occurrence of jet pump cracking & commitment for long-term solution.
DALE L F Mississippi Power & Light Co 01/01/14 3pp 07502

S Reportable occurrences, LERs & related correspondence

B101260765 Part 21 repl re defective Pacific Air Products Co actuator on inlet damper, initially reported on B00730. Caused by failure to set actuator cams properly. Manufacturer notified. Final repl will be issued by B10617.
MCGAUGHY J P Mississippi Power & Light Co 00/12/19 2pp
07308 001

B101050339 Status Rept 0 re Potential Reportable Deficiency 79/05 concerning discrepancies in design documentation for power generation control computer panels. Corrective actions by supplier are not finalized. Final repl scheduled by B10324.
MCGAUGHY J P Mississippi Power & Light Co 00/12/30 2pp
07387 291

B101050346 Status Rept 4 re Potential Reportable Deficiency B0/04 concerning loss of site power on rod position indication & neutron monitoring. Matter is under review. Determination of reportability & final repl due by B10421.
MCGAUGHY J P Mississippi Power & Light Co 00/12/30 2pp
07389 293

B101260519 Interim Deficiency Rept 2 re standby svc water basin initially reported B00826 Fan pillow block bearings failed after 300-h of operation. Constructor & supplier conducting evaluations. Final repl will be filed by B10422.
MCGAUGHY J P Mississippi Power & Light Co 01/01/05 2pp

DOCKETED ITEMS

8101270139 Part 21 rept re failure of pillow block bearings on standby
w/c water cooling tower fans. Initially reported on 800826
Cause unknown. Replacement of damaged bearings recommended
Final rept will be available on 810422
MCGAUGHY, J P Mississippi Power & Light Co 81/01/06 3pp
07183 001

8101270147 Final rept for Potentially Reportable Deficiency 80/53 re
211 level indicator lines outside missile barriers. Missile
shielding of exposed oil lines has been coordinated
w/Cherant Cooling Tower Co for completion by 810421
MCGAUGHY, J P Mississippi Power & Light Co 81/01/07 2pp
07475 217

8101270141 Deficiency Status Rept I re loss of solid metallic grounding
of flexible conduit used in power generation control complex
equipment grounds to be attached at both ends of conduit
Final rept to be issued by 810319
MCGAUGHY, J P Mississippi Power & Light Co 81/01/09 2pp
07505 148

8101270104 Part 21 rept. Initially reported on 791205, re failure to
provide seismically & environ qualified instruments for use
in nuclear safety sys in BCP control complex. Caused by GE
misinterpretation of Bechtel requirements
MCGAUGHY, J P Mississippi Power & Light Co 81/01/09 6pp
07182 001

8101270500 Interim deficiency rept. originally reported on 800905, re
seismic hangers w/incomplete welds at member connection
points. Insp to be completed by 810227. Final rept expected
by 810528
MCGAUGHY, J P Mississippi Power & Light Co 81/01/15 2pp
07510 024

8101230559 Interim Deficiency Rept I, originally reported on 800319, re
pipe hanger nonconformances. Nonconformances attributed to
failure of const to follow installation instructions &
proper insp procedures. Insp program initiated
MCGAUGHY, J P Mississippi Power & Light Co 81/01/15 4pp
07510 028

8101230607 Interim deficiency rept. originally reported on 801216, re
unapproved mode to control each fire dampers. Caused by A/E
error. Vendor investigation re possible effects on UL
classification & air flow testing in progress
MCGAUGHY, J P Mississippi Power & Light Co 81/01/15 2pp
07510 031

8101230482 Final deficiency rept. originally reported on 800314, re
Limitorque valve operator malfunctions. Testing results
determined that problem was isolated incident on nonsafety
related equipment & not reportable per 10CFR50.53(a)
MCGAUGHY, J P Mississippi Power & Light Co 81/01/16 2pp
07510 015

8101300388 Interim deficiency rept. first reported on 800912, re
incorrectly ordered throttling valves for RHR sys. Four
valves suitable w/modes by manufacturer. Constructor
evaluation to be reviewed to determine corrective action
MCGAUGHY, J P Mississippi Power & Light Co 81/01/23 3pp
07580 358

8101300424 Interim deficiency rept. originally reported on 810116, re
RHR B pump damage during const testing. Damaged parts being
returned to manufacturer for repairs & Unit 2 parts
installed in Unit 1. Final rept scheduled for 810827
MCGAUGHY, J P Mississippi Power & Light Co 81/01/23 5pp
07586 089

8101300455 Interim deficiency rept. originally reported on 800912, re
nonconforming Reactor Controls. Inc seismic piping supports.
Constructor QA manual approval pending & all future work will
conform to revised QA program
MCGAUGHY, J P Mississippi Power & Light Co 81/01/23 4pp
07586 097

8101300475 Second interim deficiency rept. originally reported on
800806, re inadequate control of supplier drawing revision
notice program. Nonconforming conditions under scrutiny &
procedural controls being revised
MCGAUGHY, J P Mississippi Power & Light Co 81/01/23 2pp
07586 101

DOCKET 50-423 HILLSTONE NUCLEAR POWER STATION, UNIT 3

A Application/construction stage documents & correspondence

8101220466 Ltr to all power reactor licensees & applicants forwar
summary of 801112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D O Division of Licensing 80/11/26 8pp

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP h
& CP applicants. Revised radiological emergency response
plans must be submitted by licensees within 60 days of
810102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

8101000734 Requests that encl facility emergency planning info be
publicly available w/o encl
SOUDEK, J L Division of Rules and Records 80/12/31 1p
07445 128

J Insurance & indemnity information

8101270736 Forwards Endorsement 4 to NELIA Binders EB-15 & EB-16
IFFLAND, R R Northeast Utilities 81/01/22 3pp 07548 055

8101270744 Forwards Endorsements 65 & 66 to NELIA Policy NF-173.
IFFLAND, R R Northeast Utilities 81/01/22 4pp 07548 046

P Operating license stage documents & correspondence

8101160029 Notification of 801218 meeting w/SEP owners group in
Bethesda, MD re SEP program, schedule for licensee topic
completion & assignment of lead topics to plants
RUSSELL, W T Technical Support Branch 80/12/16 2pp

Q Inspection reports, IE Bulletins & correspondence

8101070425 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Stu
Terry Turbine Steam Inlet Flange." No written response
required
ORIER, B H Region 1, Philadelphia, Office of the Director
80/11/26 1p 07414 035

8101060836 Forwards IE Info Notice 80-44, "Actuation of ECCS in
Recirculation Mode While in Hot Shutdown." No written
response required
ORIER, B H Region 1, Philadelphia, Office of the Director
80/12/16 1p 07397 025

S Reportable occurrences, LERs & related correspondence

8101100033 Ack receipt of 801009 ltr forwarding interim deficiency
re reduced cooling to main steam generator.
CARLSON, T T Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch 80/11/20 1p 07444 301

--8101100038 Interim deficiency rept re reduced cooling to main
generator. Initially reported on 800924. Problem is being
reviewed w/SSW Engineering Corp. Review results will be
provided
COUSIL, W O Northeast Nuclear Energy Co (subs. of Northeast
Utilities), 80/10/09 1p 07444 302

DOCKET 50-424 ALVIN W. VOOTLE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8101220466 Ltr to all power reactor licensees & applicants forwar
summary of 801112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D O Division of Licensing 80/11/26 8pp

8101050253 Summary of 801201 meeting w/util in Bethesda, MD re de
of containment encl bldg.
BURWELL, S B Licensing Branch 2 80/12/22 7pp 07384 290

BI01160104 Forwards fee for amend of CPRR-10B & CPRR-109 inadvertently omitted from 801219 application
MOORE, W M Georgia Power Co 81/01/14 1p 07466 261

BI01300398 Forwards 'Savannah River Fish Population Study & Impingement Prediction For Plant Vogtle, Burke County, GA.' Sept 1977-Dec 1978 Const scheduled for 810301 Expeditions review requested
HEAD, G F Georgia Power Co 81/01/28 1p 07595 024

--BI01300429 'Savannah River Fish Population Study & Impingement Prediction For Plant Vogtle, Burke County, GA.' Sept 1977-Dec 1978
WILTZ, J W Georgia Power Co 81/01/31 34pp 07595 025

F Security, medical, emergency & fire protection plans

BI01090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of BI0102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp.

G Adjudicatory correspondence

BI01140752 Forwards request for info to assess intervenor Georgians Against Nuclear Energy 800925 petition for proceeding to assess need for power at facilities Latest official capital cost estimate & expenditures to date required
TEDESCO, R L Assistant Director for Licensing 80/12/19 4pp. 07461 310

I Financial information

BI01140752 Forwards request for info to assess intervenor Georgians Against Nuclear Energy 800925 petition for proceeding to assess need for power at facilities Latest official capital cost estimate & expenditures to date required
TEDESCO, R L Assistant Director for Licensing 80/12/19 4pp 07461 310

BI01260396 Forwards assessment of need for power from facilities per 801219 request for info Discusses scheduled on-line operating dates, capital cost estimates, expenditures to date, integrated hour peak demand & sys expansion plan
EHRENSPERGER, W Georgia Power Co 81/01/22 34pp 07531 182

Q Inspection reports, IE Bulletins & correspondence

BI01060247 Forwards IE Info Notice 80-44, "Actuation of ECCB in Recirculation Mode While in Hot Shutdown" No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/16 1p 07391 393

BI01190335 Responds to IE Bulletin 80-21 re Malcolm Foundry Co valve gates Util has no Malcolm Foundry Co valve parts in safety-related sys.
DUTTON, D Georgia Power Co 80/12/30 2pp 07475 219

BI01190342 Responds to IE Bulletin 80-23 re Valcor solenoid valve failure Util has no Valcor solenoid valves V70900-21-1 or V70900-21-3 for safety-related functions
DUTTON, D Georgia Power Co 80/12/30 2pp 07475 221

DCCRET 50-425 ALVIN W VOGTLE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

BI01220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp.

BI01140752 Forwards request for info to assess intervenor Georgians Against Nuclear Energy 800925 petition for proceeding to assess need for power at facilities Latest official capital cost estimate & expenditures to date required
TEDESCO, R L Assistant Director for Licensing 80/12/19 4pp 07461 310

BI01090293 Summary of 801201 meeting w/util in Bethesda, MD re deletion of containment encl bldg.
BURWELL, S B Licensing Branch 2 80/12/22 7pp 07384 250

BI01260396 Forwards assessment of need for power from facilities per 801219 request for info Discusses scheduled on-line operating dates, capital cost estimates, expenditures to date, integrated hour peak demand & sys expansion plan
EHRENSPERGER, W Georgia Power Co 81/01/22 34pp 07531 182

BI01160104 Forwards fee for amend of CPRR-10B & CPRR-109 inadvertently omitted from 801219 application
MOORE, W M Georgia Power Co 81/01/14 1p 07466 261

BI01300398 Forwards 'Savannah River Fish Population Study & Impingement Prediction For Plant Vogtle, Burke County, GA.' Sept 1977-Dec 1978 Const scheduled for 810301 Expeditions review requested
HEAD, G F Georgia Power Co 81/01/28 1p 07595 024

--BI01300429 'Savannah River Fish Population Study & Impingement Prediction For Plant Vogtle, Burke County, GA.' Sept 1977-Dec 1978
WILTZ, J W Georgia Power Co 81/01/31 34pp 07595 025

F Security, medical, emergency & fire protection plans

BI01090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of BI0102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

I Financial information

BI01140752 Forwards request for info to assess intervenor Georgians Against Nuclear Energy 800925 petition for proceeding to assess need for power at facilities Latest official capital cost estimate & expenditures to date required
TEDESCO, R L Assistant Director for Licensing 80/12/19 4pp

BI01260396 Forwards assessment of need for power from facilities per 801219 request for info Discusses scheduled on-line operating dates, capital cost estimates, expenditures to date, integrated hour peak demand & sys expansion plan
EHRENSPERGER, W Georgia Power Co 81/01/22 34pp

Q Inspection reports, IE Bulletins & correspondence

BI01060247 Forwards IE Info Notice 80-44, "Actuation of ECCB in Recirculation Mode While in Hot Shutdown" No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/16 1p 07391 393

BI01190335 Responds to IE Bulletin 80-21 re Malcolm Foundry Co valve gates Util has no Malcolm Foundry Co valve parts in safety-related sys.
DUTTON, D Georgia Power Co 80/12/30 2pp 07475 219

BI01190342 Responds to IE Bulletin 80-23 re Valcor solenoid valve failure Util has no Valcor solenoid valves V70900-21-1 or V70900-21-3 for safety-related functions
DUTTON, D Georgia Power Co 80/12/30 2pp 07475 221

DCCRET 50-427 FLOATING NUCLEAR PLANT, OFFSHORE POWER SYSTEM

A Application/construction stage documents & correspondence

BI01220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

BI01270555 FOIA request for all documents re OPB application for license to mfg floating nuclear plants containing statements re alternate land uses
BRYAN, L L Jacksonville, FL 80/12/16 2pp 07541 129

BI01070891 Requests detailed analyses that assess effect of potential hydrogen burn on floating nuclear plant containment integrity Info should include design pressure, calculated static pressure retaining capacity & general results
TEDESCO, R L Assistant Director for Licensing 80/12/17 5pp 07430 156

B01270551 Responds to FOIA request for all documents re CPB application for license to mfg floating nuclear plants containing statements re alternate land uses. NRC can locate no documents subj to request
FELTON, M. Division of Rules and Records 81/01/13 1p
07541 123

F Security, medical, emergency & fire protection plans

B01090367 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of B0102 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing 80/11/13 2pp

G Inspection reports, IE Bulletins & correspondence

B01050260 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown." No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/16 1p 07392 034

I Hearing transcripts on non-antitrust matters

B01260355 Unofficial transcript of 781201 Affirmation Session 78-30 in Washington, DC re CPB order Ps 1-3
* Commissioners 78/12/01 4pp 07308 001

DOCKET 50-438 BELLERON-TE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

B01220460 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lateral Tearing on Component Supports."
EISENHUT, D G Division of Licensing 80/11/26 8pp

B01210642 Advises that ATWS issue will be subj of future rulemaking to determine requirements & schedule for plant mode (NRC will not comment on until 800917 ltr describing program for resolving issue until rulemaking is finalized)
EISENHUT, D G Division of Licensing 80/12/29 2pp

B01220372 Forwards repts re post-tensioned anchor tendons in rock installation & testing of tendons by Inland-Ryerson Const Co & Strossteel Corp & "Analysis of Tendon Jacking Tests for Behavior of Rock Foundation"
MILLS, L M Tennessee Valley Authority 81/01/15 1p 07183 001

--B01220375 Post-tensioned Anchor Tendons in Rock Installation & Testing of Tendons by Inland-Ryerson Const Products Co "
BULLOCK, R E Tennessee Valley Authority 73/12/19 8pp
07183 001

- B01220373 "Post-tensioned Anchor Tendons in Rock Installation & Testing of Tendons by Inland-Ryerson Const Products Co "
BULLOCK, R E Affiliation Unknown 73/12/19 8pp

--B01220375 "Post-tensioned Anchor Tendons in Rock Installation & Testing of Tendons by Strossteel Corp "
BULLOCK, R E Tennessee Valley Authority 73/12/11 8pp
07183 001

--B01220375 "Post-tensioned Anchor Tendons in Rock Installation & Testing of Tendons by Strossteel Corp "
BULLOCK, R E Affiliation Unknown 73/12/11 8pp

--B01220377 "Analysis of Tendon Jacking Tests for Behavior of Rock Foundation "
CUMMINS, J H Tennessee Valley Authority 73/11/06 29pp
07183 001

B01230384 Forwards application for reissuance of NPDES Permit AL0074635 Preliminary draft permit will be submitted by B01020 Oversight maps encl
EL-ASHRY, K T Tennessee Valley Authority 81/01/20 82pp
07187 001

F Security, medical, emergency & fire protection plans

B01050387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of

B01010607 Transcript of B01217 briefing on TVA emergency offsite facilities in Washington, DC Ps 1-45
* Commissioners 80/12/17 49pp

B01230580 Forwards request for addl info re B01001 guard training qualification plan
TEDESCO, R L Assistant Director for Licensing 81/01/06 3pp
07487 113

B01010013 Forwards request for addl info re guard training & qualification plan. Requests resubmittal of revised plan within 30 days
TEDESCO, R L Assistant Director for Licensing 81/01/08 3pp
07448 260

J Insurance & indemnity information

B01090469 Forwards Endorsement 10 to ANI Policy NF-258
FIELDER, J Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc Div 80/12/28 3pp 07442 038

B01090517 Forwards Endorsement 7 to ANI Policy NF-258
FIELDER, J Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc Div 80/12/28 2pp 07442 263

K Utility Final Safety Analysis Report (FSAR) & amends

B01220043 Forwards Amend 20 to FSAR
MILLS, L M Tennessee Valley Authority 81/01/16 2pp

--B01220044 Amend 20 to FSAR
* Tennessee Valley Authority 81/01/12 1000pp

B01270659 Forwards affidavit certifying that Amend 20 to FSAR was served upon individuals identified on B01023
MILLS, L M Tennessee Valley Authority 81/01/23 2pp 07330

G Inspection reports, IE Bulletins & correspondence

B010140619 Updates licensee corrective actions following NRC B00707 insp of util Div of Engineering Design QA organization restructured to provide sufficient organizational freedom, authority & access to mgt.
MURPHY, C E Tennessee Valley Authority 80/10/08 3pp

B01090112 Ack receipt of B01024 ltr informing NRC of steps taken correct violations noted in IE Insp Repts 80-438/80-14 & 80-439/80-14 Disagrees w/response refuting items of noncompliance
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/12/05 4pp 07426 325

--B01090121 Responds to NRC B00912 ltr re violations noted in IE Repts 80-438/80-14 & 80-439/80-14 Disagrees that visual examination program & magnetic particle examination procedure do not meet ASME requirements.
MILLS, L M Tennessee Valley Authority 80/10/24 3pp
07426 329

--B01090721 Forwards IE Insp Repts 80-438/80-14 & 80-439/80-14 on B00721-25 & notice of violation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/12 2pp 07426 336

--B01090727 Notice of violation from Insp on B00721-25.
* Region 3, Chicago, Office of the Director 80/09/08 2pp
07426 338

--B01090735 IE Insp Repts 80-438/80-14 & 80-439/80-14 on B00721-25 Noncompliance noted inadequate visual insp program & magnetic particle examination procedures.
BLAKE, J, KLEINGORCE, W, ZAJAC, L Region 2, Atlanta, Office of Director 80/09/08 13pp 07426 340

B01120240 Forwards response to IE Bulletin 80-20 re Westinghouse W-2 control switches w/spring return to neutral position. Switches used in all facilities except Yellow Creek Units 3 & 4 in which switches are employed
MILLS, L M Tennessee Valley Authority 80/12/12 2pp

B01060203 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown." No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/11/13 07391:312

receipt of B01212 ltr informing NRC of steps taken to
actions noted in IE Insp Repts 50-439/B0-19 &

Region 2: Atlanta. Reactor Construction & Engineering
B0/12/22 1p 07443 293

responds to NRC B01014 ltr re violations noted in IE Insp
B0/00-19 & 50-439/B0-19 Corrective actions
supports reinspected & drawing changed to reflect
configuration

Tennessee Valley Authority B0/12/12 2pp

responds to IE Bulletin B0-23 re Valcor Engineering Corp
failure Valcor solenoid valves V70900-21-1 &
not used Util waiting for vendor response on
package components

Tennessee Valley Authority B0/12/30 1p

responds to IE Bulletin B0-21. "Valve Yokes Supplied by
Jury Co. Inc." Util is in process of obtaining
from valve suppliers that no Malcolm Foundry
obtained in furnished valves

Tennessee Valley Authority B1/01/06 1p

Operating reports & related correspondence

wards "Environ Radioactivity Levels - Bellefonte Nuclear
al Rept - 1979" Rept presents results obtained
optional environ radiological monitoring program
Tennessee Valley Authority B1/01/22 3pp 07576 146

Environ Radioactivity Levels - Bellefonte Nuclear Plant -
- 1979

Tennessee Valley Authority BA-B0-9-BL1 B1/01/22 37pp

Occurrences, LERs & related correspondence

rd interim deficiency rept. originally reported B00907. re
fillet welds Reinsp of socket welds continuing
documentation sys being developed to identify
welds Next rept will be submitted by B10309.

Tennessee Valley Authority B0/12/15 1p 07566 349

rd interim deficiency rept. originally reported on
dashed buttonheads on rock anchor tendons Insp
in Group 1 tendons overstressed & buttonheads
oversized Next rept to be submitted by B10428.

Tennessee Valley Authority B0/12/29 3pp 07383 282

rd interim deficiency rept. originally reported B00319 re
main steam line breaks because of feedwater
evaluation of dynamic loading effects on main steam
line Next rept will be submitted by B10625.

Tennessee Valley Authority B0/12/29 1p 07566 352

st interim deficiency rept re Consolidated Control Corp
cards. Initially reported on B01203 Util is
method of verifying adequacy of all field
Next rept will be forwarded by B10521

Tennessee Valley Authority B1/01/02 2pp 07415 300

st interim deficiency rept re automatic switchover of
storage tank. Initially reported on B01203 Util
control documents providing for automatic
Next rept will be forwarded by B10210

Tennessee Valley Authority B1/01/02 2pp 07413 302

rim Deficiency Rept 1 re essential raw cooling water sys
Design of essential raw cooling water piping is
led to incorporate ability to deal w/ wide
fouling factors Originally reported on B01207

Tennessee Valley Authority B1/01/07 2pp 07461 130.

st interim rept. originally reported on B01208. re low
shear installation seismic mounting
not welded per design drawings. QA auditing
Investigation to be completed by B10423.

Tennessee Valley Authority B1/01/06 2pp 07461 238

rd interim deficiency rept. originally reported on B00709.
svc factors on Westinghouse motor nameplates.
to be changed to reflect vendor-documented svc

Tennessee Valley Authority B1/01/09 2pp 07475 238

B101210327 Final deficiency rept. originally reported B01212. re threaded
piper qualification hfl. ltr piper identified, analyzed &
accepted per design procedures. Remainder will be analyzed
for stress intensity factors by B10306

MILLER, L. M. Tennessee Valley Authority B1/01/13 2pp 07490 131

B101220311 Forwards first interim rept re potential flammability of
suspended ceiling tile in control rooms in response to
B01104 ltr Addl info to be provided by B10211

MILLER, L. M. Tennessee Valley Authority B1/01/14 3pp

B101230498 Fourth interim deficiency rept re failed motor operated
valves mfg by Acta Actuators, Inc & defective limit switches.
Initially reported on B00611 Actuators were returned to
factory for repairs Next rept by B10325

MILLER, L. M. Tennessee Valley Authority B1/01/14 2pp 07511 147

B101260446 Fifth interim deficiency rept. originally reported on
771125. re purchase requests issued c/o specified IEEE
qualifications All deficient requests revised to include
proper qualifications Next rept will be submitted by B10422

MILLER, L. M. Tennessee Valley Authority B1/01/15 2pp 07531 223

B101270419 Second interim deficiency rept re fillet weld
misclassification. Initially reported on B01107. Design review
repeats discrepancies in each TVA Facility Util will
evaluate facilities Next rept will be submitted by B10407

MILLER, L. M. Tennessee Valley Authority B1/01/19 2pp 07549 042

B101270622 Second interim deficiency rept re ITT Grinnell welded
supports. Initially reported B00905 Detail sheets w/
discrepancies in weld designations will be revised by ITT
Grinnell for use in insp of fabricated welds

MILLER, L. M. Tennessee Valley Authority B1/01/22 2pp 07548 339

DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding
summary of B01152 meeting re implementation of guidance for
Unresolved Safety Issue A-12. "Potential for Low Fracture
Toughness & Laminar Tearing on Component Supports"
EISENHUT, D. O. Division of Licensing B0/11/26 8pp

B101210642 Advises that AT&S issue will be suby of future rulemaking to
determine requirements & schedule for plant mods. NRC will
not comment on util B00917 ltr describing program for
resolving issue until rulemaking is finalized

EISENHUT, D. O. Division of Licensing B0/12/29 2pp

B101220372 Forwards repts re post-tensioned anchor tendons in rock.
Installation & testing of tendons by Inland-Ryerson Const
Co & Streestel Corp. "Analysis of Tendon Jacking
Tests for Behavior of Rock Foundation"

MILLER, L. M. Tennessee Valley Authority B1/01/19 1p 07183 001

--B101220373 Post-tensioned Anchor Tendons in Rock. Installation &
Testing of Tendons by Inland-Ryerson Const Products Co.
BULLOCK, R. E. Tennessee Valley Authority 73/12/19 8pp
07183 001

--B101220375 Post-tensioned Anchor Tendons in Rock. Installation &
Testing of Tendons by Streestel Corp.
BULLOCK, R. E. Tennessee Valley Authority 73/12/11 8pp
07183 001

--B101220377 "Analysis of Tendon Jacking Tests for Behavior of Rock
Foundation"
COULSON, J. H. Tennessee Valley Authority 73/11/06 29pp
07183 001

B101230384 Forwards application for reissuance of NPDES Permit
ALC024635 Preliminary draft permit will be submitted by
B10220 Oversize rapt encl
EL-AISHY, M. I. Tennessee Valley Authority B1/01/20 82pp
07187 001

F Security, medical, emergency & fire protection plans

B1010790387 Ltr to all licensees of operating reactor plants, CP holders
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B10102 & by applicants as part of FSAR
EISENHUT, D. O. Division of Licensing B0/11/13 2pp

B101210607 Transcript of B01217 briefing on TVA emergency offsite
facilities in Washington, DC. Pp 1-49
* Commissioners. B0/12/17 49pp.

B10120580 Forwards request for addl info re guard training & qualification plan Requests resubmitted of revised plan within 30 days
 TEDESCO, R L Assistant Director for Licensing 81/01/06 3pp 07487 113

B101130013 Forwards request for addl info re guard training & qualification plan Requests resubmitted of revised plan within 30 days
 TEDESCO, R L Assistant Director for Licensing 81/01/08 3pp 07448 288

J Insurance & indemnity information

B101070465 Forwards Endorsement 10 to ANI Policy NF-258
 FIELDER, J Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc Div 80/12/26 3pp 07442 038

B101070517 Forwards Endorsement 9 to ANI Policy NF-258
 FIELDER, J Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc Div 80/12/26 2pp 07442 283

K Utility Final Safety Analysis Report (FSAR) & amends

B101290115 Forwards Amend 20 to FSAR
 MILLS, L M Tennessee Valley Authority 81/01/16 2pp

--B10129044 Amend 20 to FSAR
 * Tennessee Valley Authority 81/01/12 1000pp

B101270659 Forwards affidavit certifying that Amend 20 to FSAR was served upon individuals identified on B10123
 MILLS, L M Tennessee Valley Authority 81/01/23 2pp 07550 140.

Q Inspection reports, IE Bulletins & correspondence

B101140619 Updates licensee corrective actions following NRC B00707-11 Insp of Util Div of Engineering Design QA organization restructured to provide sufficient organizational freedom, authority & access to regt
 KIMMONS, G H Tennessee Valley Authority 80/10/08 3pp

B101090112 Ack receipt of B01024 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/80-14 & 50-439/80-14 Disagrees w/response refuting items of noncompliance
 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/12/05 4pp 07426 325.

--B101090121 Responds to NRC B00912 ltr re violations noted in IE Insp Repts 50-438/80-14 & 50-439/80-14 Disagrees that visual examination program & magnetic particle examination procedure do not meet ASME requirements
 MILLS, L M Tennessee Valley Authority 80/10/24 3pp. 07426 329

--B101090721 Forwards IE Insp Repts 50-438/80-14 & 50-439/80-14 on B00721-25 & notice of violation.
 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/17 2pp. 07426 336.

--B101090727 Notice of violation from Insp on B00721-25
 * Region 3, Chicago, Office of the Director 80/09/08 2pp. 07426 338

--B101090735 IE Insp Repts 50-438/80-14 & 50-439/80-14 on B00721-25 Noncompliance noted inadequate visual insp program & magnetic particle examination procedures.
 BLAKE, J. KLEINSORGE, W J, ZAJAC, L Region 2, Atlanta, Office of the Director 80/09/08 15pp. 07426 340

B101120040 Forwards response to IE Bulletin 80-20 re Westinghouse Type W-2 control switches w/spring return to neutral position. Switches used in all facilities except Yellow Creek Units sys in which switches are employed
 MILLS, L M Tennessee Valley Authority 80/12/12 2pp.

B101060203 Forwards IE Info Notice 80-44. "Activation of ECCS in Recirculation Mode While in Hot Shutdown" No written response required
 O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/12/16 1p 07391 312

B101100279 Ack receipt of B01212 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/80-19 & 50-437/80-19.
 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/12/22 1p 07443 295

--B101100287 Responds to NRC B01014 ltr re violations noted in IE Insp Repts 50-438/80-19 & 50-437/80-19 Corrective actions generator supports reinspected & drawing changed to reflect as-built configuration
 MILLS, L M Tennessee Valley Authority 80/12/12 2pp 07443 276

B101270050 Responds to IE Bulletin 80-23 re Valcor Engineering Corp solenoid valve failure Valcor solenoid valves V70900-21-1 & V70900-21-3 not used Util waiting for vendor response on valves in package components
 MILLS, L M Tennessee Valley Authority 80/12/30 1p.

B101210237 Responds to IE Bulletin 80-21. "Valve Yokes Supplied by Malcolm Foundry Co, Inc Util is in process of obtaining assurance from valve suppliers that no Malcolm Foundry yokes are contained in furnished valves
 MILLS, L M Tennessee Valley Authority 81/01/06 1p

R Periodic operating reports & related correspondence

B101290267 Forwards "Environ Radioactivity Levels - Bellefonte Nuclear Plant - Annual Rept - 1979" Rept presents results obtained from preoperational environ radiological monitoring program
 MILLS, L M Tennessee Valley Authority 81/01/22 3pp 07576 1

--B101290269 "Environ Radioactivity Levels - Bellefonte Nuclear Plant - Annual Rept - 1979"
 * Tennessee Valley Authority BA-80-9-BLI 81/01/22 37pp 07564 039

S Reportable occurrences, LERs & related correspondence

B101290651 Third interim deficiency rept. originally reported B00507 deficient fillet welds Reinsp of socket welds continuing Weld history documentation sys being developed to identify deficient welds. Next rept will be submitted by B10309
 MILLS, L M Tennessee Valley Authority 80/12/15 1p. 07566 34

B101050325 Second interim deficiency rept. originally reported on B00923 re raised buttonheads on rock anchor tendons Insp revealed ulse in Group 1 tendons overstressed & buttonheads in Group 2 oversized Next rept to be submitted by B10428.
 MILLS, L M Tennessee Valley Authority 80/12/29 3pp 07585 2

B101290850 Third interim deficiency rept. originally reported B00319 failure of main steam line breaks because of feedwater overfill. Evaluation of dynamic loading effects on main steam lines continuing Next rept will be submitted by B10625
 MILLS, L M Tennessee Valley Authority 80/12/29 1p. 07566 33

B101070417 First interim deficiency rept re Consolidated Control C field buffer cards, initially reported on B01203 Util is investigating method of verifying adequacy of all field buffer cards. Next rept will be forwarded by B10521
 MILLS, L M Tennessee Valley Authority 81/01/02 2pp 07415 3

B101070424 First interim deficiency rept re automatic switchover d borated water storage tank, initially reported on B01203 Util will reissue control documents providing for automatic switchover Next rept will be forwarded by B10210
 MILLS, L M Tennessee Valley Authority 81/01/02 2pp. 07415:

B101140611 Interim Deficiency Rept 1 re essential raw cooling water steam flash. Design of essential raw cooling water piping is being evaluated to incorporate ability to deal w/wide spectrum of fouling factors. Originally reported on B01209.
 MILLS, L M Tennessee Valley Authority 81/01/07 2pp. 07461.

B101140627 First interim rept. originally reported on B01208 re low voltage switchgear installation seismic mounting configuration not welded per design drawings. QA auditing all switchgears. Investigation to be completed by B10423
 MILLS, L M Tennessee Valley Authority 81/01/08 2pp. 07461:

B101190762 Third interim deficiency rept. originally reported on B01203 re incorrect svc factors on Westinghouse motor nameplates. Nameplates to be changed to reflect vendor-documented svc factor
 MILLS, L M Tennessee Valley Authority 81/01/09 2pp. 07475:

B101230311 Interim Part 21 rept re Atwood & Morrill valve deficient Initially reported B01212 Decay heat removal valve 380413-WD-3D S/N 142-13894 has 2-inch surface crack in upper body Investigation continuing.
 MILLS, L M Tennessee Valley Authority 81/01/12 3pp. 07187:

8010120327 Final deficiency rept. originally reported 801212 re threaded
 pipet qualification WFL Inc pipets identified, analyzed &
 accepted per design procedures Remainder will be analyzed
 for stress intensity factors by 810306
 MILLS, L M Tennessee Valley Authority 81/01/13 2pp 07490 131.

80101220311 Forwards first interim rept re potential flammability of
 suspended ceiling tile in control rooms in response to
 801104 ltr Addl info to be provided by 810211
 MILLS, L M Tennessee Valley Authority 81/01/14 3pp

80101230458 Fourth interim deficiency rept re failed motor operated
 valves mfg by Aump Actuators, Inc & defective limit switches,
 initially reported on 800611. Actuators were returned to
 factory for repairs Next rept by 810325
 MILLS, L M Tennessee Valley Authority 81/01/14 2pp 07511 147.

80101260446 Fifth interim deficiency rept. originally reported on
 771125 re purchase requests issued w/o specified IEEE
 qualifications All deficient requests revised to include
 proper qualifications Next rept will be submitted on 810422
 MILLS, L M Tennessee Valley Authority 81/01/15 2pp 07531 223

80101270419 Second interim deficiency rept re fillet weld
 at specification, initially reported on 801107 Design review
 repeats discrepancies in each TVA facility Util will
 evaluate facilities Next rept will be submitted by 810409
 MILLS, L M Tennessee Valley Authority 81/01/19 2pp 07549 042

80101270422 Second interim deficiency rept re ITI Grinnell welded
 supports, initially reported 800903 Detail sheets w/
 discrepancies in weld designations will be revised by ITI
 Grinnell for use in insp of fabricated welds
 MILLS, L M Tennessee Valley Authority 81/01/22 2pp 07548 358.

DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1

A Application/construction stage documents & correspondence

80101220466 Ltr to all power reactor licensees & applicants forwarding
 summary of 801112 meeting re implementation of guidance for
 Unresolved Safety Issue A-12, "Potential for Low Fracture
 Toughness & Lamellar Tearing on Component Supports"
 EISENHUT, D G Division of Licensing 80/11/26 8pp.

8010120710 Forwards request for addl info re ultimate capacity analysis
 of ice condenser & Mark III containments
 TEDESCO, R L Assistant Director for Licensing 80/12/18 3pp
 07494 040.

80101190305 Ltr to all BWR applicants for OL re BWR steam discharge sys
 safety evaluation & requirements Rept specifying acceptable
 basis for continued BWR plant operation & design criteria
 for steam discharge vol encl
 TEDESCO, R L Assistant Director for Licensing 80/12/22 2pp
 07193 001.

--80101190514 Forwards generic safety evaluation re BWR steam discharge
 sys. Review identified two addl requirements to those
 proposed by owners group re steam discharge vol designs Rept
 should be transmitted to license applicants.
 CHECK, P. B. Assistant Director for Plant Systems. 80/12/01 2pp
 07183 001.

80101200458 Responds to NRC 801226 ltr requesting schedule for
 performing ultimate capacity analysis for Mark III
 containment design. Static pressure analysis for surfaces
 w/min sectional strength may be completed by Nov 1981
 DAVIDSON, D R Cleveland Electric Illuminating Co. 81/01/22 1p
 07582 352

F Security, medical, emergency & fire protection plans

80101090387 Ltr to all licensees of operating reactor plants, CP holders
 & CP applicants Revised radiological emergency response
 plans must be submitted by licensees within 60 days of
 810102 & by applicants as part of PSAR.
 EISENHUT, D G. Division of Licensing. 80/11/13 2pp.

G Inspection reports, IE Bulletins & correspondence

80101050244 Forwards IE Info Notice 80-38, "Cracking in Charging Pump
 Casing Cladding." No response required
 KEPLER, J G Region 3, Chicago, Office of the Director. 80/10/30.
 2pp 07387 116

80101040110 Forwards IE Circular 80-23, "Potential Defects in Below
 Power Sys Emergency Generators" No written response
 required
 KEPLER, J G Region 3, Chicago, Office of the Director 80/10/
 1p 07397 323

80101030264 Forwards IE Insp Repts 50-440/80-25 & 50-441/80-23 on
 801001-21 & notice of violation
 FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering
 Support Branch 80/11/17 2pp 07421 289

--80101080271 Notice of violation from insp on 801001-31
 "Region 3, Chicago, Office of the Director 80/11/17 1p
 07421 291

--80101080284 IE Insp Repts 50-440/80-25 & 50-441/80-23 on 801001-31
 Noncompliance noted failure to follow engineer drawings &
 fabricated spool pieces 1-E19-32 & 1-E19-33 being cold-
 pulled into position
 HUGHES, J J WILLIAMS, C C Region 3, Chicago, Office of the
 Director 80/11/17 1pp 07421 292

80101050526 Forwards IE Info Notice 80-43, "Failures of Continuous
 Level Monitor for Steam Discharge Vol at Dresden Unit 2." No
 response required.
 KEPLER, J G Region 3, Chicago, Office of the Director 80/12/
 2pp 07390 297

80101080056 Forwards IE Info Notice 80-45, "Potential Failure of H
 Backup Manual Steam Capability." No written response
 required
 KEPLER, J G Region 3, Chicago, Office of the Director 80/12/
 2pp 07420 325

80101050246 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of Con
 Rods to Insert During Scram at BWR." No written response
 required.
 KEPLER, J G Region 3, Chicago, Office of the Director 80/12/
 2pp 07465 339

80101050202 Forwards IE Bulletin 80-25, "Operating Problems W/Targ
 Rock Safety Relief Valves at 3Mw." No response required
 KEPLER, J G Region 3, Chicago, Office of the Director 80/12/
 2pp 07377 349

80101290484 Forwards IE Insp Repts 50-440/80-27 & 50-441/80-28 on
 801101-30 No noncompliance noted
 FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering
 Support Branch 80/12/22 2pp 07575 158.

--80101290491 IE Insp Rept 50-440/80-27 & 50-441/80-28 on 801101-30
 noncompliance noted Major areas inspected safety-related
 const activities including containment spray sys piping &
 heating, ventilation & air conditioning ducts.
 HUGHES, J J WILLIAMS, C C Region 3, Chicago, Office of the
 Director 80/12/17 3pp 07575 160

80101200517 Responds to IE Bulletin 80-21, "Valve Yokes Supplied
 Malcolm Foundry Co, Inc." Castings are not used in active
 safety-related valves at facilities
 DAVIDSON, D R Cleveland Electric Illuminating Co 80/12/23.
 07487 051

80101290160 Ack receipt of 801015 ltr informing NRC of steps taken
 correct violations noted in IE Insp Rept 50-440/80-18
 FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering
 Support Branch 81/01/08 1p 07567 354.

--80101290169 Responds to NRC 800912 ltr re violations noted in I
 Rept 50-440/80-18 Corrective actions formal definition of
 weave per ASME Section IX will be added to each general
 welding std
 DAVIDSON, D R Cleveland Electric Illuminating Co 80/10/15
 07567 355

80101220116 Ack receipt of 801219 ltr informing NRC of steps taken
 correct violations noted in IE Insp Repts 50-440/80-25 &
 50-441/80-23
 FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering
 Support Branch 80/01/09 1p 07502 004

--80101220121 Responds to NRC 801119 ltr re violations noted in I
 Repts 50-440/80-25 & 50-441/80-23 Corrective actions
 Pullman Power Products Procedure IX-53 incorporating
 procedures of piping stress tests initiated.
 DAVIDSON, D R Cleveland Electric Illuminating Co. 80/12/15
 07502 005

S. Reportable occurrences, LERs & related correspondence

8101220555 Interim deficiency rept re improper reactor protection sys flexible conduit grounding in power generation control complex. Caused by mounting termination module on painted surface. Final rept will be submitted by 810701
DAVIDSON, D R Cleveland Electric Illuminating Co 81/01/14 2pp 07503 151

8101220420 Interim deficiency rept re lamination identified in A36 gusset plate hanger steel matl. initially reported on 801219. Insp program & evaluation of results will determine addl corrective actions. Final rept will be submitted by 810302
DAVIDSON, D R Cleveland Electric Illuminating Co 81/01/15 2pp 07502 249

DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2

A. Application/construction stage documents & correspondence

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

8101130710 Forwards request for addl info re ultimate capacity analysis of ice condenser & Mark III containment
TEGEBACK, R L Assistant Director for Licensing 80/12/18 3pp 07454 040

8101300458 Responds to NRC 801226 ltr requesting schedule for performing ultimate capacity analysis for Mark III containment design. Static pressure analysis for surfaces within sectional strength may be completed by Nov 1981
DAVIDSON, D R Cleveland Electric Illuminating Co 81/01/22 1p 07582 352

F. Security, medical, emergency & fire protection plans

8101070387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

G. Inspection reports, IE Bulletins & correspondence

8101050244 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/30 2pp 07389 116

8101060110 Forwards IE Circular 80-23, "Potential Defects in Boloit Power Sys Emergency Generators." No written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/31 1p 07397 323

8101090264 Forwards IE Insp Repts 50-440/80-25 & 50-441/80-23 on 810101-31 & notice of violation
FIERELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/11/19 2pp 07421 289

--8101090271 Notice of violation from Insp on 801001-31, "Region 3, Chicago, Office of the Director 80/11/17 1p 07421 291

--8101090284 IE Insp Repts 50-440/80-25 & 50-441/80-23 on 801001-31. Noncompliance noted. Failure to follow engineer drawings & fabricated spool pieces 1-E15-32 & 1-E15-33 being cold-pulled into position
HUGHES, J J WILLIAMS, C C Region 3, Chicago, Office of the Director 80/11/17 11pp 07421 292

8101050526 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Steam Discharge Vol at Dresden Unit 2." No response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/05 2pp 07390 297

8101090556 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Scram Capability." No written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/17 2pp 07420 325

8101050246 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of Rods to Insert During Scram at BWR." No written response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/05 2pp 07463 359

8101050232 Forwards IE Bulletin 80-25, "Operating Problems With Rock Safety Relief Valves at BWRs." No response required
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/05 2pp 07377 349

8101290486 Forwards IE Insp Repts 50-440/80-27 & 50-441/80-25 on 801101-30. No noncompliance noted
FIERELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/22 2pp 07575 198

--8101290491 IE Insp Rept 50-440/80-27 & 50-441/80-25 on 801101-30. Noncompliance noted. Major areas inspected safety-related consist activities including containment spray sys piping & heating, ventilation & air conditioning ducts
HUGHES, J J WILLIAMS, C C Region 3, Chicago, Office of the Director 80/12/17 3pp 07575 160

8101290517 Responds to IE Bulletin 80-21, "Valve Yokes Supplied Malcolm Foundry Co. Inc." Castings are not used in active safety-related valves at facilities
DAVIDSON, D R Cleveland Electric Illuminating Co 80/12/23 07487 051

8101220116 Ack receipt of 801219 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/80-25 & 50-441/80-23
FIERELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/01/09 1p 07502 004

--8101220121 Responds to NRC 801119 ltr re violations noted in Repts 50-440/80-25 & 50-441/80-23. Corrective actions Pullman Power Products Procedure IX-53 incorporating procedures of piping stress tests initiated
DAVIDSON, D R Cleveland Electric Illuminating Co 80/12/07502 005

S. Reportable occurrences, LERs & related correspondence

8101220565 Interim deficiency rept re improper reactor protection flexible conduit grounding in power generation control complex. Caused by mounting termination module on painted surface. Final rept will be submitted by 810701
DAVIDSON, D R Cleveland Electric Illuminating Co 81/01/14 07503 151

8101220420 Interim deficiency rept re lamination identified in gusset plate hanger steel matl. initially reported on 801219. Insp program & evaluation of results will determine addl corrective actions. Final rept will be submitted by 810302
DAVIDSON, D R Cleveland Electric Illuminating Co 81/01/15 07502 249

DOCKET 50-443 SEABROOK NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

8101220466 Ltr to all power reactor licensees & applicants for summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

8101100228 Informs that 801118 request for partial transfer of CP & CPFR-136 only requires Class II fee for Unit 1 & Class I fee for Unit 2. Refund will be processed in 2-wk period
DUGGS, R H License Fee Management Branch 80/12/22 1p 07445 216

8101190625 Approves until 801208 request for authorization to use Code Case N-279 in const of components at facility. When preloading is used as locking device & joint requires removal, bolting shall be replaced if original is strained
VUNGSLIOD, G J Licensing Branch 1 80/12/29 2pp 07472 000

F. Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

8101070254 Requests that encl emergency planning info be made publicly available w/o encl
SQUJER, J L Division of Rules and Records 80/12/17 1p
07414 298

G Adjudicatory correspondence

8101070513 Interrogatories directed to applicant Requests info re witnesses & util position on Intensity IX earthquake
Certificate of Svc encl
WEISS, E R JORDAN, W S New England Coalition on Nuclear Pollution
WEISS, E R Sheldon, Harmon & Weiss 81/01/02 11pp 07415 100

8101070306 Chinnery answers to applicant interrogatories re seismic issues Affidavit to be forwarded shortly Certificate of Svc encl
JORDAN, W S New England Coalition on Nuclear Pollution JORDAN, W S
Sheldon, Harmon & Weiss 81/01/06 25pp 07187 001

8101270334 Responds to ltr re NRC discovery Requests New England Coalition on Nuclear Power delete interrogatories B, 9 & 15
Proposes single deposition of NRC witnesses as panel & B10212 as deposition date
LESSY, R P Antitrust Division 81/01/15 3pp 07546 081

8101230196 Order granting extension until 810130 for Commission to review ALAB-623 Certificate of Svc encl
CHILK, S J Office of the Secretary of the Commission 81/01/16 4pp 07512 026

8101280591 Answers & objections to New England Coalition on Nuclear Power interrogatories Certificate of Svc encl
VANDEBURGH, D J DIGNAN, T G Public Service Co. of New Hampshire
DIGNAN, T G Dignan, T G 81/01/21 20pp 07555 140

8101270434 Forwards transcript of MD Trifunac deposition Corrections listed Requests review & addl changes
LESSY, R P Antitrust Division 81/01/26 2pp 07546 184

H General correspondence

8101080399 Responds to 801113 ltr expressing concerns re usefulness in siting policy as outlined in NUREG-0625 Financial problems have not excluded facility owners from activities authorized by NRC regulations Ltr dtd 801021 to RA Backus encl
YOUNGBLQDD, B J Licensing Branch 1 80/12/08 2pp 07419 263

8101140208 Responds to 801116 ltr expressing concern re nuclear accident insurance Price-Anderson Act provides sys of private funds & govt indemnity to pay public liability claims for personal injury & property damage
BENTON, H R Office of Nuclear Reactor Regulation, Director, 80/12/24 5pp 07309 001

--8101140214 Expresses concern re const of facilities & requests info re nuclear accident insurance.
PETIT, R Affiliation Unknown 80/11/16 2pp 07309 001

8101070100 Comments that Seabrook const should be stopped, since nuclear power is unsafe & power plant operation is inefficient
PETIT, R Affiliation Unknown 80/12/30 1p 07442 235

8101050508 Expresses adamant opposition to licensing of facilities
MOYER, H S Affiliation Unknown 81/01/07 5pp 07463 145

8101190114 Responds to encl 801210 ltr to President Carter expressing concern re const of facilities & questioning need for nuclear power Licensing procedure explained.
YOUNGBLQDD, B J Licensing Branch 1 81/01/07 3pp 07475 319

G Inspection reports, IE Bulletins & correspondence

8101070395 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange" No written response required.
GRIER, B H Region 1, Philadelphia, Office of the Director, 80/11/26 1p 07414 086

8101060849 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown." No written response required
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/16 1p 07397 009

8101170301 Immediate Action Ltr 80-55, confirming until 801222 commitments re items of non-compliance re cold repairs in safety-related piping by licensee until issue stop work order to halt repairs performed by Pullman-Higgins
GRIER, B H Region 1, Philadelphia, Office of the Director 80/12/22 2pp 07474 276

S Reportable occurrences, LERs & related correspondence

8101230497 Final deficiency rept. originally reported on 801216 re pipe supports not meeting ASME code requirements Caused by design & human error Formal design manual issued, check list initiated to confirm requirements & training session begun
DEVINCENTIS, J Public Service Co. of New Hampshire 81/01/15 07510 022

T Hearings transcripts on non-antitrust matters

8101260256 Transcript of 780609 proceedings in Washington, DC re consideration of stay of facilities during review of ALAB-471
Commissioners 78/06/09 46pp 07503 320

DOCKET 80-444 SEABROOK NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8101280144 Ltr to all power reactor licensees & applicants forward summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D G Division of Licensing 80/11/26 8pp

8101100228 Informs that 801118 request for partial transfer of CPR & CPRR-136 only requires Class 1 fee for Unit 1 & Class 1 fee for Unit 2 Refund will be processed in 2-wk period
DIQGS, R H License Fee Management Branch 80/12/22 1p 07449 216

8101190625 Approves until 801208 request for authorization to use Code Case N-279 in const of components at facility when preloading is used as locking device & joint requires removal, bolting shall be replaced if original is strained
YOUNGBLQDD, B J Licensing Branch 1 80/12/29 2pp 07472 312

F Security, medical, emergency & fire protection plans

8101070387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing 80/11/13 2pp

8101070254 Requests that encl emergency planning info be made publicly available w/o encl
SQUJER, J L Division of Rules and Records 80/12/17 1p 07414 298

G Adjudicatory correspondence

8101070513 Interrogatories directed to applicant Requests info re witnesses & util position on Intensity IX earthquake
Certificate of Svc encl
WEISS, E R JORDAN, W S New England Coalition on Nuclear Pollution
WEISS, E R Sheldon, Harmon & Weiss 81/01/02 11pp 07415 100

8101070306 Chinnery answers to applicant interrogatories re seismic issues Affidavit to be forwarded shortly Certificate of Svc encl
JORDAN, W S New England Coalition on Nuclear Pollution JORDAN, W S
Sheldon, Harmon & Weiss 81/01/06 25pp 07187 001

8101270334 Responds to ltr re NRC discovery Requests New England Coalition on Nuclear Power delete interrogatories B, 9 & 15
Proposes single deposition of NRC witnesses as panel & B10212 as deposition date
LESSY, R P Antitrust Division 81/01/15 3pp 07546 081

8101230156 Order granting extension until 810130 for Commission review, ALAB-623 Certificate of Svc encl
CHILK, S J Office of the Secretary of the Commission 81/01/16 4pp 07512 026

8101280091 Answers & objections to New England Coalition on Nuclear Power interrogatories Certificate of Svc encl
VANDEBURGH, D J DIGNAN, T G Public Service Co. of New Hampshire
DIGNAN, T G Dignan, T G 81/01/21 20pp 07555 140

011270334 Forwards transcript of MD T-Forum deposition Corrections
listed Requests review & addl changes
LESTER R P Antitrust Division 81/01/26 2pp 07346 184

H General correspondence

0101140238 Responds to 801116 ltr expressing concern re nuclear
accident insurance Price-Anderson Act provides sys of
private funds & govt indemnity to pay public liability
claims for personal injury & property damage
DELMONAH R Office of Nuclear Reactor Regulation, Director
80/12/24 3pp 07309 001

--0101140214 Expresses concern re const of facilities & requests info re
nuclear accident insurance
PETIT R Affiliation Unknown 80/11/16 2pp 07309 001

0101090100 Comments that Federal const should be stopped, since
nuclear power is unsafe & power plant operation is
inefficient
PETIT R Affiliation Unknown 80/12/30 1p 07442 235

0101150508 Expresses adamant opposition to licensing of facilities
HOVERMAN S Affiliation Unknown 81/01/07 3pp 07463 149

0101140114 Responds to encl 801210 ltr to President Carter expressing
concern re const of facilities & questioning need for
nuclear power Licensing procedure explained
VORHAGEN J J Licensing Branch 1 81/01/07 3pp 07475 319

I Inspection reports, IE Bulletins & correspondence

0101070395 Forwards Suppl 1 to IE Info Notice 80-29. Broken Studs on
Terry Turbine Steam Inlet Flange. No written response
required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/11/26 1p 07414 006

0101060844 Forwards IE Info Notice 80-44. 'Activation of ECCS in
Recirculation Mode While in Hot Shutdown' No written
response required
GRIER, B H Region 1, Philadelphia, Office of the Director
80/12/16 1p 07377 009

G Reportable occurrences, LERs & related correspondence

0101230497 Final deficiency rept. originally reported on 801216, re
pipe supports not meeting ASME code requirements caused by
design & human error. Formal design manual issued, check list
initiated to confirm requirements & training session begun.
DEVINCENFIS J Public Service Co. of New Hampshire 81/01/15 1p
07510 022

T Hearing transcripts on non-antitrust matters

0101220296 Transcript of 700609 proceedings in Washington, DC re
consideration of stay of facilities during review of
ALAB-471
* Commissioners 78/06/09 46pp 07503 328

DSCKET 90-445 (PMANCHE PEAK STEAM ELECTRIC STA. UNIT 1

A Application/construction stage documents & correspondence

0101220466 Ltr to all power reactor licensees & applicants forwarding
summary of 801112 meeting re implementation of guidance for
Unresolved Safety Issue A-12. 'Potential for Low Fracture
Toughness & Lateral Tearing on Component Supports'
EISENHUT, D G Division of Licensing 80/11/26 8pp

0101050318 Submits suppl to util 800808 rept re architectural tapping
placed on floor slabs Project completion anticipated 810201
GARY, R J Texas Utilities Generating Co 80/12/22 1p 07305 271

0101200242 Informs that evaluation of pull-out performance of 1-inch
diameter Hilti Quik-Bolt anchors continues due to change in
published values Status rept will be provided by 810901
GARY, R J Texas Utilities Generating Co 81/01/12 1p 07487 092

0101270110 Forwards request for addl info needed to complete review of
the application FEAR should be amended to include new info
TEDESCO R L Assistant Director for Licensing 81/01/13 4pp
07547 041

0101290443 Summary of 801015 meeting w/ util in Bethesda, MD re facility
response to proposed design change for improving nuclear
steam sys response to boron dilution transients List of
attendees & slide presentation encl
BARNWELL, S P Licensing Branch 2 81/01/14 4pp 07371 001

0101300521 Requests documentation of maint records re preservice ins
testing of snubbers due to problems w/inoperable &
incorrectly installed snubbers Preservice exam should be
made of snubbers listed in SIS Tables 3 7-4a & 3 7-4b
TEDESCO, R L Assistant Director for Licensing 81/01/14 3pp
07587 074

0101270347 Forwards updated 810115 Well data rept Rept superseded
800422 rept
WERNER, H Texas Utilities Services, Inc 81/01/16 1p 07560 001

--0101270753 Well data on all wells within 5-mile radius of
facility, as of 801231
REHNER, L J H J Gray & Associates, Inc 81/01/15 8pp
07360 001

C Utility Environmental Report (ER), amends & correspondence

0101060462 Forwards affidavit of svc of Amend 2 to environ rept. DL
stage
SCHMIDT, H C Texas Utilities Generating Co 80/12/29 9pp
07396 079

0101160550 Forwards Amend 3 to environ rept Affidavit encl
GRAY, J R Texas Utilities Co 81/01/08 2pp 07472 130

--0101160557 Amend 3 to environ rept
* Texas Utilities Co 81/01/31 2pp 07472 132

F Security, medical, emergency & fire protection plans

0101090387 Ltr to all licensees of operating reactor plants, CP hold
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
810102 & by applicants as part of FEAR
EISENHUT, D G Division of Licensing 80/11/13 2pp

0101070291 Releases public version of State of TX, Hood County, City of
Granbury, Somervell County & City of Glen Rose emergency
operations plans
FELTON, J H Division of Rules and Records 80/12/02 1p
07309 001

--0101070298 Forwards public version of State of TX, Hood County, City of
Granbury, Somervell County & City of Glen Rose emergency
operations plans
EDWARDS, J D Texas Utilities Co 80/01/29 1p 07309 001

--0101070302 Public version of State of TX, Hood County & City of
Granbury emergency operations plan
* Hood County, TX * Granbury, TX 76/09/20 26pp 07309 001

--0101070307 Public version of State of TX, Somervell County & City of
Glen Rose emergency operations plan
* Somervell County, TX * Glen Rose, TX 80/01/29 23pp
07309 001

0101300131 Forwards facility emergency planning info for placement
LPDR w/o 8101070298
SOUDER, J L Division of Rules and Records 81/01/16 1p
07583 075

Q Adjudicatory correspondence

0101050478 Response to Citizens Association for Bound Energy second
of interrogatories. Discovery request relevancy determined in
view of Contention 3, worded as accepted by ASLB in 800616
order Certificate of Svc encl Related correspondence.
REYNOLDS, N S HORN, W A Texas Utilities Generating Co
REYNOLDS, N S Debevoise & Liberman 80/12/22 11pp 07390 206

0101050523 Response to NRC 801209 response to Citizens Association
Bound Energy motions for separate intervenor status &
appointment as lead party for consolidated contentions.
Clarifies previous pleadings Certificate of Svc encl.
ELLIS, J Citizens Association for Bound Energy 80/12/23 9pp
07390 236

0908 Order denying Citizens Association for Sound Energy motion
separate intervenor status Consolidates parties on
motions 4, 5, 22, 23 & 24 Appoints lead party intervenor
on other contentions
R.V.B. Atomic Safety and Licensing Board Panel 80/12/31
07415 067

0037 Answers to applicant first set of interrogatories & requests
to produce per ASLB 801219 memorandum & order Most responses
are supplemented at later date Certificate of Svc encl
ated correspondence
J.M. Association of Community Organizations for Reform
Texas GAY, Q.M. West Texas Legal Services 81/01/09 13pp
8 326

0233 Second set of interrogatories & requests to produce directed
Citizens Association for Sound Energy re Contention 22.
licants' failure to comply w/10CFR50 emergency planning
requirements Certificate of Svc encl
BLDS, M.S. , HERIN, W.A. Texas Utilities Generating Co
BLDS, M.S. Debevoise & Liberman 81/01/12. 17pp 07470 199

0073 First set of interrogatories & request for production of
documents directed to intervenor Citizens Association for
Sound Energy Includes identification of witnesses &
series of positions Certificate of Svc encl
SCHILD, M.U. Operations & Administrative Division 81/01/19
07502.009

0078 First set of interrogatories & request for production of
documents directed to Association of Community Organizations
for Reform Now Includes identification of witnesses &
series of positions Certificate of Svc encl
SCHILD, M.U. Operations & Administrative Division 81/01/19
07502.036

0082 First set of interrogatories & request for production of
documents directed to Citizens for Fair Util Regulation
Includes identification of witnesses & summaries of
positions Certificate of Svc encl
SCHILD, M.U. Operations & Administrative Division. 81/01/19
07502.077

ection reports, IE Bulletins & correspondence

0117 Ack receipt of IE Insp Repts 50-445/80-18 & 50-446/80-18 No
proprietary info
R.J. Texas Utilities Generating Co. 80/10/18. 1p 07547.212

0247 Discusses IE Insp Repts 50-445/80-23 & 50-446/80-23
01009 & forwards notice of violation Repts to be
ad in near future
E.H.C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 80/10/16. 2pp. 07445.221.

100251 Notice of violation from insp on 801008 Noncompliance noted
dis connecting stiffener plates to balance of Assembly
07 were not complete penetration welds
Region 4, Dallas, Office of the Director. 80/10/16 1p.
045.223

0814 Ack receipt of IE Insp Repts 50-445/80-20 & 50-446/80-20
proprietary info
R.J. Texas Utilities Generating Co. 80/11/12. 1p 07549.073

0059 Forwards IE Insp Repts 50-445/80-23 & 50-446/80-23 on
01-31.
E.W.C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 80/11/19 2pp 07443.019

100063 IE Insp Repts 50-445/80-23 & 50-446/80-23 on 801001-1031
noncompliance noted: failure to follow procedures for making
all penetration welds
VLDR, R.O., CROSSMAN, W.A. Region 3, Chicago, Office of the
Director. 80/11/19 7pp 07443.021

0171 Forwards IE Insp Repts 50-445/80-28 & 50-446/80-28 on
03-06 No noncompliance noted.
E.W.C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch. 80/11/19 2pp. 07443.008.

10017B IE Insp Repts 50-445/80-28 & 50-446/80-28 on 801103-06 No
noncompliance noted. Major areas inspected: const activities &
records for RCPB piping.
LBERT, L.D., CROSSMAN, W.A. Region 3, Chicago, Office of the
Director. HALL, R.E. Region 3, Chicago, Reactor Construction &
Engineering Support Branch. 80/11/18 3pp. 07443.010

8101710456 Responds to IE Bulletin 80-20. "Failures of Westinghouse
Type 1-2 Spring Return to Neutral Control Switches "
Corrective actions scheduled for 811201 completion contact
lights will be required & auxiliary relay for alarm added
GRAY, R.J. Texas Utilities Generating Co 80/11/19 2pp
07488.242

8101270152 Ack receipt of IE Insp Repts 50-445/80-24 & 50-446/80-24 No
proprietary info
GARY, R.J. Texas Utilities Generating Co 80/11/19 1p 07547.292

8101270147 Ack receipt of IE Insp Repts 50-445/80-25 & 50-446/80-25 No
proprietary info
GARY, R.J. Texas Utilities Generating Co 80/12/03 1p 07547.258

8101030619 Forwards IE Info Notice 80-43. "Failures of Continuous Water
Level Monitor for Steam Discharge Vap at Dresden Unit 2 " No
response required
SEYFRIT, K.V. Region 4, Dallas, Office of the Director 80/12/08
1p 07371.051

8101060182 Forwards IE Info Notice 80-44. "Actuation of ECCS in
Recirculation Mode While in Hot Shutdown " No written
response required
SEYFRIT, K.V. Region 4, Dallas, Office of the Director 80/12/16
1p 07371.288

8101100716 Ack receipt of 801112 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-445/80-23 &
50-446/80-23
SEIDLE, W.C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 80/12/23 1p 07443.225

--8101100726 Responds to NRC 801016 ltr re violations noted in IE Insp
Repts 50-445/80-23 & 50-446/80-23 Corrective actions
assembly repaired & fabrication drawings reviewed
GARY, R.J. Texas Utilities Generating Co 80/11/12. 3pp
07443.226

8101100732 Ack receipt of 801118 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-445/80-20 &
50-446/80-20
SEIDLE, W.C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 80/12/23 1p 07443.229

--8101100738 Responds to NRC 801021 ltr re violations noted in IE Insp
Repts 50-445/80-20 & 50-446/80-20 Corrective actions
applicable flow diagrams revised to reflect actual
pressurizer/spray valve arrangement
GARY, R.J. Texas Utilities Generating Co 80/11/18 3pp
07443.230

8101210372 Forwards IE Insp Repts 50-445/80-26 & 50-446/80-26 on
801105-07, 13-14, 18-20 & 24-25 No noncompliance noted
SEIDLE, W.C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch. 80/12/23 2pp 07467.308

--8101210077 IE Insp Repts 50-445/80-26 & 50-446/80-26 on 801105-07,
13-14, 18-20 & 24-25 No noncompliance noted Major areas
inspected const activities including reactor vessel/
internals & instrumentation components & sys
CROSSMAN, W.A., STEWART, R.C. Region 4, Dallas, Office of the
Director. 80/12/23 6pp 07489.310

8101300621 Requests documentation of maint records re preservice insp &
testing of snubbers due to problems w/inoperable &
incorrectly installed snubbers Preservice exam should be
made of snubbers listed in STS Tables 3 7-4a & 3 7-4b
TEDESCO, R.L. Assistant Director for Licensing 81/01/14 3pp
07587.074

B Reportable occurrences, LERs & related correspondence

8101200746 Interim deficiency rept re mfg deficiency of component
supports associated w/auxiliary piping sys diesel
generators. Initially reported 800726 Evaluation will be
completed by 810731.
GARY, R.J. Texas Utilities Generating Co 81/01/12 1p 07487.091.

8101200253 Interim deficiency rept re unauthorized field mods to
Hilti-Kwik concrete anchor bolts, initially reported 801001.
Bolts have not been modified in unauthorized manner
Follow-up rept will be submitted by 810417
GARY, R.J. Texas Utilities Generating Co 81/01/12 2pp
07487.089

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12. Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports
 EISENHART, D. G. Division of Licensing 03/11/26 2pp

G Adjudicatory correspondence

B101050316 Submits suppl to util E00008 rept re architectural topping placed on floor slabs Project completion anticipated B10081
 GARY, R. J. Texas Utilities Generating Co. 08/12/22 1p 07385 271

B101050472 Response to Citizens Association for Sound Energy second set of interrogatories Discovery request relevancy determined in view of Contention 3: Jorred as accepted by ASLB in B00616 order Certificate of Svc encl Related correspondence
 REYNOLDS, N. S., HODIN, W. A. Texas Utilities Generating Co.
 REYNOLDS, N. S., Debevoise & Liberman 08/12/22 11pp 07390 206

B101200242 Informs that evaluation of pull-out performance of 1-inch diameter Hilti Kwik-Bolt anchors continues due to change in published values Status rept will be provided by B10901
 GARY, R. J. Texas Utilities Generating Co. 01/01/12 1p 07487 092

B101050523 Response to NRC B01209 response to Citizens Association for Sound Energy motions for separate intervenor status & appointment as lead party for consolidated contentions Clarifies previous pleadings Certificate of Svc encl
 ELLIS, J. Citizens Association for Sound Energy 08/12/23 7pp 07390 236

B101270110 Forwards request for addl info needed to complete review of application FSAR should be amended to include new info.
 TEDESCO, R. L. Assistant Director for Licensing 01/01/13 4pp 07547 041

B101070508 Order denying Citizens Association for Sound Energy motion for separate intervenor status Consolidates parties on Contentions 4, 5, 22, 23 & 24 Appoints lead party intervenor status on other contentions
 DEALE, V. B. Atomic Safety and Licensing Board Panel. 08/12/31 13pp 07415 CB7

B101290463 Summary of B01015 meeting w/util in Bethesda, MD re facility response to proposed design change for improving nuclear steam sys response to boron dilution transients List of attendees & slide presentation encl
 BURWELL, S. G. Licensing Branch 2 01/01/14 4pp 07371 001

B101130037 Answers to applicant first set of interrogatories & request to produce per ASLB B01219 memorandum & order Most responses to be supplemented at later date Certificate of Svc encl Related correspondence
 GAY, G. M. Association of Community Organizations for Reform Now-Texas GAY, G. M. West Texas Legal Services. 01/01/09 13pp 07448 326

B101300521 Requests documentation of maint records re preservice insp & testing of snubbers due to problems w/inoperable & incorrectly installed snubbers Preservice exam should be made of snubbers listed in SIS Tables 3 7-4a & 3 7-4b
 TEDESCO, R. L. Assistant Director for Licensing 01/01/14 3pp 07587 074

B101160233 Second set of interrogatories & requests to produce directed to Citizens Association for Sound Energy re Contention 22; applicants' failure to comply w/10CFR50 emergency planning requirements Certificate of Svc encl
 REYNOLDS, N. S., HODIN, W. A. Texas Utilities Generating Co.
 REYNOLDS, N. S. Debevoise & Liberman. 01/01/12 17pp 07470: 149.

B101270347 Forwards updated B10115 well data rept Rept supersedes B00922 rept
 WEKNER, R. Texas Utilities Services, Inc. 01/01/16 1p 03560 001.

--B101270353 Well data on all wells within 5-mile radius of facility as of B01231.
 REHAEEMPER, L. J. H. J. Gray & Associates, Inc. 01/01/15 8pp 03560 001

B101220073 First set of interrogatories & request for production of documents directed to intervenor Citizens Association for Sound Energy Includes identification of witnesses & summaries of positions Certificate of Svc encl
 ROTHSCHEILD, M. U. Operations & Administrative Division 01/01/19 27pp 07502 009

C. Utility Environmental Report (ER), agenda & correspondence

B101060462 Forwards affidavit of svc of Amend 2 to environ rept.OL stage.
 SCHMIDT, H. C. Texas Utilities Generating Co. 08/12/29 9pp 07396 079

B101220078 First set of interrogatories & request for production of documents directed to Association of Community Organizations for Reform Now Includes identification of witnesses & summaries of positions Certificate of Svc encl
 ROTHSCHEILD, M. U. Operations & Administrative Division. 01/01/19 41pp 07502 036

B101160560 Forwards Amend 3 to environ rept Affidavit encl
 GRAY, J. R. Texas Utilities Co. 01/01/08 2pp 07472 130

--B101160507 Amend 3 to environ rept
 Texas Utilities Co. 01/01/31 2pp 07472 132

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
 EISENHART, D. O. Division of Licensing 08/11/13 2pp.

G Inspection reports, IE Bulletins & correspondence

B101270117 Ack receipt of IE Insp Repts 50-445/80-18 & 50-446/80-18 M proprietary info
 GARY, R. J. Texas Utilities Generating Co. 08/10/15 1p 07547 211

B101070291 Releases public version of State of TX.Hood County, City of Granbury, Somervell County & City of Glen Rose emergency operations plans
 FELTON, J. M. Division of Rules and Records. 08/12/02 1p 07309 001

B101100247 Discusses IE Insp Repts 50-445/80-23 & 50-446/80-23 on B01009 & forwards notice of violation Repts to be issued in near future
 SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 08/10/16 2pp 07443: 221.

--B101070298 Forwards public version of State of TX.Hood County, City of Granbury, Somervell County & City of Glen Rose emergency operations plans
 EDWARDS, J. D. Texas Utilities Co. 08/01/29 1p 07309 001

--B101100251 Notice of violation from insp on B01008 Noncompliance no welds connecting stiffener plates to balance of Assembly M-29 were not complete penetration welds.
 Region 4, Dallas, Office of the Director. 08/10/16 1p 07443 223

--B101070302 Public version of State of TX.Hood County & City of Granbury emergency operations plan
 Hood County, TX Granbury, TX 76/09/20 26pp 07309 001.

B101270814 Ack receipt of IE Insp Repts 50-445/80-20 & 50-446/80-20 No proprietary info
 GARY, R. J. Texas Utilities Generating Co. 08/11/12 1p 07549 091

--B101070307 Public version of State of TX.Somervell County & City of Glen Rose emergency operations plan
 Somervell County, TX Glen Rose, TX 08/01/29 25pp 07309 001

B101100059 Forwards IE Insp Repts 50-445/80-23 & 50-446/80-23 on B01001-31.
 SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 08/11/19 2pp 07443 019.

00563 IE Insp Repts 50-445/80-23 & 50-446/80-23 on 801001-1031 compliance noted failure to follow procedures for making penetration welds
LORR, G. CROSSMAN, W. A. Region 3, Chicago, Office of the Director 80/11/19 7pp 07443 021

171 Forwards IE Insp Repts 50-445/80-20 & 50-446/80-26 on 3-06 No noncompliance noted.
E.W.C. Region 4, Dallas, Reactor Construction & Engineering Branch 80/11/19 2pp 07443 CCR

00178 IE Insp Repts 50-445/80-20 & 50-446/80-26 on 801103-06 No compliance noted Major areas inspected const activities & bids for RCPB piping
BERT, L. D., CROSSMAN, W. A. Region 3, Chicago, Office of the Director HALL, R. E. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/11/19 3pp 07443 010

666 Responds to IF Bulletin 80-20, "Failures of Westinghouse 12 Spring Return to Neutral Control Switches"
Positive actions scheduled for 81201 completion contact will be required & auxiliary relay for alarm added
J. Texas Utilities Generating Co 80/11/19 2pp 242

52 Ack receipt of IE Insp Repts 50-445/80-24 & 50-446/80-24 No entry info
J. Texas Utilities Generating Co 80/11/19 1p 07547 292

47 Ack receipt of IE Insp Repts 50-445/80-25 & 50-446/80-29 No entry info
J. Texas Utilities Generating Co 80/12/03 1p 07547 259

62 Forwards IE Info Notice 80-44, "Actuation of ECCB in violation Mode While in Hot Shutdown" No written response required
T.K.V. Region 4, Dallas, Office of the Director 80/12/16 7391 20B

16 Ack receipt of 801112 ltr informing NRC of steps taken to violations noted in IE Insp Repts 50-445/80-23 & 50-23
W.C. Region 4, Dallas, Reactor Construction & Engineering Branch 80/12/23 1p 07443 229

0726 Responds to NRC 801016 ltr re violations noted in IE Insp & 50-445/80-23 & 50-446/80-23 Corrective actions visibly repaired & fabrication drawings reviewed
R.J. Texas Utilities Generating Co. 80/11/12 3pp 3 226

02 Ack receipt of 801118 ltr informing NRC of steps taken to violations noted in IE Insp Repts 50-445/80-20 & 50-20
W.C. Region 4, Dallas, Reactor Construction & Engineering Branch 80/12/23 1p 07443 229

0738 Responds to NRC 801021 ltr re violations noted in IE Insp & 50-445/80-20 & 50-446/80-20 Corrective actions visible flow diagrams revised to reflect actual surtifier/spray valve arrangement
R.J. Texas Utilities Generating Co 80/11/18 3pp 3 230

072 Forwards IE Insp Repts 50-445/80-26 & 50-446/80-26 on 07-13-14, 18-20 & 24-25 No noncompliance noted
W.C. Region 4, Dallas, Reactor Construction & Engineering Branch 80/12/23 2pp 07489 308

0077 IE Insp Repts 50-445/80-26 & 50-446/80-26 on 801105-07, 18-20 & 24-25 No noncompliance noted Major areas inspected const activities including reactor vessel/instruments & instrumentation components & sys
SMAN, W. A., STEWART, R. C. Region 4, Dallas, Office of the Director 80/12/23 6pp 07489 310

19 Forwards IE Info Notice 80-43, "Failures of Continuous Water Monitor for Steam Discharge Vol at Dresden Unit 2" No response required
T.K.V. Region 4, Dallas, Office of the Director 80/12/08 7391 031

21 Requests documentation of maint records re preservice insp & of snubbers due to problems w/inoperable & partly installed snubbers. Preservice exam should be of snubbers listed in STB Tables J 7-4a & 3 7-4b
R.L. Assistant Director for Licensing 81/01/14 3pp

S Reportable occurrences LERs & related correspondence

B101205246 Interim deficiency rept re rfg deficiency of component supports associated w/auxiliary piping sys diesel generators. Initially reported ECG926 Evaluation will be completed by 810731
GARY, R. J. Texas Utilities Generating Co 81/01/12 1p 07487 091

B101206253 Interim deficiency rept re unauthorized field rods to Multi-Mark concrete anchor bolts. Initially reported 801601 Bolts have not been modified in unauthorized manner Follow-up rept will be submitted by 810417
GARY, R. J. Texas Utilities Generating Co 81/01/12 2pp 07487 089

DOCKET 50-447 GEISSA-238, GENERAL ELECTRIC CO

A Application/construction stage documents & correspondence

810190589 Grants 6-month extension to preliminary design approval. PDA-1 pending development & implementation of new extension guidelines
EISENHUT, D. G. Division of Licensing 80/12/31 3pp 07475 012

DOCKET 50-448 DOUGLAS POINT NUCLEAR STATION, UNIT 1

C Adjudicatory correspondence

B101090379 Response raising no objection to applicant B01224 motion to withdraw CP applications No determination made as to conditions of Withdrawal Certificate of Svc encl
BARTH, C. A. Hearing Branch 3 81/01/07 3pp 07422 240

B101206057 Order granting applicant B01224 motion to withdraw application for CPs w/o qualifying terms or conditions Certificate of Svc encl
BACHERS, E. S. Atomic Safety and Licensing Board Panel 81/01/14 4pp 07486 322

DOCKET 50-449 DOUGLAS POINT NUCLEAR STATION, UNIT 2

C Adjudicatory correspondence

B101090379 Response raising no objection to applicant B01224 motion to withdraw CP applications No determination made as to conditions of withdrawal Certificate of Svc encl
BARTH, C. A. Hearing Branch 3 81/01/07 3pp 07422 240

B101206057 Order granting applicant B01224 motion to withdraw application for CPs w/o qualifying terms or conditions Certificate of Svc encl
BACHERS, E. S. Atomic Safety and Licensing Board Panel 81/01/14 4pp 07486 322

DOCKET 50-452 GREENWOOD ENERGY CENTER, UNIT 2

A Application/construction stage documents & correspondence

B012100052 Addl response to FOIA request for nine categories of records re fees concerning withdrawn, suspended or postponed applications Forwards documents listed in App A
FELTON, J. H. Division of Rules and Records 80/11/21 3pp 07222 211

--8008050201 Amends 800627 memo re manpower costs for CP review Associated contractual costs are \$124,000
BERKOW, K. H. Management Analysis Branch 80/07/29 1p 03078 180

--B011240002 Submits CP review costs incurred by various program ofcs from filing of application to date of withdrawal
HULLOWAY, C. J. License Fee Management Branch 80/11/10 1p 03745 245

--B011240224 Requests billing of util for fees for review of CP application withdrawn on 800707 Ofc of Administration should be notified when total amount is collected
MILLER, W. D. License Fee Management Branch 80/11/10 1p 03745 334

--B012100135 Forwards IE cost data worksheets reflecting prof manhours expended & associated costs in reviewing CP application for facilities info encompasses 750101-800714
DOUGHERTY, L. J. Resource Management Branch 80/08/15 3pp

B01120143 Informs that 145.5 prof manhours were expended on joint CP review of facilities
MCKINNEY, R E - ACRS - Advisory Committee on Reactor Safeguards.
80/08/04 1p

--B012100151 Informs that prof manhours expended by ASLB re CP application have not been recorded Proceeding was contested
LAZO, R M Atomic Safety and Licensing Board Panel. 80/07/29 1p

--B012100165 Informs that no prof manhours were expended in connection w/ sua sponte review of CP application for facilities
ROSENTHAL, A S Atomic Safety and Licensing Appeal Panel
80/07/29 1p

DOCKET 90-453 GREENWUDD ENERGY CENTER, UNIT 3

A Application/construction stage documents & correspondence

B012100002 Addl response to FOIA request for nine categories of records re fees concerning withdrawn, suspended or postponed applications Forwards documents listed in App A
FELTCH, J M Division of Rules and Records 80/11/21 3pp
07222 211

--B008050201 Amends 000627 memo re manpower costs for CP review.
Associated contractual costs are \$124,000
BERKOW, H M Management Analysis Branch 80/07/29 1p
03078 180

--B011240002 Submits CP review costs incurred by various program ofcs from filing of application to date of withdrawal.
HOLLADAY, C J License Fee Management Branch 80/11/10 1p
03745 245

--B011240024 Requests billing of util for fees for review of CP application, withdrawn on 800709 Ofc of Administration should be notified when total amount is collected.
MILLER, M D License Fee Management Branch. 80/11/10 1p
03745 334

--B012100135 Forwards IE cost data worksheets reflecting prof manhours expended & associated costs in reviewing CP application for facilities info encompasses 750101-B00714
DO'NELLY, L J Resource Management Branch 80/08/15 3pp

--B012100143 Informs that 145.5 prof manhours were expended on joint CP review of facilities
MCKINNEY, R E - ACRS - Advisory Committee on Reactor Safeguards
80/08/04 1p

--B012100151 Informs that prof manhours expended by ASLB re CP application have not been recorded Proceeding was contested
LAZO, R M Atomic Safety and Licensing Board Panel 80/07/29 1p

--B012100165 Informs that no prof manhours were expended in connection w/ sua sponte review of CP application for facilities
ROSENTHAL, A S Atomic Safety and Licensing Appeal Panel
80/07/29 1p

DOCKET 90-454 BAYON STATION, UNIT 1

A Application/construction stage documents & correspondence

B01220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, 'Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports.'
EISENHUT, D O Division of Licensing 80/11/26 8pp

B011100002 Notification of caseload forecast panel B0104-08 meetings w/ util at sites to update NRC estimate of const completion date
MOJNA, C W Licensing Branch 1 80/12/24 3pp 07443 061.

B011130426 Requests addl info re OL applications for facilities
Specific requests in encl are ninth set of round one questions
TEDESCHI, R L Assistant Director for Licensing. 81/01/02 23pp.
07454 070

B011160543 Forwards request for addl info re first set of second round questions on OL application
TEDESCHI, R L Assistant Director for Licensing. 81/01/02 18pp.
07471 163.

B01220050 Forwards offsite dose calculation sys description per meteorological data requirements in NUREG-0737 Task 111 A 2
DELGE(RSE), D Commonwealth Edison Co 81/01/19 1p

--B01220374 "Offsite Dose Calculation Sys Meteorological Monitoring: Offsite Dose Calculation Program for Emergency Preparedness at Operating Nuclear Power Plants," Revision 2
GILBERT, J C Commonwealth Edison Co 80/07/31 130pp

--B01220379 "Study of Low Level Dispersion Over Northern IL."
Murray & Trettel, Inc 74/06/30 106pp

F Security, medical, emergency & fire protection plans

B01090039 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B01002 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

B01160572 Notifies that guard training & qualification plan, as revised by util B00811 ltr, is acceptable
YOUNGBLOOD, B J Licensing Branch 1 80/12/30 2pp 07471 205

0 Adjudicatory correspondence

B011130008 Memorandum & order admitting DeKalb Area Alliance for Responsible Energy & Mississippi Alliance for Environmental Contentions 1, 2, 2a, 3, 4, 6, 7, 8 & 9 & denying Contention 5
MILLER, M E Atomic Safety and Licensing Board Panel 80/12/14 3pp 07448 262.

--B01130019 Order admitting Rockford League of Women Voters Contentions 2, 5, 6-10, 14, 16, 17, 19, 20-63, 66-78, 80, 81, 83-90, 93, 97-100, 102-117, 119, 120, 122-126, 129, 134-137, 141-144 & 146 & denying other contentions Certificate of Svc encl
MILLER, M E, COLE, R F, CALLIHAN, D Atomic Safety and Licensing Board Panel 80/12/19 23pp 07448 265

B01200187 Advises that B01121 petition on behalf of Rockford League of Women Voters will be treated as request under 10CFR2, 206. Request (d) for halt of const is denied Public health & safety considerations not jeopardized
DEITHORN, W R Office of Nuclear Reactor Regulation, Director 80/12/22 3pp. 07487 098

--B01200191 Notice of Rockford League of Women Voters request for action under 10CFR2, 206 & 10CFR2 202
DEITHORN, W R Office of Nuclear Reactor Regulation, Director 80/12/22 1p. 07487 101

--B01200195 Discusses B01121 petition on behalf of Rockford League of Women Voters requesting proceeding per 10CFR2, 202 Offers assistance & suggestions in preparing response. Draft acknowledgment ltr encl
MURRAY, J P. Rulemaking & Enforcement Division. 80/12/02. 4 07487 102

B01050416 Renews Rockford League of Women Voters B01102 request immediate const shutdown Cites NRC B01222 refusal as illegal & grossly negligent Serves notice that if NRC does not reply by B01116, relief will be sought from courts.
CHERRY, M M Cherry, M M /Cherry, Flynn & Kanter 80/12/30 07380 188

B011160732 Order granting extension until B01031 for Commission consideration of Director's partial denial of Rockford League of Women Voters petition Certificate of Svc encl
CHILKIS, J Office of the Secretary of the Commission. 81/01/14 2pp 07472 061.

B01280047 Requests that Rockford Register Star newspaper be placed on svc list for facility proceeding Certificate of Svc encl.
MCRRIB, C E Affiliation Unknown. 81/01/14. 3pp. 07555 105.

B01270323 Forwards B01219 memorandum & order re admissibility of revised contentions filed by Intervenor League of Women Voters, Rockford League of Women Voters Contention 19 also encl. 11/0 encl
CHRISTENBURY, E Office of the Executive Legal Director. 81/01/14 1p 07546 073

DOCKETED ITEMS

P. Operating license stage documents & correspondence

B101090301 Forwards Revision 15 pages to CE-1-A, OA program topical report Revisions reflect Summer 1980 addenda to Section III of ASME code & recent ASME survey for renewal of ASME corporate certifications
AUEL, J. S. Commonwealth Edison Co. 81/01/02 1p

--B101090005 Revision 15 pages to OA program topical report
* Commonwealth Edison Co. CE-1-A R15 81/01/02 57pp.

Q. Inspection reports, IE Bulletins & correspondence

B101050247 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/10/30 2pp

B101050462 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/11/06 2pp.

B101050330 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Steam Discharge Vol at Dresden Unit 2." No response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/12/05 2pp

B101070105 Forwards IE Info Notice 80-44, "Actuation of ECCB in Recirculation Mode While in Hot Shutdown." No written response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/12/16 1p 07415 024

B101120567 Responds to B01114 ltr re IE Bulletin 80-23 No Valcor solenoid valves V70900-21-1 or V70900-21-3 are in use at LaSalle County Station Rept addressing affected valves at Byron & Braidwood Stations to be submitted by B10212
RAUSCH, T. J. Commonwealth Edison Co. 80/12/29 2pp 07454 033

B101190796 Confirms B10109 meeting to review insp findings re electrical const work at site
KEPPLER, J. G. Region 3, Chicago, Office of the Director 81/01/06 1p 07472, 289

B101200528 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." LaSalle County Station contains 139 safety-related valves cast by Malcolm & mfg by Anchor-Corning Valve Co. Valves will be replaced
RAUSCH, T. J. Commonwealth Edison Co. 81/01/06 2pp 07407 046

B101280613 Responds to IE Bulletin 80-16 re potential misapplication of Rosemount, Inc. pressure transmitters Rosemount Model 1152 transmitters used could not be exposed to input pressures resulting in anomalous output signals
RAUSCH, T. J. Commonwealth Edison Co. 81/01/08 2pp 07557 308

B101280636 Submits supplemental response to IE Bulletin 80-20 Addl use of Westinghouse Type W-2 spring return to neutral control switches identified. Initial response to bulletin unchanged. List of addl switches & applications encl
RAUSCH, T. J. Commonwealth Edison Co. 81/01/09 3pp 07557 305.

B101260698 Ack receipt of B01211 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-454/B0-09, 80-455/B0-08, 80-456/B0-04 & 80-457/B0-04
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 81/01/12 1p 07531 177

--B101260707 Responds to NRC B00711 ltr re violations noted in IE Insp Repts 80-454/B0-09, 80-455/B0-08, 80-456/B0-04 & 80-457/B0-04
Completion of supplier study & util technical assessment expected by B10215
ADEL, J. S. Commonwealth Edison Co. 80/12/11 1p 07531 178

B101270397 Immediate action ltr re B01231 & B10109 meetings held to discuss recent insp findings Util will discontinue installation of Class IE cables until listed QA/QC programmatic actions completed
KEPPLER, J. G. Region 3, Chicago, Office of the Director 81/01/13 2pp 07546 179

DOCKET 80-455 BYRON STATION UNIT 2

A. Application/construction stage documents & correspondence

B101201466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unproved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D. G. Division of Licensing 80/11/26 8pp

B101100007 Notification of caseload forecast panel B10106-08 reest L/0611 at sites to update NRC estimate of const completion date
MORAN, C. W. Licensing Branch 1 80/12/21 3pp 07443 051

B101130426 Requests addl info re OL applications for facilities. Specific requests in encl are ninth set of round and questions
TEDESCO, R. L. Assistant Director for Licensing 81/01/02 23p 07454 070

B101160513 Forwards request for addl info re first set of second questions on OL application
TEDESCO, R. L. Assistant Director for Licensing 81/01/02 19p 07471 163

B101220365 Forwards offsite dose calculation sys description per meteorological data requirements in NUREG-0737 Test 111 A.2
DELOERGER, L. D. Commonwealth Edison Co. 81/01/19 1p

--B101220374 "Offsite Dose Calculation Sys Meteorological Monitor: Offsite Dose Calculation Program for Emergency Preparedness at Operating Nuclear Power Plants." Revision 2
COLLEN, J. C. Commonwealth Edison Co. 80/07/31 130pp

--B101220379 "Study of Low Level Dispersion Over Northern Ill."
* Murray & Trettel, Inc. 74/06/30 106pp

F. Security, medical, emergency & fire protection plans

B101090587 Ltr to all licensees of operating reactor plants, CP lic & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 ltr by applicants as part of EAR
EISENHUT, D. G. Division of Licensing 80/11/13 2pp

B101160572 Notifies that guard training & qualification plan is acceptable by Util B00811 ltr. Is acceptable
YOUNGBLOOD, B. J. Licensing Branch 1 80/12/33 2pp 07471 20

G. Adjudicatory correspondence

B101130068 Memorandum & order admitting DeKalb Area Alliance for Responsible Energy & Mississippi Alliance for Environ B00509 Contentions 1, 2, 2a, 3, 4, 6, 7, B & 4 & denying Contention 5.
MILLER, M. E. Atomic Safety and Licensing Board Panel 80/12/13 3pp 07448 262.

--B101130019 Order admitting Rockford League of Women Voters Cont. 2, 5, 8-10, 14, 16, 17, 19, 20-63, 66-78, 80, 81, 83-90, 95, 97-100, 102-117, 119, 120, 122-126, 129, 134-137, 141-144 & 146 & denying other contentious Certificate of Gov encl.
MILLER, M. E., COLE, R. F., CALLIHAN, D. Atomic Safety and Licensing Board Panel 80/12/19 23pp 07448 265

B101200187 Advises that B01171 petition on behalf of Rockford League of Women Voters will be treated as request under 10CFR2.204 Request (d) for halt of const is denied Public health & safety considerations not jeopardized
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 80/12/22 3pp 07487 070

--B101200191 Notice of Rockford League of Women Voters request for action under 10CFR2.206 & 10CFR2.202
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 80/12/22 1p 07487 101.

--B101200195 Discusses B01121 petition on behalf of Rockford League of Women Voters requesting proceeding per 10CFR2.202 Offers assistance & suggestions in preparing response Draft

B10105041a Forwards Rockford League of Women Voters B01102 request for immediate const shutdown Cites NRC B01222 refusal as illegal & grossly negligent. Jerves notice that if NRC does not reply by B1011a, relief will be sought from courts
CHERRY, M. M. Cherry, M. R. Cherry, Flynn & Manter B01/12/30 3pp
07380 168

B101150732 Order granting extension until B10131 for Commission consideration of Director's partial denial of Rockford League of Women Voters petition Certificate of Svc encl
CHILK, G. J. Office of the Secretary of the Commission B1/01/14
2pp 07472 051

B101283947 Requests that Rockford Register Star newspaper be placed on sus list for facility preceding Certificate of Svc encl
MCRAIB, C. E. Affiliation Unknown B1/01/14 3pp 07559 105

B101274923 Forwards B01215 memorandum to order re admissibility of revised contentions filed by Intervenor League of Women Voters Rockford League of Women Voters Contention 19 also encl 1/1a encl
CHRISTENSEN, R. E. Office of the Executive Legal Director B1/01/22
1p 07546 073

F. Operating license stage documents & correspondence

B101040001 Forwards Revision 15 pages to CE-1-A.0A program topical rept Revisions reflect Summer 1980 addenda to Section III of ASME code & recent ASME survey for renewal of ASME corporate certifications
AUEL, J. S. Commonwealth Edison Co B1/01/02 1p

--B101090005 Revision 15 pages to QA program topical rept
Commonwealth Edison Co CE-1-A R15 B1/01/02 57pp

G. Inspection reports, IE Bulletins & correspondence

B101050247 Forwards IE Info Notice B0-26, "Cracking in Charging Pump Casing Cladding." No response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director B01/02/30
2pp

B101050462 Forwards IE Bulletin B0-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director B01/11/06
2pp

B101050530 Forwards IE Info Notice B0-43, "Failures of Continuous Water Level Monitor for Steam Discharge Vals at Dresden Unit 2." No response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director B01/12/05
2pp

B101070105 Forwards IE Info Notice B0-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown." No written response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director B01/12/16
1p

B101170667 Responds to B01114 ltr re IE Bulletin B0-23 No Valcor solenoid valves V70900-21-1 or V70900-21-3 are in use at LaSalle County Station Repl addressing affected valves at Byron & Braidwood Stations to be submitted by B10212
RAUSCH, T. J. Commonwealth Edison Co B01/12/29 2pp

B101150796 Confirms B10109 meeting to review insp findings re electrical const work at site
KEPPLER, J. G. Region 3, Chicago, Office of the Director B1/01/06
1p 07472 285

B101050528 Responds to IE Bulletin B0-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." LaSalle County Station contains 133 safety-related valves cast by Malcolm & mfg by Anchor-Burling Valve Co. Valves will be replaced
RAUSCH, T. J. Commonwealth Edison Co B1/01/06 2pp

B101280513 Responds to IE Bulletin B0-16 re potential misapplication of Rosemount, Inc pressure transmitters Rosemount Model 1152 transmitters used could not be exposed to input pressures resulting in anomalous output signals
RAUSCH, T. J. Commonwealth Edison Co B1/01/08 2pp 07557 308

B101280636 Submits supplemental response to IE Bulletin B0-20 Addl use of Westinghouse Type W-2 spring return to neutral control switches identified. Initial response to bulletin unchanged. List of addl switches & applications encl
RAUSCH, T. J. Commonwealth Edison Co B1/01/09 3pp 07557 305

B101274923 Receipt of B01211 ltr informing NRC of steps taken to correct violations noted in IE Repts B0-454/B0-09, B0-455/B0-09, B0-456/B0-04 & B0-457/B0-04
FIORELLI, J. Region 3, Chicago, Reactor Construction & Engineering Support Branch B1/01/12 1p 07531 177

--B101260707 Responds to NRC B00711 ltr re violations noted in IE Repts B0-454/B0-09, B0-455/B0-09, B0-456/B0-04 & B0-457/B0-04
Completion of supplier study & util technical assessment expected by B10215
AUEL, J. S. Commonwealth Edison Co B01/12/11 1p 07531 170

B101270177 Immediate action ltr re B101231 & B10109 meetings held to discuss recent insp findings Util will discontinue installation of Class IE cables until listed QA/QC programmatic actions completed
KEPPLER, J. G. Region 3, Chicago, Office of the Director B1/01/14
2pp 07516 179

SECRET B0-456 BRAIDWOOD STATION, UNIT 1

A. Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwards summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D. O. Division of Licensing B01/11/26 3pp

B101100007 Notification of calendar forecast panel B10106-08 meeting w/util at sites to update NRC estimate of const completion date
ROUCH, C. W. Licensing Branch 1 B01/12/24 3pp 07443 061

B101130426 Requests addl info re CL applications for facilities. Specific requests in encl are ninth set of round one questions
TEFFESCU, R. L. Assistant Director for Licensing B1/01/02 23pp
07494 070

B101160543 Forwards request for addl info re first set of second round questions on CL application
TEFFESCU, R. L. Assistant Director for Licensing B1/01/02 18pp
07471 163

B101220368 Forwards offsite dose calculation sys description per meteorological data requirements in NUREG-0737 Task III A 2
OELGECROE, L. Q. Commonwealth Edison Co B1/01/19 1p

--B101220374 "Offsite Dose Calculation Sys Meteorological Monitoring Offsite Dose Calculation Program for Emergency Preparedness at Operating Nuclear Power Plants." Revision 2
OULDER, J. C. Commonwealth Edison Co B01/07/31 130pp

--B101220379 "Study of Low Level Dispersion Over Northern IL."
Murray & Bretzel, Inc 74/05/30 106pp

F. Security, medical, emergency & fire protection plans

B101070387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D. O. Division of Licensing B01/11/13 2pp

B101200029 Notifies that guard training & qualification program reqd by licensee B00811 ltr is acceptable
YOUNGBLOOD, J. J. Licensing Branch 1 B01/12/30 2pp 07486 193

F. Operating license stage documents & correspondence

B101090001 Forwards Revision 15 pages to CE-1-A.0A program topical rept Revisions reflect Summer 1980 addenda to Section III of ASME code & recent ASME survey for renewal of ASME corporate certifications
AUEL, J. S. Commonwealth Edison Co B1/01/02 1p

--B101090005 Revision 15 pages to QA program topical rept
Commonwealth Edison Co CE-1-A R15 B1/01/02 57pp

G. Inspection reports, IE Bulletins & correspondence

B101050247 Forwards IE Info Notice B0-38, "Cracking in Charging Pump Casing Cladding." No response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director B01/10/29
2pp

Forwards IE Bulletin 80-21. "Valve Yokes Supplied by Malcolm Co. Inc." Written response required
J G Region 3. Chicago. Office of the Director 80/11/06

Forwards IE Info Notice 80-43. "Failures of Continuous Water Monitor for Steam Discharge Val at Dresden Unit 2" No response required
J G Region 3. Chicago. Office of the Director 80/12/09

Forwards IE Info Notice 80-44. "Actuation of ECCS in Recirculation Mode While in Hot Shutdown" No written response required
J G Region 3. Chicago. Office of the Director 80/12/16

Ack receipt of 801204 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-456/80-12 & 80-457/80-11
J G Region 3. Chicago. Reactor Construction & Engineering Branch 80/12/29 2pp 07443 303

01 Responds to NRC 801023 ltr re violations noted in IE Insp Repts 80-456/80-12 & 80-457/80-11 Corrective actions w/open ends sealed & surveillance performed
S Commonwealth Edison Co 80/12/04 3pp 07443 305

Responds to 801114 ltr re IE Bulletin 80-23 No Valcor valves V70900-21-1 or V70900-21-3 are in use at County Station Rept addressing affected valves at Braided Stations to be submitted by 810212
J Commonwealth Edison Co 80/12/29 2pp

Responds to IE Bulletin 80-21. "Valve Yokes Supplied by Country Co. Inc." LaSalle County Station contains 138 related valves cast by Malcolm & mfg by Anchor-Valve Co Valves will be replaced
J Commonwealth Edison Co 81/01/06 2pp

Responds to IE Bulletin 80-16 re potential misapplication of Rosemount, Inc pressure transmitters Rosemount Model 1152 trans used could not be exposed to input pressures resulting in anomalous output signals
J Commonwealth Edison Co 81/01/08 2pp 07557 308

Submits supplemental response to IE Bulletin 80-20 Addl use of pressure Type H-2 spring return to neutral control identified. Initial response to bulletin unchanged addl switches & applications uncl
J Commonwealth Edison Co 81/01/09 3pp 07557 305

Ack receipt of 801211 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-454/80-09, 80-456/80-04 & 80-457/80-04
J G Region 3. Chicago. Reactor Construction & Engineering Branch 81/01/12 1p 07531 177

07 Responds to NRC 800711 ltr re violations noted in IE Insp Repts 80-454/80-09, 80-456/80-04, 80-457/80-11 Corrective actions w/open ends sealed & surveillance performed
S Commonwealth Edison Co 80/12/11 1p 07531 178

457 BRAIDWOOD STATION. UNIT 2

Construction stage documents & correspondence

Ltr to all power reactor licensees & applicants forwarding of 801112 meeting re implementation of guidance for Safety Issue A-12. "Potential for Low Fracture & Lamellar Tearing on Component Supports"
J D O. Division of Licensing 80/11/26 8pp

Notification of scheduled forecast panel 810106-CB meeting at sites to update NRC estimate of const completion
Licensing Branch 1 80/12/24 3pp.

Requests addl info re CL applications for facilities requests in encl are ninth set of round one
R L. Assistant Director for Licensing 81/01/02 27pp

Forwards request for addl info re first set of second round of an CL application
R L. Assistant Director for Licensing. 81/01/02 18pp

010120069 Forwards Offsite dose calculation sys description per meteorological data requirements in NUREG-0737 Tag 111 A 2
DELSECELEL D Commonwealth Edison Co 81/01/19 1p

8101200374 Offsite Dose Calculation Sys Meteorological Monitoring. Offsite Dose Calculation Program for Emergency Preparedness at Operating Nuclear Power Plants. Revision 2
COLLEH J C Commonwealth Edison Co 80/07/31 130pp

8101200379 "Study of Low Level Dispersion Over Northern IL"
* Murray & Tackett, Inc 77/05/30 106pp

S Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants CF holders & CF applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 3 by applicants as part of FSAR
EISENHUT D G Division of Licensing 80/11/13 2pp

8101200029 Notifies that joint training & qualification program revised by licensee 800811 ltr is acceptable
YOUNGELWOOD J J Licensing Branch 1 80/12/30 2pp 07484 153

P Operating license stage documents & correspondence

8101070001 Forwards Transmittal 15 pages to CE-1-A-04 program topical report Revisions reflect Summer 1980 addenda to Section III of ASME Code & recent ASME survey for renewal of ASME corporate certifications
ASCEL J S Commonwealth Edison Co 81/01/02 1p

8101090005 Revision 15 pages to QA program topical rept
* Commonwealth Edison Co CE-1-A R15 81/01/02 57pp

Q Inspection reports, IE Bulletins & correspondence

8101050249 Forwards IE Info Notice 80-58. "Cracking in Charging Pump Casing Cladding" No response required
MEPPLER J G Region 3. Chicago. Office of the Director 80/10/30 2pp

8101050463 Forwards IE Bulletin 80-21. "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required
MEPPLER J G Region 3. Chicago. Office of the Director 80/11/06 2pp

8101050536 Forwards IE Info Notice 80-43. "Failures of Continuous Water Level Monitor for Steam Discharge Val at Dresden Unit 2" No response required
MEPPLER J G Region 3. Chicago. Office of the Director 80/12/05 2pp

8101070105 Forwards IE Info Notice 80-44. "Actuation of ECCS in Recirculation Mode While in Hot Shutdown" No written response required
MEPPLER J G Region 3. Chicago. Office of the Director 80/12/16 1p

8101100294 Ack receipt of 801204 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-456/80-12 & 80-457/80-11
FICRELLI J G Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/12/29 2pp 07443 303

8101100301 Responds to NRC 801023 ltr re violations noted in IE Insp Repts 80-456/80-12 & 80-457/80-11 Corrective actions w/open ends sealed & surveillance performed
ASCEL J S Commonwealth Edison Co 80/12/04 3pp 07443 305

8101130657 Responds to 801114 ltr re IE Bulletin 80-23 No Valcor solenoid valves V70700-21-1 or V70900-21-3 are in use at LaSalle County Station Rept addressing affected valves at Byron & Braidwood Stations to be submitted by 810212
RAUSCH T J Commonwealth Edison Co 80/12/29 2pp

8101200536 Responds to IE Bulletin 80-21. "Valve Yokes Supplied by Malcolm Foundry Co. Inc." LaSalle County Station contains 138 safety-related valves cast by Malcolm & mfg by Anchor-Valve Co Valves will be replaced
RAUSCH T J Commonwealth Edison Co 81/01/06 2pp

8101280613 Responds to IE Bulletin 80-16 re potential misapplication of Rosemount, Inc pressure transmitters Rosemount Model 1152 transmitters used could not be exposed to input pressures resulting in anomalous output signals
RAUSCH T J Commonwealth Edison Co 81/01/08 2pp

B01010577 Submits supplemental response to IE Bulletin B0-20 Add use of Westinghouse Type W-2 spring return to neutral control switches identified. Initial response to bulletin unchanged. List of add'l switches & applications encl.
BRAPER,E L Gulf States Utilities Co 8/10/79 3pp.

B01026098 Ack receipt of B01211 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/80-09, 50-455/80-09, 50-456/80-04 & 50-457/80-04
FICHELLE,W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 8/10/79 1p

--B01026097 Responds to NRC B00711 ltr re violations noted in IE Insp Repts 50-454/80-09, 50-455/80-09, 50-456/80-04 & 50-457/80-04. Completion of supplier study & util technical assessment expected by B00215
ADEL,J E Commonwealth Edison Co 8/12/79 1p

DOCKET 50-459 RIVER BEND STATION, UNIT 1

A Application/construction stage documents & correspondence

B01020466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports"
EISENHUT,D G Division of Licensing 8/11/76 8pp

B01027187 Advises that no new items have been discovered which would require IEEE-323 environ qualification testing, per B01205 ltr
BRAPER,E L Gulf States Utilities Co 8/10/79 1p 07548 092.

F Security, medical, emergency & fire protection plans

B010109087 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B01102 & by applicants as part of FSAR
EISENHUT,D G Division of Licensing 8/11/76 2pp

B010140437 Forwards facility emergency planning info to be made publicly available W/o encl
SOUDER,J L Division of Rules and Records 8/12/76 1p 07461 335

I Financial information

B01020447 Forwards loan commitment agreement which includes conditions required for funds loaned by REA, per B01003 ltr
BRAPER,E L Gulf States Utilities Co 8/10/79 18pp 07183 001

G Inspection reports, IE Bulletins & correspondence

B010210670 Responds to IE Bulletin B0-16, "Potential Misapplication of Rosemount, Inc Models 1151 & 1152 Pressure Transmitters W/ Either A or D Output Codes." Final response scheduled for B01124, pending investigation by vendor
BRAPER,E L Gulf States Utilities Co 8/11/79 1P, 07488 244

B0101089301 Forwards IE Investigation Rept 50-458/80-15 on B01029-31
SEYFRIT,K V Region 4, Dallas, Office of the Director. 8/11/78 2pp 07421 313

--B0101089307 IE Investigation Rept 50-458/80-11 on B01029-31 No noncompliances noted. Major areas discussed. B01021 allegation that upper mgt engineering supervisors lowered quality of work by creating difficult engineering schedules
SEYFRIT,K V Region 4, Dallas, Office of the Director
MARTIN,L Region 4, Dallas, Reactor Construction & Engineering Support Branch 8/11/77 11pp 07421 315

B010210672 Submits supplemental response to IE Bulletin B0-16, "Potential Misapplication of Rosemount, Inc Models 1151 & 1152 Pressure Transmitters W/ Either A or D Output Codes." OE will perform design review during First Quarter 1981.
BRAPER,E L Gulf States Utilities Co 8/12/79 2pp, 07468 245.

B010100162 Ack receipt of B00710 & 1103 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-450/80-07
FICHELLE,W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 8/12/79 1p 07443 002

B01010717 Responds to NRC B01003 ltr re violations noted in IE Insp Rept 50-458/80-07 lists for weather requirements to be imposed. Completion testing will be performed on all Category 1 concrete placements w/ compliance
BRAPER,E L Gulf States Utilities Co 8/11/79 3pp 07443 003

B01020617 Forwards IE Info Notice B0-43, "Failures of Continuous Water Level Monitor for Steam Discharge Vals at Dresden Unit 2." No response required
SEYFRIT,K V Region 4, Dallas, Office of the Director 8/12/78 1p 07591 046

B010210045 Forwards IE Insp Rept 50-458/80-12 on B01118-21 & notice of violation
FICHELLE,W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 8/12/78 2pp 07489 301

--B010210058 Notice of violation from Insp on B01118-21
* Region 4, Dallas, Reactor Construction & Engineering Support Branch 8/12/78 2pp 07489 303

--B010210075 IE Insp Rept 50-450/80-12 on B01118-21 Noncompliance note insufficient lighting of concrete placement & water/cement ratio exceeded max allowable
TAPIA,J J, HALL,R E Region 4, Dallas, Reactor Construction & Engineering Support Branch, CRUSMAN,W A Region 4, Dallas, Office of the Director 8/12/79 3pp 07489 305

B010130388 Forwards IE Info Notice B0-45, "Potential Failure of BWR Backup Manual Steam Capability." No response required
SEYFRIT,K V Region 4, Dallas, Office of the Director 8/12/79 1p 07452 090

B010130387 Forwards IE Bulletin B0-29, "Operating Problems W/Target Rock Safety-Relief Valves at BWRs." No response required
SEYFRIT,K V Region 4, Dallas, Office of the Director 8/12/79 1p 07449 139

E Reportable occurrences, IERs & related correspondence

B0101090204 PRC-IV-80-41 on B01230, util QA manager notified Region 4 that stop work order had been issued on Category 1 work. Order resulted from discovery that incoming drawings had not been processed by document control since B01106
JEACH,A D, HALL,R E Region 4, Dallas, Office of the Director 8/12/79 1p 07442 272

DOCKET 50-459 RIVER BEND STATION, UNIT 2

A Application/construction stage documents & correspondence

B01020466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports"
EISENHUT,D G Division of Licensing 8/11/76 8pp

B010270667 Advises that no new items have been discovered which would require IEEE-323 environ qualification testing, per B01205 ltr
BRAPER,E L Gulf States Utilities Co 8/10/79 1p, 07548 092

F Security, medical, emergency & fire protection plans

B010109087 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B01102 & by applicants as part of FSAR
EISENHUT,D G Division of Licensing 8/11/76 2pp

B010140437 Forwards facility emergency planning info to be made publicly available W/o encl
SOUDER,J L Division of Rules and Records 8/12/76 1p 07461 335

G Inspection reports, IE Bulletins & correspondence

B010210670 Responds to IE Bulletin B0-16, "Potential Misapplication of Rosemount, Inc Models 1151 & 1152 Pressure Transmitters W/ Either A or D Output Codes." Final response scheduled for B01124, pending investigation by vendor
BRAPER,E L Gulf States Utilities Co 8/11/79 1P, 07488 244

B010210672 Submits supplemental response to IE Bulletin B0-16, "Potential Misapplication of Rosemount, Inc Models 1151 & 1152 Pressure Transmitters W/ Either A or D Output Codes." OE will perform design review during First Quarter 1981.
BRAPER,E L Gulf States Utilities Co 8/12/79 2pp 07488 245

B010552617 Forwards IE Info Notice B0-40. "Failures of Continuous Water Level Monitor for Steam Discharge Vol at Dresden Unit 2 " No response required
SEYFRIT, K V Region 4, Dallas, Office of the Director B0/12/08
1p 07391 046

B01030388 Forwards IE Info Notice B0-40. "Potential Failure of BWR Start Manual Steam Capability " No response required
SEYFRIT, K V Region 4, Dallas, Office of the Director B0/12/17
1p 07452 070

B010130087 Forwards IE Bulletin B0-25. "Operating Problems W/Target Rod Safety-Relief Valves at BWRs " No response required
SEYFRIT, K V Region 4, Dallas, Office of the Director B0/12/19
1p 07449 139

S Reportable occurrences, LERs & related correspondence

B010905204 PNO-IV-B0-41 on B01270, until QA manager notified Region 4 that stop work order had been issued on Category 1 Work Order resulted from discovery that incoming drawings had not been processed by document control since B01106
BEACON, A B, HALL, R E Region 4, Dallas, Office of the Director B0/12/31 1p 07442 272

SECRET 50-460 WPPSS NUCLEAR PROJECT, UNIT 1

A Application/construction stage documents & correspondence

B010220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports "
EISENHUT, D G Division of Licensing B0/11/26 8pp

F Security, medical, emergency & fire protection plans

B010906387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B01002 & by applicants as part of FSAK
EISENHUT, D G Division of Licensing B0/11/13 2pp

Q Inspection reports, IE Bulletins & correspondence

B01060085 Forwards supplemental response to IE Bulletin 79-02. Revision 2. "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts "
MAZUR, D W Washington Public Power Supply System B0/11/13 3pp 07399 119

B010505810 Forwards IE Info Notice B0-40. "Failures of Continuous Water Level Monitor for Steam Discharge Vol at Dresden Unit 2 " No response required
ENGELKEN, R H Region 5, San Francisco, Office of the Director B0/12/05 1p 07390 277

B01050837 Forwards IE Info Notice B0-44. "Actuation of ECCS in Recirculation Mode While in Hot Shutdown " No response required
ENGELKEN, R H Region 5, San Francisco, Office of the Director B0/12/16 1p 07308 001

B010300583 Ack receipt of B01212 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-460/B0-13 & 50-513/B0-13
SPENCER, G S Region 5, San Francisco, Reactor Construction & Engineering Support Branch B1/01/26 1p 07586 041

--B010300588 Responds to NRC B01121 ltr re violations noted in IE Insp Repts 50-460/B0-13 & 50-513/B0-13 Corrective actions QA personnel will provide procurement controls for staff substitutions
MAZUR, D W Washington Public Power Supply System B0/12/12 4pp 07586 042

--B010300573 Forwards IE Insp Repts 50-460/B0-13 & 50-513/B0-13 on B01020-23 & notice of violation
SPENCER, G S Region 5, San Francisco, Reactor Construction & Engineering Support Branch B0/11/21 2pp 07586 046

--B010300578 Notice of violation from insp on B01020-23
* Region 5, San Francisco, Office of the Director B0/11/21 1p 07585 048

B010552617 IE Insp Repts 50-460/B0-13 & 50-513/B0-13 on B01020-23 Noncompliance with failure to provide adequate procurement controls for parts to be used within containment
HAYES, R C, HENDERSON, F, KASLOUT, P P Region 5, San Francisco, Office of the Director B0/11/21 10pp 07506 049

S Reportable occurrences, LERs & related correspondence

B010200230 Part 21 report re failure to provide proper Control Component inlet valves supplying 2" gas flow when in closed position
Caused by valve failure Affected licensees notified & selection of alternative method under way
HAYES, R C, HENDERSON, F, KASLOUT, P P B1/01/07 2pp 07399 001

SECRET 50-461 CLINTON POWER STATION, UNIT 1

A Application/construction stage documents & correspondence

B01020466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports "
EISENHUT, D G Division of Licensing B0/11/26 8pp

B01060059 Forwards preliminary CL review schedule for facility Requests identification of branch reviewers & contact & mailing address of contracted technical assistance
TEDESCO, R L Assistant Director for Licensing B0/12/16 3pp 07399 123

B010100016 Inform of licensing milestones for facility & staffing arrangements for project Preliminary review schedule encl
TEDESCO, R L Assistant Director for Licensing B0/12/16 3pp 07445 155

B010100019 Requests performance of ultimate reactivity analysis of MTR III containment as part of generic review of effects of hydrogen evolving from postulated accident Analysis procedure encl
TEDESCO, R L Assistant Director for Licensing B0/12/19 3pp 07445 196

B010100505 Ltr to all BWR applicants for CL re BWR steam discharge safety evaluation & requirements Rept specifying acceptable basis for continued BWR plant operation & design criteria for steam discharge vol encl
TEDESCO, R L Assistant Director for Licensing B0/12/22 2pp

--B010100514 Forwards generic safety evaluation re BWR steam discharge safety Review identified (unaid) requirements to those proposed by owners group re steam discharge vol designs Rept should be transmitted to license applicants
CHECK, P S Assistant Director for Plant Systems B0/12/01 2pp 07183 001

B01090631 Requests acceleration of NRC licensing process re facility Review of R. Tedesco B01216 ltr re preliminary review schedule indicates that many activities are scheduled later than prudent for anticipated fuel loading & startup
KOCHE, J D Illinois Power Co B1/01/05 2pp 07442 062

F Security, medical, emergency & fire protection plans

B010906387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B01002 & by applicants as part of FSAK
EISENHUT, D G Division of Licensing B0/11/13 2pp

G Adjudicatory correspondence

B010230172 Forwards Prairie Alliance suppl to petition for leave to intervene & request for hearing
SAWELSON, A Prairie Alliance B1/01/14 1p 07187 001

--B010230178 Suppl to petition for leave to intervene & request for hearing Certificate of svc encl
SAWELSON, A Prairie Alliance B1/01/14 10pp 07187 001

B01020057 Notice of filing of encl applicant answer to Prairie Alliance suppl to petition for leave to intervene & request for hearing W/notice of appearance
FAZIO, P V Illinois Power Co FAZIO, P V Schiff, Hardin & Waite B1/01/26 2pp 07567 202

801060730 Forwards: Lapsing Prairie Alliance supply to petition for leave to intervene. Request for hearing. Suppl fails to present reportable contentions of core defects in original filing. Certificate of Service notices of appearance and
KLEIN, D. Illinois Power Co. 8/10/26 2pp 0795/204

3 Inspection reports, IE Bulletins & correspondence

801060547 Forwards: IE Circular 80-23, "Potential Defects in Beloit Press Sys Emergency Generators." No written response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/10/31 1p 07406 081

801060551 Forwards: IE Info Notice 80-29, "Malfunction of Solenoid Valves." Hg by Valcor Engineering Corp. No written response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/10/31 1p 07406 147

801060710 Forwards: IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Written response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/11/06 2pp 07400 135

801060613 Forwards: IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety-Relief Valve Operation to Cause Reactor Degassification." No written response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/11/07 2pp 07400 140

801060275 Forwards: IE Info Notice 80-41, "Failure of Swing Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1." No response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/11/10 2pp 07391 073

801060382 Forwards: IE Insp Rept 50-461/80-23 on 801001-1101 & notice of violation
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/11/12 2pp 07444 153

--801060189 Notice of violation from Insp on 801001-1101
Region 3, Chicago, Office of the Director 80/11/10 1p 07444 155

--801060197 IE Insp Rept 50-461/80-23 on 801001-1101 Noncompliance noted: rigging restraints attached to fuel transfer tube & carbon steel contact made w/stainless steel surfaces of transfer tubes
LIVENHORN, H. H. KNOX, R. C. Region 3, Chicago, Office of the Director 80/11/10 10pp 07444 156

801060527 Forwards: IE Bulletin 80-23, "Failures of Solenoid Valves Hg by Valcor Engineering Corp." Written response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/11/14 2pp 07391 247

801060367 Ack receipt of 801112 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-461/80-19
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/11/25 1p 07425 345

801060135 Forwards: IE Insp Rept 50-461/80-24 on 80105-07 No noncompliance noted
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/11/28 2pp 07460 343

--801060151 IE Insp Rept 50-461/80-24 on 80105-07 No noncompliance noted: Major areas inspected: electrical conduit work activities & electrical conduit work activities
LEE, R. L. GARDNER, H. A. Region 3, Chicago, Office of the Director 80/11/28 7pp 07460 345

801060544 Forwards: IE Info Notice 80-40, "Failures of Continuous Water Level Monitor for Steam Discharge Vessel at Dresden Unit 2." No response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/12/05 2pp 07399 297

801060766 Forwards: IE Insp Rept 50-461/80-26 on 80103-26 No noncompliance noted
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/09 2pp 07461 003

801060772 IE Insp Rept 50-461/80-26 on 80103-26 No noncompliance noted: Major areas inspected: safety-related const activities, main laydown & storage areas & fire protection/prevention
LIVENHORN, H. H. KNOX, R. C. Region 3, Chicago, Office of the Director 80/12/05 8pp 07461 005

801060721 Ack receipt of 801112 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-461/80-21
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/11 1p 07400 296

--801060731 Responds to NRC 801023 ltr re violations noted in IE Insp Rept 50-461/80-21 Corrective actions: ultrasonic instrument recalled & added to reactor core isolation recall cycle log
KEPPLER, J. G. Illinois Power Co. 80/11/24 2pp 07400 297

801060763 Responds to IE Bulletin 80-23, "Failures of Solenoid Valves Hg by Valcor Engineering Corp." Specified valves will not be installed at facility
KEPPLER, J. G. Illinois Power Co. 80/12/12 1p 07414 292

801060282 Forwards: IE Insp Rept 50-461/80-25 on 801119-21 No noncompliance noted
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/12 2pp 07489 316

--801060956 IE Insp Rept 50-461/80-25 on 801119-21 No noncompliance noted: Major areas inspected: containment dome lifting & attaching procedures & observation of fitup for primary coolant inlet piping
DAWIELSCHI, D. H. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/12 4pp 07469 310

801060554 Forwards: IE Info Notice 80-49, "Potential Failure of Backup Manual Scram Capability." No written response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/11/10 2pp 07420 321

801060218 Forwards: Suppl 4 to IE Bulletin 80-17, "Failure of Coils to Insert During Scram at BWR." No written response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/11/10 2pp 07465 335

801060156 Forwards: IE Bulletin 80-25, "Operating Problems W/Ear Rock Safety Relief Valves at BWRs." No response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/11/10 2pp 07377 317

801060602 Ack receipt of 801219 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-461/80-23
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 81/01/07 1p 07465 240

--801060606 Responds to NRC 801112 ltr re violations noted in IE Insp Rept 50-461/80-23 Corrective actions: personnel trained re restrictions of Baldwin Associates's rigging hoisting & handling procedure
KOCHEL, J. Illinois Power Co. 80/12/19 1p 07465 241

801060600 Responds to IE Bulletin 80-21 re Malcolm Foundry Co. valve failures. Investigations remain uncompleted. Complete response expected by 810228
KEPPLER, J. G. Illinois Power Co. 81/01/08 1p 07550 212

5 Reportable occurrences, LERs & related correspondence

801070144 Final deficiency rept originally reported on 800620.0 thin-walled elbow discovered in reactor pressure vessel drain line. Defective elbow replaced. Drain line elbows extensively investigated. Manufacturer to inspect elbows
KOCHEL, J. Illinois Power Co. 80/12/31 3pp 07413 203

DOCKET 50-462 CLINTON POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

801022046 Ltr to all power reactor licensees & applicants for summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lateral Tearing on Component Supports."
CISELMUT, D. G. Division of Licensing 80/11/26 8pp

Forwards preliminary DL review schedule for facility identification of branch reviewers & contact & address of contracted technical assistance
R L Assistant Director for Licensing 80/12/16 3pp
23.

Infers of licensing milestones for facility & staffing elements for project Preliminary review schedule encl
R L Assistant Director for Licensing 80/12/16 3pp
25

Requests performance of ultimate capacity analysis of Markainment as part of generic review of effects of evolving from postulated accident Analysis
e oncl
R L Assistant Director for Licensing 80/12/19 3pp
28

Requests acceleration of NRC licensing process re Facility of RL Tedesco 801216 ltr re preliminary review
indicates that many activities are scheduled later
udent for anticipated fuel loading & startup
J Illinois Power Co 81/01/05 2pp 07442.062

Medical, emergency & fire protection plans

Ltr to all licensees of operating reactor plants. CP holders
licants Revised radiological emergency response
st be submitted by licensees within 60 days of
y by applicants as part of FSAH
D O Division of Licensing 80/11/13 2pp

atory correspondence

Forwards Prairie Alliance suppl to petition for leave to
e & request for hearing
A Prairie Alliance 81/01/14 1p 07187.001

78 Suppl to petition for leave to intervene & request for
Certificate of Svc encl
CH A Prairie Alliance 81/01/14 10pp 07187.001

7 Notice of filing of encl applicant answer to Prairie
y suppl to petition for leave to intervene & request
ing U/notices of appearance
U Illinois Power Co FA210.P V Schiff, Hardin & Waite
5 2pp 07567.202

069 Answer opposing Prairie Alliance suppl to petition for leave
ervene & request for hearing Suppl fails to present
fiable contention or cure defects in original filing
ficate of Svc & notices of appearance encl.
D Illinois Power Co 81/01/26 25pp 07567.204.

tion reports. IE Bulletins & correspondence

7 Forwards IE Circular 80-23. "Potential Defects in Detroit
s Emergency Generators " No written response
J Q Region 3, Chicago, Office of the Director 80/10/31.
398.081

4 Forwards IE Info Notice 80-39. "Malfunction of Solenoid
Mfg by Valcor Engineering Corp " No written response
red.
J Q Region 3, Chicago, Office of the Director 80/10/31
401.140

0 Forwards IE Bulletin 80-21. "Valve Yokes Supplied by
Foundry Co. Inc " Written response required.
J Q Region 3, Chicago, Office of the Director 80/11/06
7400.135.

3 Forwards IE Info Notice 80-40. "Excessive Nitrogen Supply
e Actuates Safety-Relief Valve Operation to Cause
Depressurization " No written response required.
J Q Region 3, Chicago, Office of the Director 80/11/07
7400.148

5 Forwards IE Info Notice 80-41. "Failure of Swing Check
n Decay Heat Removal Sys at Davis Besse Unit 1 " No
e required
J Q Region 3, Chicago, Office of the Director 80/11/10
7391.073.

810105054H Forwards IE Info Notice 80-43. "Failures of Continuous Water
Level Monitor for Steam Discharge Vnl at Dresden Unit 2 " No
response required
NEPPLER, J Q Region 3, Chicago, Office of the Director 80/12/05
2pp 07390.257

8101070213 Responds to IE Bulletin 80-23. "Failures of Solenoid Valves
Mfg by Valcor Engineering Corp " Specified valves will not
be installed at facility
WULLER, G E Illinois Power Co 80/12/12 1p 07314.292

8101060594 Forwards IE Info Notice 80-45. "Potential Failure of BUR
Jarvis Manual Screen Capability " No written response
required
NEPPLER, J Q Region 3, Chicago, Office of the Director 80/12/17
2pp 07423.321

8101150210 Forwards Suppl 4 to IE Bulletin 80-17. "Failure of Control
Rods to Insert During Scram at BWR " No written response
required
NEPPLER, J Q Region 3, Chicago, Office of the Director 80/12/18
2pp 07465.335

8101050196 Forwards IE Bulletin 80-25. "Operating Problems w/Target
Ruck Safety Relief Valves at 3URs " No response required
NEPPLER, J Q Region 3, Chicago, Office of the Director 80/12/19
2pp 07377.337

8101280620 Responds to IE Bulletin 80-21 re Malcolm Foundry Co valve
yoke failures Investigations remain uncompleted Complete
response expected by 810220
WULLER, G E Illinois Power Co 81/01/08 1p 07550.212

DOCKET 50-463 FULTON GENERATING STATION, UNIT 1

G Adjudicatory correspondence

8101270315 Reply supporting applicant earlier motion to withdraw CP
application w/o prejudice Opposes intervenor York Committee
for Safe Environ response supporting withdrawal of
application w/prejudice Certificate of Svc encl
IRWIN, D P Philadelphia Electric Co 81/01/23 5pp 07546.066

I Financial information

8012160144 Forwards SEC Form 10-Q, Quarterly Financial Rept & supporting
mgt comments, in response to NRC 790721.1109 & 800811
requests for info re significant financial developments
affecting utility in restart proceeding
CUNDON, V H General Public Utilities 80/11/26 3pp

--8012160154 Quarterly Financial Rept Sept 1980 & supporting mgt
comments
General Public Utilities 80/11/14 44pp

DOCKET 50-464 FULTON GENERATING STATION, UNIT 2

G Adjudicatory correspondence

8101270315 Reply supporting applicant earlier motion to withdraw CP
application w/o prejudice Opposes intervenor York Committee
for Safe Environ response supporting withdrawal of
application w/prejudice Certificate of Svc encl
IRWIN, D P Philadelphia Electric Co 81/01/23 5pp 07546.066.

I Financial information

8012160144 Forwards SEC Form 10-Q, Quarterly Financial Rept & supporting
mgt comments, in response to NRC 790721.1109 & 800811
requests for info re significant financial developments
affecting utility in restart proceeding
CUNDON, V H General Public Utilities 80/11/26 3pp

--8012160154 Quarterly Financial Rept Sept 1980 & supporting mgt
comments
General Public Utilities 80/11/14 44pp

DOCKET 50-466 ALLENS CREEK NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

D. NRC Draft/Final Environmental Statements, Suppl & correspondence

B101050280 Forwards draft Suppl 2 to facility FES (NUREG-0470) & FR notice of availability Draft not encl
VOUNGELCDD, B J Licensing Branch 1 80/12/12 1p 07389 237

B101050282 Notice of availability of draft Suppl 2 to FES
VOUNGELCDD, B J Licensing Branch 1 80/12/12 2pp 07389 238

B101050533 Forwards draft Suppl 2 to FES for facility & FR notice of availability w/o draft Suppl 2
VOUNGELCDD, B J Licensing Branch 1 80/12/12 3pp 07390 307

B101050106 Forwards draft suppl to FES for review & comment Comments due within 45 days after publication in FR
VOUNGELCDD, B J Licensing Branch 1 80/12/12 3pp 07426 298

B101210312 Forwards FR notice & draft Suppl 2 to FES, NUREG-0470
Requests contents w/o Suppl 2
VOUNGELCDD, B J Licensing Branch 1 80/12/12 2pp 07488 225

B101050055 Verifies filing of EIS, NUREG-0470, Suppl 2 w/ Dfc of Environ Review. EPA scheduled publication of notice of availability in FR on 8/12/24 & public review period is scheduled to terminate on 8/30/21
MILSON, K L Environmental Protection Agency, 80/12/22 1p 07385 267

B101120407 Ack receipt of draft Suppl 2 to FES re proposed const of facility
COHNRE, M L Agriculture, Dept of 81/01/05 1p 07446 277

B101230444 Advises that draft suppl to FES has been reviewed No comments forthcoming
HAYCOCK, V J Housing & Urban Development, Dept of 81/01/19 1p 07511 125

F. Security, medical, emergency & fire protection plans

B101050087 Ltr to all licensees of operating reactor plants, LP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing 80/11/13 2pp

G. Adjudicatory correspondence

B101050019 Requests info re public hearings in Houston, TX scheduled for B10114 & 19 Expresses wish to make prepared statement
BRWDNAGE, J T Affiliation Unknown 80/12/17 1p 07442 001

B101050014 Appeal to receive transcript of B01202 prehearing conference Intervenor was under impression that recently changed NRC rules would provide gratis copy Certificate of Bvc encl
DOHERTY, J F Doherty, J F 80/12/27 2pp 07378 349

B101050065 Expresses concern re amount of time taken to handle & process requests re Reop Rept
DOHERTY, J F Doherty, J F 80/12/27 1p 07376 288

B101050608 Response to Intervenor B01222 motion for B01231 late filing of Saxon direct testimony NRC has no objection Certificate of Bvc encl
SLACK, R L Hearing Branch 1 80/12/31 3pp 07390 293

B101050055 Response to TX PIRG B01216 motion & Intervenor Hinderstein B01222 motion for extension to file H Saxon direct testimony Applicant does not oppose motion Certificate of Bvc encl
RASKIN, D J COPELAND, J G Houston Lighting & Power Co RASKIN, D, Loenstein, Newman, Reis, Atelrad & Toll 80/12/31 3pp 07427 298

B101050442 Requests permission to present testimony at CP hearing for proposed facility on B10114 at Univ of Houston, TX
HARDT, B Affiliation Unknown 81/01/01 1p 07420 312

B101050400 Requests to make limited appearance statement at B10114 hearing in Houston, TX re proposed facility operation
WCD03, J Affiliation Unknown 81/01/03 1p 07442:105

B101140391 Requests to make limited appearance statement at B10114 hearing in Houston, TX
FRAM, F Affiliation Unknown 81/01/03 1p 07308 001

B101050408 Order granting extension until B10130 for intervenor to respond to applicant B01218 answers in support of NRC B01126 motion for summary disposition Only new facts & arguments should be addressed
WLF, S J Atomic Safety and Licensing Board Panel 81/01/05 07419 341

B101050408 Notice that ASLB & other interested parties will meet w/ applicant representative on B10113 in Bealy, TX to visit proposed site
WLF, S J Atomic Safety and Licensing Board Panel 81/01/05 07426 244

B101050107 Order dismissing JF Doherty appeal restating entitlement transcript of B01202 prehearing conference Decision based on ASLB B01209 order rescinding orders or issuances granting assistance to intervenors
TOMPAHUS, S A Atomic Safety and Licensing Appeal Panel 81/01/05 07426:303

B101200030 Requests to make limited appearance statement at license hearing
BERKMAN, M Affiliation Unknown 81/01/05 1p 07477 316

B101120538 Order granting extension until B01231 for intervenors TX PIRG & Hinderstein to file H Saxon written direct testimony
WLF, S J Atomic Safety and Licensing Board Panel 81/01/06 07445 189

B101160184 Response to ASLB B01120 order, providing nexus between BL jet pumps & earlier 36RS, in support of Intervenor B10115 Contention 53 Certificate of Bvc encl
DOHERTY, J F Affiliation Unknown 81/01/06 3pp 07183 001

B101200030 Requests to make limited appearance statement at license hearing
STRUBE, W P Affiliation Unknown 81/01/08 1p 07477:317

B101150011 Brief in form of pleading opposing Potthoff appeal to ASLB B01113 order which granted applicant motion for summary disposition & dismissing Potthoff as intervenor Certificate of Bvc encl
NEWMAN, J R Houston Lighting & Power Co NEWMAN, J R Loenstein, Newman, Reis, Atelrad & Toll 81/01/09 12pp 07462 1

B101140853 Requests to make limited appearance statement
WESTON, J Affiliation Unknown 81/01/12 1p 07308 001

B101200027 Requests to make limited appearance statement at license hearing Certificate of Bvc encl
FEIRE, C A Affiliation Unknown 81/01/14 4pp 07187 001

B101230604 Motions directed to ASLB for interlocutory appeal & certification of questions re NEPA requirements on Class 9 accidents & to ASLB for directed certification of questions per ALAB-271
SCOTT, J H Texas Public Interest Research Group 81/01/15 3pp 07812 239

B101270289 Contention 51 re designation of site L1-3 as superior & Contention 52 re ability of govt to decide issues of wildlife habitat & Contentions 53 & 94 re NUREG-470, Suppl 2, Certificate of Bvc encl
DOHERTY, J F Affiliation Unknown 81/01/15 12pp 07309:001

B101260494 Order withholding action on Intervenor TX PIRG B10115 motion for direct certification until ASLB decision on referring ruling or certifying questions Certificate of Bvc encl
BISHOP, C J Atomic Safety and Licensing Appeal Panel 81/01/19 3pp 07329 221

B101280293 Supplemental response to applicant motion for summary disposition of Intervenor Doherty Contention 5 Portions withheld (ref 10CFR2 790)
DOHERTY, J F Affiliation Unknown 81/01/19 2pp 07308 001

B101280325 Motion requesting that ASLB call D Basdoras as witness Intervenor J Doherty Contentions 8, 12, 24, 28, 41, 42 & 17 Certificate of Bvc encl
DOHERTY, J F Affiliation Unknown 81/01/19 3pp 07308 001

B101280168 Response in form of brief opposing Potthoff appeal of ASLB B01130 order Board action dismissing Contention 6 re marine biomass production & Potthoff as party-Intervenor was correct Certificate of Bvc encl
BLACK, R L Hearing Branch 1 81/01/26 22pp 07586:120

031 Opposes proposed facility No permit should be granted
M H Affiliation Unknown 80/12/22 1p 07309 001

035 Opposes facility operation No more pollution is needed in
R J Affiliation Unknown 80/12/28 1p 07442 287

037 Opposes facility const
Affiliation Unknown 81/01/08 1p 07187 001

ing transcripts on non-antitrust matters

452 Transcript of 810112 hearing in Wallis, TX Pp 2.005-2.121
Atomic Safety and Licensing Board Panel 81/01/12 117pp
093

472 Transcript of 810113 hearing in Wallis, TX Pp 2.122-2.202
Atomic Safety and Licensing Board Panel 81/01/13 82pp
030

424 Transcript of 810114 hearing in Houston, TX Pp 2.203-2.309
Atomic Safety and Licensing Board Panel 81/01/14 108pp
148

478 Transcript of 810115 hearing in Houston, TX Pp 2.310-2.495
Atomic Safety and Licensing Board Panel 81/01/15 187pp
114

460 Transcript of 810116 hearing in Houston, TX Pp 2.496-2.731
Atomic Safety and Licensing Board Panel 81/01/16 237pp
195

279 Transcript of 810117 hearing in Houston, TX Pp 2.732-2.969
Atomic Safety and Licensing Board Panel 81/01/19 239pp
056

283 Transcript of 810120 hearing in Houston, TX Pp 2.970-3.230.
Atomic Safety and Licensing Board Panel 81/01/20 262pp.
295

098 Transcript of 810121 hearing in Houston, TX Pp 3.231-3.479
Atomic Safety and Licensing Board Panel 81/01/21 250pp
163

285 Transcript of 810122 hearing in Houston, TX Pp 3.480-3.736
Atomic Safety and Licensing Board Panel 81/01/22 256pp
196

182 Transcript of 810123 hearing in Houston, TX Pp 3.737-3.878
Atomic Safety and Licensing Board Panel 81/01/23 143pp
142

ressional/Executive Correspondence

314 Responds to 801009 ltr re NRC progress in review of CPs, use
resources for Section 110 of NRC 1980 Authorization Act.
in adjudicatory proceedings & lack of coherent
regulatory guidance W/o encl documentation
NEARNE, J F. Commissioners 80/12/22 4pp 07422 007

80362 Responds to 801009 ltr re NRC progress in review of CPs, use
resources for Section 110 of NRC 1980 Authorization Act.
delay in adjudicatory proceedings & lack of coherent
regulatory guidance Related documentation encl
NEARNE, J F. Commissioners 80/12/22 4pp 07422 023

80-467 ALLENS CREEK NUCLEAR STATION, UNIT 2

ressional/Executive Correspondence

314 Responds to 801009 ltr re NRC progress in review of CPs, use
resources for Section 110 of NRC 1980 Authorization Act.
in adjudicatory proceedings & lack of coherent
regulatory guidance W/o encl documentation
NEARNE, J F. Commissioners 80/12/22 4pp 07422 007

80362 Responds to 801009 ltr re NRC progress in review of CPs, use
resources for Section 110 of NRC 1980 Authorization Act.
delay in adjudicatory proceedings & lack of coherent
regulatory guidance Related documentation encl
NEARNE, J F. Commissioners 80/12/22 4pp 07422 023

A Application/construction stage documents & correspondence

810150145 Grants six month extension to preliminary design approval
for CESSAR Sys 80 std plant
EISENHUT, D G Division of Licensing 80/12/31 2pp 07463 217

K Utility Final Safety Analysis Report (FSAR) & amendments

810101196 Forwards FSAR W/o encl
SCHEPER, A E C-t Power Systems 80/12/18 1p 07414 291

DOCKET 80-471 PILGRIM NUCLEAR POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

8101220466 Ltr to all power reactor licensees & applicants forwarding
summary of 801112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D G Division of Licensing 80/11/26 8pp

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP holders
& CP applicants. Revised radiological emergency response
plans must be submitted by licensees within 60 days of
810102 & by applicants as part of FSAR.
EISENHUT, D G Division of Licensing 80/11/13 2pp

D Adjudicatory correspondence

8101060918 Order granting NRC 800117 motion to receive into record CB
Bauer & CV Hodge suppl testimony re applicant Contention 9.
Testimony received as NRC Exhibit 6B
GOODRICKE, A C Atomic Safety and Licensing Board Panel 80/12/30
1p 07401 092

D Advisory Committee on Reactor Safeguards reports & correspondence

8101308477 Forwards ACRS 810112 ltr to Chairman Ahearne re review of
requirements for near-term CP applications
MIRACLE, A F J Licensing Branch 3 81/01/21 4pp 07507 058

U Congressional/Executive Correspondence

8101080314 Responds to 801009 ltr re NRC progress in review of CPs, use
of resources for Section 110 of NRC 1980 Authorization Act.
delay in adjudicatory proceedings & lack of coherent
regulatory guidance W/o encl documentation
AHEARNE, J F Commissioners 80/12/22 4pp

--8101080362 Responds to 801009 ltr re NRC progress in review of CPs, use
of resources for Section 110 of NRC 1980 Authorization Act.
delay in adjudicatory proceedings & lack of coherent
regulatory guidance Related documentation encl
AHEARNE, J F Commissioners 80/12/22 4pp

DOCKET 87N-50-460 RESEARCH-41

A Application/construction stage documents & correspondence

810119016B Grants 6-month extension to preliminary design approval of
facility
EISENHUT, D G Division of Licensing 80/12/31 2pp 07475 209

DOCKET 87N-50-402 WOLF CREEK GENERATING STATION, KANSAS GAS & ELECTRIC

A Application/construction stage documents & correspondence

8101220466 Ltr to all power reactor licensees & applicants forwarding
summary of 801112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D G Division of Licensing 80/11/26 8pp

8101090674 Approves Revision 1 to GA program Revision contents &
chronology encl
VOURGSLUGG, B J Licensing Branch 1 80/12/22 5pp 03893 255

80121213 Ack receipt of 801216 ltr re corrective actions revision in regard to Work Hold Agreement 13 Jfc should be informed of plans to resolve work in advance to allow pipe cleanliness evaluation
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 01/12/03 1p 07549 202

80121214 Comments on 801209-10 meeting w/NRC & LLL Recommends measures to be taken to further expedite & facilitate FSAR review. More technical review meetings should be held. Format revision provided:
SEIDLE, W C Standardized Nuclear Unit Power Plant System 80121214 1p 07775 011

80121215 Forwards request for addl info re FSAR for facility. Applicant must provide provisions for emergency food/water & medical supplies in description of control room habitability. 5 list areas of habit in emergency ventilation sys zone
SEIDLE, W C Assistant Director for Licensing 81/01/07 4pp 07492 048

801215021 Notification of 801113 meeting w/attls in Bethesda, MD to discuss C. Review
POTTS, PATT & TROUBRIDGE Licensing Branch 1 81/01/08 3pp 07463 223

801215055 Forwards forwarded transcript of 801209-10 SWPPS review meeting re FSAR chapter B Transcript available in Central files only
POTTS, PATT & TROUBRIDGE Standardized Nuclear Unit Power Plant System 80121505 1p 07517 035

F. Security, medical, emergency & fire protection plans

801215058 Ltr to all licensees of operating reactor plants. CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 801002 & b, applicants as part of FSAR
SEIDLE, W C Division of Licensing 80/11/13 2pp

G. Adjudicatory correspondence

801216025 Petition to intervene in proceeding Certificate of Svc encl
KNEIST, W Affiliation Unknown 81/01/06 2pp 07508 001

801216012 Petition to intervene in proceeding Certificate of Svc encl
SALAVA, M E Affiliation Unknown 81/01/13 2pp 07183 001

801216018 Forwards petition for leave to intervene on behalf of PSC of MO Notice of appearance also encl
KNEIST, W Missouri, State of 81/01/16 2pp 07523 296

801216019 Petition for leave to intervene in proceeding Affidavit & Certificate of Svc encl
KNEIST, W Missouri, State of 80/12/16 5pp 07523 298

801216020 Petition for leave to intervene in proceeding Certificate of Svc encl
NEBAL, L American Nuclear Society 81/01/16 2pp 07546 039

801216053 Petition for leave to intervene
MILLER, C C, MASCH, J E, DAVIS, L J Kansans for Sensible Energy 81/01/19 3pp 07512 283

801216043 Answer opposing W Christy 801006 petition to intervene. Applicant does not oppose Christy limited appearance statement Certificate of Svc encl
RIDGEWAY, D A Kansas Gas & Electric Co RIDGEWAY, D A Shaw, Pittman, Potts & Troubridge 81/01/21 5pp 07546 112

801216052 Answer opposing ME Salava 801113 motion to intervene. Applicant does not oppose Salava limited appearance statement Certificate of Svc encl
SILBER, J E Kansas Gas & Electric Co SILBER, J E Shaw, Pittman, Potts & Troubridge 81/01/21 5pp 07544 037

801216060 Response to PSC of MO 801116 petition to intervene as representative of State Applicant does not object to participation if hearing is ordered Certificate of Svc encl
RIDGEWAY, D A Kansas Gas & Electric Co RIDGEWAY, D A Shaw, Pittman, Potts & Troubridge 81/01/21 4pp 07544 091

801216048 Notice of appearance in proceeding Certificate of Svc encl
RIDGEWAY, D A Kansas Gas & Electric Co RIDGEWAY, D A Shaw, Pittman, Potts & Troubridge 81/01/21 3pp 07550 108

801216051 Answer supporting W Christy petition for leave to intervene re standing issue ASLH ruling on petition as whole would be premature because petitioner still has time to file Certifications Certificate of Svc encl
KAPPA, B Hearing Branch 2 81/01/22 3pp 07529 233

801216052 Notice of appearance in proceeding Certificate of Svc encl
KAPPA, B Hearing Branch 2 81/01/22 2pp 07529 236

801216014 Answer to PSC of MO 801116 petition for leave to intervene as representative state NRC would support petition if hearings are held to consider DL application Certificate of Svc encl
KAPPA, B Hearing Branch 2 81/01/26 2pp 07556 091

H. General correspondence

801217024 Opposes licensing of facility
KNEIST, W Affiliation Unknown 81/01/14 1p 07546 074

I. Inspection reports, IE Bulletins & correspondence

801218027 Forwards IE Mtg Meeting Rept 50-482/80-22 on 801103 SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/11/14 1p 07421 303

801218029 IE Mtg Meeting Rept 50-482/80-22 on 801103 Noncompliance noted failure to approve qualifications of blasting specialist & to establish housekeeping zone designations for cleanliness
SEYFRIT, K V, CROSEMAN, W A Region 4, Dallas, Office of the Director SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/11/14 9pp 07421 304

801218048 Ack receipt of 801030 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-482/80-18
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/03 1p 07557 339

801218047 Responds to NRC 801008 ltr re violations noted in IE Insp Rept 50-482/80-18 Corrective actions Weld portion deposited by shielded manual arc process removed & welders responsible for electrode maint recommended & suspended.
KNEIST, G L Kansas Gas & Electric Co 80/10/30 2pp 07557 340

801218050 Discusses IE Insp Rept 50-482/80-18 on 800922-1031 & forwards notice of violation
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/10/08 1p 07557 342

801218058 Notice of violation from Insp on 801001 Noncompliance noted low hydrogen electrodes not maintained in heated containers & welding done using overexposed & cold electrodes.
Region 4, Dallas, Office of the Director 80/10/08 1p 07557 343

801218056 Forwards IE Insp Rept 50-482/80-18 on 800922-1031 SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/05 2pp 07557 344

801218053 IE Insp Rept 50-482/80-18 on 800922-1031 Noncompliance noted failure to follow procedures in welding.
VANCE, L E, CROSEMAN, W A Region 4, Dallas, Office of the Director 80/12/04 13pp 07557 346

801050614 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Steam Discharge Vd at Dresden Unit 2" No response required
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/12/08 1p 07391 042

801060105 Forwards IE Info Notice 80-44, "Actuation of ECCB in Recirculation Mode While in Hot Shutdown." No written response required
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/12/16 1p 07391 292

801140481 Approves lifting of 801120 Work Hold Agreement 13 re pipe cleanliness program at facility. Util corrective actions acceptable
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/12/31 1p 07461 349

801219024 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Ref parts not found in continuing investigation Final rept will be filed within 30 days.
POTTS, PATT & TROUBRIDGE Standardized Nuclear Unit Power Plant System 81/01/05 1p 07570 345

1 Interim deficiency rept. originally reported on B00124.
crete block walls in control bldg. Re-work of walls
ing Completion of installation of add'l stiffeners &
of walls scheduled prior to B01201

Q L Kansas Gas & Electric Co 80/09/30 1p 07414 139

3 Final interim deficiency rept. originally reported on B00930
cable jacket deficiencies. Defects confined to
& footage markings on jackets. Defects have no effect
performance & are not reportable under 10CFR50.55e

Q L Kansas Gas & Electric Co 80/10/29 1p 07410 335

5 Interim deficiency rept. originally reported on B00606, re
Mechanics, Inc. anchor bolts & nuts having
diameters which do not conform w/ tolerance limitations
NABJ 01/3-1960 Further rept will be submitted B01231

Q L Kansas Gas & Electric Co 80/10/29 2pp 07410 333

3 Interim deficiency rept re nuclear coating in reactor bldg.
ly reported B00725 Coating activities were released
4 hols on B00909 Compilation of coating record data

Q L Kansas Gas & Electric Co 80/10/29 1p 07404 337

5 Interim deficiency rept re loose sway strut bushings.
ly reported B00627 No add'l ITT Orinell or Bergen
on loose bushings found Buchtel will review vendor

Q L Kansas Gas & Electric Co 80/11/12 1p 07404 339

1 Interim deficiency rept re nonconforming welds in main
panels. Initially reported B01014 Company, which
did seismic design is on strike Util will perform

Q L Kansas Gas & Electric Co 80/11/12 1p 07404 338

5 Ack receipt of B01107 ltr forwarding add'l info to final rept
Active Corner & Lada pipe support sway braces info
reviewed & evaluated

Q L Kansas Gas & Electric Co 80/11/13 1p 07443 242

3 Interim deficiency rept re damaged motor control ctr JNG03C
will inspect equipment, determine extent of damage &
recommendations Next rept will be submitted by B10201

Q L Kansas Gas & Electric Co 80/11/28 1p 07414 090

5 Interim deficiency rept re nonconforming concrete masonry
all walls identified in NCR INUJ536C removed &
w/exceptions listed If work not complete on B10701,

Q L Kansas Gas & Electric Co 80/11/28 2pp 07414 027

5 Interim deficiency rept. originally reported on 790731, re
damaged electrical equipment & mechanical components &
Boils Cleaning of pressurized piping formations along

Q L Kansas Gas & Electric Co 81/01/02 2pp 07414 132

5 Summarizes B01224 telcon rept re generic deficiency in
techniques used by Bechtel in design of pipe whip
nts used for std power block Bechtel reviewing design

Q L Kansas Gas & Electric Co 81/01/23 2pp 07414 331

5 Ltr to all power reactor licensees & applicants forwarding
of B01112 meeting re implementation of guidance for
ved Safety Issue A-12: "Potential for Low Fracture

Q L Kansas Gas & Electric Co 80/11/26 8pp

4 Approves Revision 1 to QA program Revision contents &
logy encl
000, B J. Licensing Branch 1. 80/12/22. 5pp. 03893 255

2 Comments on B01209-10 meeting w/NRC & LLL. Recommends
to be taken to further expedite & facilitate FSAR

5 Ltr to all power reactor licensees & applicants forwarding
of B01112 meeting re implementation of guidance for
ved Safety Issue A-12: "Potential for Low Fracture

Q L Kansas Gas & Electric Co 80/11/26 8pp

4 Approves Revision 1 to QA program Revision contents &
logy encl
000, B J. Licensing Branch 1. 80/12/22. 5pp. 03893 255

2 Comments on B01209-10 meeting w/NRC & LLL. Recommends
to be taken to further expedite & facilitate FSAR

5 Ltr to all power reactor licensees & applicants forwarding
of B01112 meeting re implementation of guidance for
ved Safety Issue A-12: "Potential for Low Fracture

Q L Kansas Gas & Electric Co 80/11/26 8pp

4 Approves Revision 1 to QA program Revision contents &
logy encl
000, B J. Licensing Branch 1. 80/12/22. 5pp. 03893 255

2 Comments on B01209-10 meeting w/NRC & LLL. Recommends
to be taken to further expedite & facilitate FSAR

5 Ltr to all power reactor licensees & applicants forwarding
of B01112 meeting re implementation of guidance for
ved Safety Issue A-12: "Potential for Low Fracture

Q L Kansas Gas & Electric Co 80/11/26 8pp

B101140641 Requests Ltr actions re cultural resources onsite &
transmission corridors at facility as result of NRC B01216
visit Actions include physical structure survey & analysis &
marit of fence around site
YOUNGBLDED, B J. Licensing Branch 1 80/12/24 3pp 07308 001

B101150596 Forwards request for add'l info re QA program compliance
w/ various reg guides Response should be forwarded by B10223
TEDESCO, R C Assistant Director for Licensing 80/12/22 9pp
07463 186

B101210250 Forwards request for add'l info re FSAR for facility
Applicant must provide provisions for emergency food, water &
medical supplies in description of control room habitability
& list areas & rats in emergency ventilation sys zone
TEDESCO, R C Assistant Director for Licensing 81/01/07 4pp
07492 040

B101150361 Notification of B10113 meeting w/Util in Bethesda, MD to
discuss U review
DROVERICK, A W Licensing Branch 1 81/01/08 3pp 07463 223

B101230565 Forwards marked-up transcript of B01209-10 SHAPPS review
recting on FSAR Chapter 8 Transcript available in Central
files only
PETRICK, H A Standardized Nuclear Unit Power Plant System
81/01/20 1p 07517 035

C Utility Environmental Report (ER), amendments & correspondence

B101130021 Ack receipt of environ rept for facility FR notice of
availability encl
YOUNGBLDED, B J. Licensing Branch 1 80/12/24 2pp 07448 291

--B101130026 Notice of availability of environ rept
YOUNGBLDED, B J. Licensing Branch 1 80/12/27 2pp 07448 293

B101160566 Forwards request for add'l info for completion of environ
rept review Outstanding areas: cooling tower operation &
noise, terrestrial ecology & land use, aquatic ecology, water
treatment & chemical discharges & socioeconomics
TEDESCO, R C Assistant Director for Licensing 81/01/02 10pp
07471 186

B101300702 Advises that accepted version of environ rept, Vols 1-3 is
being forwarded Previously submitted version should be
discarded
SQUJER, J L Division of Rules and Records 81/01/19 1p
07594 152

B101300708 Advises that accepted version of environ rept, Vols 1-3 is
being forwarded Previously submitted version should be
discarded
SQUJER, J L Division of Rules and Records 81/01/19 1p
07594 153

F Security, medical, emergency & fire protection plans

B101070387 Ltr to all licensees of operating reactor plants, CP holders
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B10102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

G Adjudicatory correspondence

B101160231 Requests intervenor status in proceeding
BOTHWICK, J Affiliation Unknown 80/12/08 1p 07470 184

--B101160240 Requests to represent City of Owensville, MD in proceeding
Certificate of Svc encl
STEFFEN, H Affiliation Unknown 80/12/24 4pp 07470 185

B101050032 Requests to make limited appearance statement on behalf of
City of Rhineland, MD Certificate of Svc encl
LUEVEY, F. Affiliation Unknown 80/12/22 2pp 07377 358

B101050005 Requests to make limited appearance statement on behalf of
City of Chamala, MD
STIFFER, H Affiliation Unknown 80/12/22 1p 07378 344

--B101050008 Requests to make limited appearance statement on behalf of
City of Owensville, MD Certificate of Svc encl
LOTHMAN, H Affiliation Unknown 80/12/22 2pp 07378 345

Y-50-483 CALLAWAY PLANT, UNIT 1

ation/construction stage documents & correspondence

5 Ltr to all power reactor licensees & applicants forwarding
of B01112 meeting re implementation of guidance for
ved Safety Issue A-12: "Potential for Low Fracture

Q L Kansas Gas & Electric Co 80/11/26 8pp

4 Approves Revision 1 to QA program Revision contents &
logy encl
000, B J. Licensing Branch 1. 80/12/22. 5pp. 03893 255

2 Comments on B01209-10 meeting w/NRC & LLL. Recommends
to be taken to further expedite & facilitate FSAR

Q L Kansas Gas & Electric Co 80/11/26 8pp

5 Ltr to all power reactor licensees & applicants forwarding
of B01112 meeting re implementation of guidance for
ved Safety Issue A-12: "Potential for Low Fracture

Q L Kansas Gas & Electric Co 80/11/26 8pp

8101120454 Motion for extension until 810116 to answer local govt
petitions to participate in hearings Certificate of Svc
encl
BAXTER, T A Union Electric Co BAXTER, T A Shaw, Pittman, Potts &
Troubridge 81/01/08 4pp 07442 321

8101140226 Response opposing petition to intervene by MD-KA section.
ANS who prejudice to timely renewal Supports petitions for
participation by E Brown, H Lottman & K Lueley Certificate of
Svc encl
LESSY, R P Antitrust Division 81/01/12 9pp 07450 088

8101190477 Response opposing MD-KS section of ANS 801219 petition to
intervene Applicant would not oppose refiling petition to
intervene to cure deficiencies Certificate of Svc encl
BAXTER, T A Union Electric Co BAXTER, T A Shaw, Pittman, Potts &
Troubridge 81/01/13 7pp 07474 068

8101230615 Response to 801222 requests for participation Applicant does
not object to two petitions but requests that Presiding
Judges Lottman & Lueley & School District Superintendent
Brown show representative authority Certificate of Svc encl
BERNSTEIN, D L Union Electric Co BERNSTEIN, D L Shaw, Pittman,
Potts & Troubridge 81/01/16 5pp 07512 269

8101260486 Answer to Judge Wright 810116 request for participation
Applicant has no objection provided that petitioner can
substantiate representative authority during first
prehearing conference Certificate of Svc encl
BERNSTEIN, D L Union Electric Co BERNSTEIN, D L Shaw, Pittman,
Potts & Troubridge 81/01/21 4pp 07529 211

8101280307 Answer opposing J Botwinick 801208 petition for leave to
intervene & request for hearing Petitioner failed to
establish particular interest or standing Certificate of Svc
encl
BAXTER, T A Union Electric Co BAXTER, T A Shaw, Pittman, Potts &
Troubridge 81/01/23 5pp 07537 164

8101300318 Response supporting Wright 810116 petition for local govt
representative participation when representative capacity is
shown Botwinick 810113 petition for leave to intervene
should be denied w/leave to amend Certificate of Svc encl
LESSY, R P Antitrust Division 81/01/28 10pp 07582 199

H General correspondence

8101440031 Responds to 801209 ltr re requirements to limit discharge
into MD River NRC will require that util meet regulations
YOUNGBERG, D J Licensing Branch 1 80/12/29 1p 07308 001

--8101140037 Requests info re requirements for util in limiting discharge
into MD River according to NRC & Federal regulations
HUNPAT, J E Affiliation Unknown 80/12/09 1p 07308 001

8101290783 Responds to 801219 ltr requesting comment on TB Class 801203
ltr expressing concern re dumping of low level radioactive
water into MD River All operating reactors must stay within
design objective dose limits
DIRCKS, W J Office of the Executive Director for Operations
81/01/06 2pp 07309 001

--8101290787 Forwards TB Class 801203 ltr expressing concern re dumping
of low level radioactive water from facilities into MD
River Requests response.
BOLLING, R House of Rep 80/12/09 2pp 07309 001

8101150510 Forwards 801203 ltr to State of MD Clean Water Commission &
MD Dept of Resource 801215 response re issuance of OL
Petition std 801203 protesting licensing of facility
provided
ECHELE, C Affiliation Unknown 81/01/11 6pp 07309 001

I Inspection reports, IE Bulletins & correspondence

8101050287 Forwards IE Info Notice 80-38, "Cracking in Charging Pump
Casting Cladding." No response required
KEPPLER, J Q Region 3, Chicago, Office of the Director 80/10/30
2pp 07389 294

Polysys Generators " No written response required
KEPPLER, J Q Region 3, Chicago, Office of the Director
2pp 07444 097

8101060737 Forwards IE Bulletin 80-21, "Valve Yokes Suppl
Malcorn Foundry Co, Inc." Written response required
KEPPLER, J Q Region 3, Chicago, Office of the Director
2pp 07400 270

8101070421 Forwards IE Info Notice 80-40, "Excessive Nitr
Pressure Actuates Safety-Relief Valve Operation to Cause
Reactor Depressurization." No written response required
KEPPLER, J Q Region 3, Chicago, Office of the Director
2pp 07442 219

8101060385 Forwards IE Info Notice 80-41, "Failure of Sulf
Valve in Decay Heat Removal Sys at Davis Besse Unit 1."
response required
KEPPLER, J Q Region 3, Chicago, Office of the Director
2pp 07391 082

8101060510 Forwards IE Bulletin 80-23, "Failures of Bolts
Mfg by Valcor Engineering Corp." Written response requi
KEPPLER, J Q Region 3, Chicago, Office of the Director
2pp 07391 235

8101050572 Forwards IE Info Notice 80-43, "Failures of Co
Level Monitor for Steam Discharge Vol at Dresden Unit 2
response required
KEPPLER, J Q Region 3, Chicago, Office of the Director
2pp 07386 040

8101220536 Forwards IE Insp Rept 80-483/80-28 on 801117-2
violation
FIORELLI, G Region 3, Chicago, Reactor Construction &
Support Branch 80/12/12 2pp 07183 001

--8101220510 Notice of violation from insp on 801117-28
FIORELLI, G Region 3, Chicago, Reactor Construction
Support Branch 80/12/12 1p 07183 001

--8101220516 IE Insp Rept 80-483/80-28 on 801117-28. Noncon
inadequate design control of delineation of acceptance
criteria for insp
KNOP, R C, HANSEN, W A Region 3, Chicago, Office of
80/12/08 7pp 07183 001

8101070092 Forwards IE Info Notice 80-44, "Actuation of &
Recirculation Mode While in Hot Shutdown." No written
response required.
KEPPLER, J Q Region 3, Chicago, Office of the Director
1p 07415 036

8101290264 Responds to IE Bulletin 80-21, "Valve Yokes B
Malcolm Foundry Co, Inc." Ref parts not found in contin
investigation. Final rept will be filed within 30 days
PETRICK, N A Standardized Nuclear Unit Power Plant By
81/01/05 1p 07570 345

8101270850 Ack receipt of 810106 ltr informing NRC of str
correct violations noted in IE Insp Rept 80-483/80-28
FIORELLI, G Region 3, Chicago, Reactor Construction &
Support Branch 81/01/16 1p 07550 129

--8101270853 Responds to NRC 801212 ltr re violations no
Rept 80-483/80-28 Corrective actions approval obtain
allow smaller cable bend radius Bend radii shall be
to inside edge of bend
BRYAN, J K Union Electric Co 81/01/06 2pp 075

J Reportable occurrences, LERs & related correspondence

8101100045 Ack receipt of 801107 ltr forwarding addl inf
re defective Corner & Leda pipe support sway braces In
will be reviewed & evaluated
CAHLSO, R T Region 1, Philadelphia, Reactor Construct
Engineering Support Branch 80/11/13 1p 07445 242

B101140589 Interim deficiency rept. originally reported on B01209, re concrete deficiencies discovered near surface of reactor bldg core. Further evaluation will be performed by Bechtel. Final evaluation to be completed by B10401
BRYAN, J. W. Union Electric Co B1/01/02 1p 07461 244

B101140505 Final deficiency rept. originally submitted B00620, re out of tolerance conditions on major bolt diameters & minor nut diameters supplied by Industrial Mechanic, Inc. Analysis by A/E indicates no predicted reduction in design capacity
BRYAN, J. W. Union Electric Co B1/01/07 2pp 07461 160

B101290690 Summarizes B01224 telcon rept re generic deficiency in analytical techniques used by Bechtel in design of pipe whip restraints used for std power block Bechtel reviewing design calculations. Final rept not to be issued until B10228
SEIKEN, S. J. Standardized Nuclear Unit Power Plant System B1/01/23 2pp 07566 331

DOCKET BTN-50-405 STERLING POWER NUCLEAR PROJECT, UNIT 1

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D. O. Division of Licensing B0/11/26 8pp

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of B01002 & by applicants as part of FSAR.
EISENHUT, D. O. Division of Licensing B0/11/13 2pp

B101290583 Releases public version of evacuation time estimates for facility
FELTON, J. M. Division of Rules and Records B1/01/27 1p 07373 267

--B101290589 Forwards public version of upgraded evacuation time estimates for facilities in response to NRC B01209 ltr
MAIER, J. E. Rochester Gas & Electric Corp B1/01/14 23pp 07573 268

3 Inspection reports, IE Bulletins & correspondence

B101070392 Forwards Suppl 1 to IE Info Notice B0-27, "Broken Studs on Terry Turbine Steam Inlet Flange." No written response required
GRIER, D. H. Region 1, Philadelphia, Office of the Director B0/11/26 1p 07414 089

B101050829 Forwards IE Info Notice B0-44, "Actuation of ECCB in Recirculation Mode While in Hot Shutdown." No written response required
GRIER, D. H. Region 1, Philadelphia, Office of the Director B0/12/16 1p 07397 033

DOCKET BTN-50-406 CALLAWAY PLANT, UNIT 2

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D. O. Division of Licensing B0/11/26 8pp

B101050052 Comments on B01209-10 meeting w/NRC & LLL. Recommends measures to be taken to further expedite & facilitate FSAR review. More technical review meetings should be held. Format revision provided.
PETRICK, N. A. Standardized Nuclear Unit Power Plant System B0/12/23 1p 07373 311

B101140641 Requests util actions re cultural resources onsite & transmission corridors at facility as result of NRC B01216 visit. Actions include physical structure survey & analysis & maint of fence around site
YOUNGBLOOD, B. J. Licensing Branch 1 B0/12/24 3pp 07308 001

B101210253 Forwards request for addl info re FSAR for facility. Applicant must provide provisions for emergency food, water & medical supplies in description of control room habitability & list areas & rats in emergency ventilation sys zone
TEBESCO, R. L. Assistant Director for Licensing B1/01/07 4pp 07492 048

B101230565 Forwards marked-up transcript of B01209-10 SNUPPS review meeting on FSAR Chapter B transcript available in Central Files only
PETRICK, N. A. Standardized Nuclear Unit Power Plant System B1/01/20 1p 07517 035

C Utility Environmental Report (ER), amendments & correspondence

B101300702 Advises that accepted version of environ rept. Vols 1-3 being forwarded. Previously submitted version should be discarded
SCUDFR, J. L. Division of Rules and Records B1/01/19 1p 07584 152

B101300708 Advises that accepted version of environ rept. Vols 1-3 being forwarded. Previously submitted version should be discarded
SCUDFR, J. L. Division of Rules and Records B1/01/19 1p 07584 153

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of B01002 & by applicants as part of FSAR.
EISENHUT, D. O. Division of Licensing B0/11/13 2pp

D Adjudicatory correspondence

B10120454 Motion for extension until B10116 to answer local govt petitions to participate in hearings. Certificate of Svc encl
BAXTER, T. A. Union Electric Co BAXTER, T. A. Shaw, Pittman, P. Troubridge B1/01/06 4pp 07442 321

B101140226 Response opposing petition to intervene by MD-KA sects. AF5, w/o prejudice to timely renewal. Supports petitions for participation by E. Brown, H. Lottman & K. Luekey. Certificate of Svc encl
LESSY, R. P. Antitrust Division B1/01/12 9pp 07458 088

B101300010 Response supporting Wright B10116 petition for local govt representative participation when representative capacity is shown. Botwinick B10113 petition for leave to intervene should be denied w/leave to amend Certificate of Svc encl
LESSY, R. P. Antitrust Division B1/01/28 10pp 07982 199

H General correspondence

B101140031 Responds to B01209 ltr re requirements to limit discharge into MD River. HRC will require that util meet regulations
YOUNGBLOOD, B. J. Licensing Branch 1 B0/12/29 1p 07308 001

--B101140037 Requests info re requirements for util in limiting d into MD River according to NRC & Federal regulations
MURRAY, J. E. Affiliation Unknown B0/12/09 1p 07308 001

B101290783 Responds to B01219 ltr requesting comment on TB Glass ltr expressing concern re dumping of low level radioactive water into MD River. All operating reactors must stay within design objective dose limits
PITRICK, M. J. Office of the Executive Director for Operations B1/01/06 2pp 07309 001

--B101290789 Forwards TB Glass B01203 ltr expressing concern re d of low level radioactive water from facilities into MD River. Requests response
BOLLING, R. House of Rep B0/12/07 2pp 07309 001

B10150310 Forwards B01203 ltr to State of MD Clean Water Commis. MD Dept of Resource B01215 response re issuance of OL. Petition dtd B01203 protesting licensing of facility provided
ECHELE, C. Affiliation Unknown B1/01/11 6pp 07309 001

U. Inspection reports, IE Bulletins & correspondence

B101050237 Forwards IE Info Notice 80-39, "Cracking in Charging Pump
Casing Cladding." No response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/10/30
2pp 07349 254

B101050527 Forwards IE Info Notice 80-39, "Malfunction of Solenoid
Valves Pkg by Valcor Engineering Corp." No written response
is required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/10/31
2pp 07401 184

B101102492 Forwards IE Circular 80-23, "Potential Defects in Heloit
Power Sys Emergency Generators." No written response
required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/10/31
4pp 07444 297

B101060707 Forwards IE Bulletin 80-25, "Valve Yokes Supplied by
Malcolm Foundry Co. Inc." Written response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/11/06
2pp 07403 270

B101050421 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply
Pressure Actuates Safety-Relief Valve Operation to Cause
Reactor Depressurization." No written response required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/11/07
2pp 07442 215

B101060385 Forwards IE Info Notice 80-41, "Failure of Spring Check
Valve in Delay Heat Removal Sys at Davis Besse Unit 1." No
response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/11/10
2pp 07371 062

B101060510 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves
Mfg by Valcor Engineering Corp." Written response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/11/14
2pp 07391 235

B101090572 Forwards IE Info Notice 80-43, "Failures of Continuous Water
Level Monitor for Steam Discharge Val at Dresden Unit 2." No
response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/12/05
2pp 07386 040

B101070092 Forwards IE Info Notice 80-44, "Actuation of ECCS in
Recirculation Mode While in Hot Shutdown." No written
response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/12/16
1p 07415 036

B101290264 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by
Malcolm Foundry Co. Inc." Ref parts not found in continuing
investigation. Final rept will be filed within 30 days.
PETRIC, H. A. Standardized Nuclear Unit Power Plant System
81/01/05 1p 07570 345

S. Reportable occurrences, LERs & related correspondence

B101100045 Ack receipt of B01107 ltr forwarding addl info to final rept
re defective Corner & Lade pipe support stay braces info
will be reviewed & evaluated
CARLSNER, T. Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch 80/11/13 1p 07445 242

B101140559 Interior deficiency rept. originally reported on B01205, re
concrete deficiencies discovered near surface of reactor bldg
done. Further evaluation will be performed by Bechtel. Final
evaluation to be completed by B10401
BRYAN, J. K. Union Electric Co 81/01/02 1p 07461 244

B101290690 Summarizes B01224 telcon rept re generic deficiency in
analytical techniques used by Bechtel in design of pipe whip
restraints used for std power block Bechtel reviewing design
calculations. Final rept not to be issued until B10223
BEIKENS, J. Standardized Nuclear Unit Power Plant System 81/01/23
2pp 07565 331

DOCKET STN-50-480 PERKINS NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports."

F. Security, medical, emergency & fire protection plans

B101070327 Ltr to all licensees of operating reactor plants. CP
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B10102 & by applicants as part of FSAR
EISENHUT, D. G. Division of Licensing 80/11/13 2pp

G. Adjudicatory correspondence

B101050516 Brief in opposition to intervenor B00B29 exceptions
ASL3 B00222 Partial Initial Decision 3 holding no obviously
superior alternative site exists. Decision should be
affirmed. Certificate of Bvc encl
MCOARRY, J. M., PCRTER, W. L. Duke Power Co MCOARRY, J. M. Dou
Garhan 80/12/31 48pp 07397 029

B101150299 Response opposing intervenors' exceptions on appeal
B00222 partial initial decision re site alternatives.
Decision should be affirmed. Certificate of Bvc encl
SARTHC, A. Hearing Branch 3 81/01/12 42pp 07462 273

B101140745 Order setting B10218 oral argument in Bethesda, MD re
intervenors RA Davis & Yadin River Committee appeal from
ASLB B00222 partial initial decision. Certificate of Bvc
encl
BISHOP, C. J. Atomic Safety and Licensing Appeal Panel 81/0
4pp 07472 080

B101260499 Motion for extension to set oral argument on altern
site issue for B10401 Certificate of Bvc encl
MCOARRY, J. M. Duke Power Co MCOARRY, J. M. Debevoise & Libe
81/01/21 4pp 07529 226

B101270064 Denies B10117 request for limited appearance statement.
Right to make statement is limited to evidentiary hearing &
proceeding is now in appellate stage
BISHOP, C. J. Atomic Safety and Licensing Appeal Panel 81/0
2pp 07347 032

--B101270070 Requests to make limited appearance statement
SPRINGER, D. Affiliation Unknown 81/01/17 1p 07547 0

B101280139 Order granting applicant motion to postpone oral ar
appeal from ASLB B00222 partial initial decision until
B10401 Certificate of Bvc encl
BISHOP, C. J. Atomic Safety and Licensing Appeal Panel 81/0
4pp 07596 099

Q. Inspection reports, IE Bulletins & correspondence

B101060216 Forwards IE Info Notice 80-44, "Actuation of ECCS in
Recirculation Mode While in Hot Shutdown." No written
response required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 8
1p 07391 321

U. Congressional/Executive Correspondence

B101080314 Responds to B01007 ltr re NRC progress in review of
of resources for Section 110 of NRC 1980 Authorization Act.
delay in adjudicatory proceedings & lack of coherent
regulatory guidance. W/o encl documentation
AHEARN, J. F. Commissioners 80/12/22 4pp

--B101080362 Responds to B01009 ltr re NRC progress in review
of resources for Section 110 of NRC 1980 Authorization Act
delay in adjudicatory proceedings & lack of coherent
regulatory guidance. Related documentation encl
AHEARN, J. F. Commissioners 80/12/22 4pp

DOCKET STN-50-489 PERKINS NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants for
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D. G. Division of Licensing 80/11/26 8pp

ity, medical, emergency & fire protection plans

97 Ltr to all licensees of operating reactor plants. CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 1/4 by applicants as part of FSAR
UT.D.O. Division of Licensing 80/11/13 2pp

Adjudicatory correspondence

16 Brief in opposition to intervenor EC0029 exceptions to 800222 Partial Initial Decision 3 holding no obviously superior alternative site exists Decision should be affirmed Certificate of Svc encl
V. J. M. , PERTER, W. L. Duke Power Co MCGARRY, J. M. Douglass & Barban 80/12/31 48pp 07307 025

99 Response opposing intervenors' exceptions on appeal of ASLB 800222 partial initial decision re site alternatives Decision should be affirmed Certificate of Svc encl
C. A. Hearing Branch 3 81/01/12 42pp 07462 273

45 Order setting 810218 oral argument in Bethesda, MD re intervenors MA Davis & Yacklin River Committee appeal from 800222 partial initial decision Certificate of Svc encl

C. J. Atomic Safety and Licensing Appeal Panel 81/01/13 42p 07472 080

99 Motion for extension to set oral argument on alternative site issue for 810401 Certificate of Svc encl
V. J. M. , PERTER, W. L. Duke Power Co MCGARRY, J. M. Debevoise & Liberman 81/01/21 4pp 07529 226

64 Denies 810117 request for limited appearance statement. Right to make statement is limited to evidentiary hearing & proceeding is now in appellate stage
C. J. Atomic Safety and Licensing Appeal Panel 81/01/22 2p 07547 032

070 Requests to make limited appearance statement
SPRINGER, D. Affiliation Unknown 81/01/17 1p 07547 034

97 Order granting applicant motion to postpone oral argument on appeal from ASLB 800222 partial initial decision until 810401 Certificate of Svc encl
C. J. Atomic Safety and Licensing Appeal Panel 81/01/22 4pp 07556 099

Inspection reports, IE Bulletins & correspondence

16 Forwards IE Info Notice 80-44, "Actuation of ECCB in Recirculation Mode While in Hot Shutdown " No written response required
LY, J. P. Region 2, Atlanta, Office of the Director 80/12/16 1p

Congressional/Executive Correspondence

14 Responds to 801009 ltr re NRC progress in review of CPs, use of resources for Section 110 of NRC 1980 Authorization Act, delay in adjudicatory proceedings & lack of coherent regulatory guidance W/o encl documentation
HEARNE, J. F. Commissioners 80/12/22 4pp

032 Responds to 801009 ltr re NRC progress in review of CPs, use of resources for Section 110 of NRC 1980 Authorization Act, delay in adjudicatory proceedings & lack of coherent regulatory guidance Related documentation encl
HEARNE, J. F. Commissioners 80/12/22 4pp

UNIT-50-470 PERKINS NUCLEAR STATION, UNIT 3

Application/construction stage documents & correspondence

66 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
UT.D.O. Division of Licensing 80/11/26 8pp

F. Security, medical, emergency & fire protection plans

810102007 Ltr to all licensees of operating reactor plants. CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 1/4 by applicants as part of FSAR
EISENHUT, D. O. Division of Licensing 80/11/13 2pp

G. Adjudicatory correspondence

8101050616 Brief in opposition to intervenor EC0029 exceptions to ASLB 800222 Partial Initial Decision 3 holding no obviously superior alternative site exists Decision should be affirmed Certificate of Svc encl
MCGARRY, J. M. , PERTER, W. L. Duke Power Co MCGARRY, J. M. Douglass & Barban 80/12/31 48pp 07307 025

8101150277 Response opposing intervenors' exceptions on appeal of ASLB 800222 partial initial decision re site alternatives Decision should be affirmed Certificate of Svc encl
BARBAN, C. A. Hearing Branch 3 81/01/12 42pp 07462 273

8101160745 Order setting 810218 oral argument in Bethesda, MD re intervenors MA Davis & Yacklin River Committee appeal from ASLB 800222 partial initial decision Certificate of Svc encl
BISHOP, C. J. Atomic Safety and Licensing Appeal Panel 81/01/13 42p 07472 080

8101260499 Motion for extension to set oral argument on alternative site issue for 810401 Certificate of Svc encl
MCGARRY, J. M. Duke Power Co MCGARRY, J. M. Debevoise & Liberman 81/01/21 4pp 07529 226

810127064 Denies 810117 request for limited appearance statement. Right to make statement is limited to evidentiary hearing & proceeding is now in appellate stage
BISHOP, C. J. Atomic Safety and Licensing Appeal Panel 81/01/22 2p 07547 032

--8101270070 Requests to make limited appearance statement
SPRINGER, D. Affiliation Unknown 81/01/17 1p 07547 034

8101280119 Order granting applicant motion to postpone oral argument on appeal from ASLB 800222 partial initial decision until 810401 Certificate of Svc encl
BISHOP, C. J. Atomic Safety and Licensing Appeal Panel 81/01/22 4pp 07556 099

G. Inspection reports, IE Bulletins & correspondence

8101060216 Forwards IE Info Notice 80-44, "Actuation of ECCB in Recirculation Mode While in Hot Shutdown " No written response required
D'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/12/16 1p

U. Congressional/Executive Correspondence

8101080311 Responds to 801009 ltr re NRC progress in review of CPs, use of resources for Section 110 of NRC 1980 Authorization Act, delay in adjudicatory proceedings & lack of coherent regulatory guidance W/o encl documentation
HEARNE, J. F. Commissioners 80/12/22 4pp

--8101080362 Responds to 801009 ltr re NRC progress in review of CPs, use of resources for Section 110 of NRC 1980 Authorization Act, delay in adjudicatory proceedings & lack of coherent regulatory guidance Related documentation encl
HEARNE, J. F. Commissioners 80/12/22 4pp

DOCKET BTR-50-471 CHEROKEE NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D. O. Division of Licensing 80/11/26 8pp

F Security, medical, emergency & fire protection plans

B101070387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing 80/11/13 2pp

G Inspection reports, IE Bulletins & correspondence

B101070320 Forwards supplemental responses to NRC B01016 ltr re violations noted in IE Insp Repts 50-369/80-08, 50-370/80-05, 50-413/80-09, 50-414/80-09, 50-491/80-02, 50-492/80-06 & 50-493/80-06 Final rept to be submitted by B10131
PARKER, W D Duke Power Co 80/11/11 2pp

B101050216 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown" No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/16 1p

H Reportable occurrences, LERs & related correspondence

B101220502 Intern. deficiency rept. originally reported on B01217, re breakdowns in mfg. cleaning & insp processes on shutdown heat exchangers caused by contamination of tube side matl surfaces Exchangers returned to supplier for exam & repair
DAIL, L C Duke Power Co 81/01/15 2pp 07910 026

DOCKET 50-492 CHEROKEE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D G Division of Licensing 80/11/26 8pp

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing 80/11/13 2pp

G Inspection reports, IE Bulletins & correspondence

B101070320 Forwards supplemental responses to NRC B01016 ltr re violations noted in IE Insp Repts 50-369/80-08, 50-370/80-05, 50-413/80-09, 50-414/80-09, 50-491/80-02, 50-492/80-06 & 50-493/80-06 Final rept to be submitted by B10131
PARKER, W D Duke Power Co 80/11/11 2pp

B101060216 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown" No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/16 1p 07391 321

DOCKET 50-493 CHEROKEE NUCLEAR STATION, UNIT 3

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D G Division of Licensing 80/11/26 8pp

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing 80/11/13 2pp

G Inspection reports, IE Bulletins & correspondence

B101070320 Forwards supplemental responses to NRC B01016 ltr re violations noted in IE Insp Repts 50-369/80-08, 50-370/80-05, 50-413/80-09, 50-414/80-09, 50-491/80-02, 50-492/80-06 & 50-493/80-06 Final rept to be submitted by B10131
PARKER, W D Duke Power Co 80/11/11 2pp

B101060216 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown" No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/16 1p 07391 321

DOCKET 50-496 MONTAGUE NUCLEAR POWER STATION, UNIT 1

J Insurance & indemnity information

B101270735 Forwards Endorsement 4 to NElIA Binders EB-15 & EB-16
IFFLAND, R R Northeast Utilities 81/01/22 3pp

B101270744 Forwards Endorsements 65 & 66 to NElIA Policy NF-173
IFFLAND, R R Northeast Utilities 81/01/22 4pp

DOCKET 50-497 MONTAGUE NUCLEAR POWER STATION, UNIT 2

J Insurance & indemnity information

B101270735 Forwards Endorsement 4 to NElIA Binders EB-15 & EB-16
IFFLAND, R R Northeast Utilities 81/01/22 3pp

B101270744 Forwards Endorsements 65 & 66 to NElIA Policy NF-173
IFFLAND, R R Northeast Utilities 81/01/22 4pp

DOCKET 50-498 SOUTH TEXAS PROJECT, UNIT 1

A Application/construction stage documents & correspondence

B101050281 Informs of review of FSAR describing QA program subm support of facility CL Description of QA program in compliance w/regulations & guidelines.
MOONAN, V G Assistant Director for Materials & Qualification Engineering 80/11/18 2pp 07385 047

--B101050288 Safety evaluation supporting operations phase QA g
e Office of Nuclear Reactor Regulation, Director 80/11/18 07385 049

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D G Division of Licensing 80/11/26 8pp

B101270257 Ack receipt of B00924 ltr describing analysis & resp Bechtel recommendations requested by NRC during B00819 public meeting
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/16 1p 07546 029

--B101270257 Forwards util analysis & response to Bechtel recommendations as result of B00819 public meeting
OPREA, G W Houston Lighting & Power Co 80/09/24 8pp 07546 030

B101270918 Ack receipt of B00922 ltr transmitting addl info req during B00912 meeting
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/16 1p 07550 114

--B101270924 Forwards addl info requested during B00912 meeting re-orientation, repair & restart of safety-related welding, concrete restart plans & schedules & interim controls
OPREA, G W Houston Lighting & Power Co 80/09/22 13pp 07550 115

B101080131 Ack receipt of util B00904 documentation re complex restart program & STP welding program per NRC B00430 order to show cause
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/23 1p 07421 061

B101080140 Submits preliminary schedule for complex concrete restart program & GTP welding program for repairs & repair of existing welds & restart plan re safety-related AWS & ASME welding Requests 000913 meeting in Arlington, TX
GPREA, G M Houston Lighting & Power Co 80/09/04 1p
07421 062

B101120388 Ack receipt of B00815 ltr forwarding concrete verification program status repts in response to B00430 order to show cause item 3b
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/23 1p 07439 119

--B101120391 Forwards concrete verification program status repts in response to B00720 show cause order item 3b
GPREA, G M Houston Lighting & Power Co 80/08/15 2pp
07439 120

--B101120393 "Concrete Verification Program" status repts
* Houston Lighting & Power Co 80/08/15 41pp 07439 122

B101270261 Notification of cancellation of B10126-28 meeting w/util in Houston & Bay City, TX to prepare SER input & hearing on mgt qualification
SELLS, D. Licensing Branch 2 80/12/30 1p 07546 038

B101300194 Confirms B10102 discussion & util B01217 & 30 ltrs re ASME safety-related welding 10-wk work plan & resumption of safety-related AWS welding work will commence B10105 ASME welding will be expanded as set forth in util B01217 ltr
SEYFRIT, K V Region 4, Dallas, Office of the Director 81/01/05 2pp 07502 131

B101210628 Confirms B10109 discussion of util B10108 ltr re actions taken in initiating complex concrete work activities Util should inform NRC of plans to extend concrete placement beyond 7-h
SEYFRIT, K V Region 4, Dallas, Office of the Director 81/01/13 2pp 07489 250

E NRC Safety Evaluation Report (SER), supp's & correspondence

B101100577 Notification of B10126 & 28 meeting in Houston, TX & B10127 meeting in Bay City, TX w/util to prepare SER input & to prepare for hearing on mgt qualification.
SELLS, D. Licensing Branch 2 80/12/30 3pp 07444 150

B101270261 Notification of cancellation of B10126-28 meeting w/util in Houston & Bay City, TX to prepare SER input & hearing on mgt qualification
SELLS, D. Licensing Branch 2 80/12/30 1p 07546 038

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FBAR.
EISENHUT, D O Division of Licensing 80/11/13 2pp.

G. Adjudicatory correspondence

B012180257 FOIA request for V Stello closed door statement & items which were not included in show cause order re facility proceeding
EASTMAN, K Citizens Concerned About Nuclear Power, Inc 80/10/29 1p 07271 346

B012180252 Responds to FOIA request for V Stello closed door statement & items which were not included in show cause order re facility proceeding Forwards B00415 transcript & NRC addl response to requests for info
FELTON, J H Division of Rules and Records 09/12/11 1p 07271 345

--B012180263 Transcript of B00415 briefing in Bethesda, MD re investigation of QA-QC problems at facilities Pp 1-72
* Commissioners 80/04/15 73pp

--B012100549 Addl response to Citizens Concerned About Nuclear Power
B01117 requests for info Inspector names withheld per 10CFR2.790. V Stello statement encl Items not encl in show cause order available in LPDR. W/Certificate of SVC
BORDENICK, B M Hearing Branch 4 80/12/08 7pp 03774 351.

B101230192 Third set of interrogatories to Citizens for Equitable Utils, Inc re intended witnesses & testimony in B10504 licensing hearing Certificate of SVC encl
HUDSON, T B, SEIDLE, W C Houston Lighting & Power Co HUDSON, Baker & Betts 81/01/16 3pp 07512 034

B101230198 Fourth set of interrogatories to Citizens Concerned About Nuclear Power, Inc re intended witnesses & testimony in B10504 licensing hearing Certificate of SVC encl
HUDSON, T B, SEIDLE, W C Houston Lighting & Power Co HUDSON, Baker & Betts 81/01/16 3pp 07512 037

B101280577 Requests extension to file motion to compel answers to interrogatories or to compel production of documents within 10 days after applicant receives responses to interrogatories & other requests Certificate of SVC encl
HUDSON, T B, SEIDLE, W C Houston Lighting & Power Co HUDSON, Baker & Betts 81/01/16 12pp 07557 204

--B101280505 Second set of interrogatories & request to produce documents directed to Citizens for Equitable Utils Concerns
GTP const records Certificate of SVC encl
HUDSON, T B Houston Lighting & Power Co HUDSON, Baker & Betts 80/12/05 3pp 07557 219

B101290149 Informs that review of applicant managerial capabilities will be performed on B10217-17 & appropriate SER sections will be issued in Apr 1981 Hearings on QC/QA plans will be deferred until June 1981
REIS, E J Hearing Branch 3 81/01/26 2pp 07566 317

--B101290155 Advises of delay in preparation of Licensee Qualification Branch input re mgt qualification to SER
FEDERCO, R Assistant Director for Licensing 81/01/23 2pp 07566 319

B101290142 Forwards NRC transcript from B00819 public meeting in City, TX per ASLB request during B1119 prehearing conference 11/2 encl
GUTIERREZ, J M Hearing Branch 3 81/01/27 1p 07567 350

B101300022 Advises that NRC by Commission directive cannot provide transcripts during evidentiary hearings Comptroller General opinion encl
GUTIERREZ, J M Hearing Branch 3 81/01/28 5pp 07309 001

I Financial information

B101090223 Forwards annual repts for Houston Lighting & Power, Central Power & Light & financial statements for City of San Antonio, TX & City of Austin, TX
GOLDBERG, J H Houston Lighting & Power Co 80/12/31 1p 07517 045

Q Inspection reports, IE Bulletins & correspondence

B101100260 Forwards IE Insp Repts 50-49B/80-35 & 50-499/80-35, on B01102-07 No noncompliance noted.
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/11/19 2pp 07443 290

--B101100249 IE Insp Repts 50-49B/80-35 & 50-499/80-35 on B01103- noncompliance noted Major areas inspected followup of const activities & review of responses to Insp Repts 50-49B/79-17 & 50-499/79-19
TOMLINSON, D P, CROSSMAN, W A Region 4, Dallas, Office of the Director, HALL, R E Region 4, Dallas, Reactor Construction Engineering Support Branch 80/11/18 3pp 07443 292

B101100072 Advises of review of util B00720 response to NRC B00413 order to show cause & responds to util B01024 corrective actions re safety-related complex concrete const Restart of work will be authorized by immediate action ltr
STELLO, V Office of Inspection & Enforcement, Office of the Director 80/11/21 3pp 07444 313

B101100739 Forwards IE mgt Meeting Repts 50-49B/80-37 & 50-499/80-37 on B01118 No noncompliance noted
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/11/24 1p 07444 058

--B101100746 IE mgt Meeting Repts 50-49B/80-37 & 50-499/80-37 on No noncompliance noted Major areas discussed status of show cause order items & limited work restart
SEYFRIT, K V, CROSSMAN, W A Region 4, Dallas, Office of the Director, SEIDLE, W C Region 4, Dallas, Reactor Construction Engineering Support Branch 80/11/24 3pp 07444 059.

8101140548 Forwards IE Insp Repts 50-498/80-30 & 50-499/80-30 on 801021-31. No noncompliance noted.
SEATTLE W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/07 2pp 07461 132

8101140556 IE Insp Repts 50-498/80-30 & 50-499/80-30 on 801021-31. No noncompliance noted. Major areas inspected const activities.
Unresolved items & show cause orders
HARRIS W C Region 4, Dallas, Office of the Director
TAPPALE L L GILBERT L D Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/02 3pp 07461 134

8101010623 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor For Steam Discharge Vessel at Dresden Unit 2." No response required.
SEATTLE W C Region 4, Dallas, Office of the Director 80/12/08 1p 07391 059

8101060177 Forwards IE Info Notice 80-44, "Activation of ECCS in Recirculation Mode while in Hot Standby." No written response required.
SEATTLE W C Region 4, Dallas, Office of the Director 80/12/16 1p 07391 204

8101276872 Ack receipt of 800910 ltr transmitting commitments in response to 80728 order to show cause & 800819 public meeting re violations in IE Insp Repts 50-498/79-19 & 50-499/79-19
SEATTLE W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/16 1p 07350 062

8101270070 Forwards commitments in response to 800728 order to show cause & 800819 public meeting items classified into three categories
OPREA G W Houston Lighting & Power Co 80/09/18 4pp 07553 063

8101270087 Ack receipt of 800929 ltr transmitting updated response to IE Investigation Repts 50-498/79-19 & 50-499/79-19
SEATTLE W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/16 1p 07375 163

8101270194 Updates response to IE Investigation Repts 50-498/79-19 & 50-499/79-19 Full compliance w/commitment to add site auditors will not be met until 810101
OPREA G W Houston Lighting & Power Co 80/09/29 3pp 07375 164

8101140479 Ack receipt of 800828 ltr transmitting list of completed commitments in response to NRC 800430 order to show cause
SEATTLE W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/23 1p 07458 147

8101140484 Forwards list of completed commitments to NRC 800430 order to show cause per discussions at close of 800819 public meeting
OPREA G W Houston Lighting & Power Co 80/08/28 3pp 07458 148

8101270904 Ack receipt of 800829 ltr transmitting documentation re mod of commitment dates to reflect work load of concrete placements in response to NRC 800430 order to show cause & IE Insp Repts 50-498/79-19 & 50-499/79-19
SEATTLE W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/22 1p 07350 108

8101270907 Informs that amount of work required for order to show cause Item 33 is greater than earlier anticipated. Commitment dates modified.
OPREA G W Houston Lighting & Power Co 80/08/29 3pp 07350 109

8101200151 Ack receipt of ltr 800909 ltr re vibratory rollers used for backfill compaction at facilities in response to NRC 800430 order to show cause. Info & corrective actions will be reviewed during future insps
SEATTLE W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 81/01/13 1p 07309 031

8101300188 Forwards Dynapac rept. "Recent Developments in Field of Dynamic Compaction of Soil-Rock Fill & Asphalt." in response to NRC 800819 request for criteria re vibratory rollers used for backfill compaction at facilities
HARRIS W C Houston Lighting & Power Co 80/09/09 4pp 07309 031

8101300176 Lectures entitled "Recent Developments in Field of Dynamic Compaction of Soil-Rock Fill & Asphalt." presented in Australia, Far East & Iran
* Dynapac, Inc 1113 7-9-1613 26/02/79 27pp 07309 001

8101300182 "Vibratory Compaction in Const of Roads, Airfields, Other Projects"
* Dynapac, Inc 8222 77/02/78 25pp 07309

5. Reportable occurrences, LERs & related correspondence

8101140154 Interior Deficiency, Rept 2 re environ qualification electrical equipment associated w/auxiliary feedwater pumps. Analytical model for isolation valve cubicle structure has been developed. Next rept to be submitted by 810820
OPREA G W Houston Lighting & Power Co 81/01/09 4pp 0

8101140460 Interior deficiency rept re tensile strengths of 1-1/2" cast-in-place expansion anchors. Revised load capacity values are reflected in revised technical ref document. Next rept to be submitted by 810220
OPREA G W Houston Lighting & Power Co 81/01/09 3pp 0

8101280403 P.O.-IV-80-340 by 810108 ltr. Util requested Region 4 authority for limited restart of placement of complex concrete. Limited resumption of complex concrete placement authorized.
HARRIS W C (CHRISMAN, W A) Region 4, Dallas, Office of the Director 81/01/13 1p 07557 057

8101270031 Final deficiency rept. Initially reported 800529, re cooling water intake structure gentry crane seismic analysis SSE response spectra values incorrectly calculated. Crane & diesel generator fuel storage tanks requalified.
OPREA G W Houston Lighting & Power Co 81/01/15 3pp 0

8101280515 Second interim deficiency rept re welding of main steam pipe whip restraints. Initially reported on 800926. Visual reinsp will determine if welds meet AWS D 1.1-1977 requirements. Next rept will be forwarded by 810501
OPREA G W Houston Lighting & Power Co 81/01/15 4pp 0

8101270118 Fifth interim deficiency rept re matl control of ASME A190 structural steel bolts. Originally reported 800617. Required documentation to qualify bolts for Category I has been received. Final rept will be submitted by 810410
OPREA G W Houston Lighting & Power Co 81/01/20 4pp 0

800618 SH-50-499 SOUTH TEXAS PROJECT, UNIT 2

A. Application/construction stage documents & correspondence

8101050281 Informs of review of FSAR describing QA program sub support of facility CL. Description of QA program in compliance w/regulations & guidelines.
MOZAFAN, V S Assistant Director for Materials & Qualification Engineering 80/11/18 2pp 07385 047

8101050288 Safety evaluation supporting operations phase QA
* Office of Nuclear Reactor Regulation, Director. 80/11/07395 049

8101280466 Ltr to all power reactor licensees & applicants for summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D G Division of Licensing 80/11/26 3pp

8101270257 Ack receipt of 800924 ltr describing analysis & recommendations requested by NRC during 800819 public meeting.
SEATTLE W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/16 1p 07346 029

8101270657 Forwards util analysis & response to Dechtel recd made as result of 800819 public meeting.
OPREA G W Houston Lighting & Power Co 80/09/24 3pp 07346 030

8101270918 Ack receipt of 800922 ltr transmitting addl info re during 800912 meeting.
SEATTLE W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/16 1p 07350 114

8101270924 Forwards addl info requested during 800912 meeting re examination, repair & restart of safety-related welding, concrete restart plans & schedules & interim controls.
OPREA G W Houston Lighting & Power Co 80/09/22 13pp 07350 115

DOCKETED ITEMS

B0108013: Ack receipt of util B00904 documentation re complex concrete restart program & STP welding program per NRC B00430 order to show cause
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/23 1p 07421 061

--B01080140 Submits preliminary schedule for complex concrete restart program & STP welding program for reinsp & repair of existing welds & restart plan re safety-related AWS & ASME welding Requests B00913 meeting in Arlington, TX
CPREA, G W Houston Lighting & Power Co 80/09/04 1p 07421 062

B01120388 Ack receipt of B00815 ltr forwarding concrete verification program status rpt. in response to B00430 order to show cause Item 3b
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/12/23 1p 07439 119

--B01120391 Forwards concrete verification program status rpt. in response to B00728 show cause order Item 3b
CPREA, G W Houston Lighting & Power Co 80/08/15 2pp 07439 120

--B01120393 "Concrete Verification Program," status rpt.
Houston Lighting & Power Co 80/08/15, 41pp 07439 122.

B01270261 Notification of cancellation of B01026-2B meeting w/util in Houston & Bay City, TX to prepare SER input & hearing on mgt qualification
SELLS, D Licensing Branch 2 80/12/30 1p

B01300194 Confirms B0102 discussion & util B01217 & 30 ltrs re ASME safety-related welding 10-wk work plan & resumption of safety-related AWS welding work will commence B0105 ASME welding will be expanded as set forth in util B01217 ltr
SEYFRIE, K V Region 4, Dallas, Office of the Director 81/01/05 2pp 07582 131

B01210628 Confirms B0102 discussion of util B0108 ltr re actions taken in initiating complex concrete work activities. Util should inform NRC of plans to extend concrete placement beyond 7-h
SEYFRIE, K V Region 4, Dallas, Office of the Director 81/01/13 2pp 07489 259

E. NRC Safety Evaluation Report (SER), supp's & correspondence

B01100577 Notification of B01026 & 2B meeting in Houston, TX & B01027 meeting in Bay City, TX w/util to prepare SER input & to prepare for hearing on mgt qualification
SELLS, D Licensing Branch 2 80/12/30 3pp 07444 150

B01270261 Notification of cancellation of B01026-2B meeting w/util in Houston & Bay City, TX to prepare SER input & hearing on mgt qualification
SELLS, D Licensing Branch 2 80/12/30 1p 07546 038

F. Security, medical, emergency & fire protection plans

B01090387 Ltr to all licensees of operating reactor plants, CP holders & CP Applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B0102 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing 80/11/13, 2pp

G. Adjudicatory correspondence

B012180257 FOIA request for V Stello closed door statement & items which were not included in show cause order re facility proceeding
EASTMAN, K Citizens Concerned About Nuclear Power, Inc. 80/10/29 1p 07271 346

B012180252 Responds to FOIA request for V Stello closed door statement & items which were not included in show cause order re facility proceeding Forwards B00415 transcript & NRC add'l response to requests for info
FELTON, J M Division of Rules and Records 89/12/11, 1p 07271 345

--B012180263 Transcript of B00415 briefing in Bethesda, MD re investigation of QA-QC problems at facilities. Pp 1-72
Commissioners 89/04/15 73pp

--B012180549 Add'l response to Citizens Concerned About Nuclear Power, Inc. B01117 requests for info Inspector names withheld per 10CFR2 770 V Stello statement encl items not encl in show cause order available in LPSR W/Certificate of Five
B040810003 M Hearing Branch 4 80/12/08 7pp 03774 351

B01230192 Third set of interrogatories to Citizens For Equitable Utils. Inc. re intended witnesses & testimony in B010504 licensing hearing Certificate of Sec encl
HUDSON, T B, LEWIS, J R Houston Lighting & Power Co HUDSON, T B, Baker & Batts 81/01/16 3pp 07512 031

B01230198 Fourth set of interrogatories to Citizens Concerned About Nuclear Power, Inc. re intended witnesses & testimony in B010504 licensing hearing Certificate of Sec encl
HUDSON, T B, LEWIS, J R Houston Lighting & Power Co HUDSON, T B, Baker & Batts 81/01/16 3pp 07512 037

B01280777 Requests extension to file motion to compel answers to interrogatories or to compel production of documents within 10 days after applicant receives responses to interrogatories & other requests Certificate of Sec encl
HUDSON, T B, LEWIS, J R Houston Lighting & Power Co HUDSON, T B, Baker & Batts 81/01/16 12pp 07532 204

--B01280585 Second set of interrogatories & request to produce documents directed to Citizens for Equitable Utils. Concerns STP cost records Certificate of Sec encl
HUDSON, T B Houston Lighting & Power Co HUDSON, T B, Baker & Batts 80/12/05 3pp 07557 219

B01290149 Informs that review of applicant managerial capabilities will be performed on B01217-19 & appropriate SER sections will be issued in Apr 1981 Hearings on QC/QA plans will be deferred until June 1981
REIS, E J Hearing Branch 3 81/01/26 2pp 07546 317

--B01290155 Advises of delay in preparation of Licensee Qualification Branch input re mgt qualification to SER
TEDESCO, R Assistant Director for Licensing 81/01/23 2pp 07566 319

B01290142 Forwards NRC transcript from B00819 public meeting in City, TX per ASME request during B01119 prehearing conference W/o encl
CUTIERREZ, J M Hearing Branch 3 81/01/27 1p 07567 390

B01300022 Advises that NRC, by Commission directive, cannot provide transcripts during evidentiary hearings Controller General opinion encl
CUTIERREZ, J M Hearing Branch 3 81/01/28 5pp 07309 001

J. Financial information

B01090023 Forwards annual repts for Houston Lighting & Power, Central Power & Light & financial statements for City of San Antonio, TX & City of Austin, TX
CULBERG, J H Houston Lighting & Power Co 80/12/31 1p 07517 045

K. Inspection reports, IF Bulletins & correspondence

B01100260 Forwards IE Insp Repts 50-498/80-35 & 50-499/80-35, on B01103-07 No noncompliance noted
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/11/19 2pp 07443 290

--B01100267 IE Insp Repts 50-498/80-39 & 50-499/80-39 on B01103- noncompliance noted Major areas inspected Followup of const activities & review of responses to Insp Repts 50-498/79-19 & 50-499/79-19
TOKLINSO, D P, CROSBYMAN, W A Region 4, Dallas, Office of the Director HALL, R E Region 4, Dallas, Reactor Construction Engineering Support Branch 80/11/10, 3pp 07443 292.

B01100072 Advises of review of util B00728 response to NRC B00415 order to show cause & responds to util B01024 corrective actions re safety-related complex concrete const Restart of work will be authorized by immediate action ltr
STELLO, V Office of Inspection & Enforcement, Office of the Director 80/11/21 3pp 07444 313

B01100759 Forwards IF Mgt Meeting Repts 50-498/80-37 & 50-499/80-37 B01118 No noncompliance noted
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/11/24 1p 07444 058

--B101100765 IE Insp Repts 50-498/80-37 & 50-499/80-37 on B01118
No non-compliance noted Major areas discussed status of show
cause order items & limited work restart
SEYFRIT, K W. CROSSMAN, W A Region 4, Dallas, Office of the
Director SEIDLE, W C Region 4, Dallas, Reactor Construction &
Engineering Support Branch 80/11/24 3pp 07444 059

B101149548 Forwards IE Insp Repts 50-498/80-30 & 50-499/80-30 on
B01021-J1 No non-compliance noted
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering
Support Branch 80/12/03 3pp 07461 132

--B101140556 IE Insp Repts 50-498/80-30 & 50-499/80-30 on B01021-J1 No
non-compliance noted Major areas inspected const activities,
unresolved items & show cause orders
HUZACHEK, W G Region 4, Dallas, Office of the Director
TAFIA, J J, GILBERT, L D Region 4, Dallas, Reactor Construction &
Engineering Support Branch 80/12/02 8pp 07461 134

B101050623 Forwards IE Info Notice 80-43, 'Failures of Continuous Water
Level Monitor for Srian Discharge Vot at Dresden Unit 2' No
response required
SEYFRIT, K W Region 4, Dallas, Office of the Director 80/12/08
1p 07391 059

B101060177 Forwards IE Info Notice 80-44, 'Actuation of ECCS in
Recirculation Mode While in HSB Shutdown' No written
response required
SEYFRIT, K W Region 4, Dallas, Office of the Director 80/12/16
1p 07391 284

B101270872 Ack receipt of B00918 ltr transmitting commitments in
response to B00728 order to show cause & B00819 public
meeting re violations in IE Insp Repts 50-498/79-19 &
50-499/79-19
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering
Support Branch 80/12/16 1p 07350 062

--B101270876 Forwards commitments in response to B00728 order to show
cause & B00819 public meeting Items classified into three
categories.
OPREA, G W Houston Lighting & Power Co 80/09/18 41pp
07350 063

B101290487 Ack receipt of B00929 ltr providing updated response to IE
Investigation Repts 50-498/79-19 & 50-499/79-19
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering
Support Branch 80/12/16 1p 07375 163

--B101290494 Updates response to IE Investigation Repts 50-498/79-19 &
50-499/79-19 Full compliance w/commitment to add site
auditors will not be met until B10101
OPREA, G W Houston Lighting & Power Co 80/09/29 5pp
07375 164

B101140479 Ack receipt of B00828 ltr transmitting list of completed
commitments in response to NRC B00430 order to show
cause
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering
Support Branch 80/12/23 1p 07438 147

--B101140484 Forwards list of completed commitments to NRC B00430 order
to show cause, per discussions at close of B00819 public
meeting
OPREA, G W Houston Lighting & Power Co 80/08/28 3pp
07438 148

B101270904 Ack receipt of B00829 ltr transmitting documentation re mod
of commitment dates to reflect work load of concrete
placements in response to NRC B00430 order to show cause
& IE Insp Repts 50-498/79-19 & 50-499/77-14
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering
Support Branch 80/12/23 1p 07350 108

--B101270909 Informs that amount of work required for order to show cause
Item 33 is greater than earlier anticipated Commitment dates
modified
OPREA, G W Houston Lighting & Power Co 80/08/29 3pp
07350 109

B101260161 Ack receipt of Util B00909 ltr re vibratory rollers used for
backfill compaction at facilities, in response to NRC B00430
order to show cause Info & corrective actions will be
reviewed during future insps
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering
Support Branch 81/01/13 1p 07309 001

--B101300168 Forwards Dynapac rept, 'Recent Developments in Field
Dynamic Compaction of Soil, Rock Fill & Asphalt,' in response
to NRC B00819 request for criteria re vibratory rollers
used for backfill compaction at facilities
BARBER, D G Houston Lighting & Power Co 80/09/09 4cp
07309 001

--B101300176 Lectures entitled 'Recent Developments in Field of
Compaction of Soil, Rock Fill & Asphalt,' presented in
Australia, Far East & Iran
* Dynapac, Inc 1113-7 9-1613 76/02/29 27pp 07309 001

--B101300182 'Vibratory Compaction in Const of Roads, Airfields, D
Other Projects "
FORSEBLED, L Dynapac, Inc 8222 77/02/28 25pp 07309 0

S Reportable occurrences, LERs & related correspondence

B101160454 Interim Deficiency Rept 2 re environ qualification of
electrical equipment associated w/auxiliary feedwater pumps.
Analytical model for isolation valve cubic structure has
been developed Next rept to be submitted by B10820
OPREA, G W Houston Lighting & Power Co 81/01/09 4pp 074

B101160460 Interim deficiency rept re tensile strengths of 1-inc
lark-bolt expansion anchors Revised load capacity values
are reflected in revised technical ref document Next rept
to be submitted by B10320
OPREA, G W Houston Lighting & Power Co 81/01/09 5pp 074

B101280403 PKD-IV-80-34D by B10108 ltr, util requested Region 4
authority for limited restart of placement of complex
concrete Limited resumption of complex concrete placement
authorized
HUZACHEK, W G, CROSSMAN, W A Region 4, Dallas, Office of the
Director 81/01/13 1p 07357 057

B101260331 Final deficiency rept, initially reported B00529, re ex
cooling water intake structure gantry crane seismic
analysis SSE response spectra values incorrectly calculated.
Crane & diesel generator fuel storage tanks requalified
OPREA, G W Houston Lighting & Power Co 81/01/15 5pp 075

B101220515 Second interim deficiency rept re welding of main ste
pipe whip restraints, initially reported on B00926 Visual
reinsp will determine if welds meet AWS D 1 1-1977
requirements Next rept will be forwarded by B10901
OPREA, G W Houston Lighting & Power Co 81/01/15 4pp 075

B101270718 Fifth interim deficiency rept re natl control of ASTM
A490 structural steel bolts, originally reported B00617
Required documentation to qualify bolts for Category I has
been received Final rept will be submitted by B10410.
OPREA, G W Houston Lighting & Power Co 81/01/20 4pp 075

DOCKET 50-500 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forw
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports."
ET6ENHUT, D G Division of Licensing 80/11/26 8pp.

F Security, medical, emergency & fire protection plans

B101040387 Ltr to all licensees of operating reactor plants, CP I
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B10102 & by applicants as part of FSAR.
ET6ENHUT, D G Division of Licensing 80/11/13 2pp.

G Adjudicatory correspondence

B101060910 Order compelling NRC & applicant to file detailed br
by B10219 re steps necessary to complete termination of
proceeding & estimated dates of completion.
COTTER, B P Atomic Safety and Licensing Board Panel. 80/12/1
07401:089

D-501 DAVIS-355SF NUCLEAR POWER STATION, UNIT 2

ation/construction stage documents & correspondence

6 Ltr to all power reactor licensees & applicants forwarding
of B01112 meeting re implementation of guidance for
ved Safety Issue A-12. "Potential for Low Fracture
ss & Lamellar Tearing on Component Supports"
T.D.G. Division of Licensing 80/11/26 8pp

ty, medical, emergency & fire protection plans

7 Ltr to all licensees of operating reactor plants, CP holders
licants Revised radiological emergency response
ust be submitted by licensees within 60 days of
& by applicants as part of FSAR
T.D.G. Division of Licensing 80/11/13 2pp

atory correspondence

0 Order compelling NRC & applicant to file detailed briefs
ing re steps necessary to complete termination of
ing & estimated dates of completion
B.P. Atomic Safety and Licensing Board Panel 80/12/31 1p
089

N-50-508 WPPSS NUCLEAR PROJECT, UNIT 3

ation/construction stage documents & correspondence

6 Ltr to all power reactor licensees & applicants forwarding
of B01112 meeting re implementation of guidance for
ved Safety Issue A-12. "Potential for Low Fracture
ss & Lamellar Tearing on Component Supports"
T.D.G. Division of Licensing 80/11/26 8pp

ty, medical, emergency & fire protection plans

7 Ltr to all licensees of operating reactor plants, CP holders
licants Revised radiological emergency response
ust be submitted by licensees within 60 days of
& by applicants as part of FSAR
T.D.G. Division of Licensing 80/11/13 2pp

tion reports, IE Bulletins & correspondence

0 Forwards IE Info Notice 80-43, "Failures of Continuous Water
onitor for Steam Discharge Vol at Dresden Unit 2"
onse required
N.R.H. Region 5, San Francisco, Office of the Director
9 1p 07390 277

5 Forwards IE Info Notice 80-44, "Actuation of ECCB in
lation Mode While in Hot Shutdown." No response
d.
N.R.H. Region 5, San Francisco, Office of the Director
6 1p 07308 001

0 Ack receipt of B01219 ltr informing NRC of steps taken to
violations noted in IE Insp Repts 90-508/80-12
9/80-12 Addl beam clip will be added to safety-
duct
Q.B. Region 5, San Francisco, Reactor Construction &
ring Support Branch 81/01/12 1p 07497 298

325 Responds to NRC B01126 ltr re violations noted in IE Insp
90-508/80-12 & 50-509/80-12 Corrective actions
informing Wallace/Superior Procedure, DCP 12-12, revised
EE.F.D. Washington Public Power Supply System 80/12/19
07497 299

531 Forwards IE Insp Repts 90-508/80-12 & 50-509/80-12 on
1-24 & notice of violation
KEN, R.H. Region 5, San Francisco, Office of the Director
26 2pp. 07497 303

535 Notice of violation from Insp on 801021-24
gion 5, San Francisco, Office of the Director 80/11/26 1p
7 305

543 IE Insp Repts 90-508/80-12 & 50-509/80-12 on 801021-24
pliance noted nonconforming conditions by heating,
lation & air conditioning contractor not controlled
S.R.C. Region 5, San Francisco, Reactor Construction &
eering Support Branch, HAIST, D.P., WAGNER, W.J. Region 5, San
isco, Office of the Director 80/11/26 8pp. 07497 306

S Reportable occurrences, LEAs & related correspondence

B101200730 Part 21 rept re failure to provide proper Control Components
Intl valves supplying 2 gpm flow when in closed position
Caused by valve failure Affected licensees notified &
selection of alternative method underway
TAYLOR, J.H. Babcock & Wilcox Co 81/01/09 2pp

DOCKET 50-509 WPPSS NUCLEAR PROJECT, UNIT 5

A Application/construction stage documents & correspondence

B101220465 Ltr to all power reactor licensees & applicants forwarding
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issue A-12. "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D.G. Division of Licensing 80/11/26 8pp.

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B10102 & 5; applicants as part of FSAR
EISENHUT, D.G. Division of Licensing 80/11/13 2pp

G Inspection reports, IE Bulletins & correspondence

B101056510 Forwards IE Info Notice 80-43, "Failures of Continuous Water
Level Monitor for Steam Discharge Vol at Dresden Unit 2"
No response required
ENGELKEN, R.H. Region 5, San Francisco, Office of the Director
80/12/05 1p

B101150835 Forwards IE Info Notice 80-44, "Actuation of ECCB in
Recirculation Mode While in Hot Shutdown." No response
required
ENGELKEN, R.H. Region 5, San Francisco, Office of the Director
80/12/16 1p 07308 031

B101220520 Ack receipt of B01219 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-508/80-12
& 50-509/80-12 Addl beam clip will be added to safety-
related duct
SPENCER, J.S. Region 5, San Francisco, Reactor Construction &
Engineering Support Branch 81/01/12 1p 07497 298

--B101220525 Responds to NRC B01126 ltr re violations noted in IE Insp
Repts 50-508/80-12 & 50-509/80-12 Corrective actions
nonconforming Wallace/Superior Procedure, DCP 12-12, revised
MCELWEE, F.D. Washington Public Power Supply System 80/12/19
4pp 07497 299

--B101220531 Forwards IE Insp Repts 50-508/80-12 & 50-509/80-12 on
801021-24 & notice of violation
ENGELKEN, R.H. Region 5, San Francisco, Office of the Director
80/11/26 2pp 07497 303

--B101220535 Notice of violation from Insp on 801021-24
* Region 5, San Francisco, Office of the Director 80/11/26 1p
07497 305

--B101220543 IE Insp Repts 50-508/80-12 & 50-509/80-12 on 801021-24
Noncompliance noted nonconforming conditions by heating,
ventilation & air conditioning contractor not controlled
HAYNES, R.C. Region 5, San Francisco, Reactor Construction &
Engineering Support Branch, HAIST, D.P., WAGNER, W.J. Region 5, San
Francisco, Office of the Director 80/11/26 8pp. 07497 306

S Reportable occurrences, LEAs & related correspondence

B101230730 Part 21 rept re failure to provide proper Control Components
Intl valves supplying 2 gpm flow when in closed position
Caused by valve failure Affected licensees notified &
selection of alternative method underway
TAYLOR, J.H. Babcock & Wilcox Co 81/01/09 2pp

DOCKET 50-510 BLUE HILLS STATION, UNIT 1

G Adjudicatory correspondence

B101280304 Response to ASLB B00909 order requesting briefs & addl info
re early site review portion of CP application Issue
identified in order do not affect issuance of partial
initial decision Certificate of SVC encl
WETTERHAHN, H.J., PLETTMAN, S. Gulf States Utilities Co.
WETTERHAHN, H.J. Conner, Moore & Carter 81/01/23 7pp 07557 154

BUCKET 50-511 BLUE HILLS STATION, UNIT 2

G Adjudicatory correspondence

B10120030 Response to ASLB B00907 order requesting briefs & addl info re early site review portion of CP application Issues identified in order do not affect issuance of partial initial decision Certificate of SVC encl
WETTERMAN, J. J. DIRECTOR, S. Gulf States Utilities Co
WETTERMAN, J. J. Connors, Moore & Corbett 01/01/23 7pp 07557 154

BUCKET 50-512 LAGUNA VERDE STATION

G Inspection reports, IE Bulletins & correspondence

B101140415 Updates licensee corrective actions following NRC B00707-11 Insp of Civil Div of Engineering Design QA organization restructured to provide sufficient organizational freedom, authority & access to NRC
KIPPON, S. H. Tennessee Valley Authority 03/10/00 3pp

BUCKET 50-513 APPS NUCLEAR PROJECT, UNIT 4

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lameillar Tearing on Component Supports"
EISENHUT, D. G. Division of Licensing 00/11/26 6pp

F Security, medical, emergency & fire protection plans

B101040587 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 by applicants as part of FSAR
EISENHUT, D. G. Division of Licensing 30/11/13 2pp

G Inspection reports, IE Bulletins & correspondence

B101040193 Forwards supplemental response to IE Bulletin 79-02, Revision 2 "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts"
HART, D. U. Washington Public Power Supply System 00/11/13 3pp 07399 119

B101050510 Forwards IE Info Notice B0-43, "Failures of Continuous Water Level Monitor for Steam Discharge Val at Dresden Unit 2"
No response required
ENGELKE, R. H. Region 5, San Francisco, Office of the Director 00/12/05 1p

B101150937 Forwards IE Info Notice B0-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown." No response required
ENGELKE, R. H. Region 5, San Francisco, Office of the Director 00/12/16 1p 07308 001

B101200533 Ack receipt of B01212 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts B0-460/B0-13 & 50-513/B0-13
SPENCER, G. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch 01/01/26 1p 07396 041

--B101300555 Responds to NRC B01121 ltr re violations noted in IE Insp Repts 50-460/B0-13 & 50-513/B0-13 Corrective actions QA personnel will provide procurement controls for all substitutions
HART, D. U. Washington Public Power Supply System 00/12/12 4pp 07396 042

--B101300593 Forwards IE Insp Repts 50-460/B0-13 & 50-513/B0-13 on B01020-23 & notice of violation
SPENCER, G. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch 00/11/21 2pp 07396 046

--B101300598 Notice of violation from insp on B01020-23
* Region 5, San Francisco, Office of the Director 00/11/21 1p 07396 048

--B101302604 IE Insp Repts 50-460/B0-13 & 50-513/B0-13 on B01020-23 Noncompliance noted failure to provide adequate procurement controls for paint to be used within containment.
HART, D. U. KINSCH, D. F. NARBUT, P. P. Region 5, San Francisco, Office of the Director 00/11/21 10pp 07396 049

5 Reportable occurrences, LERs & related correspondence

B101200230 Part 21 report re failure to provide proper Control Corp Intl valves supplying 2 gpm flow when in closed position caused by valve failure Affected licensees notified & selection of alternative method underway
TAYLOR, J. H. Babcock & Wilcox Co 01/01/04 2pp

BUCKET 50-514 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lameillar Tearing on Component Supports"
EISENHUT, D. G. Division of Licensing 00/11/26 6pp

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 by applicants as part of FSAR
EISENHUT, D. G. Division of Licensing 00/11/13 2pp

G Adjudicatory correspondence

B101070169 Fourth status report per ASLB B00721 order Applicant filed proposed findings of fact & conclusions of law on B01022 NRC
filed same on B01202 Certificate of SVC encl
SCORDEWICK, B. H. Hearing Branch 4 00/12/31 4pp 07415 122

V Congressional/Executive Correspondence

B101080314 Responds to B01009 ltr re NRC progress in review of CP of resources for Section 110 of NRC 1980 Authorization Act, delay in adjudicatory proceedings & lack of coherent regulatory guidance N/A encl documentation
AHEARNE, J. F. Commissioners 00/12/22 4pp

--B101080362 Responds to B01009 ltr re NRC progress in review of CP of resources for Section 110 of NRC 1980 Authorization Act, delay in adjudicatory proceedings & lack of coherent regulatory guidance Related documentation encl
AHEARNE, J. F. Commissioners 00/12/22 4pp

BUCKET 50-515 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lameillar Tearing on Component Supports"
EISENHUT, D. G. Division of Licensing 00/11/26 6pp

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 by applicants as part of FSAR
EISENHUT, D. G. Division of Licensing 00/11/13 2pp

G Adjudicatory correspondence

B101070169 Fourth status report per ASLB B00721 order Applicant filed proposed findings of fact & conclusions of law on B01022 NRC
filed same on B01202 Certificate of SVC encl
SCORDEWICK, B. H. Hearing Branch 4 00/12/31 4pp 07415 122

V Congressional/Executive Correspondence

B101080314 Responds to B01009 ltr re NRC progress in review of CP of resources for Section 110 of NRC 1980 Authorization Act, delay in adjudicatory proceedings & lack of coherent regulatory guidance N/A encl documentation
AHEARNE, J. F. Commissioners 00/12/22 4pp

--B101080362 Responds to B01009 ltr re NRC progress in review of CP of resources for Section 110 of NRC 1980 Authorization Act, delay in adjudicatory proceedings & lack of coherent regulatory guidance Related documentation encl
AHEARNE, J. F. Commissioners 00/12/22 4pp

14-50-516 JAMESPORT NUCLEAR STATION, UNIT 1
 Mandatory correspondence

 23 Response supporting applicants B01219 request to end pending
 & CP proceedings Outstanding CPs should be revoked
 date of Svc encl
 CX, B M Hearing Branch 4 B1/01/08 6pp 07445 171

 27 Memorandum & order granting applicants' motion to dismiss
 AELB decision authorizing const is vacated due to
 & CP proceeding terminated Ofc of Nuclear Reactor
 tion will revoke CPs Certificate of Svc encl
 C J Atomic Safety and Licensing Appeal Panel B1/01/15
 07486 334

 28 Inspection reports, IE Bulletins & correspondence

 34 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on
 Turbine Steam Inlet Flange " No written response
 d.
 H Region 1, Philadelphia, Office of the Director
 6 1p 07414 071

 33 Forwards IE Info Notice 80-44, "Actuation of ECCB in
 Station Mode While in Hot Shutdown " No written
 e required
 H Region 1, Philadelphia, Office of the Director
 6 1p 07397 029

 14-50-517 JAMESPORT NUCLEAR STATION, UNIT 2
 Mandatory correspondence

 23 Response supporting applicants B01219 request to end pending
 & CP proceedings Outstanding CPs should be revoked
 date of Svc encl
 CX, B M Hearing Branch 4 B1/01/08 6pp 07445 171

 27 Memorandum & order granting applicants' motion to dismiss
 AELB decision authorizing const is vacated due to
 & CP proceeding terminated Ofc of Nuclear Reactor
 tion will revoke CPs Certificate of Svc encl
 C J Atomic Safety and Licensing Appeal Panel B1/01/15
 07486 334

 28 Inspection reports, IE Bulletins & correspondence

 34 Forwards Suppl 1 to IE Info Notice 80-29, "Broken Studs on
 Turbine Steam Inlet Flange " No written response
 d.
 H Region 1, Philadelphia, Office of the Director
 6 1p 07414 071

 33 Forwards IE Info Notice 80-44, "Actuation of ECCB in
 Station Mode While in Hot Shutdown " No written
 e required
 H Region 1, Philadelphia, Office of the Director
 6 1p 07397 029

 14-50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1
 Mandatory correspondence

 26 Ltr to all power reactor licensees & applicants forwarding
 of B01112 meeting re implementation of guidance for
 Revised Safety Issue A-12, "Potential for Low Fracture
 & Lamellar Tearing on Component Supports "
 T.D O Division of Licensing 80/11/26 6pp

 27 Forwards Amends 4 to CPRR-150, CPRR-151, CPRR-152 & CPRR-153
 CER.A Licensing Branch 2 80/12/29 4pp 07477 261

 28 Amends 4 to CPRR-150, CPRR-151, CPRR-152 & CPRR-153, deleting
 requirements for monitoring primary water quality & const
 ts to determine impact on water quality & aquatic biota
 Cumberland River
 CER.A Licensing Branch 2 80/12/29 4pp 07477 265

 29 Notice of issuance of Amends 4 to CPRR-150, CPRR-151 &
 152 & CPRR-153
 CER.A Licensing Branch 2 80/12/29 2pp 07477 269

 B0102064F Advises that AHS issue will be subj of future rulemaking to
 determine requirements & schedules for plant needs NRC will
 not comment until B00917 ltr describing program for
 resolving issue until rulemaking is finalized
 EISENHUT, D G Division of Licensing 80/12/29 2pp

 B0102904E Summary of B01114 meeting w/Hartsville Project Coordination
 Committee & utility data relationship Committee dissatisfied
 w/retent labor layoffs technical advice & financial support
 for interconnecting water sys requested
 VERLSEA, S Licensing Branch 2 B1/01/14 4pp 07515 153

 F Security, Medical, emergency & fire protection plans

 B0100903B Ltr to all licensees of operating reactor plants, CP holders
 & CP applicants Revised radiological emergency response
 plans must be submitted by licensees within 60 days of
 B01002 & by applicants as part of FSAR
 EISENHUT, D G Division of Licensing 80/11/13 2pp

 B0102100F Transcript of B01217 briefing on TVA emergency offsite
 facilities in Washington, DC Pg 1-45
 * Commissioners 80/12/17 49pp

 28 Inspection reports, IF Bulletins & correspondence

 B01010064 Forwards IE Insp Repts 50-518/80-23, 50-519/80-22,
 50-520/80-23 & 50-521/80-21 on B00429-1078 No noncompliance
 noted
 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering
 Support Branch 80/11/26 2pp 07444 143

 --B010100472 IE Insp Repts 50-518/80-23, 50-519/80-22, 50-520/80-23 &
 50-521/80-21 on B00924-1028 No noncompliance noted Major
 areas inspected A-2 & 3-1 reactor pressure vessel storage
 & operation review
 SHAW, H B Region 2, Atlanta, Office of the Director
 CAMRELL, F B Region 2, Atlanta, Reactor Construction &
 Engineering Support Branch 80/11/26 9pp 07444 145

 B01005098 Forwards IE Info Notice 80-43, "Failures of Continuous Water
 Level Monitor for Steam Discharge Vol at Dresden Unit 3 " No
 response required
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/30
 1p

 B010080267 Ack receipt of B00922 & 1027 ltrs informing NRC of steps
 taken to correct violation noted in IE Insp Repts
 50-518/80-17 & 50-520/80-17 Disagree w/response refuting
 items of noncompliance
 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering
 Support Branch 80/12/05 4pp 07421 063

 --B010080792 Forwards addl response to NRC B00828 ltr re violations noted
 in IE Insp Repts 50-518/80-17 & 50-520/80-17 Re-evaluation
 supports previous disagreement w/items of noncompliance
 MILLS, L M Tennessee Valley Authority 80/10/27 3pp
 07421 067

 --B010080397 Respc to NRC B00828 ltr re violations noted in IE Insp
 Repts 50-518/80-17 & 50-520/80-17 Disagree that magnetic
 particle examination procedure was in violation of ASME
 requirements
 MILLS, L M Tennessee Valley Authority 80/09/22 6pp
 07421 070

 --B010080318 Forwards IE Insp Repts 50-518/80-17 & 50-520/80-17 on
 B00804-08 & notice of violation
 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering
 Support Branch 80/08/28 2pp 07421 076

 --B010080326 Notice of violation from insp on B00304-08
 * Region 2, Atlanta, Office of the Director 80/08/27 1p
 07421 076

 --B010080343 IE Insp Repts 50-518/80-17 & 50-520/80-17 on B00004-08
 Noncompliance noted inadequate magnetic particle examination
 program & qualification requirements for visual examiners
 ZACARI, D Region 2, Atlanta, Office of the Director HERDT, A R
 Region 2, Atlanta, Reactor Construction & Engineering Support
 Branch 80/09/27 6pp 07421 079

 B010080153 Forwards IE Info Notice 80-45, "Potential Failure of BWR
 Backup Manual Steam Capability " No response required
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/17
 1p

810106023 Forwards Suppl 4 to IE Bulletin 80-17. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR." No written response required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/18 1p 07-12 317

8101090217 Forwards IE Bulletin 80-25. "Operating Problems W/Target Rock Safety Relief Valves at BWRs." No response required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/19 1p 07389 055

8101090544 Forwards IE Insp Repts 50-518/80-19, 50-519/80-18, 50-520/80-14 & 50-521/80-17 on 801028-31 No noncompliance noted.
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/12/19 2pp 07575 257

8101090549 IE Insp Repts 50-518/80-19, 50-519/80-18, 50-520/80-14 & 50-521/80-17 on 801028-31 No noncompliance noted. Major areas inspected wgt controls, CP environ conditions & commitments & status of site spill program.
CUMMINGHAM, A L Region 2, Atlanta, Office of the Director
JEWKINS, G R Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/12/19 5pp 07575 259

8101190051 Forwards response to IE Bulletin 80-23 re failure of Valcor Engineering Corp solenoid valves. Valcor solenoid valves 070900-21-1 & 070900-21-3 not used until waiting for vendor response re valves in package components.
MILLS, L M Tennessee Valley Authority 80/12/29 2pp 07475 215

8101200135 Responds to IE Bulletin 80-21. Valve Yokes Supplied by Malcolm Foundry Co, Inc. Util awaiting vendor response that parts do not contain Malcolm Foundry yokes. Final rept will be filed by 010527.
MILLS, L M Tennessee Valley Authority 81/01/05 1p 07307 001

S. Reportable occurrences, IERs & related correspondence

8101230718 Final Part 21 rept re cracks in reactor pressure vessel shield wall inner shell plates, initially reported on 800314. Cause not determined. Shield wall repaired w/GE-approved metal & welding procedures changed.
MILLS, L M Tennessee Valley Authority 80/12/31 3pp 07308 001

8101140499 Interim Deficiency Rept 1 re fillet weld misspecification. American Inst of Steel Const stds are being evaluated. Originally reported on 801208.
MILLS, L M Tennessee Valley Authority 81/01/07 2pp 07308 001

8101210240 First interim deficiency rept re pressure drop in essential svc water piping, initially reported on 801210. Util is reanalyzing essential svc water piping & high pressure fire protection piping. Final rept will be submitted by 810320.
MILLS, L M Tennessee Valley Authority 81/01/12 3pp 07489 077

8101220311 Forwards first interim rept re potential flammability of suspended ceiling tile in control rooms in response to 801104. For Addl info to be provided by 810211.
MILLS, L M Tennessee Valley Authority 81/01/14 3pp

8101230426 Second supplemental deficiency rept, originally reported on 800618, re heaters omitted from motor operator. GE anticipates shipping deficient motor replacements by 811101.
MILLS, L M Tennessee Valley Authority 81/01/16 1p 07308 001

8101290489 Corrects numbers on Util 810109 & 12 interim deficiency repts re pressure drop in essential svc water piping & standby gas treatment design deficiency.
MILLS, L M Tennessee Valley Authority 81/01/20 1p 07566 325

DOCKET SIN-50-519 HARTSVILLE NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D G Division of Licensing 80/11/26 8pp

8101200557 Forwards Amdts 4 to CPR-150, CPR-151, CPR-152 & CPR-153
SCHWENCER, A Licensing Branch 2 80/12/29 4pp 07477 261

8101200563 Amdts 4 to CPR-150, CPR-151, CPR-152 & CPR-153, deleting requirements for monitoring primary water quality & const effects to determine impact on water quality & aquatic biota of Cumberland River.

8101200567 Notice of issuance of Amdts 4 to CPR-150, CPR-152 & CPR-153
SCHWENCER, A Licensing Branch 2 80/12/29 2pp

8101210447 Advises that AWC issue will be subj of future determine requirements & schedule for plant mods NRC not comment on Util 800417 ltr describing program for resolving issue until rulemaking is finalized.
EISENHUT, D G Division of Licensing 80/12/29 2pp

8101290485 Summary of 801114 meeting w/Hartsville Prod Committee & Util re work relationship Committee dissa w/current labor layoffs. Technical advice & financial a for interconnecting water sys requested.
EISENHUT, D G Division of Licensing 81/01/14 4pp 07

F. Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor 1 & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR.
EISENHUT, D G Division of Licensing 80/11/13 2pp

8101210407 Transcript of 801217 briefing on TVA emergency facilities in Washington, DC. Pp 1-49.
Commissioners 80/12/17 49pp

G. Inspection reports, IE Bulletins & correspondence

8101140619 Updates licensee corrective actions following inspg of Util Div of Engineering Design QA organization restructured to provide sufficient organizational freedom authority & access to mgmt.
KIMMEL, S G H Tennessee Valley Authority 80/10/08

810100664 Forwards IE Insp Repts 50-518/80-23, 50-519/80-22, 50-520/80-23 & 50-521/80-21 on 800929-1028. No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Reactor Construction Support Branch 80/11/26 2pp 07444 143

8101100572 IE Insp Repts 50-518/80-23, 50-519/80-22, 50-520/80-21 on 800929-1028. No noncompliance noted. Areas inspected A-2 & B-1 reactor pressure vessel & open item review.
SWAN, W B Region 2, Atlanta, Office of the Director
CANTRELL, F S Region 2, Atlanta, Reactor Construction Engineering Support Branch 80/11/26 5pp 07444

8101050588 Forwards IE Info Notice 80-43, "Failures of Level Monitor for Scram Discharge Val at Dresden Unit." Response required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 1p

8101050153 Forwards IE Info Notice 80-45, "Potential Failure Backup Manual Scram Capability." No response required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 1p

8101070023 Forwards Suppl 4 to IE Bulletin 80-17. "Failure of Control Rods to Fully Insert During Scram at BWR." No written response required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 1p 07413 317

8101050217 Forwards IE Bulletin 80-25. "Operating Problems Rock Safety Relief Valves at BWRs." No response required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 1p 07389 055

8101290544 Forwards IE Insp Repts 50-518/80-19, 50-519/80-18, 50-520/80-19 & 50-521/80-17 on 801028-31. No noncompliance noted.
STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Branch 80/12/19 2pp 07575 257

8101290549 IE Insp Repts 50-518/80-19, 50-519/80-18, 50-520/80-19 & 50-521/80-17 on 801028-31. No noncompliance noted. Major areas inspected wgt controls, CP environ conditions & commitments & status of site spill program.
CUMMINGHAM, A L Region 2, Atlanta, Office of the Director
JEWKINS, G R Region 2, Atlanta, Fuel Facility & Materials Branch 80/12/19 5pp 07575 259

8101190C51 Forwards response to IE Bulletin 80-23 re failure of Valcor Engineering Corp solenoid valves Valcor solenoid valves V7C900-21-1 & V70900-21-3 not used until waiting for vendor response on valves in package components
MILLS:L M Tennessee Valley Authority 80/12/29 3pp 07475 215

8101290236 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Util awaiting vendor response that parts do not contain Malcolm Foundry yokes Final rept will be filed by 810527
MILLS:L M Tennessee Valley Authority 81/01/05 1p 07309 001

B Reportable occurrences, LERs & related correspondence

8101140499 Interim Deficiency Rept 1 re fillet weld misspecification American Inst of Steel Const stds are being evaluated. Originally reported on 801208
MILLS:L M Tennessee Valley Authority 81/01/07 2pp 07308 001

8101210390 First interim deficiency rept re pressure drop in essential svc water piping, initially reported on 801210 Util is reanalyzing essential svc water piping & high pressure fire protection piping Final rept will be submitted by 810320
MILLS:L M Tennessee Valley Authority 81/01/12 3pp 07489 077

8101220311 Forwards first interim rept re potential flammability of suspended ceiling tile in control rooms in response to 801104 ltr Addl info to be provided by 810211
MILLS:L M Tennessee Valley Authority 81/01/14 3pp

8101290489 Corrects numbers on util 810109 & 12 interim deficiency repts re pressure drop in essential svc water piping & standby gas treatment design deficiency
MILLS:L M Tennessee Valley Authority 81/01/20 1p 07566 325

DOCKET STN-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3

A Application/construction stage documents & correspondence

8101220166 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT,D O Division of Licensing 80/11/26 8pp

8101200557 Forwards Amends 4 to CPPR-150, CPPR-151, CPPR-152 & CPPR-153
SCHWENCER,A Licensing Branch 2 80/12/29 4pp 07477 261

--8101200563 Amends 4 to CPPR-150, CPPR-151, CPPR-152 & CPPR-153, deleting requirements for monitoring primary water quality & const effects to determine impact on water quality & aquatic biota of Cumberland River
SCHWENCER,A Licensing Branch 2 80/12/29 4pp 07477 265

--8101200567 Notice of issuance of Amends 4 to CPPR-150, CPPR-151 & CPPR-152 & CPPR-153
SCHWENCER,A Licensing Branch 2 80/12/29 2pp 07477 269

8101210642 Advises that ATWS issue will be subj of future rulemaking to determine requirements & schedules for plant mode NRC will not comment on util 800917 ltr describing program for resolving issue until rulemaking is finalized
EISENHUT,D O Division of Licensing 80/12/29 2pp

8101290485 Summary of 801114 meeting w/Hartsville Project Coordination Committee & util re work relationship Committee dissatisfied w/recent labor layoffs Technical advice & financial support for interconnecting water sys requested
KEBLUSEK,S Licensing Branch 2 81/01/14 4pp 07575 153

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of FSAR
EISENHUT,D O Division of Licensing 80/11/13 2pp

8101210607 Transcript of 801217 briefing on TVA emergency offsite facilities in Washington, DC Pp 1-45
* Commissioners 80/12/17 47pp

G Inspection reports, IE Bulletins & correspondence

8101140619 Updates licensee corrective actions following NRC 800701 insp of Util Div of Engineering Design Organization restructured to provide sufficient organizational freedom, authority & access to mgt
KIMPHUIS,G H Tennessee Valley Authority 80/10/08 3pp

8101160564 Forwards IE Insp Repts 50-518/80-23, 50-519/80-22, 50-520/80-23 & 50-521/80-21 on 800921-1028 No noncompliance noted
MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/26 2pp 07444 143

--8101160572 IE Insp Repts 50-518/80-23, 50-519/80-22, 50-520/80-23 & 50-521/80-21 on 800929-1028 No noncompliance noted Major areas inspected A-2 & 3-1 reactor pressure vessel storage & open item review
SARLAW,G Region 2, Atlanta, Office of the Director
CARRELL,F B Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/26 5pp 07444 145

8101650589 Forwards IE Info Notice 80-43, "Failures of Continuous Level Monitor for Steam Discharge Val at Dresden Unit 2." No response required
O'REILLY,J P Region 2, Atlanta, Office of the Director 80/12/1p

8101660667 Ack receipt of 800922 & 1027 ltrs informing NRC of steps taken to correct violation noted in IE Insp Repts 50-516/80-17 & 50-520/80-17 Disagrees w/response refuting items of noncompliance
MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/12/05 4pp 07421 063

--810180272 Forwards addl response to NRC 800828 ltr re violations in IE Insp Repts 50-518/80-17 & 50-520/80-17 Re-evaluation supports previous disagreement w/items of noncompliance
MILLS:L M Tennessee Valley Authority 80/10/27 3pp 07421 067

--810180307 Responds to NRC 800828 ltr re violations noted in IE Repts 50-518/80-18 & 50-520/80-17 Disagrees that magnetic particle examination procedure was in violation of ASME requirements
MILLS:L M Tennessee Valley Authority 80/09/22 6pp 07421 070

--810180318 Forwards IE Insp Repts 50-518/80-17 & 50-520/80-17 on 800804-08 & notice of violation
MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/28 2pp 07421 076

--810180326 Notice of violation from insp on 800804-08
* Region 2, Atlanta, Office of the Director 80/08/27 1p 07421 078

--810180343 IE Insp Repts 50-518/80-17 & 50-520/80-17 on 800804-0 Noncompliance noted, inadequate magnetic particle examination program & qualification requirements for visual examiners
ZACAR,L D Region 2, Atlanta, Office of the Director
HERDT, Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/27 4pp 07421 074

8101660153 Forwards IE Info Notice 80-45, "Potential Failure of BW Backup Manual Gear Capability." No response required
O'REILLY,J P Region 2, Atlanta, Office of the Director 80/12/1p

8101070023 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of 76 Control Rods to Fully Insert During Steam at BWR." No written response required
O'REILLY,J P Region 2, Atlanta, Office of the Director 80/12/1p 07413 317

8101050217 Forwards IE Bulletin 80-25, "Operating Problems w/Targ Rock Safety Relief Valves at BWRs." No response required
O'REILLY,J P Region 2, Atlanta, Office of the Director 80/12/1p 07389 055

8101290544 Forwards IE Insp Repts 50-518/80-19, 50-519/80-18, 50-520/80-19 & 50-521/80-17 on 801028-31 No noncompliance noted
STCHR,J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/12/19 2pp 07575 297

-B101240517 IE Insp Repts 50-518/80-19, 50-519/80-18, 50-520/80-19 & 50-521/80-17 on 801028-31 No noncompliance noted Major areas inspected ngt controls, CP environ conditions & commitments & status of site spill program
CUNNINGHAM, A L Region 2, Atlanta, Office of the Director
JENNINGS, G R Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/12/19 2pp 07275 257

B10190041 Forwards response to IE Bulletin 80-23 re failure of Valcor Engineering Corp solenoid valves Valcor solenoid valves V20900-21-1 & V20900-21-3 not used Util waiting for vendor response on valves in package components
MILLS, L M Tennessee Valley Authority 80/12/29 2pp 07475 215

B101290236 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co, Inc. Util awaiting vendor response that parts do not contain Malcolm Foundry yokes Final rept will be filed by B10527
MILLS, L M Tennessee Valley Authority 81/01/05 1p 07309 001

S Reportable occurrences, LERs & related correspondence

B101140499 Interim Deficiency Rept 1 re fillet weld misspecification American Inst of Steel Const stds are being evaluated
Originally reported on 801208
MILLS, L M Tennessee Valley Authority 81/01/07 2pp 07308 001

B101210390 First interim deficiency rept re pressure drop in essential svc water piping, initially reported on 801210 Util is reanalyzing essential svc water piping & high pressure fire protection piping Final rept will be submitted by B10320
MILLS, L M Tennessee Valley Authority 81/01/12 3pp 07489 077

B101220311 Forwards first interim rept re potential flammability of suspended ceiling tile in control rooms in response to B01104 ltr Addl info to be provided by B10211
MILLS, L M Tennessee Valley Authority 81/01/14 3pp

B101290469 Corrects numbers on util B10109 & 12 interim deficiency repts re pressure drop in essential svc water piping & standby gas treatment design deficiency
MILLS, L M Tennessee Valley Authority 81/01/20 1p 07866 325

BUCKET SIX: 50-521 HARTSVILLE NUCLEAR PLANT, UNIT 4

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lateral Tearing on Component Supports"
EISENHUT, D G Division of Licensing 80/11/26 8pp

B101207557 Forwards Amends 4 to CFR-150, CFR-151, CFR-152 & CFR-153
SCHUENGER, A Licensing Branch 2 80/12/29 4pp

--B101260553 Amends 4 to CFR-150, CFR-151, CFR-152 & CFR-153, deleting requirements for monitoring primary water quality & const effects to determine impact on water quality & aquatic biota of Cumberland River
SCHUENGER, A Licensing Branch 2 80/12/29 4pp

--B101200567 Notice of issuance of Amends 4 to CFR-150, CFR-151 & CFR-152 & CFR-153
SCHUENGER, A Licensing Branch 2 80/12/29 2pp

B101210642 Advises that ATUS issue will be subj of future rulemaking to determine requirements & schedules for plant mode NRC will not comment on Util B00917 ltr describing program for resolving issue until rulemaking is finalized.
EISENHUT, D G Division of Licensing 80/12/29 2pp

B101290485 Summary of B01114 meeting w/Hartsville Project Coordination Committee & Util re work relationship Committee dissatisfied w/recent labor layoffs Technical advice & financial support for interconnecting water sys requested.
AEHLUSEN, B Licensing Branch 2 81/01/14 4pp

F Security, medical, emergency & fire protection plans

B101290337 Ltr to all licensees of operating reactor plants, CP holders & CP applicants, Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FEAR
EISENHUT, D G Division of Licensing 80/11/13 2pp

B101210607 Transcript of B01217 briefing on TVA emergency offsite facilities in Washington, DC Pp 1-45
Commissioners 80/12/17 49pp

G Inspector reports, IE Bulletins & correspondence

B101140619 Updates licensee corrective actions following NRC B0070 Insp of Util Div of Engineering Design QA organization restructured to provide sufficient organizational freedom, authority, & access to mgt
KIRKENDALL, G H Tennessee Valley Authority 80/10/08 3pp

B101100664 Forwards IE Insp Repts 50-518/80-23, 50-519/80-22, 50-520/80-23 & 50-521/80-21 on 800927-1028 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/26 2pp

-B101100672 IE Insp Repts 50-518/80-23, 50-519/80-22, 50-520/80-23 & 50-521/80-21 on 800929-1028 No noncompliance noted Major areas inspected A-2 & B-1 reactor pressure vessel storage & open item review
SWEENEY, H B Region 2, Atlanta, Office of the Director 80/11/26 5pp

B101050568 Forwards IE Info Notice 80-43, "Failures of Continuous Level Monitor for Scram Discharge Val at Dresden Unit 2 " No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/1p

B101050153 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Scram Capability " No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/1p

B101070023 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of 76 Control Rods to Fully Insert During Scram at BWR " No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/1p

B101050217 Forwards IE Bulletin 80-25, "Operating Problems w/Targe Rock Safety Relief Valves at BWRs " No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/1p

B101290544 Forwards IE Insp Repts 50-518/80-19, 50-519/80-18, 50-520/80-19 & 50-521/80-17 on 801028-31 No noncompliance noted
STONER, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/12/19 2pp

--B101290549 IE Insp Repts 50-518/80-19, 50-519/80-18, 50-520/80-19 & 50-521/80-17 on 801028-31 No noncompliance noted Major areas inspected ngt controls, CP environ conditions & commitments & status of site spill program
CUNNINGHAM, A L Region 2, Atlanta, Office of the Director 80/12/19 5pp

B101190051 Forwards response to IE Bulletin 80-23 re failure of Val Engineering Corp solenoid valves Valcor solenoid valves V20900-21-1 & V20900-21-3 not used Util waiting for vendor response on valves in package components
MILLS, L M Tennessee Valley Authority 80/12/29 2pp

B101290236 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co, Inc. Util awaiting vendor response that parts do not contain Malcolm Foundry yokes Final rept will be filed by B10527
MILLS, L M Tennessee Valley Authority 81/01/05 1p

S Reportable occurrences, LERs & related correspondence

B101140499 Interim Deficiency Rept 1 re fillet weld misspecification American Inst of Steel Const stds are being evaluated
Originally reported on 801208
MILLS, L M Tennessee Valley Authority 81/01/07 2pp

B101210390 First interim deficiency rept re pressure drop in essential svc water piping, initially reported on 801210 Util is reanalyzing essential svc water piping & high pressure fire protection piping Final rept will be submitted by B10320
MILLS, L M Tennessee Valley Authority 81/01/12 3pp

B101220311 Forwards first interim rept re potential flammability of suspended ceiling tile in control rooms in response to B01104 ltr Addl info to be provided by B10211
MILLS, L M Tennessee Valley Authority 81/01/14 3pp

040387 Corrects numbers on Util B10109 & 12 interim deficiency
lets re pressure drop in essential svc water piping &
addby gas treatment design deficiency
L5.1.R Tennessee Valley Authority 81/01/20 1p

STN-50-522 SKAGIT NUCLEAR PLANT, UNIT 1

Application/construction stage documents & correspondence

040466 Ltr to all power reactor licensees & applicants forwarding
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

Security, medical, emergency & fire protection plans

040387 Ltr to all licensees of operating reactor plants, CP holders
CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

Adjudicatory correspondence

010388 Submits applicant second quarterly status rept per ASLO
Order of B00827 Geological & geophysical program involved
essential field work by consultants, including drilling,
mapping & geological mapping Related correspondence
EISENHUT, D O Puget Sound Power & Light Co 80/12/24 3pp
069 088

050625 Order granting Skagit County, WA B01124 motion to withdraw
from proceeding
ALE, V B Atomic Safety and Licensing Board Panel 80/12/31 2pp
0387 261

Congressional/Executive Correspondence

080314 Responds to B01009 ltr re NRC progress in review of CPs use
of resources for Section 110 of NRC 1980 Authorization Act.
delay in adjudicatory proceedings & lack of coherent
regulatory guidance N/A encl documentation
WEAHRNE, J F Commissioners 80/12/22 4pp

01080362 Responds to B01009 ltr re NRC progress in review of CPs use
of resources for Section 110 of NRC 1980 Authorization Act.
delay in adjudicatory proceedings & lack of coherent
regulatory guidance Related documentation encl
WEAHRNE, J F Commissioners 80/12/22 4pp

STN-50-523 SKAGIT NUCLEAR PLANT UNIT 2

Application/construction stage documents & correspondence

040466 Ltr to all power reactor licensees & applicants forwarding
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

010388 Submits applicant second quarterly status rept per ASLO
Order of B00827 Geological & geophysical program involved
essential field work by consultants, including drilling,
mapping & geological mapping Related correspondence
EISENHUT, D O Puget Sound Power & Light Co 80/12/24 3pp
069 088

Security, medical, emergency & fire protection plans

040387 Ltr to all licensees of operating reactor plants, CP holders
CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing 80/11/13 2pp

Adjudicatory correspondence

050625 Order granting Skagit County, WA B01124 motion to withdraw
from proceeding
ALE, V B Atomic Safety and Licensing Board Panel 80/12/31 2pp
0387 261

Congressional/Executive Correspondence

01080314 Responds to B01009 ltr re NRC progress in review of CPs use
of resources for Section 110 of NRC 1980 Authorization Act.
delay in adjudicatory proceedings & lack of coherent
regulatory guidance N/A encl documentation
WEAHRNE, J F Commissioners 80/12/22 4pp

01080362 Responds to B01009 ltr re NRC progress in review of CPs use
of resources for Section 110 of NRC 1980 Authorization Act.
delay in adjudicatory proceedings & lack of coherent
regulatory guidance Related documentation encl
WEAHRNE, J F Commissioners 80/12/22 4pp

BUCKET 50-524 BARTON UNIT 1

Adjudicatory correspondence

0101090370 Forwards NRC response to applicant request for withdrawal
of applications N/A encl
GRAY, J R Hearing Branch 1 81/01/07 1p 07425 267

BUCKET 50-525 BARTON UNIT 2

Adjudicatory correspondence

0101090370 Forwards NRC response to applicant request for withdrawal
of applications N/A encl
GRAY, J R Hearing Branch 1 81/01/07 1p 07425 267

BUCKET 50-526 BARTON UNIT 3

Adjudicatory correspondence

0101090370 Forwards NRC response to applicant request for withdrawal
of applications N/A encl
GRAY, J R Hearing Branch 1 81/01/07 1p 07425 267

BUCKET 50-527 BARTON UNIT 4

Adjudicatory correspondence

0101090370 Forwards NRC response to applicant request for withdrawal
of applications N/A encl
GRAY, J R Hearing Branch 1 81/01/07 1p

BUCKET STN-50-528 PALO VERDE NUCLEAR STATION, UNIT 1

Application/construction stage documents & correspondence

0101220466 Ltr to all power reactor licensees & applicants forwarding
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp

0101120098 Forwards 425 updated electrical instrumentation & control
drawings & 135 updated PIDs, per FSAR Amend 3 Aperture
Cards only in PDF
VAN BRUNT, E E Arizona Public Service Co 80/12/18 1p
07453 175

0101060500 Forwards "Summary of Future Qualification Tests" & Vol 1.
"Instruction Manual for Installation, Operation & Maint of
Auxiliary & Isolation Relay Cabinets, Generator Protection
Cabinet, Metering Cabinet & Auto Synchronizer Cabinet"
VAN BRUNT, E E Arizona Public Service Co 80/12/23 6pp
07309 001

0101060507 Vol 1, Revision 3, "Instruction Manual for Installation,
Operation & Maint of Auxiliary & Isolation Relay Cabinets,
Generator Protection Cabinet, Metering Cabinet & Auto
Synchronizer Cabinet"
Arizona Public Service Co 80/10/03 59pp

0101060478 Requests meeting in Jan to discuss sys review schedule
status & to determine which sys could, in advance, be
prepared for sys reviews
VAN BRUNT, E E Arizona Public Service Co 80/12/29 1p
07396 315

0115092B Requests lists of attendees, contracts and agenda for
B10127-29 site visit info re potential contentions encl
MIRAGLIA, F J Licensing Branch 3 B1/01/36 2pp 07464 143

01131322 Clarifies technical support air handling requirements
discussed at B01116 meeting
VAN BRUNT, E E Arizona Public Service Co B1/01/08 2pp
07151 392

01260853 Responds to Ltr B01229 ltr requesting meeting to discuss
facility review schedule Meeting on B10122 suggested
EISENHUT, D G Division of Licensing B1/01/14 2pp 07534 173

01303044 Notification of B01119 meeting w/utl & ANL in Buckeye, AZ to
discuss environ review site visit
MIRAGLIA, F J Licensing Branch 3 B1/01/19 3pp 07576 340.

01270441 Forwards response to NRC B01219 request for updated
subsistence info Site plots exhibit random scatter within
Accuracy of survey Settlement results from localized causes
induced by man
VAN BRUNT, E E Arizona Public Service Co B1/01/20 4pp
07549 031

Utility Environmental Report (ER), amends & correspondence

01070463 Forwards proof of svc for updated distribution list for
suppl & amends to facility; general info.FSAR & environ
rept per NRC B00625 ltr
VAN BRUNT, E E Arizona Public Service Co B0/12/29 5pp

NRC Draft/Final Environmental Statements, suppl & correspondence

01280474 Requests info re proposed or listed plant &/or animal
species which may be present in vicinity of facilities Also
extends invitation to participate in B10127-28 site visit
MIRAGLIA, F J Licensing Branch 3 B1/01/23 6pp 07187 001

Security, medical, emergency & fire protection plans

01090337 Ltr to all licensees of operating reactor plants, CP holders
& CP applicants Revised radiological emergency response
plans must be submitted by licensees within 60 days of
B10302 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing B0/11/13 2pp

Adjudicatory Correspondence

01120459 Order granting Intervenor PL Hourihan until B10120 to
respond to contentions objected to by joint applicants or
NRC Certificate of Svc encl
LAZO, R H Atomic Safety and Licensing Board Panel B1/01/06 3pp
07447 219

01270272 Informs of representation for PL Hourihan in claim against
utl B01211 action re invasion of privacy by wiretapping
Certificate of Svc & news articles encl
TOBIN, J S Tobin, J S B1/01/13 6pp 07309 001

01270175 Ack receipt of B10113 ltr re PL Hourihan claim against utl
B10101P, C J Atomic Safety and Licensing Appeal Panel B1/01/16
1p 07546 059

0101270306 Informs of representation for PL Hourihan in claim against
utl B01211 action re invasion of privacy by wiretapping
Certificate of Svc encl
TOBIN, J S Tobin, J S B1/01/13 3pp 07546 060

Utility Final Safety Analysis Report (FSAR) & amends

01070264 Forwards proof of svc of Amend 3 to FSAR
distribution list encl
VAN BRUNT, E E Arizona Public Service Co B0/12/29 3pp.
07414 124

01070463 Forwards proof of svc for updated distribution list for
suppl & amends to facility; general info.FSAR & environ
rept per NRC B00825 ltr
VAN BRUNT, E E Arizona Public Service Co B0/12/29 5pp

0 Inspection reports, IE Bulletins & correspondence

0101050533 Forwards IE Info Notice B0-43, "Failures of Continuous Water
Level Monitor for Screen Discharge Val at Dresden Unit 2"
No response required
EISENHUT, R H Region 5, San Francisco, Office of the Director
B0/12/35 1p 07307 289

B10150638 Forwards IE Info Notice B0-44, "Actuation of ECCS in
Recirculation Mode While in Hot Shutdown" No response
required
EISENHUT, R H Region 5, San Francisco, Office of the Director
B0/12/16 1p 07308 031

B101220976 Requests 60-day extension to respond to IE Bulletin B0-23,
"Failures of Solenoid Valves Mfg by Valcor Engineering
Corp - Info from vendors required
VAN BRUNT, E E Arizona Public Service Co B0/12/18 1p
07495 254

B101220104 Responds to IE Bulletin B0-21, "Valve Yokes Supplied by
Malcolm Foundry, Co. Inc - Vendors have confirmed that
specified valves were not supplied Two responses are
outstanding
VAN BRUNT, E E Arizona Public Service Co B0/12/30 1p
07495 255

B101270459 Approves utl B01218 request for 30-day extension to respond
to IE Bulletin B0-23, "Failures of Solenoid Valves Mfg by
Valcor Engineering Corp -
EISENHUT, R H Region 5, San Francisco, Office of the Director
B1/01/08 1p 07549 060

5 Reportable occurrences, LERs & related correspondence

B101060425 Revised final deficiency rept. originally reported on B00612,
re undersized structural steel fillet welds Suppl original
final rept w/ corrections & addl info re "Analysis of Safety
Implications" section
VAN BRUNT, E E Arizona Public Service Co B0/12/24 23pp.
07309 001

B101210330 Interim deficiency rept re assumption in containment fuel
transfer housing tube design Revised calculation will be
completed by B10301 Final rept will be submitted by B10401.
VAN BRUNT, E E Arizona Public Service Co B1/01/12 3pp
07490 128

B101210335 Interim deficiency rept re cable tray supports not meeting
drawing requirements Installation drawings & work plan
procedures will be reviewed & revised Installation will be
corrected or accepted after insp Final rept due by B10401.
VAN BRUNT, E E Arizona Public Service Co B1/01/12 4pp
07490 124

B101230492 Final deficiency rept. originally reported on B01211, re Class
IE conductors within six inches of non-Class IE conductors
on six 1TE Gould 480 volt load ctr isolation relay cabinets
Corrective action will be completed prior to sys startup
VAN BRUNT, E E Arizona Public Service Co. B1/01/12 4pp
07510 010

DOCKET STN-90-529 PALO VERDE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding
summary of B01112 meeting re implementation of guidance for
Unresolved Safety Issue A-12, "Potential for Low Fracture
Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D G Division of Licensing, B0/11/26 8pp.

B101220976 Forwards 425 updated electrical, instrumentation & control
drawings & 135 updated P&IDs, per FSAR Amend 3. Aperture
cords only in PDR
VAN BRUNT, E E Arizona Public Service Co. B0/12/18 1p.
07453 175

B101060500 Forwards "Summary of Future Qualification Tests" & Vol 1,
"Instruction Manual for Installation, Operation & Maint of
Auxiliary & Isolation Relay Cabinets, Generator Protection
Cabinet, Metering Cabinet & Auto Synchronizer Cabinet."
VAN BRUNT, E E Arizona Public Service Co. B0/12/23 6pp.
07309 031

0101070707 Vol 1, Revision 1 - Instruction Manual for Installation, Operation & Maint of Auxiliary & Isolation Relay Cabinets, Generator Protection Cabinet, Metering Cabinet & Auto Recloser Cabinet
* Arizona Public Service Co 00/10/01 5pp

0101060470 Requests meeting in Jan to discuss eye review schedule status & to determine which eye could in advance be prepared for eye review
VAM BRUNT, E E Arizona Public Service Co 00/12/29 1p
07376 117

0101070461 Forwards proof of eye for updated distribution list for supply & amends to facility general info, I&AR & environ rept per IHC 000629 Itr
VAM BRUNT, E E Arizona Public Service Co 00/12/29 5pp
07404 125

0101150720 Requests list of attendees, contracts and agenda for 010127/29 site visit info re potential contentions encl
HRAQI IAL, J Licensing Branch 1 01/01/06 3pp 07464 145

0101100629 Clarifies technical support city training requirements discussed at 010110 meeting
VAM BRUNT, E E Arizona Public Service Co 01/01/00 2pp
07451 170

0101260451 Responds to 010110/29 Itr requesting meeting to discuss facility review schedule meeting on 010123 suggested
HRAQI IAL, J Division of Licensing 01/01/14 2pp 07514 121

0101300444 Notification of 010112 meeting w/uttl & ARE in Buckeye, AZ to discuss environ review site visit
HRAQI IAL, J Licensing Branch 1 01/01/19 3pp 07576 160

0101270441 Forwards response to IHC 010112 request for updated systems info this plants exhibit random scatter within accuracy of survey. Rejection results from localized causes induced by man
VAM BRUNT, E E Arizona Public Service Co 01/01/20 4pp
07542 175

0101300441 Notification of 010122 meeting w/uttl in Bethesda, MD to discuss facilities review schedule
HRAQI IAL, J Division of Licensing Branch 1 01/01/22 3pp 07601 005

C. Utility Environmental Report (IHC), Amends & correspondence

0101070461 Forwards proof of eye for updated distribution list for supply & amends to facility general info, I&AR & environ rept per IHC 000629 Itr
VAM BRUNT, E E Arizona Public Service Co 00/12/29 5pp

D. IHC Draft/Final Environmental Statements, supply & correspondence

0101200494 Requests info re proposed or listed plant &/or animal species which may be present in vicinity of facilities Also extends invitation to participate in 010127/28 site visit
HRAQI IAL, J Licensing Branch 1 01/01/21 6pp 07107 001

F. Security, medical, emergency & fire protection plans

0101090107 Itr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 010102 & by applicants as part of I&AR
HRAQI IAL, J Division of Licensing 00/11/13 2pp

G. Adjudicatory correspondence

0101200494 Order granting intervenor PL Hourihan until 010120 to respond to contentions objected to by joint applicants or IHC Certificate of five encl
LAZU, R H Atomic Safety and Licensing Board Panel 01/01/06 3pp
07442 210

0101270272 Informs of representation for PL Hourihan in claim against uttl 001211 action re invasion of privacy by wiretapping Certificate of five & news articles encl
TOBIN, J B Tobin, J B 01/01/13 4pp 07309 001

0101270295 Ack receipt of 010113 Itr re PL Hourihan claim against uttl
BISOP, C J Atomic Safety and Licensing Appeal Panel 01/01/16 1p 07546 054

0101270706 Informs of representation for PL Hourihan in claim against uttl 001211 action re invasion of privacy by wiretapping Certificate of five encl
TOBIN, J B Tobin, J B 01/01/13 3pp 07546 060

K. Utility Final Safety Analysis Report (I&AR) & amends

0101070364 Forwards proof of eye for Amend 3 to I&AR Distribution list encl
VAM BRUNT, E E Arizona Public Service Co 00/12/29 3pp
07414 124

0101070461 Forwards proof of eye for updated distribution list for supply & amends to facility general info, I&AR & environ rept per IHC 003629 Itr
VAM BRUNT, E E Arizona Public Service Co 00/12/29 5pp

0101270532 Forwards I&AR Pages 9 5-1/2 5-16 & 9 5-18/9 5-2 to rep Pages 9 5-1/2 5-2 previously provided as part of I&AR Amend 3 to Vol II
* Hechtel Power Corp (subs of Hechtel Corp) 01/01/19 5p
07540 129

L. Inspection reports, IF Bulletins & correspondence

0101050503 Forwards IF Info Notice 80-43, "Failures of Continuous Level Monitor for Steam Discharge Val at Dresden Unit 2" No response required
INGELKEN, R H Region 5, San Francisco, Office of the Director 00/12/05 1p 07307 200

0101300438 Forwards IF Info Notice 80-44, "Actuation of ECCB in Recirculation Mode While in Hot Shutdown" No response required
INGELKEN, R H Region 5, San Francisco, Office of the Director 00/12/16 1p 07300 001

0101260796 Requests 60-day extension to respond to IF Bulletin 00 "Failures of Solenoid Valves Hfg by Valcon Engineering Corp" Info from vendors required
VAM BRUNT, E E Arizona Public Service Co 00/12/10 1p
07475 254

0101201014 Responds to IF Bulletin 80-24, "Valve Yokes Supplied by Malcolm Foundry Co, Inc" Vendors have confirmed that specified valves were not supplied Two responses are outstanding
VAM BRUNT, E E Arizona Public Service Co 00/12/30 1p
07493 255

0101270459 Approves uttl 001210 request for 30-day extension to respond to IF Bulletin 80-24, "Failures of Solenoid Valves Hfg by Valcon Engineering Corp"
INGELKEN, R H Region 5, San Francisco, Office of the Director 01/01/01 1p 07549 060

M. Reportable occurrences, IIRs & related correspondence

0101060425 Revised final deficiency rept, originally reported on 010106 re undersized structural steel fillet welds Supply original final rept w/corrections & add info re "Analysis of Safety Implications" section
VAM BRUNT, E E Arizona Public Service Co 00/12/24 23pp
07309 001

0101060504 Interim deficiency rept re concrete void in unit concrete sump Caused by lack of complete concrete consolidation due to reinforcement steel density Final rept will be submitted by 010315
VAM BRUNT, E E Arizona Public Service Co 00/12/24 3pp
07376 076

0101210330 Interim deficiency rept re assumption in containment transfer housing tube design Revised calculation will be completed by 010301 Final rept will be submitted by 010401
VAM BRUNT, E E Arizona Public Service Co 01/01/12 3pp
07490 120

0101210735 Interim deficiency rept re cable tray supports not meeting drawing requirements Installation drawings & work plan procedures will be reviewed & revised Installation will be corrected or accepted after insp Final rept due by 010401
VAM BRUNT, E E Arizona Public Service Co 01/01/12 4pp
07490 124

8101210038 Final deficiency rept. originally reported 801211 re Class IE conductors within six inches of non-Class IE conductors on six ITE Gould 480 volt load ctr isolation relay cabinets possibly overstressing welds Bechtel Corp will repair piping s/s Personnel instructed to follow installation spec VAN BRUNT, E E Arizona Public Service Co 81/01/12 4pp 07490 120

8101230492 Final deficiency rept. originally reported on 801211 re Class IE conductors within six inches of non-Class IE conductors on six ITE Gould 480 volt load ctr isolation relay cabinets Corrective action will be completed prior to s/s startup VAN BRUNT, E E Arizona Public Service Co 81/01/12 4pp 07510 018

8004ET 81N-50-530 FALCO VERDE NUCLEAR STATION, UNIT 3

A Application/construction stage documents & correspondence

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for Unresolved Safety Issue A-12: "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports" EISENHUT, D G Division of Licensing 80/11/26 8pp

8101200018 Forwards 425 updated electrical instrumentation & control drawings & 135 updated P&IDs per FSAR A-end 3 Aperture cards only in PDR VAN BRUNT, E E Arizona Public Service Co 80/12/18 1p 07493 175

8101060500 Forwards "Summary of Future Qualification Tests" & Vol 1, "Instruction Manual for Installation, Operation & Maint of Auxiliary & Isolation Relay Cabinets, Generator Protection Cabinet, Metering Cabinet & Auto Synchronizer Cabinet" VAN BRUNT, E E Arizona Public Service Co 80/12/23 6pp 07309 001

--8101060507 Vol 1, Revision 3, "Instruction Manual for Installation, Operation & Maint of Auxiliary & Isolation Relay Cabinets, Generator Protection Cabinet, Metering Cabinet & Auto Synchronizer Cabinet" * Arizona Public Service Co 80/10/03 39pp

8101060478 Requests meeting in Jan to discuss s/s review schedule status & to determine which s/s could, in advance, be prepared for s/s reviews VAN BRUNT, E E Arizona Public Service Co 80/12/29 1p 07396 315

8101070463 Forwards proof of svc for updated distribution list for supply & amends to facility general info, FSAR & environ rept per NRC 800825 ltr VAN BRUNT, E E Arizona Public Service Co 80/12/29 5pp 07403 355

8101150928 Requests lists of attendees, contracts and agenda for 810127-29 site visit info re potential contentions encl MIRAGLIA, F J Licensing Branch 3 81/01/06 2pp 07464 149

8101130327 Clarifies technical support ctr running requirements discussed at 801118 meeting. VAN BRUNT, E E Arizona Public Service Co. 81/01/08 2pp 07451 350

8101268553 Responds to util 801229 ltr requesting meeting to discuss facility review schedule Meeting on 810122 suggested EISENHUT, D G Division of Licensing 81/01/14 2pp 07534 173

8101300344 Notification of 810119 meeting w/util & ANL in Buckeye, AZ to discuss environ review site visit KERRIGAN, J D Licensing Branch 3 81/01/19 3pp 07576 360

8101270441 Forwards response to NRC 801219 request for updated subsistence info Six plots exhibit random scatter within accuracy of survey Settlement results from localized causes induced by man VAN BRUNT, E E Arizona Public Service Co. 81/01/20 4pp 07549 051

8101300041 Notification of 810122 meeting w/util in Bethesda, MD to discuss facilities review schedule KERRIGAN, J D Licensing Branch 3 81/01/22 3pp 07583 005

C Utility Environmental Report (ER)- amends & correspondence

8101070463 Forwards proof of svc for updated distribution list for supply & amends to facility general info, FSAR & environ rept per NRC 800825 ltr VAN BRUNT, E E Arizona Public Service Co. 80/12/29 5pp

D NRC Draft/Final Environmental Statements, supply & correspondence

8101280494 Requests info re proposed or listed plant &/or animal species which may be present in vicinity of facilities Also extends invitation to participate in 810127-28 site visit MIRAGLIA, F J Licensing Branch 3 81/01/23 6pp 07187 001

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensee of operating reactor plants, CP hold & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 b by applicants as part of FSAR EISENHUT, D G Division of Licensing 80/11/13 2pp

G Adjudicatory correspondence

8101120499 Order granting intervenor PL Hourihan until 810120 to respond to contentions objected to by joint applicants or NRC Certificate of Svc encl LATO, R M Atomic Safety and Licensing Board Panel 81/01/06 07447 210

8101270272 Informs of representation for PL Hourihan in claim appeal until 801211 action re invasion of privacy by wiretapping. Certificate of Svc & news articles encl TOSIN, J S Tobin, J S 81/01/13 6pp 07309 001

8101270245 Ack receipt of 810113 ltr re PL Hourihan claim against OISHOP, C J Atomic Safety and Licensing Appeal Panel 81/01/16 1p 07546 059

--8101270306 Informs of representation for PL Hourihan in claim appeal until 801211 action re invasion of privacy by wiretapping Certificate of Svc encl TOSIN, J S Tobin, J S 81/01/13 3pp 07546 060

K Utility Final Safety Analysis Report (FSAR) & amends

8101070364 Forwards proof of svc of Amend 3 to FSAR Distribution list encl VAN BRUNT, E E Arizona Public Service Co 80/12/29 3pp 07414 124

8101070463 Forwards proof of svc for updated distribution list for supply & amends to facility general info, FSAR & environ rept per NRC 800825 ltr VAN BRUNT, E E Arizona Public Service Co. 80/12/29 5pp

8101270522 Forwards FSAR Pages 9 3-1/9 3-1A & 9 5-1B/9 5-2 to repl Pages 9 3-1/9 5-2 erroneously provided as part of FSAR Amend 3 in Vol B * Bechtel Power Corp. (subs of Bechtel Corp.) 81/01/19 5pp 07548 329

Q Inspection reports, IE Bulletins & correspondence

8101050503 Forwards IE Info Notice 80-43, "Failures of Continuous Level Monitor for Bcam Discharge Vol at Dresden Unit 2" No response required ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/12/05 1p 07387 288

8101150838 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown" No response required ENGELKEN, R H Region 5, San Francisco, Office of the Director. 81/12/16 1p 07308 001

8101220096 Requests 60-day extension to respond to IE Bulletin 80-44 "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." Info from vendors required. VAN BRUNT, E E Arizona Public Service Co 80/12/18 1p 07495 254

8101220104 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Vendors have confirmed that specified valves were not supplied. Two responses are outstanding. VAN BRUNT, E E Arizona Public Service Co. 80/12/30 1p 07495 255

8101270459 Approves util 801218 request for 30-day extension to repl to IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp." ENGELKEN, R H Region 5, San Francisco, Office of the Director. 81/01/08 1p 07547 060

portable occurrences. LERs & related correspondence

60425 Revised final deficiency rept. originally reported on 800612. undersized structural steel fillet welds Suppl's original rept w/corrections & addl info re "Analysis of Safety Locations" section
BRUNT, E E Arizona Public Service Co 80/12/24 23pp.
09 001.

60338 Interim deficiency rept re cable tray supports not meeting wiring requirements. Installation drawings & work plan procedures will be reviewed & revised. Installation will be rejected or accepted after insp. Final rept due by 010401
BRUNT, E E Arizona Public Service Co 81/01/12 4pp.
90 124

60492 Final deficiency rept. originally reported on 801211. re Class conductors within six inches of non-Class IE conductors six 17E Gould 480 volt load ctr isolation relay cabinets. Corrective action will be completed prior to sys startup
BRUNT, E E Arizona Public Service Co 81/01/12 4pp
00:018

50-537 CLINCH RIVER BREEDER REACTOR

Application/construction stage documents & correspondence

60222 "Thermal Hydraulic LMFBR Safety Experiments." monthly highlights for June 1980
BERG, T., ABUAF, N Brookhaven National Laboratory FIN A-3024
270222 80/06/30 4pp 07547-095

60654 "Thermal Hydraulic LMFBR Safety Experiments." monthly highlights for Jul 1980
AF, N., DINBERG, T Brookhaven National Laboratory FIN A-3024
230654 80/07/31 4pp. 07511-240

60545 "Thermal Hydraulic LMFBR Safety Experiments." monthly highlights for Aug 1980
BERG, T., ABUAF, N Brookhaven National Laboratory FIN A-3024
270545 80/08/31 4pp 07543 353.

60065 "Thermal Hydraulic LMFBR Safety Experiments." monthly highlights for Sept 1980.
BERG, T., ABUAF, N Brookhaven National Laboratory FIN A-3024
270065 80/09/30 4pp 07547-200

60827 AN ADVANCED THERMOHYDRAULIC SIMULATION CODE FOR POOL-TYPE RB (BSC-P CODE)
AF, I. R., CAZIO, L. E Q Brookhaven National Laboratory. FIN
015 NUREG/CR-1738 80/09/30 109pp Available at NTIS
02:136

60127 EVALUATION OF TECHNIQUES FOR DYNAMIC MEASUREMENT OF FUEL ROD IN LIQUID-METAL-COOLED FAST-BREEDER REACTOR SAFETY EXPERIMENTS
AB, A. E., ORNDORFF, J. D. Los Alamos Scientific Laboratory. FIN
046 NUREG/CR-1398 80/10/31 67pp. 07523-226

60112 "Thermal Hydraulic LMFBR Safety Experiments." monthly highlights for Oct 1980
Brookhaven National Laboratory. 8101270112. 80/10/31. 3pp.
07:209.

60337 "Application of Super Svc Code-L to Investigate Natural Convection in Damaged LMFBR Cores." submitted to ANS/ECB/AIE
17-21 International conference.
AF, J. Q. Brookhaven National Laboratory CURTIS, R. T Division of
for Safety Research. 8101210537 80/11/21 4pp 07489:100.

60466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D. Q Division of Licensing. 80/11/26. 8pp

60758 "Thermal Hydraulic LMFBR Safety Experiments." monthly highlights for Nov 1980.
BERG, T., GREENE, O. A Brookhaven National Laboratory FIN
024. 8101260758 80/11/30. 4pp. 07536:018

60944 "Thermal Hydraulic LMFBR Safety Experiments." monthly highlights for Jul 1980
AF, N. Brookhaven National Laboratory 8101210544. 81/01/15.
07488:334.

U Utility Preliminary Safety Analysis Report. amends

8101090492 Forwards Certificate of Svc re distribution of Amend 59 to PSAR
CEPELAND, R L Energy Dept. of. Clinch River Breeder Reactor Plant
81/01/05 2pp 07427 331

F Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of PSAR
EISENHUT, D. Q Division of Licensing 80/11/13 2pp

DOCKET 51N-50-546 HARBLE HILL NUCLEAR STATION. UNIT 1

A Application/construction stage documents & correspondence

8101070237 Requests written notification to resume const activities per NRC 800515 order re mechanical & piping const activities by Chernobyl Contracting Corp & electrical const activities by Commonwealth-Lord JV
GHELDOS, S W Public Service Co of Indiana, Inc 80/11/13 1p.
07415 237

8101220466 Ltr to all power reactor licensees & applicants forwarding summary of 801112 meeting re implementation of guidance for unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D. Q Division of Licensing 80/11/26 8pp

8101050015 Forwards info re environ qualification tests scheduled for next 2 yrs on safety-related equipment. Info includes equipment description, sys where equipment installed & test location & schedule
GHELDOS, S W Public Service Co of Indiana, Inc 80/12/18 4pp
07379:346

8101290504 Requests NRC approval for use of ASME Code Case N-290. Code Case provides use of magnetic particle or liquid penetrant examination in lieu of visual examination
GHELDOS, S W Public Service Co of Indiana, Inc. 81/01/23. 1p
07568-354

F. Security, medical, emergency & fire protection plans

8101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants. Revised radiological emergency response plans must be submitted by licensees within 60 days of 810102 & by applicants as part of PSAR.
EISENHUT, D. Q Division of Licensing 80/11/13. 2pp.

H General correspondence

8101130044 Responds to 800930 ltr forwarding encl F Hauck, HO Cassidy & R Gray ltrs re nuclear waste disposal bills before Congress & concerns about facilities Util estimate of facility const costs generally consistent w/NRC estimate.
DIRCKS, W J Office of the Executive Director for Operations
80/12/30 10pp 07449 310.

Q Inspection reports, IE Bulletins & correspondence

8101050203 Forwards IE Info Notice 80-38, "Cracking in Charging Pump Casing Cladding." No response required.
KEPPLER, J. Q Region 3, Chicago, Office of the Director 80/10/30
2pp. 07389:027

8101060548 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp." No written response is required.
KEPPLER, J. Q. Region 3, Chicago, Office of the Director 80/10/31
1p 07401:151

8101100790 Forwards IE Circular 80-23, "Potential Defects in Baloit Power Sys Emergency Generators." No written response required
KEPPLER, J. Q. Region 3, Chicago, Office of the Director 80/10/31.
2pp. 07444-086.

8101050475 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co, Inc." Written response required
KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 80/11/06
2pp 07390 048

Pressure Actuates Safety-Relief Valve Operation to Cause
Reactor Depressurization " No written response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/11/07
2pp 07426 269

B01060379 Forwards IE Info Notice 80-41, "Failure of Swing Check
Valve in Decay Heat Removal Sys at Davis Besse Unit 1" No
response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/11/10
2pp 07391 076

B01060515 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves
Mfg by Valcor Engineering Corp " Written response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/11/14
2pp 07391 238

B01060330 Forwards IE Insp Repts 50-546/80-41 & 50-547/80-41 on
B01001-31 No noncompliance noted.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/11/26. 2pp. 07392 037

--B01060306 IE Insp Repts 50-546/80-41 & 50-547/80-41 on B01001-31 No
noncompliance noted Major areas inspected: auxiliary bldg,
fuel handling bldg & containments to verify compliance w/
790807 stop work order
HARRISON, J. J., WILLIAMS, C. C. Region 3, Chicago, Office of the
Director. 80/11/26 4pp. 07392 039.

B01100369 Forwards IE Insp Repts 50-546/80-42 & 50-547/80-42 on
B01104-06 No noncompliance noted
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/11/26 2pp 07444 001

--B01100378 IE Insp Repts 50-546/80-42 & 50-547/80-42 on B01104-06 No
noncompliance noted Major areas inspected QA program of
vendor
HARRISON, J. J., KEY, W., WILLIAMS, C. C. Region 3, Chicago, Office of the
Director 80/11/25 12pp 07444 003

B01050571 Forwards IE Info Notice 80-43, "Failures of Continuous Water
Level Monitor for Scram Discharge Vol at Dresden Unit 2." No
response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/12/05
2pp 07386 035.

B01100177 Submits supplemental response to IE Bulletin 79-03A re
longitudinal weld defects in stainless steel piping Addl
review of welds completed No welded components designated
for use in any safety-related sys.
SHIELDS, S. W. Public Service Co. of Indiana, Inc. 80/12/15 2pp
07413 013

B01070085 Forwards IE Info Notice 80-44, "Actuation of ECCB in
Recirculation Mode While in Hot Shutdown." No written
response required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/12/16
1p 07415 041

B01210097 Forwards IE Insp Repts 50-546/80-39 & 50-547/80-39 on
B01021-24, 1105-07 & 11-14. No noncompliance noted.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/12/16 2pp. 07489 324

--B01210104 IE Insp Repts 50-546/80-39 & 50-547/80-39 on B01021-24,
1105-07 & 11-14. No noncompliance noted Major areas
inspected: review of BPP-2 const verification program final
rept & insp of civil insp & testing svcs lab.
MAYES, D. W. Region 3, Chicago, Reactor Construction & Engineering
Support Branch HAWKINS, F. C., NEISLER, J. H. Region 3, Chicago,
Office of the Director 80/12/11. 11pp 07489 326.

B012310165 Notification of B01018 meeting w/util in Bethesda, MD on insp
& testing re cad weld deficiencies at Facilities
MCKO, H. J. Assistant Director for Components & Structures
Engineering 80/12/18 3pp 07369 277.

B01290152 Forwards IE Insp Repts 50-546/80-43 & 50-547/80-43 on
B01101-30 Noncompliance noted.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 80/12/18 2pp. 07568 289

--B01290166 IE Insp Repts 50-546/80-43 & 50-547/80-43 on B01101-30. No
noncompliance noted Major areas inspected: auxiliary bldg &
fuel handling bldg & containments to verify compliance
w/790807 stop work order
HARRISON, J. J., WILLIAMS, C. C. Region 3, Chicago, Office of the
Director. 80/12/16 8pp 07568 261.

correct violations noted in IE Insp Repts 50-546/80-28
50-547/80-28
FIORELLI, G. Region 3, Chicago, Reactor Construction &
Support Branch 81/01/14 1p 07583 234.

--B01300421 Responds to NRC B01208 ltr re violations no
Repts 50-546/80-28 & 50-547/80-28 Corrective actions
gauges installed on equipment & indicator gauges ver
against calor gauge
SHIELDS, S. W. Public Service Co. of Indiana, Inc. 81/
07583 235

S Reportable occurrences, LCRs & related correspondence

B01140645 Interim deficiency rept, first reported on B01
inability to verify certain pipe sleeve installation f
const records Investigation to be augmented by onsite
engineering evaluation Final rept to be filed by B0106
SHIELDS, S. W. Public Service Co. of Indiana, Inc. 81/
07461 242

B01230487 Interim deficiency rept, originally reported o
radiographs of steam generator upper lateral support
embedments not meeting ASME density requirements.
Re-examination results will be available by B01220
SHIELDS, S. W. Public Service Co. of Indiana, Inc. 81/
07510 017.

COCKET BIN-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

B01070239 Requests written notification to resume const
per NRC B00315 order re mechanical & piping const acts
by Charne Contracting Corp & electrical const activiti
Commonwealth-Lord JV
SHIELDS, S. W. Public Service Co. of Indiana, Inc. 80/
07415 237

B01220466 Ltr to all power reactor licensees & applican
summary of B0112 meeting re implementation of guidance
Unresolved Safety Issues A-12, "Potential for Low Fract
Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D. Q. Division of Licensing 80/11/26 8pp.

B012310165 Notification of B01018 meeting w/util in Beth
& testing re cad weld deficiencies at Facilities.
MCKO, H. J. Assistant Director for Components & Structures
Engineering 80/12/18. 3pp. 07369 277.

B01050015 Forwards info re environ qualification tests
next 2 yrs on safety-related equipment Info includes
equipment description; sys where equipment installed &
location & schedule.
SHIELDS, S. W. Public Service Co. of Indiana, Inc. 80/
07379 346

B01290504 Requests NRC approval for use of ASME Code C
Case provides use of magnetic particle or liquid penetr
examination in lieu of visual examination.
SHIELDS, S. W. Public Service Co. of Indiana, Inc. 81/
07368 354

F Security, medical, emergency & fire protection plans

B01090387 Ltr to all licensees of operating reactor pla
& CP applicants Revised radiological emergency respon
plans must be submitted by licensees within 60 days o
B01012 & by applicants as part of FSAR.
EISENHUT, D. Q. Division of Licensing. 80/11/13. 2pp.

H General correspondence

B01130044 Responds to B00930 ltr forwarding encl F Hau
R Drag ltrs re nuclear waste disposal bills before Con
& concerns about facilities. Util estimate of facility
costs generally consistent w/NRC estimate.
DRACKS, W. J. Office of the Executive Director for Oper
80/12/30 10pp 07449 310.

G Inspection reports, IE Bulletins & correspondence

B01050209 Forwards IE Info Notice 80-38, "Cracking in
Casing Cladding " No response required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director
2pp. 07389 027.

B101040548 Forwards IE Info Notice 80-39, "Malfunction of Solenoid Valves Mfg by Valcor Engineering Corp " No written response is required
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/10/31
1p 07401 151

B101100790 Forwards IE Circular 80-23, "Potential Defects in Deloit Power Sys Emergency Generators " No written response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/10/31
2pp. 07444 086

B101050475 Forwards IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc " Written response required
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/11/06
2pp. 07390 048

B101090090 Forwards IE Info Notice 80-40, "Excessive Nitrogen Supply Pressure Actuates Safety-Relief Valve Operation to Cause Reactor Depressurization " No written response required
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/11/07
2pp 07426 268

B101060379 Forwards IE Info Notice 80-41, "Failure of Spring Check Valve in Decay Heat Removal Sys at Davis Besse Unit 1 " No response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/11/10
2pp 07391 076.

B101060515 Forwards IE Bulletin 80-23, "Failures of Solenoid Valves Mfg by Valcor Engineering Corp " Written response required
KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/11/14.
2pp. 07391 238.

B101060300 Forwards IE Insp Repts 50-546/80-41 & 50-547/80-41 on B01001-31 No noncompliance noted.
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/11/26. 2pp. 07392 037

--B101060306 IE Insp Repts 50-546/80-41 & 50-547/80-41 on B01001-31. No noncompliance noted. Major areas inspected: auxiliary bldg, fuel handling bldg & containments to verify compliance w/ 790807 stop work order.
HARRISON, J. J., WILLIAMS, C. C. Region 3, Chicago, Office of the Director 80/11/26 4pp. 07392 039.

B101100369 Forwards IE Insp Repts 50-546/80-42 & 50-547/80-42 on B01104-06 No noncompliance noted.
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/11/26 2pp. 07444 001.

--B101100378 IE Insp Repts 50-546/80-42 & 50-547/80-42 on B01104-06 No noncompliance noted. Major areas inspected: OA program of vendor.
HARRISON, J. J., KEV, W., WILLIAMS, C. C. Region 3, Chicago, Office of the Director. 80/11/29 12pp. 07444 003

B101050571 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Scram Discharge Vol at Dresden Unit 2." No response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/12/05.
2pp. 07386 035.

B101100177 Submits supplemental response to IE Bulletin 79-03A re longitudinal weld defects in stainless steel piping. Add'l review of welds completed. No welded components designated for use in any safety-related sys.
SHIELDS, B. W. Public Service Co. of Indiana, Inc. 80/12/15. 2pp. 07443 013

B101070085 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown " No written response required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/12/16.
1p 07415 041.

B101210097 Forwards IE Insp Repts 50-546/80-39 & 50-547/80-39 on B01021-24, 1105-07 & 11-14 No noncompliance noted.
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/16. 2pp. 07489 324.

--B101210104 IE Insp Repts 50-546/80-39 & 50-547/80-39 on B01021-24, 1105-07 & 11-14 No noncompliance noted. Major areas inspected: review of SPP-2 const verification program final rept & insp of civil insp & testing svcs lab.
HAYES, D. W. Region 3, Chicago, Reactor Construction & Engineering Support Branch. HANKINS, F. C., NEIBLER, J. H. Region 3, Chicago, Office of the Director. 80/12/11. 11pp. 07489 326.

B101290152 Forwards IE Insp Repts 50-546/80-43 & 50-547/80-43 on B01101-30 Noncompliance noted
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/12/18 2pp 07568 259.

--B101290166 IE Insp Repts 50-546/80-43 & 50-547/80-43 on B01101-30 noncompliance noted. Major areas inspected: auxiliary bldg & fuel handling bldg & containments to verify compliance w/ 790807 stop work order.
HARRISON, J. J., WILLIAMS, C. C. Region 3, Chicago, Office of the Director 80/12/16. 8pp 07568 261

B101300413 Ack receipt of B01230 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-546/80-28 & 50-547/80-28
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 81/01/14 1p 07503 234.

--B101300421 Responds to NRC B01208 ltr re violations noted in IE Insp Repts 50-546/80-28 & 50-547/80-28. Corrective actions: calibr gauges installed on equipment & indicator gauges verified against calibr gauge
SHIELDS, B. W. Public Service Co. of Indiana, Inc. 80/12/30 3p 07583 235.

S Reportable occurrences, IERs & related correspondence

B101140645 Interim deficiency rept, first reported on B01208, re inability to verify certain pipe sleeve installation from const records. Investigation to be augmented by onsite insp & engineering evaluation. Final rept to be filed by B10601
SHIELDS, B. W. Public Service Co. of Indiana, Inc. 81/01/07. 2pp 07461 242

B101230487 Interim deficiency rept, originally reported on B00717, re radiographs of steam generator upper lateral support embedments not meeting ASME density requirements. Re-examination results will be available by B10220
SHIELDS, B. W. Public Service Co. of Indiana, Inc. 81/01/15 1p 07510 017

DOCKET 50-548 FORT CALHOUN STATION, UNIT 2

A Application/construction stage documents & correspondence

B101210272 Advises of util B01114 request that CP application be withdrawn. Also advises of ASLB proceeding dismissed on B01222 info submitted re manpower hours expended for review.
YOUNGBLOOD, B. J. Licensing Branch 1. 81/01/08 1p. 07492 059.

B101270431 Forwards FR notice re withdrawal of CP application
YOUNGBLOOD, B. J. Licensing Branch 1. 81/01/12 1p 07183 001

---B101270436 Notice of withdrawal of CP application
YOUNGBLOOD, B. J. Licensing Branch 1 81/01/12 1p 07183 001

DOCKET STN-50-553 PHIPPS BEND NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Laminar Tearing on Component Supports."
EISENHUT, D. O. Division of Licensing 80/11/26 8pp.

B101120269 Requests util perform ultimate capacity analysis of Mark containment for NRC generic review re effects of hydrogen evolving from postulated accident
TEDESCO, R. L. Assistant Director for Licensing 80/12/19. 3pp 07437 316

B101210642 Advises that ATWS issue will be subj of future rulemaking to determine requirements & schedules for plant mods. NRC will not comment on util B00917 ltr describing program for resolving issue until rulemaking is finalized.
EISENHUT, D. O. Division of Licensing. 80/12/29. 2pp.

B101220207 Forwards Suppl 1 to Revision 1 of "Geologic Foundation R Fault Descriptions" per NRC 780531 request
MILLS, L. H. Tennessee Valley Authority 81/01/14. 1p. 07500 071

--B101220211 "Geologic Foundation Rept Descriptions of Faults 19-25, Suppl 1 to Revision 1.
AVEL, A. P. Tennessee Valley Authority. 80/12/31. 4pp 07500 071

F. Security, medical, emergency & fire protection plans

B10109030/ Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing 80/11/13 2pp

B101210607 Transcript of B01217 briefing on TVA emergency offsite facilities in Washington, DC Pp 8-45
* Commissioners 80/12/17 49pp

G. Inspection reports, IE Bulletins & correspondence

B101140619 Updates licensee corrective actions following NRC 800707-11 Insp of util Div of Engineering Design QA organization restructured to provide sufficient organizational freedom, authority & access to mgt.
KIMMONS, G H Tennessee Valley Authority 80/10/08 3pp

B101050588 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Scram Discharge Val at Dresden Unit 2." No response required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/05. 1p

B101050153 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Scram Capability." No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/17 1p

B101070023 Forwards Suppl 4 to IE Bulletin 80-17, "Failure of 7b of 185 Control Rods to fully Insert During Scram at BWR." No written response required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/18 1p

B101050217 Forwards IE Bulletin 80-23, "Operating Problems w/Target Rod Safety Relief Valves at BWRs." No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/19 1p

B101100370 Ack receipt of B01215 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-553/80-15 & 80-554/80-16
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/12/24 1p 07444 015

--B101100391 Responds to NRC 801121 ltr re violations noted in IE Insp Repts 80-553/80-15 & 80-554/80-16. Corrective actions all E-308-L stainless steel welding electrodes stored in separate holding ovens
MILLS, L M Tennessee Valley Authority 80/12/15 4pp 07444 016

--B101100394 Forwards IE Insp Repts 80-553/80-15 & 80-554/80-16 on B00927-1002 & notice of violation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/21 2pp. 07444 020

--B101100400 Notice of violation from insp on B00929-1002 * Region 2, Atlanta, Office of the Director 80/11/20 1p 07444 022

--B101100410 IE Insp Repts 80-553/80-15 & 80-554/80-16 on B00929-1002. Noncompliance noted 308-L welding electrodes mixed together w/309-L type electrodes
ECCO, C O Region 2, Atlanta, Office of the Director HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/20 7pp 07444 023.

B101190051 Forwards response to IE Bulletin 80-23 re failure of Valcor Engineering Corp solenoid valves. Valcor solenoid valves V70900-21-1 & V70900-21-3 not used. Util waiting for vendor response on valves in package components
MILLS, L M Tennessee Valley Authority 80/12/29. 2pp.

B101290236 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Util awaiting vendor response that parts do not contain Malcolm Foundry yokes. Final rept will be filed by B10827
MILLS, L M Tennessee Valley Authority 81/01/05 1p.

H. Reportable occurrences, LERs & related correspondence

B101140499 Interim Deficiency Rept 1 re Fillet weld misspecification American Inst of Steel Const stds are being evaluated.
Originally reported on B01208
MILLS, L M Tennessee Valley Authority 81/01/07 2pp.

B101210390 First interim deficiency rept re pressure drop in essential svc water piping. Initially reported on B01210 Util is reanalyzing essential svc water piping & high pressure fire protection piping. Final rept will be submitted by B10320
MILLS, L M Tennessee Valley Authority 81/01/12 3pp

B101210348 Final deficiency rept initially submitted B01014, re embedded plates w/c heat traceability. Plates analyzed & found to meet requirements of ASTM A-36
MILLS, L M Tennessee Valley Authority 81/01/13 2pp. 07490 116.

B101220311 Forwards First interim rept re potential flammability of suspended ceiling tile in control rooms in response to B01104 ltr. Addl info to be provided by B10211
MILLS, L M Tennessee Valley Authority 81/01/14 3pp

B101290489 Corrects numbers on util B10109 & 12 interim deficiency repts re pressure drop in essential svc water piping & standby gas treatment design deficiency
MILLS, L M Tennessee Valley Authority 81/01/20. 1p

B101270639 First interim deficiency rept, originally reported on B01221, re failure to radiograph reactor pressure vessel pedestal welds & bypass hold points on concrete pour. Util & GE will evaluate deficiency Util currently investigating cause.
MILLS, L M Tennessee Valley Authority 81/01/22 2pp. 07309 001

DOCKET 80N-50-554 PHIPPS BEND NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports."
EISENHUT, D G Division of Licensing 80/11/26. 8pp.

B101120269 Requests util perform ultimate capacity analysis of Mark 1 containment for NRC generic review re effects of hydrogen evolving from postulated accident
TEDESCO, R L Assistant Director for Licensing 80/12/19 3pp 07457 316

B101210642 Advises that ATWS issue will be subj of future rulemaking determine requirements & schedules for plant mods. NRC will not comment on util B00717 ltr describing program for resolving issue until rulemaking is finalized
EISENHUT, D G Division of Licensing 80/12/29 2pp

B101220207 Forwards Suppl 1 to Revision 1 of "Geologic Foundation Rept Fault Descriptions" per NRC 780531 request.
MILLS, L M Tennessee Valley Authority 81/01/14. 1p 07500 074

--B101220211 "Geologic Foundation Rept Descriptions of Faults 19-25." Suppl 1 to Revision 1
AVEL, A P Tennessee Valley Authority 80/12/31 4pp 07500 075

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D G Division of Licensing 80/11/13 2pp.

B101210607 Transcript of B01217 briefing on TVA emergency offsite facilities in Washington, DC Pp 1-45.
* Commissioners 80/12/17 49pp

G. Inspection reports, IE Bulletins & correspondence

B101140619 Updates licensee corrective actions following NRC 800707-11 Insp of util Div of Engineering Design QA organization restructured to provide sufficient organizational freedom, authority & access to mgt.
KIMMONS, G H Tennessee Valley Authority 80/10/08. 3pp.

B101050588 Forwards IE Info Notice 80-43, "Failures of Continuous Water Level Monitor for Scram Discharge Val at Dresden Unit 2." No response required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/05. 1p

B101060153 Forwards IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Scram Capability." No response required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/12/17. 1p.

01070023 Forwards Suppl 4 to IE Bulletin 80-17. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR " No written response required

01REILLY, J.P. Region 2. Atlanta. Office of the Director 80/12/18. 1p

01050217 Forwards IE Bulletin 80-25. "Operating Problems W/Target Rock Safety Relief Valves at BWRs " No response required.

01REILLY, J.P. Region 2. Atlanta. Office of the Director 80/12/19. 1p

01100370 Ack receipt of B01215 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 90-553/80-15 & 90-554/80-16.

MURPHY, C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/12/24 1p 07444 015.

0101100391 Responds to NRC B01121 ltr re violations noted in IE Insp Repts 90-553/80-15 & 90-554/80-16 Corrective actions all E-308-L stainless steel welding electrodes stored in separate holding ovens

ILLIS, L.M. Tennessee Valley Authority. 80/12/15 4pp 07444 016

0101100394 Forwards IE Insp Repts 90-553/80-15 & 90-554/80-16 on 800929-1002 & notice of violation

MURPHY, C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/11/21 2pp 07444 020

0101100400 Notice of violation from insp on 800929-1002

* Region 2. Atlanta. Office of the Director 80/11/20 1p 07444 022

0101100410 IE Insp Repts 90-553/80-15 & 90-554/80-16 on 800929-1002 Noncompliance noted 308-L welding electrodes mixed together w/309-L type electrodes

ECCHUGH, S.N. Region 2. Atlanta. Office of the Director HERDT, A.R. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/11/20 7pp 07444 023

01190051 Forwards response to IE Bulletin 80-23 re failure of Valcor Engineering Corp solenoid valves Valcor solenoid valves

070900-21-1 & 070900-21-3 not used. Util awaiting for vendor response on valves in package components

ILLIS, L.M. Tennessee Valley Authority 80/12/29 2pp

1290235 Responds to IE Bulletin 80-21. "Valve Yokes Supplied by Malcolm Foundry Co. Inc " Util awaiting vendor response that parts do not contain Malcolm Foundry yokes. Final rept will be filed by B10527

ILLIS, L.M. Tennessee Valley Authority 81/01/05 1p

Reportable occurrences, LERs & related correspondence

1140499 Interim Deficiency Rept 1 re Fillet weld misspecification. American Inst of Steel Const stds are being evaluated originally reported on B01208

ILLIS, L.M. Tennessee Valley Authority. 81/01/07. 2pp.

1210370 First interim deficiency rept re pressure drop in essential svc water piping. Initially reported on 801210. Util is analyzing essential svc water piping & high pressure fire protection piping Final rept will be submitted by B10320

ILLIS, L.M. Tennessee Valley Authority 81/01/12 3pp

1220311 Forwards first interim rept re potential flammability of suspended ceiling tile in control rooms in response to 01104 ltr Addl info to be provided by B10211.

ILLIS, L.M. Tennessee Valley Authority. 81/01/14 3pp

1290487 Corrects numbers on util B10109 & 12 Interim deficiency re pressure drop in essential svc water piping & standby gas treatment design deficiency

ILLIS, L.M. Tennessee Valley Authority. 81/01/20 1p

CKET STN-50-556 BLACK FOX STATION, UNIT 1

Application/construction stage documents & correspondence

1220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports "

EISENHUT, D.O. Division of Licensing. 80/11/26 8pp

F. Security, medical, emergency & fire protection plans

0101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR

EISENHUT, D.O. Division of Licensing 80/11/13 2pp

B101210607 Transcript of B01217 briefing on TVA emergency offsite facilities in Washington, DC Pp 1-45

* Commissioners 80/12/17 49pp

G. Adjudicatory correspondence

0101200404 FOIA request for extracts of 27 safety-related issues identified by GE in Rept Rept

BYARS, C. Houston Chronicle 80/12/10 1p 07485-315

B101200401 Responds to FOIA request for extracts of 27 safety-related issues identified by GE in Rept Rept NRC cannot provide info pending resolution of court claims Forwards NRC decision & addendum re public availability of Rept Rept w/o encls

CHALK, S.J. Office of the Secretary of the Commission 81/01/06 1p 07485-314

U. Congressional/Executive Correspondence

B101200314 Responds to B01009 ltr re NRC progress in review of CPs, use of resources for Section 110 of NRC 1980 Authorization Act, delay in adjudicatory proceedings & lack of coherent regulatory guidance. w/o encl documentation

AHEARNE, J.F. Commissioners 80/12/22 4pp

--B101200362 Responds to B01009 ltr re NRC progress in review of CPs, use of resources for Section 110 of NRC 1980 Authorization Act, delay in adjudicatory proceedings & lack of coherent regulatory guidance Related documentation encl

AHEARNE, J.F. Commissioners 80/12/22 4pp

CKET STN-50-557 BLACK FOX STATION, UNIT 2

A. Application/construction stage documents & correspondence

B101200466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports "

EISENHUT, D.O. Division of Licensing 80/11/26 8pp

F. Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR

EISENHUT, D.O. Division of Licensing 80/11/13 2pp

B101210607 Transcript of B01217 briefing on TVA emergency offsite facilities in Washington, DC Pp 1-45

* Commissioners 80/12/17 49pp

U. Congressional/Executive Correspondence

B101200314 Responds to B01009 ltr re NRC progress in review of CPs, use of resources for Section 110 of NRC 1980 Authorization Act, delay in adjudicatory proceedings & lack of coherent regulatory guidance. w/o encl documentation

AHEARNE, J.F. Commissioners 80/12/22 4pp.

--B101200362 Responds to B01009 ltr re NRC progress in review of CPs, use of resources for Section 110 of NRC 1980 Authorization Act, delay in adjudicatory proceedings & lack of coherent regulatory guidance. Related documentation encl

AHEARNE, J.F. Commissioners 80/12/22 4pp

CKET STN-50-566 YELLOW CREEK NUCLEAR PLANT, UNIT 1, TENNESSEE VALLEY

A. Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forwarding summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12. "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports "

EISENHUT, D.O. Division of Licensing 80/11/26 8pp.

B101050610 Forwards geologic rept re suggested graben in Gravelly Springs, AL area Distance to facilities precludes significance of structures Related documentation encl
LEFEVRE, H E Geosciences Branch 80/12/11 15pp

B101210642 Advises that ATWS issue will be subj of future rulemaking to determine requirements & schedules for plant mods NRC will not comment on until 800917 ltr describing program for resolving issue until rulemaking is finalised
EISENHUT, D O Division of Licensing. 80/12/29 2pp

F Security, medical, emergency & fire protection plans

B101070587 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing. 80/11/13 2pp.

G Inspection reports, IE Bulletins & correspondence

B101140619 Updates licensee corrective actions following NRC 800707-11 insp of util Div of Engineering Design. QA organization restructured to provide sufficient organizational freedom, authority & access to mgt
KIMMONS, Q H Tennessee Valley Authority 80/10/08 3pp

B101120240 Forwards response to IE Bulletin 80-20 re Westinghouse Type W-2 control switches w/spring return to neutral position Switches used in all facilities except Yellow Creek Lists sys in which switches are employed
MILLS, L M Tennessee Valley Authority 80/12/12 2pp.

B101060203 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown." No written response required.
O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/12/16 1p

B101270030 Responds to IE Bulletin 80-23 re Valcor Engineering Corp solenoid valve failure Valcor solenoid valves V70900-21-1 & V70900-21-3 not used Util waiting for vendor response on valves in package components
MILLS, L M Tennessee Valley Authority 80/12/30. 1p.

B101210239 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Util is in process of obtaining assurance from valve suppliers that no Malcolm Foundry yokes are contained in furnished valves.
MILLS, L M Tennessee Valley Authority 81/01/06 1p.

B101220055 Ack receipt of B01223 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-566/80-17 & 80-567/80-17
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 81/01/07 1p 07501:346.

--B101220058 Responds to NRC 801125 ltr re violations noted in IE Insp Repts 80-566/80-17 & 80-567/80-17 Corrective actions Part II, Section 5.1 of Div of Nuclear Power Operational QA manual rewritten
MILLS, L M Tennessee Valley Authority 80/12/23 2pp. 07501:347

--B101220060 Forwards IE Insp Repts 80-566/80-17 & 80-567/80-17 on B01015-17 & notice of violation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/25 2pp. 07501:349.

--B101220062 Notice of violation from insp on B01015-17
* Region 2, Atlanta, Office of the Director. 80/11/24. 1p. 07501:351

--B101220065 IE Insp Repts 80-566/80-17 & 80-567/80-17 on B01015-17 Noncompliance noted Failure to establish responsibilities in preservice insp of vendor shops.
TAJACI, D., COLEY, J. L Region 2, Atlanta, Office of the Director.
HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/11/24. 0pp. 07501:352

G Reportable occurrences, LFRs & related correspondence

B101190475 First interim deficiency rept re fillet weld misspecification initially reported B01210 American Inst of Steel Const stds & affected welds under review. Next rept will be submitted by B10408
MILLS, L M Tennessee Valley Authority 81/01/09 2pp. 07476:007.

B101220311 Forwards first interim rept re potential planarization of suspended ceiling tile in control rooms in response to B01104 ltr Addl info to be provided by B10211.
MILLS, L M Tennessee Valley Authority 81/01/14 3pp

BUCKET STN-50-567 YELLOW CREEK NUCLEAR PLANT, UNIT 2, TENNESSEE VAL

A Application/construction stage documents & correspondence

B101220466 Ltr to all power reactor licensees & applicants forward summary of B01112 meeting re implementation of guidance for Unresolved Safety Issue A-12, "Potential for Low Fracture Toughness & Lamellar Tearing on Component Supports"
EISENHUT, D O Division of Licensing 80/11/26 8pp.

B101050610 Forwards geologic rept re suggested graben in Gravelly Springs, AL area Distance to facilities precludes significance of structures Related documentation encl.
LEFEVRE, H E Geosciences Branch 80/12/11 15pp

B101210642 Advises that ATWS issue will be subj of future rulemaking to determine requirements & schedules for plant mods. NRC will not comment on until 800917 ltr describing program for resolving issue until rulemaking is finalised
EISENHUT, D O Division of Licensing 80/12/29 2pp.

F Security, medical, emergency & fire protection plans

B101090387 Ltr to all licensees of operating reactor plants, CP holders & CP applicants Revised radiological emergency response plans must be submitted by licensees within 60 days of B10102 & by applicants as part of FSAR
EISENHUT, D O Division of Licensing. 80/11/13 2pp

G Inspection reports, IE Bulletins & correspondence

B101140619 Updates licensee corrective actions following NRC 800707-11 insp of util Div of Engineering Design. QA organization restructured to provide sufficient organizational freedom, authority & access to mgt
KIMMONS, Q H Tennessee Valley Authority 80/10/08 3pp

B101120240 Forwards response to IE Bulletin 80-20 re Westinghouse W-2 control switches w/spring return to neutral position Switches used in all facilities except Yellow Creek Lists sys in which switches are employed
MILLS, L M Tennessee Valley Authority. 80/12/12. 2pp.

B101060203 Forwards IE Info Notice 80-44, "Actuation of ECCS in Recirculation Mode While in Hot Shutdown." No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/12/16 1p

B101270030 Responds to IE Bulletin 80-23 re Valcor Engineering Corp solenoid valve failure Valcor solenoid valves V70900-21-1 & V70900-21-3 not used Util waiting for vendor response on valves in package components
MILLS, L M Tennessee Valley Authority. 80/12/30. 1p

B101210239 Responds to IE Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Co. Inc." Util is in process of obtaining assurance from valve suppliers that no Malcolm Foundry yokes are contained in furnished valves.
MILLS, L M Tennessee Valley Authority. 81/01/06. 1p.

B101220055 Ack receipt of B01223 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-566/80-17 & 80-567/80-17
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 81/01/07. 1p. 07501:346.

--B101220058 Responds to NRC 801125 ltr re violations noted in IE Insp Repts 80-566/80-17 & 80-567/80-17 Corrective actions: Part II, Section 5.1 of Div of Nuclear Power Operational QA manual rewritten
MILLS, L M Tennessee Valley Authority. 80/12/23. 2pp. 07501:347.

--B101220060 Forwards IE Insp Repts 80-566/80-17 & 80-567/80-17 on B01015-17 & notice of violation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/11/25 2pp. 07501:349.

--B101220062 Notice of violation from insp on B01015-17
* Region 2, Atlanta, Office of the Director 80/11/24. 1p. 07501:351

--801220066 IE Insp Repts 50-566/80-17 & 50-567/80-17 on 801015-17 Noncompliance noted failure to establish responsibilities in pre-service insp of vendor shops. ZAJAC, L D - COLEY, J L Region 2, Atlanta, Office of the Director HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/11/24 Bpp 07501 352

B Reportable occurrences, LERs & related correspondence

B012190475 First interim deficiency rept re fillet weld misspecification initially reported B01210 American Inst of Steel Const stds & affected welds under review Next rept will be submitted by 810408 MILLS, L M Tennessee Valley Authority 81/01/09 2pp 07476-007

B01220311 Forwards first interim rept re potential flammability of suspended ceiling tile in control rooms in response to B01104 ltr Addl info to be provided by B10211 MILLS, L M Tennessee Valley Authority 81/01/14 3pp

DOCKET STN-50-900 ERIE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

B012100002 Addl response to FOIA request for nine categories of records re fees concerning withdrawn, suspended or postponed applications Forwards documents listed in App A FELTON, J M Division of Rules and Records 80/11/21 3pp

--8005220807 Advises of contractual costs associated w/review of CP application Billing may be completed for project BERKOW, H H Administrative Section Branch (Pre 790604) 80/04/18 1p 02632-208

--8011240009 Submits summary of CP review costs incurred by various program ofcs from filing of application to date of withdrawal. HOLLGWAY, C J License Fee Management Branch. 80/11/10 1p 02227 001

--8011250112 Requests billing of util for fees for review of CP application, withdrawn on B00123 Ofc of Administration should be notified when total amount is collected MILLER, W O License Fee Management Branch 80/11/10 1p 07052-284

--8012100086 Forwards IE cost data worksheets reflecting manpower expended on review of CP application withdrawn on B00128 COBB, L I Executive Officer for Management & Analysis 80/04/22 3pp

--8012100091 Informs that 302 prof manhours were expended in joint CP review of facility, in response to B00320 request MCKINNEY, R E ACRS - Advisory Committee on Reactor Safeguards 80/04/11 1p

--8012100105 Informs that no manhours were expended in connection w/sua sponte review of ASLB action in facility proceeding, in response to B00320 request. ROSENTHAL, A S Atomic Safety and Licensing Appeal Panel 80/03/24 1p

--8012100111 Confirms ASLBP B00331 rept All ASLB time was spent as contested case. No record of prof manhours on facility recorded FITZ, C J Atomic Safety and Licensing Board Panel 80/05/22 1p

--8012100120 Informs that prof manhours expended by ASLBP re CP application have not been recorded Proceeding was contested LAZO, R M Atomic Safety and Licensing Board Panel. 80/03/31 1p

DOCKET STN-50-581 ERIE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

B012100002 Addl response to FOIA request for nine categories of records re fees concerning withdrawn, suspended or postponed applications Forwards documents listed in App A FELTON, J M Division of Rules and Records 80/11/21 3pp

--8005220807 Advises of contractual costs associated w/review of CP application Billing may be completed for project BERKOW, H H Administrative Section Branch (Pre 790604) 80/04/18 1p 02632-208

--8011240009 Submits summary of CP review costs incurred by various program ofcs from filing of application to date of withdrawal. HOLLGWAY, C J License Fee Management Branch 80/11/10 1p 02227 001

--8011250112 Requests billing of util for fees for review of CP application, withdrawn on B00123 Ofc of Administration should be notified when total amount is collected. MILLER, W O License Fee Management Branch 80/11/10 1p 07052-284

--8012100086 Forwards IE cost data worksheets reflecting manpower expended on review of CP application withdrawn on B00128 COBB, L I Executive Officer for Management & Analysis 80/04/22 3pp

--8012100091 Informs that 302 prof manhours were expended in joint CP review of facility, in response to B00320 request MCKINNEY, R E ACRS - Advisory Committee on Reactor Safeguards 80/04/11 1p

--8012100105 Informs that no manhours were expended in connection w/sua sponte review of ASLB action in facility proceeding, in response to B00320 request ROSENTHAL, A S Atomic Safety and Licensing Appeal Panel 80/03/24 1p

--8012100111 Confirms ASLBP B00331 rept All ASLB time was spent as contested case. No record of prof manhours on facility recorded FITZ, C J Atomic Safety and Licensing Board Panel 80/05/22 1p

--8012100120 Informs that prof manhours expended by ASLBP re CP application have not been recorded Proceeding was contested LAZO, R M Atomic Safety and Licensing Board Panel 80/03/31

DOCKET 50-582 SUNDEBERT, UNIT 1

A Application/construction stage documents & correspondence

B01190738 Forwards FR notice of withdrawal of CP application YOUNGBLOND, B J Licensing Branch 1 81/01/09 3pp 07476-116

--801190741 Notice of CP application withdrawal. YOUNGBLOND, B J Licensing Branch 1 81/01/09 1p 07476-119

DOCKET 50-583 SUNDEBERT, UNIT 2

A Application/construction stage documents & correspondence

B01190738 Forwards FR notice of withdrawal of CP application YOUNGBLOND, B J Licensing Branch 1 81/01/09 3pp 07476-116

--801190741 Notice of CP application withdrawal. YOUNGBLOND, B J Licensing Branch 1 81/01/09 1p 07476-119

DOCKET STN-50-592 PALU VERDE NUCLEAR STATION, UNIT 4

A Application/construction stage documents & correspondence

B012100002 Addl response to FOIA request for nine categories of records re fees concerning withdrawn, suspended or postponed applications Forwards documents listed in App A FELTON, J M Division of Rules and Records 80/11/21 3pp

--8005080556 Advises of reported review cost for CP application Bill procedure may be completed. BERKOW, H H Office of Nuclear Reactor Regulation, Director 80/04/23 1p 02593 363

--8011240009 Submits fees incurred for CP review from application to date of withdrawal. Draft memo encl MILLER, W O License Fee Management Branch. 80/11/10 2pp 03747 253

--8012100031 Discusses CP review cost for facilities through 790824 withdrawal of application NRC Ofc of Controller will be notified to bill util for costs incurred for review w/o encl summary of review costs. HOLLGWAY, C J License Fee Management Branch 80/11/10 1p

--B012100550 Forwards IE cost data worksheets for facilities Review of contract & consultant records did not reveal any cost directly associated w/facilities
COBB, L. I. Executive Officer for Management & Analysis 79/11/20 3pp

--B012100059 Informs that 216 2 prof manhours were expended in joint CP review for facility, in response to 791026 request.
FRALEY, R F ACRS - Advisory Committee on Reactor Safeguards 79/11/29 1p

--B012100071 Informs that prof manhours expended by ASLB re CP applications have not been recorded Proceeding was contested
LAZD, R M Atomic Safety and Licensing Board Panel 79/10/30 1p

--B012100080 Informs that no prof manhours were expended in review of CP applications for facility
ROSENTHAL, A B Atomic Safety and Licensing Appeal Panel 79/10/29 1p

DOCKET 50-50-593 PALO VERDE NUCLEAR STATION, UNIT 3

A Application/construction stage documents & correspondence

B012100002 Addl response to FOIA request for nine categories of records re fees concerning withdrawn, suspended or postponed applications Forwards documents listed in App A
FELTON, J M Division of Rules and Records 80/11/21 5pp

--B035053555 Advises of reported review cost for CP application Billing procedure may be completed
BERKHAUS, L R Office of Nuclear Reactor Regulation, Director 80/04/23 1p 02593 363

--B011260593 Submits fees incurred for CP review from application filing to date of withdrawal Draft memo encl
MILLER, W D License Fee Management Branch 80/11/10 2pp 03747 253

--B012100031 Discusses CP review cost for facilities through 790824 withdrawal of application NRC Ofc of Controller will be notified to bill util for costs incurred for review. W/O encl summary of review costs.
HOLLOWAY, L J License Fee Management Branch 80/11/10 1p

--B012100050 Forwards IE cost data worksheets for facilities Review of contract & consultant records did not reveal any cost directly associated w/facilities
COBB, L. I. Executive Officer for Management & Analysis. 79/11/20 3pp

--B012100059 Informs that 216 2 prof manhours were expended in joint CP review for facility, in response to 791026 request
FRALEY, R F ACRS - Advisory Committee on Reactor Safeguards. 79/11/29 1p

--B012100071 Informs that prof manhours expended by ASLB re CP applications have not been recorded Proceeding was contested
LAZD, R M Atomic Safety and Licensing Board Panel 79/10/30 1p.

--B012100080 Informs that no prof manhours were expended in review of CP applications for facility
ROSENTHAL, A B Atomic Safety and Licensing Appeal Panel 79/10/29 1p

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

DOCKET 70-0008 BATTELLE COLUMBUS LABORATORIES

B010100777 Forwards IE Insp Repts 70-0008/80-02, 30-05728/80-02 & 50-006/80-01 & notice of violation
KEPPLER, J O Region 3, Chicago, Office of the Director. 80/12/08 2pp 07444 062

--B010100783 Notice of violation from Insp on 800422-26 & 1112
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/03 1p 07444 064

--B010100811 IE Insp Repts 50-006/80-01, 70-0008/80-02 & 30-05728/80-02 on BOC922-26 & 1112 Noncompliance noted overexposure of one individual to external radiation & excess radioactivity concentrations in fuel storage pool
PECK, C C Region 3, Chicago, Office of the Director. FISHER, W. L. Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/11/25 10pp 07444 065

DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP

B012100002 Addl response to FOIA request for nine categories of records re fees concerning withdrawn, suspended or postponed applications Forwards documents listed in App A
FELTON, J M Division of Rules and Records 80/11/21 5pp

--B012100199 Requests partial refund of fee due Rockwell Intl in connection w/780823 application for amend to License SNM-21 Lists actual manhours required for review & amount of refund due
MILLER, W D License Fee Management Branch 78/12/22 1p

--B012100284 Notifies of partial refund re abandoned application to License SNM-21 Ofc of Controller has been notified
MILLER, W D License Fee Management Branch 78/12/22 1p

B01070555 Forwards notice of violation from Insp of License SNM-21 on B01120 Areas inspected security procedures of transportation activities Notice withheld (ref 10CFR2 790)
MORDEHAUS, L R Region 5, San Francisco, Safeguards Branch 80/12/02 2pp 07415 234

B01160052 Forwards IE Insp Rept 70-0025/80-10 on B01023-24 & 1103-07 No noncompliance noted Encl withheld (ref 10CFR2 790)
MORDEHAUS, L R Region 5, San Francisco, Safeguards Branch 81/01/07 2pp 07470 350

B01290545 Forwards IE Insp Rept 70-0025/80-13 conducted on B01208-14 No noncompliance noted Major areas inspected control & accounting program of SNM Encl withheld (ref 10CFR2 790)
MORDEHAUS, L R Region 5, San Francisco, Safeguards Branch 81/01/13 2pp 07575 264

DOCKET 70-0027 BARCOCK & WILCOX CO

B01150029 Responds to B00607 request to use DOE printed instructions for completing Matl Statute & Matl Transfer Repts Approves request & revises Safeguards Amend MMP-1 accordingly
PARTLO, J O Material Control Licensing Branch 80/12/02 1p 07462 163

B01050594 Forwards IE Insp Rept 70-0027/80-17 on B01028-31 No noncompliance noted
KEPPLER, J O Region 2, Atlanta, Safeguards Branch 80/12/11 1p 07390 247

--B010505993 IE Insp Rept 70-0027/80-17 on B01028-31 No noncompliance noted Major areas inspected records, rept storage, internal controls, measurement controls & matl controls mgt Details withheld (ref 10CFR2 790)
FINLEY, A O, PATTERSON, J P, BATES, J W Region 3, Chicago, Office of the Director. 80/11/17 1p 07390 248

B01070566 Informs of cost & manhours incurred for reviewing B&W B00603 application to amend License SNM-42 Application withdrawn B01028
KETZLACH, N., PAGE, R O Uranium Fuel Licensing Branch 80/12/11 1p 07415 282

B01210267 Safety evaluation supporting license amend authorizing CO of additions to north end of Bays 1A & 2A, mod of process in Bay 3A & utilization of SNM in expanded facility, per vendor 763807 application & B01211 suppl
KETZLACH, N., CROW, W T Uranium Fuel Licensing Branch. 80/12/30 2pp 07492 057

B01220212 Amend 13 to License SNM-42, authorizing hot isostatic press operations re modified process, in response to 780807 application & B01211 suppl
PAGE, R O Uranium Fuel Licensing Branch 80/12/30 1p 07495 3

B01280418 Notifies that Amend 12 to License SNM-43, issued B01230, was mistakenly identified as Amend 13
PAGE, R O Uranium Fuel Licensing Branch 81/01/14 1p 07588 0

DOCKET 70-0033 TEXAS INSTRUMENTS, INC

B012100002 Addl response to FOIA request for nine categories of records re fees concerning withdrawn, suspended or postponed applications Forwards documents listed in App A
FELTON, J M Division of Rules and Records 80/11/21 5pp

--B010150034 Submits costs & manhours for review of 790215 application for renewal of License SNM-23
KETZLACH, N Uranium Recovery Licensing Branch 80/09/26 1p
03630 250

B010160116 Forwards IE Insp Rept 70-0033/80-10 on B01029-31 No noncompliance noted
SMITH, Q. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/11/26 2pp 07469 329

--B010160125 IE Insp Rept 70-0033/80-10 on B01029-31 No noncompliance noted Major areas inspected training, terminations, smears, bioassay, procedures & ventilation
CLEMONS, P Region 1, Philadelphia, Office of the Director
KNAAPP, P J Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/11/24 6pp 07469 331

DOCKET 70-0121 INTERIOR, DEPT. OF, GEOLOGICAL SURVEY

B01070563 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Materials" No written response required
SMITZ, J. H. Division of Fuel Facility & Materials Safety 80/08/29 1p 07415 341

DOCKET 70-0124 TELEDYNE ISOTOPES

B010190100 Ack receipt of vendor B01110 ltr re possession of radioactive matl in excess of license limits
KINIERAN, J. D. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/12/29 1p 07475 317

--B010190103 Provides written notification of item of noncompliance re possession of U-235 in excess of license limits
BLACK, S. A. Teledyne Isotopes 80/11/10 1p 07475 310

DOCKET 70-0135 BARCOCK & WILCOX CO

B010300191 Forwards IE Insp Rept 70-0135/80-29 on B01007-10 & 20-23 No noncompliance noted
MARTIN, W. Q. Region 1, Philadelphia, Safeguards Branch 80/11/14 2pp 07500 355

--B010300196 IE Insp Rept 70-0135/80-29 on B01007-10 & 20-23 No noncompliance noted Major areas inspected measurements of residual U holdup in high enriched U facility Details withheld (ref 10CFR2.790)
DISETT, P., CONEY, I., HOLUDY, D. Region 1, Philadelphia, Safeguards Branch 80/11/13 1p 07500 357

B010260772 Ack receipt of B01118 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0135/80-27 Encl to B01118 ltr withheld (ref 10CFR2.790)
MARTIN, W. Q. Region 1, Philadelphia, Safeguards Branch 80/12/10 1p 07536 022

--B010260776 Nonproprietary response to NRC B01028 ltr re violations noted in IE Insp Rept 70-0135/80-27 Corrective actions withheld (ref 10CFR2.790)
AUSTIN, M. A. Barcock & Wilcox Co., Nuclear Material Div. 80/11/18 1p 07536 023

--B010260782 Forwards nonproprietary version of IE Insp Rept 70-0135/80-27 on B00908-10 & notice of violation Portions of insp rept & notice of violation withheld (ref 10CFR2.790)
ORIER, B. H. Region 1, Philadelphia, Office of the Director 80/10/28 2pp 07536 024

--B010260787 Nonproprietary version of IE Insp Rept 70-0135/80-27 on B00908-10 Noncompliance noted Failure to have required number of security force members on duty Details withheld (ref 10CFR2.790)
MCKEDON, L. M., SMITH, O. Region 1, Philadelphia, Office of the Director
DEVLIN, J. W. Region 1, Philadelphia, Safeguards Branch 80/10/20 1p 07536 026

DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC

B01090814 Forwards IE Insp Rept 70-0143/80-35 on B00909-1104 No noncompliance noted
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/11/25 2pp 07430 259

--B01090821 IE Insp Rept 70-0143/80-35 on B00909-1104 No noncompliance noted Major areas inspected reported inventory difference which exceeded limit of error on inventory difference Details withheld (ref 10CFR2.790)
KAHLE, J. B. Region 2, Atlanta, Office of the Director KENNA, Region 2, Atlanta, Safeguards Branch 80/11/24 1p 07430 2

B01060279 Ack receipt of B01112 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0143/80-29
KENNA, W. B. Region 2, Atlanta, Safeguards Branch 80/12/15 1p 07392 022

--B01060287 Responds to NRC B01024 ltr re violations noted in IE Insp Rept 70-0143/80-29 Attachment withheld (ref 10CFR2.790)
MANSER, W. C. Nuclear Fuel Services, Inc (subs of Getty Oil Co) 80/11/12 1p 07392 023

--B01060291 Forwards IE Insp Rept 70-0143/80-29 on B00811-0912 & violation Notice of violation withheld (ref 10CFR2.790)
KENNA, W. B. Region 2, Atlanta, Safeguards Branch 80/10/24 07392 024

--B01060295 IE Insp Rept 70-0143/80-29 on B00811-0912 Noncompliance noted containers not tamper-safe Details withheld (ref 10CFR2.790)
LEE, T. D. Region 2, Atlanta, Office of the Director KAHLE, J. B. Region 2, Atlanta, Safeguards Branch 80/10/24 1p 07392 0

B01080378 Responds to B01120 ltr requesting 6-month time extension recovering certain "old generation" scrap matls Extension granted Encl to B01120 ltr withheld (ref 10CFR2.790)
PARTLOW, J. D. Material Control Licensing Branch 80/12/17 1p 07416 361

B011140818 Responds to B00922 ltr re NRC response to public law re addition of six positions in Div of Safeguards devoted to regulatory improvement & requesting info re facility inventory differences Six person task force formed
WHEATHE, J. F. Commissioners 80/12/18 2pp 07461 319

--B011140832 Responds to B00922 ltr re NRC response to public law re addition of six positions in Div of Safeguards devoted to regulatory improvement & requesting info re facility inventory differences Six person task force initiated
WHEATHE, J. F. Commissioners 80/12/18 2pp 07461 321

--B011140846 Requests info re NRC response to Public Law 96-295 re addition of six Div of Safeguards positions devoted to regulatory improvements Also requests monthly reports re facility matl losses vs limits prior to B00626 order
UDALL, M. K. House of Rep., Interior & Insular Affairs
QUILLEN, J. H. House of Rep 80/09/22 2pp 07461 323

B01020219 Ack receipt of revised Sections 1.0.3 0.4.0 & 0.0 to fundamental nuclear matl control plan Plan revisions acceptable except Section 4.2.3.2
PARTLOW, J. D. Material Control Licensing Branch 80/12/22 2pp 07447 039

B01060812 Addl response to FOIA request for info re Pu unaccounted at facility Forwards IE rept, "Technical Assessment of Inventory Differences at NBS Jan 1978-Mar 1980"
FELTCH, J. H. Division of Rules and Records 80/12/24 1p 07400 125

--B01060819 Informs NRC of possible overexposure to highly enriched employee Exposure resulted from leak in U hexafluoride process vent sys. Lists rods to prevent recurrence. RD Bailey 790906 ltr encl
MANSER, W. C. Nuclear Fuel Services, Inc (subs of Getty Oil Co) 79/09/06 5pp

B01060131 Ack receipt of B01219 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0143/80-24
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/12/30 1p 07469 338

--B01060138 Advises that scheduled commitment dates will be delayed to delays in equipment delivery New commitment dates listed All other corrective actions completed as scheduled
MANSER, W. C. Nuclear Fuel Services, Inc (subs of Getty Oil Co) 80/12/19 1p 07469 337

--B01060148 Ack receipt of B01015 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0143/80-24 Supplemental response re review of hexanal storage & process sys within Bldgs 302 & 303 to be submitted by B01205
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/11/05 1p 07469 341

DOCKET 70-0157 TEXAS, UNIV OF

8101070574 Forwards IE Info Notice 80-32. Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Materials. No written response required.
SMITCHEL, J H Division of Fuel Facility & Materials Safety
80/08/29 1p 07415 337

DOCKET 70-0168 ANCLIDE CORP

8101290119 Order to show cause why License SM-168 should not be revoked permanently due to failure to pay insp fee
MILLER, W D License Fee Management Branch 81/01/19 3pp
07567 262

DOCKET 70-0761 SCHLUMBERGER TECHNOLOGY CORP

8101130213 Ack receipt of 801114 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0261/80-01, 30-03766/80-01 & 30-03767/80-01
KINNEMAN, J U Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/12/23 1p 07452.087

--8101130260 Responds to NRC 801024 ltr re violations noted in IE Insp Repts 70-0261/80-01, 30-03766/80-01 & 30-03767/80-01
Corrective actions instituted: continuous surveillance of test shack area; rope & sign fence erected.
QUISELORFERRY, K Schlumberger Technology Corp 80/11/14 2pp
07452 098

DOCKET 70-0354 KANSAS, UNIV OF

8101070581 Forwards IE Info Notice 80-32. Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Materials. No written response required.
SMITCHEL, J H Division of Fuel Facility & Materials Safety
80/08/29 1p 07415 327

DOCKET 70-0364 PARKS TOWNSHIP SITE, BARCOCK & WILCOX CO

8012100022 Addl response to FOIA request for nine categories of records re fees concerning withdrawn, suspended or postponed applications. Forwards documents listed in App A
FELTON, J M Division of Rules and Records 80/11/21 5pp

--8012100322 Requests partial refund of fee to B&W re review of 790911 application for amend to License SM-414 (lists actual manhours required for review & amount of refund due).
MILLER, W D License Fee Management Branch 80/01/21 1p

--8012100327 Submits costs & manhours incurred in review of 790911 application for amend to License SM-414
McCORMACK, D W Physical Security Licensing Branch PARLOUGH, J O Material Control Licensing Branch 80/01/07 1p

8101100704 Amend 11 to License SM-414 revising Spec 1-4 (organization) & Spec 1-5 (Tech Specs & control sys) of conditions section.
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 80/12/22 2pp 07445 101

--8101100707 Safety evaluation of license amend applications for revisions to Specs 1-4 & 1-5 of License SM-414. Recommends approval.
BURKHARDT, W J ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 80/12/22 2pp 07445 121

DOCKET 70-0371 UNITED NUCLEAR CORP.

8012100002 Addl response to FOIA request for nine categories of records re fees concerning withdrawn, suspended or postponed applications. Forwards documents listed in App A.
FELTON, J M Division of Rules and Records 80/11/21 3pp.

--8012100160 Requests partial refund of amend fee to United Nuclear Corp re review of 780113 amend application. Lists actual manhours required to review application & amount of refund due.
MILLER, W D License Fee Management Branch 78/08/01 1p

8101070561 Informs of costs & manhours incurred for reviewing United Nuclear Corp 800919 application to amend License SM-368
STEVENSON, R L PAGE, R G Uranium Fuel Licensing Branch 80/12/11 1p 07415 203

8101200574 Ack receipt of 801117 ltr re IE Insp Rept 70-0371/80-07. It is App A of NRC 800515 ltr stands as item of noncompliance. Future assignments for annual audit will include instructions to meet license requirements.
SMITH, O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/12/12 1p 07503 155

--8101200577 Responds to NRC 801105 ltr re IE Insp Rept 70-0371/80-07. License SM-368 does not require results of audit be completely documented w/written procedures or checklists.
OAKLEY, D E United Nuclear Corp, Naval Products Div 80/11/17 1p 07503 156

--8101200581 Ack receipt of 800929 ltr in response to NRC 800402 ltr. IE Insp Rept 70-0371/80-07. Reviews by corporate nuclear safety team & American Nuclear Insurers do not constitute adequate audit.
SMITH, O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/11/05 2pp 07503 157

--8101200584 Responds to NRC 800402 ltr re licensee 800609 ltr info forwarded by 800609 ltr was expected to be sufficient to demonstrate corporate nuclear safety team review was adequate annual audit w/o encl 791128 audit rept.
OAKLEY, D E United Nuclear Corp, Naval Products Div 80/09/24 2pp 07503 154

--8101200588 Ack receipt of 800609 ltr in response to NRC 800515 ltr. IE Insp Rept 70-0371/80-07. Requests submission of info not forwarded w/800609 ltr. Bldg D South was not posted properly during insp.
SMITH, O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/09/02 2pp 07503 161

--8101200529 Responds to NRC 800515 ltr re IE Insp Rept 70-0371/80-07. Inspector was presented w/info to justify corporate nuclear safety team review at adequate ANI 791030 Insp rept & nuclear safety team review encl.
OAKLEY, D E United Nuclear Corp, Naval Products Div 80/06/09 17pp 07503 163

--8101200632 Forwards IE Insp Rept 70-0371/80-07 on 800409-11 & notice violation.
SMITH, O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/05/15 2pp 07503 181

--8101200634 Notice of violation from Insp on 800409-11.
Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/05/06 1p 07503 183

--8101200638 IE Insp Rept 70-0371/80-07 on 800409-11. Noncompliance notices. Failure to conduct audit & failure to post area.
CLEMONS, P Region 1, Philadelphia, Office of the Director, KNAPP, P J Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/05/06 7pp 07503 184

8101120214 Responds to 801119 ltr re partial revisions to Chapters 3 & 4.0 of fundamental nuclear matl control plan. Barriorius scale performance capabilities changed.
PARLOUGH, J O Material Control Licensing Branch 80/12/19 2pp 07447 037

8101130196 Requests payment of administrative amend fee for page changes to fundamental nuclear matl control plan.
WEISS, D License Fee Management Branch 80/12/19 1p 07309 001

8101190229 Forwards revised Amend HPP-2 to License SM-368, amending fundamental nuclear matl control plan, in response to 801202 request New License Condition 2.1 incorporates revisions.
PARLOUGH, J O Material Control Licensing Branch 80/12/24 2pp 07475 303

8101070598 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Materials." No written response required
SNIEZEK, J H Division of Fuel Facility & Materials Safety
80/08/29 1p 07414-176

DOCKET 70-0687 UNION CARBIDE CORP.

8101100137 Submits info re exemption from compliance w/10CFR70.24 in portions of criticality monitoring program where requirements are inappropriate. Exemption requested for areas where matl is handled in dry oxide form
VOTH, H H Union Carbide Corp 80/12/05 8pp 07441-341

8101070226 Recommends that nuclear criticality safety aspects of Union Carbide Corp application to store waste form process containers underwater in transfer canal at facility receive approval
PAGE, R G Uranium Fuel Licensing Branch 80/12/11 1p 07415-240

8101130232 Requests payment of addl minor safety & environ amend fee for Amend 3 to License BNM-639
WEISS, D License Fee Management Branch 80/12/19 1p 07309-001

8101130123 Application for amend to License R-B1 & License BNM-639 to change licensee name from Union Carbide Corp to Union Carbide Subsidiary H, Inc (Co B)
MCGOVERN, J J Union Carbide Corp 81/01/08 1p 07449-361

DOCKET 70-0720 UTAH, UNIV OF

8101070579 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Materials." No written response required
SNIEZEK, J H Division of Fuel Facility & Materials Safety
80/08/29 1p 07415-325

DOCKET 70-0734 GENERAL ATOMIC CO

8101210002 Addl response to FOIA request for nine categories of records re fees concerning withdrawal, suspended or postponed applications. Forwards documents listed in App A
FELTON, J M Division of Rules and Records 80/11/21 5pp

--8012100268 Requests withdrawal of 780413 proposed amend to License BNM-368. Amend fee should be returned
KIRK, W F United Nuclear Corp 78/06/12 1p

--8012100336 Notifies of partial refund of fee re 780629 application for amend to License BNM-696 due to NRC denial. Actual expenditures for prof manpower have been determined & Ofc of Controller notified
MILLER, W O License Fee Management Branch 80/02/01 1p

--8012100340 Requests partial refund of fee to OA Co re review of 780629 application for amend to License BNM-696. Lists actual manhours required for review & amount of refund due.
MILLER, W O License Fee Management Branch 80/02/01 1p

--8012100344 Submits costs & manhours incurred in review of 780629 application for amend to License BNM-696
MCCORMACK, Q W Physical Security Licensing Branch, PATLOW, J Q Material Control Licensing Branch 79/12/17 1p

8101290537 Forwards IE Insp Rept 70-0734/80-10 on 800915-19. No noncompliance noted
BOOK, H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 80/12/04 2pp 07309-001

--801290542 IE Insp Rept 70-0734/80-10 on 800915-19. No noncompliance noted. Major areas inspected: liquid waste evaporation ponds & submerged radioactive liquid waste retention tanks for possible leakage & environ monitoring
COOLEY, W J, THOMAS, R D, BOOK, H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 80/12/01 10pp 07309-001

8012100602 Addl response to FOIA request for nine categories of records re fees concerning withdrawal, suspended or postponed applications. Forwards documents listed in App A
FELTON, J M Division of Rules and Records 80/11/21 5pp

--8012100187 Notifies of partial refund due re withdrawal of 780629 application for amend to License BNM-960 Ofc of Controller has been notified
MILLER, W O License Fee Management Branch 78/08/23 1p

--8012100192 Requests partial refund of fee due OE re review of application for amend to License BNM-960. Lists actual manhours required for review & amount of refund due
MILLER, W O License Fee Management Branch 78/08/23 1p

--8012100277 Denies 780405 application for amend to License BNM- exempt Vital Areas 2.3 & 5. Reasons provided are inadequate to support redesignation of vital areas
MCCORMACK, Q W Physical Security Licensing Branch 78/07/14

8101050494 Response to AELB 801210 notice of second prehearing conference. Prehearing process should resume immediately. Evidentiary hearing should begin 60 days after 810106 prehearing conference
EDGAR, G L General Electric Co 80/12/29 3pp 07390-221

8101160236 Responds to State of CA Regional Water QC Board 80102 re proposed radiological environ monitoring program. Licensee review of program, reflecting board resolution, will be considered in license renewal evaluation
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 80/12/29 3pp 07460-355

8101290522 Forwards increment of analysis of effects of natural phenomena re facility. Two repts & LLL draft "Seismic Evaluation of Bldg 102 of GE Vallecitos Nuclear Ctr" encl
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 81/01/19 2pp 07573-001

--8101290527 Draft "Seismic Evaluation of Bldg 102 of GE Vallecitos Nuclear Ctr"
ENDEBROCK, E O Los Alamos Scientific Laboratory 81/01/19 112pp 07573-003

--8101290529 Forwards Hall & Newmark review of LLL draft rept, "Evaluation of Bldg 102 of GE Vallecitos Nuclear Ctr". Recommends that review be adopted as staff position
AYER, J E, BURKHARDT, W Advanced Fuel & Spent Fuel Licensing Branch 81/01/19 1p 07573-115

DOCKET 70-0818 EASTERN NAZARENE COLLEGE

8101290588 Discusses IE Insp Rept 70-0818/80-01 conducted on 801015. Noncompliance noted. Major areas inspected: examination of procedures, representative records & measurements & observations by inspector.
KINNEHAN, J D Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/11/25 1p 07571-316

DOCKET 70-0820 UNITED NUCLEAR CORP

8101290754 Forwards IE Insp Rept 70-0820/80-21 on 801015. No noncompliance noted
MARTIN, W O Region 1, Philadelphia, Safeguards Branch 80/12/29 07568-227

--8101290758 IE Insp Rept 70-0820/80-21 on 801015. No noncompliance noted. Major areas inspected: packaging & sealing matl for export
JOYNER, J H Region 1, Philadelphia, Safeguards Branch
MCKEOWN, L M Region 1, Philadelphia, Office of the Director 80/11/12 1p 07568-229

8101230218 Forwards IE Insp Rept 70-0820/80-22 on 801104-05. No noncompliance noted. Details of insp withheld (ref 10CFR2.790)
MARTIN, W O Region 1, Philadelphia, Safeguards Branch 80/12/29 07511-061

--8101230223 IE Insp Rept 70-0820/80-22 on 801104-05. No noncompliance noted. Major areas inspected: verification of imports & exports & review of SNM holdings. Details of insp withheld (ref 10CFR2.790)
ZIBULSKY, H Region 1, Philadelphia, Office of the Director
JOYNER, J H Region 1, Philadelphia, Safeguards Branch 80/12/29 07511-063

8101210188 Submits agenda of issues to be discussed at next Citizens
Advisory Committee state meeting w/related info
GRANT, M. Rhode Island, State of 80/12/05 18pp 07308 001

DOCKET 70-0925 CIMARRON FACILITY

8101190221 Notifies that shipment of residual waste composed of
collected ash, discussed in 801224 telcon, will be approved,
pending verification of QA program procedures. Approval of
lagoon 3, and waste shipments has been deferred.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
80/12/11 2pp 07475 307

8012100902 Addl response to FOIA request for nine categories of re
re fees concerning withdrawn, suspended or postponed
applications. Forwards documents listed in App A
FELTON, J. M. Division of Rules and Records 80/11/21. 5pp

--8012100380 Notifies of partial refund due re 790918 application
amend to License SNM-928 to use facility for bench-scale
coal liquefaction development project. No amend to license
was necessary.
MILLER, W. D. License Fee Management Branch 80/03/28 1p

8101160205 Forwards list of identification numbers re drums & boxes
that are acceptable for shipment & burial in Barnwell, SC. NRC
insp verified that packages contained no liquid waste.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
80/12/15 2pp 07468 331

--8012100385 Requests partial refund of fee to Kerr-McGee Nuclear
application for amend to License SNM-928. Lists actual
manhours required for review & amount of refund due.
MILLER, W. D. License Fee Management Branch 80/03/28 1p

8101160410 Discusses NRC 801210-12 & 15 insp of packaged waste for
shipment from facility to SC. Waste is properly packaged for
shipment & burial.
GRIER, B. H. Region 1, Philadelphia, Office of the Director
80/12/16 2pp 07309 001

--8012100389 Submits costs & manhours incurred in reviewing 790918
application for amend of License SNM-928. Review was
completed on 791228.
DELANEY, J. C., PAGE, R. Q. Uranium Fuel Licensing Branch 80/03/28 1p

--8101160412 Submits list of drums & contents for waste shipment from
facility to SC burial site.
O'DONNELL, J. United Nuclear Corp 80/12/12 2pp 07309 001

DOCKET 70-1007 GENERAL ELECTRIC CO

--8101160413 Submits list of boxes & contents for waste shipment from
facility to SC burial site.
O'DONNELL, J. United Nuclear Corp 80/12/12 1p 07309 001

8101090343 Amend 3 of License SNM-59, changing License Condition 2
performance of flow rate checks on process ventilation sys &
incorporating Conditions 34 & 35 re exemption from
criticality & emergency drill requirements.
PAGE, R. Q. Uranium Fuel Licensing Branch 80/11/10. 2pp
07425 341.

--8101160414 Submits list of boxes & contents for waste shipment from
facility to SC burial site.
O'DONNELL, J. United Nuclear Corp 80/12/12 1p 07309 001

--8101090351 Safety evaluation re application to amend License SNM-59
exempting requirements re annual ventilation flow rate
checks & criticality & emergency drill. Recommends issuance
of amend.
STEVENSON, R. L., CROW, W. T. Uranium Fuel Licensing Branch
80/11/10 2pp 07425 343

8101190262 Forwards revised Amend MPP-2 to License SNM-777, amending
decommissioning fundamental nuclear matl control plan in
response to 801203 request. New License Condition 2 I
incorporates revisions re timing of record adjustments.
PARTLOW, J. O. Material Control Licensing Branch 80/12/22 2pp.
07476 049

DOCKET 70-1035 BRIDHAM YOUNG UNIV.

8101050551 PHD-I-80-129 United Nuclear Corp Recovery Sys granted
permission to ship non-lagoon waste to Barnwell, SC, for
burial. Region 1 inspected packaging consisting of 61 drums &
16 boxes of waste for QA. Waste shipped on 801217 & 19.
KINNEY, W. W., CROCKER, H. W. Region 1, Philadelphia, Office of the
Director 80/12/23 2pp 07375 336.

8101070598 Forwards IE Info Notice 80-32, "Clarification of Certain
Requirements for Exclusive Use Shipments of Radioactive
Mats." No written response required.
SNIEXEK, J. H. Division of Fuel Facility & Materials Safety
80/08/29 1p 07414 176

DOCKET 70-0821 WASHINGTON & LEE UNIV.

8101090796 Submits estimated resource requirements for completing QESMD
proceeding. Differences in estimates for original QESMD
project & estimates to complete proceeding noted.
CUAVINGHAM, R. E. Division of Fuel Cycle & Materials Safety 80/09/15.
3pp 07309 001

DOCKET 70-1100 COMBUSTION ENGINEERING, INC

8101060739 Forwards IE Insp Rept 70-1100/80-09 on 801006-10. No
noncompliance noted.
MARTIN, W. Q. Region 1, Philadelphia, Safeguards Branch 80/10/24
2pp 07400 259

DOCKET 70-0824 BABCOCK & WILCOX CO.

8101120548 Discusses info required for development of criteria re
decontamination of area adjacent to property. Area must be
decontaminated & radionuclides identified.
CROW, W. T. Uranium Fuel Licensing Branch 80/12/30 2pp
07447 187

--8101060747 IE Insp Rept 70-1100/80-09 on 801006-10. No noncompliance
noted. Major areas inspected: records & repts & licensee
action on immediate action ltr. Portions withheld (ref
10CFR2.7901)
DELLA RATTIA, A., WOLTER, E. F. Region 1, Philadelphia, Office of
Director. JOYNER, J. H. Region 1, Philadelphia, Safeguards Branch
80/10/29 1p 07400 301

DOCKET 70-0882 COLUMBIA UNIV.

8101230319 Forwards renewed License SNM-0870, containing conditions
discussed & agreed upon on 801113 License valid for 5
yrs. Amends must be requested in form of replacement pages to
license application.
PAGE, R. Q. Uranium Fuel Licensing Branch 81/01/14. 1p. 07512:073

8101300157 Ack receipt of 801024 ltr informing NRC of steps taken
correct violations noted in IE Insp Rept 70-1100/80-07.
SMITH, O. H. Region 1, Philadelphia, Fuel Facility & Materials Safety
Branch 80/11/17 1p 07583:162

--8101230323 License SNM-0870 for Columbia Univ in NY City authorizing
possession & use of U-235, U-232 & Pu in fission counters &
for storage purposes.
PAGE, R. Q. Uranium Fuel Licensing Branch 81/01/14. 17pp
07512 076.

--8101300164 Responds to NRC 801008 ltr re violations noted in IE
Rept 70-1100/80-07. Corrective actions: criticality analyses
for not-safe-by-geometry containers will be updated & fuel
bundle shipping containers relocated.
PIANKI, F. J. Combustion Engineering, Inc. 80/10/24. 2pp
07583:163

--8101300169 Forwards IE Insp Rept 70-1100/80-07 on 800826-29 & non-
violation.
SMITH, O. H. Region 1, Philadelphia, Fuel Facility & Materials
Safety Branch 80/10/08. 2pp. 07583:165

--B010300173 Notice of violation from insp on B00B26-29
e Region 1, Philadelphia, Office of the Director B0/10/07 1p
07583 167

--B010300177 IE Insp Rept 70-1103/B0-07 on B00B26-29 Noncompliance noted
ngt did not assure that use of hot-safe-by-geometry
containers had been analyzed to establish safety units &
controls
ROTH, J Region 1, Philadelphia, Office of the Director
CRICKER, H W Region 1, Philadelphia, Fuel Facility & Materials
Safety Branch B0/10/07 17pp 07583 168

B010190253 Approves vendor B01212 request for 19-day extension to
reconcile physical inventory of low enriched U.
BURNETT, R F Division of Safeguards B0/12/23 1p 07476 072

B010190268 Revises Amend MPP-4 to License SNM-1067, adding License
Condition 2.1.1 re inventory procedures for item
verification of low enriched U fuel rods. In response to
B01218 request
PARTLOW, J O Material Control Licensing Branch B0/12/24 1p
07476 048

DOCKET 70-1110 C-E POWER SYSTEMS

B010130127 Requests payment of minor safety & environ amend fee for
administrative amend to license SNM-1067
WEISS, D License Fee Management Branch B0/12/19 1p 07309 001

DOCKET 70-1111 ELIZABETH TOWN COLLEGE

B010130705 Discusses IE Insp Rept 70-1111/B0-01 of License SNM-1063
conducted on B01205 No noncompliance noted. Major areas
inspected: radiation safety & regulations compliance
KINNEHAN, J D Region 1, Philadelphia, Fuel Facility & Materials
Safety Branch B0/12/22 1p 07454 039

DOCKET 70-1113 GENERAL ELECTRIC CO

B012100002 Addl response to FOIA request for nine categories of records
re fees concerning withdrawn, suspended or postponed
applications Forwards documents listed in App A
FELTON, J M Division of Rules and Records B0/11/21 5pp

--B012100238 Requests partial refund of fee to GE re 790402 application
for amend to License SNM-1097 Lists actual manhours required
for review & amount of refund due.
MILLER, W D License Fee Management Branch 79/07/16 1p

--B012100245 Requests partial refund of fee to GE re 780803 application
for amend to License SNM-1097 Lists actual manhours required
for review & amount of refund due.
MILLER, W D License Fee Management Branch 79/08/13 1p

--B012100302 Notifies of partial refund due re NRC denial of 790402
application for amend to License SNM-1097 Manhour
expenditures have been reviewed & Ofc of Controller
notified.
MILLER, W D License Fee Management Branch 79/07/16 1p

--B012100316 Withdraws 780803 application for amend to License SNM-1097,
to use particular canister U/Fuel face masks Canisters will
continue to be shipped by current vendor in accordance w/
relevant purchase orders.
KAPLAN, A L General Electric Co 79/04/20 1p

B01290698 Forwards request for addl info re actions to be taken to
correct violations noted in IE Insp Rept 70-1113/B0-14.
D'REILLY, J P Region 2, Atlanta, Office of the Director B1/01/12
3pp 07574 299

DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP

B010200134 Ack receipt of IE Insp Rept 70-1151/B0-27 on B01104-07. No
proprietary info.
GOODWIN, W L Westinghouse Electric Corp. B0/12/04 1p 07406 132

--B010200137 Forwards IE Insp Rept 70-1151/B0-27 on B01104-07. No
noncompliance noted.
KENNA, W B Region 2, Atlanta, Safeguards Branch B0/11/19 1p
07486 133

--B010200144 IE Insp Rept 70-1151/B0-27 on B01104-07 No noncompliance
noted Major areas inspected nuclear criticality safety,
operations/procedure control, maint. safety committees & IE
Circulars B0-14 & B0-20
CORVELL, O P Region 2, Atlanta, Office of the Director
KAHLE, J B Region 2, Atlanta, Safeguards Branch B0/11/19
07406 134

B010505573 Forwards IE Insp Rept 70-1151/B0-26 on B01020-24 No
noncompliance noted.
KENNA, W B Region 2, Atlanta, Safeguards Branch B0/12/16 2p
07390 178

--B010505579 IE Insp Rept 70-1151/B0-26 on B01020-24 No noncompliance
noted Major areas inspected shipping & receiving Details
withheld (ref 10CFR2 790)
JOHNS, D W Region 2, Atlanta, Office of the Director KAHLE,
Region 2, Atlanta, Safeguards Branch B0/12/15 1p 07390 1

DOCKET 70-1257 MIXED OXIDE FABRICATION PLANT, EXXON NUCLEAR CO. I

B010600377 Forwards IE Insp Rept 70-1257/B0-09 on B01117-21 No
noncompliance noted Insp rept withheld (ref 10CFR2 790)
NORDERHAG, L R Region 5, San Francisco, Safeguards Branch
B0/12/17 1p 07391 250

B010600347 Forwards IE Insp Rept 70-1257/B0-10 on B01208-12 No
noncompliance noted Encl withheld (ref 10CFR2 790)
NORDERHAG, L R Region 5, San Francisco, Safeguards Branch
B1/01/06 1p 07470 349

B01210653 Ack receipt of B01208 ltr in response to NRC B01128 not
of violation Corrective actions will be reviewed during next
insp
NORDERHAG, L R Region 5, San Francisco, Safeguards Branch
B1/01/06 1p 07448 360

B01220192 Amend 1 to License SNM-1227, authorizing changes in filter
tests, Condition 9 & company organization
PAGE, R O Uranium Fuel Licensing Branch B1/01/06 1p 07495

--B010220197 Safety evaluation supporting licensee B01121 applicat
amend License SNM-1227 to authorize change in filter tests &
company organization
STEVENSON, R L, CRD, J W T Uranium Fuel Licensing Branch
B1/01/06 2pp 07495 347

B012705575 Notifies that administrative amend fee is due re vendor
B01222 request for extension to submit physical protection
plan
WEISS, D License Fee Management Branch B1/01/12 1p 07543:

DOCKET 70-1268 UTAH UNIV OF

B01070579 Forwards IE Info Notice B0-32, 'Clarification of Certain
Requirements for Exclusive Use Shipments of Radioactive
Mats.' No written response required
SMETEK, J H Division of Fuel Facility & Materials Safety
B0/08/29 1p 07415 325

DOCKET 70-1308 MORRIS OPERATIONS, GENERAL ELECTRIC CO

B010230049 Forwards DM Dawson B010105 ltr to RE Cunningham & Review
to "Radiological Emergency Plan for Morris Operation."
NEED-21894 Related correspondence
ROONEY, M A Mayer, Brown & Platt B1/01/07 2pp 07511 265

--B010230054 Forwards Revision 3 to "Radiological Emergency Plan for
Morris Operation," NEED-21894
DALBO, D M General Electric Co B1/01/05 2pp 07511 267

--B010230059 "Radiological Emergency Plan for Morris Operation," R
3
e General Electric Co NEED-21894-3 B0/12/31 64pp
07511 269

B010230032 Forwards amended application for license renewal submit
to NRC on B01112 Related correspondence
ROONEY, M A Mayer, Brown & Platt B1/01/13 1p 07183 001

--B010230038 Forwards amended application for renewal of License
SNM-1265
WOLF, E D General Electric Co B1/01/12 4pp 07183 001

--B101230943 A-rended application for renewal of License SNM-1265 authorizing receipt, possession, storage & transfer of irradiated fuel from LHRs
* General Electric Co 80/12/31 154pp 07183 C01

B101260175 Forwards illustrations existed from Attachment H on Tech Specs to amended application for renewal of License SNM-1265 Related correspondence
RODLEY, M A Mayer, Brown & Platt 81/01/14 3pp 07523 293

DOCKET 70-1327 UT & CONVERSION FACILITY, ALLIED GENERAL NUCLEAR

B101090779 Forwards memos re preliminary estimates of resource needs should "GESMO-type" proceeding be reinstituted info derived from discussion during 801201 meeting
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 80/12/05 1p

--B101090796 Submits estimated resource requirements for completing GESMO proceeding Differences in estimates for original GESMO project & estimates to complete proceeding noted
CUMMINGHAM, R E Division of Fuel Cycle & Material Safety 80/09/15 3pp

--B101060686 Advises that GESMO 1976 study & rept should be revised pending congressional mandate to reopen hearings
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 80/08/08 3pp

DOCKET 70-1374 IDAHO STATE UNIV

B101070568 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Materials" No written response required
SMIEZEK, J H Division of Fuel Facility & Materials Safety 80/08/29 1p 07415 343

DOCKET 70-1426 OLAHOMA, UNIV OF

B101070571 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Materials" No written response required
SMIEZEK, J H Division of Fuel Facility & Materials Safety 80/08/29 1p 07415 339

DOCKET 70-1462 HARPER-GRACE HOSP HARPER HOSP DIV, DETROIT, MI

B101090779 Forwards memos re preliminary estimates of resource needs should "GESMO-type" proceeding be reinstituted info derived from discussion during 801201 meeting
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 80/12/05 1p

--B101090796 Submits estimated resource requirements for completing GESMO proceeding Differences in estimates for original GESMO project & estimates to complete proceeding noted
CUMMINGHAM, R E Division of Fuel Cycle & Material Safety 80/09/15 3pp

--B101060686 Advises that GESMO 1976 study & rept should be revised pending congressional mandate to reopen hearings
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 80/08/08 3pp

DOCKET 70-1470 VET ADMIN HCSP, LOS ANGELES, CA

B101060687 Forwards IE Info Notice 80-35, "Leaking & Dislodged I-125 Implant Seeds" No written response required w/o encl
ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/10/10 1p 07400:182

DOCKET 70-1738 PACIFIC GAS & ELECTRIC CO

B101140780 Amend 9 to License SNM-1503, extending expiration date until 810630, in response to 801202 request
PAGE, R G Uranium Fuel Licensing Branch 80/12/31 1p 07451 314

DOCKET 70-1739 TRI-STATE MOTOR TRANSIT CO

B101100161 Responds to FOIA request for five categories of documents transportation of Pu Forwards documents listed in Apps A & B info partially withheld safeguards info in ref FOIA Exemption 3
FELT, J M Division of Rules and Records 80/12/12 6pp 07437 319

--B101100373 Requests temporary amend to SNM Security Transportation 11 to transport MO-1 containers in conventional 40-ft self-loader van trailer Amend required due to size of containers to be transported
RUTENAR, ROGER E Tri-State Motor Transit Co (subs of Georgia Pacific Corp) 80/01/30 3pp

DOCKET 70-1821 PLUT PROD FACIL., ALLIED GENERAL NUCLEAR SERVICES CORP

B101090779 Forwards memos re preliminary estimates of resource needs should "GESMO-type" proceeding be reinstituted info derived from discussion during 801201 meeting
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 80/12/05 1p

--B101090796 Submits estimated resource requirements for completing GESMO proceeding Differences in estimates for original GESMO project & estimates to complete proceeding noted
CUMMINGHAM, R E Division of Fuel Cycle & Material Safety 80/09/15 3pp

--B101060686 Advises that GESMO 1976 study & rept should be revised pending congressional mandate to reopen hearings
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 80/08/08 3pp

B101200094 Advises that add review of Allied-General Nuclear Svcs application fails to provide basis for discretionary refund of any part of application fee
DONOHUE, J O Office of Administration 80/12/22 3pp 07487 101

DOCKET 70-1936 TEXAS A&M UNIV

B101070575 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Materials" No written response required
SMIEZEK, J H Division of Fuel Facility & Materials Safety 80/08/29 1p 07415 335

DOCKET 70-2249 HUTZEL HOSP DETROIT, MI

B101070292 Ack receipt of 801016 & 1201 ltrs informing NRC of steps taken to correct violations noted in IE insp of License SNM-1639 & 21-03001-01
KEPPLER, J O Region 3, Chicago, Office of the Director 80/12/22 1p 07413 200

--B101070297 Informs of formation of committee to monitor regulatory compliance
JACOBELL, F Hutzel Hosp Detroit, MI 80/12/01 1p 07415 208

--B101070299 Responds to NRC 800925 ltr re violations noted in IE insp License 21-03001-01 on 800925, corrective actions: amend to license incorporating imported individuals & new possession limit requested
BOOTH, E, NOWICKI, K Hutzel Hosp, Detroit, MI 80/10/16 7pp 07415 201

DOCKET 70-2322 EDLOW INTERNATIONAL CO

B101100208 Requests extensions to 791219 route approvals & 800928 Fayetteville bypass Shipment will be four casks containing MTR type fuel elements imported from Sweden
RAVENSCROFT, N Edlow International Co 80/12/03 1p 07309:001

DOCKET 70-2375 PACIFIC GAS & ELECTRIC CO

B101140798 Amend 5 to License SNM-1667, extending expiration date until 810630, in response to 801202 request
PAGE, R G Uranium Fuel Licensing Branch 80/12/31 1p 07461 315

DOCKET 70-2434 TRANSNUCLEAR, INC

01290426 Amend 2 to license for Transnuclear, Inc. changing expiration date from 810131 to 820131
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards 81/01/23 1p 07570 344

DOCKET 70-2479 TRANSNUCLEAR, INC

01100161 Responds to FOIA request for five categories of documents re transportation of Pu Forwards documents listed in Apps A & B. Info partially withheld safeguards info (ref FOIA Exemption 3)
FELTON, J. H. Division of Rules and Records 80/12/12 6pp

0101100296 Application by Transnuclear, Inc to amend license to import irradiated fuel elements from West Germany, adding addl B. 470 kg U-6, 270 kg U-235 & 0143 kg Pu
MATSDON, V Transnuclear, Inc 78/07/06 3pp

0101100354 Application by Transnuclear, Inc for license to import 100 2 kg U-72, 1 kg U-235 & 106 kg Pu in form of irradiated fuel elements from West Germany
MATSDON, V Transnuclear, Inc. 77/01/12 3pp

01290417 Amend 5 to license for Transnuclear, Inc. increasing amount of matl imported to 445, 277 kg U-235, contained in 935-296 kg U & 966 kg produced Pu
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards 81/01/26 1p 07570:343

DOCKET 70-2511 TRANSNUCLEAR, INC.

01300761 Amend 2 to license for Transnuclear, Inc. extending expiration date from 810131 to 820131
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards 81/01/23 1pp 07582:345

DOCKET 70-2529 CARDINAL CUSHING GENERAL HOSP. BRECKTON, MA

01290623 Ack receipt of 801103 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-01935/80-01 & 70-2529/80-01
KINNEMAN, J. D. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/11/25 1p 07571 324

0101290626 Responds to NRC 800926 ltr re violations noted in IE Insp Repts 30-01935/80-01 & 70-2529/80-01. Corrective actions: different style syringe shields will be used.
JEPSEN, R. J. Cardinal Cushing General Hosp. Brockton, MA. 80/11/03 1p. 07571 325

DOCKET 70-2623 MCQUIRE SPENT FUEL POOL, DUKE POWER CO

01120554 Submits Amend 4 to License 8NM-1773, permitting movement & insertion of single fuel assembly into various reactor vessel locations for indexing purposes
PAGE, R. G. Uranium Fuel Licensing Branch 80/12/30 1p. 07447.191

01140170 Safety evaluation supporting movement & insertion of single fuel assembly into different locations of core for indexing purposes. License amend recommended.
METZLACH, N. Uranium Fuel Licensing Branch 80/12/30 2pp 07460:360

01160200 Request for extension until 810209 to file brief in response to NRC & intervenor 801222 briefs on exceptions. Certificate of Bvc encl.
WEISS, E. R., BISHOP, L. L., SCHERR, B. J. Natural Resources Defense Council 81/01/13 4pp 07470:053

01230404 Response opposing NRDC 810113 motion for extension until 810209 to file brief in opposition to exceptions, because of time constraints. Certificate of Bvc encl.
MCQUARRY, J. H. Duke Power Co. MCGARRY, J. H. Debevoise & Liberman 81/01/16 4pp. 07512.120

01220086 Answer to NRDC 810113 motion for extension of time. Clarifies that NRC will not object to motion provided that Council will not object to NRC reply to brief w/notice of appearance & Certificate of Bvc.
BRENNER, L. Hearing Branch 3. 81/01/19 5pp. 07502.115

8101230113 Order granting extension until 810209 for NRDC & other parties to file briefs supporting ASLB decision in spent fuel transportation proceeding. Util brief due 10 days after appellee brief w/Certificate of Bvc
BISHOP, C. J. Atomic Safety and Licensing Appeal Panel 81/01/19 5pp 07512 006

8101230462 Reply supporting NRDC 810113 motion for extension until 810209 to file brief opposing exceptions. Issues are detailed & all counsel are new to case. Certificate of Bvc encl.
WEISS, E. R., BISHOP, L. L. Natural Resources Defense Council 81/01/19 4pp 07512 153

8101270375 Forwards NRC 810114 answer to NRDC motion for extension of time & notice of appearance. W/o encl.
BRENNER, L. Hearing Branch 3 81/01/23 1p 07544 095

8101270049 Notice to ASLB of new info to amicus curiae brief of Electric Util Cos Nuclear Transportation Group re DOT final rules on highway routing of spent fuel shipments. FR excerpt encl.
TROSTEN, L. M. Electric Utility Companies Nuclear Transportation Group. TROSTEN, L. M. LeBoeuf, Lomb, Leiby & MacRae 81/01/23 24pp 07309 001

8101230442 Request to file reply to NRDC brief & any other brief filed opposing extensions to ASLB 810131 decision. Certificate of Bvc encl.
MCQUARRY, J. H. Duke Power Co. MCGARRY, J. H. Debevoise & Liberman 81/01/16 4pp. 07512.135

DOCKET 70-2838 CINCINNATI GAS & ELECTRIC CO

8101100201 Informs of issuance of Amend 5 to License 8NM-182, adding Condition 15 re maintaining & fully implementing all provisions of App F to facility. Amend becomes effective 801114
PAGE, R. G. Uranium Fuel Licensing Branch 80/11/05 1p 07444:168

DOCKET 70-2882 SOUTHERN CALIFORNIA Edison CO

8101070232 Requests addl info re util 801027 application for revision of proposed license for new fuel storage. Util should describe controls used to ensure conformance w/fuel storage pattern & that subcritical conditions will be maintained.
STEVENSON, R. L. Uranium Fuel Licensing Branch 80/12/17 1p 07414 275

DOCKET 70-2901 SOUTHERN CALIFORNIA Edison CO.

8101070232 Requests addl info re util 801027 application for revision of proposed license for new fuel storage. Util should describe controls used to ensure conformance w/fuel storage pattern & that subcritical conditions will be maintained.
STEVENSON, R. L. Uranium Fuel Licensing Branch 80/12/17 1p

DOCKET 70-2908 VEY ADMIN HOSP SAN DIEGO, CA

8101060681 Forwards IE Info Notice 80-35, "Leaking & Dislodged I-125 Implant Beads." No written response required w/o encl.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 80/12/10 1p 07400:181

DOCKET 70-2909 WESTINGHOUSE ELECTRIC CORP. POWER SYSTEMS

8101070371 Expresses opinions on preliminary hearings held by NRC. Westinghouse & Safe Energy Alliance of Central AL re facility license application.
WILLIAMS, L. Q. Affiliation Unknown 80/12/31 1p 07309 001

8101140931 Response opposing C Donelson petition to intervene & motion substituting C Donelson for DL Allied Certificate of Bvc encl.
CONAN, B. Z., KEURICK, J. R. Westinghouse Electric Corp. CONAN, B. Z. Eckert, Seagrams, Cherin & Hellogg 81/01/05 7pp. 07438 237

8101290136 Confirms telcon re 801202 ltr. Discusses Safe Energy Alliance of Central AL attempt to intervene, receipt of 801124 meetings, whether Alliance contentions will be closed matter after 801215 & limited statement request.
TURK, B. E. Office of the Executive Legal Director 81/01/27 3pp. 07567.290

8101150292 Informs that NRC will not file response to C Donelson 801206
suppl to petition or 801220 second suppl to petition until
30 days after ASLB ruling on 801110 joint motion for
substitution of named intervenor
TJRK, S E Office of the Executive Legal Director 81/01/13 1p
07462 202

DOCKET 70-2936 MISSISSIPPI POWER & LIGHT CO

8101060102 Forwards review of util 801001 application for authorization
to possess & use in-core detectors & for receipt, possession,
storage, insp & transportation of SM & byproduct -atl Addl
info from util needed by 810109.
KETZLACH, H Uranium Fuel Licensing Branch 80/12/03 5pp
07379 113

DOCKET 70 2937 PENNSYLVANIA POWER & LIGHT CO

8101060736 Forwards request for addl info needed to complete review of
application to receive & store fuel
KETZLACH, H Uranium Fuel Licensing Branch 80/12/02 4pp
03097 261

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND
TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN
CONDITIONS

DOCKET 71-0102 SOURCE PROD & EQUIP CO, INC

810120060 Forwards Revision 1 to QA program for radioactive matl
package
DICHAIRY, R F Source Production & Equipment Co, Inc 80/12/05 1p
07439 339

--8101120061 Revision 1 to QA program for radioactive matl package
* Source Production & Equipment Co, Inc 80/12/05 12pp
07439 340

DOCKET 71-0179 NUCLEAR CONTAINERS, INC

8101190748 Advises that unless response is received to NRC 791009
request for addl info, QA program application will be denied.
MACDONALD, C E Transportation Branch 81/01/06 1p 07476 121

DOCKET 71-0350 NAVY, DEPT OF, USE SIERRA

8101120054 Forwards QA program for radioactive matl package
SMITH, R H Navy, Dept of 80/12/03 1p 07445 294

--8101120057 QA program for radioactive matl package
KINSLEY, S B Navy, Dept of 80/09/14 5pp 07445 295

DOCKET 71-0398 TEXAS A&M UNIV

8101140154 Forwards revised QA program in response to NRC 801114 ltr
KANDALL, J D Texas A & M Univ 80/12/09 2pp 07461 197

--8101140163 QA program for shipping packages.
* Texas A & M Univ 80/12/31 6pp 07461 199

8101270934 Forwards QA program approval for radioactive matl package,
Revision 0
MACDONALD, C E Transportation Branch 81/01/09 1p 07549:203

--8101270937 QA program approval for radioactive matl package: 0398,
Revision 0
MACDONALD, C E Transportation Branch 81/01/09 1p 07549:204

DOCKET 71-0400 NAVY, DEPT OF

8101120042 Forwards NRC 800126 ltr w/ written statement confirming that
USS Bryce Canyon possesses NRC-approved QA program
Certificates of Compliance 9005 & 9007 issued to Automation
Industries under License 37-00611-09 retained by ship.
RIEDER, A E Navy, Dept of 80/12/08 2pp 07447 086

DOCKET 71-0401 RELIANCE TESTING LABORATORIES, INC

8101080370 Forwards QA program for NRC approval
FRIEDEL, F C Reliance Testing Laboratories, Inc 80/12/05 1p
07417 338

--8101080376 QA program for radiography Organizational chart encl.
FRIEDEL, F C, 3RD & W F Reliance Testing Laboratories, Inc
80/12/05 9pp 07417 339

DOCKET 71-0402 CSR LABORATORIES

8101160606 Lists approved procedures re activities under 10CFR71
utilized at lab Includes location where sealed sources will
be used &/or stored, approved sealed sources to be used in
radiography & approved exposure devices
WATSON, R L C & R Laboratories 80/12/06 4pp 07471:216

--8101160612 Informs that transportation activities may not be cond
in accordance w/10CFR71. Lab must register w/NRC prior to
first shipment by certificate number for each package design
intended for use & have acceptable QA plan
MACDONALD, C E Transportation Branch 80/11/26 1p 07471:2

DOCKET 71-0403 SCHLUMBERGER WELL SERVICE

8101270337 Forwards QA program for Type B radioactive matl sealed
source transport packages
RACSTER, C E Schlumberger Well Services 80/12/19 1p 07546

--8101270342 QA program for Type G radioactive matl sealed source
transport packages
SHOUD, R R Schlumberger Well Services 80/12/19 19pp
07546 150

DOCKET 71-0404 ALASKA WELDING CENTER

8101270124 Forwards QA program for industrial radiography licenses
WATSON, S M Alaska Welding Center 80/12/18 1p 07547 047

--8101270126 QA program for industrial radiography licenses
* Alaska Welding Center 80/12/15 17pp 07547 048

DOCKET 71-0405 ENERGY, INC

8101230275 Forwards QA program for industrial radiography licenses
SHAMEL, W H Energy Incorporated 80/12/18 1p 07512 069

--8101230286 QA program for industrial radiography licenses
* Energy Incorporated 80/12/10 5pp 07512 070

DOCKET 71-4986 MODEL RA-2, EXXON NUCLEAR CO, INC

8012100002 Addl response to FOIA request for nine categories of rec
re fees concerning withdrawn, suspended or postponed
applications. Forwards documents listed in App A
FELTON, J M Division of Rules and Records 80/11/21 5pp

--8012100396 Notifies of review completion re 800402 application fo
revision to Certificate of Compliance 4986
* Transportation Branch 80/07/22 1p

8012290565 Forwards application for renewal of Certificate of
Compliance 4986 for Model RA-2 Info still relevant to Model
RA-2 from all previous amend applications consolidated into
present application
HAPLAN, A L General Electric Co 80/12/10 2pp 07340 189

--8012290571 Application for Amend T-15 to Certificate of Compliance
consolidating all info from previous applications for Model
RA-2
* General Electric Co 80/12/05 98pp 07340 192

8101090907 Forwards Revision 9 to Certificate of Compliance 4986 fo
Models RA-1, RA-2, RA-3 & RA-J
MACDONALD, C E Transportation Branch 80/12/19 2pp 03893:28

--B101070917 Certificate of Compliance 4986, Revision 9, for Models RA-1,
RA-2, RA-3 & RA-J
MACDONALD, C E Transportation Branch 80/12/19 6pp 03693 283

DOCKET 71-5059 MODEL URAINY NIT-INK, NUCLEAR FUEL SERVICES, INC

B101190356 Requests that expiration date of Certificate of Compliance
5059 be extended until B10331 Consolidated application for
certificate renewal will be provided by B10131 in response
to NRC B01008 request Renewal Fee encl
MICHEL, C J Nuclear Fuel Services, Inc (subs of Getty Oil Co)
80/12/08 1p 07476 079

DOCKET 71-5086 MODEL UNC-2600, GENERAL ATOMIC CO

B101290556 Forwards Revision 5 of Drawing D-20354-B, Sheet 7, modifying
outer drum lid from 14 gauge min to 16 gauge min Density mod
change will not affect performance requirements
KIRK, W F United Nuclear Corp, Naval Products Div 80/12/16 2pp
07575-273

DOCKET 71-5364 MODEL NPI-67-0442 NEUTRON PRODUCTS, INC

B101050426 Notifies of registration as user of Model NPI-67-0442.
MACDONALD, C E Transportation Branch 80/12/10 1p 07389 325

DOCKET 71-5760 MODEL BB-250-2, COMBUSTION ENGINEERING CO., INC

B101200003 Advises that drawing revisions to B00726 application for
Certificate of Compliance 5768 for Model BB-250-2 shipping
package will be submitted before B10131 Addl revisions will
be submitted pending resolution of Item 2
AUSTIN, M A Babcock & Wilcox Co., Nuclear Material Div 80/12/11
1p 07487 022

DOCKET 71-5796 MODEL 181361, PICKER CORPORATION

B101140130 Requests to continue registration as user of Certificate of
Compliance 5796
GILIN, S Laurence Livermore Laboratory 80/12/12 1p 07461 193

DOCKET 71-5805 MODEL ATCOR VNUB CASK, ATCOR, INC

B101290577 Forwards application for renewal of Certificate of
Compliance 5805 Encl reflects compilation & consolidation of
previously approved SAR & all amends in reg guide approved
format.
CORBETT, J S Chem-Nuclear Systems, Inc 80/11/26 1p 07340 047

--B101290581 "SAR for Model CNS-3-55 Shipping Cask."
Chem-Nuclear Systems, Inc 80/11/26 149pp 07340 048

DOCKET 71-5908 MODEL DOT-6M TYPE B, BABCOCK & WILCOX CO

B101100100 Notifies of registration as user of Model DOT-6M Type B
MACDONALD, C E Transportation Branch 80/12/10 1p 07445 000

B101270061 Notifies of expiration of Certificate of Compliance 5908
for Model DOT-6M Type B. To continue using package, should
request renewal of existing certificate of compliance.
MACDONALD, C.E. Transportation Branch 81/01/07 1p 07547 031

DOCKET 71-5926 MODEL 100, GENERAL ELECTRIC CO

B101290949 Forwards simplified drawings of GE Model 100 shipping
container as requested Requests replacement of previously
submitted detailed engineering drawings & extension of
Certificate of Compliance 5926, pending renewal review
CUNNINGHAM, O E General Electric Co. 80/11/14 1p 07340 003

DOCKET 71-5938 MODEL HMPF, GENERAL ATOMIC CO

B101160763 Notifies of expiration of Certificate of Compliance 5938 for
Model HMPF. To continue using package, should submit
consolidated application for renewal.
MACDONALD, C.E. Transportation Branch 81/01/07 1p 07472 063

DOCKET 71-5935 MODEL GE-1500, GENERAL ELECTRIC CO

B101290569 Forwards simplified drawings for GE Model 1500 ship
container Requests replacement of previously submitted
detailed engineering drawings
CUNNINGHAM, O E General Electric Co 80/11/14 1p 07340

B101300755 Advises of forthcoming amend Fee refund re Revision
Certificate of Compliance 5939
MILLER, W D License Fee Management Branch 81/01/19 1p
07589 260

DOCKET 71-5957 MODEL HMI-1, ENERGY DEPT OF

B101290618 Submits addl info describing container for B00714 am
request to Certificate of Compliance 5957 Contents will not
decompose at temps below 800 F Forwards revised drawing of
container
VOITH, M H Union Carbide Corp. 80/11/17 4pp 07340 039

DOCKET 71-5971 MODEL GE-200, GENERAL ELECTRIC CO

B101290532 Forwards simplified drawings of GE Model 200 shippr
container for review Requests replacement of previously
submitted detailed engineering drawings
CUNNINGHAM, O E General Electric Co 80/11/14 1p 07340

DOCKET 71-5980 MODEL GE-600, GENERAL ELECTRIC CO

B101290515 Forwards simplified drawings for GE Model 600 shippr
container Requests replacement of previously submitted
detailed engineering drawings
CUNNINGHAM, O E General Electric Co. 80/11/14 1p 07340

DOCKET 71-6144 MODEL 32, NUCLEAR ENGINEERING CO

B101190398 Requests registration as user of Certificate of Comp
6144 for Model 15-160B
BRACKEN, K W Energy, Dept of 80/12/04 1p 07475 174

B101100069 Notifies of registration as user of Model B-2
MACDONALD, C E Transportation Branch 80/12/10 1p 07444

DOCKET 71-6273 MODEL 48X, F. A. Y. ALLIED-GENERAL NUCLEAR SERV

B101190645 Requests renewal of Certificate of Compliance 6273 &
requests issuance of certificate of compliance for shipment
of natural U under License SUB-526
CIPOLLA, A J. Allied Chemical Corp 80/10/22 1p 07474 0

--B101190652 Certificate of Compliance 6273, Revision 3 for Model
48X, 48F & 48Y
MACDONALD, C E Transportation Branch 77/01/24 3pp 0

--B101190657 Ack receipt of B101027 ltr for renewal of Certificate
Compliance 6273 Renewal fee should be submitted
WEISS, D License Fee Management Branch 80/11/12 1p
07474 045

B101190744 Informs that application addressing 10CFR71.21 requ
must be filed in order to renew Certificate of Compliance
5442
MACDONALD, C.E. Transportation Branch 81/01/02 1p 0747

DOCKET 71-6375 MODEL PB-1, CHEM-NUCLEAR SYSTEMS, INC

B101130257 Requests payment of fee for 180-day extension of Ce
of Compliance 6375
WEISS, D License Fee Management Branch 80/12/19 1p 07

B101050171 Forwards Revision 10 to Certificate of Compliance 6
Model CNS 4-45
MACDONALD, C.E. Transportation Branch 80/12/23 3pp 073

--B101050173 Certificate of Compliance 6375, Revision 10, for Mo
CNS 4-19
MACDONALD, C E Transportation Branch 80/12/23 2pp 0

DOCKET 71-6460 MODEL SUPER TIGER, WESTINGHOUSE ELECTRIC CORP

8012290495 Requests exemption from 10CFR71.42(b)(3) for Model 6400 shipping package. Certificate of Compliance 6400, in accordance w/encl info
DIP/AZZA R P. Westinghouse Electric Corp 80/11/20 1p 07340 017

--8012290498 "Treatment, Packaging & Safety Assessment for Transporting Large Equipment Waste"
* Westinghouse Electric Corp 80/11/20 14pp 07340 018

--8012290532 "Description of OCE/Richland Operations-Super Tiger (Model 6400)"
* Westinghouse Electric Corp 80/11/20 3pp 07340 032

801060021 Notifies of authorization to use Model Super Tiger to deliver large equipment waste to carrier for transport, in response to 801120 & 1215 requests. Waste may not exceed 5 g Pu
MACDONALD, C E Transportation Branch 80/12/18 2pp 07392 399.

DOCKET 71-6458 MODEL BU-5, GENERAL ELECTRIC CO

801270058 Notifies of expiration of Certificate of Compliance 6458 for Model BU-5. To continue using package, should request renewal of existing certificate of compliance
MACDONALD, C E Transportation Branch 81/01/07 1p 07547 035

DOCKET 71-6573 MODEL HIT-906, NUCLEAR BATTERY CORP

801270026 Notifies of expiration of Certificate of Compliance 6573 for Model HIT-906. To continue using package, should request renewal of existing certificate of compliance
MACDONALD, C E Transportation Branch 81/01/07 1p 07546 018.

DOCKET 71-6573 MODEL HN-200, HITTMAN NUCLEAR & DEVELOPMENT CORP

801050431 Notifies of registration as user of Models HN-100 Series 1, HN-100 Series 2, HN-100S, HN-200, NLI-1/2 & 9080
MACDONALD, C E Transportation Branch 80/12/10 1p 07389 346

DOCKET 71-6601 MODEL LL-50-100, CHEM-NUCLEAR SYSTEMS, INC

801050464 Notifies of registration as user of Models CNS B-120, GE-1600 & CNS 14-175-H
MACDONALD, C E Transportation Branch 80/12/10 1p 07390 030.

801050039 Requests to register as user of Model CNS; LL-50-100 radioactive metal shipping cask
MOVEY, G. K Metropolitan Edison Co 80/12/18 2pp 07385 273

DOCKET 71-6642 MODEL 4 5 TON CF, ENERGY SEPT OF

801270084 Notifies of expiration of Certificate of Compliance 6642 for Model 4 5 ton Cf. To continue using package, should request renewal of existing certificate of compliance
MACDONALD, C E Transportation Branch 81/01/07 1p 07547 039

DOCKET 71-6698 MODEL NFS-4, NUCLEAR FUEL SERVICES, INC.

8011400168 Requests that Certificate of Compliance 6698, Revision 12, be revised to recognize that inside diameters of end castings & inner cavity pipe were .nfg to be slightly different
JOHNSON, C R Nuclear Assurance Corp 80/12/01 2pp 07443 006.

801050450 Notifies of registration as user of Model NFS-4
MACDONALD, C E Transportation Branch 80/12/10 1p 07387 023.

DOCKET 71-6717 MODEL 6717 B

801100108 Notifies of registration as user of Models 6717-B & C-1
MACDONALD, C E Transportation Branch 80/12/10 1p 07445 011.

DOCKET 71-6744 MODEL POLY TIGER, NUCLEAR ENGINEERING CO

8012290613 Informs of review of applications for renewal of Certificate of Compliance 6744. Previously submitted Drawing Revision J found not applicable. Two cash drawings encl.
CSMEYER, W E Teledyne Energy Systems 80/11/11 4pp 0

DOCKET 71-9001 MODEL IF-300, GENERAL ELECTRIC CO

801140008 Application for revision of Certificate of Compliance Revision 10. Revision 1111 clarify requirements for measurement of radiation & permit use of 73J Target Rock valve Fee encl
DANSON, D M General Electric Co 80/11/26 3pp 07461

DOCKET 71-9007 MODEL 520, AUTOMATION INDUSTRIES, INC

801050162 Forwards Revision 4 to Certificate of Compliance Model 520
MACDONALD, C E Transportation Branch 80/12/23 2pp 0

--801050165 Certificate of Compliance 9007, Revision 4, for Model 520
MACDONALD, C E Transportation Branch 80/12/23 2pp

DOCKET 71-9010 MODEL NLI-1/2, NL INDUSTRIES, INC

801050431 Notifies of registration as user of Models HN-100 HN-100 Series 2, HN-100S, HN-200, NLI-1/2 & 9080
MACDONALD, C E Transportation Branch 80/12/10 1p.

801050456 Notifies of registration as user of Model NLI-1/2
MACDONALD, C E Transportation Branch 80/12/10 1p. 07

801107122 Notifies of registration as user of Model NLI-1/2
MACDONALD, C E Transportation Branch 80/12/10 1p 07

DOCKET 71-9019 MODEL BU-7, GENERAL ELECTRIC CO

801300749 Advises that no addl fee is required re Revision Certificate of Compliance 9019
MILLER, W D License Fee Management Branch 81/01/19 1p 07585 359

DOCKET 71-9023 MODEL NLI-10/24, NL INDUSTRIES, INC

801270076 Notifies of expiration of Certificate of Compliance for Model NLI-1/2. To continue using package, should request renewal of existing certificate of compliance
MACDONALD, C E Transportation Branch 81/01/07 1p. 07

DOCKET 71-9032 MODEL 650, TECHNICAL OPERATIONS, INC.

801140152 Requests registration as user of Tech/Ops Models under Certificates of Compliance 9032 & 9033, respectively
FRIEDEL, F C Reliance Testing Laboratories, Inc. 80/12/05 07460 353

DOCKET 71-9033 MODEL 660 & 660E, TECHNICAL OPERATIONS, INC.

801140152 Requests registration as user of Tech/Ops Models under Certificates of Compliance 9032 & 9033, respectively.
FRIEDEL, F C Reliance Testing Laboratories, Inc. 80/12/05 07460 353.

DOCKET 71-9035 MODEL 680, TECHNICAL OPERATIONS, INC.

801140360 Requests that Knolls Atomic Power Lab be registered as user of Certificate of Compliance 9035
SMITH, M E Energy, Dept. of 80/12/06 1p 07476 076

DOCKET 71-9036 MODEL C-1, SOURCE PRODUCTION EQUIPMENT CO.

801100108 Notifies of registration as user of Models 6717-B MACDONALD, C E Transportation Branch 80/12/10 1p. 0

BUCKET 71-9044 MODEL GE-1600. GENERAL ELECTRIC CO

12290590 Forward simplified drawings of GE Model 1600 shipping container. Requests replacement of previously submitted detailed engineering drawings & extension of Certificate of Compliance 9044 pending renewal review process.
CUNNINGHAM, G E General Electric Co 80/11/14 1p. 07340 011

01190353 Requests that Lynchburg Research Ctr be registered as user of Model CNSI 1-130
OLSEN, A R Babcock & Wilcox Co. 80/12/01 1p. 07475 002

01050464 Notifies of registration as user of Models CNS 8-120, GE-1600 & CNS 14-195-H
MACDONALD, C E Transportation Branch 80/12/10 1p. 07390 030

01100104 Notifies of registration as user of Model GE-1600
MACDONALD, C E Transportation Branch 80/12/10 1p. 07449 010

01090927 Forwards Revision 7 to Certificate of Compliance 9044 for Model GE-1600
MACDONALD, C E Transportation Branch 80/12/23 3pp. 07430 273

0101090830 Certificate of Compliance 9044, Revision 7, for Model GE-1600
MACDONALD, C E Transportation Branch 80/12/23 4pp. 07430 276

BUCKET 71-9065 MODEL BU-4. GENERAL ELECTRIC CO

01270072 Notifies of expiration of Certificate of Compliance 9065 for Model BU-4. To continue using package, should submit consolidated application for renewal.
MACDONALD, C E Transportation Branch 81/01/07 1p. 07547 036

BUCKET 71-9070 MODEL N-55. ENERGY DEPT OF

01200007 Requests that Item 5(b)(2)(iii) of Revision 3 to Certificate of Compliance 9070 be changed to permit transport of up to 200 g fissile Pu plus U/235 total quantity of Pu not to exceed 200 g. Amend fee encl.
HANSEN, L E Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 80/12/04 1p. 07407 019

01100113 Notifies of registration as user of Model N-55
MACDONALD, C E Transportation Branch 80/12/10 1p. 07445 012

BUCKET 71-9072 MODEL GAHC-1. GENERAL ATOMIC CO

01270054 Notifies of expiration of Certificate of Compliance 9072 for Model GAHC-1. To continue using package, should submit consolidated application for renewal.
MACDONALD, C E Transportation Branch 81/01/07 1p. 07547 029

BUCKET 71-9074 MODEL AP-100. ANEPCO, INC.

01090446 Notifies of registration as user of Model AP-100
MACDONALD, C E Transportation Branch 80/12/10 1p. 07389 348

BUCKET 71-9079 MODEL HN-100 SERIES 2. HITTMAN NUCLEAR & DEVELOPMENT

01030431 Notifies of registration as user of Models HN-100 Series 1, HN-100 Series 2, HN-100B, HN-200, NL1-1/2 & 9080
MACDONALD, C E Transportation Branch 80/12/10 1p. 07389 346

BUCKET 71-9080 MODEL HN-600. HITTMAN NUCLEAR & DEVELOPMENT CORP

01030431 Notifies of registration as user of Models HN-100 Series 1, HN-100 Series 2, HN-100B, HN-200, NL1-1/2 & 9080
MACDONALD, C E Transportation Branch 80/12/10 1p. 07389 346

BUCKET 71-9086 MODEL HN-100 SERIES 1. HITTMAN NUCLEAR & DEVELOPMENT

01030431 Notifies of registration as user of Models HN-100 Series 1, HN-100 Series 2, HN-100B, HN-200, NL1-1/2 & 9080.
MACDONALD, C E Transportation Branch 80/12/10 1p.

0101210132 Advises of intent to ship radioactive matl using Model HN-100
HAYNES, J O Northern States Power Co 80/12/10 1p. 07491 301

BUCKET 71-9089 MODEL HN-100B

0101050431 Notifies of registration as user of Models HN-100 Series 1, HN-100 Series 2, HN-100B, HN-200, NL1-1/2 & 9080
MACDONALD, C E Transportation Branch 80/12/10 1p.

BUCKET 71-9094 MODEL CNSI-14-195-H. CHEM-NUCLEAR SYSTEMS, INC

0101050464 Notifies of registration as user of Models CNS 8-120, GE-1600 & CNS 14-195-H
MACDONALD, C E Transportation Branch 80/12/10 1p. 07390 030

BUCKET 71-9111 MODEL CN6-80A. CHEM-NUCLEAR, INC

0101070216 Requests registration as user of Model CN 6-80A
HAYNES, J O Southern California Edison Co 80/11/24 1p. 07414 243

0101050467 Notifies of registration as user of Model CN6-80A
MACDONALD, C E Transportation Branch 80/12/10 1p. 07390 031

0101270143 Application for revision of Certificate of Compliance 9111 to permit use of improved const. matls & strengthened outer shell
HANSEN, L J Nuclear Packaging, Inc 80/12/17 2pp. 07546 033

--0101270146 "BAR for Model CNS-80 Shielded Cask to 10CFR71 Type A Packaging Requirements." Revision 3
* Nuclear Packaging, Inc 80/12/17 3pp. 07546 005

BUCKET 71-9124 MODEL L2-101 & L3-101. NUCLEAR ENGINEERING CO, INC

0101210002 Addl response to FOIA request for nine categories of records re fees concerning withdrawn, suspended or postponed applications. Forwards documents listed in App A
FELTON, J M Division of Rules and Records 80/11/21 5pp.

--01012100212 Requests payment of addl fee for review of 780602 application for approval of Models L2-101 & L3-101, withdrawn on 770115. Addl charge concerns manhours involved in review of application
MILLER, H O License Fee Management Branch 77/03/07 1p.

--01012100290 Reiterates 740307 request for addl fee re withdrawal of 780602 application for approval of Models L2-101 & L3-101. Fee should be provided within 30 days.
WFISS, D License Fee Management Branch 77/04/24 1p.

BUCKET 71-9129 MODEL UNI LA-90. NORTHEAST UTILITIES

01012100002 Addl response to FOIA request for nine categories of records re fees concerning withdrawn, suspended or postponed applications. Forwards documents listed in App A
FELTON, J M Division of Rules and Records 80/11/21 5pp.

--01012100357 Notifies that addl fee is required for review costs re 780828 application for RRC approval of Model UNI LA-90. Request for approval was denied due to failure to provide addl info to support application.
MILLER, H O License Fee Management Branch 80/02/25 1p.

--01012100360 Requests that invoice for actual cost of processing 780828 application for shipping package approval be sent to utility
MILLER, H O License Fee Management Branch 80/02/25 1p.

--01012100366 Notifies of review completion of 780828 application for shipping package approval. Project was completed in 36-h.
" Transportation Branch 79/09/17 1p.

BUCKET 71-9130 MODEL NP-50-XXL. NUCLEAR PACKAGING, INC

0101050459 Notifies that Certificate of Compliance 9130 expired on 801031. Use of Model NP-50-XXL cannot be authorized.
MACDONALD, C E Transportation Branch 80/12/10 1p. 07390 016

DOCKET 71-9132 MODEL T-3. NUCLEAR PACKAGING, INC

B101200002 Responds to 800825 application to amend Model T-3 shipping
case approval licensee should demonstrate that each of seven
possible contents will remain substantial within 9-inch
diameter capacity or that seven contents remain intact.
MACDONALD, C E Transportation Branch 80/12/19 1p 07487 023

DOCKET 71-9133 MODEL C-10, GAMMA INDUSTRIES

B101199725 Requests addl info in order to complete review of Model
C-10
MACDONALD, C E Transportation Branch 80/12/31 2pp 07476 109

DOCKET 71-9141 MODEL 900 TYPE B, TECHNICAL OPERATIONS, INC

B101100035 Notifies of registration as user of Model 900
MACDONALD, C E Transportation Branch 80/12/10 1p 07445 006

DOCKET 71-9145 MODEL NUPAC 50, NUCLEAR PACKAGING, INC

B101200316 Forwards info re Model NUPAC 50 in response to
ltr Applicable pages of SAR have been revised to incorporate
data lists summary of response
HANSEN, L J Nuclear Packaging, Inc 80/12/12 12pp

B101270133 Forwards corrected Page 1-13 of B01112 ltr re v
horizontal loads
HANSEN, L J Nuclear Packaging, Inc 80/12/10 1p 07

--B101270137 Corrected Page 1-13 re vertical & horizontal
HANSEN, L J Nuclear Packaging, Inc 80/12/10 1p

NONDOCKETED ITEMS

DCFR COMMISSION MEETING RECORDS

012290476 Transcript of 801211 meeting in Washington, DC re SECY-80-474C. Pp 1-32
 * Commissioners 80/12/11 34pp 07335 066

012290483 SECY-80-474C
 Suppls SECY-80-474 & forwards clarifying changes to 10CFR60 final rule & conforming amends
 DIRCKB, W J Office of the Executive Director for Operations 80/12/09 16pp 07335 104

012290489 Transcript of 801211 Affirmation Session 80-54 in Washington, DC re SECY-80-448, SECY-A-80-168 & SECY-80-482 Pp 1-11
 * Commissioners 80/12/11 13pp 07335 142

012110612 Draft Commission paper re denial of Public Citizen Litigation Group petition for rulemaking re increase in required levels of financial protection for reactor operators. Abstracts of comments & draft FR notice encl
 GENDON, H R Office of Nuclear Reactor Regulation, Director 80/10/23 48pp 03771 145

010230624 SECY-80-448
 Requests Commission approval of encl revised narrative explanation of Table 5-3 specified in Commission order on final fuel cycle rule & draft FR notice
 DAVIS, J O Office of Nuclear Material Safety & Safeguards 80/09/29 100pp 06747 001

01040041 Commission determination releasing portions of transcript of NRC briefing by Dept of State/Arms Control & Disarmament Agency on 780713 in Washington, DC
 CHILK, S J Office of the Secretary of the Commission. 80/11/24 2pp. 07392 217

01060044 Portions of transcript of NRC briefing by Dept of State/Arms Control & Disarmament Agency on 780713 in Washington, DC. Pp 1-66
 * Commissioners 80/11/24 66pp 07392: 219.

01060590 Transcript of 801210 briefing in Washington, DC re SECY-80-551 re storage of low level radwaste at power reactor sites. Pp 1-43
 * Commissioners. 80/12/10 44pp. 07391: 139.

01060596 SECY-80-551
 Requests approval of plan for review of applications proposing addl low level radwaste storage capacity & preparation of programmatic EIS on long-term retrievable radwaste storage. IE survey summary & proposed util ltr encl
 DIRCKB, W J. Office of the Executive Director for Operations 80/11/18. 21pp 07391. 184.

01060699 Transcript of 801211 meeting to discuss SECY 80-491 re proposed rulemaking on reactor operator qualification & operator qualification & licensing requirements
 * Commissioners 80/12/11. 49pp 07400: 189

010280094 SECY-80-491
 Recommends Commission approval of proposed rulemaking "Qualification of Reactor Operators " Draft FR notice, background & discussion, recommendations of SECY-79-330E & draft Congressional ltr & public announcement encl
 MINOQUE, R B. Office of Standards Development, Director 80/11/04 80pp 03768 094.

01140111 Staff requirements memo re Affirmation Session 80-54 on 801211 concerning SECY-80-448 Proposed explanatory narrative & proposed rule should be revised as specified. Marked-up pages encl
 CHILK, S J Office of the Secretary of the Commission MB0121C 80/12/15. 13pp. 07460 327.

--8101140120 Recommends endorsement of interim reliability evaluation program w/o condition of revising Crystal River rept prior to continuing w/program w/o encl recd for signature to accompany endorsement
 FURLEY, T E Division of Reactor Safety Research 80/12/04 2pp 07460 340

--8101140127 Advises of need for interim reliability evaluation program. Revision of Crystal River work before undertaking Phase II studies recommended
 FANAUER, S H Division of Human Factors Safety 80/11/25 1p 07460 342

8101190792 Transcript of Commission 801222 meeting in Washington, DC re SECY 80-474 Pp 1-79 W/related info
 * Commissioners 80/12/22 100pp: 07472 324

8101200552 Transcript of R & D Association 800425 briefing on containment concept to withstand core melt in Bethesda, MD Pp 1-79 Exempt session
 * Commissioners 80/04/25 81pp 07476 200

8101210246 Staff requirements memo re 801217 briefing on TVA activities in emergency offsite facilities. Requests comments on acceptability of util proposal to centralize facilities & applicability of concept to other licensees
 CHILK, S J Office of the Secretary of the Commission MB01217J 80/12/18 1p 07492 047

8101220235 Transcript of 800415 public Affirmation Session 80-22 in Bethesda, MD re statement of interim policy relative to accident considerations under NEPA Pp 1-5
 * Commissioners 80/04/15 5pp 07503 294

8101220239 Unofficial transcript of 791017 open Affirmation Session 79-32 in Washington, DC re order on Westinghouse export to the Philippines Pp 1-2
 * Commissioners 79/10/17 4pp 07503 289.

8101220267 Unofficial transcript of 780906 public session in Washington, DC re SECY-78-308, provision for protection of individuals who provide info to NRC Pp 1-37
 * Commissioners 78/09/06. 39pp: 07504 044

8101220273 Unofficial transcript of 780906 public session in Washington, DC re presentation of Commissioner Kennedy & presentation of certificates of appointment to HR Denton & WJ Dircks. Pp 1-4
 * Commissioners 78/09/06. 5pp 07504 083

8101220270 Unofficial transcript of 780906 public session in Washington, DC re SECY-78-350, role of use of deadly force in safeguarding strategic SNM. Pp 1-47
 * Commissioners 78/09/06. 50pp 07504 087

8101220504 Unofficial transcript of 790425 public meeting in Washington, DC re interim briefing by study group on const during review. Pp 1-34
 * Commissioners 79/04/25. 35pp 07501 197

8101220647 Transcript of Commission 810115 meeting in Washington, DC re action plan items due Jan 1981 Pp 1-47
 * Commissioners 81/01/15 49pp 07502 143

8101230658 Transcript of Commission 810115 meeting in Washington, DC re status of SRP. Pp 1-30
 * Commissioners 81/01/15 41pp 07512 296

8101260328 Unofficial transcript of 790920 Affirmation Session 79-27 in Washington, DC re ACRS appointments Pp 1-3
 * Commissioners 79/09/20 4pp 07536 057

NONDOCKETED ITEMS

B101276275 Transcript from Affirmation Session B0-36 on B01222 in Washington, DC. Pp 1-7 Includes consideration of SECY-B0-325 re open gov. FOIA appeal. SECY-A-146A re Tyrone decision. SECY-B0-307 & SECY-B0-501
* Commissioners B0/12/22 5pp 07546 117

B101280369 Responds to FOIA request for documents re Task Force on Interim Operation of Indian Point submitted to NRC after B00531 Forwards App A documents App B documents withheld (ref FOIA Exemption 5)
FELTON, J. H. Division of Rules and Records B1/01/21 3pp

--B101280588 Staff requirements memo re B00626 briefing on recommendations of facilitator, task force Commission took no action during meeting Task force report & other info re facility operation will be reviewed further
CHILKINS, J. Office of the Secretary of the Commission B0/06/30 1p.

B101290392 Unofficial transcript of B00107 Commission meeting in Washington, DC re SECY-B0-474. Final rule. 10CFR60, "Disposal of High Level Radwaste in Geologic Repositories Licensing Procedures." Pp 1-85
* Commissioners B1/01/07 88pp 07570-001

--B101290399 Submits draft language changes to original text of SECY-B0-474 for 10CFR60 Final rulemaking. Off. of General Counsel concerns re NRC deference to DOE on common defense & security matters addressed.
BICKHIT, L. Office of the General Counsel B1/01/06 2pp 07573 090

--B101290409 Discusses procedural aspects of final rule deserving further Commission consideration prior to approval of publication as part of 10CFR60, "Disposal of High Level Radwaste in Geologic Repositories." Licensing policy statement encl.
HARRAHAN, E. J. Office of Policy Evaluations B1/01/06 5pp 07570 091

--B101290410 Confirms discussion w/ W Dirks re dept concerns w/ proposed regulations governing disposal of high level radwaste. Commission accommodation of dept views on problems outlined in B00303 ltr requested prior to issuing final rule.
* Energy, Dept of B1/01/06 2pp 07570 096

--B101290419 Staff requirements memo re discussion of SECY-B0-474 final rule, 10CFR60, "Disposal of High Level Radwaste in Geologic Repositories Licensing Procedures." Commissioner views on proposed memo to SECY-B0-474 encl.
CHILKINS, J. Office of the Secretary of the Commission B0-474 B1/01/05 4pp 07570 098

--B101290420 Suggests memo to SECY-B0-474 final rule, 10CFR60, "Disposal of High Level Radwaste in Geologic Repositories Licensing Procedures."
BRADFORD, F. A. Commissioners B0/12/18 4pp 07570 102

B101290479 Staff requirements memo re B10113 discussion of near-term CP requirements. Commission deferred decision re hydrogen control question pending further discussion & requested further discussion re need for CP process revision.
CHILKINS, J. Office of the Secretary of the Commission B010113 B1/01/16 1p 07368 355

B101290509 Staff requirements memo re B10115 briefing on SRP revisions due in Apr 1981. No requests or requirements forwarded.
CHILKINS, J. Office of the Secretary of the Commission. B010115B. B1/01/16 1p 07368 353

B101290636 Transcript of Commissioners/ACRS B00808 joint meeting in Washington, DC re nuclear data ltr. Pp 411-446
* ACRS - Advisory Committee on Reactor Safeguards
* Commissioners B0/08/08 37pp 07573 120

B101305409 Unofficial transcript of Commission B10115 meeting in Washington, DC re Affirmation Session B1-2 to discuss waste confidence rulemaking Pp 1-6
* Commissioners B1/01/15 8pp 07583 219

--B101300416 Forwards proposed memorandum & order authorizing use of consultants to assist Commission working group w/ waste confidence rulemaking proceeding. Memorandum & order should be adopted & issued.
MILLER, H. E. Atomic Safety and Licensing Board Panel. B0/12/19 6pp 07583 228

ACRS ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

B1012020784 Responds to 790727 requests that ACRS address consistency actual component failure experience w/ that projected in WASH-1400 & that ACRS determine probabilities of occurrence re Davis-Besse 770724 & Rancho Seco 780320 events
PLESSER, M. S. ACRS - Advisory Committee on Reactor Safeguards B0/02/20 8pp

--B1012020797 Forwards "Analysis of Feedwater Transient Sequences in NSSS," to aid in formulating response to M Udell 790729 ltr. Using WASH-1400 event trees & data directly gives meaningless results
ABBOTT, E. ACRS - Advisory Committee on Reactor Safeguards B0/02/07 1p

--B1012020804 "Analysis of Feedwater Transient Sequences in B&W NSSS." ABBOTT, E. E. ACRS - Advisory Committee on Reactor Safeguards B0/02/07 21pp.

B101090243 Appx to certified summary of 240th ACRS meeting on B00410-12
* ACRS - Advisory Committee on Reactor Safeguards B0/04/10. 400pp 07382 115

B101050637 Comments on repts re waste mgt & waste confidence rulemaking. Biting & design & const of geologic repositories is relatively simple. Demonstration of facts is important work to be performed.
PHILBRICK, S. S. Philbrick, S. S. B0/11/06 1p. 07387 019

B101060038 Forwards continuation of B00810 comments on proposed Reg Guide RS 705-6 re lightning protection for nuclear power plants.
JOHNSON, J. B. Affiliation Unknown B0/10/08 35pp. 07187 001

B101060223 Summary of ACRS Fluid Dynamics Subcommittee B01119-20 meeting in Los Angeles, CA re recent difficulties w/ BWR hydraulic steam sys
* ACRS - Advisory Committee on Reactor Safeguards B0/11/07 9pp 07391 325.

B101070347 Comments on waste confidence rulemaking as requested in Waste Mgt Subcommittee B01113-14 meeting. Continued min maint & surveillance will insure safety & practicality of spent fuel storage in reactor water basins.
ALSAUGH, F. W. Affiliation Unknown B0/11/19. 3pp 07408 133

B101080317 Forwards review of IIRC-sponsored research re nondestructive evaluation research programs. Reliability of insp. code interp & human factors engineering for nondestructive evaluation operators should receive more attention.
BERGER, H. Commerce, Dept. of, National Bureau of Standards. B0/11/07 12pp 07417 354

B101090043 Transcript of ACRS Subcommittee on Regulatory Activities B10105 meeting in Washington, DC Pp 1-138.
* ACRS - Advisory Committee on Reactor Safeguards. B1/01/06 141pp 07426 006

B101090046 Transcript of ACRS Subcommittee on Safety Philosophy, Technology & Criteria B10106 meeting in Washington, DC re proposed requirements for plants w/ near-term CPs Pp 1-178 Supporting documents encl.
* ACRS - Advisory Committee on Reactor Safeguards B1/01/06 278pp 07427 001.

B101090327 Comments on passive containment sys. Principle is to thann LCCA steam via closed sys to suppression pool in form of deluge tanks filled w/ water, designed to act as passive heat sink.
ZUBAUS, Z. Franklin Institute/Franklin Research Center. B0/11/21. 2pp 07422 251

B101090336 Transcript of ACRS Subcommittee on Metal Components B10107 meeting in Washington, DC re inservice insp requirements. Pp 1-232 Supporting documents encl.
* ACRS - Advisory Committee on Reactor Safeguards. B1/01/07. 378pp 07422 253

B101090324 Certified summary of ACRS Safety Philosophy, Technology & Criteria Subcommittee B00903 meeting in Washington, DC re NRC mgt philosophy in developing licensing requirements & cascading failures in nuclear plants.
* ACRS - Advisory Committee on Reactor Safeguards. B0/11/23. 18p 07424 322

B101090544 Certified summary of ACRS Waste Mgt B01003 meeting in Washington, DC re proposed rulemaking on technical criteria for regulating geological disposal of high level radioactive waste
* ACRS - Advisory Committee on Reactor Safeguards B01/1/20 17pp
07462 108

B101093705 Certified summary of ACRS Subcommittee on Reactor Operations B01007 meeting in Washington, DC re NRC response to Congress on plan for systematic safety evaluation of all currently operating plants
* ACRS - Advisory Committee on Reactor Safeguards B01/0/23 19pp
07430 286

B101090716 Certified summary of ACRS LER Subcommittee B01120 meeting in Washington, DC re Ofc for Analysis & Evaluation of Operational Data evaluation of operating events & collection & sorting of data
* ACRS - Advisory Committee on Reactor Safeguards B01/2/02 4pp
07430 329

B101090929 Comments on ACRS Subcommittee on ECCS B01021-23 tour Concern for pump reliability in various modes of two-phase flows in full scale reactors lacking ACOSTA, A Union 76 Minerals Exploration Co B01/0/31 2pp
07428 354

B101120244 Transcript of ACRS 249th general meeting to discuss LOFT Special Review Group rept on B10108 in Washington, DC Pp 1-20
* ACRS - Advisory Committee on Reactor Safeguards B1/01/08 22pp
07447 062

B101130278 Transcript of ACRS 249th general meeting on B10109 in Washington, DC Pp 21-191
* ACRS - Advisory Committee on Reactor Safeguards B1/01/09 174pp 07309 001

B101160358 Summary of 249th ACRS meeting on B10108-10 re requirements for near-term CP applications Agree w/NRC proposed approach on siting & current position on reliability engineering NRC should defer final action until 250th meeting
MARCO, J C ACRS - Advisory Committee on Reactor Safeguards B1/01/12 3pp 07471 150

B101160463 Advises of actions taken during 249th ACRS meeting on B10108-10 ACRS concurred w/positions of Reg Guides SC 704-3 & RS 110-5
MARK, J C ACRS - Advisory Committee on Reactor Safeguards B1/01/13 1p 07469 358

B101200010 Comments on proposed rules 10CFR50 & 51. "Proposed Rulemaking on Storage & Disposal of Nuclear Waste " Ability to validate models could become crucial to confidence question
BIEHLER, H Argonne National Laboratory B01/11/18 2pp
07487 015

B101200911 Comments on proposed rules 10CFR50 & 51. "Proposed Rulemaking on Storage & Disposal of Nuclear Waste " Current direction of deep geologic disposal at environmentally favorable sites w/high integrity packages is safe
FOSTER, R F. Affiliation Unknown B01/11/21 3pp 07487 009

B101220324 Transcript of ACRS Subcommittee on ECCS B10115 meeting in Albuquerque, NM Pp 295-490
* ACRS - Advisory Committee on Reactor Safeguards B1/01/15 197pp 07309 001

B101220327 Transcript of ACRS Subcommittee on ECCS B10114 meeting in Albuquerque, NM Pp 1-294
* ACRS - Advisory Committee on Reactor Safeguards B1/01/14 296pp 07504 229

B101260442 Transcript of ACRS Subcommittee on AC/DC Power Sys Reliability B10122 meeting in Washington, DC Pp 1-242
* ACRS - Advisory Committee on Reactor Safeguards B1/01/22 244pp 07528 009

B101290413 Transcript of ACRS Subcommittee on Electric Power Sys B10123 meeting in Washington, DC re interaction of control & safety sys Pp 1-152
* ACRS - Advisory Committee on Reactor Safeguards B1/01/23 154pp 07570 106

B101290656 Transcript of Commissioners/ACRS B00308 joint meeting in Washington, DC re nuclear data link Pp 411-446
* ACRS - Advisory Committee on Reactor Safeguards Commissioners B01/08/08 37pp 07573 120

B101300658 Notice of ACRS Subcommittee on Consideration of Class 9 Accidents B01121 meeting in Washington, DC to review NRC safety research budget for FY82 decision on severe accident phenomena Portions of meeting may be closed
HOYLE, J C Office of the Secretary of the Commission B01/0/31 3pp 07587 052

B101300760 Certified minutes of ACRS Advanced Reactor Subcommittee B00613 meeting in Washington, DC re NRC sponsored research on advanced reactors FR notice, attendee list & tentative schedule encl
* ACRS - Advisory Committee on Reactor Safeguards B01/09/11 07584 223

B101300767 Notice of ACRS Subcommittee on Procedures & Administration B01203 meeting in Washington, DC re proposed procedures & guidelines for ACRS review of safety-related stds & criteria
HOYLE, J C Office of the Secretary of the Commission B01/11/13 2pp 07584 249

B101300775 Notice of proposed ACRS subcommittees & working groups meetings scheduled from B01203-B10204 re procedures & administration, ECCS, reactor radiological effects & site evaluation & combination of dynamic loads
HOYLE, J C Office of the Secretary of the Commission B01/11/20 6pp 07584 253

B101300778 Notice of ACRS Subcommittee on Transportation of Radioactive Materials B01029 meeting in Washington, DC re NRC transportation, certification process for package design
HOYLE, J C Office of the Secretary of the Commission B01/0/14 2pp 07584 259

B101300781 Notice of ACRS Subcommittee on Procedures & Administration B01105 meeting in Washington, DC re proposed changes in ACRS role to strengthen position in regulatory process
HOYLE, J C Office of the Secretary of the Commission B01/0/19 2pp 07584 261

B101300790 Certified summary of ACRS Fluid Dynamics Subcommittee B01113 meeting in Burlingame, CA re Nucleonics Engineering Corp passive containment sys
* ACRS - Advisory Committee on Reactor Safeguards B01/12/05 07584 277

B101300794 Certified minutes of ACRS Subcommittee on Waste Mgt B01113-14 meeting in Washington, DC re proposed rulemaking on storage & disposal of nuclear waste FR notice & attendee list encl
* ACRS - Advisory Committee on Reactor Safeguards B01/12/11 07584 280

B101300798 Notice of indefinite postponement of ACRS Subcommittee on B&W Water Reactors B01030 meeting
HOYLE, J C Office of the Secretary of the Commission B01/0/24 1p 07584 294

B101300800 Notice of rescheduled B01112 meeting ACRS Subcommittee on B&W Water Reactors will meet on B01218
HOYLE, J C Office of the Secretary of the Commission B01/11/05 1p 07584 295

B101300804 Notice of rescheduled B01030-31 meeting ACRS Subcommittee on B&W Water Reactors will meet on B01112 in Washington, DC
HOYLE, J C Office of the Secretary of the Commission B01/0/28 1p 07584 296

B101300807 Certified minutes of ACRS Subcommittee on Transportation of Radioactive Materials B01029 meeting in Washington, DC re NRC request to conduct independent review of transportation certification process of NRC
* ACRS - Advisory Committee on Reactor Safeguards B01/11/07 07584 297

B101300810 Certified summary of ACRS ECCS Subcommittee B01022-23 meeting in ID Falls, ID re review of NRC program to determine need for automatic reactor coolant pump trip following small break LOCA
* ACRS - Advisory Committee on Reactor Safeguards B01/12/05 07584 304

B101300833 Notice of ACRS Subcommittee on ECCS B01209-10 meeting in Los Gatos, CA re NRC reactor safety research program & plans for LOCA & transient research
HOYLE, J C Office of the Secretary of the Commission B01/11/20 2pp 07584 317

8101300610 Notice of ACRS Subcommittee on NRC Reactor Safety Research
Program 801203 meeting in Washington, DC re new developments
in program since issuance of NUREG-0699 Portions of meeting
may be closed
MOYLE, J C Office of the Secretary of the Commission 80/11/14
3pp 07586 200

810130054 Certified summary of ACRS Subcommittee on Regulatory
Activities 801105 meeting in Washington, DC to review
Revision 2 to Reg Guides 1.12 & proposed amend to 10CFR50 re
domestic licensing of production & utilization facilities
* ACRS - Advisory Committee on Reactor Safeguards 80/12/04 11pp
07586 243

810130056 Notice of ACRS Subcommittee on Reliability, & Probabilistic
Assessment 801203 meeting in Washington, DC to review items
on use of risk assessment in licensing process Portions of
meeting may be closed
CHILKUS, J Office of the Secretary of the Commission 80/11/12
3pp 07586 294

COMMISSION NRC COMMISSIONERS

801210036 Responds to 801003 ltr re NRC review of emergency
procedures at operating reactors as part of consideration of
ATWS problem IE Bulletin 80-17 required BWR licensees to
review emergency procedures re operator shutdown actions
AHEARNE, J F Commissioners IE8-B0-17 80/11/24 2pp 03772 020

801210047 Responds to 800511 request for NRC to consider control sys
failures in nuclear power plants Forwards summary of
significant corrective measures required as result of
control sys malfunction or failure analyses
AHEARNE, J F Commissioners 80/11/17 3pp 03772 023

--801210052 Requests clarification of NRC 800514 response to 800207 ltr
re control sys failures Nature of analysis leading to NRC
consensus re safety sys mitigating failures unclear
UDALL, M K House of Rep , Interior & Insular Affairs 80/06/17
2pp 03772 027

8101050528 Forwards list of pending legislation re NRC & programs
FITZGERALD, J A Office of the General Counsel 80/12/02 1p
07385 271

--8101050631 Forwards three active NRC-related legislative items FY81
Authorization Bill, H.R. 8378 waste mgmt bill & SECY-80-366.
Fourth item re providing financial assistance to NRC
resident inspectors is under development
STOBER, C Office of the General Counsel 80/12/02 70pp
07386 292

--8101050634 SECY-80-366
Informs Commission of NRC legislative program for 97th
Congress
STICKLEY, L Office of the General Counsel 80/08/06 11pp
07386 352

8101050636 Forwards memo re status of implementation of Reorganization
Plan
FITZGERALD, J A Office of the General Counsel 80/12/02 1p
07387 011

8101060046 Forwards IE notes & plant status rept for 801208
DIRCKS, W J Office of the Executive Director for Operations
80/12/09 3pp 07349 129

8101060052 Discusses possible emergency measures in event of major
cutoff of Persian Gulf as result of continued hostilities
in Middle East Safety implications should be reviewed in
advance to determine safety or emergency production benefit.
GILINSKY, V Commissioners 80/12/05 2pp 07399 127

8101060061 Forwards IE notes & plant status rept for 801209
DIRCKS, W J Office of the Executive Director for Operations
80/12/10 3pp 07187 001

8101060266 Responds to 801010 ltr requesting withdrawal of Pilot Knob
mine from list of potential facilities for consideration by
Lawrence Berkeley Lab until concerns are resolved
AHEARNE, J F Commissioners 80/11/24 1p 07399 076

8101060432 Responds to 801004.20 & 28 ltrs re concerns involving
transportation & disposal of low level radwastes from
United Nuclear Corp NRC investigating ban on United Nuclear
shipments in State of NV
AHEARNE, J F Commissioners 80/12/03 5pp 07399 005

- 8101060436 Requests NRC inquiry into circumstance surrounding ban
against United Nuclear Corp shipping of radwastes from
Wood River Junction, RI to Beatty, NV
GARRAHY, J J Rhode Island, State of 80/10/29 2pp 07399 001

--8101060440 Expresses gratitude for prompt NRC response to situation
in NV re refusal of United Nuclear Corp request to dispose
of radwastes NRC should assure that waste is properly
packaged
GARRAHY, J J Rhode Island, State of 80/10/20 9pp 07399 001

--8101060446 Requests full & public investigation of United Nuclear
present waste packaging & QC programs to determine if NRC
enforcement sanctions are needed
GARRAHY, J J Rhode Island, State of 80/10/28 2pp 07399 001

8101060905 Responds to 801110 request for biweekly rept on transit
activities at NRC Forwards list of documents provided to NRC
transition team, list of personnel associated w/team &
Commission instructions re info to be provided to team
AHEARNE, J F Commissioners 80/12/04 10pp 07400 112

8101060952 Requests that ACRS review NRC rationale re control sys
info re ATWS in response to Representative Udall request
AHEARNE, J F Commissioners 80/12/12 1p 07401 110

--8101060953 Requests ACRS review NRC rationale re control sys fail
UDALL, M K House of Rep , Interior & Insular Affairs 80/12/12
1p 07401 111

--8101060954 Requests ACRS review of NRC 801023 & 1124 responses to
inquiries re ATWS issue
UDALL, M K House of Rep , Interior & Insular Affairs 80/12/12
1p 07401 112

8101070221 Submits daily notes for 801217 Plant status for five IE
regions encl
DIRCKS, W J Office of the Executive Director for Operations
80/12/18 4pp 07197 001

8101070487 Submits daily staff notes for 801216
DIRCKS, W J Office of the Executive Director for Operations
80/12/17 3pp 07307 001

8101070488 Submits daily staff notes for 801215
DIRCKS, W J Office of the Executive Director for Operations
80/12/16 3pp 07404 351

8101070541 Forwards transcript of State Liaison Officers' 801207
meeting in Washington, DC Comments requested by 801233
CORNELLE, E K Office of the Executive Director for Operations
80/12/17 1p 07407 071

--8101070543 Transcript of State Liaison Officers' 801210 meeting
Washington, DC Pp 1-121
* Commissioners 80/12/10 129pp 07407 072

--8101070550 Transcript of State Liaison Officers' 801209 meeting
Washington, DC Pp 1-239
* Commissioners 80/12/09 360pp 07407 148

8101080072 Advises that no problem expected w/supplying transition
lead Ofc of Executive Director staff notes & preliminary
notification of events or replacing both classes of
documents in PDR.
FITZGERALD, J A Office of the General Counsel 80/12/04 1p
07417 260

8101080241 Forwards V Stello comments on recommendations in Rept
96-1452 of House Committee on Govt Operations for
improvement of NRC IE program Encl lists each recommendation
& related comment, Commission agrees in general w/comments
AHEARNE, J F Commissioners 80/12/09 10pp 07422 026

8101080231 Responds to 801007 ltr re NRC progress in review of CP
of resources for Section 110 of NRC 1980 Authorization Act.
delay in adjudicatory proceedings & lack of coherent
regulatory guidance w/o encl documentation
AHEARNE, J F Commissioners 80/12/22 4pp 07422 011

--8101080336 Responds to 801009 ltr re NRC progress in review of
of resources for Section 110 of NRC 1980 Authorization Act.
delay in adjudicatory proceedings & lack of coherent
regulatory guidance w/o encl documentation
AHEARNE, J F Commissioners 80/12/22 4pp 07422 015

--B101080360 Responds to B01009 ltr re NRC progress in review of CPs, use of resources for Section 110 of NRC 1980 Authorization Act, delay in adjudicatory proceedings & lack of coherent regulatory guidance w/o encl documentation
AHEARNE, J F Commissioners 80/12/22 4pp 07422 019

--B101080392 Expresses concern re NRC failure to resume casework reviews of CP applications Expedient processing of applications should be resumed in light of successful identification of lessons learned from TMI-2
BRIDY, C L GLEFFLER, T GRAMM, P House of Rep 80/10/09 2pp 07422 026

B101080390 Submits status repts re pending appeals court case challenging NRC export license issuance for nuclear reactor to be constructed in Philippines & implementation of Executive Order 12114
STOIBER, C Office of the General Counsel 80/12/15 13pp 07419 276

B101090390 Forwards list & explanation of pending NRC adjudicatory matters of special policy significance
FITZGERALD, J A Office of the General Counsel 80/12/10 4pp 07417 331

B101090746 Informs of B01020 meeting w/DGE to discuss technical aspects of initial DOE plans to implement high level waste solidification project Certain areas require resolution between DOE & NRC Slide presentation encl.
DAVIS, J O Office of Nuclear Material Safety & Safeguards 80/11/13 2pp 07429 321

B101090759 Submits daily staff notes for B01203
DIRCKS, W J Office of the Executive Director for Operations 80/12/08 3pp 07442 043

B101090764 Submits daily staff notes for B01212
DIRCKS, W J Office of the Executive Director for Operations 80/12/15 3pp 07430 070

B101070840 Forwards summary of C Stoiber B01216 memo re status of Philippine lawsuit & Executive Order 12114
FITZGERALD, J A Office of the General Counsel 80/12/18 3pp 07427 356

B101090850 Forwards 790130 list of documents re nuclear siting & licensing reform, in response to R Stratford request
FITZGERALD, J A Office of the General Counsel 80/12/17 26pp 07429 290

B101100003 Forwards Kyburz manuscript & translation w/o encl
HENDRIE, J H Commissioners 80/12/15 1p 07445 213

B101100004 Responds to request for review of H R 7865, "Nuclear Safety Research, Development & Demonstration Act of 1980 " NRC takes no position on encl bill.
AHEARNE, J F Commissioners 80/12/17 6pp 07445 207

B101100007 Responds to B01031 legislative referral memorandum re judicial review of agency actions NRC opposes three versions of Bumpers amend Amend does not adequately deal w/broad jurisdiction of agency in dealing w/public health & safety
GICKNIT, L Office of the General Counsel 80/12/10 3pp 07445 191

--B101100010 Legislative referral memorandum requesting judicial review of agency actions Requests review of encl three versions of Bumpers amend.
CARLSTROM, R E Office of Management & Budget 80/10/31 12pp 07445 194

B101100079 Forwards DC Circuit Court decision in S Sholly vs NRC w/o decision
FITZGERALD, J A Office of the General Counsel 80/12/03 1p 07444 319

B101100149 BECY-80-394
Weekly info rept for wk ending B01219.
REMBT, T A Office of the Executive Director for Operations 80/12/29 31pp 07443 064

B101100169 Responds to request for info re monitoring of adjudicatory proceedings Each month ASLB submits notice of occurrences, providing list of events in proceedings. Ofc of General Counsel summarizes developments
FITZGERALD, J A Office of the General Counsel 80/12/09 1p 07445 019

B101100209 Advises that final GAO rept, "Electricity Planning - Improvements Can Alter Tomorrow's Investment Decisions," correctly interprets NRC comments on draft rept NRC continues to endorse recommendation
AHEARNE, J F Commissioners 80/12/10 1p 07445 045

--B101100207 Advises that final GAO rept, "Electricity Planning Improvements Can Alter Tomorrow's Investment Decisions," correctly interprets NRC comments on draft rept NRC continues to endorse recommendation
AHEARNE, J F Commissioners 80/12/10 1p 07445 046

--B101100212 Advises that final GAO rept, "Electricity Planning Improvements Can Alter Tomorrow's Investment Decisions," correctly interprets NRC comments on draft rept NRC continues to endorse recommendation
AHEARNE, J F Commissioners 80/12/10 1p 07445 017

--B101100219 Advises that final GAO rept, "Electricity Planning Improvements Can Alter Tomorrow's Investment Decisions," correctly interprets NRC comments on draft rept NRC continues to endorse recommendation.
AHEARNE, J F Commissioners 80/12/10 1p 07445 040

--B101100226 Advises that final GAO rept, "Electricity Planning Improvements Can Alter Tomorrow's Investment Decisions," correctly interprets NRC comments on draft rept NRC continues to endorse recommendation
AHEARNE, J F Commissioners 80/12/10 1p 07445 049

--B101100250 Advises that final GAO rept, "Electricity Planning Improvements Can Alter Tomorrow's Investment Decisions," correctly interprets NRC comments on draft rept NRC continues to endorse recommendation
AHEARNE, J F Commissioners 80/12/10 1p 07445 050

--B101100298 Advises that final GAO rept, "Electricity Planning Improvements Can Alter Tomorrow's Investment Decisions," correctly interprets NRC comments on draft rept NRC continues to endorse recommendation
AHEARNE, J F Commissioners 80/12/10 1p 07445 051

--B101100245 Advises that final GAO rept, "Electricity Planning Improvements Can Alter Tomorrow's Investment Decisions," correctly interprets NRC comments on draft rept NRC continues to endorse recommendation
AHEARNE, J F Commissioners 80/12/10 1p 07445 052

B101120164 Delegates appropriate authority to Ofc of Nuclear React Regulation Transmittal notice, organization & functions section from NRC manual & CR notice re domestic licensing proceedings encl
ALBERS, W A Commissioners 79/01/20 32pp 07436 324

B101130033 Forwards draft "Safety Goal Issue in Historical Perspective," per request.
STOIBER, C R Office of the General Counsel 80/12/22 1p 07448 300

--B101130039 "Safety Goal Issue in Historical Perspective," draft
MAZUZAN, G Y WALKER, J S Office of the Secretary of the Commission 80/12/31 29pp 07448 301

B101130620 Responds to GAO B00B18 rept, "Analysis of Price-Anders Act," recommending NRC assist Congress in determining realistic liability limitation for nuclear accidents Congress should decide whether to increase liability limit
AHEARNE, J F Commissioners 80/12/31 3pp 07453 184

--B101130622 Responds to GAO B00B18 rept, "Analysis of Price-Anders Act," recommending NRC assist Congress in determining realistic liability limitation for nuclear accidents Congress should decide whether to increase liability limit
AHEARNE, J F Commissioners 80/12/31 3pp 07453 187

--B101130632 Responds to GAO B00B18 rept, "Analysis of Price-Anders Act," recommending NRC assist Congress in determining realistic liability limitation for nuclear accidents Congress should decide whether to increase liability limit
AHEARNE, J F Commissioners 80/12/31 3pp 07453 190

--B101130634 Responds to GAO B00B18 rept, "Analysis of Price-Anders Act," recommending NRC assist Congress in determining realistic liability limitation for nuclear accidents Congress should decide whether to increase liability limit
AHEARNE, J F Commissioners 80/12/31 3pp 07453 193

--B101130637 Responds to GAO B00B10 rept. "Analysis of Price-Anderson Act." recommending NRC assist Congress in determining realistic liability limitation for nuclear accidents. Congress should decide whether to increase liability limit. AHEARNE, J F Commissioners 80/12/31 3pp 07453 196

--B101130640 Responds to GAO B00B10 rept. "Analysis of Price-Anderson Act." recommending NRC assist Congress in determining realistic liability limitation for nuclear accidents. Congress should decide whether to increase liability limit. AHEARNE, J F Commissioners 80/12/31 3pp 07453 199

--B101130643 Responds to GAO B00B10 rept. "Analysis of Price-Anderson Act." recommending NRC assist Congress in determining realistic liability limitation for nuclear accidents. Congress should decide whether to increase liability limit. AHEARNE, J F Commissioners 80/12/31 3pp 07453 202

--B101130646 Responds to GAO B00B10 rept. "Analysis of Price-Anderson Act." recommending NRC assist Congress in determining realistic liability limitation for nuclear accidents. Congress should decide whether to increase liability limit. AHEARNE, J F Commissioners 80/12/31 3pp 07453 205

B101130725 Forwards GJ Chilk B01113 memo to Commissioners on proposed revisions to internal procedures & Commissioner Action paper on review of delegations of authority in response to request. FITZGERALD, J A Office of the General Counsel 80/12/04 1p 07452 161

--B101130727 Responds to B00929 memo requesting review of internal procedures to identify areas where rods would be appropriate for implementation of reorganization plan. Revisions re format of SECY papers & correspondence are recommended. CHILK, S J Office of the Secretary of the Commission 80/11/13 10pp 07452 162

B101140041 Forwards daily notes for B01218 Plant status for five IE regions encl. DIRCKS, W J Office of the Executive Director for Operations 80/12/19 3pp 07308 C01

B101140666 Responds to B00917 request for NRC views re HR B119.b111 requiring Secretary of Commerce to undertake study on effects of past ocean dumping of radwastes. Section re NRC assistance should also include CCE. AHEARNE, J F Commissioners 80/12/12 1p 07462 016

--B101140677 Requests comments on encl B111, HR B119, requiring Secretary of Commerce to undertake study to determine effects of past ocean dumping of radwastes. ASHLEY, T L House of Rep. Merchant Marine & Fisheries 80/09/17 4pp 07462:017

B101140716 Forwards NUREG-0090, Vol 3, Number 2, "Rept to Congress on AOs, Apr-June 1980." Two AOs at operating nuclear power plants involved loss of decay heat removal & failure of control rods to fully insert during scram W/o encl. AHEARNE, J F Commissioners 80/12/05 1p 07458 313.

--B101140725 Forwards NUREG-0090, Vol 3, Number 2, "Rept to Congress on AOs, Apr-June 1980." Two AOs at operating nuclear power plants involved loss of decay heat removal & failure of control rods to fully insert during scram. AHEARNE, J F Commissioners 80/12/05 1p 07458 314

--B101140736 NUREG-0090 V3 N02 REPORT TO CONGRESS ON ABNORMAL OCCURRENCES April-June 1980 * Office of Management and Program Analysis 80/11/30. 38pp Available at NTIS 07458 313

B101140774 Forwards proposed rule 10CFR2.50.70 & 73, "Protection of Unclassified Safeguards Info." Required rept to Congress will be submitted concurrent w/issuance of final rule W/o encl. AHEARNE, J F Commissioners 80/12/22 1p 07457 030.

--B101140779 Forwards proposed rule 10CFR2.50.70 & 73, "Protection of Unclassified Safeguards Info." Required rept to Congress will be submitted concurrent w/issuance of final rule W/o encl. AHEARNE, J F Commissioners 80/12/22 1p 07457 031

--B101140786 Forwards proposed rule 10CFR2.50.70 & 73, "Protection of Unclassified Safeguards Info." Required rept to Congress will be submitted concurrent w/issuance of final rule W/o encl. AHEARNE, J F Commissioners 80/12/22 1p 07457 032

--B101140790 Forwards proposed rule 10CFR2.50.70 & 73, "Protection of Unclassified Safeguards Info." Required rept to Congress will be submitted concurrent w/issuance of final rule W/o encl. AHEARNE, J F Commissioners 80/12/22 1p 07457 033

--B101140799 Forwards proposed rule 10CFR2.50.70 & 73, "Protection of Unclassified Safeguards Info." Required rept to Congress will be submitted concurrent w/issuance of final rule W/o encl. AHEARNE, J F Commissioners 80/12/22 1p 07457 034

--B101140802 Forwards proposed rule 10CFR2.50.70 & 73, "Protection of Unclassified Safeguards Info." Required rept to Congress will be submitted concurrent w/issuance of final rule W/o encl. AHEARNE, J F Commissioners 80/12/22 1p 07457 035

--B101140811 "Protection of Unclassified Safeguards Info." 10CFR2.73 proposed rule Regulations identify types of safeguards info to be protected, establish min protection requirements & set conditions for access to safeguards info. CHILK, S J Office of the Secretary of the Commission 80/12/27pp 07457 036

B101140852 Forwards addl info re licenses permitting introduction radioactive matl in sea Review revealed no addl info re sea disposal of radwaste W/o encl. AHEARNE, J F Commissioners 80/12/09 1p 07457 319

--B101140855 Forwards addl info re licenses permitting introduction radioactive matl in sea Review revealed no addl info re sea disposal of radwaste W/o encl. AHEARNE, J F Commissioners 80/12/09 1p 07457 320

--B101140859 Forwards addl info re licenses permitting introduction radioactive matl in sea Review revealed no addl info re sea disposal of radwaste W/o encl. AHEARNE, J F Commissioners 80/12/09 1p 07457 321

--B101140862 Forwards addl info re licenses permitting introduction radioactive matl in sea Review revealed no addl info re sea disposal of radwaste W/o encl. AHEARNE, J F Commissioners 80/12/09 1p 07457 322

--B101140871 Forwards addl info re licenses permitting introduction radioactive matl in sea Review revealed no addl info re sea disposal of radwaste. AHEARNE, J F Commissioners 80/12/09 2pp 07457 323.

B101140876 Submits info re NRC program plans to assure that safety related equipment in nuclear facilities is qualified to perform function under accident conditions. Forwards SECY-B0-319 outlining new qualification program W/o encl. AHEARNE, J F Commissioners 80/12/15 2pp 07457 331

--B101140881 Submits info re NRC program plans to assure that safety related equipment in nuclear facilities is qualified to perform function under accident conditions. Forwards SECY-B0-319 outlining new qualification program W/o encl. AHEARNE, J F Commissioners 80/12/15 2pp 07457 333

--B101140894 Submits info re NRC program plans to assure that safety related equipment in nuclear facilities is qualified to perform function under accident conditions. Forwards SECY-B0-319 outlining new qualification program W/o encl. AHEARNE, J F Commissioners 80/12/15 2pp 07457 335.

--B101140895 Submits info re NRC program plans to assure that safety related equipment in nuclear facilities is qualified to perform function under accident conditions. Forwards SECY-B0-319 outlining new qualification program W/o encl. AHEARNE, J F Commissioners 80/12/15 2pp 07457 337.

--B101140899 Submits info re NRC program plans to assure that safety related equipment in nuclear facilities is qualified to perform function under accident conditions. Forwards SECY-B0-319 outlining new qualification program W/o encl. AHEARNE, J F Commissioners 80/12/15 2pp 07457 339

--B101140904 Submits info re NRC program plans to assure that safety related equipment in nuclear facilities is qualified to perform function under accident conditions. Forwards SECY-B0-319 outlining new qualification program. AHEARNE, J F Commissioners 80/12/15 2pp 07457 361

B101140963 Ack receipt of B00822 ltr & manuscript which have been forwarded to nuclear fission staff at DOE. HENDRIE, J M Commissioners 80/12/15 1p 07461 096.

Observations & Recommendations Re Problem of Steam Generator
Overfill & Combined Primary & Secondary Side Blowdown "
DIRCKS, W J Office of the Executive Director for Operations
80/12/23 1p 07463 026

--8101150366 "Ofc of Analysis & Evaluation of Operational Data
Observations & Recommendations Re Problem of Steam Generator
Overfill & Combined Primary & Secondary Side Blowdown "
IMORD, E V , LANNINO, W D Director's Office 80/12/17 28pp
07363 027

8101150425 Forwards proposed revisions to internal Commission
procedures, in response to Commission 800929 request
Proposed revisions handling of correspondence & format of
SECY papers
CHILK, S J Office of the Secretary of the Commission 80/11/13
10pp 07462 231.

8101150555 Forwards requested excerpts from hearings re Nuclear Siting
& Licensing Act of 1970
FITZGERALD, J A Office of the General Counsel 80/12/18 8pp
07309 001

8101150862 Submits daily notes for 801222 Plant status for five IE
regions encl
DIRCKS, W J Office of the Executive Director for Operations
80/12/23 3pp 07309 001

8101150914 Weekly info rept for wk ending 810102
REHM, T A Office of the Executive Director for Operations
80/11/08 29pp 07465 007

8101160124 Forwards requested documents re oil emergencies
HANRAHAN, E J Office of Policy Evaluations 80/12/30 1p
07467 307

--8101160135 Forwards draft response to DOE 801103 ltr requesting contact
for contingency planning in event of oil shortfall emergency
& info re nuclear strategies EJ Hanrahan named as NRC
contact.
HANRAHAN, E J Office of Policy Evaluations 80/12/11 13pp
07467 308.

--8101160142 Requests NRC contact for contingency planning in event of
oil shortfall emergency & info re nuclear strategies
HCGUSE, B R Energy, Dept of, Economic Regulatory Administration
80/11/03 3pp 07467 321

--8101160147 Forwards rept of meeting at DOE re development of
initiatives to respond to potential oil shortages
HANRAHAN, E J Office of Policy Evaluations 79/11/19 1p
07467 324

--8101160153 Summary of 801214 meeting in Washington, DC re development of
federal emergency planning for responding to oil shortage
RATHBURN, D Office of Policy Evaluations 79/11/16 15pp
07467 325.

--8101160199 Forwards answers in response to 791114 memo re initiatives
to respond to potential oil shortages Areas addressed plant
status & possible startup dates & methods for restricting
new reactors to 30% power
HANRAHAN, E J Office of Policy Evaluations 79/12/19 10pp
07467 340

--8101160164 Forwards draft NRC paper re domestic initiatives to respond
to potential oil shortages
RATHBURN, D Office of Policy Evaluations 79/11/13 23pp
07467 350

--8101160172 Responds to 801208 memo requesting status rept on actions to
be taken during natl energy emergency. In 1979, NRC prepared
analysis of options to increase nuclear productivity in
response to energy emergency
HANRAHAN, E J Office of Policy Evaluations 80/12/18 3pp
07467 011

8101190175 Forwards 810102 memo re NRC actions in event of natl energy
emergency.
FITZGERALD, J A Office of the General Counsel 81/01/06 1p
07475 211.

--8101190182 Responds to 801205 memo requesting assessment of legislation
required for natl energy emergency. Currently, no statutory
authority exists for licensing temporary operation prior
to completion of hearings.
BICKWIT, L B Office of the General Counsel 81/01/02 2pp
07475 212

BICKWIT, L B Office of the General Counsel 79/03/14 21pp
02450 078.

8101270879 Responds to 801125 ltr X McCarthy has been accepted for
course in health physics & radiation protection & U Kerr has
been directed to arrange meeting re CT interest in becoming
Agreement State
AHEARNE, J F Commissioners 80/12/11 1p 07590 106

--8101270882 Discusses K McCarthy application to attend course in
physics & radiation protection & requests that favorable
consideration be given
GRASSO, E Connecticut, State of 80/11/25 1p 07590 107

8101280378 Response to 800912 ltr re still plans to scale down clean
activities due to PA Public Util Commission 800918 order
denying request for rate relief & NRC action schedule Encl
Table 1 lists NRC requirements for safe shutdown
AHEARNE, J F Commissioners 81/01/12 6pp

8101300784 Forwards second monthly Ofc of Nuclear Reactor Regulation
status rept, for 801115-1215, per House Rept 96-1093 Repl
discusses actions taken during month for operating reactors
& licensing reviews of new facilities
AHEARNE, J F Commissioners 80/12/31 14pp 07584 263

CONTRACT NRC CONTRACTS AND MODIFICATIONS

8101090183 Notification of contract execution, Mod B to "PDR
Micrographic Storage & Retrieval Sys " Contractor: ACCESS
Corp
MEDROW, L A Administrative Contracts Branch NRC-17-79-449
80/12/22 1p 07382 109

--8101090189 Mod B, clarifying mandatory specs re translator program
"PDR Micrographic Storage & Retrieval Sys "
BAKER, N D Access Corp MATTIA, M J Administrative Contracts
Branch NRC-17-79-449 80/12/22 2pp 07392 110.

8101090200 Notification of contract execution, Mod 1 to "Cylogenetic
Studies in Grand Junction, CO " Contractor CO Dept of Health
GUSTAVE, R P Research Contracts Branch FIN 6-7102-0
NRC-01-00-022 80/12/02 1p 07383 209

--8101090208 Mod 1, adding effective date 800930 in Block 2 of Std F
26, to "Cylogenetic Studies in Grand Junction, CO."
TRAYLOR, F A Colorado, State of MORTON, K V Research Contra
Branch FIN 6-7102-0 NRC-01-00-022 80/12/02 1p 07383 2

8101060231 Notification of contract execution, Mod 5 to "Licensee
Performance Evaluation " Contractor: Teknekron, Inc.
BATHEN, L Research Contracts Branch FIN 8-122B NRC-05-78-302
80/12/19 1p 07391 338

--8101060237 Mod 5, changing completion schedule & rept requirements
extending period of performance through 801128, to "Licensee
Performance Evaluation "
COHEN, B Teknekron, Inc MORTON, K V Research Contracts Branch
FIN 8-122B NRC-05-78-302 80/12/19 2pp 07391 339

8101060249 Notification of contract execution, Mod 2 to "NRC Monitor
Heissdampfreaktor Seismic Tests " Contractor ANCO
Engineers, Inc
WOLLETT, B Research Contracts Branch FIN 8-675B NRC-04-79-203
80/12/18 1p 07391 357.

--8101060258 Mod 2, refining statement of work, task & yearly final r
requirements, to "NRC Monitor Heissdampfreaktor Seismic
Tests "
SMITH, C B Anco Testing Laboratory, Inc MORTON, K V Research
Contracts Branch FIN 8-675B NRC-04-79-203 80/12/18 8pp
07391 358

8101060275 Notification of contract execution, Mod 4 to "Implementat
of Mods to NRC Contract Info Sys " Contractor Small Business
Administration Subcontractor Social Research Applications
Corp
MEDROW, L A Administrative Contracts Branch NRC-10-79-381
80/11/13 1p 07342 014.

--8101060280 Mod 4, decreasing number of progress repts & total amount
of contract, to "Implementation of Mods to NRC Contract Info
Sys "
TUNSTALL, J E Small Business Administration MATTIA, M J
Administrative Contracts Branch WOLFE, R H Social Research
Applications Corp NRC-10-79-381 80/11/13 2pp 07392 015

8101060312 Notification of contract execution, Mod 5 to "Sys Maint Programming" Contractor Small Business Administration Subcontractor Rehab Group, Inc
MAGAN, T F Administrative Contracts Branch NRC-10-79-375
80/10/15 1p 07392 049

--8101060321 Mod 5, defining Mod 4, incorporating two add'l labor categories & rates & increasing funds to "Sys Maint Programming"
JUILLO, R S Rehab Group, Inc COLLINS, F M Small Business Administration MATTLIA, M J Administrative Contracts Branch
NRC-10-79-375 80/10/15 5pp 07392 050

8101060328 Forwards executed contract mod forms
LEBO, C D Administrative Contracts Branch NRC-10-60-702
80/12/31 1p 07392 059

--8101060341 Notification of contract execution, Mod 2 to "Word Processing Svcs" Contractor Automated Correspondence Sys, Inc
COLEMAN, R Administrative Contracts Branch NRC-10-80-702
80/12/31 1p 07392 060

--8101060347 Mod 3, changing contract requirements, to "Word Processing Svcs"
SPAISMAN, J A Automated Correspondence Systems, Inc LEBO, C D Administrative Contracts Branch NRC-10-80-702 80/12/31 1p 07392 061

8101060743 Notification of contract execution Human Factors Program Plan, awarded to Human Factors Soc, Inc
MORTON, K V Research Contracts Branch FIN B-7239 NRC-04-81-186
80/12/14 1p 07400 302

--8101060750 Contract "Human Factors Program Plan," awarded to Human Factors Soc, Inc
SNYDER, H L Human Factors Society, Inc MORTON, K V Research Contracts Branch FIN B-7239 NRC-04-81-186 80/12/14 4pp 07400 303

8101060783 Notification of contract execution "Political Economy of Alternative Safety Goals," awarded to L Lave
LAVE, L B Administrative Contracts Branch NRC-19-81-492 80/12/18 1p 07400 309

--8101060790 Contract "Political Economy of Alternative Safety Goals," awarded to L Lave
LAVE, L B PERLMAN, J Administrative Contracts Branch
NRC-19-81-492 80/12/18 5pp 07400 310

8101060799 Notification of contract execution, Mod 4 to "Analysis of Matl Accounting Practices at Specific Nuclear Facility"
Contractor Science Applications, Inc
MILES, E B Administrative Contracts Branch FIN B-6393-B
NRC-02-78-049 80/12/01 1p 07401 101

--8101060942 Mod 4, deobligating funds to "Analysis of Matl Accounting Practices at Specific Nuclear Facility"
MANN, B O Science Applications, Inc PERLMAN, J Administrative Contracts Branch FIN B-6393-B NRC-02-78-049 80/12/01 1p 07401 102

8101070321 Notification of contract execution "Technical Assistance for EIS on 10CFR61," awarded to Dames & Moore
HAIRSTON, C SMITH, C Technical Assistance Contracts Branch FIN B-7318-1 NRC-02-81-049 80/12/01 2pp 07408 122

8101090392 Notification of contract execution, Mod 7 to "PDR Micrographic Storage & Retrieval Sys" Contractor ACCESS Corp
MEDROW, L A Administrative Contracts Branch NRC-17-79-449
80/12/10 1p 07442 211

--8101090394 Mod 7, extending maint coverage & increasing total amount of contract, to "PDR Micrographic Storage & Retrieval Sys."
* ACCESS Corp. MATTLIA, M J Administrative Contracts Branch
NRC-17-79-449 80/12/10 7pp 07442 212

8101090395 Notification of contract execution, Mod 3 to "Guidelines on Use of Geochronological Methods in Nuclear Power Plant Siting" Contractor OH Curtis
GUSTAVE, R P Research Contracts Branch FIN B-10057
NRC-01-77-070 80/12/16 1p 07442 021

--8101090706 Mod 3, re-establishing final delivery date of 810115, to "Guidelines on Use of Geochronological Methods in Nuclear Power Plant Siting"
* Curtis, O H MORTON, K V Research Contracts Branch FIN B-10357 NRC-01-77-070 80/12/16 1p 07442 022

8101090393 Notification of contract execution, Mod 3 to "Indices" Contractor Data Composition Svcs, Inc
MAGAN, T F Administrative Contracts Branch NRC-10-80-702 80/12/18 1p 03893 231

--8101090398 Mod 3, changing specs re issuances required cumulative index required for 1975 through 1979, to "Issuance & Indices"
WHITE, R J Data Composition Services, Inc MATTLIA, M J Administrative Contracts Branch NRC-10-80-661 80/12/17 1p 03893 232

8101090998 Notification of contract execution "Holding And Conflict," awarded to Graduate School, USOA
COLEMAN, R Administrative Contracts Branch NRC-10-80-702 80/12/17 1p 03893 346

--8101091000 Contract "Holding Public Meetings And Conflict" to Graduate School, USOA
SHEA, A C Agriculture, Dept of LEBO, C D Administrative Contracts Branch NRC-10-81-389 80/12/17 6pp

8101100302 Notification of contract execution, Mod 3 to "Assistance for Fire Protection Program Review & Evaluation" Contractor Gage-Babcock & Associates, Inc
SHEA, O Technical Assistance Contracts Branch FIN B-6588 NRC-03-79-127 80/11/28 1p 07443 311

--8101100307 Mod 3, allotting add'l funds to "Technical Assistance Program Review & Evaluation"
COHEN, B M Gage-Babcock Associates, Inc ODOHERTY, J Assistance Contracts Branch FIN B-6588 NRC-03-79-127 80/11/28 1p 07443 312

8101100311 Notification of contract execution, Mod 10 to "Seismology Support" Contractor Natl Academy of Sciences
WOLLETT, S Research Contracts Branch FIN A-4053
80/12/18 1p 07443 326

--8101100316 Mod 10, extending period of performance to 8/80, allocating add'l funds, to "Committee on Seismology & Earthquake Prediction" Contractor Natl Academy of Sciences
MORTON, K V Research Contracts Branch FIN A-4053 NRC-04-76-184 80/12/18 1p 07443 327

8101100321 Notification of contract execution, Mod 3 to "Gas-Liquid Flow Patterns" Contractor, Univ of Houston
HADEY, H Research Contracts Branch FIN B-6273 NRC-04-78-213 80/12/15 1p 07443 328

--8101100325 Mod 3, extending period of performance to 8/80, to "Gas-Liquid Flow Patterns"
NORRIS, J J Houston, Univ of MORTON, K V Research Contracts Branch FIN B-6273 NRC-04-78-213 80/12/15 2pp

8101100392 Notification of contract execution, Mod 3 to "Nuclear Facilities in Warst & Other Areas Susceptible to Ground Collapse" Contractor Dept of Army
GUSTAVE, R P Research Contracts Branch B-10869 NRC-01-77-070 80/12/15 1p 03886 330

--8101100399 Mod 3, extending period of performance to 8/80, to "Nuclear Facilities in Warst & Other Areas Susceptible to Ground Collapse"
GUSTAVE, R P Research Contracts Branch B-10869 NRC-01-77-070 80/12/15 1p 03886 331

8101100347 Notification of contract execution, Mod 15 to "Operate Document Control Sys." Contractor TERA Advanced Svcs Corp
SCHLOSSER, L A Contract Policy Branch NRC-10-78-500 80/12/31 1p 07454 148

--8101100355 Mod 15, increasing funds to "Implement & Operate Document Control Sys."
* TERA Corp. LEBO, C D Administrative Contracts Branch NRC-10-78-500 80/12/31 2pp 07454 149

8101140367 Notification of contract execution, Mod 5 to "Bus Svc" Contractor Beltway Limousine Svc, Inc
MARTIN, L C Technical Assistance Contracts Branch
80/12/31 1p 07458 142

--8101140375 Mod 5, deobligating funds & completing closeout of "Bus Svc"
ROBERTSON, J Q Beltway Limousine Service, Inc LEBO, C D Administrative Contracts Branch NRC-10-78-415 80/12/31 1p 07458 143

B101140792 Notification of contract execution.Mod 6 to 'FLECHT SEASET " Contractor Westinghouse & EPRI
 HOLLEY, S Research Contracts Branch FIN B-6204 NRC-04-77-127
 80/12/29 1p 07461 113

--B101140776 Mod 6,adding incremental funds.to "FLECHT SEASET " FARRAR, A O Electric Power Research Institute TAYLOR, J J Westinghouse Electric Corp MORTON, K V Research Contracts Branch FIN B-6204 NRC-04-77-127 80/12/29 2pp 07461 114

B101140805 Notification of contract execution.Mod 6 to 'Consulting on Foreign Countries' Code Development Programs ' Contractor PS Andersen
 HOLLEY, S Research Contracts Branch FIN B-6300 NRC-04-79-177
 80/12/18 1p 07461 097

--B101140813 Mod 6,correcting scope of work, to "Consulting on Foreign Countries' Code Development Programs " ANDERSEN, P B P B Andersen, MORTON, K V Research Contracts Branch FIN B-6300 NRC-04-79-177 80/12/18 2pp 07461 098

B101140835 Notification of contract execution.Mod 1 to 'Behavioral Observation Program to Assure Continued Reliability of Employees' Contractor Personnel Decisions, Inc
 GUSTAVE, R P Research Contracts Branch FIN B-10829 NRC-01-79-003 80/12/12 1p 07461 030

--B101140843 Mod 1,extending period of performance to 801208 w/no increase in cost, to "Behavioral Observation Program to Assure Continued Reliability of Employees " MEYER, P Personnel Decisions, Inc MORTON, K V Research Contracts Branch FIN B-10829 NRC-01-79-003 80/12/12 1p 07461 031

B101150039 Notification of contract execution.Mod 1 to 'Study of US Nuclear Health & Safety Info Dissemination to Foreign Countries " Contractor Franklin Inst
 MEDRICH, L A Administrative Contracts Branch NRC-08-80-338
 80/12/24 1p 07462 179

--B101150045 Mod 1,extending period of performance & time of delivery to "Study of US Nuclear Health & Safety Info Dissemination to Foreign Countries " LOVEACE, R F Franklin Institute/Franklin Research Center LEBOW, C D Administrative Contracts Branch NRC-08-80-338 80/12/24 2pp 07462 180

B101150120 Notification of contract execution.Mod 12 to 'Consulting Svcs (A-E) Re Evaluation of Facilities Concepts, Cost Estimates & Schedules For Experimental Facilities ' Contractor Burns & Roe, Inc
 BROMBERG, D Research Contracts Branch NRC-04-77-097 80/12/22 1p 07462 188

--B101150127 Mod 12,changing date in work directive 7,scope of work, estimated period of performance, to 801230 to, "Consulting Svcs (A-E) Re Evaluation of Facilities Concepts, Cost Estimates & Schedules For Experimental Facilities " PUCILLO, A C Burns & Roe Co MORTON, K V Research Contracts Branch NRC-04-77-097 80/12/22 1p 07462 189

B101150205 Notification of contract execution.Mod 7 to 'Tornado Parameters for Nuclear Power Plants " Contractor Univ of Chicago
 HAGEY, H Research Contracts Branch FIN A-4059 NRC-04-74-239
 80/12/31 1p 07462 169

--B101150210 Mod 7,extending period of performance & increasing funds to "Tornado Parameters for Nuclear Power Plants " BIAL, D B Chicago, Univ of MORTON, K V Research Contracts Branch FIN A-4059 NRC-04-74-239 80/12/31 4pp 07462 170

B101150217 Notification of contract execution.Mod 6 to "Extreme Max/Min Temp Analysis." Contractor US Dept of Commerce
 GUSTAVE, R P Research Contracts Branch FIN B-10318 NRC-01-76-340 80/12/24 1p 07465 338

--B101150223 Mod 6,extending completion date to 810331 w/no cost extension to, "Extreme Max/Min Temp Analysis " MITCHELL, D B Commerce, Dept of MORTON, K V Research Contracts Branch FIN B-10318 NRC-01-76-340 80/12/24 1p 07465 339

B101150229 Notification of contract execution.Mod 3 to "Extreme Snow Loads for the Great Lake States " Contractor US Dept of Commerce
 GUSTAVE, R P Research Contracts Branch FIN B-10807 NRC-01-77-109 80/12/24 1p 07465 343

--B101150237 Mod 3,extending completion date to 810331 w/no cost to, "Extreme Snow Loads for Great Lake States " MITCHELL, D B Commerce, Dept of MORTON, K V Research Contracts Branch FIN B-10807 NRC-01-77-109 80/12/24 1p 07465 344

B101150286 Notification of contract execution.Mod 3 to "Side for Psychological Assessment of Security Personnel " Contractor Assessment Designs, Inc
 GUSTAVE, R P Research Contracts Branch FIN B-1083 NRC-01-79-004 80/12/29 1p 07466 004

--B101150328 Mod 3,extending period of performance to 801231 at no cost to, 'Side for Psychological Assessment of Security Personnel ' FRANK, F D Assessment Designs, Inc FIN B-1063 NRC-01-79-004 80/12/29 1p 07466 005

B101160071 Mod 1,extending period of performance to 810930 w/no add'l funding required
 * Navy, Dept of, Naval Research Laboratory MATTIA, M J Administrative Contracts Branch NRC-03-80-123 80/12/30 1p 07469 302

B101160380 Notification of contract execution.Mod 12 to 'Review & Evaluation of Approx 500 Pending Operating Reactors Licensing Actions " Contractor Franklin Inst
 HAIRSTON, C J GLADOLA, A F Technical Assistance Contracts Branch FIN B-7539 NRC-03-79-118 80/12/23 1p 07469 303

B101160091 Notification of contract execution.Mod 2 to 'Technical Assistance Assessment of Repository Siting & Design " Contractor US Bureau of Mines
 HAIRSTON, C J FIELDS, J Technical Assistance Contracts Branch FIN B-6934-1 NRC-02-80-075 80/12/24 1p 07469 304

B101160105 Notification of contract execution.Mod 5 to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt " Contractor Nuclear Svcs Corp
 HAIRSTON, C J SMITH, P A Technical Assistance Contracts Branch NRC-02-77-201-1 81/01/08 1p 07469 323

--B101160111 Mod 5,extending period of performance one add'l yr to 8110 to, "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt " * Nuclear Services Corp MATTIA, M J Administrative Contracts Branch NRC-02-77-201-1 81/01/08 3pp 07469 324

B101190154 Response to FOIA request for documents re six categories of written communications between NRC & Human Factors Research, Inc, Lifespring Corp, or Lifespring Foundation forwards documents listed in App A
 FELTON, J M, Division of Rules and Records 81/01/09 2pp 07475 204

--B101190167 Confirms verbal request for ltr of credit financing for Contract NRC-04-81-186 issued to Human Factors Soc Type 1a cost (no-fee) contract, w/13-month performance period
 MORTON, K V Research Contracts Branch FIN B-7229 NRC-04-81-186 80/12/11 1p

B101200426 Notification of contract execution, "Bioassay Procedures for Promethium-147," awarded to Univ of FL
 HOYLE, A E Administrative Contracts Branch FIN B-7110 NRC-01-81-004 81/01/08 1p 07487 039

--B101200432 Contract "Bioassay Procedures for Promethium-147," awarded to Univ of FL
 RANDAZZO, A F Florida, Univ of Gainesville PERLMAN, J Administrative Contracts Branch FIN B-7110 NRC-01-81-004 81/01/08 6pp 07487 040

B101200455 Notification of contract execution.Mod 1 to "Technical Assistance to NRC in Area of Reactor Vessel Irradiation Damage " Contractor Naval Research Lab
 HAIRSTON, C J GLADOLA, A F Technical Assistance Contracts Branch FIN B-6807 NRC-03-80-123 80/12/30 1p 07487 117

B101200465 Notification of contract execution.Mod 5 to 'Seismic Zoning Map for Siting Nuclear Electric Power Generating Facilities in Eastern US " Contractor Rondout Associates, Inc
 HAIRSTON, C A J SMITH, P A Technical Assistance Contracts Branch NRC-03-78-154 80/12/02 1p 07487 119

--B101200473 Mod 5,increasing funds, to "Seismic Zoning Map for Siting Nuclear Electric Power Generating Facilities in Eastern US." POMEROY, P W Rondout Associates DRUOHERTY, D J Technical Assistance Contracts Branch NRC-03-78-154 80/12/02 1p 07487 120

B010200471 Notification of contract execution, Mod 2 to "Table B-3 Rulemaking Expert Testimony - Contractor Science Applications, Inc PERLMAN, J Administrative Contracts Branch FIN B-6360 NRC-02-78-026 01/01/02 1p 07487 121

--B010200480 Mod 2, closing out contract & deobligating balance to "Table B-3 Rulemaking Expert Testimony - Contractor Science Applications, Inc PERLMAN, J Administrative Contracts Branch FIN B-6360 NRC-02-78-026 01/01/02 1p 07487 122

B010200484 Mod 2, increasing funds, to "Technical Assistance for Assessment of Repository, Siting & Design - Interior, Dept of Mines MATTHEW M J Administrative Contracts Branch FIN B-6934-1 NRC-02-80-075 00/12/24 1p 07487 123

B010200487 Notification of contract execution, Mod 10 to "Technical Assistance in Reviewing Original Seismic Design Bases & Design Bases for Operating Plants," Contractor NM Neumann, Consulting Engineering Svcs GLACIELA A. HAIRSTON, C Technical Assistance Contracts Branch FIN B-1168 NRC-03-78-190 00/12/22 1p 07487 124

--B010200498 Mod 10, increasing funds & modifying authorized representative to "Technical Assistance in Reviewing Original Seismic Design Bases & Design Bases for Operating Plants," EMMARK, H M Neumann Consulting Engineering Services MATTHEW M J Administrative Contracts Branch FIN B-1168 NRC-03-78-190 00/12/22 1p 07487 125

B010200022 Notification of contract execution, Mod 6 to "Mobile Lab - Contractor Mobile Sys WIGGINS, E Administrative Contracts Branch FIN B-1014 NRC-05-79-257 01/01/12 1p 07489 298

--B010200027 Mod 6, de-obligating remaining balance to, "Mobile Lab - KIMMEL, J J Mobile Systems MATTHEW M J Administrative Contracts Branch FIN B-1014 NRC-05-79-257 01/01/12 1p 07489 299

B010200037 Notification of contract execution, Mod 2 to "Emergency Procedures Criteria for Nuclear Power Plant Operations - Contractor XYZYX Info Corp HAIRSTON, C YEYBER, J Technical Assistance Contracts Branch FIN B-6872 NRC-03-80-118 00/12/31 1p 07489 300

B010200294 Mod 5, extending period of performance for addl yr, to "Basic Ordering Agreement to Develop Regulatory Framework for Nuclear Waste Mgt - STAGGS, D O Dames & Moore MATTHEW M J Administrative Contracts Branch NRC-02-77-201-20 00/12/24 5pp 07493 083

B010200374 Notification of contract execution, Mod 10 to "Geophysical Investigation of Anna, Ok Earthquake Region - Contractor Univ of MI JACOBS, A Research Contracts Branch, FIN B-5545 NRC-04-76-192 00/12/30 1p 07493 094

--B010200378 Mod 10, modifying Article 111, Govt Property, to "Geophysical Investigation of Anna, Ok Earthquake Region - MATHEWS, C W Michigan, Univ of MORTON, K V Research Contracts Branch, FIN B-5545 NRC-04-76-192 00/12/30 3pp 07493 095

B010200381 Notification of contract execution, "Foreign Research & Licensing Practice Coordinator for General Reactor Safety Research," awarded to Structural Mechanics Associates BAIDEN, L Research Contracts Branch FIN B-6769 NRC-04-81-175 00/12/31 1p 07493 098

--B010200391 Contract "Foreign Research & Licensing Practice Coordinator for General Reactor Safety Research," awarded to Structural Mechanics Associates STEVENSON, J D Structural Mechanics Associates BORTON, K V Research Contracts Branch FIN B-6769 NRC-04-81-175 00/12/31 9pp 07493 099

B010200553 Mod 2, to include Task 2 to "Emergency Procedures Criteria for Nuclear Power Plant Operations - GOLD, R L XYZYX Information Corp, DOUGHERTY, D J Technical Assistance Contracts Branch FIN B-6872 NRC-03-80-118 00/12/31 6pp 07489 030

B010200560 Mod 3, extending & increasing funds, to "Engineering Assistance in Connection W/ Antitrust Hearings - MOZER, H M Ch2m Hill, Inc, DOUGHERTY, D J Technical Assistance Contracts Branch NRC-03-78-127-09 01/01/06 2pp 07488 008

B010200572 Notification of contract execution, Mod 2 to "Licensing Technical Assistance - Contractor Science Applications, Inc HAIRSTON, C EDGEMORTH, P J Technical Assistance Contracts Branch NRC-02-80-035-003 00/12/24 1p 07480 010

--B010200578 Mod 2, extending period of performance to B010320 to "Licensing Technical Assistance - Science Applications, Inc MATTHEW M J Administrative Contracts Branch NRC-02-80-035-0003 00/12/24 1p 07400 011

B010207027 Mod 3, extending contract from B01231 to B01013 & increasing funds to, "Vol Reduction Techniques in Low Level Radwaste Mgt - CDHEHS Teknekon Research, Inc MATTHEW M J Administrative Contracts Branch B-6413-1 NRC-02-79-024 00/12/31 2pp 07549 134

B010207034 Notification of contract execution, "Conduct Hearing Re Employee Grievance Under Agency Grievance Procedure & Provide Recommendation for Action by Reviewing Official in Resolving Grievance," awarded to AH Mallor FLYNN, M J Administrative Contracts Branch NRC-10-80-392 01/01/12 1p 07549 139

--B010207041 Contract "Conduct Hearing re Employee Grievance Under Agency Grievance Procedure & Provide Recommendation for Action by Reviewing Official in Resolving Grievance," MALLOR, A J Affiliation Unknown, PERLMAN, J Administrative Contracts Branch NRC-10-81-393 01/01/21 7pp 07549 140

B010207066 Notification of contract execution, Mod 1 to "Computer Support of Info Requirements Control Automated Sys," awarded to Dept of Defense FLYNN, M J Administrative Contracts Branch NRC-10-80-392 01/01/13 1p 07549 136

--B010207082 Mod 1, extending period of performance for 1 yr & increasing total funding to, "Computer Svcs in Support of Info Requirements Control Automated Sys - SCOTT, W S Defense, Dept of, Defense Nuclear Agency LEBO, C D Administrative Contracts Branch, NRC-10-80-392 01/01/13 2p 07549 137

B010280440 Responds to FOIA request for Task 2 rept & monthly progress reports submitted by NUSAC, Inc under NRC-02-80-024, "Development of Advanced Matl Accounting Sys Simulation Model - Forwards nonproprietary versions of repts FELTON, J H Division of Rules and Records, 01/01/16 1p 07558 083

--B010280451 Forwards nonproprietary version of Revision 1 to Task 2 draft technical rept, "Mathematical Derivation of Advanced Matl Accounting Sys Simulation (AMASS) Model," prepared under NRC-02-80-024 PEVENSTEIN, J E NUSAC, Inc NRC-5.1 00/10/24 1p

--B010280455 591 Nonproprietary version of Task 2 draft technical rept, "Mathematical Derivation of Advanced Matl Accounting Sys Simulation (AMASS) Model," NUSAC, Inc NRC-02-80-024 00/10/30 33pp

--B010280459 Submits nonproprietary version of monthly progress rept NRC-02-80-024, "Development of Advanced Matl Accounting Sys Simulation Model - AMASS mathematical methodology is under development PEVENSTEIN, J E NUSAC, Inc NRC-02-80-024 00/08/18 3pp

--B010280464 Submits nonproprietary version of addendum to monthly progress rept for NRC-02-80-024, "Development of Advanced Matl Accounting Sys Simulation Model - Addl info concerns BOOBOS meeting to discuss results of Task 1. PEVENSTEIN, J E NUSAC, Inc NRC-02-80-024 00/08/21 1p

--B010280469 Submits nonproprietary version of monthly progress rept NRC-02-80-024, "Development of Advanced Matl Accounting Sys Simulation Model," for BOOBOS-0908 includes work performed, personnel time expenditures & costs. PEVENSTEIN, J E NUSAC, Inc NRC-02-80-024 00/09/19 2pp

--B010280474 Submits nonproprietary version of monthly progress rept NRC-02-80-024, "Development of Advanced Matl Accounting Sys Simulation Model," for BOOBOS-0910 includes work performed, personnel time expenditures & costs. PEVENSTEIN, J E NUSAC, Inc NRC-02-80-024 00/10/15 3pp

--B010280478 Submits nonproprietary version of monthly progress rept NRC-02-80-024, "Development of Advanced Matl Accounting Sys Simulation Model," for B01011-1110 includes work performed, administrative matters & costs. PEVENSTEIN, J E NUSAC, Inc NRC-02-80-024 00/11/15 3pp

01280447 FOIA request for Task 2 rept & monthly progress repts submitted by NUSAC, Inc under NRC-02-80-024. "Development of Advanced Matl Accounting Sys Simulation Model " FINDLEY, D E Science Applications, Inc 80/12/16 1p 07558 086

01290096 Notification of contract execution "Evaluation of NRC Executive Development & Mgt Program," awarded to Project Associates, Inc COLEMAN, R Administrative Contracts Branch NRC-10-81-356 81/01/16 1p 07309 001

0101290105 Contract "Evaluation of NRC Executive Development & Mgt Program," awarded to Project Associates, Inc QIBSEN, R S Project Associates LEBD, C D Administrative Contracts Branch NRC-10-81-356 81/01/16 38pp 07309 001

01290337 Notification of contract execution "Consultant to LCFT Special Review Group," awarded to Aerospace Corp LITTLE, M Administrative Contracts Branch FIN B-7490 NRC-04-81-197 80/12/29 1p 07570 264

0101290341 Contract "Consultant to LCFT Special Review Group," awarded to Aerospace Corp GULVER, C M Aerospace Corp PERLMAN, J Administrative Contracts Branch FIN B-7490 NRC-04-81-197 80/12/29 3pp 07570 265

01290525 Notification of contract execution, Mod 3 to "Engineering Assistance in Connection w/Antitrust Hearings " Contractor CH2M Hill GLAODLA, A F, HAIRSTON, C Technical Assistance Contracts Branch NRC-03-78-127-09 81/01/06 1p 07575 252

01290794 Notification of contract execution, Mod 2 to "Environ Monitoring Program w/Commonwealth of VA " Contractor Commonwealth of VA BAIBDEN, L Research Contracts Branch FIN B-5116 NRC-05-80-277 81/01/26 1p 07568 037

0101290798 Mod 2, providing funding for CYBI effort, to "Environ Monitoring Program w/Commonwealth of VA " * Virginia, State of MORTON, K V Research Contracts Branch FIN B-5116 NRC-05-80-277 81/01/01 1p 07568 038

01300069 Notification of contract execution, Mod 1 to "Environ Monitoring Program w/State of MN " Contractor State of MN. BAIBDEN, L Research Contracts Branch FIN B-1252 NRC-05-80-289 81/01/26 1p 07583 031

0101300075 Mod 1, providing funding for CYBI effort to "Environ Monitoring Program w/State of MN " * Minnesota, State of MORTON, K V Research Contracts Branch FIN B-1252 NRC-05-80-289 81/01/26 1p 07583 032

01300086 Notification of contract execution, Mod 3 to "Environ Monitoring Program w/Commonwealth of PA " Contractor Commonwealth of PA. BAIBDEN, L Research Contracts Branch FIN B-5111 NRC-05-80-272 81/01/26 1p 07583 075

0101300093 Mod 3, providing funding for CYBI effort to "Environ Monitoring Program w/Commonwealth of PA " * Pennsylvania, State of MORTON, K V Research Contracts Branch. FIN B-5111 NRC-05-80-272 81/01/26 1p 07583 076

01300183 Notification of contract execution, Mod 2 to "Environ Monitoring Program w/State of WI " Contractor State of WI. BAIBDEN, L Research Contracts Branch. FIN B-5114 NRC-05-80-275 81/01/26 1p 07580 353

0101300187 Mod 2, providing funding for CYBI effort, to "Environ Monitoring Program w/State of WI " * Wisconsin, State of MORTON, K V Research Contracts Branch FIN B-5114 NRC-05-80-275 81/01/26 1p 07580 354

01300285 Notification of contract execution, Mod 5 to "Sys Analysis of Shallow Land Burial " Contractor Science Applications, Inc. HAIRSTON, C, EDGEWORTH, P Technical Assistance Contracts Branch. NRC-02-79-032 80/12/26 1p 07587 006

0101300291 Mod 5, extending period of performance, to "Sys Analysis of Shallow Land Burial." * Science Applications, Inc MATTIA, M J Technical Assistance Contracts Branch NRC-02-79-032 80/12/26 1p 07587 007

01300300 Notification of contract execution, Mod 5 to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt." Contractor Dames & Moore HAIRSTON, C, SMITH, P Technical Assistance Contracts Branch NRC-02-77-201-20 80/12/24 1p 07586 227

8101300307 Notification of contract execution, Mod 1 to "Licensing Review of CL Applications " Contractor Naval Surface Weapons Ctr HAIRSTON, C, EDGEWORTH, P Technical Assistance Contracts Branch FIN B-6978 NRC-03-80-104 80/12/22 1p 07587 003

8101300312 Notification of contract execution, Mod 2 to "Environ Monitoring Program w/State of NY " Contractor State of NY. BAIBDEN, L Research Contracts Branch FIN B-5109 NRC-05-80-271 81/01/26 1p 07587 039

--8101300316 Mod 2, providing funding for CYBI effort, to "Environ Monitoring Program w/State of NY " * New York, State of MORTON, K V Research Contracts Branch FIN B-5109 NRC-05-80-271 81/01/26 1p 07587 010

8101300320 Notification of contract execution, Mod 1 to "Environ Monitoring Program w/State of MS " Contractor State of MS. BAIBDEN, L Research Contracts Branch FIN B-1257 NRC-05-80-289 81/01/26 1p 07587 025

--8101300325 Mod 1, providing funding for CYBI effort, to "Environ Monitoring Program w/State of MS " * Michigan, State of MORTON, K V Research Contracts Branch FIN B-1257 NRC-05-80-289 81/01/26 1p 07587 026

8101300332 Notification of contract execution, Mod 3 to "Statistical Analysis Study " Contractor SL Wolflein. FLYNN, M J Administrative Contracts Branch NRC-10-80-694 81/01/12 1p 07587 023

--8101300337 Mod 3, extending period of performance, to "Statistical Analysis Study " * Wolflein, S L LEBD, C D Administrative Contracts Branch. NRC-10-80-694 81/01/12 1p 07587 024

8101300344 Notification of contract execution, Mod 2 to "Environ Monitoring Program w/State of MD " Contractor State of MD. BAIBDEN, L Research Contracts Branch FIN B-5106 NRC-05-80-269 81/01/26 1p 07585 254

--8101300349 Mod 2, providing funding for CYBI effort, to "Environ Monitoring Program w/State of MD " * Maryland, State of MORTON, K V Research Contracts Branch FIN B-5106 NRC-05-80-269 81/01/26 1p 07585 255

8101300359 Notification of contract execution, Mod 2 to "Environ Monitoring Program w/State of CO " Contractor State of CO. BAIBDEN, L Research Contracts Branch FIN B-5104 NRC-05-80-267 81/01/26 1p 07587 051

--8101300365 Mod 2, providing funding for CYBI effort, to "Environ Monitoring Program w/State of CO " * Colorado, State of MORTON, K V Research Contracts Branch FIN B-5104 NRC-05-80-267 81/01/26 1p 07587 052

8101300372 Notification of contract execution, Mod 2 to "Environ Monitoring Program w/State of ME " Contractor State of ME. BAIBDEN, L Research Contracts Branch FIN B-5113 NRC-05-80-274 81/01/26 1p 07587 054

--8101300381 Mod 2, providing funding for CYBI effort, to "Environ Monitoring Program w/State of ME " * Maine, State of MORTON, K V Research Contracts Branch FIN B-5113 NRC-05-80-274 81/01/26 1p 07587 055

8101300378 Notification of contract execution, Mod 1 to "Environ Monitoring Program w/State of DE " Contractor State of DE. BAIBDEN, L Research Contracts Branch FIN B-1260 NRC-05-80-291 81/01/26 1p 07587 056

--8101300406 Mod 1, providing funding for CYBI effort, to "Environ Monitoring Program w/State of DE " * Delaware, State of MORTON, K V Research Contracts Branch FIN B-1260 NRC-05-80-291 81/01/26 1p 07587 057

DISCLOSURE FINANCIAL DISCLOSURE INFORMATION

8101090700 Informs that exemption is granted from requirements of 10CFR 735-21 Recipient may participate in matters affecting Sandia Recipient possesses vested interest in Sandia pension plan, but cannot influence amount received. SEYFRIT, K V Region 4, Dallas, Office of the Director. 80/12/08 1p 07442 049

9004250139 Submits comments on Ofc of Mgt & Program Analysis review of Commission paper re enforcement program. Proposed policy presents more aggressive enforcement program but does not address timing, regional delegation or enforceability
STELLID, V. Office of Inspection & Enforcement, Office of the Director 80/03/18 6pp 02564 23M.

--80034250144 Requests review of Ofc of Mgt & Program Analysis comments on Commission paper re enforcement program by 800318 Info should include estimates impacts of sanctions, addl resources needed & ability to delegate enforcement to regions
DIREK, W. J. Office of the Executive Director for Operations, 80/03/14, 1p. 02564 244

80036030653 Forwards comments re 800220 proposed IE Commission paper Supports objective to publish comprehensive enforcement policy & program defining levels of severity. Paper requires addl work prior to issuance for public comment
MILKOW, E. B. Office of Standards Development, Director 80/02/27 3pp 02680 017

8007250359 Comments on revised NRC enforcement policy in response to 800630 memo Causes of equipment failure for which citations are not issued does not include failure
BUSH, L. L. Division of Safeguards Inspections 80/07/09 1p. 03063 206

--8007250362 Requests comments on revised NRC enforcement policy by 800709
THOMPSON, D. Executive Officer for Operations Support 80/06/30 1p 03063 207

--8007250364 Forwards marked up copy of revised NRC enforcement policy Comments requested by 800714
STELLID, V. Office of Inspection & Enforcement, Office of the Director 80/06/30 3pp. 03063 208

8009120018 Advises that comments re revised NRC enforcement policy were previously in form of marked up copy. No further comments.
MUSELEV, N. C. Division of Reactor Operations Inspections 80/07/16 1p 03526 030

8009120327 Forwards comments re revised NRC enforcement policy
SHIELEK, J. H. Division of Fuel Facility & Materials Safety 80/07/14 4pp. 03526 021

8009120328 Forwards comments on draft Commission paper re NRC enforcement program. No addl comments will be submitted
SHIELEK, J. H. Division of Fuel Facility & Materials Safety, 80/06/26 4pp 03525 080

8010100204 Forwards 10CFR2, "Proposed General Statement of Policy & Procedure for Enforcement Actions," for transmittal to Ofc of FR for publication w/90-day public comment period.
THOMPSON, D. Executive Officer for Operations Support 80/10/01 1p 03629 220

--8010100210 "Proposed General Statement of Policy & Procedure for Enforcement Actions," 10CFR2 informs licensees & public of basis for taking various enforcement actions. Comments due by 801231. Suppls encl
STELLID, V. Office of Inspection & Enforcement, Office of the Director 80/10/01 47pp 03629 222.

8011070114 Forwards revised proposed general statement of policy & procedure for enforcement actions. Commission should seek concurrence in first few cases in which application of reduction of civil penalties for "good faith" is used.
STELLID, V. Office of Inspection & Enforcement, Office of the Director 80/04/23 50pp 03714 156.

--8011070118 Summarizes 800904 discussion & vote on general statement of enforcement policy & Commission requests
CHILK, S. J. Office of the Secretary of the Commission 80/09/10 2pp 03714 206

8012050060 FOIA request for nine categories of info re Fees concerning withdrawn, suspended or postponed applications
SILBER, J. E. Shaw, Pittman, Potts & Trowbridge 80/10/30 3pp 07204 127

8012100023 "List of Withdrawn & Announced Cancellations, Suspensions or Infinite Postponements Beginning 780323."
* Commissioners 80/11/21, 4pp.

--8012100252 Forwards 511 cases in which CP applications have been withdrawn, denied or abandoned by licensee & ltr to Philadelphia Electric Co notifying of fees based on manpower expended
MILLER, W. G. License Fee Management Branch 79/12/04 1p

--8012100400 Forwards FR notice re fees for review of applications ltr to appropriate Congressional committees w/a encl ltr
SHAPAR, H. K. Office of the Executive Legal Director 80/10/1p

--8012100402 Notice of proposed rule to clarify fees for review of applications. Related documentation encl.
CHILK, S. J. Office of the Secretary of the Commission 80/10/9pp.

8012180267 App C to 800530 ltr listing noncompliances to rept del includes noncompliance criterion, rept section ref & rept page number
* Commissioners 80/05/30 1p.

801060652 Responds to FOIA request for listing of people &/or companies licensed by NRC to use radioactive matl & state agencies & addresses for Agreement States which issue licenses. Forwards computer printout w/a encl
FELTON, J. M. Division of Rules and Records 80/12/24 1p 07399 360.

801060626 FOIA request for listing of people &/or companies licensed by NRC to use radioactive matl & state agencies & addresses for Agreement States which issue licenses to companies
RUSIECKI, G. Axon Industries Services, Inc 80/12/03 1p 07399 361.

801060724 Responds to FOIA request for various categories of info re use, mpq & sales of cobalt between 1946 & 1958. Forwards documents listed in App A Home telephone numbers withheld (ref FOIA Exemption 6)
FELTON, J. M. Division of Rules and Records 80/12/22 3pp 07400 098

--801060736 Notifies that all authorizations for radioisotope procurement will expire in 90 days. Requests submittal of application for all byproduct matl or stored waste w/o instructions, application forms & regulations
AEBERGLD, P. C. Atomic Energy Commission 1EB:29 57/01/01

--801060742 Forwards application for matl/byproduct license
MARTIN, W. F. Sun Shipbuilding & Dry Dock Co. (subs. Sun Co. 97/04/16 1p

--801060752 Application for matl/byproduct license authorizing use to use &/or supervise use of four sources of 400 mCi Co-60 in metal to be used as source of radiation for radiographic exam. Home telephone numbers withheld (ref FOIA Exemption 6)
* Sun Shipbuilding & Dry Dock Co. (subs. Sun Co., Inc.) 57/04/15, 9pp

--801060759 Matl/Byproduct License 37-02900-01 for Sun Ship Bldg Dock Co. authorizing possession & use of four sources of 400 mCi Co-60 in metal to be used as source of radiation for radiographic exams of weldments, castings & forgings.
* Atomic Energy Commission 57/04/25, 2pp.

--801060766 Requests act of ltr & advisement as to whether new Co sources may be purchased by authority of License 37-02900-01 or whether new authorization is warranted. Inquires whether spent sources should be returned to original vendor.
BOETTGER, C. S. Sun Shipbuilding & Dry Dock Co. (subs. Sun Co. Inc.) 58/08/26, 2pp.

--801060775 Responds to 580826 ltr re replacement of four sources Co-60 under License 37-02900-01. Co-60 sources are no longer available from ORNL. New matl/byproduct license application should be submitted. New vendor will dispose spent sources
MILLER, W. G. Atomic Energy Commission 58/09/12, 1p.

801060730 FOIA request for various categories of info re use, mpq sales of cobalt between 1946 & 1958
KANN, J. R. Blank, Rose, Comisky & McCauley 80/11/24, 3pp. 07400 101.

801070004 Responds to FOIA request for four categories of documents cold shutdown w/regard to fire protection requirements in App R to 10CFR50. Forwards D Davis 790614 memo & P Matthews/J Knight memo re 790228 review group meeting.
FELTON, J. M. Division of Rules and Records 80/12/30, 1p 07414 182

--B101070012 Discusses requirements for achieving cold shutdown of SEP plants Lists shutdown & coldown criteria developed in ongoing fire protection review SEP position for plant coldown capabilities encl
DAVIS, D K Systematic Evaluation Program Branch (Pre 791030)
79/06/14 4pp

B101070008 FOIA request for four categories of documents re cold shutdown w/regard to fire protection requirements in App R to 10CFR50
STEINMETZ, J D Edison Electric Institute 80/12/12 2pp
07414 183

B101070022 FOIA request for seven categories of NRC documents
MADDEN, T J Kaye, Scholer, Fierman, Hays & Handler 80/10/16 3pp.
07414 187

B101070026 Responds to FOIA request for all documents discussing or identifying alternatives to fire protection requirements of App R to 10CFR50 Documents are available in PDR.
FELTON, J M Division of Rules and Records 80/12/31 1p
07414 189

B101070028 FOIA request for all documents discussing or identifying alternatives to fire protection requirements of App R to 10CFR50.
WATKINS, M Debevoise & Liberman 80/12/12 2pp 07414 190.

B101070034 Responds to FOIA request for winning proposal awarded under RFP RS-NHS-B1-032, "Technical Support for Confidence Rulemaking Proceeding" Contract has not yet been awarded
FELTON, J M Division of Rules and Records 80/12/30 1p
07414 192.

B101070040 FOIA request for winning technical proposal awarded under RFP RS-NHS-B1-032, "Technical Support for Confidence Rulemaking Proceeding"
RUTHERFORD, J F BDM Corp BDM/W-JFR-0738 80/12/12 1p
07414 193

B101070046 Responds to FOIA request for addresses of Ohmart Corp. Inc. US Radium Corp. AECL & Central Scientific Labs Forwards list of addresses. Central Scientific Labs is not NRC licensee, therefore, no address is available.
FELTON, J M Division of Rules and Records 80/12/31 1p
07414 194.

--B101070053 List of addresses for Ohmart Corp. Inc. US Radium Corp. AECL & Central Scientific Labs
* Commissioners 80/12/31 1p 07414 195

B101070049 FOIA request for addresses of Ohmart Corp. Inc. US Radium Corp. AECL & Central Scientific Labs
LAUDIG, B 80/08/25 1p 07414 196

B101070059 Responds to FOIA request for six categories of info re fire protection requirements in App R to 10CFR50 Encl PR Matthews draft memo is responsive to request & will be placed in PDR
FELTON, J M Division of Rules and Records 80/12/30 1p
07414 197

--B101070070 Summary of 790228 fire protection review group meeting to discuss differences in fire protection measures accepted by Div of Sys Safety & Div of Operating Reactors to protect redundant div of sys necessary for safe hot shutdown
MATTHEWS, P R Auxiliary Systems Branch KNIGHT, J Assistant Director for Engineering 79/03/14 18pp.

B101070076 Addl response to FOIA request for info re spent nuclear fuel transportation routes. Forwards final version of NUREG-0725 & list of transfers of spent fuel into, out of, or through State of CA W/o encl NUREG-0725.
FELTON, J M Division of Rules and Records 80/12/29 1p.
07414 200

--B101070080 Listing of transfers of spent fuel into, out of, or through State of CA during 790101-801031
* Commissioners 80/12/29 2pp 07414 203

B101070086 Responds to FOIA request for documents re BECY-80-409, "Proposed Rulemaking to Amend 10CFR50 Concerning ATWS Events" NRC will provide all ATWS documentation & list of any which may be withheld.
FELTON, J M Division of Rules and Records 80/12/31 3pp
07414 205

B101070091 FOIA request for documents re BECY-80-409, "Proposed Rulemaking to Amend 10CFR50 Concerning ATWS Events"
EARLEY, A F Hutton & Williams 80/11/25 19pp 07414 208

B101090137 Forwards draft IE bulletin entitled, "Performance of Licensed Operators at Controls of Reactors" & draft ltr to all holders of operator or senior operator licenses re performance while on duty at controls of nuclear reactor
KEPPLER, J G Region 3, Chicago, Office of the Director 80/07/2pp

--B101090190 Discusses IE policies for reporting, evaluating & doing significant safety matters, in light of incident at facility. Consideration of safety significance always precedes noncompliance in evaluating any concern Related info encl
STELLID, V Office of Inspection & Enforcement, Office of the Director 80/10/01 4pp

--B101090163 Forwards Ofc of Nuclear Reactor Regulation & Ofc of Development comments on draft Commission paper, "NRC Enforcement Program" IE draft notification of significant enforcement action encl
URVAN, S E Division of Reactor Operations Inspections EN-80/03/10 2pp

--B101090166 Notification of 800527 meeting in Bethesda, MD to discuss enforcement policy. Limited personnel closely associated w/subj & able to contribute to discussions may attend
DIRKSB, W J Office of the Executive Director for Operations 80/05/23 1p

--B101090169 Act receipt of ltr concerning NRC enforcement policy. Proposed changes to enforcement policy are currently undergoing extensive review & will clarify concerns raised
STELLID, V Office of Inspection & Enforcement, Office of the Director 80/06/05 3pp

--B101090172 Discusses NRC proposed enforcement policy. Increasing emphasis on penalties in enforcement actions will be counterproductive to increasing safety. Recommends greater flexibility in applying penalties
JENSEN, W H Detroit Edison Co 80/05/05 2pp

--B101090179 Requests comments on encl revised NRC enforcement policy 800709
THOMPSON, D Executive Officer for Operations Support 80/06/36pp

--B101090183 Forwards revised NRC enforcement policy Requests review comment
STELLID, V Office of Inspection & Enforcement, Office of the Director 80/06/30 38pp

--B101090188 Forwards draft of revised NRC enforcement policy. Recommendations by 800714 W/o encl
STELLID, V Office of Inspection & Enforcement, Office of the Director 80/07/01 1p

--B101090196 Requests NRC policy statement re resident inspector participation in licensee internal labor relation disputes that result from enforcement action
BRYAN, S E Division of Reactor Operations Inspections 80/06/1p

--B101090202 Notifies that regional public meetings on NRC enforcement policy will be scheduled Requests cooperation
THOMPSON, D Executive Officer for Operations Support 80/06/1p

--B101090213 Discusses use of IE revised enforcement criteria. New enforcement criteria should be invoked when insp or investigation programs disclose serious violations occurring between 800630 & 0904
THOMPSON, D Executive Officer for Operations Support 80/06/1p

B101090298 Partial response to FOIA request for documents re nuclear accident in USSR in 1955 Forwards documents listed in Apps A & B, NRC 1979 Annual Rept, "Outline History of Nuclear Regulation & Licensing, 1946-1979" & 801110 transcript
FELTON, J M Division of Rules and Records 80/12/03 3pp
07442 085

--B101090307 Book review of, "Nuclear Disaster in Urals," published by Press Intelligence, Inc. Newspaper clippings re nuclear disaster encl
PATTERSON, W G Affiliation Unknown 79/07/15 4pp

--B101090318 Transcript of 60 Minutes 801110 television program re nuclear disaster. Pg 1-7
* CBS News, CBS, Inc NRC-0343, 80/11/10 7pp

1150688 FOIA request for nonproprietary version of winning proposal submitted in response to RFP RS-05D-80-019. "Evaluation of Geotechnical Surveillance Techniques for Monitoring High Level Waste Repository Performance" SHANNON & WILSON, INC. 80/12/16 1p 07462 207

1150093 Responds to FOIA request for listing of all bidders responding to RFP RS-05D-01-001. "Evaluation of Util Self-Insurance as Option for Assuring Funds for Decommissioning" FELTON, J.M. Division of Rules and Records 81/01/07 1p 07462 209

1150099 FOIA request for listing of all bidders responding to RFP RS-05D-01-001. "Evaluation of Util Self-Insurance as Option for Assuring Funds for Decommissioning" LEBOEUF, LAM, LEIBY & MACRAE. 80/12/08 1p 07462 209

1150107 Responds to FOIA request for winning proposals submitted under RFP RS-05D-80-012 & RFP RS-05D-80-019 Forwards nonproprietary versions of proposals listed in app FELTON, J.M. Division of Rules and Records 80/12/30 2pp 07462 210

1150127 Nonproprietary response to RFP RS-05D-80-019. "Evaluation of Geotechnical Surveillance Techniques for Monitoring High Level Waste Repository Performance" Describes technical effort, resources, relevant qualifications & subcontractors HOCKING, G., HARDY, M.P., AGAPITO, J.F., J.F.T. Acapito & Associates, Inc. RS-05D-80-019 80/07/09 44pp

1150134 Nonproprietary response to RFP RS-05D-80-019. "Evaluation of Geotechnical Surveillance Techniques for Monitoring High Level Waste Repository Performance" Describes technical effort, available resources & relevant qualifications HOCKING, G., AGAPITO, J.F., HARDY, M.P., J.F.T. Acapito & Associates, Inc. RS-05D-80-019 80/07/07 131pp

1150142 Submits answers to NRC questions & revised cost estimate concerning response to RFP RS-05D-80-012. "Info Needs for Site Characterization Plans" Response constitutes best & final offer WERNER, M. FUORO, INC. RS-05D-80-012 80/07/15 1pp

1150149 Response to RFP RS-05D-80-012. "Info Needs for Site Characterization Plans." Vol 3 Includes scope of work & technical approach, experience w/regulatory sys, support personnel & facilities & potential problem areas FUORO, INC. RS-05D-80-012 80/07/31 176pp

1150110 FOIA request for winning proposals re RFP RS-05D-80-012. "Info Needs for Site Characterization Plans" & RFP RS-05D-80-019. "Evaluation of Geotechnical Surveillance Techniques for Monitoring High Level Waste" FELTON, J.M. Energy Resources Co., Inc. 80/10/24. 1p 07462:212

1190137 Responds to FOIA request for 11 documents Forwards requested documents w/o encls FELTON, J.M. Division of Rules and Records 81/01/09 1p 07475 325

1190142 FOIA request for 11 specific documents DINES, L. Black Hills Alliance. 80/12/12 2pp 07475 326

1190145 Partial response to FOIA request for all documents re correspondence between NRC & T Madden of Kaye, Scholer, Fierman, Hays & Handler Forwards documents listed in App A w/o encls. FELTON, J.M. Division of Rules and Records 81/01/08 2pp 07475 200

1190148 FOIA request for all documents re correspondence between NRC & T Madden of Kaye, Scholer, Fierman, Hays & Handler STEWART, G.B. Davis Polk & Wardwell 80/12/16 9pp 07475 202

1190154 Responds to FOIA request for documents re six categories of written communications between NRC & Human Factors Research, Inc. Lifespring Corp. or Lifespring Foundation Forwards documents listed in App A FELTON, J.M. Division of Rules and Records 81/01/09 2pp 07475 204.

1190167 Confirms verbal request for ltr of credit financing for Contract NRC-04-81-186 issued to Human Factors Soc Type is cost (no-fee) contract, w/13-month performance period MORTON, K.V. Research Contracts Branch FIN B-7239 NRC-04-81-186. 80/12/11. 1p

1190176 Forwards ltr of credit & authorized signature card for payment vouchers on ltr of credit for Human Factors Soc PUGLISE, A.S. Division of Accounting 80/12/31 3pp

1190199 FOIA request for documents re six categories of written communications between NRC & Human Factors Research, Inc. Lifespring Corp. or Lifespring Foundation FINELSTEIN, J. Bergson, Burkland, Margolis & Ailer 80/12/01 3pp 07475 206

1190536 Responds to FOIA request for data re individual shipments of U made 1976-1980 Forwards computer printout of data on U shipments from Jan 1976-April 1980 & listing of current reporting identification symbols w/o encls FELTON, J.M. Division of Rules and Records 81/01/08 1p 07475 353

1190541 FOIA request for data re individual shipments of U made during 1976-1980 CRAIGFORD, W.T. General Electric Co 80/11/17 1p 07475 356

1190548 Responds to FOIA request for listing of all matl concerning areas of nuclear science such as reactor design, const & security, general publications & nuclear weapons program Forwards documents listed in App A w/o encls FELTON, J.M. Division of Rules and Records 81/01/16 2pp 07489 110

1190549 FOIA request for listing of all matl concerning areas of nuclear science such as reactor design, const & security, general publications & nuclear weapons program SHAMMAN, M. Affiliation Unknown: 81/01/05 1p 07489 112

1190554 Partial response to FOIA request for four categories of documents re NRC release of spent fuel routing & other shipment info to public Forwards documents listed in App A Addl documents are undergoing review for release FELTON, J.M. Division of Rules and Records 81/01/15 2pp 07489 113

1190563 Responds to item 7 of 750525 memo re release of info re irradiated fuel shipments Specific details of approved routes, ship maps & shipment notices will be withheld (ref 16CFR2 790) info will be distributed on need-to-know basis DIRKSB, W.J. Office of Nuclear Material Safety & Safeguards 79/08/23 2pp

1190569 Reviews rept re withholding of spent fuel info Disagrees w/recommendation Alternative 3 should be replaced w/method of releasing route info to statu authorities w/suggestion that info be retained in official channels MCCORMICK, G.W. Physical Security Licensing Branch. 80/03/26 2pp

1190574 Advises of BCO630 meeting w/Off. of Executive Legal Director re policy for release of safeguards info per FY80 authorization bill Meeting summary encls BURNETT, R.F. Division of Safeguards 80/07/11 3pp

1190558 FOIA request for four categories of documents re NRC release of spent fuel routing & other shipment info to public LEE, D.D. Americans for Nuclear Energy 80/12/18 1p 07489 115

1190560 Responds to FOIA request for documents re Nuclear Equipment Chemical Corp & Fern Labs NRC has no documents subj to request FELTON, J.M. Division of Rules and Records 001462 81/01/16 1p 07489 123

1190562 FOIA request for documents re Nuclear Equipment Chemical Corp & Fern Labs HATBOUL, M. FOI Service 001462 80/12/15 1p 07489 124

1190597 Responds to FOIA request for final version of generic EIS re U milling, NUREG-0706 Forwards documents listed in App A w/o encls FELTON, J.M. Division of Rules and Records 81/01/13 2pp 07489 131

1190599 FOIA request for final version of generic EIS re U milling PULS, M. Folks United to Thwart Unsafe Radiation Emission (FUTURE) 80/12/21 2pp. 07489 133

1190602 Responds to FOIA request for documents re use of burros in radiation research during 1950s No documents are available subj to request. Request has been forwarded to BCE FELTON, J.M. Division of Rules and Records 81/01/15 1p 07489 135.

8101260059 FOIA request re use of LWRs in radiation research during 1950s
SOMMERFELD, V. Strict Files 80/12/22 1p 07487 136

8101260176 Responses to FOIA request that specified documents be placed in PCR items 1-5 GE topical reports are located in PCR on microfiche items 4 & 7 are being replaced in PCR
FELTON, J. M. Division of Rules and Records 80/01/19 1p 07511 031

8101260175 FOIA request re placement of documents listed in encl in PCR
CUNNINGHAM, L. Doc-Search Associates 80/12/17 1p 07511 035

8101260225 Responses to FOIA request for seven categories of NRC documents Forwards computer printout indicating pertinent NUREG's & other documents published 1979-80 & documents in response to request
FELTON, J. M. Division of Rules and Records 80/12/31 2pp 07526 152

--8101260024 Confirms that encl listed documents responding to FOIA requests were received by firm representative
CARR, J. C. Division of Rules and Records 80/12/18 3pp 07506 136

--8101260052 Confirms that encl listed documents responding to FOIA requests were received by firm representative
CARR, J. C. Division of Rules and Records 80/12/02 3pp 07506 146

--8101260034 Confirms that encl listed documents responding to FOIA requests were received by firm representative
CARR, J. C. Division of Rules and Records 80/12/18 3pp 07506 136

--8101260052 Confirms that encl listed documents responding to FOIA requests were received by firm representative
CARR, J. C. Division of Rules and Records 80/12/02 3pp 07506 115

--8101260061 Forwards 790324 & 0921 memo re investigation rept. "Michelson Rept - Events & Levels of Review. Meras should be made part of official file
STRICKLER, L. J. Office of Inspector & Auditor 79/10/12 1p 07507 023

--8101260034 Confirms that encl listed documents responding to FOIA requests were received by firm representative
CARR, J. C. Division of Rules and Records 80/12/18 3pp 07506 126

--8101260052 Confirms that encl listed documents responding to FOIA requests were received by firm representative
CARR, J. C. Division of Rules and Records 80/12/02 3pp 07506 146

--8101260120 Forwards "Michelson Rept - Events & Levels of Review." in response to request
CUMMINGS, J. J. Office of Inspector & Auditor 79/08/01 1p 07507 063

--8101260128 Rept of investigation. "Michelson Rept - Events & Levels of Review."
STRICKLER, L. J. Office of Inspector & Auditor 79/07/25 16pp 07507 065

--8101260161 Discusses 790705 interview w/ S. Newberry re events & levels of review concerning analysis of Michelson rept. "Decay Heat Removal During Very Small Break LCCA for B&W 205 Fuel Assembly PWR." Newberry unaware of rept prior to 790701
STRICKLER, L. J. Office of Inspector & Auditor 79/07/10 1p 07507 070

--8101260173 Discusses 790702 interview w/ G. Paretis re Michelson rept. "Decay Heat Removal During Very Small Break LCCA for B&W 205 Fuel Assembly PWR." Paretis received rept in 1977 or 1978, but did not review in detail WA Post article encl
GAMBLE, D. H. Office of Inspector & Auditor 79/07/10 3pp 07507 071

--8101260188 Submits rept of interview w/ C. Michelson on 790521 re rept. "Decay Heat Removal During Very Small Break LCCA for B&W 205 Fuel Assembly PWR."
WARD, W. J. Office of Inspection & Enforcement, Office of the Director 79/09/21 4pp 07507 093

--8101260201 Lists principal lines of inquiry on which investigation of rept. "Decay Heat Removal During Very Small Break LCCA for B&W 205 Fuel Assembly PWR." will be based
IE & Dfc of Inspector & Auditor are responsible
THORNBURG, H. D. Division of Reactor Construction Inspection 79/05/21 1p 07507 098

--8101260208 Confirms 790608 memo characterizing C. Michelson as no adequate forum existed within nuclear regulatory sys for safety-related concerns info re decay heat removal problem encl
STRICKLER, L. J. Office of Inspector & Auditor 79/06/11 07507 099

--8101260218 Submits rept of interview w/ RC Jones on 790529 re "Decay Heat Removal During Very Small Break LCCA for B&W Fuel Assembly PWR."
WARD, W. J. Office of Inspection & Enforcement, Office of the Director 79/05/29 2pp 07507 243

--8101260224 Forwards reft entitled "NRC Program for Regulatory Generic Issues Related to Nuclear Power Plants." in accordance w/ reporting requirements of Energy Reorganization Act of 1974 W/o encl
HEINRICH, J. M. Commissioners 77/12/30 2pp 07507 245

--8101260227 Draft Commission paper informing Commission of investigation results & proposed enforcement actions re B&W PWR response to small break LCCAs Forwards draft civil penalty package & notice of noncompliance
STELLID, V. Office of Inspection & Enforcement, Office of the Director 80/03/25 13pp 07507 268

--8101260237 Discusses IE May-Nov 1979 investigations into whether adequately analyzed potential safety problems & whether problems should have been reported per 10CFR21 No evidence constituting criminality found
CUMMINGS, J. J. Office of Inspector & Auditor 80/04/02 07507 288

--8101260247 Submits results of first phase of audit of implementation action plan items relating to Dfc of Nuclear Reactor Regulation Investigation focused on util personnel licensing & training Provides scope, findings & comments
CUMMINGS, J. J. Office of Inspector & Auditor 80/10/03 07507 270

--8101260255 Comments on draft reft re audit of implementation action plan items relating to Dfc of Nuclear Reactor Regulation Reft focused on util personnel licensing & training Related documentation encl
DIRCKS, W. J. Office of the Executive Director for Operations 80/07/29 7pp 07507 295

--8101260260 Discusses audit review of NRC reactor insp program objective was to assess degree to which IE policies & procedures for inspecting nuclear plants were being implemented Forwards info reft on reactor insp program
CUMMINGS, J. J. Office of Inspector & Auditor 80/07/31 07507 297

--8101260267 Informs that IE has no substantive comment on audit insp program IE will utilize reft & survey responses in ongoing reviews of insp program
DIRCKS, W. J. Office of the Executive Director for Operations 80/07/01 1p 07507 356

--8101260274 Discusses potential problem w/ temporary duty transfer authorizations for resident inspectors Practice is contrary to Controller General Decisions B-188093, B-182427 & B-193601 W/o encl Decision B-188093
CUMMINGS, J. J. Office of Inspector & Auditor 80/06/20 07507 397

--8101260282 Forwards reft re review of NRC plan for research safety of LWRs Review purpose was to determine whether NRC was responsive to Public Law 95-209 Provides summary of findings, recommendations & agency comments
CUMMINGS, J. J. Office of Inspector & Auditor 80/06/11 07507 360

--8101260288 Comments on recommendations in draft reft on research plan for research to improve safety of LWRs Concurs w/ recommendations
BURNETT, R. J. Office of Nuclear Regulatory Research, Director 80/06/09 2pp 07508 021

--8101260298 Discusses NRC required experience for senior resident inspectors. Inspector must possess min of 2 yrs experience NRC regulatory program before being relocated as senior resident inspector
STELLID, V. Office of Inspection & Enforcement, Office of the Director 80/03/06 1p 07508 023

--B101260314 Submits rept on undesirable effects of accelerating implementation of NRC resident insp program Includes summary of findings, conclusions, recommendations & agency comments Related documentation encl
CUMMINGS, J J Office of Inspector & Auditor 79/06/22 15pp 07508 062

--B101260319 Submits no comment on draft rept re undesirable effects of accelerating implementation of NRC resident insp program
GOSBICK, L V Office of the Executive Director for Operations 79/06/22 200pp 07508 077

--B101260329 Submits audit rept of ongoing review of Ofc of Nuclear Regulatory Research activities NRC should continue to negotiate w/ERDA to clarify responsibilities of each agency & simplify organization of working relationship
MCITERNAH, T J Office of Inspector & Auditor 76/07/24 31pp 07508 078

--B101260334 Memorandum of understanding between NRC & ERDA re joint research program
SEAMANS, H C Energy Research & Development Admin (Presently DOE)
ANDERS, W A Commissioners 75/08/08 10pp 07508 111

--B101260339 Submits review of rept on NRC/ERDA relations in research activities Joint task force should investigate working relationship Related documentation encl
GOSBICK, L V Office of the Executive Director for Operations 76/07/29 390pp 07508 120

B101270171 Responds to FOIA request for documents re disposal of nuclear wastes off NJ coast by Navy in Oct 1947 NRC has no documents subj to request
FELTON, J M Division of Rules and Records 81/01/21 1p 07547 066

B101270178 FOIA request for documents re disposal of nuclear wastes off NJ coast by Navy in Oct 1947
MAUDIS, S Courier-News Bridgewater, NJ 81/01/02 2pp 07547 067

B101270197 FOIA request for four categories of documents
REID, A B Black Hills Alliance 80/12/14 2pp 07543 023

B101280350 Responds to FOIA request for updated list of threats to licensed nuclear facilities since 790330 Info can be found in NUREG-0525, Revisions 2 & 3, which are available at NRC.
Div of Technical & Document Control & NTIS
FELTON, J M Division of Rules and Records 81/01/21 1p 07558 057

B101280358 FOIA request for updated list of threats made to licensed nuclear facilities since 790330
MAZUR, A Syracuse Univ 81/01/01 1p 07558 058

B101280365 Responds to FOIA request for documents re Task Force on Interim Operation of Indian Point submitted to NRC after 800331 Forwards App A documents App D documents withheld (ref FOIA Exemption 3)
FELTON, J M Division of Rules and Records 81/01/21 3pp

--B101280388 Staff requirements memo re 800626 briefing on recommendations of facility task force Commission took no action during meeting Task force rept & other info re facility operation will be reviewed further
CHILKIS, J Office of the Secretary of the Commission 80/06/30 1p

B101280408 Responds to FOIA request for NRC most recent functional organizational chart Forwards requested info w/o encl
FELTON, J M Division of Rules and Records 81/01/23 1p 07558 073

B101280410 FOIA request for NRC most recent functional organizational chart
EBERLEIN, F Control Data Corp 81/01/19 1p 07558 074

B101280432 Partial response to FOIA request for documents re Paragraphs 1 & 2 of 701027 FR notice Lists excerpt from NRC 1975 annual rept w/respect to query re vacant commissioner'ship Another document subj to request is undergoing review
FELTON, J M Division of Rules and Records 81/01/21 1p 07558 080

--B101280431 Forwards nonproprietary version of Revision 1 to Task 2 draft technical rept. "Mathematical Derivation of Advanced Matl Accounting Sys Simulation Model." Forwards nonproprietary versions of repts
FELTON, J M Division of Rules and Records 81/01/16 1p 07558 083

--B101280451 Forwards nonproprietary version of Revision 1 to Task 2 draft technical rept. "Mathematical Derivation of Advanced Matl Accounting Sys Simulation Model." prepares under NRC-02-80-024
PEVENSTEIN, J E NUSAC, Inc NRC-02-80-024 80/10/24 1p

--B101280455 591 Nonproprietary version of Task 2 draft technical rept. "Mathematical Derivation of Advanced Matl Accounting Sys Simulation Model." "AMASS" Model "
NUSAC, Inc NRC-02-80-024 80/10/30 73pp

--B101280459 Submits nonproprietary version of monthly progress r NRC-02-80-024. "Development of Advanced Matl Accounting Sys Simulation Model." AMASS mathematical methodology is under development
PEVENSTEIN, J F NUSAC, Inc NRC-02-80-024 80/08/15 3pp

--B101280464 Submits nonproprietary version of addendum to monthly progress rept for NRC-02-80-024. "Development of Advanced Matl Accounting Sys Simulation Model." Add: info concerns 800805 meeting to discuss results of Task 1
PEVENSTEIN, J E NUSAC, Inc NRC-02-80-024 80/08/21 1p

--B101280469 Submits nonproprietary version of monthly progress r NRC-02-80-024. "Development of Advanced Matl Accounting Sys Simulation Model." for 800809-0908 Includes work performed, personnel time expenditures & costs
PEVENSTEIN, J E NUSAC, Inc NRC-02-80-024 80/09/15 2pp

--B101280474 Submits nonproprietary version of monthly progress r NRC-02-80-024. "Development of Advanced Matl Accounting Sys Simulation Model." for 800909-1010 Includes work performed, personnel time expenditures & costs
PEVENSTEIN, J E NUSAC, Inc NRC-02-80-024 80/10/15 3pp

--B101280478 Submits nonproprietary version of monthly progress r NRC-02-80-024. "Development of Advanced Matl Accounting Sys Simulation Model." for 801011-1110 Includes work performed, administrative matters & costs
PEVENSTEIN, J E NUSAC, Inc NRC-02-80-024 80/11/19 2p

B101280447 FOIA request for Task 2 rept & monthly progress repts submitted by NUSAC, Inc under NRC-02-80-024. "Development of Advanced Matl Accounting Sys Simulation Model."
FINDLEY, D E Science Applications, Inc 80/12/16 1p 07558 044

B101280481 Responds to FOIA request for documents re Paragraphs of 801027 FR notice Forwards SECY-80-345 w/o encl
FELTON, J M Division of Rules and Records 81/01/22 1p 07558 106

B101280608 Responds to FOIA request for info re incidents concerning radii unaccounted for & other types of safeguards violations Forwards NUREG-0525, Revision 3, "Safeguards Summary Event List (SSEL)" PNDs are located in PDR 11/a encl NUREG-0525
FELTON, J M Division of Rules and Records 81/01/22 1p 07558 203

B101280612 FOIA request for info re incidents concerning radii unaccounted for & other types of safeguards violations, for use in research project
EISENHAEUER, M M Affiliation Unknown 81/01/06 1p 07558 204

B101280655 Responds to FOIA request for records re investigation audit or regulatory proceedings involving Enserch Corp & subsidiaries or affiliates & all correspondence within past 10 yrs Encl App A documents available in PDR
FELTON, J M Division of Rules and Records 81/01/13 3pp 07573 291

--B101290067 Matl/Byproduct License 29-07056-03 for Ebasco Svcs. Amended per 790224 application Amend 5 changes expiration date in Item 4 to 806331 & revises Condition 16
BASIN, N Licensing Management Branch 75/06/10 1p

--B101270362 Matl/Byproduct License 29-07056-03 for Ebasco Svcs. Inc. is amended per 721115 application Amend 3 revises Condition 16 & authorizes possession, use, transfer & import of 549 kg U contained as shielding matl in radiography devices
BASSEN, N Atomic Energy Commission, Directorate of Licensing
73/04/10 1p

--B101290347 Matl/Byproduct License 29-07056-03 for Ebasco Svcs. Inc. is amended per 720426 application Amend 2 authorizes possession & use of Co-60, no single source to exceed 10 Ci in Technical Operations Model A-424-15 sealed sources
BASSEN, N Atomic Energy Commission, Directorate of Licensing
72/09/19 1p

--B101290490 Matl/Byproduct License 29-07056-03 for Ebasco Svcs. Inc. is amended per 710218 application Amend 1 authorizes possession & use of Co-60, no single source to exceed 250 Ci in Technical Operations Model 676 exposure devices
BASSEN, N Atomic Energy Commission, Directorate of Licensing
71/04/30 1p

--B101290104 Matl/Byproduct License 29-07056-03 for Ebasco Svcs. Inc. authorizing possession & use of Ir-192 & Co-60 in forms of Technical Operations sealed sources & exposure devices
BASSEN, N Atomic Energy Commission 71/02/07 1p

--B101270116 Forwards application for renewal of Matl/Byproduct License 29-07056-03
TENZER, B E Ebasco Services, Inc (subs of Enserch Corp)
95016 75/02/24 2pp

--B101290124 Application for renewal of Matl/Byproduct License 29-07056-03, authorizing possession & use of Ir-192 & Co-60 in forms of Technical Operations sealed sources & exposure devices Incumbency certificate & prof qualifications encl
TENZER, B E Ebasco Services, Inc (subs of Enserch Corp)
95016 75/02/24 14pp

--B101290131 Requests renewal of Matl/Byproduct License 29-07056-03
BU, LEN, H C Ebasco Services, Inc (subs of Enserch Corp)
94548 75/01/28 1p

--B101290143 Forwards list indicating quantity of depleted U contained as shielding matl in radiography devices & source changers authorized under License 29-07056-03 Addl exposure devices have not been purchased
BU, LEN, H C Ebasco Services, Inc (subs of Enserch Corp)
74/06/20 2pp

--B101290255 Requests amend to Matl/Byproduct License 29-07056-03, authorizing use, transfer & import of 1,000 kg or more U, contained as shielding matl in radiography devices & source changers Radiographic exposure device inventory sheet encl
BU, LEN, H C Ebasco Services, Inc (subs of Enserch Corp)
43969 74/01/03 2pp

--B101290261 Requests amend to Matl/Byproduct License 29-07056-03 procedure, "Manual for Operating & Emergency Procedures for Isotope Radiography," Revision & Supplemental data sheet encl
ALLIKBERG, R Ebasco Services, Inc (subs of Enserch Corp)
32056 72/11/15 3pp

--B101290151 Responds to AEC 720821 request for clarification re use of source changer for quarterly insp & maint of radiographic equipment Forwards Revision 5 to isotope radiography manual for operating & emergency procedures Cover page only
ALLIKBERG, R Ebasco Services, Inc (subs of Enserch Corp)
72/09/01 2pp

--B101290171 Requests clarification of statement contained in 720728 procedures for quarterly insp & maint of radiographic equipment re storage of source in Technical Operations Model 416 source changer Review to continue upon receipt of info
BASSEN, N Atomic Energy Commission 72/03/21 1p

--B101290159 Responds to AEC 720630 request for more complete instructions re quarterly insp & maint procedure W/o encl manual for operating & emergency procedures for isotope radiography
ALLIKBERG, R Ebasco Services, Inc (subs of Enserch Corp)
72/07/23 1p

--B101290310 Revision 3 of manual for operating & emergency procedures for isotope radiography
* Ebasco Services, Inc (subs of Enserch Corp) 72/05/31 71pp

--B101290186 Informs that revised operating & emergency procedures, per 720426 application for amend to License 29-07056-03, should include ref or instructions for use of Model 684 exposure device & name of person conducting quarterly insp & maint
BASSEN, N Atomic Energy Commission, Directorate of Licensing
72/09/09 1p

--B101290324 Requests amend to Matl/Byproduct License 29-07056-03, authorizing use of Co-60, no single source to exceed 10 Ci, for use in Model A-424-15 sealed sources & revising Condition 14
DIZ, C V Ebasco Services, Inc (subs of Enserch Corp) 27/01 72/04/26 2pp

--B101290281 Submits addl info re amend to Matl/Byproduct License 29-07056-03, in response to AEC 710301 request Technical Operations devices Models 680 & 676 will be utilized at Port Neary facility only Technical Operations 710401 ltr encl
DIZ, C V Ebasco Services, Inc (subs of Enserch Corp)
71/04/01 3pp

--B101290203 Requests addl info re 710218 application for license to possess & use 250 Ci Co-60 in Technical Operations Model 676 exposure device, including where source & device will be used & revised operating & emergency procedures
BASSEN, N Atomic Energy Commission 71/03/11 1p

--B101290330 Requests amend to Matl/Byproduct License 29-07056-03, authorizing possession & use of 250 Ci Co-60 in Technical Operations Model 676 exposure device for industrial radiography
DIZ, C V Ebasco Services, Inc (subs of Enserch Corp) 20376 71/02/18 1p

--B101290287 Responds to AEC 701221 ltr Picker Corp performs calibr survey meters at Stoughton, MA facility, after instruments are repaired Clarifies discrepancies re training program & operating & emergency procedures W/Picker Corp 710104 ltr
TENZER, B E Ebasco Services, Inc (subs of Enserch Corp)
71/01/20 4pp

--B101290343 Matl/Byproduct License 34-07225-08 for Picker X-Ray Corp amended in its entirety per 681115 application Amend 20 authorizes use & possession of 3,000 Ci Co-60, 100 Ci Ir-192, 200 Ci Tm-170 & 200 Ci Yb-169 in sealed sources
MALARD, J C Atomic Energy Commission 68/12/10 5pp

--B101290349 Matl/Byproduct License 34-07225-13 for Picker Corp authorizing possession & use of 3,000 Ci Co-60, 100 Ci Ir-192, 200 Ci Tm-170 & 200 Ci Yb-169 in sealed sources
MALARD, J C Atomic Energy Commission 69/03/07 5pp

--B101290360 Matl/Byproduct License 34-07225-08 for Picker Corp is amended per 691126 application Amend 24 revises Subitems 9 C, 9 D, 9 E, 9 F & authorizes possession, use, transfer & import of U contained as shielding in exposure devices
MALARD, J C Atomic Energy Commission 69/12/09 7pp

--B101290337 Ack receipt of 701203 addl info submitted in response to request Requests license number or authority by which Picker Corp uses byproduct matl for instrument calibr W/o encl AEC licensing guide for radiography
BASSEN, N Atomic Energy Commission 70/12/21 2pp

--B101290290 Responds to AEC 701124 ltr re application for amend to Byproduct License 31-07056-02 Calibr of survey instruments is performed by Ebasco Matls Engineering Lab, using Technical Operations Model 571 meter calibr kit
TENZER, B E Ebasco Services, Inc (subs of Enserch Corp)
70/12/03 10pp

--B101290313 "Procedure for Qualification & Certification of Nondestructive Testing Personnel" Related info encl
* Ebasco Services, Inc (subs of Enserch Corp) 70/06/30 83pp

--B101290246 Requests addl info re 701105 application for amend to License 31-07056-02 Includes info re instrument calibr svcs offered by Picker Industrial & X-Ray Industrial Distributors & revised procedures
BASSIN, N Atomic Energy Commission 70/11/24 2pp.

--B101290298 Confirms 701113 telcon instructing AEC to disregard phrase in manual for operating & emergency procedures for isotope radiography Phraseology is for internal purposes & does not apply to AEC
TENZER, B E Ebasco Services, Inc (subs of Enserch Corp) 70/11/13 1p

--B101290304 Forwards application for amend to Matl/Byproduct License 31-0056-02 due to transfer of all nondestructive testing equipment to new facility
TENZER, B E Ebasco Services, Inc (subs of Enserch Corp) 70/11/06 1p

--B101290335 Application for amend to Matl/Byproduct License 31-07056-02, authorizing use & possession of 100 Ci Ir-192 & 200 Ci Co-60 in Technical Operations exposure devices for industrial radiography, source changers & storage containers
TENZER, B E Ebasco Services, Inc (subs of Enserch Corp) 70/11/03 10pp

--B101290317 Revision 1 of manual for operating & emergency procedures for isotope radiography Related info encl
* Ebasco Services, Inc (subs of Enserch Corp) 18616 70/11/30 8pp

B101290061 FOIA request for records re investigations, audits or regulatory proceedings involving Enserch Corp & subsidiaries or affiliates & all correspondence within past 10 yrs
SCHIFF, R F Washington Service Bureau, Inc 80/12/30 1p 07573 294

GEN TEC IS GENERIC TECHNICAL ISSUES

B101090178 Forwards nonproprietary version of Burns & Roe, Inc rept. "Analytical Model for LOCA Water Jet in Mark II Containers (Ring Vortex Model)," provided on behalf of Mark II owners group as part of Mark II containment program
BUCHHELD, R H General Electric Co MFN-108-B0 80/12/11 1p 07376 088

--B101090107 Nonproprietary version of rept. "Analytical Model for LOCA Water Jet in Mark II Containers (Ring Vortex Model)"
CHU, C K, LEE, T Burns & Roe Co 80/09/30 11pp 07376:089

B101210322 Forwards Draft 2 of proposed Reg Guide 5C 709-A, "Ultrasonic Testing of Reactor Vessel Welds During Preservice & Inservice Insp."
ARLDT, G A Division of Engineering Standards 81/01/02. 39pp 07308 001.

B101290632 "ASYMMETRIC BLOWDOWN LOADS ON PWR PRIMARY SYSTEMS," RESOLUTION OF GENERIC TASK ACTION PLAN A-2
HOBFORD, S D, MATTU, R, MEYER, R O Division of Safety Technology 81/01/31. 81pp Available at NTIS \$4.00 07374 001

B101290684 Forwards NUREG-0609, "Asymmetric Blowdown Loads on PWR Primary Sys.," providing NRC resolution of Unresolved Safety Issue Task A-2 Rept covers development of loading transients & structural analysis criteria. W/o encl
DENTON, H R Office of Nuclear Reactor Regulation, Director 81/01/03 1p 07576-145

B101290694 Forwards NUREG-0609, "Asymmetric Blowdown Loads on PWR Primary Sys.," providing NRC resolution of Unresolved Safety Issue Task A-2 Rept covers development of loading transients & structural analysis criteria W/o encl.
DENTON, H R Office of Nuclear Reactor Regulation, Director 81/01/03 1p. 07574-192

B101290710 Forwards NUREG-0609, "Asymmetric Blowdown Loads on PWR Primary Sys.," providing NRC resolution of Unresolved Safety Issue Task A-2 Rept covers development of loading transients & structural analysis criteria W/o encl
DENTON, H R Office of Nuclear Reactor Regulation, Director 81/01/05 1p. 07574 244

B101300015 Forwards NUREG-0609, "Asymmetric Blowdown Loads on PWR Primary Sys.," providing NRC resolution of Unresolved Safety Issue Task A-2 Rept covers development of loading transients & structural analysis criteria W/o encl.
DENTON, H R Office of Nuclear Reactor Regulation, Director 81/01/05. 1p 07579 317.

12E INSPECTION AND ENFORCEMENT

B002200670 IE Info Notice 80-17, "Potential Hazards Associated With Interchangeable Parts on Radiographic Equipment"
* Office of Inspection & Enforcement, Office of the Director 80/05/05 1p 05148 200

B005050346 IE Info Notice 80-25, "Transportation of Pyrophoric U"
* Office of Inspection & Enforcement, Office of the Director 80/05/30 3pp 03755 248

B006190050 IE Bulletin 80-22, "Automation Industries, Model 200-52 Sealed Source Connectors" IE Circular 79-16, "Excessive Radiation Exposures to Members of General Public & Radiographer" & hood & eye drawing encl
* Office of Inspection & Enforcement, Office of the Director 80/09/11 2pp 06810 117

B008220279 IE Info Notice 80-43, "Failures of the Continuous Water Level Monitor for the Sram Discharge Volume at Dresder Unit 2"
* Office of Inspection & Enforcement, Office of the Director 80/12/03 2pp 07374 020

B011040252 IE Bulletin 80-17 Supp 4, "Failure of Control Rods to During a Sram at BWR"
* Director's Office, Office of Inspection and Enforcement 80/12/18 4pp

B012160001 IE Info Notice 80-44, "Actuation of ECCS in the Recirculation Mode While in Hot Shutdown"
* Office of Inspection & Enforcement, Office of the Director 80/12/16 2pp 07374 280

B012160002 IE Info Notice 80-45, "Potential Failure of BWR Backup Manual Stop Capability"
* Office of Inspection & Enforcement, Office of the Director 80/12/17 2pp 07374 283

B012160266 PND-1-80-177 on 801222, main valve of fire sprinkler system cracked & released 4,000 gallons of water onto floor of plant. Small quantity leaked outside protected area but was surveyed as not contaminated Sys currently inoperable
ROTH, J Region 1, Philadelphia, Office of the Director 80/12/22 2pp 07361 287

B101050539 PND-1-80-178 on 801222, Cifer Nuclear tractor trailer carrying low level radioactive from util was involved in traffic accident near Bordentown, NJ. No visible damage to cask detected. Shipment proceeded to Jernell, SC
CAMPELLE, M Region 1, Philadelphia, Office of the Director 80/12/23 2pp

B101090192 PND-1V-81-01 on 810102, main turbine was tripped at low power conditions to investigate suspected problems w/rotor seal valves. Valves failed to fully close following trip. Unit will be shut down for approx seven days for repairs
WESTERMAN, T F Region 4, Dallas, Office of the Director 81/01/11 1p

B101090204 PND-1V-80-41 on 801230, util (IA manager notified Region 4 that stop work order had been issued on Category 1 work. Order resulted from discovery that incoming drawings had not been processed by document control since 801106
BEACH, A B Region 4, Dallas, Office of the Director 00/12/30 2pp

B101090224 PND-1-80-181 on 801229, while conducting surveillance leakage, two through-wall cracks were found in 3-Pt straight section of 4-inch cleanup sys piping. Cleanup sys isolated & power held at 25% pending repair
GREENMAN, E Region 1, Philadelphia, Office of the Director 80/12/30 2pp

B101090241 PND-1-80-180: Unit 1 outage has been extended until after 810111 Outage caused by 801224 discovery of failed main turbine thrust bearing during initial Cycle 9 startup
MCCABE, E C Region 1, Philadelphia, Office of the Director 80/12/29 1p

B101190544 PNA-80-029A on 801203, State of AR notified Nuclear Diagnostic Labs that license had been revoked. Caused by failure to respond to state 801024 enforcement ltr. Updates & closes-out PNA-80-029 issued on 800822
LUBENAU, J O, BOLLING, L A Office of State Programs, Director 80/12/18 1p 07475:338

8101200127 PHO-TMI-B1-01 on 810101. Water samples from onsite well 2 contained trace quantities of Cs-137 & Cs-134. Subsequent samples on 810106, 15 & 18:03 indicated concentrations at less than lower limit of detection. Item to be reviewed 810115. SWANBERG, M. TMI Program Office 81/01/13 3pp

8101200374 PHO-I B1-05 on 810112. Monthly sample of auxiliary, cooler condensate return identified 10-5 uCi/ml activity, primarily, Cs-134 & Cs-137. Monitor should have detected activity but solenoid valve found closed in sample line. KUTHEER, K. K. KISTEN, H. D. Region 1, Philadelphia, Office of the Director 81/01/13 2pp

8101200590 PHO-I-B1-06 on 810115. High airborne radioactivity was identified on refueling floor of reactor bldg. Caused by two workers cleaning area around head of reactor below refueling floor. Whole body counts indicated 20 & 200 MPC-hrs. HUNT, L. R. Region 1, Philadelphia, Office of the Director 81/01/15 2pp

8101200403 PHO-IV-B0-340 by 810108. Ltr. util. requested Region 4 authority for limited restart of placement of complex concrete. Limited resumption of complex concrete placement authorized. HADACEK, W. D. Region 4, Dallas, Office of the Director 81/01/13 1p

8101200416 PHO-I-B1-04 on 810111. During sampling of val control tank, inadvertent gaseous release occurred resulting in 62.2 Ci noble gas being released over period of 131 minutes. No personnel exposures involved. Media interest expected. WHITE, J. Region 1, Philadelphia, Office of the Director 81/01/12 2pp

8101200426 PHO-I-B1-02 on 810107. During heatup for restart, event occurred which resulted in introduction of reactor coolant into nitrogen gas supply sys. Caused by two open valves in nitrogen supply line to RCS. Valves left open during paint. KEITH, R. Region 1, Philadelphia, Office of the Director 81/01/09 2pp

8101200507 PHO-TMI-B1-03A on 810118. Operational & testing activities temporarily terminated due to small leak in makeup sys. piping discovered on 810117. RCS depressurized to 45 psig & being held in that condition. HAVENHAMP, D. R. TMI Program Office 81/01/19 2pp

8101200513 PHO-I-B1-012 Ion Track Instruments, Inc. License 20-15525-02E. Distributes explosive detection devices exempt from NRC licensing which are suspected of leaking Ni-63. Special insp will be conducted to determine cause. JERMAN, P. C. KINNEHAN, J. D. Region 1, Philadelphia, Office of the Director 81/01/22 1p 07557 050

8101200519 PHO-TMI-B1-02 on 810113. Estimated 600 gallons of concentrated sulfuric acid siphoned from storage tank, through two valves, & out of 2-inch flange pipe. Valves inadvertently opened or left open by maint. BARLEY, W. L. BARRETT, L. TMI Program Office 81/01/14 2pp

8101200524 PHO-TMI-B1-03 on 810116. Licensee commenced planned activities to raise reactor coolant pressure & temp from 0 psig, 121 F to approx 340 psig & max 195 F. Activities expected to last approx one wk. REATTO, L. W. BARRETT, L. TMI Program Office 81/01/16 2pp

8101200655 PHO-IV-B1-04 State of TX notified that individual in Omulgee, OK, hosp. suffering from serious radiation injuries to chest & left forearm. Individual had recently worked for Houston (hosp in State of NM). BROOK, C. D. Region 4, Dallas, Office of the Director 81/01/23 2pp 07566 347

MISC PUBLIC DOCUMENT ROOM MISCELLANEOUS

8101140056 Delegates D. Reiff as acting chief of Mechanical Engineering Research Branch from 801224 - 810102. RICHARDSON, J. E. Mechanical Engineering Branch 80/12/24 1p 07461 226

8101140061 Supports J. E. Richardson for membership on Affirmative Action Advisory Committee. SERPAN, C. Z. Assistant Director for General Reactor Safety Research 80/12/22 1p 07461 227

8101150579 Forwards memorandum of understanding between Ofc of Nuclear Reactor Regulation & IE re regionalization of operator licensing program & final implementation schedule. DENTON, H. R. Office of Nuclear Reactor Regulation, Director 80/12/23 1p 07464 266

8101150583 Memorandum of understanding between Ofc of Nuclear Reactor Regulation & IE re regionalization of operator licensing program. STELLON, V. Office of Inspection & Enforcement, Office of the Director 80/12/11 10pp 07464 267

8101150876 "Low Level Radwaste Modeling Needs from NRC Perspective. SMITH, R. D., HANNA, S. E. F. Low Level Waste Licensing Branch 80/12/22 3pp 07464 134

8101150725 Nuclear Reactor Regulation Ofc Letter 19, Revision 1, forwarding revised procedures for notifying licensing boards of relevant new info. DENTON, H. R. Office of Nuclear Reactor Regulation, Director 80/12/09 6pp 07308 001

8101150937 Ack receipt of 801203 ltr requesting meeting w/NRC to re info re Isoline plotout. Meeting w/RW Houston in second or third wk of Jan 1981 could be appropriate. DENTON, H. R. Office of Nuclear Reactor Regulation, Director 80/12/24 1p 07464 179

810120267 Summary of 801209 meeting w/Paul-Monroe Hydraulics, Inc. Bethesda, MD re hydraulic snubbers & inservice insp/test in place capability. ENGLE, L. B. Operating Reactors Branch 3, 81/01/06 6pp 07309

810120074 NR-AIG-003 "Financial Implications of Retrospective Premium Assessments on Electric Utility." Related info encl. * Commissioners. MELCHER, R. W. Colorado, Univ. of, Denver 76/09/30 37pp Available at NTIS 84-CO 07956 346

8101200348 Responds to 801201 request for info on nuclear plant locations, waste dumps & safe distances from nuclear plants. Excerpts from 1979 annual rept & from rept of President's Commission on TMI encl in response to inquiries. ZELCH, G. G. Technical Support Branch 81/01/06 26pp 07571 329

NUREG NUREG REPORTS AND RELATED CORRESPONDENCE

8101200440 Comments on DO Eisenhower ltr to licensees re Section II C "Performance Testing of 3WR & PWR Relief & Safety Valves." Present program does not provide for testing of PWR valves under ATRS conditions or include tests of block valves. LEVENSON, M. Electric Power Research Institute 80/11/26 1p 07171 346

8101200226 Forwards Ofc of Nuclear Regulatory Research 800711.22.23 29 cards referred to in NUREG-0735, "Plan for Developing Safety Goal." Matl should be included in PDR files. WFO encl. LARKINS, J. T. Program Coordination Branch 80/12/08 1p 07371 201

8101050062 Forwards Change 1 to "LOFT Sys & Test Description (5 5-F Nuclear Core 1 LOCEs)." NUREG/CR-0247, TREE-120B includes addition which contains recently calculated coolant vols of LOFT primary coolant sys. KAUFMAN, W. C. EG&G Idaho, Inc. TREE-120B. 80/10/21 2pp 07378 001

--8101050069 NUREG/CR-0247 Change 1 to LOFT SYSTEM & TEST DESCRIPTION (5 5-F NUCLEAR CORE 1 LOCEs) * EG&G Idaho, Inc. TREE-120B 80/09/30 250pp 07378 004

8101050111 NUREG/CR-1211 UNCERTAINTY IN CALCULATED SURFACE TEMPERATURE & SURFACE HEAT FLUX OF THERMAL HYDRAULIC TEST FACILITY HEATER RODS. CHILDS, K. W. Union Carbide Corp. FIN 8-0125 80/12/31 60pp 07398 001

8101060439 Forwards comments on NUREG-0731, "Guidelines for Util Mgt & Technical Resources, Sept 1980." Concurs that organizational structure should not be prescriptive. SHIELDS, S. H. Public Service Co. of Indiana, Inc. 80/12/23 5pp 07376 204

8101060860 Provides info concerning testing program sponsored by U in BWR owners group to satisfy provisions of NUREG-0578, Section 2.1.2, safety & relief valves. Test program description & program scope encl. WATERS, D. B. Carolina Power & Light Co. 80/09/17 3pp 07400 1

--8101060860 NUREG-0578 BWR safety relief valve test description * 3WR Owners Group 80/09/17 71pp 07400 318

NONDOCKETED ITEMS

- 8101080256 NUREQ-0384 R1
ASSURING AVAILABILITY OF FUNDS FOR DECOMMISSIONING NUCLEAR
FACILITIES Draft Report Revision 1
WOOD, R S Utility Finance Branch (formerly Antitrust & Indemnity)
7/7/12/31 57pp 07420 027
- 8101090445 NUREQ/CR-1274
FLAW PREPARATIONS FOR NEST PROGRAM VESSEL FRACTURE
MECHANICS TESTING MECHANICAL-CYCLOC PUMPING & ELECTROCHEM
WELD-HYDROGEN CHARGE CRACKING SCHEMES
HCLZ, P P Oak Ridge National Laboratory FIN D-0119
ORNL/NUREG/TH-3 80/05/31 18pp 07424 253
- 8101090487 Forwards "NWR Owners Group Evaluation of NUREQ-0737, Item
II K 3 13B Reactor Core Isolation Cooling Sys Automatic
Reset"
WATERS, D B BWR Owners Group BWRDC-80-12 80/12/29 1p
07440 226
- 8101090453 "NWR Owners Group Evaluation of NUREQ-0737, Item II K 3 13B
Reactor Core Isolation Cooling Sys Automatic Reset"
* BWR Owners Group 80/12/29 97pp 07440 227
- 8101090951 NUREQ/CR-1774
HIGH-TEMPERATURE GAS-COOLED REACTOR SAFETY STUDIES FOR THE
DIVISION OF REACTOR SAFETY RESEARCH, QUARTERLY PROGRESS
REPORT, APRIL 1 - JUNE 30, 1980
DALL, S J, CLEVELAND, C J, CHALKIN, J C Oak Ridge National
Laboratory FIN D-0122 ORNL/NUREG/TH-4 80/12/31 14pp
Available at NTIS 07430 213
- 8101090762 NUREQ/CR-1028
EDDY-CURRENT INSPECTION FOR STEAM GENERATOR TUBING PROGRAM,
QUARTERLY PROGRESS REPORT FOR PERIOD ENDING MARCH 31, 1980
DODD, C V, DEEDS, W E, MCCLUNG, R W Oak Ridge National Laboratory
FIN D-0417 ORNL/NUREG/TH-4 80/12/31 13pp Available at NTIS
07430 146
- 8101090769 NUREQ/CR-1029
EDDY-CURRENT INSPECTION FOR STEAM GENERATOR TUBING PROGRAM,
QUARTERLY PROGRESS REPORT FOR PERIOD ENDING JUNE 30, 1980
DODD, C V, DEEDS, W E, MCCLUNG, R W Oak Ridge National Laboratory
FIN D-0417 ORNL/NUREG/TH-4 80/12/31 10pp Available at NTIS
07430 138
- 8101100128 NUREQ-0535 R3
SAFEGUARDS SUMMARY EVENT LIST (SSEL) REVISION 3
DAVIDSON, J J, MACMURDY, P H Office of Nuclear Material Safety &
Safeguards 80/12/31 165pp Available at NTIS 07434 206
- 8101100714 Ack receipt of comments re NUREQ/CR-1021, "Final Rept -
Phase 1 Sys Interaction Methodology Applications Program"
BCHRECHER, F Assistant Director for Generic Projects 80/12/24
2pp 07445 123
- 8101100808 NUREQ/CR-1017
COMPARISON OF COMPARE P30-1 SUBCOMPARTMENT CALCULATIONS
W/BATTELLE-FRANKFURT D-SERIES TEST RESULTS
DOLSTAD, J H, OGDON, R O, GREGORY, W S Los Alamos Scientific
Laboratory FIN A-7111 LA-8615-MS 80/12/12 59pp Available at
NTIS 07441 223
- 8101100857 NUREQ/CR-1241
LWR PRESSURE VESSEL IRRADIATION SURVEILLANCE DOSEIMETRY,
QUARTERLY PROGRESS REPORT, JANUARY-MARCH 1980 Volume 1
OUTTHIE, O L, MCLEOD, W H Hanford Engineering Development
Laboratory FIN D-3988-7 HDL-TPE 80-4 80/12/31 71pp
Available at NTIS 07431 256
- 8101120049 Comments on NUREQ-0735 re NRC plan for developing safety
goal Endorse concept Goal should focus on providing
adequate level of protection to public relative to benefit
derived from plant-electrical power production
SHERWOOD, O O General Electric Co. MFN-204-80 80/11/26 2pp
07309 001
- 8101120053 Responds to request for comments on list of topics being
considered in development of safety goal for nuclear power
plants Many individuals exhibit fairly extreme risk aversion
to low probability-high consequence events
BUEHRING, W A Argonne National Laboratory 80/11/21 2pp
07447 083
- 8101120359 NUREQ/CP-0015
REVIEW GROUP CONFERENCE ON ADVANCED INSTRUMENTATION
RESEARCH FOR REACTOR SAFETY Proceedings of NRC Conference
at ORNL July 29-31, 1980
HOM, A L, BASDEKAS, D, HSU, Y Y Division of Reactor Safety Research
- 8101130074 NUREQ-0383 V2 R3
DIRECTORY OF CERTIFICATES OF COMPLIANCE FOR RADIOACTIVE
MATERIALS PACKAGES Certificates of Compliance, Volume 2,
Revision 3
* Division of Fuel Cycle & Material Safety 80/12/31 60p
07450 001
- 8101130090 NUREQ-0383 V3
DIRECTORY OF CERTIFICATES OF COMPLIANCE FOR RADIOACTIVE
MATERIALS PACKAGES Summary Report of NRC Approved Quality
Assurance Programs for Radioactive Material Packages
Volume 3
* Division of Fuel Cycle & Material Safety 80/12/31 11p
07309 001
- 8101130311 NUREQ-0585 V1 R3
DIRECTORY OF CERTIFICATES OF COMPLIANCE FOR RADIOACTIVE
MATERIALS PACKAGES Summary Report of NRC Approved Packages
Volume 1, Revision 3
* Division of Fuel Cycle & Material Safety 80/12/31 25p
07452 182
- 8101130317 Comments on NUREQ-0577, "Potential for Low Fracture
Toughness & Lamellar Tearing on PWR Steam Generator &
Reactor Coolant Supports." & add guidance Stress corrosion
acceptance criterion should be eliminated
GRIDLEY, R L General Electric Co MFN-219-80 80/12/30
07447 278
- 8101130402 NUREQ-0747
DESCRIPTION OF CURRENT & PLANNED RESEARCH IN STRUCTURAL
ENGINEERING
BAGCHI, O Division of Reactor Safety Research 80/12/31
Available at NRC #3 75 07454 253
- 8101130408 NUREQ/CR-1024
ASSESSMENT OF FRACCON-1 3E/EM CALCULATED FISSION GAS
RELEASE IN RISO FUEL RODS
CHAMBERS, R, LAATS, E T EG&G Idaho, Inc FIN A-6167
EOC-CAAP-5219 80/12/31 21pp 07454 243
- 8101130414 NUREQ/CR-1023
DESCRIPTION & CHARACTERIZATION OF EVALUATION MODELS IN
FRACCON-1
LAATS, E T, CHAMBERS, R EG&G Idaho, Inc FIN A-6167
EOC-CAAP-5217 80/12/31 45pp 07454 202
- 8101130683 Forwards draft guidelines, "Draft Emergency Action
Guidelines for Nuclear Power Plants," for interim use
DEBTON, H R Office of Nuclear Reactor Regulation, Director
7/7/07/19 1p 07454 182
- 8101130694 NUREQ-0610
DRAFT EMERGENCY ACTION LEVEL GUIDELINES FOR NUCLEAR POWER
PLANTS
* Office of Nuclear Reactor Regulation, Director 7/7/07/19
19pp 07454 183
- 8101140539 NUREQ/CR-1171
THE EFFECT OF CRACK LENGTH AND SIDE GROOVES ON THE DUCTILE
FRACTURE TOUGHNESS PROPERTIES OF ASTM A533 STEEL
CARLSON, K W, WILLIAMS, J A Hanford Engineering Development
Laboratory FIN D-3-0119 HDL-TPE 79-65 80/01/31 71pp
Available at NTIS 07157 252
- 8101140544 NUREQ-0533
FUEL PERFORMANCE ANNUAL REPORT Period Through December 1978
HOUSTON, M D Division of Systems Safety 7/7/12/31 30pp
Available at NTIS 07457 221
- 8101140550 NUREQ-0623
GENERIC ASSESSMENT OF DELAYED REACTOR COOLANT PUMP TRIP
DURING SMALL BREAK LOSS-OF-COOLANT ACCIDENTS IN PRESSURIZED
WATER REACTORS
SHELDON, B Tril-2 Bulletins & Orders 7/7/11/30 79pp Avail
NTIS 07457 145
- 8101140716 Forwards NUREQ-0090, Vol 3, Number 2, "Rept to Congre
ADs, Apr-June 1980" Two ADs at operating nuclear power
plants involved loss of decay heat removal & failure of
control rods to fully insert during scram W/d encl
AHEARNE, J F Commissioners 80/12/05 1p 07458 313
- 8101140725 Forwards NUREQ-0090, Vol 3, Number 2, "Rept to Congre
ADs, Apr-June 1980" Two ADs at operating nuclear power
plants involved loss of decay heat removal & failure of
control rods to fully insert during scram
SHELDON, B Commissioners 80/12/05 1p 07458 313

--8101140736 NUREG-0690 V3 N22
REPORT TO CONGRESS ON ANNUAL OCCURRENCES April-June 1980
• Office of Management and Program Analysis BO/11/30 38pp
Available at NTIS 07450 315

8101140723 NUREG/CR-1169
SAFEGUARD VULNERABILITY ANALYSIS PROGRAM (SVAP) Executive
Summary
JILMAN, F. M., DITTMER, M. H., GRVINS, H. J. Lawrence Livermore
Laboratory File A-0115 UCRL-52724 BO/04/30 34pp Available at
NTIS 07457 113

8101150307 NUREG/CR-1811
NUCLEAR REACTOR SAFETY Quarterly Progress Report for
April-June 1980
STEVENSON, M. O., WIGIL, J. C. Los Alamos Scientific Laboratory File
A-7014 LA-B507-PR BO/11/30 72pp Available at NTIS
07463 290

8101150801 NUREG/CR-1174
A STUDY TO DETERMINE THE FEASIBILITY OF CONDUCTING
EPIDEMIOLOGIC INVESTIGATIONS OF THE HEALTH EFFECTS OF
LOW LEVEL IONIZING RADIATION Phase I Report
DREYER, A. A., CLAPP, R. W., COVINO, S. J. Equifax Health Systems Div
File B-1070-9 RM-901-9 BO/05/31 132pp Available at NTIS
07464 005

8101190513 Comments on NUREG-0668 re NRC review of Heisterberg rept NRC
assessment on biological absorption of radionuclides is
narrow in scope & does not account for meteorological
conditions suggests use of plant-specific analysis method
ROBERTS, T. H. Affiliation Unknown BO/12/30 7pp 07475 069

8101190520 NUREG/CR-1045
ACUTE EFFECTS OF INHALATION EXPOSURE TO URANIUM HEXAFLUORIDE
& PATTERNS OF DEPOSITION Corrected Pages 29 & 31
• Rochester Univ. of BO/12/30 3pp 07475 026

8101210219 Comments on NUREG-0518 re possession, use & transfer of low
enriched U as contaminant in metals Opposes NUREG
SHIVELY, P. P., SHIVELY, V. M. Affiliation Unknown 45FR70874 1394
BO/12/08 1p 07487 252

8101210271 NUREG/CR-1794 V3
SUMMARY OF ACTIVITIES & ACCOMPLISHMENTS AUGUST 1 TO
OCTOBER 31, 1979 A PROPOSAL TO DEVELOP A METHOD FOR THE
DETECTION OF HELIUM EMPLOYING CHEMILUMINESCENCE REACTIONS
Progress Report, Volume 3
NEARBY, R. P. Los Alamos Scientific Laboratory File A-7210
LA-B595-PR BO/11/30 12pp Available at NTIS 07490 072

8101210278 NUREG/CR-1787
EXPERIMENTAL & STATISTICAL INVESTIGATION OF THERMALLY
INDUCED FAILURE IN REACTOR FUEL PARTICLES
LUNSFORD, J. L., IMPRESCIA, R. J., BOHMAN, A. L. Los Alamos Scientific
Laboratory File A-7014 LA-B547-MS BO/10/31 26pp Available at
NTIS 07490 091

8101210285 NUREG-0530 V3 N06
ADVANCED REACTOR SAFETY RESEARCH Status Summary Report Data
as of November 30, 1979 Volume 3, Number 6 (Buff Book)
• Office of Nuclear Regulatory Research, Director 79/11/30 77pp.
Available at NTIS.

8101210597 Responds to FOIA request for final version of generic EIS
re U milling, NUREG-0705 Forwards documents listed in App A
H/O encl
FELTON, J. M. Division of Rules and Records 81/01/13 2pp
07487 131

8101220249 PNL-2950
"Valuing Environ Via Bidding Games Psychological
Perspective." Interim reprint excerpt from NUREG/CR-0989, Vol 2.
App B
NEDEBT, J. A., SHIKHAR, R., PERRY, R. W. Battelle Memorial Institute,
Pacific Northwest Laboratory PNL-2950 BO/08/31 50pp
07503 280

8101220501 NUREG/CR-1240 V4
LIGHT WATER REACTOR PRESSURE VESSEL IRRADIATION SURVEILLANCE
DOSIMETRY Quarterly Progress Report October-December 1979
Volume 4
GUTHRIE, O. L., MCCLROY, W. N. Hanford Engineering Development
Laboratory File B-5988-7 MEDL-TME 80-3 BO/12/31 80pp
Available at NTIS \$5.50 07500 323

8101220603 NUREG/CR-1240 V3
LIGHT WATER REACTOR PRESSURE VESSEL IRRADIATION SURVEILLANCE
DOSIMETRY Quarterly Progress Report, July-September 1979.
Volume 3
GUTHRIE, O. L., MCCLROY, W. N. Hanford Engineering Development
Laboratory File B-5988-7 MEDL-TME 80-2 BO/12/31 65pp.
Available at NTIS 07497 316

8101220619 NUREG-0540 V2 N07
TITLE LIST OF DOCUMENTS MADE PUBLICLY AVAILABLE
1-30, 1980 Volume 2, Number 9
• Office of Administration BO/12/31 485pp
07309 001

8101220647 Transcript of Commission 810115 meeting
re action plan items due Jan 1981 Pp 1-47
• Commissioners 81/01/15 49pp 07502 143

8101230658 Transcript of Commission 810115 meeting
status of SRP Pp 1-38
• Commissioners 81/01/15 41pp 07512 296

8101260079 NUREG-0669 V3
FIXED SITE PHYSICAL PROTECTION UPGRADE RULE GUIDANCE
COMPENDIUM Volume 3
EVANS, L. J., ALLEN, T. Regulatory Improvements Branch
450pp Available at NTIS 07519 030

8101260114 NUREG/CR-1614
APPROACHES TO ACCEPTABLE RISK A CRITICAL GUIDE
FISCHOFF, B., LICHTENSTEIN, S., SLOVIC, P. Decision
B-0424 ORNL/SUB-7556/1 BO/12/31 336pp 0752

8101260127 NUREG/CR-1398
EVALUATION OF TECHNIQUES FOR DYNAMIC MEASUREMENT
MOTION IN LIQUID-METAL-COOLED FAST-BREEDER REACTOR
EXPERIMENTS
EVANS, A. E. Los Alamos Scientific Laboratory File
BO/10/31 67pp

8101260136 NUREG/CR-1070
AN EVALUATION OF THE UNLOADING COMPLIANCE PROCEDURES
INTEGRAL TESTING IN THE HOT CELL Final Report.
CLARKE, O. A. Westinghouse Electric Corp File B-01
ORNL/SUB-7594/1 79/10/31 71pp 07523 157

8101260144 NUREG/CR-1717 V4
SOIL-STRUCTURE INTERACTION METHODS SLAM CODE Volume
CONSTANTINO, C., MILLER, C. A. Brookhaven National Lab
A-3216-9 ORNL-NUREG-51263 79/09/30 150pp 075

8101260163 NUREG/CR-1717 V3
SOIL-STRUCTURE INTERACTION METHODS SIM CODE Volume
MILLER, C. A., CONSTANTINO, C. Brookhaven National Lab
A-3216-9 ORNL-NUREG-51263 79/09/30 98pp 075

8101270301 NUREG-0030 V3 N03
CONSTRUCTION STATUS REPORT, NUCLEAR POWER PLANTS
August 31, 1980 For Period May 1, 1980 - August 31, 1980
(Yellow Book) Volume 3, Number 3
• Commissioners 80/12/31 156pp. Available at

8101270131 NUREG/CR-1645
THE FWR LOSS-OF-COOLANT ACCIDENT ANALYSIS CAPABILITY
WRAP-FW SYSTEM
GREGORY, M. V., BERANEK, F. Savannah River Ecology Lab
B-4126-8 DPGT-NUREG-80-1. BO/08/31 47pp. 075

8101270583 Forwards Page 7 for NUREG/CR-0773, "Train
Personnel for Performing Measurements for Control
Accounting of SNM."
• Division of Technical Information & Document Co
1p. 07543 359

--8101270589 NUREG/CR-0773 ERR
ERRATA (PAGE 7) for NUREG/CR-0773, "TRAINING AND
PERSONNEL FOR PERFORMING MEASUREMENTS FOR CONTROL
ACCOUNTING OF SPECIAL NUCLEAR MATERIAL."
• Battelle Memorial Institute, Pacific Northwest
BO/12/30 1p. 07543 360

8101270602 NUREG/CR-1806
HEAVY-SECTION STEEL TECHNOLOGY PROGRAM QUARTERLY P
REPORT FOR JULY-SEPTEMBER 1980
WHITMAN, O. D., BRYAN, R. H. Oak Ridge National Labor
ORNL/NUREG/TM-4 BO/12/31 70pp. Available at

8101270810 NUREG-0540 V2 N10
TITLE LIST OF DOCUMENTS MADE PUBLICLY AVAILABLE
October 1-31, 1980 Volume 2, Number 10
• Office of Administration 81/01/31 481pp
07183 001

8101270818 NUREG/BR-0007
INSTRUCTIONS FOR COMPLETING MATERIAL BALANCE REPORT
PHYSICAL INVENTORY LISTING & CONCISE NOTE FORMS (P
NRC-712, 742C & 740M).
• Office of Nuclear Material Safety & Safeguards.
07542 103

B101270827 NUREQ/CR-1738
 "AN ADVANCED THERMOHYDRAULIC SIMULATION CODE FOR POOL-TYPE
 LMFBRs (SSC-P CODE)"
 MADNI, F. K. Brookhaven National Laboratory FIN A-3015
 BNL-NUREG-91280. 80/09/30 105pp Available at NTIS

B101270838 NUREQ/CR-1510
 CONTAMINATION CONTROL IN SANDIA EQUATION-OF-STATE
 EXPERIMENTS
 DREITUNG, W. H. Sandia Laboratories FIN A-1016 SAND80-1277
 80/10/31 112pp Available at NTIS. 07546 185

B101270861 NUREQ/CR-1157 V3
 THERMAL/HYDRAULIC ANALYSIS RESEARCH PROGRAM QUARTERLY
 REPORT, JULY-SEPTEMBER 1980 Volume 3
 THOMPSON, S. L. Sandia Laboratories FIN A-1205 SAND80-1091
 80/08/31 116pp Available at NTIS. 07541 140

B101270867 NUREQ-0380 V4 N03
 PROGRAM SUMMARY REPORT Volume 4 Number 3
 * Office of Management and Program Analysis 80/03/21 94pp
 Available at NTIS 07542 281

B101270943 NUREQ/CR-1818
 FUEL PERFORMANCE ANNUAL REPORT FOR 1979
 TOKAR, M. Core Performance Branch BAILEY, W. J., CUNNINGHAM, M. E.
 Battelle Memorial Institute, Pacific Northwest Laboratory FIN
 B-2320 PNL-3583 81/01/31 45pp Available at NTIS \$2.50
 07542 239

B101280187 Documents B10114 telcon clarifying NUREQ-0737 items
 11 K J 24 & 11 K J 29 Loss of alternating current power is
 intended to mean only loss of offsite power for both items
 & failure of onsite emergency power need not be assumed
 WATERS, D. B. BWR Owners Group. BWR80 8114 81/01/23 1p
 07558:051.

B101290008 Discusses review of NUREQ-0731 to evaluate regulation bases
 for approved IMI action plan items. Categorization to cover
 wide variation outlined w/o encl recommended procedure for
 add'l items & categorization tables.
 SCINTO, J. V. Hearings Division 81/01/16 4pp 07567 186

B101290024 Forwards comments on NUREQ-0660 re NRC action plan developed
 as result of IMI-2 accident. Plan should require inserting of
 BWR Mark III & PWR ice containments
 BATES, A. The Nuclear Regulatory Commission 45FR50613 C04
 80/12/09. 2pp. 07568 337.

B101290062 Forwards addendum to SAND80-0701, "Assessment of Core
 Penetration of PWR Reactor Vessel & Particulate Debris
 Coolability in TMLD, S2D & ABC Accidents"
 LIPINSKI, R. J. Sandia Laboratories. 80/11/10. 1p 07309 001

--B101290066 NUREQ/CR-1518 ADD
 ASSESSMENT OF CORE PENETRATION OF PWR REACTOR VESSEL &
 PARTICULATE DEBRIS COOLABILITY IN TMLD, S2D & ABC
 ACCIDENTS Addendum
 * Sandia Laboratories SAND80-0701 80/11/10 5pp 07309 001

B101290180 NUREQ/CR-1132
 A SURVEY OF POTENTIAL LIGHT WATER REACTOR FUEL ROD FAILURE
 MECHANISMS & DAMAGE LIMITS
 COURTRIGHT, E. L. Battelle Memorial Institute, Pacific Northwest
 Laboratory PIN B-2150 PNL-2787 79/07/31 48pp. Available at
 NTIS 07575 322

B101290465 Informs of three errors in NUREQ/CR-1746, "Steam Explosion
 Efficiency Studies."
 CORRADINI, M. L. Sandia Laboratories. SAND80-1324 81/01/19 3pp
 07568 337

B101290509 Staff requirements memo re B10115 briefing on SRP revisions
 due in Apr 1981. No requests or requirements forwarded
 CHILK, S. J. Office of the Secretary of the Commission MB10115B
 81/01/16. 1p 07568 353

B101290632 "ASYMMETRIC BLOWDOWN LOADS ON PWR PRIMARY SYSTEMS."
 RESOLUTION OF GENERIC TASK ACTION PLAN A-2.
 HOSFORD, S. B., MATTU, R., MEYER, R. D. Division of Safety Technology
 81/01/31 81pp. Available at NTIS \$4.00 07574 001

B101290684 Forwards NUREQ-0609, "Asymmetric Blowdown Loads on PWR
 Primary Sys.," providing NRC resolution of Unresolved Safety
 Issue Task A-2. Rept covers development of loading transients
 & structural analysis criteria w/o encl.
 DENTON, H. R. Office of Nuclear Reactor Regulation, Director
 81/01/05. 1p. 07576 145

B101290692 NUREQ/CR-1842
 REACTIVITY INITIATED ACCIDENT TEST SERIES. TEST RIA 1-2
 FUEL BEHAVIOR REPORT
 OCH, S. A., FUKUDA, S. K., MARTINSON, Z. R. Idaho National Engineer-
 ing Laboratory FIN A-6041 EG0-2073 81/01/31 56pp Available
 NTIS 07574 302

B101290694 Forwards NUREQ-0609, "Asymmetric Blowdown Loads on PWR
 Primary Sys.," providing NRC resolution of Unresolved Safety
 Issue Task A-2. Rept covers development of loading transients
 & structural analysis criteria w/o encl.
 DENTON, H. R. Office of Nuclear Reactor Regulation, Director
 81/01/05. 1p. 07574 192

B101290695 Comments on NUREQ-0518 re possession, use & transfer
 enriched U as contaminant in metals Opposes NUREQ
 JONES, A. Affiliation Unknown 45FR70874 1947 80/12/08
 07183 001

B101290700 NUREQ-0485 V3 N01
 BUFF BOOK SYSTEMATIC EVALUATION PROGRAM Status Summary
 Report Volume 3, Number 1 Data as of December 1, 1980
 RUSSELL, W. T. Systematic Evaluation Program Branch CRUTCHER,
 Operating Reactors Branch 5 80/12/01 66pp Available at
 \$3.75 07567 293.

B101290703 NUREQ/CR-1641
 EXPERIMENT DATA REPORT FOR SEMISCALE MOD-3 SMALL BREAK TEST
 S-07-100 (GASLINE TEST SERIES)
 SACKETT, K. E., CLEGOL, L. B. Idaho National Engineering Laboratory
 A-6038 EG0-2065 80/12/31 57pp Available at NTIS 07574 302

B101290706 NUREQ/CR-0006
 INSTRUCTIONS FOR COMPLETING NUCLEAR MATERIAL TRANSACTION
 REPORTS Forms DCE/NRC-741, 741A & 7404
 * Office of Nuclear Material Safety & Safeguards 81/01/01
 07574 079

B101290710 Forwards NUREQ-0609, "Asymmetric Blowdown Loads on PWR
 Primary Sys.," providing NRC resolution of Unresolved Safety
 Issue Task A-2. Rept covers development of loading transients
 & structural analysis criteria w/o encl.
 DENTON, H. R. Office of Nuclear Reactor Regulation, Director
 81/01/05. 1p. 07574 244

B101290745 NUREQ/CR-1907
 LMFBR ACCIDENT DECLARATION STUDY, PHASE I, FINAL REPORT
 WILLIAMS, D. C., SHELTON, J. A., SCIACCA, F. H. Sandia Laboratories
 A-1197 SAND80-1267 80/11/30 609pp 07564 076

B101290796 NUREQ/CR-1791
 LMFBR AEROSOL RELEASE & TRANSPORT PROGRAM QUARTERLY
 PROGRESS REPORT FOR APRIL-JUNE 1980
 KRESS, T. S., TOBIAS, M. L. Oak Ridge National Laboratory FIN
 ORNL/NUREG/TM-4 80/12/31 38pp Available at NTIS 07560

B101290811 NUREQ/CR-1790
 LMFBR AEROSOL RELEASE & TRANSPORT PROGRAM QUARTERLY
 PROGRESS REPORT FOR JANUARY-MARCH 1980.
 KRESS, T. S., TOBIAS, M. L. Oak Ridge National Laboratory FIN
 ORNL/NUREG/TM-4 80/12/31 37pp. Available at NTIS 07568

B101290817 NUREQ/CR-1768
 ADVANCED TWO-PHASE FLOW INSTRUMENTATION PROGRAM QUARTERLY
 PROGRESS REPORT FOR APRIL-JUNE 1980
 TURNAGE, X. G., DAVIS, C. E., ANDERSON, R. L. Oak Ridge National
 Laboratory FIN B-0401 ORNL/NUREG/TM-4 80/12/31 27pp
 Available at NTIS 07568:138

B101290819 NUREQ/CR-1601
 LIGHT-WATER-REACTOR SAFETY RESEARCH PROGRAM Quarterly
 Progress Report, April-June 1980
 MASSEY, W. E., TILL, C. E. Argonne National Laboratory. FIN A-2
 ANL-80-107 80/10/31 41pp Available at NTIS 07568 183

B101290825 NUREQ/CR-1794 V4
 SUMMARY OF ACTIVITIES & ACCOMPLISHMENTS, FINAL REPORT A
 PROPOSAL TO DEVELOP A METHOD FOR THE DETECTION OF HELIUM
 EMPLOYING CHEMILUMINESCENCE REACTIONS, Volume 4
 NEARY, M. P. Los Alamos Scientific Laboratory FIN A-7210
 LA-8396-PR. 81/01/31 51pp Available at NTIS 07568 269

B101300009 NUREQ-CR-1859
 SYSTEMS INTERACTION STATE-OF-THE-ART REVIEW & METHODS
 EVALUATION
 LIM, J. J., RICE, T. R., MCCORD, R. K. Lawrence Livermore Laboratory
 A-0247 UCRL-53016 81/01/31 134pp Available at NTIS
 07579 094

STRUCTURAL ANALYSIS (Criteria 170 ENCL)
LEWIS, H. R. Office of Nuclear Reactor Regulation, Director
81/01/25 1p 07579 217

8101300153 NUREG/CR-1071
PARTICLE ANALYSIS OF MIXED-OXIDE NUCLEAR FUEL MATERIALS BY
ENERGY DISPERSIVE X-RAY FLUORESCENCE
EIDSON, A. F. SEVPE, P. B. MACHELL, C. A. Lovelace Biomed & Environmental
Research Institute FIN A-1031 LMF-90 81/01/31 17pp
Available at NTIS \$1.75 07579 302

8101300209 NUREG/CR-1650
INITIAL QUANTIFICATION OF HUMAN ERRORS ASSOCIATED WITH
REACTOR SAFETY SYSTEM COMPONENTS IN LICENSED NUCLEAR POWER
PLANTS
LOHMEYER, J. J. HALL, R. E. Brookhaven National Laboratory FIN A-9219
81-NUREG-5123 81/01/31 42pp Available at NTIS \$2.25
07579 224

8101300217 NUREG/CR-1605
PROGRAM FOR FIELD VALIDATION OF THE SYNTHETIC APERTURE
FOCUSING TECHNIQUE FOR ULTRASOUND TESTING (SAFT UT)
JACKSON, J. L. Southwest Research Institute FIN 8-5605 81/01/31
42pp Available at NTIS \$2.25 07579 263

8101300225 NUREG/CR-0912 V1
GEOSCIENCE DATA BASE HANDBOOK FOR MODELING A NUCLEAR WASTE
REPOSITORY Volume 1
SHEER, GUD, D. Lawrence Livermore Laboratory FIN A-0277 UCRL-52719
V1 81/01/31 358pp Available at NTIS \$7.50 07581 001

8101300397 NUREG-0400 V4 R01
LICENSEE CONTRACTOR & VENDOR INSPECTION STATUS REPORT
Quarterly Report, March 31, 1980, Volume 4, Number 1
* Office of Inspection & Enforcement, Office of the Director
80/03/31 195pp Available at NTIS 07579 264

8101300439 NUREG-0020 V4 R12
OPERATING UNITS STATUS REPORT, LICENSED OPERATING REACTORS
Data as of November 30, 1980 Volume 4, Number 12 (Grey Book)
* Office of Management and Program Analysis 80/12/31 163pp
Available at NTIS \$12.50

8101300768 NUREG/CR-1465
REACTIVITY INITIATED ACCIDENT TEST SERIES TEST RIA 1-1
(RADIAL AVERAGE FUEL ENTHALPY OF 205 CAL/G) FUEL BEHAVIOR
REPORT
CEIFFERT, S. L. MARTINSON, L. R. FUKUDA, S. M. EG&G Idaho, Inc FIN
A-6041 EGG-2040 80/09/30 137pp Available at NTIS 07183 001

CRC CORRESPONDENCE WITH OTHER ORGANIZATIONS

8012230207 Summary of 801119 meeting w/Int of Nuclear Power Operations
in Bethesda, MD Info on organizational roles exchanged &
possibility of interface to further efforts in regulation
process discussed
RICHARDSON, S. B. Reactor Systems Branch 80/11/19 4pp 07317 046

8101090516 Informs that IE Bulletin 80-25, "Operating Problem w/Target
Rock Safety Relief Valves at BWRs," was sent to listed
licensees on 801219
CARROLL, D. E. Region 3, Chicago, Office of the Director 80/12/19
2pp 07390 261

8101070645 Advises that encl IE Circular 80-25, "Case Histories of
Radiography Events," should be issued on 801209 Draft
transmittal ltr also encl
THORNBURG, H. D. Division of Reactor Construction Inspection
80/11/24 8pp 03897 117

8101090337 Requests analyses of interactions of severe geophysical
events, earthquakes & volcanic eruptions, w/state & local
plans for radiological emergency preparedness around
commercial power plant in region per NRC request
MCNEELY, J. H. Federal Emergency Management Agency 80/12/01 1p
07187 001

8101090312 Advises that IE Info Notice 80-17, "Potential Hazards
Associated w/Interchangeable Parts on Radiographic
Equipment," was sent to listed licensees on 800505
PAPPAS, H. Region 3, Chicago, Office of the Director 80/05/06
8pp 07425 254

8101090765 Informs that branch has not commented on NCA-3800 for
several yrs Changes made to Jul 1980 draft were made w/o NRC
involvement Suggests discussion of changes w/Reedy, chairman,
Subcommittee III of ASME Boiler & Pressure Vessel Committee
HAASS, W. P. Quality Assurance Branch 80/11/10 1p 07430 354

8012150262 Forwards comments on draft ANSI N45-N551 2, in response to
801114 request Section 11 2 re QA/QC requirements should be
rewritten
HAASS, W. P. Quality Assurance Branch 80/12/01 7pp 03779 329

8101150457 Forwards branch responses to 801028 memo requesting review
of stds re qualification of ASME Code Class 2 & 3 pumps for
safety sys & qualification for turbine drives
MURLEY, I. E. Division of Safety Technology 80/12/17 1p
07462 244

8101150465 Forwards Mechanical Engineering Branch comments on draft
ANSI N45-N551 2 re qualification of ASME Code Class 2 & 3
pumps for safety sys & N551 3 re qualification for turbine
drives, in response to 801114 request
BOSWELL, R. J. Mechanical Engineering Branch 80/12/12 14pp
07462 248

8101160275 Advises that IE Info Notice 80-45, "Potential Failure of
Backup Manual Scram Capability," was sent to listed
licensees on 801217
CARROLL, D. E. Region 3, Chicago, Office of the Director 80/12/18
2pp 07470 275

8101190246 Confirms NRC support for FEMA radiological emergency plan
training programs for FY81, in response to 801217 request.
ORMES, B. K. Emergency Preparedness Program Office (after 801119
18E) 80/12/30 1p 07476 073

8101210634 Forwards Radiological Health Stds Branch Info Rept 9 re
epidemiologic study of civilian employees at Portsmouth
Naval Shipyard for placement in PDR
GOLDSMITH, R. Radiological Health Standards Branch 81/01/07 2pp
07488 343

8101210637 Radiological Health Stds Branch Info Rept 9 re epidemiologic
study of civilian employees at Portsmouth Naval Shipyard.
GOLDSMITH, R. Radiological Health Standards Branch 81/01/06
2pp 07488 345

8101230472 Forwards permanent measuring point elevation for Well 27
table of water levels reflecting elevation changes since Jul
1980 installation
WATSON, L. R. Interior, Dept of, Geological Survey 81/01/03 2pp
07510 301

8101270534 Submits list of facilities within UB not associated
w/activities w/direct natl security significance to govt of
US
* Commissioners 80/11/26 40pp 07543 308

8101280573 50-80-84
Safety guide, "Site Selection & Evaluation for Nuclear Power
Plants w/Respect to Population Distribution"
* International Atomic Energy Agency (Austria) 80/12/31 32pp
07107 001

PR PRGPOSED RULE

8012110279 Comments on proposed rule 10CFR20 re disposal of liquid
scintillation media & animal carcasses containing tritium &
C-14 Supports rule Urges NRC to continue to study ways
of reducing low level waste requiring special disposal
AHMAD, M. St Louis Univ. Medical Center St Louis, MO 45FR6701B
178 80/11/10 1p 07225 302

8012120051 Comments by Intersociety Council for Biology & Medicine on
proposed rule 10CFR20 re disposal of liquid scintillation
media & animal carcasses containing tritium & C-14 Supports
proposal
MORGAN, T. E. Affiliation Unknown 45FR6701B 210 80/11/21 1p
07230 285

8012120057 Comments on proposed rule 10CFR20 re disposal of liquid
scintillation media & animal carcasses containing tritium &
C-14 Supports proposal Proposed limits are too low
DUNAWAY, G. A. Southern Illinois Univ., School of Medicine 45FR67
211 80/11/18 1p 07237 299

8012290476 Transcript of 801211 meeting in Washington, DC re UECV-80-
474C Pp 1-32
* Commissioners 80/12/11 34pp 07335 066

--B01229083 SECY-80-474C

Suppls SECY-80-474 & forwards clarifying changes to 10CFR60
final rule & conforming amendments
DIRCKS, W J Office of the Executive Director for Operations
80/12/09 16pp 07335 104

B01229089 Transcript of B01211 Affirmation Session B0-54 in
Washington, DC re SECY-80-448, SECY-A-80-169 & SECY-80-482
Pp 1-11
* Commissioners 80/12/11 13pp

B01050637 Comments on repts re waste mgt & waste confidence
rulemaking siting & design & cost of geologic repositories
is relatively simple Demonstration of facts is important
work to be performed
PHILBRICK, G B Philbrick, G B 80/11/06 1p 07387 019

B01070004 Responds to FOIA request for four categories of documents re
cold shutdown w/regard to fire protection requirements in
App R to 10CFR50 Forwards D Davis 790613 memo & P Matthews/
J Knight memo re 790220 review group meeting
FELTON, J M Division of Rules and Records 80/12/30 1p
07414 182

B01070026 Responds to FOIA request for all documents discussing or
identifying alternatives to fire protection requirements of
App R to 10CFR50 Documents are available in PDR
FELTON, J M Division of Rules and Records 80/12/31 1p
07414 189

B01070028 FOIA request for all documents discussing or identifying
alternatives to fire protection requirements of App R to
10CFR50
WATKINS, M Debovoise & Liberman 80/12/12 2pp 07414 190

B01070172 Comments on behalf of Kerr-McGee Nuclear Corp., United Nuclear
Corp., United Nuclear Homestake Partners, Union Carbide Corp.,
Amesoka Copper Co., Gulf Oil Corp & Western Nuclear, Inc. on
proposed rule 10CFR20 re U mill activities Opposes rule
NICKLES, P J MONTANGE, C H Covington & Burling 45FR26072 006
80/10/28 19pp 07411 003

--B01070178 Memorandum in support of motion for partial summary
judgment re U milling Summary judgment should be granted
CROUT, O S United Nuclear - Homestake Partners BLACK, B D
Kerr-McGee Nuclear Corp. CROUT, O S Bigbee, Stephenson, Carpenter,
Crout & Dinstead CIV 80-0203C 80/07/17 41pp 07411 140

--B01070186 Statement of natl facts as to which there is no genuine
issue Exhibits A-I encl
CROUT, O S United Nuclear - Homestake Partners BLACK, B D
Kerr-McGee Nuclear Corp. CROUT, O S Bigbee, Stephenson, Carpenter,
Crout & Dinstead CIV 80-0203C 80/07/17 100pp 07411 181

B01070230 Comments on proposed rule 10CFR2 re proposed NRC
enforcement policy Opposes rule
MILLER, R A Henry County Health Center, Mt Pleasant, IA 45FR66754
047 80/12/01 2pp 07419 241

B01070347 Comments on waste confidence rulemaking as requested in
Waste Mgt Subcommittee B01113-14 meeting Continued min reinit
& surveillance will insure safety & practicality of spent
fuel storage in reactor water basins
ALBAUGH, F W Affiliation Unknown 80/11/19 3pp 07408 133

B01070582 Comments on proposed rules 10CFR30.40, 70.150 & 170 re
revision of radiation protection stds codified as 40CFR190
Requests that NRC stay implementation of 40CFR190 pending
resolution of uncertainties & ambiguities re compliance.
OVERTON, J A American Mining Congress 44FR50012 80/12/04 4pp

--B01070590 Transcript of B01114 proceedings re 40CFR190 in Silver
Spring, MD Pp 1-99
* Commissioners 44FR50012 80/11/14 60pp

B01070600 Comments on proposed rules 10CFR30.40, 70.150 & 170 Renew
B01014 request to NRC to stay enforcement & implementation
of 40CFR190 Requests that encl petition & apps filed w/EPA
be made part of record to incorporate 40CFR190 into 10CFR20
OVERTON, J A American Mining Congress 44FR50012 80/11/07 4pp

--B01070628 Forwards petition filed w/EPA re reconsideration &
revision of radiation protection stds for nuclear power
operation in 40CFR190 Requests that NRC stay enforcement &
implementation pending EPA consideration of petition
OVERTON, J A American Mining Congress 44FR50012 80/10/14
4pp.

--B01070638 Requests for relief from 40CFR170 re environ radiation
protection stds for nuclear power operations Rulemaking
proceeding should be reopened for reconsideration & revision
of 25 mmer Apps A & B encl
MCCABE, E A American Mining Congress THOMPSON, A J Homel. P
McCabe & Saunders 80/10/14 375pp

B01080024 Comments by State Water Resources Control Board on proposed
rule 10CFR20 re disposal of liquid scintillation media &
animal carcasses containing tritium & C-14 Opposes rule
WHITNEY, C California, State of 45FR67018 308 80/11/26 4pp
07419 304

B01080028 Comments on proposed rule 10CFR20 re disposal of liquid
scintillation media & animal carcasses containing tritium &
C-14 Opposes rule
CROWELL, L A Harrisburg Hosp Harrisburg, PA 45FR67018 307
80/12/08 2pp 07419 302

B01080032 Comments by College of Physicians & Surgeons of Columbia
Univ on proposed rule 10CFR20 re disposal of liquid
scintillation media & animal carcasses containing tritium &
C-14 Supports rule
GONAY, W D Affiliation Unknown 45FR67018 310 80/11/20 1p
07419 301

B01080035 Comments by Director of Environ Health & Safety at Medic
Civ on proposed rule 10CFR20 re disposal of liquid
scintillation media & animal carcasses containing tritium &
C-14 Supports rule
STEPHENS, R S Illinois, Univ of, at Chicago Circle 45FR67018
80/12/11 1p 07419 300

B01080042 Comments on proposed rule 10CFR20 re disposal of liquid
scintillation media & animal carcasses containing tritium &
C-14 Supports rule, but suggests deferring change until
sufficient info available to make risk & cost assessments
HEDEMAN, W N Environmental Protection Agency 45FR67018 312
80/12/11 6pp 07419 292

B01080047 Forwards RJ Blarshat B01205 ltr commenting on proposed r
10CFR2 re proposed general statement of policies &
procedures for enforcement action
REUSB, H S Congress, Joint Economic Committee 45FR66734 055
80/12/12 1p 07419 289

--B01080057 Comments by Milwaukee Children's Hosp on proposed rule
10CFR2 re proposed general statement of policy & procedure
for enforcement actions Opposes rule Rule should
exempt health care facilities
STARSHAW, R J Affiliation Unknown 45FR66734 055 80/12/05
2pp 07419 290

B01080065 Comments on proposed rule 10CFR2 re proposed general
statement of policy & procedure for enforcement actions
Civil penalties will not ensure compliance w/NRC
requirements Orders & immediate action ltrs should be used
BURKE, D J Affiliation Unknown 45FR66734 053 80/12/09 2pp
07419 261

B01080127 Forwards comments on proposed rule 10CFR50 re considera
of degraded or melted cores in safety regulation
LOOYIS, J B Sargent & Lundy, Inc 45FR65474 007 80/12/12 3p
07417 357

B01080132 Comments on proposed rule 10CFR50 re domestic licensing
of production & utilization facilities Rule must not be
used as excuse to delay safety improvements
LEWIS, M I Affiliation Unknown 45FR65474 006 80/12/10 10pp
07309:001

B01070544 Certified summary of ACRS Waste Mgt B01003 meeting in
Washington, DC re proposed rulemaking on technical criteria
for regulating geological disposal of high level radwaste
* ACRS - Advisory Committee on Reactor Safeguards 80/11/20
07442 188.

B01070871 Comments on proposed rule 10CFR170 re fees for review of
applications Rule should not be adopted
AXELRAD, M Lowenstein, Newman, Reis, Axelrad & Toll. 45FR74493 001
80/12/05 2pp. 07439 061

B01090877 Forwards comments on behalf of AL Power Co on proposed
10CFR170 re fees for review of applications To assess fees
where application for permit or license was denied, withdrawn
or suspended is beyond statutory authority of NRC.
JORDAN, A L, Balch, Dingham, Baker, Hawthorne, Williams & Ward.
45FR74493 002 80/12/05 11pp 07430:050

B101090711 Comments on proposed rule 10CFR2 re proposed enforcement policy. Policy should reflect greater need for discretion in determining enforcement actions
JEH.S. W. H. Detroit Edison Co 45FR6754 051 80/12/08 2pp
07443 355

B101100341 Informs that Steering Group on Development of Safety Goal will concentrate on three extant approaches to formulating criteria during 801120 meeting. Decision was made in view of fundamental difference in nature of approaches
LIBAKKIN, M. J. AC95 - Advisory Committee on Reactor Safeguards
80/11/28 2pp 07443 331

B101130146 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FABRE, V. A. Affiliation Unknown 45FR70874 0509 80/12/08 1p

B101130150 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FABRE, L. Affiliation Unknown 45FR70874 0512 80/12/08 1p

B101130156 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MEIKENZIE, M. Affiliation Unknown 45FR70874 0513 80/12/08 1p

B101130163 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
AUGUSTE, D. Affiliation Unknown 45FR70874 0514 80/12/08 1p

B101130169 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SMITH, D. Affiliation Unknown 45FR70874 0518 80/12/08 1p

B101130172 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SCHEVER, C. Affiliation Unknown 45FR70874 0521 80/12/08 1p

B101130177 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FOURTH, E. J. Affiliation Unknown 45FR70874 0522 80/12/08 1p

B101130185 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
EVANS, H. Affiliation Unknown 45FR70874 0526 80/12/08 1p

B101130189 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CISTERNINO, M. Affiliation Unknown 45FR70874 0529 80/12/08 1p

B101130192 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 0530 80/12/08 1p

B101130197 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
GREEN, S. Affiliation Unknown 45FR70874 0532 80/12/08 1p

B101130202 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SCALERA, A. Affiliation Unknown 45FR70874 0534 80/12/08 1p

B101130207 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HEISLER, M. Affiliation Unknown 45FR70874 0535 80/12/08 1p

B101130212 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 0517 80/12/08 1p

B101130255 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
GONZALEZ, G. Affiliation Unknown 45FR70874 0469 80/12/08 1p

B101130261 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BALL, J. R. Affiliation Unknown 45FR70874 0471 80/12/08 1p

B101130263 Forwards "Proposed Changes in NRC Reactor Safety Policy Response to NRC Invitation for Comments on Degraded Cores in Safety Regulation"
HUBBARD, H. W. R & D Associates 80/12/31 1p 07451 293

--B101130274 "Proposed Changes in NRC Reactor Safety Policy Response to NRC Invitation for Comments on Degraded Cores in Safety Regulation"
HOLLIDAY, D. HUBBARD, H. W. LATTE, A. R & D Associates 80/12/29 21pp 07451 254

B101130267 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 0472 80/12/08 1p

B101130275 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
DEQUPEO, C. Affiliation Unknown 45FR70874 0474 80/12/08 1p

B101130280 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LUCAS, J. Affiliation Unknown 45FR70874 0475 80/12/08 1p

B101130286 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KENDALL, G. Affiliation Unknown 45FR70874 0476 80/12/08 1p

B101130290 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SHIPP, G. M. Affiliation Unknown 45FR70874 0477 80/12/08 1p

B101130301 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
NIORD, R. Affiliation Unknown 45FR70874 0480 80/12/08 1p

B101130306 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ROSB, P. Affiliation Unknown 45FR70874 0481 80/12/08 1p

B101130312 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MERCADO, I. Affiliation Unknown 45FR70874 0482 80/12/08 1p

B101130316 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
NASIRANKA, A. Affiliation Unknown 45FR70874 0483 80/12/08 1p

B101130319 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HODGE, A. M. Affiliation Unknown 45FR70874 0484 80/12/08 1p

B101130324 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCKENZIE, L. Affiliation Unknown 45FR70874 0489 80/12/08 1p

B101130328 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SMITH, D. Affiliation Unknown 45FR70874 0485 80/12/08 1p

NONDOCKETED ITEMS

B011130332 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
DEISEL, C Affiliation Unknown 45FR70874 0487 80/12/05 1p

B011130335 Forwards "Proposed Changes in NRC Reactor Safety Policy. Response to NRC Invitation for Comments on Degraded Cores in Safety Regulation"
HUBBARD, H W R & D Associates B1/01/06 1p 07451 331

B011130338 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
JOYCE, P Affiliation Unknown 45FR70874 0479 80/12/05 1p

B011130343 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
Affiliation Unknown 45FR70874 0473 80/12/05 1p

B011130347 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
JOYCE, M Affiliation Unknown 45FR70874 0470 80/12/05 1p

B011130351 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LEE, K Affiliation Unknown 45FR70874 0536 80/12/05 1p

B011130361 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
DORNET, C Affiliation Unknown 45FR70874 0533 80/12/05 1p

B011130367 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PAPEGNI, F Affiliation Unknown 45FR70874 0525 80/12/05 1p

B011130393 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
RAMS, Y Affiliation Unknown 45FR70874 0537 80/12/03 1p

B011140042 Requests review & comments on encl working paper no later than B01205 Comments will be used in preparation of preliminary policy paper
SEGE, O Office of Policy Evaluations 80/12/01 5pp 07460 255

B011140054 Submits highlights of D Sidebotham & C Iselin B01117 interviews Safety-cost tradeoff should be permissible only after prescribed min safety level is met Cost should not bar retrofit.
SEGE, O Office of Policy Evaluations 80/12/08 2pp 07460 260

B011140066 Informs that outline proposed in working paper re safety goal formulation suffers from definitional confusion
Outline should be restricted to safety goals.
LABARKIN, M U ACRS - Advisory Committee on Reactor Safeguards 80/12/04 3pp 07460 262

B011140074 Informs of NC Rasmussen B01117 interview to gain benefit of views re establishment of safety goals Demand for probable risk assessment exceeds available supply of people.
SEGE, O Office of Policy Evaluations 80/12/10 3pp 07460 292

B011140084 Submits comments on notice of proposed general policy evaluation of Agreement State radiation control programs.
NRC is attempting futile effort in finding clear cut guide w/numerical indicators to judge compatibility
FUNDERBURG, R D Idaho, State of 80/10/30 2pp 07461 231

B011140090 Informs of D Bridenbaugh & R Hubbard B01105 interviews re views on safety-goal formulation Safety assurance effectiveness depends on factors that involve direct costs to utility.
SEGE, O Office of Policy Evaluations 80/12/04 2pp 07460 295

B011140092 Submits comments on revised criteria for evaluation of Agreement State programs, in response to State of NV B01015 ltr.
WILSON, E F Arkansas, State of 80/10/28 2pp 07461 233

B011140096 Advises that comments on NRC proposed statement of policy on evaluation of Agreement State radiation control programs were received from 13 states. Submits comments from TN.

B011140102 Informs of V Jakimovic, WJ Houghton & CR Fisher B01104 interviews re thoughts on safety-goal formulation
Quantitative safety goals should be set before other major rulemakings are completed
SEGE, O Office of Policy Evaluations 80/12/08 2pp 07460

B011140116 Comments on behalf of Kerr-McOee Nuclear Corp on proposed policy re evaluation of Agreement State radiation control programs Statement asserts authority over Agreement States which NRC does not possess.
NICHOLSON, P J, MONTAGNE, C H Covington & Gurling 4565726 001 80/11/14 19pp 07458 170

B011140122 Submits comments on proposed statement of policy on guide for evaluation of Agreement State radiation control programs
SPELL, N H Louisiana, State of 80/12/19 2pp 07461 209

B011140127 Comments on proposed rule 10CFR2 re interim enforcement policy Policy statement is uncompromising & inflexible
RAY, C W Wisconsin Electric Power Co 45FR66754 048 80/12/03 3pp 07462 113

B011140134 Submits comments on guide for evaluation of Agreement radiation control programs Rept should remain as uncodified guide
DERUSE, L D Georgia, State of 80/12/16 1p 07461 194

B011140138 Comments on behalf of Milwaukee Children's Hosp on proposed rule 10CFR2 re general statement of policy & procedure for enforcement actions. Rule should exempt health care facilities
STARSHAW, R J Affiliation Unknown 45FR66754 053 80/12/05 07462 111

B011140141 Submits comments on NRC proposed statement of policy evaluation of Agreement State radiation control programs No objections to proposal
CLARK, U Florida, State of 80/12/12 1p 07461 196

B011140146 Forwards comments on proposed rule 10CFR2 re general statement of policy & procedure for enforcement actions. Portions of policy need clarifying to eliminate as many questions as possible
SHINNICK, J B American Electric Power Co., Inc HUNTER, R S Indiana & Michigan Electric Co 45FR66754 052 80/12/08 11p 07462 100

B011140147 Advises of no addl comments on NRC proposed guide for evaluation of state radiation control programs
MOUNT, D K North Dakota, State of 80/12/19 1p 07304 001

B011140379 Comments on proposed rule 10CFR2 re policy & procedure enforcement actions Public comment period should be extended by 30 days
REMLEY, M E Rockwell International Corp - Energy Systems Div 45FR66754 071 80/12/23 1p 07462 088

B011140423 Comments on proposed rule 10CFR2 re policy & procedure enforcement actions Comment period should be extended by 70 days Here time is needed to review vast amount of natl
1000RGVICH, H I Scientists & Engineers for Secure Energy 45FR 80/12/18 2pp 07462 077

B011140431 Comments on proposed rule 10CFR2 re policy & procedure enforcement actions Univ-owned research & training reactors should be exempt from rule. Policy discriminates against nuclear facilities w/o substantial financial resources
CUNNINGHAM, R O Pennsylvania State Univ 45FR66754 069 80/12/04 2pp 07462 075

B011140446 Comments on proposed rule 10CFR2 re policy & procedure enforcement actions Fines are much too high relative to listed violations, especially in categories other than power reactors.
GEORGE, K D Affiliation Unknown 45FR66754 068 80/12/17 2pp 07462 073

B011140527 Comments on proposed rule 10CFR2 re policy & procedure enforcement actions Rule is unreasonable Includes harsh requirement in dealing w/low level radiation Consultant presentation at NRC B01202 public hearing encl
BOCKEL, R T Palos Community Hosp, Palos Park, IL 45FR66754 067 80/12/04 5pp 07462 048

B011140532 Comments on proposed rule 10CFR2 re policy & procedure enforcement actions Concept of levying fines for accidents, should be applied to other industries Addl comments encl.

B101140537 Comments on proposed rule 10CFR2 re policy & procedure for enforcement actions Policy is unfair Nuclear reactors & other high-powered industrial applications are considered at same public safety, risk level as health physics
LANZEL, W H Lakeland Hosp Elkhorn, WI 45FR66754 057 80/12/10 3pp 07462 031

B101140541 Comments on proposed rule 10CFR2 re policy & procedure for enforcement actions Supports rule Large fines should be levied for violations
EHLIN, J S Affiliation Unknown 45FR66754 056 80/12/12 2pp 07308 001

B101140552 Comments on proposed rule 10CFR2 re policy & procedure for enforcement actions Requests reply to encl ltr from Milwaukee Children's Hosp expressing opinion that hosp need no further bureaucratic intervention.
ZAGLICKI, C J House of Rep 45FR66754 064 80/12/12 2pp 07462 027

B101140553 Comments on proposed rule 10CFR2 re policy & procedure for enforcement actions Community, hosp & other radiisotope users practice prudent radiation safety NRC already has authority to mandate corrective action whenever necessary
GRUBB, W B REED, S A St Elizabeth Hosp Appleton, WI 45FR66754 061 80/12/15 2pp 07461 295

B101140560 Comments on proposed rule 10CFR2 re policy & procedure for enforcement actions Antideficiency Act prohibits one govt agency from fining another Violations should be reviewed on case by case basis Automatic fines encourage noncompliance
RUSSELL, D H Interior, Dept of, Geological Survey 45FR66754 066 80/12/15 1p 07462 047

B101140565 Comments on proposed rule 10CFR2 re policy & procedure for enforcement actions Requests extension of comment period to B10227, to allow thorough review of complex issues
FRESTONE, E A General Electric Co 45FR66754 052 80/12/17 1p 07308 001

B101140573 Comments on proposed rule 10CFR2 re policy & procedure for enforcement actions Rule is counterproductive. Licensees will not rest problems if penalty will be imposed
DEESTER, U L Kansas Gas & Electric Co 45FR66754 065 80/12/17 3pp 07462 044

B101140578 Comments on proposed rule 10CFR2 re policy & procedure for enforcement actions Requests that comment period be extended until B10301, to permit company & clients opportunity to develop detailed comments & suggested alternatives
KNUTH, D F KMC, Inc 45FR66754 059 80/12/19 1p 07462 043

B101140583 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ACMLE, D Affiliation Unknown 45FR70874 1477 80/12/10 1p

B101140585 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
TREXLER, K Affiliation Unknown 45FR70874 1479 80/12/10 1p

B101140586 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
TERRY, J Affiliation Unknown 45FR70874 1478 80/12/10 1p

B101140588 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
DEES, M Affiliation Unknown 45FR70874 1474 80/12/10 1p

B101140590 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BRIGIER, K Affiliation Unknown 45FR70874 1467 80/12/10 1p

B101140592 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ANDERSON, F J Affiliation Unknown 45FR70874 1463 80/12/10 1p

B101140593 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
DEKER, K Affiliation Unknown 45FR70874 1466 80/12/10 1p

B101140599 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BERDIN, A Affiliation Unknown 45FR70874 1464 80/12/10 1p

B101140603 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
JENKINS, D Affiliation Unknown 45FR70874 1473 80/12/10

B101140604 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MORROW, E Affiliation Unknown 45FR70874 1472 80/12/10

B101140607 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ADAMS, J A Affiliation Unknown 45FR70874 1471 80/12/10

B101140610 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
GITLIN, S E Affiliation Unknown 45FR70874 1470 80/12/10

B101140614 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
OLMER, K Affiliation Unknown 45FR70874 1469 80/12/10

B101140624 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MITCHELL, M Affiliation Unknown 45FR70874 1476 80/12/10

B101140629 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SHEER, E Affiliation Unknown 45FR70874 1475 80/12/10

B101140637 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LITTLEJOHN, J Affiliation Unknown 45FR70874 1390 80/12/10

B101140643 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FERGUSON Affiliation Unknown 45FR70874 1399 80/12/10

B101140651 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
COLELL, G Affiliation Unknown 45FR70874 1398 80/12/10

B101140676 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WILSON, K Affiliation Unknown 45FR70874 1397 80/12/10

B101140683 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CROGELL, H Affiliation Unknown 45FR70874 1396 80/12/10

B101140688 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
DEWITT, C Affiliation Unknown 45FR70874 1468 80/12/10

B101140774 Forwards proposed rule 10CFR2.50.70 & 73. "Protect Unclassified Safeguards Info." Required rept to Congress will be submitted concurrent w/issuance of final rule w/encl
AHEARNE, J F Commissioners 80/12/22 1p 07457 030

--B101140779 Forwards proposed rule 10CFR2.50.70 & 73. "Protect Unclassified Safeguards Info." Required rept to Congress will be submitted concurrent w/issuance of final rule w/encl
AHEARNE, J F Commissioners 80/12/22 1p 07457 031

--B101140786 Forwards proposed rule 10CFR2.50.70 & 73. "Protect Unclassified Safeguards Info." Required rept to Congress will be submitted concurrent w/issuance of final rule w/encl
AHEARNE, J F Commissioners 80/12/22 1p 07457 032

--B101140790 Forwards proposed rule 10CFR2.50.70 & 73. "Protect Unclassified Safeguards Info." Required rept to Congress will be submitted concurrent w/issuance of final rule w/encl
AHEARNE, J F Commissioners 80/12/22 1p 07457 033

--B101140779 Forwards proposed rule 10CFR2.50.70 & 73. "Protection of Unclassified Safeguards Info." Required rept to Congress will be submitted concurrent w/issuance of final rule W/o encl
McEARNNE, J F Commissioners 80/12/22 1p 07497 034

--B101140802 Forwards proposed rule 10CFR2.50.70 & 73. "Protection of Unclassified Safeguards Info." Required rept to Congress will be submitted concurrent w/issuance of final rule
McEARNNE, J F Commissioners 80/12/22 1p 07487 035

--B101140811 "Protection of Unclassified Safeguards Info." 10CFR2.50.70 & 73 proposed rule Regulations identify types of safeguards info to be protected, establish min protection requirements & set conditions for access to safeguards info
CHILKIS, J Office of the Secretary of the Commission 80/12/19 27pp 07497 036

B101140962 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BURNETT, P Affiliation Unknown 45FR70874 1504 80/12/05 1p

B101140964 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MAY, T S Affiliation Unknown 45FR70874 1503 80/12/07 1p

B101140971 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
RASHTI, A Affiliation Unknown 45FR70874 1501 80/12/08 1p

B101140976 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LYKOS, M Affiliation Unknown 45FR70874 1507 80/12/08 1p

B101140981 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
RASHTI, J Affiliation Unknown 45FR70874 1500 80/12/09 1p

B101140986 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
DYER, J F Affiliation Unknown 45FR70874 1505 80/12/10 1p

B101140989 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
DONALLEY, R H Affiliation Unknown 45FR70874 1508 80/12/10 1p

B101150095 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SHOVER, D J Affiliation Unknown 45FR70874 1510 80/12/10 1p

B101150105 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PELLETIER, B C Affiliation Unknown 45FR70874 1506 80/12/10 1p

B101150109 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ZANE, A J Affiliation Unknown 45FR70874 1509 80/12/10 1p

B101150123 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LYONS, K Affiliation Unknown 45FR70874 1495 80/12/10 1p

B101150132 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BERNERSHEIM, K Affiliation Unknown 45FR70874 1436 80/12/10 1p

B101150143 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FRIEDMAN, P Affiliation Unknown 45FR70874 1487 80/12/10 1p

B101150148 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ADCOCK, A Affiliation Unknown 45FR70874 1498 80/12/10 1p

B101150157 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CANALE, J D Affiliation Unknown 45FR70874 1460 80/12/10

B101150160 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
GELM, C Affiliation Unknown 45FR70874 1461 80/12/10 1p

B101150164 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BUTLER, A Affiliation Unknown 45FR70874 1462 80/12/10

B101150173 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HOFMANN, A Affiliation Unknown 45FR70874 1450 80/12/10

B101150179 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
GLADSTAR, R Affiliation Unknown 45FR70874 1491 80/12/10

B101150184 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
DELEQ, T D Affiliation Unknown 45FR70874 1452 80/12/10

B101150191 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WINTERG, C Affiliation Unknown 45FR70874 1453 80/12/10

B101150194 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ROWLAND, A Affiliation Unknown 45FR70874 1454 80/12/10

B101150200 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SZABAT, S Affiliation Unknown 45FR70874 1443 80/12/10

B101150207 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HOWER, J Affiliation Unknown 45FR70874 1444 80/12/10 1p

B101150213 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HUGHES, G Affiliation Unknown 45FR70874 1445 80/12/10

B101150228 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
TALBOT, P Affiliation Unknown 45FR70874 1446 80/12/10

B101150226 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FOLDVARY, D Affiliation Unknown 45FR70874 1447 80/12/10

B101150239 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
GIBBS, C Affiliation Unknown 45FR70874 1448 80/12/10 1p

B101150257 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CHRISTENSEN, B Affiliation Unknown 45FR70874 1449 80/12/10

B101150267 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MANGAN, A Affiliation Unknown 45FR70874 1436 80/12/10

B101150272 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCHRA, A Affiliation Unknown 45FR70874 1439 80/12/10 1p

B101150277 Comments by Ecology Action Educational Inst on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
Affiliation Unknown 45FR70874 1438 80/12/10 1p

B101150283 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SCHMIDT, M Affiliation Unknown 45FR70874 1437 80/12/10 1p

B101150293 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
VECKHIGNE, P Affiliation Unknown 45FR70874 1442 80/12/10 1p.

B101150298 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FELDER, V E Affiliation Unknown 45FR70874 1440 80/12/10 1p

B101150479 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SHONK, K Affiliation Unknown 45FR70874 0624 80/12/01 1p

B101150480 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LCMBARDI, C Affiliation Unknown 45FR70874 0571 80/12/02 1p

B101150486 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 0627 80/12/02 1p

B101150842 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
COMPLEHAN, M Affiliation Unknown 45FR70874 0541 80/11/29 1p

B101150844 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BRENNAN, T Affiliation Unknown 45FR70874 0638 80/11/25 1p

B101150848 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ATKINSON, A Affiliation Unknown 45FR70874 1395 80/12/07 1p

B101150852 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCDDUGALL, J Affiliation Unknown 45FR70874 0612 80/12/04 1p

B101150858 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCCEMA, C Affiliation Unknown 45FR70874 0593 80/12/04 4p

B101160003 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SHARP, R H Affiliation Unknown 45FR70874 1393 80/12/09 1p.

B101160006 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 1480 80/12/09 1p

B101160008 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HARLAN, M F Affiliation Unknown 45FR70874 1469 80/12/09 1p

B101160010 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
COPE, C Affiliation Unknown 45FR70874 1481 80/12/09 1p

B101160011 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
COBY, S Affiliation Unknown 45FR70874 1488 80/12/09 1p

B101160013 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 1392 80/12/09 1p

B101160015 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SCHILLING, R K Affiliation Unknown 45FR70874 1383 80/12/09 1p

B101160018 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MARKER, R A Affiliation Unknown 45FR70874 1437 80/12/10 1p

B101160023 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 1442 80/12/10 1p.

B101160027 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SHURT, H Affiliation Unknown 45FR70874 1440 80/12/10 1p

B101160032 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCLEVAY, F Affiliation Unknown 45FR70874 0624 80/12/01 1p

B101160041 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BARRONS, D C Affiliation Unknown 45FR70874 0571 80/12/02 1p

B101160048 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LASTY, S Affiliation Unknown 45FR70874 0627 80/12/02 1p

B101160052 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
RASHID, J Affiliation Unknown 45FR70874 0541 80/11/29 1p

B101160060 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LEE, D C Affiliation Unknown 45FR70874 0638 80/11/25 1p

B101160066 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PETRIE, E R Affiliation Unknown 45FR70874 1395 80/12/07 1p

B101160075 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
GAFFNEY, E Affiliation Unknown 45FR70874 0612 80/12/04 1p

B101160093 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LIEBHART, P C Affiliation Unknown 45FR70874 0593 80/12/04 4p

B101160103 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
DEWITT, D Affiliation Unknown 45FR70874 1393 80/12/09 1p.

B101160112 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
REINSON, S Affiliation Unknown 45FR70874 1480 80/12/09 1p

B101160121 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MATTHEW, D Affiliation Unknown 45FR70874 1469 80/12/09 1p

B101160130 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FRASER, B Affiliation Unknown 45FR70874 1481 80/12/09 1p

B101160139 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BILLIG, B Affiliation Unknown 45FR70874 1488 80/12/09 1p

B101160149 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BRIGHTMAN, N Affiliation Unknown 45FR70874 1392 80/12/09 1p

B101160160 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PITTS, M Affiliation Unknown 45FR70874 1383 80/12/09 1p

81016056B Comments on proposed rules 10CFR30.32.70 & 150 re
possession, use & transfer of low enriched U as contaminant
in metals Opposes rules
KAUFMAN, M Affiliation Unknown. 45FR70874 0899. 80/12/10

B101160571 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SCHUMWAY, W. Affiliation Unknown 45FR70874 089B 80/12/18 1p

B101160576 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
JOHNS, J. Affiliation Unknown 45FR70874 0691 80/12/18 1p

B101160578 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WIENER, J. Affiliation Unknown 45FR70874 0692 80/12/18 1p

B101160583 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SCLEATU, J. Affiliation Unknown 45FR70874 0593 80/12/18 1p

B101160586 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCGUIRE, D. Affiliation Unknown 45FR70874 0694 80/12/18 1p

B101160592 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
DUBENSKY, M. D. Affiliation Unknown 45FR70874 0908 80/12/18 1p

B101160590 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FESTER, R. Affiliation Unknown 45FR70874 0910 80/12/18 1p

B101160603 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SAVAGE, G. Affiliation Unknown 45FR70874 0911 80/12/18 1p

B101160609 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
JHUNDEL, D. C. Affiliation Unknown 45FR70874 0912 80/12/18 1p

B101160614 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
JEANVITON, L. Affiliation Unknown 45FR70874 0913 80/12/18 1p

B101160618 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
RIVERA, A. Affiliation Unknown 45FR70874 0914 80/12/18 1p

B101160625 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
GREEN, M. Affiliation Unknown 45FR70874 0915 80/12/18 1p

B101160632 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
TRYLIE, M. Affiliation Unknown 45FR70874 0916 80/12/18 1p

B101160638 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
REYES, E. Affiliation Unknown 45FR70874 0906 80/12/18 1p.

B101160643 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MUSKELLY, M. Affiliation Unknown 45FR70874 0917 80/12/18 1p

B101160647 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SINDLER, L. Affiliation Unknown 45FR70874 158B 80/12/05 1p

B101160652 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules.

B101160656 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as co in metals Opposes rules
VILLAR, M. S. Affiliation Unknown 45FR70874 0902

B101160658 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as co in metals Opposes rules
SEIMEN, A. E. Affiliation Unknown 45FR70874 158D

B101160687 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as co in metals Opposes rules.
VIESTI, G. Affiliation Unknown 45FR70874 1607

B101160692 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as co in metals Opposes rules
REISERT, I. Affiliation Unknown 45FR70874 1608

B101160695 Comments on proposed rule 10CFR50 re con degraded or melted cores in safety regulation. Int approach to rulemaking should be taken. Priority given to safety goal & methodology development
LEE, B. Atomic Industrial Forum 45FR65474 021 07469 083.

--B101160697 Forwards comments on proposed rule 10CFR50 re degraded or melted cores in safety regulation. emergency planning rule should be re-examined.
GIBBS, D. C. Atomic Industrial Forum. 45FR65474 34pp 07469:085

B101160698 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as co in metals Opposes rules
BUDOFF, D. S. Affiliation Unknown 45FR70874 0639

B101160701 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as co in metals Opposes rules
SWILL, H. Affiliation Unknown 45FR70874 1612

B101160702 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as co in metals Opposes rules
BERKEN, S. I. Affiliation Unknown 45FR70874 1074

B101160705 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as co in metals Opposes rules
BUDRETZKY, F. Affiliation Unknown 45FR70874 1075

B101160707 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as co in metals Opposes rules
COHEN, H. I. Affiliation Unknown 45FR70874 1046

B101160710 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as co in metals Opposes rules
BRADY, R. Affiliation Unknown 45FR70874 1552

B101160712 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as co in metals Opposes rules
TOSK, S. Affiliation Unknown 45FR70874 1613

B101190001 Comments by Nuclear Util Group on Enforcement rule 10CFR2 re policy & procedure for enforcement. Sanctions should be designed & imposed to encourage licensees to initiate programs for solving problems
COUNCIL, W. O., REVNDLDS, N. S. Affiliation Unknown 80/12/31 103pp 07474 082

B101190002 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as co in metals Opposes rules
SMITH, J. Affiliation Unknown 45FR70874 0904

B101190003 Comments on proposed rules 10CFR30.32.70 re possession, use & transfer of low enriched U as co in metals Opposes rules.
BAHAD, M. Affiliation Unknown 45FR70874 0903

NONDOCKETED ITEMS

B101190036 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MURTHA, M Affiliation Unknown 45FR70874 0907 80/12/01 1p

B101190038 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WHEELER, J Affiliation Unknown 45FR70874 0897 80/12/01 1p

B101190011 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MONTEPEQUE, J E Affiliation Unknown 45FR70874 0895 80/12/01 1p

B101190014 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
RODRIGUEZ, D Affiliation Unknown 45FR70874 0920 80/12/01 1p

B101190016 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CHIMI, E Affiliation Unknown 45FR70874 0901 80/12/01 1p

B101190018 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CAMPBELL, H Affiliation Unknown 45FR70874 0926 80/12/01 1p

B101190020 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MORGAN, J F Affiliation Unknown 45FR70874 0925 80/12/01 1p

B101190022 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KENISTON, J Affiliation Unknown 45FR70874 0940 80/12/01 1p

B101190024 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LABOW, A Affiliation Unknown 45FR70874 0939 80/12/01 1p

B101190027 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CHUM, M Affiliation Unknown 45FR70874 0938 80/12/01 1p

B101190029 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BURNS, J Affiliation Unknown 45FR70874 0941 80/12/01 1p

B101190033 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MULLEN, J Affiliation Unknown 45FR70874 1365 80/12/10 1p

B101190039 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
TORBENSON, L Affiliation Unknown 45FR70874 1359 80/12/10 1p

B101190047 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
Affiliation Unknown 45FR70874 1360 80/12/10 1p

B101190055 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
Affiliation Unknown 45FR70874 1363 80/12/10 1p

B101190057 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
GROSS, L Affiliation Unknown 45FR70874 1358 80/12/10 1p

B101190062 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LAUGHING-DLF, P Affiliation Unknown 45FR70874 1329 80/12/10 1p

B101190065 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CORRIAN, L Affiliation Unknown 45FR70874 1324 80/12/10 1p

B101190057 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FEBL, M Affiliation Unknown 45FR70874 1325 80/12/10 1p

B101190070 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
STIEFF, A Affiliation Unknown 45FR70874 1326 80/12/10 1p

B101190073 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
VALERIO, M P Affiliation Unknown 45FR70874 1327 80/12/10 1p

B101190075 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WASSERMAN, J H Affiliation Unknown 45FR70874 1335 80/12/10 1p

B101190079 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MAUNILL, D Affiliation Unknown 45FR70874 1333 80/12/10 1p

B101190081 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SYMONIK, D Affiliation Unknown 45FR70874 1332 80/12/10 1p

B101190084 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KINKHEAD, D Affiliation Unknown 45FR70874 1331 80/12/10 1p

B101190086 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WITKOWSKI, R C Affiliation Unknown 45FR70874 1330 80/12/10 1p

B101190091 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CREBBMAN, D Affiliation Unknown 45FR70874 1328 80/12/10 1p

B101190093 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
COLMAN, L Affiliation Unknown 45FR70874 1329 80/12/10 1p

B101190111 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MIRO, L Affiliation Unknown 45FR70874 1533 80/12/10 1p

B101190117 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LADDY, B Affiliation Unknown 45FR70874 1532 80/12/10 1p

B101190121 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WIDALL, N Affiliation Unknown 45FR70874 1530 80/12/10 1p

B101190126 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BLAKELY, H S Affiliation Unknown 45FR70874 1529 80/12/10 1p

8101190593 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
GCRPCUB Affiliation Unknown 45FR70874 0592 80/12/03 1p

8101190597 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
GUTHRIEFELD P Affiliation Unknown 45FR70874 0575 80/12/03 1p

8101190599 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 0581 80/12/03 1p

8101190594 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ARNDIC D L Affiliation Unknown 45FR70874 0576 80/12/03 1p

8101190624 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PLEYER S Affiliation Unknown 45FR70874 0574 80/12/03 1p

8101190651 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ARQUA E C Affiliation Unknown 45FR70874 0644 80/12/03 1p

8101190658 Comments on general policy statement on evaluation of Agreement State radiation control plan Revision period of 4 or 5 yrs may allow for more efficient use of staff LR Holon
801114 memo to J South end
DANLEBBERGER J New York, State of 80/12/03 2pp 07476 093

8101190657 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BODDIE R Affiliation Unknown 45FR70874 0641 80/12/03 1p

8101190665 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ROTH E Affiliation Unknown 45FR70874 1060 80/12/03 1p

8101190666 Comments on general policy statement on evaluation of Agreement State radiation control plans Agreement State reviews should be conducted by third party
YOUNG R E Affiliation Unknown 80/12/22 2pp 07183 001

8101190670 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
IAMUNDO M Affiliation Unknown 45FR70874 1033 80/12/03 1p

8101190673 Comments on general policy statement on evaluation of Agreement State radiation control plans. More emphasis should be placed on technical advisory committees & consultants & on competence of senior staff
O'DRIE M J Affiliation Unknown 80/12/18 2pp 07123 001

8101190681 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LEVINE S Affiliation Unknown 45FR70874 1037 80/12/03 1p

8101190687 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SALZHAUER S Affiliation Unknown 45FR70874 1038 80/12/03 1p

8101190693 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SACHS C Affiliation Unknown 45FR70874 1049 80/12/03 1p

8101190697 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BLAUDEL C Affiliation Unknown 45FR70874 1572 80/12/03 1p

8101190712 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ACKSON R Affiliation Unknown 45FR70874 1579 80/12/03 1p

8101190719 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
YEGAMI B Affiliation Unknown 45FR70874 1604 80/12/03 1p

8101190723 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SHAPERO J Affiliation Unknown 45FR70874 1617 80/12/03 1p

8101190731 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SHANGELMAN R Affiliation Unknown 45FR70874 1618 80/12/03 1p

8101190736 Comments on proposed rules 10CFR30.32 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCMEHILLIN E R Affiliation Unknown 45FR70874 1621 80/12/03 1p

8101190752 Transcript of Commission 801222 meeting in Washington, D.C. re SECY 80-474 Pp 1-79 W/related info
* Commissioners 80/12/22 100pp 07472 324

8101200010 Comments on proposed rules 10CFR50 & 51. "Proposed Rulemaking on Storage & Disposal of Nuclear Waste." Ability to validate models could become crucial to confidence question
STEINCLER H Argonne National Laboratory 80/11/18 2pp 07487 015

8101200011 Comments on proposed rules 10CFR50 & 51. "Proposed Rulemaking on Storage & Disposal of Nuclear Waste." Current direction of deep geologic disposal at environmentally favorable sites w/high integrity packages is safe
FOSTER R F Affiliation Unknown 80/11/21 5pp 07487-009

8101200127 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
YORK J Affiliation Unknown 45FR70874 1493 80/12/03 1p

8101200130 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SABRACCI T Affiliation Unknown 45FR70874 1495 80/12/03 1p

8101200133 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
AYTELL J Affiliation Unknown 45FR70874 1067 80/12/03 1p

8101200138 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LAURENCE W Affiliation Unknown 45FR70874 1065 80/12/03 1p

8101200143 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MATHIEWS D Affiliation Unknown 45FR70874 1056 80/12/03 1p

8101200149 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HAFUANO K D Affiliation Unknown 45FR70874 1064 80/12/03 1p

8101200153 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BOSCH A Affiliation Unknown 45FR70874 1068 80/12/03 1p

8101200156 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MUELLER M Affiliation Unknown 45FR70874 1069 80/12/03 1p

8101200160 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
IMBODEN E Affiliation Unknown 45FR70874 1070 80/12/03 1p

8101200163 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
JETHINS M Affiliation Unknown 45FR70874 1071 80/12/03 1p

B101200166 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules NEEDLEMAN, L Affiliation Unknown 45FR70874 1073 80/12/07 1p	B101200318 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules ROBEY, L Affiliation Unknown 45FR70874 1080 80/12/04 1p
B101200173 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules AURA, D Affiliation Unknown 45FR70874 1052 80/12/09 1p	B101200320 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules WASSERBACH, A E Affiliation Unknown 45FR70874 1066 80/12/04 1p
B101200177 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules SCHABRACK, P Affiliation Unknown 45FR70874 1053 80/12/09 1p	B101200321 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules HART, R Affiliation Unknown 45FR70874 1027 80/12/04 1p
B101200203 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules DOL, J Affiliation Unknown 45FR70874 1072 80/12/10 1p	B101200397 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules ZEIGER, EY, K Affiliation Unknown 45FR70874 1060 80/12/04
B101200212 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules LITVICK, D Affiliation Unknown 45FR70874 1051 80/12/10 1p	B101200407 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules * Affiliation Unknown 45FR70874 1059 80/12/04 1p
B101200215 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules DIAMOND, R Affiliation Unknown 45FR70874 1459 80/12/10 1p	B101200410 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules CASTAFIAN, L Affiliation Unknown 45FR70874 1098 80/12/04
B101200222 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules HOPKINS, T R Affiliation Unknown 45FR70874 1463 80/12/10 1p	B101200421 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules AGATA, C Affiliation Unknown 45FR70874 1006 80/12/04 1p
B101200224 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules GARRETT, P Affiliation Unknown 45FR70874 1493 80/12/10 1p	B101200425 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules REGAN, A Affiliation Unknown 45FR70874 1561 80/12/04 1p
B101200226 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules ULMER, A Affiliation Unknown 45FR70874 1496 80/12/10 1p	B101200429 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules ESPPOSITO, M L Affiliation Unknown 45FR70874 1062 80/12/04
B101200230 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules ULMER, J W Affiliation Unknown 45FR70874 1494 80/12/10 1p	B101200434 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules COHEN, A Affiliation Unknown 45FR70874 1065 80/12/04 1p
B101200262 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules SHERI, Z Affiliation Unknown 45FR70874 0033 80/12/03 1p	B101200439 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules FIER, A Affiliation Unknown 45FR70874 1066 80/12/04 1p
B101200265 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules MENDOZ, P Affiliation Unknown 45FR70874 0054 80/12/03 1p	B101200443 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules MACDONALD, S Affiliation Unknown 45FR70874 1069 80/12/04
B101200267 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules FOSTER, L A Affiliation Unknown 45FR70874 0056 80/12/03 1p	B101200447 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules SULLIVAN, M Affiliation Unknown 45FR70874 1071 80/12/04
B101200270 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules CASADO, D Affiliation Unknown 45FR70874 0057 80/12/03 1p	B101200451 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules PARA, A Affiliation Unknown 45FR70874 1075 80/12/04 1p
B101200272 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules RABELAIS, P Affiliation Unknown 45FR70874 0058 80/12/03 1p	B101200456 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules QZEROTT, B Affiliation Unknown 45FR70874 1076 80/12/04
B101200276 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules DUNFORD, J Affiliation Unknown 45FR70874 0059 80/12/03 1p	B101200461 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules SMITH, E Affiliation Unknown 45FR70874 1080 80/12/04 1p
B101200283 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules NEGRI, P Affiliation Unknown 45FR70874 0052 80/12/03 1p	B101200464 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules OAKTON, W Affiliation Unknown 45FR70874 1083 80/12/04 1p
B101200308 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules * Affiliation Unknown 45FR70874 1097 80/12/04 2pp	

9101200532 Comments on proposed rules 10CFR30.32.70 & 150 re
possession, use & transfer of low enriched U as contaminant
in metals Opposes rules
PICCOLI, A M Affiliation Unknown 45FR70874 1594 80/12/05 1p

8101210013 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LEONARD, R Affiliation Unknown 45FR70874 1619. 80/12/05 10

BIO1210199 Comments on proposed rules 10CFR30.32, 70 & 150 re
 possession, use & transfer of low enriched U as contaminant
 in metals Opposes rules
 HADDIX, K F Affiliation Unknown 45R70B74 1378 80/12/GB 1p

8101210263 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LWKDS-K Affiliation Unknown J5FR70G74 1517 80/12/08 1p

B101210447 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals. Opposes rules
LUNNEY, M. Affiliation: Unknown. J58F70874 0577 HQ/12/08

8101210450 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ORSHINE, J Affiliation Unknown 45FR70B74 0580 80/12/08 1p

8101210456 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ZAHADIAI, D Affiliation Unknown 45FR70B74 0584 80/12/08 1p

8101210540 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BLUMENTHAL, J Affiliation Unknown 45FR70B74 0592 80/12/08 2pp

8101210546 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KAGAN, M Affiliation Unknown 45FR70B74 0595 80/12/08 2pp

8101210551 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BEWDE, W. J Affiliation Unknown 45FR70B74 0637 80/12/08 2pp

8101210552 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BORT, S. Affiliation Unknown 45FR70B74 0601 80/12/08 2pp

8101210556 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CUTUTO, G Affiliation Unknown 45FR70B74 0589 80/12/05 1p

8101210559 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCRIK, B Affiliation Unknown 45FR70B74 1308 80/12/08 1p

8101210562 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BRAZ, Z. Affiliation Unknown 45FR70B74 1306 80/12/08 1p

8101210564 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
JAMISON, L Affiliation Unknown 45FR70B74 1307 80/12/08 1p

8101210567 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BELIQ, A Affiliation Unknown 45FR70B74 1311 80/12/08 1p

8101210570 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FAULKNER, M. L Affiliation Unknown 45FR70B74 1319 80/12/08 1p

8101210573 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SEROUTON, N Affiliation Unknown 45FR70B74 1318 80/12/08 1p

8101210579 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
RIBORDANI, B Affiliation Unknown 45FR70B74 1317 80/12/08 1p

8101220003 Memorandum & order directing Commission working group to file by 810129 rept summarizing record & identifying key issues. Participants may submit comments on rept within 35 days of filing Certificate of Svc encl
CHILK, B. J. Office of the Secretary of the Commission 81/01/16 11pp. 07501 310

8101220064 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
AUTREY, S. F. Affiliation Unknown 45FR70B74 1323 80/12/07 1p

8101220068 Comments on behalf of WA Energy Facility Site Evaluation Council on proposed rule 10CFR2 re policy & procedure for enforcement actions Policy appears rational & reasonable Supports rule
FITCH, W. L. Washington, State of 45FR66754 058 80/12/10 2pp 07500 066

8101220072 Comments on behalf of State Board of Health on proposed rule 10CFR2 re policy & procedure for enforcement actions Large fines on nuclear power plants will not achieve improvement in safety records of involved utilities
PICKARD, R. C. Indiana, State of 45FR66754 073 80/12/22 1 07500 065

8101220074 Comments on proposed rule 10CFR2 re policy & procedure for enforcement actions Except for serious & willful violations or gross negligence, civil penalties should be last step prior to order to shut down, suspend or revoke license
HODGAS, J. W. Pennsylvania, Univ. of 45FR66754 093 80/12/23 07500 063

8101220083 Forwards comments on proposed rule 10CFR2 re policy & procedure for enforcement actions NRC should re-examine need for very aggressive enforcement policy & suspend interim use until fairness established
MINER, L. E. Marquette Univ 45FR66754 096 80/12/31 14pp 07500 049

8101220089 Comments by American Hosp Association on proposed rule 10CFR2 re policy & procedure for enforcement actions Communications & educational programs should precede enforcement of fines & other penalties
FLANAGAN, R. J. Affiliation Unknown 45FR66754 083 80/12/29 07500 046

8101220094 Comments on proposed rule 10CFR2 re policy & procedure for enforcement actions Generally approves rule, but could like mechanism for appeal established, since different inspectors would have different interpretations of rule
HENDREE, W. R. Society of Nuclear Medicine 45FR66754 082 80/12/29 2pp 07500 044

8101220099 Comments by Baptist Memorial Hosp Sys on proposed rule 10CFR2 re policy & procedure for enforcement actions Policy will probably increase medical costs w/no added benefit to public health
GCFE, D. L. Affiliation Unknown 45FR66754 072 80/12/29 2pp 07500 042

8101220103 Comments on proposed rule 10CFR2 re policy & procedure for enforcement actions Basis for civil penalty assessment should be damage to public health & safety resulting from specific violation
MITTE, R. L. Public Service Electric & Gas Co of New Jersey 45FR66754 099 80/12/31 5pp 07500 037

8101220111 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CURTIS, M. C. Affiliation Unknown 45FR70B74 1316 80/12/08

8101220118 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PRIETO, J. Affiliation Unknown 45FR70B74 1315 80/12/08 1p

8101220120 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ROEMHILD, F. Affiliation Unknown 45FR70B74 1314 80/12/08

8101220125 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LENS, B. Affiliation Unknown 45FR70B74 1320 80/12/08 1p

8101220129 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
QUINN, R. Affiliation Unknown 45FR70B74 1313 80/12/08 1p

8101220134 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BUTLER, M. Affiliation Unknown 45FR70B74 1090 80/12/08 1p

8101220136 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HARTZLER, E. Affiliation Unknown 45FR70B74 1086 80/12/08

8101220142 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LYNCH, R. Affiliation Unknown 45FR70B74 1085 80/12/08 1p

E B101220149 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
L10FR1.L Affiliation Unknown 45FR70874 1084 80/12/08 1p

E B101220148 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ATKINSON.M Affiliation Unknown 45FR70874 1083 80/12/08 1p

E B101220154 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FARBER.R Affiliation Unknown 45FR70874 1082 80/12/08 1p

E B101220159 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MORAN.R Affiliation Unknown 45FR70874 1078 80/12/08 1p

E B101220160 Comments by American Council on Education on proposed rule 10CFR2 re policy & procedure for enforcement actions Policy may have potentially deleterious effect on scholarly research at colleges & univs
STEINBACH.S E Affiliation Unknown 45FR66754 080 80/12/22 4pp
07500 028

E B101220165 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WEINSTEIN.A Affiliation Unknown 45FR70874 1076 80/12/08 1p

E B101220169 Comments by WI Hosp Association on proposed rule 10CFR2 re policy & procedure for enforcement actions Policy lacks clarity. Incentives for encouraging licensees to report are not sufficient
VEN EHREN.W R Affiliation Unknown 45FR66754 081 80/12/22 2pp
07500 121

E B101220170 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ZALAS.F D Affiliation Unknown 45FR70874 1075 80/12/08 1p

E B101220173 Comments by Troutman, Sanders, Lockerman & Ashmore for OA Power Co on proposed rule 10CFR2 re policy & procedure for enforcement actions Policy fails to provide positive incentives for self-policing by licensees
EDWARDS.R F , ROSENBERG.S C Affiliation Unknown 45FR66754 085 80/12/20 4pp
07500 115

E B101220178 Comments on behalf of BMW on proposed rule 10CFR2 re policy & procedure for enforcement actions. Rule lacks clarity & objectivity. Penalizing equipment failure is inconsistent w/ existing policy
EDGAR.D L Morgan, Lewis & Bockius 45FR66754 086 80/12/31 17pp
07500 096

E B101220184 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CURRAN.B Affiliation Unknown 45FR70874 0937 80/12/01 1p

E B101220227 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
GIBSON.M.E.K. Affiliation Unknown 45FR70874 0586 80/12/08 1p

B B101220263 Comments by Gray Panthers of Santa Barbara on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 1391 80/12/10 1p

B B101220283 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ANDERSON.T H Westinghouse Electric Corp NS-TMA-2352 80/12/09 1p

B B101220371 Forwards comments by Henry County Health Ctr on proposed rule 10CFR2 re policy & procedure for enforcement actions. Requests return of NRC views of encl ltr
JEPSELL.R Senate 45FR66754 107 80/12/06 3pp
07183 001

B B101220482 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KEMPENICH.R Affiliation Unknown 45FR70874 1063 80/12/08 1p

B101220487 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
TATELMAN.J Affiliation Unknown 45FR70874 1062

B101220509 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
JACOBSON.S.E Affiliation Unknown 45FR70874 1061

B101220514 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
SABOULIN.D A Affiliation Unknown 45FR70874 1060

B101220519 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
* Affiliation Unknown 45FR70874 0631 80/12/08

B101220524 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
GOETZ.M W Affiliation Unknown 45FR70874 0629

B101220530 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
AFRAN.B Affiliation Unknown 45FR70874 0628

B101220536 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
ROTH.L Affiliation Unknown 45FR70874 0622

B101220544 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
DEPADLA.R N Affiliation Unknown 45FR70874 0621

B101220547 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
HEAVER.J Affiliation Unknown 45FR70874 0620

B101220554 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
BERTANI.E D Affiliation Unknown 45FR70874 0619

B101220558 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
* Affiliation Unknown 45FR70874 0572 80/12/08

B101220561 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
WALKER.M Affiliation Unknown 45FR70874 0543

B101220564 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
BOIDELLE.C Affiliation Unknown 45FR70874 0539

B101220568 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
TURBES.P Affiliation Unknown 45FR70874 1355

B101220570 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
BRIDENBATER.P Affiliation Unknown 45FR70874 1354

B101220572 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
ALCURI.E C Affiliation Unknown 45FR70874 0509

B101220576 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
DEGUZMAN.M D Affiliation Unknown 45FR70874 1353

B101220579 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as in metals Opposes rules
DEGUZMAN.M D Affiliation Unknown 45FR70874 1352

8101220580 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CAKROCK, I Affiliation Unknown 45FR70874 1098 80/12/02 1p

8101220583 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 0609 80/12/08 1p

8101220585 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LIGHTSTONE, A Affiliation Unknown 45FR70874 0611 80/12/08 1p

8101220599 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ZELVIN, L Affiliation Unknown 45FR70874 1045 80/12/02 1p

8101220594 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HINNANT, S L Affiliation Unknown 45FR70874 0579 80/12/02 1p

8101220608 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SILVERMAN, A J Affiliation Unknown 45FR70874 1491 80/12/04 1p

8101220589 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ZELVIN, L Affiliation Unknown 45FR70874 1045 80/12/02 1p
07309 001

8101220594 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HINNANT, S L Affiliation Unknown 45FR70874 0579 80/12/02 1p
07309 001

8101220600 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SILVERMAN, A J Affiliation Unknown 45FR70874 1491 80/12/04 1p
07500 168

8101220589 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ZELVIN, L Affiliation Unknown 45FR70874 1045 80/12/02 1p
07309 001

8101220594 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HINNANT, S L Affiliation Unknown 45FR70874 0579 80/12/02 1p
07309 001

8101220608 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SILVERMAN, A J Affiliation Unknown 45FR70874 1491 80/12/04 1p
07500 168

8101220589 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ZELVIN, L Affiliation Unknown 45FR70874 1045 80/12/02 1p
07309 001

8101220594 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HINNANT, S L Affiliation Unknown 45FR70874 0579 80/12/02 1p
07309 001

8101220608 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SILVERMAN, A J Affiliation Unknown 45FR70874 1491 80/12/04 1p
07500 168

8101220590 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 0549 80/12/08 1p

8101220592 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FUSCHEN, G Affiliation Unknown 45FR70874 0547 80/12/08

8101220595 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
EIZENDORF, G Affiliation Unknown 45FR70874 0603 80/12/08

8101220997 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MENDELSCHEIN, M Affiliation Unknown 45FR70874 0602 80/12/08

8101220598 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 0607 80/12/08 1p

8101220500 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MOY, D Affiliation Unknown 45FR70874 0554 80/12/08 1p

8101220601 Comments on proposed App C to 10CFR2 re policy & procedure for enforcement actions Regulation goes beyond historical intent of Atomic Energy Act to promote peaceful use of atomic energy w/o jeopardizing common defense & security
MCODERN, J J Union Carbide Corp 45FR66794 109 80/12/30
07309 001

8101220602 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PERTES, L Affiliation Unknown 45FR70874 0344 80/12/08 1p

8101220604 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SALTZMAN, A Affiliation Unknown 45FR70874 0545 80/12/08

8101220606 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SWARTZ, W M Affiliation Unknown 45FR70874 0346 80/12/08

8101220607 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KEMP, H L Affiliation Unknown 45FR70874 0498 80/12/08 1p

8101220610 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SANCHEZ, R Affiliation Unknown 45FR70874 0496 80/12/08 1p

8101220612 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LEVELLE, W J Affiliation Unknown 45FR70874 0495 80/12/08

8101220614 Comments on proposed rule 10CFR2 re policy & procedure for enforcement actions Health & safety of site personnel & public should remain paramount, if not ultimate, concern for all parties
FERGUSON, J H Virginia Electric & Power Co 45FR66794 108 80/12/31 4pp 07500 164

8101220615 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
DUBARRY, R Affiliation Unknown 45FR70874 0493 80/12/08

8101220621 Comments on behalf of Houston Lighting & Power on proposed rule 10CFR2 re policy & procedure for enforcement actions Regulation places excessive emphasis on fines & penalties
POWELL, D O Lowenstein, Neuman, Reiss, Axelin & Toll 45FR66794 80/12/31 4pp 07500 160

8101220639 Forwards comments by H. Power Co to JA McClure on proposed rule 10CFR2 re policy & procedure for enforcement actions Particular attention should be given to citation for violations resulting from safety-related equipment failure
HENDRIE, J M Commissioners 45FR66794 094 80/12/18 10pp 07309 001

B101230340 Comments on proposed rules 10CFR30.32
possession, use & transfer of low enriched U as
in metals Opposes rules
GRUEI, J Affiliation Unknown 45ER70874 1402

8101230342 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SCHWARTZ, J E Affiliation Unknown 45FR70874 1402 80/12/11. 1p

8101230346 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
DILLINGHAM, M Affiliation Unknown 45FR70874 1401 80/12/11 1p

8101230387 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
JACOBS, A M Affiliation Unknown 45FR70874 0447 80/12/02 1p

8101230390 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BUNCE, D J Affiliation Unknown 45FR70874 0453 80/12/03. 1p

8101230578 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SCHNUR, M Affiliation Unknown 45FR70874 0442 80/12/04 1p.

8101230584 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCKE, V Affiliation Unknown 45FR70874 0444. 80/12/04 1p

8101230587 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
RUSSELL, H L Affiliation Unknown 45FR70874 0448 80/12/04 1p

8101230591 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ADCOCK, J L Affiliation Unknown 45FR70874 0449 80/12/04 1p

8101230596 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LYNN, L Affiliation Unknown 45FR70874 0443 80/12/05 1p

8101230617 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PESTQUE, B Affiliation Unknown 45FR70874 0445 80/12/05. 1p

8101230621 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HORDWITZ, J Affiliation Unknown 45FR70874 0450 80/12/05 1p

8101230624 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ENITHIN, D Affiliation Unknown 45FR70874 0451 80/12/05. 1p

8101230630 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FLANAGAN, E Affiliation Unknown. 45FR70874 0452 80/12/05 1p

8101230634 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
TITUS, V. Affiliation Unknown 45FR70874 1424. 80/12/05 1p

8101230640 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCREEL, V Affiliation Unknown 45FR70874 0438 80/12/06 1p

8101230645 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KLERANOW, A Affiliation Unknown. 45FR70874 1426 80/12/07 1p

8101230655 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BROWN, P Affiliation Unknown 45FR70874 1410. 80/12/09 1p

8101230664 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
NOWLIN, O. Affiliation Unknown 45FR70874 1411 80/12/09 1p

8101230670 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
VIRAMONTES, S Affiliation Unknown 45FR70874 1425 80/12/09

8101260002 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PATTEN, L Affiliation Unknown 45FR70874 0467 80/12/08 1p

8101260005 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WASHINGTON, R Affiliation Unknown 45FR70874 0466 80/12/08

8101260007 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PATTEN, L C Affiliation Unknown 45FR70874 0465 80/12/09

8101260008 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MILLS, S Affiliation Unknown 45FR70874 0464 80/12/08 1p

8101260011 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
JCSTO, J M Affiliation Unknown 45FR70874 0453 80/12/08 1p

8101260014 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SIERRA, I Affiliation Unknown 45FR70874 0462 80/12/08 1p

8101260023 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCNEZ, A Affiliation Unknown. 45FR70874 0461 80/12/08 1p

8101260027 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SHERA, D Affiliation Unknown 45FR70874 0460 80/12/08 1p

8101260032 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
RINIRA, M Affiliation Unknown. 45FR70874 0459 80/12/08 1p

8101260036 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCINTYRE, T Affiliation Unknown 45FR70874 0439 80/12/08

8101260048 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HAYLAND, R Affiliation Unknown 45FR70874 0437 80/12/08

8101260051 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
TIMOTHY, H Affiliation Unknown 45FR70874 0458 80/12/08

8101260055 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SCANLON, A Affiliation Unknown 45FR70874 0457 80/12/08 1p

8101260059 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PEARLMAN, C Affiliation Unknown 45FR70874 0456. 80/12/08

8101260062 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BERO, R A Affiliation Unknown. 45FR70874 0440. 80/12/08 1p

8101260066 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WEBB, A Affiliation Unknown 45FR70874 0446 80/12/08 1p

8101260069 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KAHN, S Affiliation Unknown 45FR70874 0455 80/12/08 1p

B101260274 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
TUTTLE, B P Affiliation Unknown 45FR70874 2434 80/12/16 1p

B101260298 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
DAY, G Affiliation Unknown 45FR70874 2435 80/12/16 1p

B101260104 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MAGICK, J Affiliation Unknown 45FR70874 2433 80/12/16 1p

B101260111 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CRONE, J Affiliation Unknown 45FR70874 2432 80/12/16 1p

B101260121 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CHARTAND, D J Affiliation Unknown 45FR70874 2431 80/12/16 1p

B101260130 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LUNNINGHAM, R B Affiliation Unknown 45FR70874 2430 80/12/16 1p

B101260149 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LEHNSSTEIN, J Affiliation Unknown 45FR70874 2426 80/12/16 1p

B101260157 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BLANCHARD, M B Affiliation Unknown 45FR70874 2427 80/12/16 1p

B101260167 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WATTERS, R Affiliation Unknown 45FR70874 2428 80/12/16 1p

B101260172 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MERK, O Affiliation Unknown 45FR70874 2422 80/12/16 1p

B101260179 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CELLENGY, S Affiliation Unknown 45FR70874 2418 80/12/16 1p

B101260183 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 2417 80/12/16 1p

B101260191 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
O'CONNELL, P Affiliation Unknown 45FR70874 2414 80/12/16 1p

B101260194 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCCLEINTOCK, S Affiliation Unknown 45FR70874 2418 80/12/16 1p

B101260203 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MURDOCH, J Affiliation Unknown 45FR70874 2412 80/12/16 1p

B101260210 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SCHWILDERER, W Affiliation Unknown 45FR70874 2411 80/12/16 1p

B101260217 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HENDRICKS, J C Affiliation Unknown 45FR70874 2410 80/12/16 1p

B101260227 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LAURENCE, C L Affiliation Unknown 45FR70874 2409 80/12/16 1p

B101260233 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 2408 80/12/16 1p

B101260259 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BENNETT, C Affiliation Unknown 45FR70874 2407 80/12/16 1p

B101260265 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 2406 80/12/16 1p

B101260275 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SPITZ, M Affiliation Unknown 45FR70874 2405 80/12/16 1p

B101260287 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
DUNN, J Affiliation Unknown 45FR70874 2404 80/12/16 1p

B101260293 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SCREECHFIELD, J Affiliation Unknown 45FR70874 2403 80/12/16 1p

B101260299 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
GARDNER, R Affiliation Unknown 45FR70874 2402 80/12/16 1p

B101260305 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
NIEVEROMSKI, P Affiliation Unknown 45FR70874 2401 80/12/16 1p

B101260309 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 2366 80/12/16 1p

B101260322 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 2365 80/12/16 1p

B101260330 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
DAVIDSON-ROLLIN Affiliation Unknown 45FR70874 2364 80/12/16 1p

B101260336 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HARTMAN, A Affiliation Unknown 45FR70874 2363 80/12/16 1p

B101260343 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
VAUPEL, J K Affiliation Unknown 45FR70874 2362 80/12/16 1p

B101260350 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCORE, C Affiliation Unknown 45FR70874 2361 80/12/16 1p

B101260354 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HANLEY, K Affiliation Unknown 45FR70874 2360 80/12/16 1p

B101260356 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 2359 80/12/16 1p

EO12864 Comments on proposed rules 10CFR30.32.70 & 150 re
possession, use & transfer of low enriched U as contaminant
in metals Disposes rules
MUELLER, A Affiliation Unknown 45FR70874 2444 EO/12/16 1p

0101260655 Comments on proposed rules 10CFR20.32.70 & 150 re
possession, use & transfer of low enriched U as contaminant
in metals Opposes rules
CRAVER,E Affiliation Unknown 451R07074 2443 60/12/16 lp

6101260640 Comments on proposed rules 10CFR30.32.70 & 150 re
possession, use & transfer of low enriched U as contaminant
in metals Opposes rules
KEYMILLER, A Affiliation Unknown 45FR70374 2442 80/12/16

01012a0565 Comments on proposed rules 10CFR20.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BALLARD, D Affiliation UNKNOWN 45FR70874 2441 80/12/16 1p

0101206B2 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BUCCINO, C Affiliation Unknown 45FR70874 2440 00/12/16 1

0101260686 Comments on proposed rules 10CFR50.32.70 & 150 re
possession, use & transfer of low enriched U as contaminant
in metals Opposes rules
MAY 11 Affiliation Unknown 45FR70874 2439 80/12/16 1p

0101260691 Comments on proposed rules 10CFR30.32.70 & 150 re
possession, use & transfer of low enriched U as contaminant
in reals Oppose rules
SCHMADT, M. Affiliation Unknown 45FA70074 2433 00/12/16 1

9101260695 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WEATHERBY, J R Affiliation Unknown -5FR70874 2437. 80/12/16.

8101260702 Comments on proposed rules 10CFR30.32.70 & 150 re
possession, use & transfer of low enriched U as contaminant
in metals Opposes rules
LAFRENIERE, J Affiliation Unknown 45FR70874 2436 80/12/16

H101260705 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules.

6101260709 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ALKECP.F U T Affiliation Unknown 45FR70974 2398 80/12/16

0101260711 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MILBURN, D A Affiliation Unknown. 491R70874 2277 B0/12/16

B101260717 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
JOHNSTON, A Affiliation Unknown 45F870B74 2276 80/12/16

B101260721 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KATZ, K Affiliation Unknown 49FR70874 2275 00/12/16 1p

B101260727 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MAYKIN, R D Affiliation Unknown 45FR70874 2274 80/12/16

Bj01260734 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MAYNARD, C A Affiliation Unknown. 45FR70874 2273 80/12/16

8101260740 Comments on proposed rules 10CFR30.32, 70 & 150 re
possession, use & transfer of low enriched U as contaminant
in metals. Opposes rules
BUSH, L Affiliation Unknown 45FR70874 2372 80/12/16 1p

B101260746 Comments on proposed rules 10CFR30.32, 70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
TREHNSTEITER, V Affiliation Unknown 49FR70874 2271 80/12/16

B01260762 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
VINCENT, M Affiliation Unknown 45FR70874 2269 80/12/16 1p

B01260766 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
TEFLER, J Affiliation Unknown 45FR70874 2270 80/12/16 1p

B01270007 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 2268 80/12/16 1p

B01270033 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 2267 80/12/16 1p

B01270036 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 2266 80/12/16 1p

B01270012 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PHILLIPS, L Affiliation Unknown 45FR70874 2265 80/12/16 1p

B01270014 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
THOMPSON, W G Affiliation Unknown 45FR70874 2264 80/12/16 1p

B01270017 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WEAVER, M Affiliation Unknown 45FR70874 2266 80/12/16 1p

B01270018 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 2262 80/12/16 1p

B01270020 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SEHMER, S L Affiliation Unknown 45FR70874 2261 80/12/16 1p

B01270022 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 2260 80/12/16 1p

B01270028 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PEEFER, S C Affiliation Unknown 45FR70874 2258 80/12/16 1p

B01270033 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ROSE, G A Affiliation Unknown 45FR70874 2303 80/12/16 1p

B01270039 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MORSEBON, J Affiliation Unknown 45FR70874 2302 80/12/16 1p

B01270050 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BENEL, P A Affiliation Unknown 45FR70874 2301 80/12/16 1p

B01270275 Transcript from Affirmation Session 80-56 on B01222 in Washington, DC Pp 1-7 Includes consideration of SECY-80-925 re open govt FOIA appeal, SECY-A-14A re Tyrone decision, SECY-80-507 & SECY-80-401
* Commissioners 80/12/22 9pp 07546 117

B01270293 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules

B01270300 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KINMAN, L Affiliation Unknown 45FR70874 2300

B01270305 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BACKER, C Affiliation Unknown 45FR70874 2301

B01270310 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
TODT, R Affiliation Unknown 45FR70874 2300

B01270316 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FIELDS, J Affiliation Unknown 45FR70874 2300

B01270320 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
RICHING, D Affiliation Unknown 45FR70874 2300

B01270325 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
REINSTADLER, J Affiliation Unknown 45FR70874 2300

B01270331 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
STUDER, M Affiliation Unknown 45FR70874 2300

B01270335 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WILLIAMS, K Affiliation Unknown 45FR70874 2300

B01270340 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PERRY, L Affiliation Unknown 45FR70874 2300

B01270365 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KRINGHAUS, G C Affiliation Unknown 45FR70874 2300

B01270371 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WARNER, R B Affiliation Unknown 45FR70874 2300

B01270374 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
DOUGLAS, A K Affiliation Unknown 45FR70874 2300

B01270381 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LEVY, P Affiliation Unknown 45FR70874 2300

B01270384 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
RYAN, B Affiliation Unknown 45FR70874 2300

B01270393 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ALLSUP, M M Affiliation Unknown 45FR70874 2300

B01270399 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SOLSTEIN, J Affiliation Unknown 45FR70874 2300

B01270407 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 2300

B101270415 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules MARTINEZ, A Affiliation Unknown 45FR70874 2283 80/12/16 1p	B101270824 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules ESTES, O Affiliation Unknown 45FR70874 1054 80/11/27 1p
B101270421 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules WHITMAN, R R Affiliation Unknown 45FR70874 2282 80/12/16 1p	B101270530 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules DETLEF, R E Affiliation Unknown 45FR70874 0597 80/11/22
B101270426 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules WODD, X Affiliation Unknown 45FR70874 2281 80/12/16 1p	B101270835 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules * Affiliation Unknown 45FR70874 1061 80/11/28 1p
B101270432 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules RAMSEY, J A Affiliation Unknown 45FR70874 2280 80/12/16 1p	B101270839 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules DJORDJEV, A Affiliation Unknown 45FR70874 1312 80/11/28
B101270437 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules THOMPSON, R Affiliation Unknown 45FR70874 2279 80/12/16 1p	B101270844 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules OLASBER, L Affiliation Unknown 45FR70874 1100 80/11/29
B101270445 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules PORTISSA, D Affiliation Unknown 45FR70874 2300 80/12/16 1p	B101270856 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules DARCELD, D Affiliation Unknown 45FR70874 1502 80/11/30
B101270449 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules HAFO, C Affiliation Unknown 45FR70874 2299 80/12/16 1p	B101270898 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules WARRER, B Affiliation Unknown 45FR70874 0543 80/11/30
B101270534 Submits list of facilities within US not associated w/activities w/direct natl security significance to govt of US * Commissioners 80/11/26 40pp 07543 308	B101280200 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules HINZEL, H Affiliation Unknown 45FR70874 2740 80/12/04 1p
B101270757 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules HADLEY, K Affiliation Unknown 45FR70874 1377 80/12/10 1p	B101280315 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules * Affiliation Unknown 45FR70874 2742 80/12/04 1p
B101270761 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules LANTZ, D E Affiliation Unknown 45FR70874 1334 80/12/11 1p	B101280319 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules HADEL, C Affiliation Unknown 45FR70874 2741 80/12/04 1p
B101270773 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules DECK, K Affiliation Unknown 45FR70874 1342 80/12/11 1p	B101280322 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules HAGGER, R Affiliation Unknown 45FR70874 2731 80/12/04 1p
B101270778 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules MUEGE, J Affiliation Unknown 45FR70874 1595 80/12/07 1p	B101280326 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules * Affiliation Unknown 45FR70874 2750 80/12/04 1p
B101270781 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules MUREAU, D Affiliation Unknown 45FR70874 1074 80/12/07 1p	B101280329 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules * Affiliation Unknown 45FR70874 1936 80/12/03 1p
B101270793 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules BRAYSON, Y Affiliation Unknown 45FR70874 0583 80/11/03 1p	B101280338 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules EASTMAN, J Affiliation Unknown 45FR70874 2743 80/12/03
B101270801 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules PRECESTIN, O Affiliation Unknown 45FR70874 0055 80/11/26 1p	B101280341 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules PARKER, D Affiliation Unknown 45FR70874 2746 80/12/03
B101270804 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules MAYO, I Affiliation Unknown 45FR70874 0069 80/11/23 1p	B101280344 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules * Affiliation Unknown 45FR70874 0060 80/12/03 1p
B101270811 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules POSE, K Affiliation Unknown 45FR70874 0640 80/11/25 1p	B101280345 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules LERNER, D Affiliation Unknown 45FR70874 0068 80/12/03
B101270817 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules SINER, T Affiliation Unknown 45FR70874 1593 80/11/29 1p	B101280349 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules MERONE, P Affiliation Unknown 45FR70874 0062 80/12/03

B101280446 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SUTTER, E Affiliation Unknown 45FR70874 0651 80/12/03 1p

B101280458 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BELTON, B Affiliation Unknown 45FR70874 0653 80/12/03 1p

B101280463 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SIGNESS, G Affiliation Unknown 45FR70874 0654 80/12/03 1p

B101280466 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
RODRE, M R Affiliation Unknown 45FR70874 0655 80/12/03 1p

B101280470 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KELLER, J J Affiliation Unknown 45FR70874 0667 80/12/03 1p

B101280475 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LEJO, J Affiliation Unknown 45FR70874 3226 80/12/13 1p

B101280479 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
RODRE, I J Affiliation Unknown 45FR70874 2521 80/12/13 1p

B101280478 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CRHEN, S S Affiliation Unknown 45FR70874 2516 80/12/13 1p

B101280480 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PAGE, P Affiliation Unknown 45FR70874 2629 80/12/13 1p

B101280483 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HAYVIC, E L Affiliation Unknown 45FR70874 2629 80/12/13 1p

B101280487 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LINDCHILD, N J Affiliation Unknown 45FR70874 2633 80/12/13 1p

B101280490 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WEBB, C Affiliation Unknown 45FR70874 2827 80/12/11 1p

B101280497 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SWANSON, K Affiliation Unknown 45FR70874 2829 80/12/11 1p

B101280404 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ALEXANDER, P Affiliation Unknown 45FR70874 2821 80/12/11 1p

B101280407 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HARRO, L C Affiliation Unknown 45FR70874 3261 80/12/11 1p

B101280415 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FEILER, I Affiliation Unknown 45FR70874 2757 80/12/11 1p

B101280437 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
Affiliation Unknown 45FR70874 2756 80/12/11 1p

B101280442 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SARGENT, S Affiliation Unknown 45FR70874 1970 80/12/11 1p

B101280446 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SUTTER, E Affiliation Unknown 45FR70874 0651 80/12/03 1p

B101280458 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BELTON, B Affiliation Unknown 45FR70874 0653 80/12/03 1p

B101280463 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SIGNESS, G Affiliation Unknown 45FR70874 0654 80/12/03 1p

B101280466 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
RODRE, M R Affiliation Unknown 45FR70874 0655 80/12/03 1p

B101280470 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KELLER, J J Affiliation Unknown 45FR70874 0667 80/12/03 1p

B101280475 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BELFRY, D Affiliation Unknown 45FR70874 3226 80/12/13 1p

B101280480 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
RODRE, I J Affiliation Unknown 45FR70874 2521 80/12/13 1p

B101280544 Comments on proposed rule 10CFR2 re policy & procedures for enforcement actions Power reactor licensees Board of review should be established to ensure severity level consistency
BOVER, V S Philadelphia Electric Co 45FR46113pp 07957 326

B101280555 Comments on proposed rule 10CFR2 re policy & procedures for enforcement actions Power reactor licensees Board of review should be established to ensure severity level consistency
ULLEY, E E Carolina Power & Light Co 45FR46112pp 07957 314

B101290038 Advises recipients of comments on proposed rules 10CFR30.32.70 & 150 that comments numbered 380 through 402 were mislabeled Comment Numbers 380 through 402 will be re-used
Socketing & Services Branch 45FR70874 0651 80/12/03 1p

B101290045 Forwards comments on behalf of utility 10CFR170 re fees for review of applications for siting criteria Rules should prevent future issues where transportation constraints would impede evacuation of persons within 20-mile radius
CHARNOFF, D Shaw, Pittman, Potts & Trowbridge 80/12/08 29pp 07568 230

B101290088 Comments on proposed rules 10CFR50.91 siting criteria Rules should prevent future issues where transportation constraints would impede evacuation of persons within 20-mile radius
PAYNE, J D Affiliation Unknown 45FR50350 07567 360

B101290112 Comments on proposed rule 10CFR50 re hydrogen control & certain degraded core conditions Negative safety impacts not adequately considered against benefits to be gained
QUAYARD, J P Long Island Lighting Co 45FR46113pp 07567 357

B101290137 Comments on proposed rule 10CFR50 re hydrogen control & certain degraded core conditions considerations implementation on interim basis waste of resources
TRIMBLE, D C Arkansas Power & Light Co 45FR46114pp 07575 036

B101290156 Comments on proposed rule 10CFR50 re design changes Rule would take design change out of process Eventually litigants would be contending approved designs that have no basis
LEWIS, M I Affiliation Unknown 45FR46102 07575 034

8101290168 Comments on proposed rule 10CFR73 re requiring thorough search of individuals before entering sensitive areas of nuclear power plants Supports rule Rule should be put into effect as soon as possible
WUJDSOV, W K Affiliation Unknown 45FR79492 033 80/12/22 1p
07575 033

8101290184 Comments on proposed rule 10CFR73 re requiring thorough search of individuals before entering sensitive areas of nuclear power plants Submits recommended definition of visitor to be used in rule
UTLEY, E E Carolina Power & Light Co 45FR79492 004 80/12/24 2pp 07575 032

8101290392 Unofficial transcript of 800107 Commission meeting in Washington, DC re BECY-80-474, final rule, 10CFR60, "Disposal of High Level Radwaste in Geologic Repositories Licensing Procedures." Pp 1-86
* Commissioners 81/01/07 8Bpp 07570 001

--8101290399 Submits draft language changes to original text of BECY-80-474 for 10CFR60 Final rulemaking Ofc of General Council concerns re NRC deference to DGE on common defense & security matters addressed
BICKWIT, L Office of the General Counsel 81/01/06 2pp 07570 090

---8101290405 Discusses procedural aspects of final rule deserving further Commission consideration prior to approval of publication as part of 10CFR60, "Disposal of High Level Radwaste in Geologic Repositories." Licensing policy statement encl
HARRAHAN, E J Office of Policy Evaluations, 81/01/06 5pp, 07570 091

--8101290410 Confirms discussion w/ Dircks re dept concerns w/proposed regulations governing disposal of high level radwaste. Commission accommodation of dept views on problems outlined in 800303 ltr requested prior to issuing final rule.
* Energy, Dept of. 81/01/06 2pp 07570 096

--8101290415 Staff requirements memo re discussion of BECY-80-474 final rule, 10CFR60, "Disposal of High Level Radwaste in Geologic Repositories Licensing Procedures." Commissioner views on proposed mods to BECY-80-474 encl
CHILK, B J Office of the Secretary of the Commission 80-474 81/01/09 4pp, 07570 098.

--8101290420 Suggests mods to BECY-80-474 final rule, 10CFR60, "Disposal of High Level Radwaste in Geologic Repositories Licensing Procedures."
BRADFORD, P A Commissioners 80/12/18 4pp 07570 102

8101290560 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KELLER, A C Affiliation Unknown 45FR 70874 1992 80/12/11 1p

8101290566 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
YOUNG, F. Affiliation Unknown 45FR70874 2499. 80/12/11 1p

8101290570 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CORNWALL, H Affiliation Unknown 45FR70874 2524 80/12/11 1p

8101290572 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules.
PORTER, A Affiliation Unknown 45FR70874 2500. 80/12/11 2pp

8101290582 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 3220 81/01/05 1p

8101290585 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
IRWIN, S Affiliation Unknown 45FR70874 3221 81/01/05 1p

8101290639 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SCHNEIDER, S Affiliation Unknown 45FR70874 1502 80/12/08 2pp

8101290644 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CHERRY, R H Affiliation Unknown, 45FR70874 2509 80/12/08 1p

8101290647 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules.
LANE, R H Affiliation Unknown 45FR70874 2502 80/12/08

8101290660 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
RYAN, G E H Affiliation Unknown 45FR70874 1968 80/12/08

8101290663 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
COHEN, S Affiliation Unknown 45FR70874 1913 80/12/08 1p

8101290665 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HASTINGS, E H Affiliation Unknown 45FR70874 1906 80/12/08

8101290670 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CEENA, D W Affiliation Unknown 45FR70874 2749 80/12/08 1p

8101290677 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ADA, E Affiliation Unknown 45FR70874 2573 80/12/08 2pp

8101290681 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LUCAS, R D Affiliation Unknown 45FR70874 2596 80/12/08 1p

8101290693 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules.
SUND, D Affiliation Unknown 45FR70874 2611 80/12/08 1p

8101290698 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules.
GRAVELLE, D. Affiliation Unknown 45FR70874 1961 80/12/08

8101290599 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
AMBER, K Affiliation Unknown, 45FR70874 1946 80/12/08 1p

8101290704 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCGOVERN, S A Affiliation Unknown 45FR70874 1944 80/12/08

8101290709 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
NICHAN, C S A Affiliation Unknown 45FR70874 1941. 80/12/08

8101290714 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HENZLER, L E Affiliation Unknown 45FR70874 1923 80/12/08 1p

8101290716 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 1896. 80/12/08 1p

8101290719 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CARR, P Affiliation Unknown 45FR70874 2324 80/12/08 1p

8101290721 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
STEIN, L L Affiliation Unknown 45FR70874 2314. 80/12/08 1p

8101290725 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PHOUNT, M Affiliation Unknown 45FR70874 2310 80/12/08 1p

B101299727 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
STATION T M Affiliation Unknown 45FR70B74 2307 80/12/08 1p

B101299730 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FEINER D A Affiliation Unknown 45FR70B74 2318 80/12/08 1p

B101299732 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CINQUE M A Affiliation Unknown 45FR70B74 1940 80/12/08 2pp

B101299735 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HADDICK B Affiliation Unknown 45FR70B74 1938 80/12/08 2pp

B1012997001 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
AYERS R Affiliation Unknown 45FR70B74 2972 80/12/05 1p

B101300002 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70B74 2767 80/12/05 1p

B101300003 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MINER U Affiliation Unknown 45FR70B74 2745 80/12/05 1p

B101300004 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
RICHARDSON C Affiliation Unknown 45FR70B74 2567 80/12/05 1p

B101300005 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KOLKEY M Affiliation Unknown 45FR70B74 1993 80/12/05 1p

B101300006 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
REED S Affiliation Unknown 45FR70B74 1921 80/12/05 1p

B101300007 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LASCOT J Affiliation Unknown 45FR70B74 1920 80/12/05 1p

B101300010 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
THOMAS B Affiliation Unknown 45FR70B74 2015 80/12/10 1p

B101300016 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MORRIS O Affiliation Unknown 45FR70B74 3118 80/12/10 1p

B101300023 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WALSH J Affiliation Unknown 45FR70B74 2049 80/12/10 1p

B101300039 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
EDWARD S L D Affiliation Unknown 45FR70B74 2967 80/12/06 1p

B101300047 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BLACKETT S F Affiliation Unknown 45FR70B74 2703 80/12/05 1p

B101300093 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MASON G Affiliation Unknown 45FR70B74 1956 80/12/06 1p

B101300098 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
D'ABRAMO T Affiliation Unknown 45FR70B74 3034 80/12/10 1p

B101300061 Responds to B012121 expressing const proposed rules 10CFR30.32.70 & 150, exempting cer residual radioactive contamination from licensing requirements Comments will be addressed in final DIRCPS W J Office of the Executive Director For 81/01/09 2pp

B101300063 Comments on proposed rules 10CFR30.32.7 possession, use & transfer of low enriched U as c in metals Opposes rules
STERN H Affiliation Unknown 45FR70B74 2733

B101300064 Comments on proposed rules 10CFR30.32.7 possession, use & transfer of low enriched U as c in metals Opposes rules
HOGERMAN E Affiliation Unknown 45FR70B74 130

B101300071 Comments on proposed rules 10CFR30.32.7 possession, use & transfer of low enriched U as c in metals Opposes rules
* Affiliation Unknown 45FR70B74 2784 80/12/05

B101300076 Comments on proposed rules 10CFR30.32.7 possession, use & transfer of low enriched U as c in metals Opposes rules
LESTER D Affiliation Unknown 45FR70B74 3257

B101300079 Comments on proposed rules 10CFR30.32.7 possession, use & transfer of low enriched U as c in metals Opposes rules
SPIEGEL J Affiliation Unknown 45FR70B74 2517

B101300081 Comments on proposed rules 10CFR30.32.7 possession, use & transfer of low enriched U as c in metals Opposes rules
DELMAN J B Affiliation Unknown 45FR70B74 240

B101300084 Comments on proposed rules 10CFR30.32.7 possession, use & transfer of low enriched U as c in metals Opposes rules
* Affiliation Unknown 45FR70B74 1369 80/12/05

B101300088 Comments on proposed rules 10CFR30.32.7 possession, use & transfer of low enriched U as c in metals Opposes rules
* Affiliation Unknown 45FR70B74 2744 80/12/05

B101300090 Comments on proposed rules 10CFR30.32.7 possession, use & transfer of low enriched U as c in metals Opposes rules
MCODY C S Affiliation Unknown 45FR70B74 233

B101300094 Comments on proposed rules 10CFR30.32.7 possession, use & transfer of low enriched U as c in metals Opposes rules
PINSKY R Affiliation Unknown 45FR70B74 2739

B101300095 Comments on proposed rules 10CFR30.32.7 possession, use & transfer of low enriched U as c in metals Opposes rules
WOLFE D Affiliation Unknown 45FR70B74 2330

B101300100 Comments on proposed rules 10CFR30.32.7 possession, use & transfer of low enriched U as c in metals Opposes rules
RIBBIN M Affiliation Unknown 45FR70B74 2326

B101300101 Comments on proposed rules 10CFR30.32.7 possession, use & transfer of low enriched U as c in metals Opposes rules
MOSHI A Affiliation Unknown 45FR70B74 2748

B101300102 Comments on proposed rules 10CFR30.32.7 possession, use & transfer of low enriched U as c in metals Opposes rules
CELBORGH D D Affiliation Unknown 45FR70B74 2

B101300105 Comments on proposed rules 10CFR30.32.7 possession, use & transfer of low enriched U as c in metals Opposes rules
LUSKE L Affiliation Unknown 45FR70B74 2328

B101300110 Comments on proposed rules 10CFR30.32.7 possession, use & transfer of low enriched U as c in metals Opposes rules
GUSTAFSON J Affiliation Unknown 45FR70B74 2

NONDOCKETED ITEMS

8101300111 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules BOJRLAND,W J Affiliation Unknown 45FR70874 2333 80/12/10 2pp	8101300184 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules JENSEN, J Affiliation Unknown 45FR70874 2734 80/12/07
8101300112 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules LEONARD,D B Affiliation Unknown 45FR70874 2332 80/12/10 2pp	8101300192 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules CEGENFELDER,E Affiliation Unknown 45FR70874 2735 80/12/07
8101300110 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules ZAUERBERGEN,H Affiliation Unknown 45FR70874 2336 80/12/10 2pp	8101300200 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules HJLLAND,O Affiliation Unknown 45FR70874 2760 80/12/07
8101300124 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules MUELLER,P E Affiliation Unknown 45FR70874 1791 80/12/10 2pp	8101300207 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules SHALLWOOD, J C Affiliation Unknown 45FR70874 2784 80/12/07
8101300130 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules * Affiliation Unknown 45FR70874 2291 80/12/07 1p	8101300215 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules KALGANI, J Affiliation Unknown 45FR70874 1923 80/12/07
8101300132 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules O'NEIL,M Affiliation Unknown 45FR70874 2335 80/12/10 2pp	8101300232 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules * Affiliation Unknown 45FR70874 2292 80/12/07 1p
8101300135 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules ROSEMAN,M L Affiliation Unknown 45FR70874 2334 80/12/10 2pp	8101300236 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules WILCOX,W Affiliation Unknown 45FR70874 2397 80/12/10
8101300137 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules VANKIRK,B Affiliation Unknown 45FR70874 2337 80/12/10 2pp	8101300241 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules LOSTYR,R S Affiliation Unknown 45FR70874 2398 80/12/10
8101300140 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules HEAVER,D A Affiliation Unknown 45FR70874 1492 80/12/07 2pp	8101300247 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules SHITH,K Affiliation Unknown 45FR70874 2295 80/12/07 1p
8101300142 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules MITCHELL,M E Affiliation Unknown 45FR70874 2278 80/12/10 2pp	8101300255 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules WILLIS,C Affiliation Unknown 45FR70874 2399 80/12/10
8101300146 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules CLEGG,M Affiliation Unknown 45FR70874 2405 80/12/10 2pp	8101300297 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules SHEETMAN,A Affiliation Unknown 45FR70874 2293 80/12/07
8101300149 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules DOCKERY,N M Affiliation Unknown 45FR70874 2579 80/12/07 1p.	8101300263 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules HALL,L F T Affiliation Unknown 45FR70874 1715 80/12/10
8101300150 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules WHITE,K Affiliation Unknown 45FR70874 2403 80/12/10 2pp	8101300268 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules LEWIS,S Affiliation Unknown 45FR70874 2289 80/12/07 1p
8101300159 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules JULIAN,B Affiliation Unknown 45FR70874 2582 80/12/07 1p.	8101300269 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules FERNANDEZ, Z Affiliation Unknown 45FR70874 1795 80/12/10
8101300166 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules YOUNGBLOOD,E M Affiliation Unknown 45FR70874 2584 80/12/07 1p.	8101300279 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules PERTER,T R Affiliation Unknown 45FR70874 1716 80/12/10
8101300174 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules KUETT,K. Affiliation Unknown 45FR70874 2656 80/12/07 1p	8101300277 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules STEADMAN,F H Affiliation Unknown 45FR70874 2288 80/12/07
8101300179 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules	8101300280 Comments on proposed rules 10CFR30.32.70 & 150 re possession,use & transfer of low enriched U as contaminant in metals Opposes rules MORRIS,R L Affiliation Unknown 45FR70874 1812 80/12/10

8101300329 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CHICESTER, G Affiliation Unknown 45FR70874 1822 80/12/10 1p

8101300331 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCNABRAY, A Affiliation Unknown 45FR70874 2295 80/12/07 1p

8101300334 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KHEIS, J Affiliation Unknown 45FR70874 1821 80/12/10 1p

8101300339 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KORN, L Affiliation Unknown 45FR70874 1822 80/12/10 1p

8101300343 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CERRATO, M Affiliation Unknown 45FR70874 2517 80/12/10 1p

8101300353 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
VILALE, R Affiliation Unknown 45FR70874 2578 80/12/10 1p

8101300362 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KINO, D Affiliation Unknown 45FR70874 2708 80/12/10 1p

8101300369 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ORANIERI, M A Affiliation Unknown 45FR70874 2586 80/12/10 1p

8101300375 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
TOTH, P Affiliation Unknown 45FR70874 2597 80/12/10 1p

8101300380 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 2571 80/12/10 1p

8101300391 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PATTEN, G A Affiliation Unknown 45FR70874 2558 80/12/10 1p

8101300403 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
VANDER SIELT, R Affiliation Unknown 45FR70874 2562 80/12/10 1p

8101300405 Unofficial transcript of Commission 810119 meeting in Washington, DC re Affirmation Session 81-2 to discuss waste confidence rulemaking Pg 1-4
* Commissioners 81/01/15 App 07583 219

--8101300416 Forwards proposed memorandum & order authorizing use of consultants to assist Commission working group w/waste confidence rulemaking proceeding Memorandum & order should be adopted & issued
MILLER, M E Atomic Safety and Licensing Board Panel 80/12/19 App 07583 228

8101300419 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MAGY, E R Affiliation Unknown 45FR70874 2568 80/12/10 1p

8101300422 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PISFLO, D M Affiliation Unknown 45FR70874 2551 80/12/10 1p

8101300449 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MURPHY, B L Affiliation Unknown 45FR70874 3212 80/12/15 1p

8101300462 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BLAZ, C Affiliation Unknown 45FR70874 3213

8101300472 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
JONES, T Affiliation Unknown 45FR70874 3216

8101300480 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
RAMS, UNID, D L Affiliation Unknown 45FR70874

8101300482 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
LAC, H Affiliation Unknown 45FR70874 3223

8101300485 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BAWKINS, P Affiliation Unknown 45FR70874 3225

8101300489 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HANNAN, S Affiliation Unknown 45FR70874 3225

8101300497 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
GALLUCIO, J Affiliation Unknown 45FR70874

8101300505 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
JAWHEY, L Affiliation Unknown 45FR70874 3235

8101300516 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
THLETT, L Affiliation Unknown 45FR70874 3235

8101300521 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MCCAULEY, S T Affiliation Unknown 45FR70874

8101300526 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
COSNER, D P Affiliation Unknown 45FR70874

8101300531 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BHSFELD, I Affiliation Unknown 45FR70874 31

8101300536 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HAYES, L Affiliation Unknown 45FR70874 3197

8101300540 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
CAURACHO, R M Affiliation Unknown 45FR70874

8101300544 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
JANULESKI, M Affiliation Unknown 45FR70874

8101300545 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
SCOTT, L Affiliation Unknown 45FR70874 3208

8101300547 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 3211 80/12/10

8101300550 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
* Affiliation Unknown 45FR70874 3240 80/12/10

01300552 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HARVEY, H Affiliation Unknown 45FR70874 2815 80/12/15 1p

01300556 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
HDLT, J Affiliation Unknown 45FR70874 2812 80/12/15 1p

01300606 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
REEVES, F P Affiliation Unknown 45FR70874 2640 80/12/15 1p

01300669 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
PERKINS, J Affiliation Unknown 45FR70874 2788 80/12/15 1p

01300679 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BRIEN, K A Affiliation Unknown 45FR70874 3067 80/12/15 1p

01300794 Certified minutes of ACRS Subcommittee on Waste Mgt 80/11/13-14 meeting in Washington, DC re proposed rulemaking on storage & disposal of nuclear waste FR notice & attendee list encl
ACRS - Advisory Committee on Reactor Safeguards 80/12/11 14pp
07584 280

01300821 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
MARTUOLLOTTA, B Affiliation Unknown 45FR70874 1794 80/12/16 1p

01300828 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
KINGHELOE, J Affiliation Unknown 45FR70874 1793 80/12/16 1p

01300834 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
BUNDON, C Affiliation Unknown 45FR70874 1718 80/12/16 1p

01300840 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
FRANCIS, D Affiliation Unknown 45FR70874 1749 80/12/16 1p

01300850 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
ALVERIO, A Affiliation Unknown 45FR70874 1748 80/12/16 1p

01140992 Comments on proposed rules 10CFR30.32.70 & 150 re possession, use & transfer of low enriched U as contaminant in metals Opposes rules
WUNDERBORN, E I Affiliation Unknown 45FR70874 1465 80/12/10 1p
07308 001

1 PETITION FOR RULEMAKING

02080008 BECY-80-901
Forwards proposed FR notice on disposition of Critical Mass Energy Project et al petition for rulemaking re emergency response, draft ltr to petitioners & proposed Congressional ltr to Representative FM Udall
HINDQUE, R D Office of Standards Development, Director. 80/11/07 1pp 03767 181

02290489 Transcript of 801211 Affirmation Session 80-54 in Washington, DC re BECY-80-148, BECY-A-80-168 & BECY-80-482
1-11
Commissioners. 80/12/11 13pp 07335 142

01160212 Forwards FR notice of petition for rulemaking 30-37 re amend of exemption for ionizing radiation measuring instruments No ltrs have been received in response to notice.
HENRY, J J Transportation & Product Standards Branch. 336-2003 80/12/19 3pp 07469 231

01270275 Transcript from Affirmation Session 80-56 on 801222 in Washington, DC, Pp 1-7 Includes consideration of BECY-80-925 re open govt FOIA appeal, BECY-A-146A re Tyrone decision, BECY-80-507 & BECY-80-501
Commissioners. 80/12/22 9pp 07546 117

801240384 Comments on petition for rulemaking 50-29 re AHS Overall cost estimates too low Proposed fines will have negative effect on reactor safety & unit availability.
Arizona Public Service Co 45FR73080 011 80/12/30 1p
07568 362

PROJ PROJECTS - PRELIMINARY LICENSING

0101060143 Summary of 801203 meeting w/DCE in Germantown, MD re DOE/NRC interagency agreement required by West Valley Demonstration Project Act Definition section should be included to define explicitly important items
TINNO, H W Advanced Fuel & Spent Fuel Licensing Branch 80/12/08 3pp 07349 088

801200034 Comments on behalf of SD State Historical Society on final GEIS re U Milling App F-2 clearly demonstrates that NRC is aware of body of law & regulation re cultural resource protection
SPERRY, J E Affiliation Unknown 18088 80/12/07 44pp
07487 021

801200008 Ack SD State Planning Bureau receipt of final GEIS re U Milling No comment
RICHARDSON, J H South Dakota, State of 18005 80/11/21 1p
07487 017

801270286 Notice of JB Rupp, C J Corica & H Monsef depositions on 801201 in Alameda, CA & H Hyland, JP Shepard & RE Cecchetti depositions on 801204 in Alameda, CA Certificate of Svc encl Related correspondence
MEISS, R L, DOYLE, M M Pacific Gas & Electric Co MEISS, R L, McCutchen, Doyle, Brown & Emerson 81/01/20 6pp 07546 03J

801290276 Forwards SH Lewis notice of appearance in proceeding Participation in proceeding poses no conflict of interest in spite of relationship w/member of participating law firm
QULDBERG, J R Office of the General Counsel 180485 A 81/01/27 2pp 07576 149

PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE

8012100406 Part 21 rept re N921-S4 actuators, reported on 801113 Parts causing problem have been changed by 801118 engineering change notice
LOCASEIO, A T Oil Shells Corp 80/11/17 4pp 07218 001

04999 QUALITY ASSURANCE INSPECTIONS

801080349 Forwards QA Program Insp Rept 99700003/80-08 on 801031-1114 No noncompliance noted Closeout survey for formerly licensed site scheduled for 1st quarter of 1981 to determine if any residual contamination is onsite
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials E Branch. 80/12/13 1p 03775 001

--801080420 QA Program Insp Rept 995 noncompliance noted Major areas determining status of expired ltr onsite
MICHELSON, H A, PAPERFELD, C J Director 80/12/02 11pp 0375

801150374 Forwards QA Program Insp f No noncompliance noted
POTAPOV, U Region 4, Dallas, Venc 2pp 07463 231

--801150381 QA Program Insp Rept 995 noncompliance noted Major areas deficiency re implementation of qualifications
BROWN, R L, WHITESELL, D E Regic Branch 80/11/14 7pp 07463 2

801150384 Forwards QA Program Insp F No noncompliance noted
POTAPOV, U Region 4, Dallas, Venc 1p 07309 001

--801150395 QA Program Insp Rept 995 noncompliance noted Major areas 10CFR50, App B & followup on 10CFR discrepancies in valves for Sequoia
GILLER, R E, BARNES, J Region 4, 80/11/21 6pp 07307 001

8101150405 Ack receipt of 801218 ltr informing NRC of steps taken to correct deviations noted in QA Program Insp Rept 99900522/80-03
POTAPQVS.U Region 4, Dallas Vendor Inspection Branch 81/01/01
1p 07463 246

- 8101150410 Responds to NRC 801120 ltr re deviation noted in QA Program Insp Rept 99900522/80-03 Corrective actions FSAP App 3 & 4 will be revised Any reanalysis required will be performed per Bechtel Engineering Best Procedure 4.37
ALLELL, R D Bechtel Power Corp (subs of Bechtel Corp) 80/12/18 3pp 07463 247

--8101150418 Forwards QA Program Insp Rept 99900522/80-03 on 801020-23 & notice of deviation
POTAPQVS.U Region 4, Dallas, Office of the Director 80/11/20 3pp 07463 250

--8101150422 Notice of deviation from insp on 801020-23
* Region 4, Dallas, Office of the Director 80/11/19 1p 07463 252

--8101150429 QA Program Insp Rept 99900522/80-03 on 801020-23 Noncompliance noted failure to perform adequate review of design calculations of high energy line break analysis as required by internal procedures
BRICKLEY, R H, ANDERSON, D G, HALE, C J Region 4, Dallas, Vendor Inspection Branch 80/11/19 14pp 07463 253

8101150441 Ack receipt of 801204 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900501/80-01
POTAPQVS.U Region 4, Dallas, Vendor Inspection Branch 80/12/16 1p 07463 267

--8101150446 Responds to NRC 801105 ltr re deviation noted in QA Program Insp Rept 99900501/80-01 Corrective actions memo issued re-emphasizing procedures re microfilm quality & control of design interface control log
WALKER, W Bechtel Power Corp (subs of Bechtel Corp) 80/12/09 2pp 07463 268

--8101150450 Forwards QA Program Insp Rept 99900501/80-01 on 801007-10 & notice of deviation
POTAPQVS.U Region 4, Dallas, Vendor Inspection Branch 80/11/09 2pp 07463 270

--8101150454 Notice of deviation from insp on 801007-10
* Region 4, Dallas, Office of the Director 80/11/03 2pp 07463 272

--8101150460 QA Program Insp Rept 99900501/80-01 on 801007-10 Noncompliance noted design insp microfilm (QA record) of two calculations were not legible Design interface control log not maintained in control sys design group
BRICKLEY, R H, ANDERSON, D G, AGE, J R Region 4, Dallas, Vendor Inspection Branch 80/11/03 16pp 07463 274

8101150826 Ack receipt of 801230 ltr clarifying questions raised in QA Program Insp Rept 99900503/80-01
POTAPQVS.U Region 4, Dallas, Vendor Inspection Branch 81/01/08 1p 07464 299

--8101150840 Clarifies questions raised in QA Program Insp Rept 99900503/80-03 re design verification procedures.
TENZER, R E Ebaco Services, Inc (subs of Enserch Corp) 80/12/30 2pp 07464 300

--8101150845 Forwards QA Program Insp Rept 99900503/80-03 on 801020-24 No noncompliance noted
POTAPQVS.U Region 4, Dallas, Vendor Inspection Branch 80/11/19 2pp 07464 302

--8101150851 QA Program Insp Rept 99900503/80-03 on 801020-24 No noncompliance noted Major areas inspected implementation of Topical Rept ETR-1001 & followup on regional requests
CORTIELLO, J R, JOHNSON, J M, HALE, C J Region 4, Dallas, Vendor Inspection Branch 80/11/19 11pp 07464 304

8101150882 Ack receipt of 801212 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900028/80-01
POTAPQVS.U Region 4, Dallas, Vendor Inspection Branch 80/12/24, 1p 07466 010

--8101150893 Responds to NRC 800926 ltr re deviation noted in QA Program Insp Rept 99900028/80-01 Corrective Actions supplier notified & QA manual revised
SEAY, J L Chemtron Corp, Tube Turns Div 80/12/08 2pp 07466 011

--8101150878 Forwards QA Program Insp Rept 99900028/80-01 on 801020-23 notice of deviation
POTAPQVS.U Region 4, Dallas, Vendor Inspection Branch 80/09/25 12pp 07466 017

--8101150905 Notice of deviation from insp on 800821
* Region 4, Dallas, Office of the Director 07466 015

--8101150910 QA Program Insp Rept 99900028/80-01 on 801020-23 Noncompliance noted failure to issue corrective request to supplier
ELLER, R E, BARNES, J Region 4, Dallas, Vendor Inspection Branch 80/09/25 12pp 07466 016

8101150780 Forwards QA Program Insp Rept 99900087/80-01 on 801020-23 No noncompliance noted
POTAPQVS.U Region 4, Dallas, Vendor Inspection Branch 80/09/25 12pp 07476 124

--8101150782 QA Program Insp Rept 99900087/80-01 on 801020-23 Noncompliance noted Major areas inspected QA procedure of vendor activities & exit interview
KELLY, W D, WHITESELL, D E Region 4, Dallas, Vendor Inspection Branch 80/10/22 4pp 07476 128

8101200106 Ack receipt of 801027 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900025/80-04
POTAPQVS.U Region 4, Dallas, Vendor Inspection Branch 80/10/27 4pp 07486 115

--8101200112 Responds to NRC 800925 ltr re deviation noted in QA Program Insp Rept 99900025/80-04 Corrective actions ultra-sonic examination of piping subassemblies
MOERKE, M H Southwest Fabricating & Welding Co International Corp 80/10/27 4pp 07486 116

--8101200117 Forwards QA Program Insp Rept 99900025/80-04 on 801020-23 & notice of deviation
POTAPQVS.U Region 4, Dallas, Vendor Inspection Branch 80/10/27 4pp 07486 120

--8101200118 Notice of deviation from insp on 800902-10
* Region 4, Dallas, Office of the Director 80/10/27 4pp 07486 122

--8101200121 QA Program Insp Rept 99900025/80-04 on 801020-23 Noncompliance noted failure to perform required ultrasonic examination of pipe
BARNES, J Region 4, Dallas, Vendor Inspection Branch 80/10/27 4pp 07486 123

8101200125 Forwards QA Program Insp Rept 99900361/80-04 on 801020-23 No noncompliance noted
POTAPQVS.U Region 4, Dallas, Vendor Inspection Branch 80/10/27 4pp 07486 127

--8101200131 QA Program Insp Rept 99900361/80-02 on 801020-23 Noncompliance noted Major areas inspected implementation of ICFR90, App B criteria, applicable codes & stds & a previous insp findings
ELLERSHAU, L E, BARNES, J Region 4, Dallas, Vendor Inspection Branch 80/11/25 3pp 07486 129

8101200538 Ack receipt of 801204 ltr resolving questions in QA Program Insp Rept 99900504/80-04
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/12/24 1p 07477 251

--8101200640 Responds to NRC 800821 ltr re questions raised in QA Program Insp Rept 99900504/80-04 Background check of core design employee qualifications performed Evaluation completed
HASLAM, E F Stone & Webster Engineering Corp 80/12/24 2pp 07477 252

8101210255 Forwards QA Program Insp Rept 99900721/80-01 on 801020-23 No noncompliance noted
POTAPQVS.U Region 4, Dallas, Vendor Inspection Branch 80/12/24 2pp 07490 058

--8101210262 QA Program Insp Rept 99900721/80-01 on 801020-23 Noncompliance noted Major areas inspected, implement ICFR90, App B, applicable codes & stds including QA review
KELLY, W D, WHITESELL, D E Region 4, Dallas, Vendor Inspection Branch 80/10/28 9pp 07490 060

8101230506 Ack receipt of 801219 ltr informing NRC of steps taken to correct violation noted in QA Program Insp Rept 99900524/80-02
POTAPQVS.U Region 4, Dallas, Vendor Inspection Branch 81/01/05
1p 07512 190

--8101230507 Responds to NRC 801124 ltr re violation noted in QA Program Insp Rept 99900524/80-02 Corrective actions documents posted where needed in safety-related areas & documents placed in storage
BERENZIO, P P Gibbs & Hill, Inc (subs of Dravo Corp) 80/12/19 14pp 07512 191

--8101230508 Forwards QA Program Insp Rept 99900524/80-02 on 801020-23 & notice of violation
POTAPQVS.U Region 4, Dallas, Vendor Inspection Branch 80/11/24
2pp 07512 192

--8101230509 Notice of violation from insp on 801020 23
* Region 4, Dallas, Office of the Director 80/11/21 1p
07512 194

--8101230510 QA Program Insp Rept 99900524/80-02 on 801020-23 Noncompliance noted failure to post copy of Section 206 & regulations
FOX, D F, JOHNSON, J N, HALE, C J Region 4, Dallas, Vendor Inspection Branch 80/11/21 11pp 07512 195

8101260161 Discusses 790706 interview w/S Newberry re events & levels of review concerning analysis of Michelson rept. "Decay Heat Removal During Very Small Break LOCA for B&W 205 Fuel Assembly PWR" Newberry unaware of rept prior to 790701.
STRICKLER, L J Office of Inspector & Auditor 79/07/10 1p
07507 090

--8101260173 Discusses 790702 interview w/G Marette re Michelson rept. "Decay Heat Removal During Very Small Break LOCA for B&W 205 Fuel Assembly PWR" G Marette received rept in 1977 or 1978, but did not review in detail WA Post article encl.
GABLE, D H Office of Inspector & Auditor 79/07/10 3pp
07507 091

--8101260201 Lists principal lines of inquiry on which investigation into handling of rept. "Decay Heat Removal During Very Small Break LOCA for B&W 205 Fuel Assembly PWR." will be based
IE & Ofc of Inspector & Auditor are responsible
THORNBURG, H D Division of Reactor Construction Inspection 79/05/24 1p 07507 098

--8101260208 Confirms 790608 memo characterizing C Michelson opinion that no adequate forum existed within nuclear regulatory sys for safety-related concerns info re decay heat removal problem.
encl
STRICKLER, L J Office of Inspector & Auditor 79/06/11 113pp
07507 099

--8101260218 Submits rept of interview w/RC Jones on 790327 re rept. "Decay Heat Removal During Very Small Break LOCA for B&W 205 Fuel Assembly PWR"
WARD, W J Office of Inspection & Enforcement, Office of the Director 79/03/29 2pp 07507 243

--8101260227 Draft Commission paper informing Commission of IE investigation results & proposed enforcement actions re B&W PWR response to small break LOCA's Forwards draft civil penalty package & notice of noncompliance
TELLO, V. Office of Inspection & Enforcement, Office of the Director 80/03/25 13pp 07507 268

--8101260237 Discusses IE May-Nov 1979 investigations into whether B&W had adequately analyzed potential safety problems & whether problems should have been reported per 10CFR21 No evidence constituting criminality found
CUMMINGS, J J Office of Inspector & Auditor 80/04/02 2pp
07507 288

8101260056 Forwards QA Program Insp Rept 99900048/80-02 on 801006-09 No noncompliance noted
POTAPQVS.U Region 4, Dallas, Office of the Director 80/11/05
2pp 07520 214

--8101260064 QA Program Insp Rept 99900048/80-02 on 801006-09 No noncompliance noted. Major areas inspected: implementation of 10CFR50, App B, criteria & applicable codes & stds including action on previous findings
HUNTER, V H, WHITEBELL, D E Region 4, Dallas, Vendor Inspection Branch 80/10/30 5pp 07520 216

8101260310 Ack receipt of 801121 & 1268 ltrs informing NRC of taken to correct deviation noted in QA Program Insp Rept 99900047/80-02
POTAPQVS.U Region 4, Dallas, Vendor Inspection Branch 80/11/05
1p 07526 021

--8101260317 Responds to NRC 801310 & 1203 ltrs re deviation in QA Program Insp Rept 99900047/80-02 Corrective actions complete DCR file reviewed, specific training session held, PQ2-001 revised & computer files reviewed & updated
MILLER, F D Westinghouse Electric Corp TCM-PO-102 80/12/20
2pp 07536 032

8101270751 Ack receipt of 801219 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900033/80-02
POTAPQVS.U Region 4, Dallas, Vendor Inspection Branch 81/01/05
1p 07549 135

--8101270955 Responds to NRC 801112 ltr re deviation noted in Insp Rept 99900033/80-02 Corrective actions 10CFR21 requirements incorporated in purchase orders for pressure boundary parts
BAKUS, F R Westinghouse Electric Corp 80/12/19 2pp
07549 156

--8101270958 Forwards QA Program Insp Rept 99900033/80-02 on 801110-20 & notice of deviation
POTAPQVS.U Region 4, Dallas, Vendor Inspection Branch 81/01/05
2pp 07549 158

--8101270963 Notice of deviation from insp on 801110-20
* Region 4, Dallas, Office of the Director 80/12/08 1p
07549 160

--8101270966 QA Program Insp Rept 99900033/80-02 on 801110-20 Noncompliance noted Part 21 not identified on purchase orders for safety-related items
MCNEILL, W H, WHITEBELL, D E Region 4, Dallas, Vendor Inspection Branch 80/12/08 4pp 07549 161

8101270970 Forwards QA Program Insp Rept 99900044/80-03 on 801110-20 No noncompliance noted
POTAPQVS.U Region 4, Dallas, Vendor Inspection Branch 80/11/05
2pp 07549 163

--8101270975 QA Program Insp Rept 99900044/80-03 on 801027-30 No noncompliance noted. Major areas inspected: fuel rod mfg particle fabrication & cleaning & previous insp action
MCNEILL, W H, WHITEBELL, D E Region 4, Dallas, Vendor Inspection Branch 80/11/15 6pp 07549 165

REG00 REGULATORY GUIDES

7907170051 Comments on proposed Reg Guide 1.1XX data base should be formulated based on current techniques & proposed improvements judged against current techniques
RENNERGER, D L Washington Public Power Supply System 79/07/17
4pp

7912310182 Comments on proposed reg guide, "Ultrasonic Testing of Reactor Vessel Heads During Inservice Examination"
Discussion should state that reg guide is intended to supplement ASME Section XI
BUCHHEIT, R H General Electric Co MFH-2H2-79 79/11/26
01661:358

8101060038 Forwards continuation of 800810 comments on proposed Guide RS 705-4 re lightning protection for nuclear power plants.
JOHNSON, I B Affiliation Unknown 80/10/08 35pp 07187 161

8101070245 Comments on second proposed Revision 2 to Reg Guide 1.8, "Personnel Qualification & Training" NRC should not finalize reg guide until ref documents are finalized
HAYDOCK, J A Florida Power & Light Co 3-120-19 80/12/04
07415 231

8101070251 Forwards comments on second proposed Revision 2 to Reg Guide 1.8, "Personnel Qualification & Training"
ABEL, J B Commonwealth Edison Co 80/12/04 4pp 07415 232

8101070255 Comments on proposed Revision 2 to Reg Guide 1.8, "Personnel Qualification & Training" Guidelines will have detrimental impact on safe operation of plants
PARKER, W O Duke Power Co 80/12/05 7pp 07415 233

B01070471 Forwards RI Dept. files & AP letter comments on proposed Revision 1 to Reg Guide 1.23. "Meteorological Programs in Support of Nuclear Power Plants".
NURLEY, T. E. Division of Systems Integration 80/12/05 1p 07405 337

--B01070478 Comments on proposed Revision 1 to Reg Guide 1.23. "Meteorological Programs in Support of Nuclear Power Plants". New paragraph should be inserted between second & third paragraphs of implementation section of guide.
SALR, R. L. Safety Program Evaluation Branch 80/11/06 2pp 07403 338

--B01070482 Trip report of B01007 & OB visit to Philadelphia, PA to discuss dynamic performance of wind vane & use of propeller anemometers, std methods for determining accuracy & precision of pressure measurements.
LEWIS, J. Accident Evaluation Branch 80/10/16 1p 07405 340

--B01070485 Comments on proposed Revision 1 to Reg Guide 1.23. "Meteorological Programs in Support of Nuclear Power Plants". Draft. "Std Method for Determining Dynamic Performance of Wind Vane." encl.
HYSBER, R. P. Commerce, Dept. of, National Oceanographic & Atmospheric Administration 80/12/05 14pp 07403 341

B01070495 Comments on proposed Revision 1 to Reg Guide 1.23. "Meteorological Programs in Support of Nuclear Power Plants". Document is excellent in all respects.
COPELAND, R. L. Energy, Dept. of, Clinch River Breeder Reactor Plant 80/12/05 1p 07404 350

B01070497 Forwards comments on second proposed Revision 2 to Reg Guide 1.8. "Personnel Qualification & Training".
MILLER, B. W. Ohio State Univ. 80/12/05 6pp 07404 344

B01080070 Comments on Revision 1 to draft Reg Guide 1.23. "Meteorological Programs in Support of Nuclear Power Plants". Guide fails to set forth guidance for "an acceptable program". Instrument requirements unjustified.
SULLIVAN, J. J. Consumers Power Co. 10273 80/12/02 7pp 07419 308

B01080105 Comments on proposed Revision 2 to Reg Guide 1.8 re personnel qualification & training. Training program fulfills objectives, however effectiveness is not determined by differences from civilian training programs.
KAPSALES, J. Affiliation Unknown 80/12/03 4pp 07419 206

B01080111 Comments on proposed revision to Reg Guide 1.80 (re Reg Guide 1.8B.3) re preoperational testing of instrument & control air sys. Rewording would improve guide w/o removing necessary requirements.
STANLEY, L. Quadrex Corp. LS-80-185 80/12/03 2pp 07419 254

B01080115 Forwards comments on second Revision 2 to Reg Guide 1.8 re personnel qualification & training.
QUACHEY, G. D. Washington Public Power Supply System 80/12/05 5pp 07419 249

B01080121 Comments on second proposed revision to Reg Guide 1.8 re personnel qualification & training. Recommendations should be adopted.
PUZM, L. C. General Electric Co. NYC 214 80/12/01 2pp 07417 360

B01090718 Comments on proposed Revision 2 to Reg Guide 1.8. "Personnel Qualification & Training". Intent should be to provide necessary knowledge & skills to assist operators in performing tasks more completely & aid supervisor decisions.
ARCONINI, G. C. Arizona Public Service Co. 80/12/15 3pp 07442 046

B01090724 Comments on draft Reg Guide FP 710-4. "Std Format & Content for Health & Safety Sections of Renewal Applications for U Fuel Fabrication Plants".
GETTIER, F. W. Gibbs & Hill, Inc. (subs. of Dravo Corp.) 80/12/11 1p 07429 361

B01090892 Comments on proposed Revision 1 to Reg Guide 1.23. "Meteorological Programs in Support of Nuclear Power Plants".
BRADBURY, R. B. Stone & Webster Engineering Corp. 80/12/09 1p 07443 356

B01090899 Comments on proposed Revision 1 to Reg Guide 1.144. "Auditing of QA Programs for Nuclear Power Plants". Audit checklists are not always in form consistent w/ official QA records & should not be retained as official QA records.
MILLS, L. M. Tennessee Valley Authority 80/12/06 2pp 07428 356

B01120001 Comments on proposed Revision 2 to Reg Guide 1.8. "Personnel Qualification & Training". Accuracy should be changed from "within factor of 2" to "within factor of 1".
HOLWAY, E. General Atomic Co. (subs. of GE) 80/12/05 1pp 07447 109

B01120242 Comments on proposed Revision 2 to Reg Guide 1.8. "Personnel Qualification & Training". "Acceptability ASME Section III Div. 1".
CAHWA, L. Birtel Power Corp. (subs. of Bechtel) 80/12/05 2pp 07446 222

B01120248 Submits clarification to B01205 concerning Reg Guide 1.8. "Personnel Qualification & Training".
PARKER, W. C. Duke Power Co. 80/12/10 2pp

B01120648 Reg Guide 1.85. Revision 1.7. "Design & Acceptability ASME Section III Div. 1".
Office of Standards Development, Director 80/12/05 1p 07494 171

B01140155 Comments on Reg Guide 1.144. "Auditing of Nuclear Power Plants". Retaining audit records for valid safety-related purpose; impose unjustified costs.
BUDNICK, R. H. General Electric Co. 80/12/05 07308 001

B01140356 Forwards Region 2 comments on draft Reg Guide 1.8. "Personnel Qualification & Training".
STONE, J. C. Reactor Programs Section 80/12/10 1p

--B01140409 Comments on draft Reg Guide 1.8B.3. "Personnel Qualification & Training".
HARRIS, C. E. Region 2, Atlanta, Reactor Control Support Branch 80/12/05 5pp 07462 083

B01140416 Forwards comments on proposed Revision 1.23. "Meteorological Programs in Support of Nuclear Power Plants".
QUACHEY, G. D. Washington Public Power Supply System 80/12/16 3pp 07462 079

B01210322 Forwards Draft 2 of proposed Reg Guide 1.8. "Personnel Qualification & Training".
Testing of Reactor Vessel Welds During Preservice Inspection.
ARLINGTON, A. Division of Engineering Standards 80/12/05 07308 001

B01220194 Comments on second proposed Revision 1.8. "Personnel Qualification & Training". Guidelines permit consideration of equivalent experience beyond an stated percentage.
UTLEY, E. E. Carolina Power & Light Co. 80/12/05 07500 093

B01220198 Forwards comments on second proposed Revision 1.8. "Personnel Qualification & Training".
SULLIVAN, L. M. Atomic Industrial Forum 80/12/05 07500 093

B01220205 Comments on second proposed Revision 1.8. "Personnel Qualification & Training". One yr. training in health physics should be required for protection technicians.
LECNARD, B. E. Institute for Resource Management 80/12/05 07503 085

B01220404 Comments on second proposed Revision 1.8. "Personnel Qualification & Training". Rule 1.8. Final versions of NUREG/CR-1280 & NUREG/CR-16 available prior to drafting of proposed rule.
COUNSILL, W. D. Connecticut Yankee Atomic Power Co. 80/12/05 07500 238

B01220552 Comments on second proposed Revision 1.8. "Personnel Qualification & Training". Require program for operators should be clearly defined.
LARSEN, K. R. Westinghouse Electric Corp. 80/12/05 07500 238

B01220560 Comments on second proposed Revision 1.8. "Personnel Qualification & Training". Degree inappropriate. Selected technical training & a think in diagnostic manner are also needed.
SHIELDS, S. J. Public Service Co. of Indiana 80/12/05 07500 169

B01260838 "For Comment" issue of proposed Reg Guide 1.8. "Personnel Qualification & Training".
Fuel Heat Generation in an Independent Spent Installation.
WORTHINGTON, P. Office of Standards Development 80/12/05 07534 153

P 034-4 Reg guide should be prepared.
 * Office of Standards Development. Director 80/12/31 6pp
 07534 137

01300894 Certified summary of ACRS Subcommittee on Regulatory Activities B01105 meeting in Washington, DC to review Revision 2 to Reg Guides 1.12 & proposed amend to 10CFR50 re domestic licensing of production & utilization facilities
 * ACRS - Advisory Committee on Reactor Safeguards 80/12/04 11pp
 07586 283

RESEARCH AND TECHNICAL ASSISTANCE REPORTS

01060097 "Experimental Facility & Preliminary Results for Flashing Transients at 1/15 Scale." technical memo
 CROLEY, C. SAM, R. Creare, Inc NRC-04-75-162 TM-708 80/07/31 68pp 07397 111

01060104 "LOFT Steam Generator Simulator & Pump Simulator Performance During LOFT Isothermal Test Series LI"
 JACOBY, M. B., PHABING, P. C. Idaho National Engineering Laboratory LTR 20-101, 79/09/03 60pp 07397 177

01060107 "Freezing of Multiphase Mixtures Flowing Downward in Circular Tubes." informal rept.
 GREENE, O. A., BARRY, J. J. Brookhaven National Laboratory BNL-NURE0-28302 80/08/31 84pp 07397 237

01060636 "Analysis of Hypothetical Accidents Resulting in Core Meltdown." monthly progress rept. Nov 1980
 DENNING, R. S., CYRULSKI, P., DAYDUT, P. Battelle Memorial Institute, Columbus Laboratories FIN A-4067 80/12/12 7pp 07392 173

01060832 "FLECHT BEASET." monthly status rept. Oct 1980
 MASSIE, H. W. Westinghouse Electric Corp NRC-04-77-127 8P-80-863 80/12/01 9pp 07401 041

01060923 "Shipping Cask Sabotage Source Term Investigation." monthly progress rept. Nov 1980
 TRUITT, R. D. Battelle Memorial Institute, Columbus Laboratories FIN B-6012 NRC-04-80-180 80/12/15 3pp 07401 098

01070036 "FLECHT BEASET." monthly status rept. Sept 1980
 MASSIE, H. W. Westinghouse Electric Corp NRC-04-77-127 8P-80-862 80/12/01 9pp 07413 335

01070043 "Steam Generator Tube Rupture Iodine Transport Mechanism." monthly progress rept. Nov 1980
 DENNING, R. S. Battelle Memorial Institute, Columbus Laboratories NRC-04-76-293 80/12/15 4pp 07414 001

01070534 "CREARE Refill Effects Program." technical memorandum
 SAM, R., SHIFF, W. Creare, Inc NRC-04-75-162 TM-705 80/06/30 65pp 07407 001

01100601 "Best Estimate Prediction for LOFT Nuclear Experiment L3-6." experiment prediction analysis rept
 CHEN, T., MODRO, S. M., CONDIE, K. O. Idaho National Engineering Laboratory, FIN A-6048 80/12/31 140pp 07431 122

01100861 "3WR Refill-Reflood Program." sixtieth monthly progress rept for Oct 1980
 BURNETTE, O. W., DIX, O. E. General Electric Co FIN B-5877 NRC-04-79-184 80/10/31 44pp 07439 088

01102090 "Environ Statements Project." monthly progress rept for Oct 1980
 ZITTEL, H. E. Oak Ridge National Laboratory, FIN B-0001 ORNL/ED/E18-141 80/10/31 9pp 07442 327

01102091 "Iodine Pathway Study." interim contractor repts for Jan-Mar & Apr-June 1980
 KELLER, J. H. Idaho National Engineering Laboratory FIN A-6288 80/06/30 5pp 07442 331

01102092 "Advanced Instrumentation for Reflood Studies Program." foreign trip rept
 BRITTON, C. L., BUCHANAN, M. E., HESS, R. A. Oak Ridge National Laboratory FIN B-0413 ORNL/FTR-99B 80/12/01 6pp 07442 334

01102095 "Mathematical Simulation of Sediment & Contaminant Transport in Surface Waters." quarterly rept. Apr-June 1980
 * Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2271 80/06/30 8pp 07442 335

807ARSK1.P C Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2287 80/12/15 4pp 07447 192

801130693 "Experimental Criticality Data for Code Validation." informal quarterly progress rept for Jul-Sept 1980
 BIERMAN, S. R. Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2074 80/12/03 3pp 07454 035

801130697 "Division of Reactor Safety Research (ORNL) Programs." monthly highlights for Nov 1980
 MYNATT, F. R. Oak Ridge National Laboratory 80/12/10 38pp 07453 345

801150598 "Definition of Parameters for Major Accidents at Waste Solidification & Spent Fuel Storage Facilities." informal monthly progress rept for Nov 1980
 FREDERICK, E. J. Oak Ridge National Laboratory FIN B-0425 80/12/17 3pp 07463 202

801150600 "LWR In-Plant Measurement Program." informal monthly progress rept for Nov 1980
 HANDLER, J. H. EG&G Idaho, Inc FIN A-6075 80/12/19 3pp 07308 001

801150605 "Source Term Characterization Resulting From Explosively Caused Secondary Violations of Spent Fuel Shipping Casks." informal monthly progress rept for Nov 1980
 TRUITT, R. D. Battelle Memorial Institute, Columbus Laboratories FIN B-6710 80/12/15 3pp 07465 242

801150610 "Physical Protection of Nuclear Facilities." informal monthly progress rept for Nov 1980
 CHAPMAN, L. D. Sandia Laboratories FIN A-1060 80/12/11 5pp 07465 245

801150617 "Shipping Cask Sabotage Source Term Investigation." informal monthly progress rept for Nov 1980
 BUCHMIDT, E. W. Battelle Memorial Institute, Columbus Laboratories FIN B-6012 80/12/16 3pp 07465 250

801150632 "Safeguards for Proliferation Resistant Fuels." informal monthly progress rept for Nov 1980
 CADWELL, J. J. Brookhaven National Laboratory FIN A-3221 80/12/11 3pp 07465 266

801150641 "Safeguards for Proliferation Resistant Fuel Cycles." informal monthly progress rept for Oct 1980. ltr rept
 CADWELL, J. J. Brookhaven National Laboratory FIN A-3221 80/12/11 3pp 07465 269

801210325 Submits status repts on core melt programs for Nov 1980
 BERMAN, M. Sandia Laboratories 81/01/08 7pp 07488 233

801210542 "3WR Blowdown/ECC Program." informal monthly progress rept for Jul 1980
 BURNETTE, O. W. General Electric Co NRC-04-76-215 80/08/07 4pp 07489 106

801210576 "Human Error Rates - Quantification Method from Nuclear Experience & Data."
 LUCKAS, W. J., HALL, R. E. Brookhaven National Laboratory BNL-NURE0-28061 81/01/15 5pp 07489 118

801210585 "Analysis of Natural Circulation Events in B&W Plants Using Super Sys Code - W." submitted to ANS/FHS/AIE 80117-21 international conference
 GUPPY, J. O., HORAK, W. C., VAN TUYLE, G. J. Brookhaven National Laboratory BNL-NURE0-28049 80/11/21 6pp 07489 125

801210610 "TRAC-PIA Predictions of Battelle-Frankfurt Top Blowdown Test"
 NEYMOT, N. L. Brookhaven National Laboratory BNL-NURE0-28127 81/01/15 8pp 07489 223

801210615 "Independent Assessment of TRAC-PIA W/Harviken Critical Flow Tests"
 RGHATGI, U. S., SANJORN, Y. Brookhaven National Laboratory BNL-NURE0-28126 81/01/15 7pp 07489 231

801210622 "Independent Assessment of TRAC-PIA W/Super-Canon Blowdown Tests"
 SAHA, P., SANJORN, Y. Brookhaven National Laboratory BNL-NURE0-28125 81/01/15 6pp 07489 243

8101220255 Presentation entitled 'Real Time Loss Detection Process' for R00326 second annual symposium on safeguard nuclear plant
CARBY, J V, BURK, D R, GRAVEL, D T Lawrence Livermore Lab
UCRL-82225 60/03-20 9pp 07309 001

9101220260 Evaluation of Pocket Files of Terminated License
progress report for Oct 1980
HOLWAY, C. F. WINTERBURN, J. Oak Ridge National Laboratory
A-9095-7 CRNL/HASRD-101 80/10/31 16pp 07902 204

B101220266 "Analysis of Hypothetical Accidents Resulting in
Meltdown." monthly progress rept for Aug 1980
DENNING, R S, CYRULSKI, P, BAYBUTT, P Battelle Memorial
Laboratory Cincinnati, OH 45467 AO/09/15 9pp 07

0101220271 "Environ Assessments of Fuel Cycle Facilities."
progress rept for Oct 1980
21TTEL.H.E Oak Ridge National Laboratory FIN 8-0279
CRNL/EN/EIS-140 80/10/31 3pp 07902 229

8101220277 "Safeguards Analysis for Byproduct Mottis & Seal
of ENL" Monthly progress rept for Nov 1980
CHESTER, R D , RANDOLPH, L L Oak Ridge National Laboratory
3-6108 OAKR/HASRD-105 80/12/05 Bpp 07502 234

R101220285 "Environ Statements Project." monthly progress
 1980
 ZITTEL, H. E. Oak Ridge National Laboratory FIN 8-0601
 GRNL/ED/EIS-143 RS/11/30 4pp 07502 242

B101220620 P4C-2991
"Visual Aesthetic Prediction Method for Use in Benefit-Cost
Analysis." interim rept. except from NUREQ/CR-0909. Vol 2
ADAMS, R C. CURRIE, J W Battelle Memorial Institute, Pacific
Northwest Laboratory P4C-2991 80/08/J1 90pp 0749

B101220622 BRL-NUREG-27961
 "NRC Nuclear Waste Mgt Technical Support in Development
 Nuclear Waste Form Criteria Task 1 Waste Package Overview
 Interim Report
 DAYAL, R. SWYLER, K. J., EDD, P. Brookhaven National Labor.
 A-3158 BRL-NUREG-27961 80/06/30 220pp 07498 062

8101220623 BNL-NUREG-28115
"Quantitative Nuclear Power Plant Siting Methods: Review
CURRENT Practice," informal rept
PIERCE, B L., ROSE, M D Brookhaven National Laboratory
BNL-NUREG-28115 77/08/31 61pp 07498 280

8101220625 DR-L-NUREG-28J43
"Liquid Entrainment By Expanding Gas Or Vapor Bubble Rev
of Experiments & Models," informal rept
POSZYNSKI, J R. , QINSBERG, I Brookhaven National Laborat
A-3024 DR-L-NUREG-28J43 80/09/30 62pp 07499 065

8101220626 BNL-NUREG-27834
"Nonlinear Dynamic Analysis of Piping Sys Using Pseudo F
Method," Informal rept
BEZLER, P. PHACHUTAM, S Brookhaven National Laboratory
HAFTZMAN, M Mechanical Engineering Branch BNL-NUREG-2
80/01/31 33pp 07499 125

8101220620 BNL-NUREG-28625
"Preliminary Determination of Power Shapes, Doppler
Coefficients & Sodium Void Worths for CDS Phase-II Oxide
Core." Informal rept
LUDWIG, R. M., MALLON, A. N. Brookhaven National Laboratory
BNL-NUREG-28625 80/11/30 3200 07499 216

8101220642 DNL-NUREG-28109
Thermal-Hydraulic Effects on Ctr Rod Drop Accidents in
BWR, Informal rept.
CHENG, H S , DIAMOND, D J Brookhaven National Laboratory
A-3323 DNL-NUREG-28109 00/07/31. 74pp. 07499 304.

B101220643 "Technology & Cost Termination Surveys Association/Decommissioning of Nuclear Facilities," monthly progress report for Nov 1980
WITHERSPOON, J., HOLDWAY, C F Oak Ridge National Laboratory
A-9042 ORNL/HASRD-106 80/11/30 4pp 07903 191

B101220646 "Dosimetry & Biotransport Models to Implement A
Uncertainties in Assessment of Long-term Collective Dose
Health Effects.' rept on foreign travel
KOCHEK, D C Oak Ridge National Laboratory FIN A-9041
GRNL/FTR-983 80/11/17 6pp 07503:195

8101220649 "BUR Glowdown/ECC," monthly progress rept for G
BURNETTE, G W General Electric Co FIN D-3014 NRC-04
80/11/20 21pp 07503 301

01220249 PHL-2950

"Valuing Environ Via Bidding Games Psychological Perspective," interim rept, excerpt from NUREG/CR-0989, Vol. 2, p. 2.

HEBERT, J A , SHIKIAR, R , PERRY, R W Battelle Memorial Institute,
Pacific Northwest Laboratory PNL-2950 80/08/31 90pp
Q7503 280

B101220650 "3-R Refill/Reflood Program." monthly progress rept for Nov 1980
BURNETTE, G U General Electric Co FIN B-5877 NRC-04-79-184
80/12/16 12pp 07503 222

B101220655 "3-R Blowdown/ECC Program." monthly progress rept for Nov 1980
BURNETTE, G U General Electric Co FIN B-3014 NRC-04-76-215
80/12/15 6pp 07503 234

B101230039 "Environ Assessments of Fuel Cycle Facilities." monthly progress rept for Nov 1980
ZITTEL, H E Oak Ridge National Laboratory FIN B-0279
CRNL/ED/EIS-142 80/11/30 5pp 07510 338

B101230047 "Review of LWR Safety."
CHENO, H Brookhaven National Laboratory BNL-NUREQ-28722.
80/12/31 43pp 07510 343

B101230189 "LWR Thermal Hydraulic Development Program." monthly highlight ltr for June 1980
ABUAF, N Brookhaven National Laboratory FIN A-3045 80/06/30
6pp 07308 001

B101230200 "Advanced Reactor Safety Analysis." monthly highlights for June 1980
BARI, R A Brookhaven National Laboratory FIN A-3000 80/07/08
4pp 07511 037

B101230202 "Advanced Reactor Safety Analysis." monthly highlights for Jul 1980
BARI, R A Brookhaven National Laboratory FIN A-3000 80/08/07
4pp 07511 041

B101230206 "Thermal Reactor Safety Code Development." monthly highlights for Jul 1980
LEVINE, M H Brookhaven National Laboratory 80/07/31 4pp
07511 045

B101230209 "SBC Code Development & Verification." monthly highlights for Jul 1980
GUPPY, J G Brookhaven National Laboratory FIN A-3015 80/08/05
6pp 07511 049

B101230213 "Evaluation of LWR RHR under Accident Conditions." monthly highlights for June 1980
BARI, R A Brookhaven National Laboratory FIN A-3315 80/07/08
6pp 07511 055

B101230236 "LWR Thermal Hydraulic Development Program." monthly highlight ltr for Jul 1980
ABUAF, N Brookhaven National Laboratory FIN A-3045 80/07/31
4pp 07511 225

B101230243 "Stress Corrosion Cracking of PWR Steam Generator Tubing." monthly highlights for Jul 1980
BULISCHECK, T J VAN ROYEN, D Brookhaven National Laboratory FIN A-3208 80/07/31 5pp 07511 227

B101230248 "HFOR Safety Program." monthly highlights ltr for Jul 1980
BASTRE, C Brookhaven National Laboratory FIN A-3016 80/08/08
6pp 07511 234

B101230262 "Evaluation of LWR RHR under Accident Conditions." monthly highlights for Jul 1980
BARI, R A Brookhaven National Laboratory FIN A-3315 80/08/07
7pp 07511 244

B101230743 "Advanced Reactor Safety Analysis." monthly highlights for Aug 1980
BARI, R A Brookhaven National Laboratory FIN A-3000 80/09/08
4pp 07511 251

B101230751 "Evaluation of LWR RHR under Accident Conditions." monthly highlights for Aug 1980
BARI, R A Brookhaven National Laboratory FIN A-3315 80/09/08
6pp 07511 255

B101230757 "RAMONA-3B Code Mod & Evaluation." monthly highlight ltr for Nov 1980
DIAMOND, D J Brookhaven National Laboratory FIN A-3014 80/11/30
4pp 07511 261

B101260752 "Simulator Improvement Program." monthly highlights for Nov 1980
WULFF, W Brookhaven National Laboratory FIN A-3014 80/11/30
4pp 07536 014

B101260828 "Stress Corrosion Cracking of PWR Steam Generator Tubing." monthly highlights for Oct-Nov 1980
JULISCHECK, T J VAN ROYEN, D Brookhaven National Laboratory FIN A-3208 80/12/05 9pp 07534 138

B101260877 "HFOR Safety Program." monthly highlights for Nov 1980
BASTRE, C Brookhaven National Laboratory FIN A-3016 80/12/05
6pp 07534 147

B101260844 "TRAC Assessment & Model Development." monthly highlight ltr for Aug 1980
SAHA, P Brookhaven National Laboratory FIN A-3215 80/08/31
6pp 07534 161

B101260849 "Advanced Reactor Safety Analysis Technical Assistance." Reactor Projects." monthly highlights for Sept 1980
BARI, R A Brookhaven National Laboratory FIN A-3000 80/10/13
4pp 07536 027

B101260850 "TRAC Assessment & Model Development." monthly highlight ltr for Jul 1980
SAHA, P Brookhaven National Laboratory FIN A-3215 80/07/31
6pp 07534 167

B101260856 "Evaluation of LWR Residual Heat Removal Under Accident Conditions." monthly highlights for Sept 1980
BARI, R A Brookhaven National Laboratory FIN A-3315 80/10/13
5pp 07534 175

B101270071 "LWR Thermal Hydraulic Development Program." monthly highlights ltr for Sept 1980
ABUAF, N Brookhaven National Laboratory FIN A-3045 80/09/30
4pp 07547 204

B101270161 "Burnite progress rept for Dec 1980 for Contract NRC-04-7-162
CROWLEY, C J, ROTHE, P H Creare, Inc NRC-04-75-162 345-12
81/01/09 3pp 07545 357

B101270201 "Distribution Coefficients for Radionuclides in Aquatic Environments." quarterly rept for Dec 1979-Feb 1980.
Washington Univ of FIN B-5749 80/07/31 10pp 07547 061

B101270213 "Coastal Zone Predictive Modeling at Power Plant Sites." quarterly progress repts for Oct-Dec 1979 & Jan-Mar 1980
BITMAR, B Argonne National Laboratory FIN A-2050 80/06/30
16pp 07547 077

B101270229 "Power Plant Condenser Tube Simulator Research Project." progress rept for 800315-0615
O'CONNOR, J H New York Univ Medical Center New York, NY FIN B-6298 80/07/31 13pp 07547 099

B101270391 "Thermal Reactor Safety Code Development." highlights for Aug 1980
LEVINE, M H Brookhaven National Laboratory FIN A-3014 80/08/08
3pp 07549 030

B101270974 "Submit status rept for Jul 1980 re qualification of safety related equipment. Supporting tables and
RONZON, L L Sandia Laboratories SCL/IEHQ T-MSLR 80/08/06
07549 191

B101270992 "Two-Phase Flow Phenomena in Nuclear Reactor Technology." highlights for Jan-Mar 1980
LAHEY, R T Rensselaer Polytechnic Inst NRC-04-76-301 80/03/31
34pp 07544 001

B101280548 "Shipping Cask Sabotage Source Term Investigation." info monthly progress rept for Dec 1980
SCHMIDT, E W Battelle Memorial Institute, Columbus Laboratories FIN B-6012 81/01/15 9pp 07187 001

B101280551 "Experimental Criticality Data for Code Validation." informal quarterly progress rept Oct-Dec 1980
BIERMAN, S R Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2094 81/01/05 3pp 07550 226

B101290073 "Forwards status rept of ref repository & technology transfer program for Jul 1980.
ORITZ, N R Sandia Laboratories FIN A-1158-9 80/08/25 5pp
07567 229

B101290090 BNL-NUREQ-28682
"Review of Recent Studies of Radiation Induced Behavior of Ion Exchange Media." informal rept.
SHYLER, K, BARLETTA, R E, DAVIS, R E Brookhaven National Laboratory FIN A-3162 BNL-NUREQ-28682 80/11/30 34pp 07567 240

B101290135 "Investigation of Accident Induced Flow & Matl Transport in Nuclear Facilities." Informal progress rept for Nov 1990
MARTIN, R. A., GREGORY, W. S. Los Alamos Scientific Laboratory FIN
A-7629 B1/01/06 7pp 07567 283

B101290181 Forwards rept of ref repository, & technology transfer
program for Oct. 1980
FINLEY, N. C. Sandia Laboratories FIN A-1158-9 B0/11/20 8pp
07549 338

B101290182 "Steam Generator Tube Rupture Iodine Transport Mechanisms."
monthly progress rept for June 1990
DENNING, R. S. Battelle Memorial Institute, Columbus Laboratories
NRC-04-76-293 B0/07/14 4pp 07575 205

B101290186 Submits status rept of core damage accident flow path &
regulation study for Oct 1980
WICKHAM, J. W. Sandia Laboratories B0/11/12 2pp 07566 353

B101290193 Speech entitled "Safeguards Research at LLL," presented at
B03325-28 Second Annual Symposium of Safeguards & Nuclear
Matl Mgt
DUNN, D. R., HJEBEL, J. O., PEGGID, A. J. Lawrence Livermore Laboratory
UCAL-82224 B0/03/20 5pp 07575 209

B101290213 Forwards status repts for work performed for Probabilistic
Analysis Staff for Aug 1980
MCCLOSKEY, D. J. Sandia Laboratories FIN A-1192 B0/09/24 31pp
07570 271

B101290245 Forwards status rept of work done for Probabilistic Analysis
Staff for Jul 1980
MCCLOSKEY, D. J. Sandia Laboratories FIN A-1192 B0/08/29 30pp
07570 289

B101290279 Submits monthly status rept of environ qualification of
safety-related equipment for Aug 1980
WOLK, L. L. Sandia Laboratories FIN B-3101 SNL/IEHQ, T-MLSR
B0/09/09 3pp 07570 261

B101290239 B101290243
Submits status rept of environ qualification of safety-
related equipment for Oct 1980
WOLK, L. L. Sandia Laboratories FIN B-3101 SNL/IEHQ, J-MLSR
B0/11/11 2pp 07570 332

B101290668 Water Reactor Research Directorate monthly rept, Apr 1980,
for semiscale, thermal, fuels behavior program, 2D/3D program,
code development & analysis program, code assessment &
applications program, GPP & line items
BOSTWICK, W. E., YARRINGTON, L. J. Idaho National Engineering Laboratory
B0/05/31 197pp 07566 143

B101290674 "Matl Control & Accounting Effectiveness Evaluation
Development." Informal progress rept, Aug 1980
FOGGO, A. J. Lawrence Livermore Laboratory FIN A-0115 B1/01/07
9pp 07568 340

B101290679 "Definition of Parameters for Major Accidents at Waste
Solidification & Spent Fuel Storage Facilities." progress
rept, Dec 1980
FREDERICK, E. J. Oak Ridge National Laboratory FIN B-0425
B1/01/21 4pp 07568 349

B101290682 "Evaluation of Docket Files of Terminated Licenses."
progress rept, Nov 1980
HOLWAY, C. F., WITHERSPON, J. Oak Ridge National Laboratory FIN
A-9085-7 ORNL/HASRD-104 B0/11/30 28pp 07574 259

B101290687 "Nondestructive Examination Evaluation Support." progress
rept, Dec 1980
SMITH, J. H. Oak Ridge National Laboratory FIN B-0233
ORNL/MCD/NEES-B B1/01/09 3pp 07574 287

B101290691 "Analysis of Hypothetical Accidents Resulting in Core
Meltdown." progress rept, Dec 1980
DENNING, R. S., CYBULSKI, P., PAYBUTT, P. Battelle Memorial Institute,
Columbus Laboratories FIN A-4067 B1/01/15 9pp 07574 290

B101290741 "Advanced Two-Phase Flow Instrumentation Program."
preliminary rept on heated thermocouple response during
thermal hydraulic test Facility Test 3 07 9 quasi-steady-
state film boiling, B00712, 18, 23 & 1001
TURNAGE, A. G., DAVIS, C. E., GLOVER, W. H. Oak Ridge National Laboratory
FIN B-0401 B0/12/31 33pp 07568 001

B101290761 "Steam Generator Tube Rupture Iodine Transport Mechanism."
progress rept, Dec 1980
DENNING, R. S. Battelle Memorial Institute, Columbus Laboratories
B1/01/15 5pp 07568 325

B101290763 "Accident Aerosol Characterization." d
rept, Dec 1980
GIZARSKI, P. C. Battelle Memorial Institute, Pacific
Laboratory FIN B-2287 B1/01/16 5pp 0730

B101300328 "BWR Blowdown/Emergency Core Cooling P
monthly progress rept for June 1980
JURNETTE, O. W. General Electric Co FIN B-3014
B0/07/09 61pp 07582 229

B101300145 LO-14-80-071
"Effects of Fuel Centerline Thermocouples on Fu
Steady State Temp & Stored Energy"
CARBONEAU, M. L. EG&G Idaho, Inc LO-14-80-071
07583 127

B101300199 EG0-WRR-5311
"Monthly Rept for Semiscale, 2D/3D, Code Developm
Assessment & Application Divs. & Thermal Fuels B
Program"
LEACH, L. P. EG&G Idaho, Inc EG0-WRR-5311 B0
07580 171

B101300543 BNL-NUREG-28796
"AUTOMATIC GENERATION OF CROSS SECTION INPUT FO
DYNAMICS CALCULATIONS." INFORMAL REPT
EISENHART, L. D., DIAMOND, D. J. Brookhaven Nation
A-3212 BNL-NUREG-28796 B0/11/30 19pp 07

B101300674 BNL-NUREG-28797
"Axial Power Distribution Control Strategies fo
Informal Rept
TODDSCH, M., ARONSON, A. L., DIAMOND, D. J. Brookha
Laboratory FIN A-3212 BNL-NUREG-28797 B0/
07585 059

B101300682 BNL-NUREG-28787
Thermal-Hydraulic Model of BNL-TWIGL." Informal
CHENO, H. Brookhaven National Laboratory FIN
BNL-NUREG-28787 B0/12/31 113pp 07585 119

B101300822 "Quick-Look Rept on LOFT Nuclear Exper
preliminary data analysis rept.
MCCLREERY, G. E. EG&G Idaho, Inc FIN A-6048. E
B0/12/31 58pp 07584 024

B101300624 "EWRI Activities in Support of NRC for
Synthetic Aperture Focusing Technique for Ultra
Testing." monthly progress rept for Dec 1980
HAMIL, D. A. Southwest Research Institute, NRC
7pp 07586 014

B101300843 "LOFT Monthly Progress Rept for Nov 19
KAUFMAN, N. C. EG&G Idaho, Inc FIN A-6048. EG
B0/12/31 94pp 07585 256

REVIEW GRP NRC RESEARCH REVIEW GROUPS

B101310226 Forwards Ofc of Nuclear Regulatory Res
29 memos referred to in NUREG-0735, "Plan for D
Safety Goal." Matl should be included in PDR fi
encs
LARKINS, J. T. Program Coordination Branch. B0/
07371. 201

B101030293 Comments on working paper, "Criteria f
Formulation." Question of verifiability must no
in subordinate rule M Spangler comments on dra
ERNST, M. L. Assistant Director for Technology R
6pp 07309 001.

B101070004 Responds to FOIA request for four cate
cold shutdown w/ regard to fire protection requi
App R to 10CFR50 Forwards D Davis 790614 memo &
J Knight memo re 790228 review group meeting.
FELTON, J. M. Division of Rules and Records. B0/
07414 182

B101070059 Responds to FOIA request for six cate
protection requirements in App R to 10CFR50 Enc
draft memo is responsive to request & will be p
FELTON, J. M. Division of Rules and Records. B0/
07414: 197

--B101070070 Summary of 790228 fire protection re
discuss differences in fire protection measur
Div of Sys Safety & Div of Operating Reactors
redundant divs of sys necessary for safe hot
MATTHEWS, P. R. Auxiliary Systems Branch, WNI
Director for Engineering. 79/03/14. 18pp.

8101100341 Informs that Steering Group on Development of Safety Goal will concentrate on three extant approaches to formulating criteria during 801120 meeting. Decision was mistake in view of fundamental difference in nature of approaches.
LIBARKIN, M W ACRS - Advisory Committee on Reactor Safeguards
80/11/28 2pp 07443 331

8101120049 Comments on NUREG-0735 re NRC plan for developing safety goal. Endorses concept. Goal should focus on providing adequate level of protection to public relative to benefit derived from plant-electrical power production.
SHERWOOD, G O General Electric Co MFN-204-B0 80/11/26 2pp 07309 001

8101120053 Responds to request for comments on list of topics being considered in development of safety goal for nuclear power plants. Many individuals exhibit fairly extreme risk aversion to low probability-high consequence events.
BUEHRING, H A Argonne National Laboratory 80/11/21 2pp 07447 083

8101130033 Forwards draft "Safety Goal Issue in Historical Perspective," per request.
STOIRER, C R Office of the General Counsel 80/12/22 1p 07448 300

--8101130039 "Safety Goal Issue in Historical Perspective," draft.
MAZUZAN, G T, WALKER, J S Office of the Secretary of the Commission 80/12/31 25pp 07440 301

8101130284 Responds to 801208 request for comments re LOFT special review group studies. Option A based on selection of most meaningful & expedient tests.
SCHERER, A E C-E Power Systems LD-81-C03 81/01/09 2pp 07447 223

8101140042 Requests review & comments on encl working paper no later than 801205. Comments will be used in preparation of preliminary policy paper.
EEGE, O Office of Policy Evaluations 80/12/01 5pp 07460 255

8101140054 Submits highlights of D Sidebotham & C Iselin 801117 interviews. Safety-cost tradeoff should be permissible only after prescribed min safety level is met. Cost should not bar retrofit.
EEGE, O Office of Policy Evaluations 80/12/08 2pp 07460 260

8101140066 Informs that outline proposed in working paper re safety goal formulation suffers from definitional confusion. Outline should be restricted to safety goals.
LIBARKIN, M W ACRS - Advisory Committee on Reactor Safeguards.
80/12/04 3pp 07460 262

8101140074 Informs of NC Rasmussen 801117 interview to gain benefit of views re establishment of safety goals. Demand for probable risk assessment exceeds available supply of people.
EEGE, O Office of Policy Evaluations 80/12/10 3pp 07460 292

8101140090 Informs of D Bridenbaugh & R Hubbard 801105 interviews re views on safety-goal formulation. Safety assurance effectiveness depends on factors that involve direct costs to utility.
EEGE, O Office of Policy Evaluations 80/12/04 2pp 07460 295

8101140102 Informs of V Joksimovic, WJ Houghton & CR Fisher 801104 interviews re thoughts on safety-goal formulation. Quantitative safety goals should be set before other major rulemakings are completed.
EEGE, O Office of Policy Evaluations 80/12/08 2pp 07460 313

8101210483 Forwards comments re future LOFT test plans for special review group. No tests necessary on safety basis. Submits table summarizing tests useful for code assessment. LOFT not representative of expected PWR behavior.
ANDERSON, T M Westinghouse Electric Corp NS-TMA-2367 81/01/16 7pp 07409 271

8101220480 Responds to 801208 request for comments on LOFT special review group studies. Option A program recommended. Tests L2-B, L7-3 & L8-4 should be carefully evaluated from cost-benefit standpoint.
TAYLOR, J H Babcock & Wilcox Co. 81/01/20 2pp 07502 259

8101220497 Responds to 801208 request for comments on LOFT special review group studies. Proposed testing in areas of man-machine interface & degraded cooling are premature. Code verification & sealing will address PWR technology.
SHERWOOD, G O General Electric Co MID-10-B1 81/01/15 2pp 07502 264

8101290377 Notification of contract execution "Consultant to Special Review Group," awarded to Aerospace Corp.
LITTLE, M Administrative Contracts Branch FIN B-7490
NRC-04-01-197 80/12/27 1p 07570 264

--8101290341 Contract "Consultant to LOFT Special Review Group" awarded to Aerospace Corp.
CULVER, C M Aerospace Corp FERLMAN, J Administrative Contracts Branch FIN B-7490 NRC-04-01-197 80/12/29 5pp 0

SECY POSITION PAPERS BEFORE THE COMMISSION

8011190612 SECY-80-497

Recommends that Commissioners conclude that no revisions to delegations of authority are required by Reorganization Plan 1 of 1980. Relevant excerpts from NRC manual & list of delegations in code to Commission level & boards encl.
SICKMILL, L Office of the General Counsel 80/11/10 2pp 06916 001

--8011190620 Advises that position is delegated authority for classification of info as top secret. Authority may not be redelegated. Authority to classify info at secret & confidential levels may be delegated as noted.
HENDRIE, J M Commissioners 79/01/02 1p 06916 001

--8011190627 Advises that position is delegated authority for classification of info as top secret. Authority may not be redelegated. Authority to classify info at secret & confidential levels may be delegated as noted.
HENDRIE, J M Commissioners 79/01/02 1p 06916 001

--8011190641 Advises that position is delegated authority for classification of info as top secret. Authority may not be redelegated. Authority to classify info at secret & confidential levels may be delegated as noted.
HENDRIE, J M Commissioners 79/01/02 1p 06916 001

--8011190657 Delegates authority to administer oaths & affirmable conduct of investigations on matters within delegated authority. Authority may be redelegated to Assistant Director for Investigations of Office of Inspector & Auditor.
HENDRIE, J M Commissioners 79/10/26 1p 06916 001

--8011190663 Delegates responsibilities for authorizing office for Commissioners & staff to each Commissioner & Secretary of Commission. Responsibilities may be redelegated within each office w/proper notification.
RENDEN, M A Commissioners 77/01/21 1p 06916 001

--8011190673 Designates line of succession for delegation of direct Commission operations & emergency functions pursuant to noted conditions.
CHILKIS, J Office of the Secretary of the Commission 2pp 06916 001

--8011190681 Delegates authority to carry out NRC national emergency functions to three executive teams designated Alpha, Bravo, Charlie. Each team shall be activated by Commission or highest official in line of succession.
CHILKIS, J Office of the Secretary of the Commission 2pp 06916 001

8101200008 SECY-80-501

Forwards proposed FR notice on disposition of Critical Mass Energy Project, et al petition for rulemaking re emergency response, draft ITR to petitioners & proposed Congressional letter to Representative M. Udall.
HINDO, J R Office of Standards Development, Director, 19pp 03767 181

8101220487 Transcript of 801211 Affirmation Session 80-54 in Washington, DC re SECY-80-448, SECY-A-80-168 & SECY-80-482.
Pp 1-11
* Commissioners 80/12/11 13pp 07335 142

--8012110612 Draft Commission paper re denial of Public Citizen Litigation Group petition for rulemaking re increase in required levels of financial protection for reactor operators. Abstracts of comments & draft FR notice encl.
DEWATON, H R Office of Nuclear Reactor Regulation, Director 80/10/23 48pp 03771 145

--8010230624 SECY-80-448

Requests Commission approval of encl revised narrative explanation of Table 5-3 specified in Commission order on final fuel cycle rule & draft FR notice.
DAVIS, J G Office of Nuclear Material Safety & Safeguards 80/09/29 100pp 06747 001

8012240377 Informs of review of proposed general evaluation of Agreement State radiation control comments
RATHLEBERGER Interior Dept of FR 00/1159 07324 091

801060622 Responds to FOIA request for listing of companies licensed by NRC to use radioactive materials & addresses for Agreement States which licenses Forwards computer printout w/o encl FELTON, J H Division of Rules and Records 02 07399 360

801060525 FOIA request for listing of people 3/0 by NRC to use radioactive mat'l & state agencies for Agreement States which issue licenses to co RUBIECKI, G Axion Industries Services, Inc 02 07399 361

801070532 Forwards M O'Brien & C Oyster of Gunn 801117 ltr re Horsetake Mining Corp till applic Ofc of State Programs should respond as matter Agreement State SCARANO, R A Uranium Recovery Licensing Branch 07415 298

801070541 Forwards transcript of State Liaison G meeting in Washington, DC Comments requested by CORNELL, E H Office of the Executive Director 80/12/17 1p 07407 071

--801070545 Transcript of State Liaison Officers Washington, DC Pp 1-124
* Commissioners 80/12/10 129pp 07407 0

--801070590 Transcript of State Liaison Officers Washington, DC Pp 1-259
* Commissioners 80/12/09 260pp 07407 1

8010705942 Forwards JD Nelson rept in response to assessment of adequacy of NM followup to NRC ltr by Church Rock Can failure w/o rept SCARANO, R A Uranium Recovery Licensing Branch 07415 087

801090328 Confirms NRC 801024 recommendations for of state radiation control program Addl staff recruited for present radioactive matts program regulatory program for U mills is currently und KERR, O W Office of State Programs, Director 07442 089

--801090335 Forwards comments from NRC 801020-24 radiation control program Review of state reg 1s forthcoming LUBENAU, J O Assistant Director for State Ag 80/11/17 5pp 07442 092

801100213 Informs of review of ltr re 800923 mee comments & recommendations in 800730 ltr for in agreement matts program Recommendations result A Schneider site visits will be incorporated in OOLDIMAN, H L New York, State of 80/10/21 1

801100221 Expresses appreciation for visit to AL difficult state has encountered in obtaining funding to carry out responsibilities under exi agreements AXELROD, D New York, State of 80/10/17 1p

801120010 Comments on evaluation of QA programs NRC should standardize program w/Agreement State paid to Agreement State or NRC for any licensee duplicate fee should be levied by another licen CASH, A Non-Destructive Testing Management Ass 012 80/11/12 1p 07447 094

801140084 Submits comments on notice of proposed evaluation of Agreement State radiation control NRC is attempting futile effort in finding clea w/numerical indicators to judge compatibility FUNDERBURG, R D Idaho, State of 80/10/30 2

801140092 Submits comments on revised criteria f Agreement State programs, in response to State o ltr WILSON, E F Arkansas, State of 80/10/28 2p

8012240377 Informs of review of proposed general evaluation of Agreement State radiation control comments
RATHLEBERGER Interior Dept of FR 00/1159 07324 091

801060622 Responds to FOIA request for listing of companies licensed by NRC to use radioactive materials & addresses for Agreement States which licenses Forwards computer printout w/o encl FELTON, J H Division of Rules and Records 02 07399 360

801060525 FOIA request for listing of people 3/0 by NRC to use radioactive mat'l & state agencies for Agreement States which issue licenses to co RUBIECKI, G Axion Industries Services, Inc 02 07399 361

801070532 Forwards M O'Brien & C Oyster of Gunn 801117 ltr re Horsetake Mining Corp till applic Ofc of State Programs should respond as matter Agreement State SCARANO, R A Uranium Recovery Licensing Branch 07415 298

801070541 Forwards transcript of State Liaison G meeting in Washington, DC Comments requested by CORNELL, E H Office of the Executive Director 80/12/17 1p 07407 071

--801070545 Transcript of State Liaison Officers Washington, DC Pp 1-124
* Commissioners 80/12/10 129pp 07407 0

--801070590 Transcript of State Liaison Officers Washington, DC Pp 1-259
* Commissioners 80/12/09 260pp 07407 1

8010705942 Forwards JD Nelson rept in response to assessment of adequacy of NM followup to NRC ltr by Church Rock Can failure w/o rept SCARANO, R A Uranium Recovery Licensing Branch 07415 087

801090328 Confirms NRC 801024 recommendations for of state radiation control program Addl staff recruited for present radioactive matts program regulatory program for U mills is currently und KERR, O W Office of State Programs, Director 07442 089

--801090335 Forwards comments from NRC 801020-24 radiation control program Review of state reg 1s forthcoming LUBENAU, J O Assistant Director for State Ag 80/11/17 5pp 07442 092

801100213 Informs of review of ltr re 800923 mee comments & recommendations in 800730 ltr for in agreement matts program Recommendations result A Schneider site visits will be incorporated in OOLDIMAN, H L New York, State of 80/10/21 1

801100221 Expresses appreciation for visit to AL difficult state has encountered in obtaining funding to carry out responsibilities under exi agreements AXELROD, D New York, State of 80/10/17 1p

801120010 Comments on evaluation of QA programs NRC should standardize program w/Agreement State paid to Agreement State or NRC for any licensee duplicate fee should be levied by another licen CASH, A Non-Destructive Testing Management Ass 012 80/11/12 1p 07447 094

801140084 Submits comments on notice of proposed evaluation of Agreement State radiation control NRC is attempting futile effort in finding clea w/numerical indicators to judge compatibility FUNDERBURG, R D Idaho, State of 80/10/30 2

801140092 Submits comments on revised criteria f Agreement State programs, in response to State o ltr WILSON, E F Arkansas, State of 80/10/28 2p

010140096 Advises that comments on NRC proposed statement of policy on evaluation of Agreement State radiation control programs were received from 13 states Submits comments from NV
WADSWORTH, Nevada, State of 80/12/15 2pp 07308 001

010140116 Comments on behalf of Kerr-McGow Nuclear Corp on proposed policy re evaluation of Agreement State radiation control programs Statement asserts authority over Agreement States which NRC does not possess
MICHALES, P J, MONTAGNE, C H Covington & Burling 4569726 001
80/11/14 19pp 07458 170

010140122 Submits comments on proposed statement of policy on guide for evaluation of Agreement State radiation control programs
SPELL, U M Louisiana, State of 80/12/19 2pp 07461 209

010140134 Submits comments on guide for evaluation of Agreement States radiation control programs Rept should remain as uncodified guide
CEROSE, L B Georgia, State of 80/12/16 1p 07461 194

010140141 Submits comments on NRC proposed statement of policy evaluation of Agreement State radiation control programs No objections to proposal
CLARK, U Florida, State of 80/12/12 1p 07461 194

010140147 Advises of no addl comments on NRC proposed guide for evaluation of state radiation control programs
MOUNT, D K North Dakota, State of 80/12/19 1p 07309 001

010160396 Confirms results of NRC review re State of ID radiation control program Program is adequate to protect public health & safety
KERR, G W Office of State Programs, Director 80/12/22 2pp 07339 001

010160400 Confirms results of State of ID radiation program review Program is adequate to protect public health & safety
Tolcans substantive in nature should be documented in license files Specific comments & recommendations encl
LUGENAU, J O Assistant Director for State Agreements Programs 80/12/22 3pp 07471 052

010170564 PNA-80-027A on 801203, State of AR notified Nuclear Diagnostic Labs that license had been revoked Caused by failure to respond to state 801024 enforcement ltr Updates & closes-out PNA-80-029 issued on 800822
LUGENAU, J O, BOLLING, L A Office of State Programs, Director 80/12/18 1p 07475 378

010190658 Comments on general policy statement on evaluation of Agreement State radiation control plan Revision period of 4 or 5 yrs may allow for more efficient use of staff LM Solon 801114 memo to J Spath encl
RUNKLEBERGER, J New York, State of 80/12/23 2pp 07476 093

010190666 Comments on general policy statement on evaluation of Agreement State radiation control plans Agreement State reviews should be conducted by third party
YOUNG, R E Affiliation Unknown 80/12/22 2pp 07183 001

010190673 Comments on general policy statement on evaluation of Agreement State radiation control plans More emphasis should be placed on technical advisory committee & consultants & on competence of senior staff
D'ARSEN, M J Affiliation Unknown 80/12/18 2pp 07183 001

010190679 Ack receipt of 801120 ltr concluding radiation protection program is adequate to protect public health & safety
Unannounced insps will be conducted
SGLOFF, L R New York, State of 80/12/18 1p 07476 095

010190721 Confirms 801204 discussion of state U mill regulatory program More details of state engineer assistance needed
Upon resolution of NRC comments, recommendation re plan adequacy will be made
KERR, G W Office of State Programs, Director 81/01/07 4pp 07183 001

010190730 Confirms 801121 discussion of state radiation control plan
Salarys need to be upgraded in order to be competitive NRC prepared to recommend finding that state program adequate to protect public health & safety Salary comparison table encl
KERR, G W Office of State Programs, Director 80/12/22 4pp 07476 111

010120032 Comments on NRC proposed statement of policy re evaluation of Agreement State radiation control programs Statement suggests that NRC is attempting to increase control over Agreement States
CORCORAN, R L Nevada, State of 80/12/01 3pp 07187 001

010120036 Forwards State of SC fourth quarterly progress rept (third yr) on transportation surveillance program, frst Jul-Sept 1980
JANICK, M Office of State Programs, Director NRC-05-80-357
81/01/07 2pp 07547 194

010120062 Submits fourth quarterly progress rept (third yr) on transportation surveillance program from Jul-Sept 1980
WILLIAMS, E F South Carolina, State of NRC-06-78-357 83/12/01 2pp 07547 195

0101270979 Responds to 801125 ltr W McCarthy has been accepted for course in health physics & radiation protection & W Kerr has been directed to arrange meeting re CF interest in becoming Agreement State
MANSUR, J F Commissioners 80/12/11 1p 07350 106

0101270982 Discusses W McCarthy application to attend course in health physics & radiation protection & requests that favorable consideration be given
GRASSO, E Connecticut, State of 83/11/25 1p 07550 107

0101290794 Notification of contract execution, Mod 2 to "Environ Monitoring Program W/ Commonwealth of VA " Contractor Commonwealth of VA
BAISDEN, L Research Contracts Branch FIN B-5116 NRC-05-80-277
81/01/26 1p 07568 037

0101290798 Mod 2, providing funding for CY81 effort to "Environ Monitoring Program W/ Commonwealth of VA "
" Virginia, State of MORTON, K V Research Contracts Branch FIN B-5116, NRC 05-80-277 81/01/01 1p 07568 038

0101300069 Notification of contract execution, Mod 1 to "Environ Monitoring Program W/ State of MN " Contractor State of MN
BAISDEN, L Research Contracts Branch FIN B-1282 NRC-05-80-288
81/01/26 1p 07583 051

0101300075 Mod 1, providing funding for CY81 effort to "Environ Monitoring Program W/ State of MN "
" Minnesota, State of MORTON, K V Research Contracts Branch FIN B-1252 NRC-05-80-288 81/01/26 1p 07583 052

0101300085 Notification of contract execution, Mod 3 to "Environ Monitoring Program W/ Commonwealth of PA " Contractor Commonwealth of PA
BAISDEN, L Research Contracts Branch FIN B-5111, NRC-05-80-272
81/01/26 1p 07583 075

0101300093 Mod 3, providing funding for CY81 effort to "Environ Monitoring Program W/ Commonwealth of PA "
" Pennsylvania, State of MORTON, K V Research Contracts Branch FIN B-5111 NRC-05-80-272 81/01/26 1p 07583 076

0101300183 Notification of contract execution, Mod 2 to "Environ Monitoring Program W/ State of WI " Contractor State of WI
BAISDEN, L Research Contracts Branch FIN B-5114 NRC-05-80-275
81/01/26 1p 07580 353

0101300187 Mod 2, providing funding for CY81 effort to "Environ Monitoring Program W/ State of WI "
" Wisconsin, State of MORTON, K V Research Contracts Branch FIN B-5114 NRC-05-80-275 81/01/26 1p 07580 354

0101300312 Notification of contract execution, Mod 2 to "Environ Monitoring Program W/ State of NY " Contractor State of NY
BAISDEN, L Research Contracts Branch FIN B-5109, NRC-05-80-271
81/01/26 1p 07587 009

0101300316 Mod 2, providing funding for CY81 effort to "Environ Monitoring Program W/ State of NY "
" New York, State of MORTON, K V Research Contracts Branch FIN B-5109 NRC-05-80-271 81/01/26 1p 07587 010

0101300320 Notification of contract execution, Mod 1 to "Environ Monitoring Program W/ State of MS " Contractor State of MS
BAISDEN, L Research Contracts Branch FIN B-1257 NRC-05-80-289
81/01/26 1p 07587 025

0101300325 Mod 1, providing funding for CY81 effort to "Environ Monitoring Program W/ State of MS "
" Michigan, State of MORTON, K V Research Contracts Branch FIN B-1257 NRC-05-80-289 81/01/26 1p 07587 026

Monitoring Program w/State of MD - Contractor State of MD
BAISEN, L Research Contracts Branch FIN B-5106 NRC-05-80-267
81/01/26 1p 07585 254

--B010300249 Mod 2, providing funding for CYBI effort, to "Environ
Monitoring Program w/State of MD - Contractor State of MD
* Maryland, State of MORTON, K V Research Contracts Branch
FIN B-5106 NRC-05-80-267 81/01/26 1p 07585 259

B010300359 Notification of contract execution, Mod 2 to "Environ
Monitoring Program w/State of CO - Contractor State of CO
BAISEN, L Research Contracts Branch FIN B-5104 NRC-05-80-267
81/01/26 1p 07587 051

--B010300365 Mod 2, providing funding for CYBI effort, to "Environ
Monitoring Program w/State of CO - Contractor State of CO
* Colorado, State of MORTON, K V Research Contracts Branch
FIN B-5104 NRC-05-80-267 81/01/26 1p 07587 052

B010300372 Notification of contract execution, Mod 2 to "Environ
Monitoring Program w/State of ME - Contractor State of ME
BAISEN, L Research Contracts Branch FIN B-5113 NRC-05-80-274
81/01/26 1p 07587 054

--B010300381 Mod 2, providing funding for CYBI effort, to "Environ
Monitoring Program w/State of ME - Contractor State of ME
* Maine, State of MORTON, K V Research Contracts Branch FIN
B-5113 NRC-05-80-274 81/01/26 1p 07587 055

B010300378 Notification of contract execution, Mod 1 to "Environ
Monitoring Program w/State of DE - Contractor State of DE
BAISEN, L Research Contracts Branch FIN B-5126 NRC-05-80-291
81/01/26 1p 07587 056

--B010300406 Mod 1, providing funding for CYBI effort, to "Environ
Monitoring Program w/State of DE - Contractor State of DE
* Delaware, State of MORTON, K V Research Contracts Branch
FIN B-5126 NRC-05-80-291 81/01/26 1p 07587 057

B010300432 Responds to B01231 ltr taking exception to provisions of
Commonwealth of VA radiological emergency response plan Plan
does provide for spokesperson who relates to media at county
level VA Dept of Health B01012 ltr encl
JONES, O L Virginia, State of 81/01/16 5pp 07586 297

TOPREF VENDOR REPORTS AND RELATED CORRESPONDENCE

B01060525 Forwards list of addl info needed to complete review of
B00321 Topical Rept B0-67459, "Performance of York Model 279
Type 30 Demister/Moisture Separator in Removing Droplets in
Air-Stream Dispersion"
TEDESCO, R L Assistant Director for Licensing 80/10/22 3pp
02219 196

B01050096 Forwards corrected input listing for LOFT Small Break test
L3-6 w/o encl
JENSEN, S E Exxon Nuclear Co., Inc. (subs. of Exxon Corp.)
SEJ 061 80 80/12/12 1p 07375 316

B01050178 Forwards nonproprietary version of Burns & Roe, Inc. rept,
"Analytical Model for LOCA Water Jet in Mark II Containments
(Ring Vortex Model)," provided on behalf of Mark II owners
group as part of Mark II containment program.
BUCHHOLD, Z R H General Electric Co RHB-074-BD 80/12/11 1p

--B01050187 Nonproprietary version of rept, "Analytical Model for LOCA
Water Jet in Mark II Containments (Ring Vortex Model)"
CHU, C K LEE, T Burns & Roe Co 80/09/30 116pp 07376 089

B01050561 Discusses B01203 meeting w/review plans in area of core
reloading licensing for coming yr Two licensing topical
repts germane to plans identified, Viewgraphs encl
BERGREN, J S Standardization & Special Projects Branch 80/12/12
23pp 07393 156

B01070296 Submits monthly progress rept for Sept 1980. Efforts were
concerned w/subaccounts for cost control, reviewing project
plans & establishing internal reporting procedures Estimated
& actual cumulative costs through FYBI encl
OISEKE, J A Battelle Memorial Institute, Columbus Laboratories
80/12/05 3pp 07415 209

B01090047 Forwards Suppl 1 to XN-NE-79-71 (NP), "Exxon Nuclear Co
Plant Transient Simulator Code for Evaluation of Abnormal
Transients for Jet-Pump BWRs."
DASLEY, G F Exxon Nuclear Co., Inc. (subs. of Exxon Corp.)
GPD 003 81 81/01/05 1p 07441 119

B01090053 Forwards Suppl 1 to XN-NE-79-71 (NP), "Exxon Nuclear Co
Plant Transient Simulator Code for Evaluation of Abnormal Transients
for Jet-Pump BWRs."
DASLEY, G F Exxon Nuclear Co., Inc. (subs. of Exxon Corp.)
GPD 003 81 81/01/05 1p 07441 119

B01090116 Summary of B01203 meeting w/Util re p
reloading licensing for coming yr Meeting identical
topical repts germane to plans submitted to NRC
NRC appeared oblivious Viewgraphs encl
BERGREN, J S Standardization & Special Projects Branch 80/12/22 43pp 07427 305

B01090198 Forwards MEDU-24057A, "Assessment of
Vibration in BWR/4 & BWR/5 Plants" & MEDU-2405
"Assessment of Reactor Internals Vibration in
Plants" MEDU-24057-A-A withheld ref 10CFR2
QUIRK, J F General Electric Co MFN-02-B1
07433 073

--B01090269 MEDU-24057A
Nonproprietary version of "Assessment of Reactor
Vibration in BWR/4 & BWR/5 Plants"
CILMAN, J D DUCKWALD, C S UMBLE, D G General Electric Co
80/12/31 61pp 07430 079

B01090487 Forwards BWR Owners Group Evaluation of
"1 K 3 138 Reactor Core Isolation Cooling Sys
Reset"
WATERS, D B BWR Owners Group BWR00-BG-12
07440 226

--B01090493 BWR Owners Group Evaluation of BWR
Reactor Core Isolation Cooling Sys Automatic
"1 K 3 138 Reactor Core Isolation Cooling Sys Automatic"
WATERS, D B BWR Owners Group 80/12/29 97pp 07440 226

B01090830 Responds to B01202 ltr re organization of
Power Corp affecting nuclear QA program Change
reduce program effectiveness Change acceptable
HAASS, W P Quality Assurance Branch 80/12/11

B01090253 Forwards SCP-01, "Radcal Gamma Thermometer
Measuring Devices for Use in Cores of all PHRs"
MORRIS, P A Scandpower, Inc 81/01/09 1p 07442 118

--B01090265 SCP-01 R3
"Radcal Gamma Thermometers as Local Power Measuring
Devices for Use in Cores of all PHRs," Revision 3
MORRIS, P A Scandpower, Inc 80/12/31 300pp 07442 118

B01090584 Requests that NRC withdraw proprietary
info was submitted by owners of Westinghouse NS
response to IE Bulletin 79-01B re equipment qualification
List of owners of Westinghouse NSSS encl
ANDERSON, T M Westinghouse Electric Corp NS-01-01
2pp 07452 145

B01090311 Requests addl info re ALARA design fed
for completion of Radiological Assessment Branch
NECC-2-P, "Radwaste Vol Reduction Sys."
TEDESCO, R L Assistant Director for Licensing 80/12/11 118

B01090020 Notification of B01013 meeting w/Exxon
Bethesda, MD to discuss planned response to first
questions on BWR nuclear methodology, w/emphasis on
verification & data bases
LOIS, L Core Performance Branch 81/01/05 2pp 07452 145

B01090342 Forwards revised Tables 1-2 & 1-4 from
revised Table 1-4 from ODYN B01003 submittal
& 1-4 from ODYN B00905 submittal withheld (ref
BUCHHOLD, Z R H General Electric Co MFN-03-B1
07468 358

--B01090361 Revised Table 1-4 from ODYN B01003 submittal
General Electric Co 81/01/12 2pp 07468 358

B01090405 Approves B01110 application & Affidavit
WCAP-9693 (ref 10CFR2.790).
JORDAN, E L Office of Inspection & Enforcement
Director 80/12/10 2pp 07471 050

B01090235 Approves proposed Revision 9 to ETR-10
annual Revision should be referenced in Section
Programmatic changes to QA program must be submitted
review prior to implementation
HAASS, W P Quality Assurance Branch 81/01/05

8101190330 Forwards nonproprietary & proprietary responses to NRC 800815 request for addl info re plant design conditions & fuel damage Application for withholding & affidavit encl. Proprietary info withheld (ref 10CFR2 790) ANDERSON, T M Westinghouse Electric Corp NS-TMA-2366 81/01/12 10pp 07474 282

8101200420 Forwards nonproprietary version of WCAP-9812, "Investigation of Feedwater Line Cracking in PWR Plants," Vols 1 & 2 ANDERSON, J M Westinghouse Electric Corp NS-TMA-2356 80/12/10 1p 07480 104

--8101200423 WCAP-9812 Nonproprietary version of "Investigation of Feedwater Line Cracking in PWR Plants," Vols 1 & 2 WHITE, D H, CAMPBELL, T E Westinghouse Electric Corp 80/12/31 700pp 07480 105

8101210246 Staff requirements memo re 801217 briefing on TVA activities in emergency offsite facilities Requests comments on acceptability of util proposal to centralize facilities & applicability of concept to other licensees CHILK, S J Office of the Secretary of the Commission 80/12/18 1p 07492 047

8101210359 Forwards Revision 3 to proprietary rept BAW-10004P-A, "Program to Determine In-Reactor Performance of BWR Fuels - Cladding Creep Collapse," Rept withheld (ref 10CFR2 790) TAYLOR, J M Babcock & Wilcox Co 81/01/13 2pp 07487 269

8101210371 Forwards Revision 1 of "Assumptions for Use in Analyzing Mark II BWR Suppression Pool Temp Response to Plant Transients Involving Safety/Relief Valve Discharge," provided on behalf of Mark II owners group DUCHONOLZ, R H General Electric Co MFN-014-B1 81/01/09 2pp 07489.039

--8101210373 Revision 1 of "Assumptions for Use in Analyzing Mark II BWR Suppression Pool Temp Response to Plant Transients Involving Safety/Relief Valve Discharge," * Mark II Owners Group 80/12/31 24pp 07489 037

8101210372 Forwards Suppl 2 to proprietary repts WCAP-B607.E16A & WCAP-B607.E16B, Suppl 2 to nonproprietary WCAP-0907.E16A & WCAP-0907.E16B & Revision 2 to EQDP-EGE-16 of Suppl 1 to WCAP-B507 Proprietary repts withheld (ref 10CFR2 790) ANDERSON, T M Westinghouse Electric Corp NS-TMA-2360 81/01/16 10pp 07487 291

--8101210375 WCAP-0907 B2-E16B Nonproprietary version of Suppl 2-E 16B to "Equipment Qualification by Combined Analysis & Test Approach for Four-Bay Cabinet of Two-Train Solid State Protection Sys (SSPS), (Seismic Design Verification Analysis & Design)," TANO, D, CHANG, S M, VOOEDINO, E L Westinghouse Electric Corp 80/12/31 20pp 07487 301

--8101210377 EQDP-EGE-16 R2 "Solid State Protection Sys (SSPS) Two-Train & Safeguard Test Cabinet Three & Four-Bay," equipment data qualification package included in Suppl 1 to WCAP-B507 (nonproprietary) ANDERSON, T M Westinghouse Electric Corp - Nuclear Energy Systems 5206A 81/01/31 27pp 07487 321

--8101210401 WCAP-0907 B2-E16A Nonproprietary version of Suppl 2-E16A to "Equipment Qualification Test Rept Two-Train Solid State Protection Sys (Normal & Abnormal Temp & Humidity Testing)," POTOCHNIK, L M, ANDERSON, T M, RAMCHANDRAN, S Westinghouse Electric Corp 81/01/16 22pp 07487 348

8101210382 Discusses draft SER approach to nuclear facility licensing review Direct discussions between NRC & applicant proved more efficient than written question & answer cycle Approach provided early resolution of issues CHAN, A L Bechtel Power Corp (subs of Bechtel Corp) 81/01/14 2pp 07489 072

8101210483 Forwards comments re future LOFT test plans for special review group No tests necessary on safety basis Submits table summarizing tests useful for code assessment LOFT not representative of expected PWR behavior ANDERSON, T M Westinghouse Electric Corp NS-TMA-2369 81/01/16 7pp 07489 271

8101210515 Forwards proprietary version of NEDE-24284-P, "Assessment of Fuel Rod Bowing in GE BWRs," Aug 1980 Withholding requested (ref 10CFR2 790) Rept available in Central Files only DUCHONOLZ, R H General Electric Co MFN-221-B0 80/12/23 4pp 07490 112

8101210523 Discusses status of NRC review of Addenda 1 to ECR "Power Generation Control Complex Design Criteria & Safety Evaluation," Summary of factory cable crimping process controls provided in 791213 1tr GANO, W G General Electric Co MFN-004-B1 81/01/12 2pp 07490 104

--8101210529 Forwards Errata 1 to NEDE-10466-A, "Power Generation Control Complex Design Criteria & Safety Evaluation," clarifying cable connector requirements STADUPE, E P General Electric Co MFN-011-B0 80/01/10 07490 104

--8101210531 NEDE-10466-A ERR 1 Errata 1 to "Power Generation Control Complex Design Criteria & Safety Evaluation," * General Electric Co 79/12/31 5pp 07490 107

8101220426 Confirms 801201 telcon & requests approval of change approved ECCS evaluation models, resulting in higher calculated fuel cladding temps Change does not affect acceptability of previous calculation results ANDERSON, T M Westinghouse Electric Corp NS-TMA-2354 80/12/31 2pp 07502 291

8101220528 Forwards XN-NF-B0-56(NP), "Generic Mechanical, Thermal Hydraulic & Neutronic Design for Exxon Nuclear ICRUD Refuel Fuel Assemblies for PWRs," GUSLEY, O F Exxon Nuclear Co, Inc (subs of Exxon Corp) GFC:008 B1 81/01/20 1p 07502 289

--8101220534 XN-NF-B0-56(NP) "Generic Mechanical, Thermal Hydraulic & Neutronic Design for Exxon Nuclear ICRUD Refuel Fuel Assemblies for PWRs," BROOK, D A, MACDOUFF, A B, WIMPY, P D Exxon Nuclear Co, Inc (subs of Exxon Corp) 80/12/18 128pp 07502 290

8101230211 Forwards proprietary & nonproprietary versions of "Analysis & Test Verification Data for Four Loop Rod Exchange Technique for Rod Worth Measurement," Proprietary version withheld (ref 10CFR2 790) Affidavits encl ANDERSON, T M Westinghouse Electric Corp, PWR Systems Div NS-TMA-2367 81/01/20 11pp 07513 293

--8101230232 Nonproprietary version of "Analytical & Test Verification Data for Four Loop Rod Exchange Technique for Rod Worth Measurement," * Westinghouse Electric Corp 81/01/20 21pp 07513 286

8101230300 Requests final concurrence J/GE approach to fatigue required by ASME code as presented in sample evaluations at 801007 meeting in San Jose, CA GANO, W G General Electric Co MFN 011-B1 81/01/15 2pp 07513 042

8101260516 Forwards nonproprietary versions of "Summary Rept. Westinghouse Reactor Vessel Level Instrumentation Sys for Monitoring Inadequate Core Cooling (7300 Sys)(Microprocessor Sys) & (UHI Plant)," Extra copy of Page 4-32 encl ANDERSON, T M Westinghouse Electric Corp NS-TMA-2371 81/01/16 2pp 07532 089

--8101260647 Nonproprietary version of "Summary Rept. Westinghouse Reactor Vessel Level Instrumentation Sys for Monitoring Inadequate Core Cooling (Microprocessor Sys)," * Westinghouse Electric Corp 80/12/30 75pp 07532 072

--8101260652 Nonproprietary version of "Summary Rept. Westinghouse Reactor Vessel Level Instrumentation Sys for Monitoring Inadequate Core Cooling (7300 Sys)," * Westinghouse Electric Corp 80/12/31 75pp 07532 122

--8101260657 Nonproprietary version of "Summary Rept. Westinghouse Reactor Vessel Level Instrumentation Sys for Monitoring Inadequate Core Cooling (UHI Plant)," * Westinghouse Electric Corp 80/12/31 75pp 07532 252

8101270427 Advises that QA review & concurrence of procedures containing QA requirements will be completed by 810430 Manpower efforts were redirected to priority tasks. MILLS, L M Tennessee Valley Authority 81/01/23 1p 07532 144

8101270598 Forwards AIR-1020, "Analysis of Halden Irradiation Assembly IFA-223 by GEAP-3 Code," included in NEDE-23785-P Rept withheld (ref 10CFR2 790) Affidavit for withholding encl DUCHONOLZ, R H General Electric Co MFN-014-B1 81/01/21 07546 144

8101270709 Forwards Supp 1, "Sys-80 Reactor Coolant Pump Loss of Component Cooling Water Test Rept." to CENPD-201-A, "Performance of C-E Sys-80 Reactor Coolant Pump W/Loss of Component Cooling Water." SCHERER, A. E. C-E Power Systems. LD-81-006. 81/01/22. 1p. 07545:249.

--8101270714 CENPD-201-A S1 "Sys-80 Reactor Coolant Pump Loss of Component Cooling Water Test Rept." * C-E Power Systems. 81/01/22. 19pp. 07545:250.

WASTE MGT NUCLEAR WASTE MANAGEMENT

8101060114 Responds to 801119 telcon re revision to criteria re cleanup of contamination from Church Rock U mill tailings dam break Revised criteria acceptable. MARTIN, J. B. Division of Waste Management. 80/12/08. 3pp. 07399:091.

--8101060119 Informs that reply to NM should include acknowledgment of receipt of revised criteria, info that mods best carried out by NM & offer of continuing contract support, if possible. DAVIS, J. G. Office of Nuclear Material Safety & Safeguards. 80/11/17. 1p. 07399:094.

--8101060122 Requests that NRC offer svcs of consultant to State of NM. DAVIS, J. G. Office of Nuclear Material Safety & Safeguards. 80/10/31. 3pp. 07399:095.

--8101060127 Requests comments on plan to clean up land contaminated by 790716 tailings dam spill. Ltr to United Nuclear Corp from state & amend to state order encl. BACA, T. E. New Mexico. State of. 80/10/14. 8pp. 07399:098.

--8101060130 Informs that JF Ahearn wishes chronology & status rept re decontamination of 790716 tailings dam spill. * Commissioners. 80/10/22. 1p. 07399:106.

8101070523 Comments on "Environ Cleanup Stds (D-2214-0)" for Aug-Oct 1980. Relevant literature searches "w/particular investigators known to have participated in related environ surveillance programs" found not vigorously pursued. EDDIE, G. G. Uranium Recovery Licensing Branch. 80/12/12. 2pp. 07415:293.

8101070528 Confirms 801126 discussions re organization & conduct of workshop concerning radiological surveys in support of Edgemont Cleanup Action Program. Lab is authorized to organize, conduct & participate in workshop. EDDIE, G. G. Uranium Recovery Licensing Branch. 80/12/12. 2pp. 07415:291.

8101070532 Forwards M O'Brien & C Oyster of Gunnison Valley Alliance 801117 ltr re Homestake Mining Corp mill application in CO. Ofc of State Programs should respond, as matter involves Agreement State. SCARAND, R. A. Uranium Recovery Licensing Branch. 80/12/11. 1p. 07415:288.

--8101070537 Urges NRC to investigate concentrated mineral development planned for Gunnison County, CO. Granting license to Homestake Mining Corp for mill & tailing pond would endanger entire surface & subsurface water sys. O'BRIEN, M. T., DYSTER, C. L. Affiliation Unknown. 80/11/17. 2pp.

8101070542 Forwards JD Nelson rept in response to request for technical assessment of adequacy of NM followup to NRC issues raised by Church Rock dam failure. W/o rept. SCARAND, R. A. Uranium Recovery Licensing Branch. 80/12/09. 1p. 07415:287.

8101070547 Discusses 801121 state hearing on Dawn Mining Co proposed below-grade tailings impoundment. NRC requirement for rock cover post reclamation unwarranted. LINEHAN, J. J. Uranium Recovery Licensing Branch. 80/12/10. 1p. 07415:286.

8101090722 Forwards RE Williams rept re groundwater contamination problem in vicinity of Cotter Mill in Canon City, CO. Technical assistance will be provided for expeditious resolution of shallow aquifer contamination problems. SCARAND, R. A. Uranium Recovery Licensing Branch. 80/12/08. 1p. 07430:329.

--8101090729 "Status of Cotter Corp Mill Tailings Pond Seepage Project as of 801106." WILLIAMS, R. E. Affiliation Unknown. 80/11/06. 8pp. 07430:330.

8101190089 Requests that O Castro of Geotechnical site on 810106 to determine whether safety evaluation recommendations have been adequately realized in stabilization program. Decision anticipated in Feb. HAZLE, A. J. Colorado. State of. 18082. 80/12/0.

8101270155 Ack receipt of 801015 ltr re license for ore buying station. State license issued to facility. 800915. Copies of all U licenses issued by NRC since requested. HAZLE, A. J. Colorado. State of. 80/12/05. 24pp.

8101270260 Trip rept of 800609-23 visit to ANL, ORNL investigations on geotechnical retardation. ROBBINS, G. Office of Nuclear Material Safety & Safeguards. BIRCHARD, G. Division of Safeguards, Fuel Cycle & Research. O'DONNELL, E. Office of Standards Development. 80/09/30. 67pp. 07547:117.

8101270354 Requests NRC attendance at 810107 & 08 meeting & future Uravan waste mgmt sys. HAZLE, A. J. Colorado. State of. 18081. 80/12/05.

8101270467 Expresses concern w/acquisition of financial arrangements provided for proper decommissioning, decontamination & reclamation of U mill site & tailings. Related info encl. HAZLE, A. J. Colorado. State of. 18083. 80/12/08.

--8101270470 Deposition re operation of Uravan mill 1 encl. HIETT, C. H. Union Carbide Corp. 18083. 80/09/11. 07543:230.

--8101270475 Supplemental deposition re operation of 1942-1976. Exhibits encl. HIETT, C. H. Union Carbide Corp. 18083. 80/09/11. 07543:241.

8101270528 Trip rept of 800908-19 technical survey of TX & MS under preliminary investigation as possible level nuclear waste storage sites. HART, P., JOHNSON, R. L. High Level Waste Technical Development. MICHAELSON, T. J. Geosciences Stds. Br. (formerly Si Br.). 81/01/31. 57pp. 07543:251.

8101270941 FES for proposed Dawn Mining Co mill tailings project. * Washington, State of. 81/01/05. 221pp. 07549:20.

8101270961 Forwards Water Quality Monitoring Rept 9-80, of water sample analyses made during Sept 1980. CAHN, J. Cotter Corp. 18174. 80/12/15. 5pp. 07549:20.

8101270968 Comments on NRC negative declaration re Anac project. NRC grant of waiver to manufacturer may have of removing project from state jurisdiction. BAILEY, E. D. Texas. State of. 18173. 80/12/16. 4pp.

8101280033 Trip rept of 800707-18 visit to Columbia Plant & hydrology & Hanford Reservation re field studies. HARTUNG, L., SIEFKEN, D. High Level Waste Technical Development. LEHMAN, L. High Level Waste Licensing Management. 80/09/30. 44pp. 07556:300.

8101290010 Forwards response to comments on NRC input for revisions to draft EIS. SCARAND, R. A. Uranium Recovery Licensing Branch. 80/12/09. 07575:300.

8101290449 Forwards "Union Carbide Corp, Uravan Co. SUA-067 Disposal Rept, Nov. 1980." JONES, R. K. Union Carbide Corp. 18175. 80/12/16. 1p.

--8101290654 "Union Carbide Corp, Uravan, CO. SUA-0673 Bol 14 Rept, Nov 1980." * Union Carbide Corp. 80/12/16. 46pp. 07309:001.

EXPORT LIC EXPORT AND IMPORT LICENSES

7909210430 Discusses findings re license request by NL Ind to import 47 kg of U, containing 27 kg U-235 enriched to 60% from Canada to Savannah River Project, Aiken, SC. Import will not be unreasonable risk to public. MOORE, R. N. Office of International Programs, Director. 2pp. 00752:303.

8101050424 Reiterates concerns in 800620 petition to intervene re export of two reactors to questionable site in Taiwan. Evidence of significant seismic dangers posed by Yen Liao site encl
MATTISON, L Center for Development Policy 80/12/11 9pp

8101050487 Response to Ctr for Development Policy 801209 petition to intervene DGS position identical to that taken in 800721 response to CDP petition re GE & Westinghouse Applications for exports to Taiwan Certificate of Gov encl
BETTAUER, P J State Dept of 80/12/29 4pp 07390 317

8101050584 License for Sigma Chemical Co to export 10 kg deuterium oxide to India
DEVINE, J B Assistant Director for Export/Import & International Safeguards D-61 80/12/26 2pp 07390 245

8101060210 Application by Sigma Chemical Co for license to export 10 kg deuterium oxide over 2-yr period to Italy
STERN, M C Sigma Chemical Co (subs of Sigma-Aldrich Corp) 80/11/24 1pp 07391 316

8101060264 Forwards IC insp rept on 801201 of activities under License XSNM-1656 No noncompliance noted Insp rept withheld (ref 10CFR 79D)
MORDEHAU, L R Region 5, San Francisco, Safeguards Branch 80/12/17 2pp 07392 008

8101060889 License for Seamedal Transport Corp to export 2.7 kg natural U & 230 g U as NBS stds to Belgium
DEVINE, J B Assistant Director for Export/Import & International Safeguards A0/1542 80/12/19 2pp 07401 053

8101060892 Forwards duplicate export license applications previously sent 801123
WILSCH, B D General Electric Co BHW 80137 80/12/10 1p 07401 035

8101060874 License for Aldrich Chemical Co, Inc to export 5 kg deuterium oxide to India
DEVINE, J B Assistant Director for Export/Import & International Safeguards 21/80 80/12/19 2pp 07401 057

8101060956 License for Mitsubishi Intl Corp to export 359 kg U-235, contained in 14,613 kg U to Japan
DEVINE, J B Assistant Director for Export/Import & International Safeguards HGA-9480-09 80/12/19 2pp 07187 001

8101060978 License for Exxon Nuclear Co, Inc to export 76 kg U-235, contained in 2,670 kg U as U dioxide fuel pellets or fabricated fuel elements, to West Germany
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/12/19 2pp 07401 057

8101070225 Application by QA Co for Amend 2 to license to export miscellaneous specially designed parts & components to Canada, extending license for 3 yrs
MORRY, W R General Atomic Co (subs of Gulf Oil Co) IEL-2030 80/12/09 1p 07414 294

8101070305 Informs that since no matl changed circumstances exist since issuance of License XSNM-166B, License XSNM-1730 may be issued
MORRE, R N Assistant Director for Export/Import & International Safeguards 80/12/13 1p 07187 001

--8101070310 License for Mitsui & Co (USA), Inc to export 626 kg U-235, contained in 22,475 kg U as U dioxide, to Japan
DEVINE, J B Assistant Director for Export/Import & International Safeguards MBK-HI-R7 80/12/19 2pp 07187 001

8101070652 Informs that since no matl changed circumstances exist since issuance of License XSNM-166B, License XSNM-1734 may be issued
MORRE, R N Assistant Director for Export/Import & International Safeguards 00/12/15 1p 07187 001

--8101070655 License for Mitsubishi Intl Corp to export 337 kg U-235, contained in 11,823 kg U to Japan
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/12/19 2pp 07187 001

8101080332 Informs that Teledyne Wah Chang Albany has requested expeditious processing of request to export components to West Germany. License issued w/o normal 15 day waiting period
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/12/12 1p 07421 326

--8101080340 License for Teledyne Wah Chang Albany to export 23 Zircaloy-2 tube shells to West Germany
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/12/12 1p 07421 327

8101080350 Submits status re pending appeals court case challenging IIRC export license issuance for nuclear reactor to be constructed in Philippines & implementation of Executive Order 12114
STOBER, C Office of the General Counsel 80/12/16 13pp 07419 276

8101090296 Executive Branch position re C E application for license to export 8,782 kg U enriched to max of 3.5% for initial cores & one full core reload to Taiwan License should be issued
MORSE, L V State Dept of, Bureau of Oceans & International Scientific Affairs 80/12/12 13pp 07424 018

8101090429 Application by Intl Business Development to amend license extending expiration date to 811231
MORSE, L V International Business Development 80/12/31 07442 014

8101090531 Discusses PNL 801125 application for license to import 607 g low enriched U from United Kingdom, West Germany & Belgium re high burnup investigations of LWR sintered U inside pellet fuel import not critical to defense
MORSE, R N Office of International Programs, Director 80/12/11 07442 186

--8101090538 License for PNL to import 607 g U containing 39 g from United Kingdom, West Germany & Belgium
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/12/11 1p 07442 187

8101090522 Executive Branch position re Marubeni America Corp application for license to export 3,486 kg U-235, contained in 136,333 kg U dioxide to Japan Ltr of assurance encl
MORSE, L V State Dept of, Bureau of Oceans & International Scientific Affairs 80/12/01 2pp 07187 001

8101090532 Forwards notice of receipt for licenses to export/import nuclear facilities on mails Requests FR publication
MORSE, J R Office of International Programs, Director 80/12/20 2pp 07427 354

8101090912 Ltr of assurance re Transnuclear, Inc application for export 1,197 kg U-235, contained in 34,900 kg U to West Germany
MORSE, J R European Communities, Commission of 80/12/04 02593 207

8101090919 Ltr of assurance re Transnuclear, Inc application for export 847,705 kg U-235, contained in 25,931 kg U to West Germany
MORSE, J R European Communities, Commission of 80/12/01 03873 230

8101090924 Ltr of assurance re Edlow Intl Co application for license to export max 19,865 kg U containing max 675 kg U-235, to Sweden
MORSE, J R Sweden 80/12/11 1p 03873 291

8101090974 License for Sigma Chemical Corp to export 10 kg deuterium oxide to India
DEVINE, J B Assistant Director for Export/Import & International Safeguards D-59 80/12/26 2pp 03775 001

8101090978 License for Exxon Nuclear Co, Inc to export miscellaneous specially designed nuclear fuel element hardware to West Germany Export of assembled pressure vessels & primary coolant pumps not authorized
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/12/22 1p 03775 001

8101090981 License for Exxon Nuclear Co, Inc to export specially designed nuclear fuel element hardware to West Germany Export of assembled pressure vessels, primary coolant pumps, fuel charging & discharging machines not authorized
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/12/22 1p 03775 001

8101090987 Amend 2 to license for Edlow Intl Co, allowing consignment re-export from United Kingdom 3.7 mg Cf-252 as cermet wire to India
DEVINE, J B Assistant Director for Export/Import & International Safeguards TRC-4 80/12/26 1p 03775 001

- 810100790 License for Carpenter Technology Corp to export 24 2mm Zircaloy-4 fuel channels & 24 2 5mm Zircaloy-4 fuel channels to Japan
DEVINE, J B Assistant Director for Export/Import & International Safeguards CAP TECH-5FO 01 80/12/30 1p 03775 001
- 810100752 Executive Branch position re Westinghouse application for license to export two light water moderated steam supply sys to Taiwan Ltr of assurance encl License should be issued subject to Section 4 of analysis
NOSENZO, L V State Dept of Bureau of Oceans & Internatl Environ & Scientific Affairs 80/12/12 13pp 03893 333
- U10100089 Ltr of assurance re export of 395 kg U-235, contained in 14 613 kg U to Japan Kansai Electric Power Co. Inc is designated as authorized person
MIYABAYASHI, H Japan 80/12/04 1p 07445 003
- 810100072 Ltr of assurance re export of 493 kg U-235, contained in 19 141 kg U to Japan Kansai Electric Power Co. Inc is designated as authorized person
MIYABAYASHI, H Japan 80/12/04 1p 07445 005
- 810100099 Ltr of assurance re export of 337 kg U-235, contained in 11 823 kg U to Japan Kansai Electric Power Co. Inc is designated as authorized person
MIYABAYASHI, H Japan 80/12/04 11p 07445 007
- 810100102 Ltr of assurance re export of 626 kg U-235, contained in 22 475 kg U to Japan Chubu Electric Power Co. Inc is designated as authorized person
MIYABAYASHI, H Japan 80/12/04 1p 07445 009
- 810100161 Responds to FOIA request for five categories of documents re transportation of Pu Forwards documents listed in Apps A & B info partially withheld safeguards info (ref FOIA Exemption 3)
FELTCH, J M Division of Rules and Records 80/12/12 6pp
- 810100198 Discusses findings re proposed import of Pu-242 & 244 by Univ of CA Mtl is of US origin import meets statutory requirements, will not be inimical to common defense & security & will have no significant environ impact
MCORE, R H Office of International Programs, Director 79/10/10 1p
- 810100203 License for Ramsey Engineering Co to import 35 2 mg Pu-238, 80-70% concentration, contained in 20 Pu-238 sources, from any country
SHEA, J R Office of International Programs, Director 78/06/21 2pp
- 810100210 Discusses findings re proposed import of Pu-238 sources by Ramsey Engineering Co Air transport is prohibited import meets statutory requirements, will not be inimical to common defense & security & will not pose undue risk to public
MCORE, R H Office of International Programs, Director 78/06/21 1p
- 810100222 Discusses BOGJ17 request for increase in quantity & extension of expiration date for license issued to NL Industries to import 47 1 kg U from Canada Requested amends will not constitute unreasonable risk
MCORE, R H Office of International Programs, Director 80/03/28 1p
- 810100230 License for NL Industries, Inc to import 47.1 kg U, containing up to 27 0 kg U-235 as spent NRU & THRU reactor fuel, from Canada
PETERSON, H R Assistant Director for Export/Import & International Safeguards 79/08/20 2pp
- 810100239 Amend 1 to license for GE to import 8 403 kg U, containing 0 442 kg U-235, enriched to 13.3 w/o max & 54 1 g Pu as metal clad fuel rods, from Norway, extending expiration date to 811001 All other conditions remain unchanged.
DEVINE, J B Office of International Programs, Director 80/08/19 1p
- 810100261 Discusses findings re DOE proposed import of high enriched U from Germany, Netherlands & France. Import will not be inimical to common defense & security or constitute undue risk to public health, safety or environ.
MCORE, R H Assistant Director for Export/Import & International Safeguards 79/12/28 2pp
- 810100272 Discusses findings re DOE proposed import of low enriched U from Germany, Netherlands & France. Import will not be inimical to common defense & security or constitute undue risk to public health, safety or environ.
MCORE, R H Assistant Director for Export/Import & International Safeguards 79/12/28 2pp
- 810100281 Discusses findings re proposed amend to authorize import of 243 31 kg U, containing U-235 & 345 3 g of produced Pu Proposed amend is inimical to common defense & security
MCORE, R H Office of International Programs, Director 1p
- 810100288 SECY-78-433
Discusses Transnuclear, Inc proposed amend to import highly enriched U to authorize addl B containing 6 27 kg U-235 & 0 143 kg produced & Austria Proposed amend should be issued
SHEA, J R Office of International Programs, Director 2pp
- 810100306 Concurs in issuance of proposed Amend ISNM-01699
SMITH, C V Office of Nuclear Material Safety 78/08/02 1p
- 810100310 Advises that Commission has accepted License ISNM-01699 to authorize addl import of Germany Any re-export will be suby to terms of Non-Proliferation Act
CHILK, S J Office of the Secretary of the Commission 1p
- 810100322 Application by Transnuclear, Inc to import irradiated fuel elements from West Germany, to 11 listed quantities of elements
MATSON, V Transnuclear, Inc 78/01/13 3pp
- 810100327 Concurs in issuance of proposed amend to import high-enriched U
SMITH, C V Office of Nuclear Material Safety 78/03/01 1p
- 810100335 Advises that Commission approves proposed License for Transnuclear, Inc to import 159 B kg U-enriched U-235 & 186 g produced Pu in form of irradiated elements, from West Germany
CHILK, S J Office of the Secretary of the Commission 1p
- 810100345 SECY-77-465
Recommends approval of Transnuclear, Inc proposed import 159 B kg high-enriched U in spent MTR fuel from Germany
SHEA, J R Office of International Programs, Director 3pp
- 810100362 Application by Transnuclear, Inc to amend license to import U & U-235, from West Germany, to 11 listed quantities of U to 159 B kg & U-235 to 121 5 kg.
MATSON, V Transnuclear, Inc 77/04/07 1p
- 810100368 Responds to NRC 770224 request. Advises that requirements in 10CFR73 in accordance w/ 73 6(b)
MATSON, V Transnuclear, Inc 77/02/25 1p
- 810100386 Discusses findings re proposed license to import 159 B kg U in form of irradiated fuel from West Germany Importation will not be inimical to common defense & security Draft license encl
MCORE, R H Office of International Programs, Director 4pp
- 810100298 Application by Westinghouse for license to import compensated ionization chambers, Model WL6377, to SCHNAUTZ, C E Westinghouse Electric Corp ZE-2 07443 310
- 810100300 Application by Nuklearna Elektransa Krsko to import 280,000 lbs natural U from Yugoslavia
DULAR, J Affiliation Unknown 80/12/11 2pp
- 810100435 Executive Branch position re Transnuclear, Inc proposed license to export 2,065.5 kg U-235 enriched to 13.6 kg U-235 enriched to 3.4% to West Germany should be issued Ltr of assurance encl.
NOSENZO, L V State Dept of Bureau of Oceans & Scientific Affairs 80/12/29 3pp 07444:19B
- 810100442 Executive Branch position re Teledyne, Inc proposed license to export 2 9 kg depleted U to China

B101100493 Executive Branch position re Transnuclear, Inc application for license to export 2,965 kg U-235 enriched to max 3.35% & 1675 kg U-235 enriched to 3.35% to West Germany License should be issued ltr of assurance encl
NOSENZO, L V State Dept of Bureau of Oceans & Internatl Environ & Scientific Affairs 80/12/29 3pp 07444 238

B101100461 Executive Branch position re Westinghouse application for license to export six radiation surveillance capsules containing total of 90 mg HP-237 to Republic of Korea License should be issued
NOSENZO, L V State Dept of Bureau of Oceans & Internatl Environ & Scientific Affairs 80/12/29 1p 07444 241

B101100470 Requests Executive Branch position re Pacific Pumps, Inc application for license to export miscellaneous specially designed components for coolant pumps to India Views re applicability to Atomic Energy Act criteria requested
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/12/31 1p 07444 242

B101100474 Executive Branch position re Edlow Intl Co application for license to export 50,000 Ci tritium in bulk gaseous form to United Kingdom License should be deferred
NOSENZO, L V State Dept of Bureau of Oceans & Internatl Environ & Scientific Affairs 80/12/22 2pp 07444 243

B101100480 Executive Branch position re Westinghouse application for license to export one compensated ion chamber to Indonesia License should be issued
NOSENZO, L V State Dept of Bureau of Oceans & Internatl Environ & Scientific Affairs 80/12/22 2pp 07444 245

B101100485 Executive Branch position re Embassy of Austria applications for license to export enriched U fuel Encl ltr of assurance meets requirements of Section 127 (3) of Atomic Energy Act
NOSENZO, L V State Dept of Bureau of Oceans & Internatl Environ & Scientific Affairs 80/12/12 2pp 07444 247

B101100480 License for Teledyne Isotopes to export 2.9 kg depleted U in form of calibr plates contained in TLD sys to China
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/12/31 2pp 07444 249

B101100494 License for Westinghouse to export one compensated ionization chamber, Model HL B105, to West Germany
DEVINE, J B Assistant Director for Export/Import & International Safeguards 2E-10227 81/01/07 1p 07309 001

B101100499 Application by Reuter-Stokes, Inc for license to export 20 regenerative incore neutron detectors, Model RS-C6-1100-242, to Sweden
EECKHOUT, A Reuter-Stokes, Inc W-8824 80/12/22 1p 07444 262

B101100509 Application by Isotope Products Labs for license to export 10 uCi neutron source Cf to Austria
HELM, K Isotope Products Laboratories W/O 8339 80/12/19 2pp 07444 271

B101100515 Application by Matheson Gas Products for license to export five Size 4 cylinders, containing total of 503 liters chemically pure deuterium to Australia
WOOD, L D Matheson Gas Products 80/12/22 1p 07444 278

B101100521 License for Westinghouse to export one compensated ionization chamber, Model WLC23745, to France
DEVINE, J B Assistant Director for Export/Import & International Safeguards 81/01/02 1p 07309 001

B101100525 Application by Westinghouse for license to export 12 BF3 proportional counters to West Germany
ACCELL, W F Westinghouse Electric Corp 2E-10349 80/12/17 1p 07444 279

B101100548 License for Westinghouse to export three compensated ionization chambers, Model WL 6377, to France
DEVINE, J B Assistant Director for Export/Import & International Safeguards 2E-20359 80/12/31 1p 07444 288

B101100559 License for Reuter-Stokes, Inc to export one incore fission chamber, Model RS-06-0201-231, to West Germany
DEVINE, J B Assistant Director for Export/Import & International Safeguards 81/01/02 1p 07309 001

B101100558 License for Edlow Intl Co to export 100,000 Ci tritium in bulk gaseous form to United Kingdom
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/12/29 2pp 07309 001

B101120023 Submits addl info re BCU721 amend request for post-enrichment storage of 248,000 kg U as natural U hexafluoride Although consignee reactor will not go on line until late 1980s, contractual obligations must be met
HARMON, D B Edlow International Co 80/12/03 2pp 07447 028

B101120027 Executive Branch position re Exxon Nuclear Co, Inc application for license to export 76 kg U-235, contained in 2,670 kg U, to West Germany License should be issued End use statement encl
NOSENZO, L V State Dept of Bureau of Oceans & Internatl Environ & Scientific Affairs 80/12/05 3pp 07447 009

B101120031 Recommends issuance of license to Sydkraft Aktiebolag to import 138,791 kg natural U from Canada, although customary period of 15 days from posting in PDR has not yet elapsed
MCDONALD, R N Assistant Director for Export/Import & International Safeguards 80/12/09 1p 07445 316

--B101120064 License for Sydkraft Aktiebolag to import 138,791 kg natural U from Canada
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/12/09 1p 07445 317

B101120037 Amend B to license for Boeing Co to export max of 250,000 lbs depleted U in form of aircraft counterweights to 54 listed airlines Amend adds New Zealand, Trinidad & Ivory Coast
DEVINE, J B Assistant Director for Export/Import & International Safeguards DDC 40-7705 80/12/16 3pp 07309 001

B101120039 License for Mitsubishi Intl Corp to export 120 mg HP-237 six reactor vessel irradiation surveillance test capsules & 84 kg natural U to Japan
DEVINE, J B Assistant Director for Export/Import & International Safeguards 61-7230-80 80/12/16 2pp 07309 001

B101120064 Confirms that Austria will maintain physical security measures re matl exported from US to Austria under License XSNM-1725 & any ENM produced by such use
LENNHART, R Austria 8176-A/80 80/12/09 1p 07437 360

B101120073 Confirms that Austria will maintain physical security measures re matl exported from US to Austria under License XSNM-1727 & any ENM produced by such use
LENNHART, R Austria 8176-A/80 80/12/09 1p 07445 314

B101120080 Provides ltr of assurance that Austria will maintain physical security measures re matl exported from US to Austria under License XSNM-1726 & any SNM produced by such use
LENNHART, R Austria 8176-A/80 80/12/09 1p 07445 315

B101120186 Executive Branch position re GE application for license to export 11,400 kg U-235, contained in 478,800 kg U, to Taiwan License should be issued
NOSENZO, L V State Dept of Bureau of Oceans & Internatl Environ & Scientific Affairs 80/12/12 13pp 07447 007

B101120188 Executive Branch position re Westinghouse application for license to export 12,480 kg U-235, contained in 312,000 kg U, to Taiwan License should be issued
NOSENZO, L V State Dept of Bureau of Oceans & Internatl Environ & Scientific Affairs 80/12/12 13pp 07447 020

B101120192 License for Nuclear Transport & Storage, Inc to import 250,000 kg depleted U as aircraft counterweights from Canada
DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/12/22 1p 07447 033

B101120198 Executive Branch position re Edlow Intl Co application for license to export 100,000 Ci tritium, in bulk gaseous form, to United Kingdom License should be issued
NOSENZO, L V State Dept of Bureau of Oceans & Internatl Environ & Scientific Affairs 80/12/19 1p 07447 034

B101130115 Forwards application to export nuclear matl & equipment soon as application is accepted, all future shipments, for approx next 5 yrs, will be against new license
MADDEN, T G New York International Customs Service, Inc 80/11/11 1p 07457 023

--B101130119 Application by NY Intl Customs Svc, Inc for license to export 907,185 kg depleted U in form of solid metal plates to Switzerland
MADDEN, T G New York International Customs Service, Inc 80/11/11 1p 07457 024

- B101130122 Informs that European Organization for Nuclear Research has instructed NY Int'l Customs Svc. Inc to apply for export license for shipments of depleted U plates.
DORAN, M. A. European Organization for Nuclear Research.
FI/HAQ/MAD/5843. 80/12/02. 1p. 07457:025.
- B101130411 License for Exxon Nuclear Co. Inc to import 530 kg U-235, contained in 21,600 kg U from West Germany.
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. 80/12/31. 1p. 07454:051.
- B101130419 Amend 1 to Transnuclear, Inc export license, extending expiration date to 820301.
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. RBU 310 79-258/. 80/12/31. 1p. 07454:056.
- B101130423 Amend 2 to Transnuclear, Inc export license, indicating exported mat'l will be in form of U-hexafluoride or U metal.
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. MISC 321 80-073. 81/01/05. 1p. 07454:057.
- B101130433 Amend 3 to Edlow Int'l Co export license, allowing re-export from United Kingdom to West Germany of 3.5 mg Cf-252 as cermet wire.
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. 7AC-4. 81/01/05. 1p. 07309:001.
- B101130696 License for Sigma Chemical Co to export 10 kg deuterium oxide to India.
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. 80/12/26. 2pp. 07309:001.
- B101140139 Requests that NUKEM GmbH be designated as intermediate consignee for B01002 application to export U-308 contained in 9,000 kg U to West Germany.
HANSEN, L. E. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 80/12/11. 1p. 07460:352.
- B101140258 Answer opposing Ctr for Development Policy B01209 petition to intervene & request for hearing. Petitioner fails to establish standing. Notice of appearance & Certificate of Svc encl.
SHEA, K. H. Combustion Engineering, Inc. 81/01/08. 16pp. 07458:108.
- B101140266 License for Australia to export 660 kg heavy water to Australia.
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. AEC RE 20/80. 80/12/16. 2pp. 07308:001.
- B101140271 Informs that Teledyne Wah Chang Albany request for license to export 4,409 lb Zircaloy-2 trex tubes to West Germany resulted in issuance of license w/o normal 15-day waiting period.
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. 80/12/16. 1p. 07462:094.
- B101140275 License for Teledyne Wah Chang Albany to export 4,409 lb Zircaloy-2 trex tubes to West Germany.
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. 3685 (JFM). 80/12/16. 1p. 07462:095.
- B101140281 License for Nissho-Iwai American Corp to export 1.82 Ci Cf-252, contained in sealed neutron radiation source, to Japan.
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. OBM-1262. 80/12/16. 2pp. 07308:001.
- B101140319 Application by Carpenter Technology Corp for license to export 48 BNR Zircaloy-4 fuel channels to Japan.
WOZNIAK, D. R. Carpenter Technology Corp. 80/12/05. 5pp. 07462:089.
- B101140350 Informs that license may be issued since there are no mat'l changed circumstances associated w/ license XSNM-1744 since previous issuance.
MOORE, R. N. Office of International Programs, Director. 80/12/19. 1p. 07458:139.
- T. Inc to export 847.705 kg U-235 in 3 U-235 in 1 kg
or Export/Import & International
7/12/31. 2pp. 07458:140.
- c export license, reflecting that
ride or U-metal.
port/Import & International
/02. 1p. 07461:100.
- B101140825 License for Westinghouse to export 90 uCi neptunium-237 contained in six radiation surveillance capsules to Korea.
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. 80/12/21. 2pp. 07308:001.
- B101140879 Submits application to amend license to import additional quantities of irradiated fuel elements packaged in modified Goslar container.
MATSON, V. Transnuclear, Inc. 80/12/23. 2pp. 07461:288.
- B101140885 Application by Reuter-Stokes, Inc for license to export Reuter-Stokes Model RS-C3-2510-114 ion chamber to Great Britain.
ECKHOUT, A. Reuter-Stokes, Inc. W-8857. 80/12/30. 1p. 07461:291.
- B101140890 Requests name of intermediate consignee be changed to subsidiary.
HARMON, D. W. Edlow International Co. 80/12/15. 1p. 07458:351.
- B101140892 Amend 3 to Edlow Int'l Co export license, extending expiration date to 810101.
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. UES/SW-1. 80/12/31. 1p. 07461:291.
- B101140896 Informs that license may be issued since there are no material circumstances since XSNM-1572 issued.
MOORE, R. N. Office of International Programs, Director. 80/12/19. 1p. 07461:292.
- B101140905 License for Exxon Nuclear Co. Inc to export 240 kg U-235, 10,000 kg U-hexafluoride, to West Germany.
DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. 80/12/31. 2pp. 07461:293.
- B101140903 Requests amend of B00115 ltr re Transnuclear, Inc application for license to export. Amount of total U should be 905.849 kg.
MARCHEL, J. European Communities, Commission of. TNP-288. 80/12/19. 1p. 07458:354.
- B101140914 Notifies that NRC has not completed licensing action on application to export Zirconium extruded tubes to Romania.
SHEA, J. R. Office of International Programs, Director. 81/01/02. 1p. 07458:355.
- B101140922 Notifies that NRC has not completed licensing action on application to export specially designed & prepared equipment to Switzerland.
SHEA, J. R. Office of International Programs, Director. 81/01/02. 1p. 07458:356.
- B101140930 Requests Commission expedite export request after receipt of necessary info from Executive Branch. Delay causes inability to meet customer obligations.
TAYLOR, R. R. Monsanto Research Corp. 80/12/24. 1p. 07458:357.
- B101140934 Application for license to import Pye Dynamics PD2F Otto Fuel Detector.
HAAS, D. J. Philips Electronic Instruments, Inc. DJH-B0-110. 80/12/12. 1p. 07458:358.
- B101140945 Submits application to amend license to change name & address of intermediate consignee in Item 14 to Japan Nuclear Fuel Conversion Co. Ltd, 2600 Ishitani Tojuku, Tokaimura Naka-Gun Ibaragi Pref, Japan.
SHIMA, S. Mitsubishi International Corp. (subs. of Mitsubishi Corp.). HSA-5480-10. 80/12/19. 2pp. 07461:056.
- B101140950 Submits application to amend license to change name & address of supplier in Item 4 to Goodyear Atomic Corp., P.O. Box 62B, Picketown, OH 45601.
SHIMA, S. Mitsubishi International Corp. (subs. of Mitsubishi Corp.). HSA-5480-11. 80/12/19. 2pp. 07461:058.
- B101140954 Forwards application for license to export deuterium oxide to Great Britain.
EDELSTEIN, B. Aldrich Chemical Co., Inc. (subs. of Sigma-Aldrich Corp.). 80/12/29. 1p. 07457:109.
- B101140959 Application by Aldrich Chemical Co. Inc for license to export 10 kg deuterium in 40 kg deuterium oxide to Great Britain.
EDELSTEIN, B. Aldrich Chemical Co., Inc. (subs. of Sigma-Aldrich Corp.). 80/12/29. 1p. 07457:110.
- B101150020 Forwards application for license to export U in form of U-hexafluoride to Switzerland for use in research.
MATSON, V.

--B101150026 Application by Transnuclear, Inc for license to export 4,254.769 kg U-235, contained in 127,008 kg U-hexafluoride & 0.175 kg U-233, contained in 5 kg U-hexafluoride, to Switzerland
MATESON, V. Transnuclear, Inc RBU 359 80-258/ 80/12/30 3pp 07462 162

B101150031 Forwards application for license to export SHM to Japan
SAIKI, T. Mitsui & Co (U.S.A.), Inc (Subs. of Mitsui & Co., Ltd.) 80/12/23 1p 07462 166

--B101150034 Application by Mitsui & Co (USA), Inc for license to export 6 kg U-233, contained in 137 kg enriched U-hexafluoride, to Japan
MAYDEN, T. Mitsui & Co (U.S.A.), Inc (Subs. of Mitsui & Co., Ltd.) MBX-NA10 80/12/23 2pp 07462 167

B101150049 Requests that DOE advise govt of Japan of Edlow Intl requested change of intermediate consignee on Export License Application XBNM-1760 so ltr of assurance will contain correct intermediate consignee
DEVINE, J.B. Assistant Director for Export/Import & International Safeguards 80/12/31 1p 07462: 182

B101150256 Requests Executive Branch position re Edlow Intl 801218 request for Amend A to license X3-1091 for removal of condition of prior approval for re-export of 3.5 mg Cf-252 from United Kingdom to West Germany
DEVINE, J.B. Assistant Director for Export/Import & International Safeguards 80/01/03 1p 07465 354

B101150265 Forwards Exxon Nuclear Co. Inc ltr advising that intermediate consignee on export license application will be NUDEM GmbH
W/O encl
DEVINE, J.B. Assistant Director for Export/Import & International Safeguards 80/12/31 1p 07465 359

B101150467 Informs license may be issued since no matl changed circumstances since XBNM-1744 issued
MOORE, R.N. Office of International Programs, Director 80/12/19 1p 07308 001

--B101150472 License for Transnuclear, Inc to export 1,159 kg U-235, in 34,900 kg U-hexafluoride, & 0.0332 kg U-233, in 1 kg U-hexafluoride, to West Germany
DEVINE, J.B. Assistant Director for Export/Import & International Safeguards RBU 354 80-230/ 80/12/31 2pp 07308 001

B101150477 Informs license may be issued since no matl changed circumstances since XBNM-1572 issued
MOORE, R.N. Office of International Programs, Director 80/12/08 1p 07309 001

--B101150481 License for Edlow Intl Co to export 699 kg U-235, contained in 19,065 kg U-hexafluoride, to Sweden
DEVINE, J.B. Assistant Director for Export/Import & International Safeguards 80/12/31 2pp 07309 001

B101150620 Discusses findings re proposed import of depleted U metal castings by Nuclear Transport & Storage, Inc, from Canada
License should be issued
MOORE, R.N. Office of International Programs, Director 80/12/22 1p 07465 253

B101160218 Requests withdrawal of condition to obtain prior approval for re-export, excluding specific countries if timely exemption cannot be granted, requests approval to re-export 3.5 mg Cf-252 source to West Germany
HARMON, D. Edlow International Co 80/12/18 1p 07183 001

B101160224 Notifies that NRC has not completed licensing action on Westinghouse application for license to export two incinerator-neutron detectors to Switzerland
SHEA, J.R. Office of International Programs, Director 81/01/02 1p 07468 354

B101160227 Approves Exxon Nuclear Co. Inc application for license to import 21,600 Kg low enriched U, enriched to 2.95%, from West Germany
MOORE, R.N. Assistant Director for Export/Import & International Safeguards 80/12/31 1p 07468 353

B101160950 Informs that NRC has not completed licensing action on export license application X8-1105 for export of 904 micrograms Cf-252 & 250 mg Hg-237 to Taiwan
SHEA, J.R. Office of International Programs, Director 81/01/02 1p 07471 295

B101190366 Application by Transnuclear, Inc for Amend 2 to export license Cern Lab notified that Intl Customs Svc Inc should be listed as licensee Original export license & Amend 1 will be returned for NRC handling
MATESON, V. Transnuclear, Inc 78-067/5/01 NY 80/12/15 07474 279

B101190382 Advises that Transnuclear, Inc has been requested to export license Intl Customs Svc is new licensee Requests that licensing procedure be expedited
DOGAN, H.A. CERN, Theory Div., Switzerland 80/12/16 1p 07183 001

B101190557 Requests ack of receipt of 801216 cable & Transnuclear export license & whether new license has been issued to Intl Customs Svc
DOGAN, H.A. CERN, Theory Div., Switzerland 80/12/17 1p 07183 001

B101190751 Forwards Mitsubishi Intl Co 801219 request for Amend export license application changing intermediate consignee Govt of Japan must be notified so that ltr of assurance reflects change w/o encl
DEVINE, J.B. Assistant Director for Export/Import & International Safeguards 81/01/07 1p 07476: 122

B101190755 Ltr of assurance re Transnuclear, Inc 801201 Application report 64 034 kg U-235, contained in 1,911 kg U, to The Netherlands
MARCMAN, J. European Communities, Commission of 80/12/23 07476 123

B101190756 Requests amend to license, changing intermediate consignee HEIMANN, D. Reactor Experiments, Inc 81/01/06 1p 07183 001

B101200005 Provides info re status of reactor components for Malaysia pending approval of license application Reactor tank & mechanical & electronic components fabricated & in storage at OA Co
MCWARY, W.R. General Atomic Co (subs. of Gulf Oil Co.) 80/12/10 1p 07487 020

B101200006 Provides status of reactor components awaiting export Morocco under pending license All mechanical & electronic components purchased & prepared for shipping
MCWARY, W.R. General Atomic Co (subs. of Gulf Oil Co.) 80/12/10 1p 07487 019

B101200396 Forwards application for export license GUMER, D.A. Nuclear Metals, Inc 81/01/02 1p 07477 358

--B101200435 Application by Nuclear Metals, Inc for license to export U-x-ray shield component to Canada
Nuclear Metals, Inc 1-201-7 80/12/24 1p 07477

B101200446 Executive Branch position re Monsanto Research Corp application for license to export 1 mg Cf-252 contained in neutron source to Bhabha Atomic Research Ctr, India
NOBENZO, L.V. State Dept. of, Bureau of Oceans & International Scientific Affairs 81/01/05 1p 07487 112

B101200453 License for Ruster-Stokes Inc to export 29 incinerator detectors for flux mapping to Sweden
DEVINE, J.B. Assistant Director for Export/Import & International Safeguards W-8524 81/01/09 1p 07487 116

B101200460 Mod 1 to add Dains Selvesha Company, Ltd as an intermediate consignee to license XBNM-1715
DEVINE, J.B. Assistant Director for Export/Import & International Safeguards 81/01/07 1p 07487 118

B101200540 Requests Executive Branch position re Transnuclear application for license to export SHM to Switzerland for use in Gossingen-Deonlen Reactor as multiple reloads
W/O encl
DEVINE, J.B. Office of International Programs, Director 81/01/02 1p 07487 126

B101210105 Executive Branch position re C-E application for license to export two light water moderated & cooled pressurized water NSS w/design power level of 700 Mw to Taiwan License should be issued
NOBENZO, L.V. State Dept. of, Bureau of Oceans & International Scientific Affairs 80/12/12 13pp 07489 337

B101210593 License for Isotope Products Labs to export 10 uCi of Au-198 to Austria
DEVINE, J.B. Assistant Director for Export/Import & International Safeguards W/O 8389 81/01/12 2pp 07488 012

0101300457 Requests Executive Branch position re IX Instruments, Inc application for license amend to export addl 100,000 Ci tritium As gas contained in glass-sealed light sources
DEVINE, J B Assistant Director for Export/Import & International Safeguards 01/01/23 1p 07587 050

0101300464 Amend 1 to license for Westinghouse, extending expiration date from 010310 to 010715
DEVINE, J B Assistant Director for Export/Import & International Safeguards 01/01/23 1pp 07583 300

0101300469 License for Reuter-Stokes, Inc to export one ion chamber, Reuter-Stokes Model RS-C3-2510-114, to United Kingdom
DEVINE, J B Assistant Director for Export/Import & International Safeguards 01/01/19 1pp 07587 053

0101300490 Application by Westinghouse for license to export one WL23914 compensated ion chamber at no charge to France
SCHNAUF, C E Westinghouse Electric Corp IE-20293-3A 01/01/16 1pp 07583 317

0101300496 License for Monsanto Research Corp to export 1 mg Cf-252 as neutron source (Model 27651) to India
DEVINE, J B Assistant Director for Export/Import & International Safeguards 191-9AD (1) 01/01/21 2pp

0101300527 License for Eberline Instrument Corp to export 0.22 micrograms Pu-237 to United Kingdom
DEVINE, J B Assistant Director for Export/Import & International Safeguards SO 7687 01/01/21 2pp 07183 001

0101300532 License for Westinghouse to export 470 micrograms Cf-252 to South Korea
DEVINE, J B Assistant Director for Export/Import & International Safeguards 1L6-011 01/01/23 1pp 07583 320

0101300534 Amend 2 to license for Hissho Iwai American Corp, extending expiration date from 010201 to 020901
DEVINE, J B Assistant Director for Export/Import & International Safeguards NIAC-7B-C03 01/01/19 1p 07583 321

0101300539 License for Nuclear Metals, Inc to export 908 kg depleted U to Canada
DEVINE, J B Assistant Director for Export/Import & International Safeguards 1-201-7 01/01/23 2pp 07587 046

0101300616 Amend 1 to for Niteul & Co, Inc license increasing quantity of export ratl from 108.853 lb to 127.316 lb, increasing value of export items & adding Kyushu Electric Power Co, Inc as ultimate consignee
DEVINE, J B Assistant Director for Export/Import & International Safeguards 01/01/23 1p 07587 048

PERSONAL AUTHOR INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ABBOTT, E	0101202797*	ACRS	AHEARNE, J F	0101140571*	COMMISSION	ALKEEP, F J T	0101260709	PR
ABBOTT, E E	01012020804*	ACRS	AHEARNE, J F	0101100200	COMMISSION	ALLEN, T	0101260079	NUREG
ABEL, J B	0101090810*	50-254 Q	AHEARNE, J F	0101100507*	COMMISSION	ALLEN, S	0101230331	PR
ABEL, J S	0101090244*	50-254 Q	AHEARNE, J F	0101100312*	COMMISSION	ALLEN, R D.	0101150410*	0A999
ABEL, J S	0101070251	REGO	AHEARNE, J F	0101100219*	COMMISSION	ALLIKBERG, R	0101290159*	FOIA
ABEL, J S	0101100331*	50-456 Q	AHEARNE, J F	0101100226*	COMMISSION	ALLIKBERG, R	0101290151*	FOIA
ABEL, J S	0101260707*	50-454 Q	AHEARNE, J F	0101100233*	COMMISSION	ALLIKBERG, R.	0101290261*	FOIA
ABEL, J S	0101260609*	50-293 Q	AHEARNE, J F	0101100239*	COMMISSION	ALLIQU, M M	0101270393	PR
ABEL, J S	0101090360	50-10 P	AHEARNE, J F	0101100245*	COMMISSION	ALLTEN, A G	0101220243	50-28
ABEL, J S	0101090301	50-10 P	AHEARNE, J F	0101140327*	50-220 P	ALLIET, D	0101140583	PR
ABEL, J S	0101230117	50-373 S	AHEARNE, J F	0101270679	COMMISSION	ALPERT, S	0101210034	PR
ADERCHONJIE, H	0101130582	50-299 R	AHEARNE, J F	0101060752	COMMISSION	ALPERT, S	0101300830	PR
ADERCHONJIE, H	0101130595	50-299 R	AHEARNE, J F	0101060755	50-320 P	AMBER, K.	0101290699	PR
ADAMSON, S	0101230293	PR	AHEARNE, J F	0101080279	50-320 U	AMSTUTZ, S	0101130233*	50-19
AQUAF, N	0101230189	REG	AHEARNE, J F	0101140666	COMMISSION	AND, E	0101290677	PR
AQUAF, N	0101270222	50-537 A	AHEARNE, J F	0101140676	COMMISSION	ANDERS, W A	0101120164*	COMMI
AQUAF, N	0101230636	REG	AHEARNE, J F	0101140681*	COMMISSION	ANDERS, W A	0101260334*	FOIA
AQUAF, N	0101230653	50-537 A	AHEARNE, J F	0101140674*	COMMISSION	ANDERSON, P A	0101100163*	50-28
AQUAF, N	0101230676	REG	AHEARNE, J F	0101140675*	COMMISSION	ANDERSON, J J	0101200291*	50-20
AQUAF, N	0101270645	50-537 A	AHEARNE, J F	0101140699*	COMMISSION	ANDERSON, S. L	0101270526*	50-34
AQUAF, N	0101270065	50-537 A	AHEARNE, J F	0101140904*	COMMISSION	ANDERSON, D G	0101130460*	0A999
AQUAF, N	0101270071	REG	AHEARNE, J F	0101100004	COMMISSION	ANDERSON, D G	0101150429*	0A999
AQUAF, N	0101210944	50-537 A	AHEARNE, J F	0101140818	70-143	ANDERSON, T M	0101220283	PR
ACOSTA, A	0101090929	ACRS	AHEARNE, J F	0101140832*	70-143	ANDERSON, E I	0101140592	PR
ACOSTA, A P	0101100129	40-8584	AHEARNE, J F	01011080314	50-466 U	ANDERSON, J M.	0101260420	TOPRE
ADAMS, R C	0101220620	REG	AHEARNE, J F	0101080331*	COMMISSION	ANDERSON, P B.	0101140813*	CONTR
ADAMSON, K	0101140607	PR	AHEARNE, J F	0101080336*	COMMISSION	ANDERSON, T M.	0101140567	50-28
ADCGCK, A	0101150140	PR	AHEARNE, J F	0101080360*	COMMISSION	ANDERSON, T M	0101220426	TOPRE
ADLER, R W	0101070202	50-387 Q	AHEARNE, J F	0101080362*	50-466 U	ANDERSON, C J	0101200197	50-32
ADLER, T A	0101130031	50-289 Q	AHEARNE, J F	0101140774	COMMISSION	ANDERSON, R L	0101290817	NUREG
ADLER, T A	0101130031	50-289 Q	AHEARNE, J F	0101140779*	COMMISSION	ANDERSON, T M	0101130584	TOPRE
ADLER, R W	0101120506	50-289 Q	AHEARNE, J F	0101140786*	COMMISSION	ANDERSON, T M	0101190330	TOPRE
ADOLPH, J L	0101230991	PR	AHEARNE, J F	0101140790*	COMMISSION	ANDERSON, T M	0101210372	TOPRE
ADERSOLD, P C	0101060736*	FOIA	AHEARNE, J F	0101140799*	COMMISSION	ANDERSON, T M	0101210401*	TOPRE
AFIFI, S	0101120444	50-329 Q	AHEARNE, J F	0101140852*	COMMISSION	ANDERSON, T M	0101210483	REVIEW
AFRAH, B	0101220530	PR	AHEARNE, J F	0101140705	50-289 H	ANDERSON, T M	0101260516	TOPRE
ADAPITO, J F	0101150134*	FOIA	AHEARNE, J F	0101130620	COMMISSION	ANDERSON, T M	0101230211	TOPRE
ADAPITO, J F	0101150127*	FOIA	AHEARNE, J F	0101120522*	COMMISSION	ANDERSON, T M	0101210377*	TOPRE
ADATA, C	0101200421	PR	AHEARNE, J F	0101130632*	COMMISSION	ANDERSON, T M	0101090718	REQD
AGFE, J R	0101150460*	0A999	AHEARNE, J F	0101130634*	COMMISSION	ANDRUS, N J	0101070311	40-44
AHEARNE, J F	0101060270	50-320 P	AHEARNE, J F	0101130637*	COMMISSION	ANGLE, D.	0101140614	PR
AHEARNE, J F	0101080304*	50-320 U	AHEARNE, J F	0101130640*	COMMISSION	ANSARI, A F	0101080402*	50-27
AHEARNE, J F	01012110047	COMMISSION	AHEARNE, J F	0101130643*	COMMISSION	ANTHONY, R L	0101290493*	50-35
AHEARNE, J F	01012110036	COMMISSION	AHEARNE, J F	0101130646*	COMMISSION	ARATA, N	0101260645	PR
AHEARNE, J F	0101060266	COMMISSION	AHEARNE, J F	0101300784	COMMISSION	ARBITZEL, R G.	0101150573*	50-31
AHEARNE, J F	0101050432	COMMISSION	AHEARNE, J F	0101280398	50-320 P	ARCIERI, W C	0101060457*	50-26
AHEARNE, J F	0101060835	COMMISSION	AHEARNE, J F	01012110279	PR	ARCIERI, W C	0101060498*	50-32
AHEARNE, J F	0101070017*	50-395 Q	AHEARNE, J F	0101130516*	50-295 S	ARCIERI, W C	0101290419*	50-32
AHEARNE, J F	0101140716	COMMISSION	AHEARNE, J F	0101190335	PR	ARENAL, A	0101300759*	50-26
AHEARNE, J F	0101140729*	COMMISSION	AHEARNE, J F	0101070362	50-206 P	ARLOTTO, G A	0101210322	REQD
AHEARNE, J F	0101080241	COMMISSION	ALAGO, A	0101280505	50-247 H	ARNOLD, L	0101190594	PR
AHEARNE, J F	0101140852	COMMISSION	ALBAUGH, F. H	0101070347	ACRS	ARNOLD, R C.	0101050111*	50-28
AHEARNE, J F	0101140855*	COMMISSION	ALCURI, E. C.	0101220572	PR	ARNOLD, R C.	0101290593	50-28
AHEARNE, J F	0101140859*	COMMISSION	ALDEN, W M	0101210520*	50-277 R	ARDONSON, A L	0101300674	RES
AHEARNE, J F	0101140862*	COMMISSION	ALEXANDER, P	0101280404	PR	ARDONSON, N	0101210427	PR

[illegible]

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BRYAN, J. A.	0101110335	50-483 S	CANTER, H.	0101285087*	50-212 Q	CARTWRIGHT, W. R.	0101230614*	50-339
BRYSON, J. O.	0101190842	PR	CANTRELL, F. S.	0101100672*	50-518 Q	CARTWRIGHT, W. R.	0101270502	50-338
BUCKHOLD, Z. R. H.	0101286882	PR	CAPITON, D. L.	0101183604*	50-213 Q	CARTWRIGHT, W. R.	0101270508*	50-338
BUCHANAN, M. E.	0101120292	RES	CAPITON, D. L.	0101280727*	50-245 Q	CARTWRIGHT, W. R.	0101300706	50-337
BUCHHOLD, Z. R. H.	7912310182	REF00	CAPITON, D.	0101280754	50-225 S	CARTWRIGHT, W. R.	0101300714*	50-339
BUCHHOLD, Z. R. H.	0101140155	REF00	CARBAUGH, E. H.	0101280381*	50-225 Q	CASAD, D.	01012003270	PR
BUCHHOLD, Z. R. H.	0101050170	TOPREP	CARDONEAU, M. L.	0101300145	RES	CASE, E. O.	0101296022*	50-413
BUCHHOLD, Z. R. H.	0101210519	TOPREP	CARDON, M.	0101280206	50-271 H	CASH, A.	0101120310	State A
BUCHHOLD, Z. R. H.	0101210371	TOPREP	CARLSON, A. M.	0101140537	AL060	CASHMELL, P. J.	0101286467	50-156
BUCHHOLD, Z. R. H.	0101180342	TOPREP	CARLSON, R. T.	0101300050*	50-333 Q	CASTAGNOLI, L.	0101200415	PR
BUCHHOLD, Z. R. H.	0101270598	TOPREP	CARLSTROM, R. E.	0101100010*	COMMISSION	CASTRO, G.	0101050234*	40-1342
BUCKALEW, H. H.	0101200841*	50-313 A	CARLSON, R. T.	0101300134	50-317 Q	CATCHPOLE, D. J.	0101220595	40-869
BUCKLEY, D.	0101180030*	50-361 A	CARLSON, R. T.	0101057491	50-354 S	CAURACHO, R. H.	0101300540	PR
BURDET, R. J.	0101267283*	FOIA	CARLSON, R. T.	0101160045	50-402 S	CAVANAGH, W.	0101120152	50-313
BURDUFF, D. S.	0101160290	PR	CARLSON, R. T.	0101100071	50-387 S	CAVANAGH, W.	0101200520	PR
BUEHRING, R. A.	0101120085	REVIEW GRP	CARLSON, R. T.	0101300088	50-333 Q	CAZZOLI, E. G.	0101270827	50-537
BUELL, S. A.	0101210113	PR	CARLSON, R. T.	0101100332	50-423 S	CECCONI, A.	0101070095	50-537
BULISCHHECK, T.	0101230643	RES	CARLSON, R. T.	0101140110	50-272 Q	CEENA, D. W.	0101290670	PR
BULISCHHECK, T.	0101230623	RES	CARLSON, R. T.	0101100512	50-278 Q	CELLEROY, S.	0101262317	PR
BULISCHHECK, T.	0101260828	RES	CARLSON, R. T.	0101290777	50-354 Q	CELRADO, H.	0101300343	PR
BULLEN, H. C.	0101290255*	FOIA	CARLSON, R. T.	0101280107	50-412 S	CHAMBERS, R.	0101130408	MUSEG
BULLEN, H. C.	0101290143*	FOIA	CARLSON, R. T.	0101300113	50-307 S	CHAMBERS, R.	0101130414	MUSEG
BULLEN, H. C.	0101290131*	FOIA	CARLSON, R. T.	0101180493	50-271 Q	CHAMBERS, R.	0101130503	50-413
BULLOCK, R. E.	0101280375*	50-438 A	CARLSON, R. T.	0101050374	50-387 S	CHANDLER, L. J.	0101140038	50-261
BULLOCK, R. E.	0101280375*	50-438 A	CARLSON, R. T.	0101050370	50-387 S	CHANEY, N. V.	0101080340	50-344
BULLOCK, R. E.	0101280375*	50-438 A	CARLSON, R. T.	0101140324	50-387 Q	CHANG, S. M.	0101210375*	TOPREP
BURKE, D. J.	0101230796	PR	CARLSON, R. T.	0101090616	50-307 S	CHARLTON, S. D.	0101090181*	50-320
BURGESS, S. L.	0101300308*	50-282 Q	CARLSON, R. T.	0101190272	50-412 S	CHARLIN, S. D.	0101190486*	50-320
BURKE, D. J.	0101180706*	50-283 Q	CARLSON, R. T.	0101190306	50-410 S	CHARLTON, S. D.	0101270571*	50-320
BURKE, D. J.	0101180706*	50-283 Q	CARLSON, R. T.	0101160590	50-387 S	CHARMAN, L. D.	0101190610	RES
BURKE, D. J.	0101080065	PR	CARLSON, R. T.	0101190794	50-272 P	CHARLES, F. K.	0101230069	50-289
BURKHARDT, W.	0101100709*	70-364	CARLSON, J. D.	0101210117*	50-377 Q	CHARNOFF, C.	0101290063	PR
BURKHARDT, W.	0101290525*	70-754	CARLSON, R. T.	0101070290	50-412 S	CHARTLAND, O. G.	0101260121	PR
BURNETTE, G. C.	0101300020	RES	CARLSON, R. T.	0101160553	50-387 S	CHECK, P. S.	0101190314*	50-322
BURNETT, R. F.	0101210574*	FOIA	CARLSON, R. T.	0101150779	50-387 S	CHEN, T.	0101100601	RES
BURNETTE, G. W.	0101210542	RES	CARLSON, R. T.	0101190314	50-382 S	CHENG, H. S.	0101220642	RES
BURNETTE, G. W.	0101220324	RES	CARR, J. C.	0101260381*	50-209 H	CHENG, H.	0101230347	RES
BURNETTE, G. W.	0101220322	RES	CARR, J. C.	0101260072*	50-209 H	CHENG, H.	0101300682	RES
BURNETTE, G. W.	0101190651*	RES	CARR, J. C.	0101260355*	50-209 H	CHERRY, R. H.	0101290644	PR
BURNETTE, G. W.	0101220649	RES	CARR, J. C.	0101280606*	50-209 H	CHERRY, M. H.	0101050416	50-454
BURNETT, P.	0101140762	PR	CARR, J. C.	0101260052*	FOIA	CHESTER, R. D.	0101230277	RES
BURNETTE, G. W.	0101220655	REC	CARR, P.	0101290719	PR	CHEWAN, J. C.	0101140697	50-271
BURNETTE, G. W.	0101280650	RES	CARR, J. C.	0101260043*	50-289 H	CHIANG, H. J.	0101070437	50-403
BURNETT, R. F.	0101193293	70-1100	CARR, J. C.	0101260034*	FOIA	CHIANG, H. J.	0101130225	50-403
BURNS, J.	0101190927	PR	CARR, J. C.	0101150177	QAC	CHICHESTER, G.	0101300293	PR
BURNS, T.	0101160330	PR	CARR, J. C.	0101160275	QAC	CHILD, K. W.	0101060111	MUSEG
BURNS, K. J.	0101090009*	50-271 P	CARR, J. C.	0101050516	QAC	CHILD, K. W.	0101120310*	50-333
BURNS, S. O.	0101120003	50-255 Q	CARR, J. C.	0101290516	50-219 S	CHILD, K. W.	0101120534*	50-333
BURNS, S. O.	0101110578	50-255 Q	CARR, J. C.	0101230461*	50-310 Q	CHILD, K. W.	0101160564*	50-333
BURNS, S. O.	0101210367*	50-271 P	CARTER, R. S.	0101060627	50-104 R	CHILD, K. W.	0101210476*	50-333
BURNS, S. O.	0101260523	50-255 Q	CARTER, R. S.	0101060633*	50-104 R	CHILK, S. J.	0101100339*	FOIA
BURNS, S. O.	0101280044	50-407 Q	CARTER, K. W.	0101070202	50-387 Q	CHILK, S. J.	0101190673*	SECY
BURSTEIN, S.	0101160551	50-266 P	CARTWRIGHT, W. R.	0101060567	50-338 Q	CHILK, S. J.	0101190681*	SECY
BURSTEIN, S.	0101280377	50-266 Q	CARTWRIGHT, W. R.	0101060597*	50-339 S	CHILK, S. J.	0101100310	FOIA
BURSTEIN, S.	0101280321	50-266 Q	CARTWRIGHT, W. R.	0101070630	50-339 S	CHILK, S. J.	0101280398*	FOIA
BURSTEIN, S.	0101270567	50-266 S	CARTWRIGHT, W. R.	0101070630*	50-339 S	CHILK, S. J.	0101070118*	FOIA
BURWELL, G. B.	0101050250	50-424 A	CARTWRIGHT, W. R.	0101130645	50-338 S	CHILK, S. J.	01012100402*	FOIA
BURWELL, S. B.	0101270647	50-445 A	CARTWRIGHT, W. R.	0101130648	50-339 S	CHILK, S. J.	0101300856	ACRS
BUSH, L. L.	0007250559	FOIA	CARTWRIGHT, W. R.	0101130647	50-339 S	CHILK, S. J.	0101170727*	COMMISSION
BUSH, L.	0101260740	PR	CARTWRIGHT, W. R.	0101130648*	50-339 S	CHILK, S. J.	0101150425	COMMISSION
BUSLIK, A. J.	0101220631	50-255 P	CARTWRIGHT, W. R.	0101130648*	50-339 S	CHILK, S. J.	0101060041	TOPREP
BUTENSKY, M. D.	0101160592	PR	CARTWRIGHT, W. R.	0101130648*	50-339 S	CHILK, S. J.	0101140111	TOPREP
BURER, S. D.	0101100364*	50-277 Q	CARTWRIGHT, W. R.	0101130528*	50-339 S	CHILK, S. J.	0101140046*	50-361
BUTLER, A. R.	0101150164	PR	CARTWRIGHT, W. R.	0101130534	50-339 S	CHILK, S. J.	0101140053*	50-361
BYRNS, C.	0101200404	50-556 Q	CARTWRIGHT, W. R.	0101130539*	50-337 R	CHILK, S. J.	0101210246	TOPREP
BYRNES, K.	0101210150	PR	CARTWRIGHT, W. R.	0101130542*	50-338 Q	CHILK, S. J.	0101120286	50-3
CACCIAPAROTTI, R.	0101060445*	50-271 P	CARTWRIGHT, W. R.	0101120331	50-338 S	CHILK, S. J.	0101140811*	COMMISSION
CADWELL, J. J.	0101150633	RES	CARTWRIGHT, W. R.	0101120385*	50-338 S	CHILK, S. J.	0101070520	50-155
CADWELL, J. J.	0101150641	RES	CARTWRIGHT, W. R.	0101300582	50-339 S	CHILK, S. J.	0101290415*	TOPREP
CAFFERTY, J.	0101070366	50-271 H	CARTWRIGHT, W. R.	0101300597*	50-339 S	CHILK, S. J.	0101200401	50-556
CALHA, A. L.	0101120212	REG00	CARTWRIGHT, W. R.	0101280331	50-339 S	CHILK, S. J.	0101120449	50-367
CAMP, A. L.	0101210382	TOPREP	CARTWRIGHT, W. R.	0101200355*	50-339 S	CHILK, S. J.	0101160246	50-247
CAMP, J.	0101270961	WASTE MGT	CARTWRIGHT, W. R.	0101200352	50-338 S	CHILK, S. J.	0101160288	50-10
CALDWELL, R. A.	0101100074*	50-267 Q	CARTWRIGHT, W. R.	0101220354*	50-338 S	CHILK, S. J.	0101130613*	50-357
CALLAHAN, C. J.	0101150573*	50-317 Q	CARTWRIGHT, W. R.	0101280375	50-339 S	CHILK, S. J.	0101140983	50-409
CALLAHAN, C. J.	0101100536*	50-313 Q	CARTWRIGHT, W. R.	0101200383*	50-339 S	CHILK, S. J.	0101150206	50-289
CALLAHAN, C. J.	0101120419*	50-454 Q	CARTWRIGHT, W. R.	0101200431	50-338 S	CHILK, S. J.	0101150003	50-155
CAMERON, H.	0101200509	PR	CARTWRIGHT, W. R.	0101200437*	50-338 S	CHILK, S. J.	0101160732	50-454
CAMPBELL, H.	0101190018	PR	CARTWRIGHT, W. R.	0101200444	50-337 S	CHILK, S. J.	0101220005	PR
CAMPBELL, H.	0101090537	50-245 B	CARTWRIGHT, W. R.	0101230452*	50-339 S	CHILK, S. J.	0101220014	50-271
CAMPBELL, T. E.	0101200423*	TOPREP	CARTWRIGHT, W. R.	0101210439	50-338 S	CHILK, S. J.	0101230156	50-443
CANALE, J. D.	0101150157	RES	CARTWRIGHT, W. R.	0101210446*	50-338 S	CHILK, S. J.	0101230437	50-155
CANDY, J. V.	0101220255	RES	CARTWRIGHT, W. R.	0101220452	50-338 S	CHILK, S. J.	0101240479	TOPREP
CANFIELD, H. G.	0101190257	PR	CARTWRIGHT, W. R.	0101220456*	50-338 S	CHILK, S. J.	0101290509	TOPREP
CANTER, H. L.	0101180103*	50-312 Q	CARTWRIGHT, W. R.	0101230593	50-339 S	CHILK, S. J.	0101230653	50-155

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CHILK, S J	0101260531	50-309 G	CLARK, R A	0101280114*	50-309 G	COLCHARD, R W	0101280280*	50-309
CHILK, S J	0101280091	50-367 G	CLARK, R A	0101300609	50-285 P	COLCHARD, R W	0101280362*	50-309
CHILSGN, V T	0101210410*	50-250 R	CLARK, R A	0101300614*	50-285 P	COLCHARD, R W	0101280302*	50-309
CHILSGN, V T	0101210429*	50-250 R	CLARK, R A	0101300624*	50-285 P	CONRADIE, K O	0101100601	RE50
CHIN, S	0101140130	71-5796	CLARK, R A	0101290686	50-348 Q	CONRADIE, V H	0012160144	50-309
CHIRAMAL, M	0101100184	50-346 P	CLAYTON, F L	0101100319*	50-348 Q	CONKLIN, J C	0101090951	REUR
CHIRIGOS, J N	0101160473*	50-206 P	CLAYTON, C	0101160262	PR	CONKLIN, T E	0101100343*	50-309
CHIRIGOS, J N	0101160473*	50-206 P	CLAYTON, F L	0101050321	50-348 P	CONKLIN, T E	0101100783*	50-309
CHODOROH, L	0101160327	PR	CLAYTON, F L	0101146507	50-348 P	CONKLIN, T E	0101120070*	50-309
CHODIN, N	0101260354	50-250 G	CLAYTON, F L	0101190101	50-364 P	CONKLIN, T E	0101100689*	50-309
CHOWLES, N C	0101160156*	50-304 Q	CLAYTON, F L	0101210402	50-348 P	CONKLIN, T E	0101160684*	50-309
CHOWLES, N C	0101290573*	50-282 Q	CLAYTON, F L	0101290363	50-348 Q	CONNER, L	0101130029	FO1A
CHOWLES, N C	0101210654*	50-346 Q	CLAYTON, F L	0101070308	50-361 A	CONNELL, C	0101200290*	50-309
CHRISTA-MARIA	0003270417*	50-155 Q	CLAYTON, F L	0101130602	50-340 S	CONNER, E L	0101190573	50-309
CHRISTA-MARIA	0101090942*	50-155 Q	CLAYTON, F L	0101220359	50-348 P	CONNER, E L	0101290778	50-309
CHRISTENSEN, J	0101050197*	50-287 T	CLAYTON, F L	0101140554	50-348 Q	CONNER, T B	0101280362	50-309
CHRISTOFFER, Q	0101300126*	XP0RTLIC	CLAYTON, F L	0101210411	50-364 P	CONRAD, C	0101230175	FO1A
CHRISTOFFER, Q	0101080392*	50-254 Q	CLAYTON, F L	0101300980	50-248 S	CONRADY, U U	0101270944	40-0
CHRISTOFFER, Q	0101150257	PR	CLAYTON, F L	0101210426	50-348 S	CONSTABLE, C L	0101070252*	50-309
CHRISTOFFER, Q	0101230310	PR	CLAYTON, F L	0101210918	50-348 R	CONWAY, W F	0101160640*	50-309
CHRISTIA, SON, W	0101290449*	50-331 Q	CLAYTON, F L	0101210491	50-364 R	CONWAY, W F	0101160627*	50-309
CHRISTENSEN, J	0101090001	50-287 T	CLAYTON, F L	0101260360	50-340 P	CONWAY, W F	0101160665*	50-309
CHRISTOFFER, Q	0101060290*	50-295 Q	CLAYTON, F L	0101290340	50-248 Q	CONWAY, W F	0101140913	50-309
CHRISTOFFER, Q	0101130206*	50-254 Q	CLAYTON, F L	0101290728	50-348 Q	CONWAY, W F	0101140707	50-309
CHRISTA-MARIA	0101070376	50-155 H	CLAYTON, F L	0101220344	50-364 P	CONWAY, W F	0101060389	50-309
CHRISTY, W	0101140065	50-482 Q	CLAYTON, F L	0101230425	50-348 P	CONWAY, W F	0101060416	50-309
CHRISTMAN, J M	0101130284	50-280 Q	CLAYTON, F L	0101260350	50-348 A	CONWAY, W F	0101210530	50-309
CHRISTIAN, R W	0101200169	50-289 H	CLAYTON, F L	0101260365	50-364 V	COOK, J W	0101050600*	50-309
CHRISTENBURY, E	0101270323	50-454 Q	CLAYTON, F L	0101270696	50-348 P	COOK, J W	0101070236*	50-309
CHJ, C K	0101050187*	TOPREP	CLAYTON, F L	0101270750	50-348 P	COOK, J W	0101120250	50-309
CHLPA, M	0101190027	PR	CLAYTON, F L	0101280164	50-364 P	COJA, R J	0101210533*	50-309
CHUNG, J W	0101150558*	50-317 Q	CLAYTON, F L	0101270914	50-348 P	COOK, J W	0101090132*	50-309
CHUNG, J W	0101150585*	50-247 Q	CLAYTON, F L	0101280288	50-348 S	COOK, J W	0101090340*	50-309
CHUNG, J W	0101300019*	50-220 Q	CLERO, M	0101300146	PR	COJA, J W	0101060272*	50-309
CHILLIS, N	0101210629*	50-361 Q	CLERO, L B	0101290703	NAMEO	COOK, J W	0101230225	50-309
CHILLIS, M	0101290556*	50-224 Q	CLEIGNS, P	0101220638*	70-371	COJA, J W	0101050365	50-309
CINGO, M A	0101290732	PR	CLEIGHNS, P	0101160125*	70-333	COOK, J W	0101090513	50-309
CIPOLLA, A J	0101170645	71-6273	CLEVELAND, C J	0101300847	50-255 P	COJA, J W	0101090594	50-309
CIPIC, LA, A J	0101100256	40-3392	CLEVELAND, C J	0101100590	50-344 P	COJA, J W	0101280591	50-309
CISTERNINO, M	0101130189	PR	CLEVELAND, C J	0101090791	NAMEO	COOK, J W	0101140653	50-309
CLAPP, R W	0101190601	NUREG	COBB, L I	0101210050*	50-592 A	COOK, J W	0101190604	50-309
CLARKE, L S	0101290449*	50-331 Q	COBB, L I	0101210086*	50-580 A	COOK, J W	0101230981	50-309
CLARKE, O A	0101260136	NUREG	COBEN, S	0101290663	PR	COJA, J W	0101290380	50-309
CLARK, D A	0003180928	50-320 C	COBY, S	0101160011	PR	COOK, B A	0101290692	NUREG
CLARK, R A	0101070129	50-338 P	COCCIN, C L	0101090660*	50-366 S	COLLE, K J	0101290542*	70-7
CLARK, R A	0101070134*	50-338 P	COCCIN, C L	0101060966*	50-366 S	COONEY, M J	0101050265	50-309
CLARK, R A	0101070143*	50-333 P	COCCIN, C L	0101060979*	50-366 S	COONEY, M J	0101050442	50-309
CLARK, R A	0101090745	50-344 P	COCCIN, C L	0101060993*	50-321 S	COONEY, M J	0101070496	50-309
CLARK, R A	0101090753*	50-344 P	COCCIN, C L	0101290423*	50-321 S	COONEY, M J	0101140519	50-309
CLARK, R A	0101090760*	50-344 P	COCCIN, C L	0101290469*	50-366 S	COONEY, M J	0101210522	50-309
CLARK, R A	0101090935	50-344 P	COHEN, I	0101300196*	70-135	COONEY, M J	0101220480	50-309
CLARK, R A	0101090938*	50-344 P	COHEN, B R	0101190932	PR	COONEY, M J	0101220496*	50-309
CLARK, R A	0101090939*	50-344 P	COHEN, A	0101200434	PR	COONEY, M J	0101260266	50-309
CLARA, U	0101140141	State Prog	COHEN, S	0101060827*	CONTRACT	COONEY, M J	0101220488	50-309
CLARK, R A	0101090941	50-317 P	COHEN, S	0101270727	CONTRACT	COONEY, M J	0101220477	50-309
CLARK, R A	0101090943*	50-317 P	COHEN, D	01011160211	50-352 G	COONEY, M J	0101220483	50-309
CLARK, R A	0101090947*	50-317 P	COHN, D M	0101100307*	CONTRACT	COONEY, M J	0101230386	50-309
CLARK, R A	0101100139	50-309 P	COHN, H I	0101160707	PR	COCKE, M J	0101260564	50-309
CLARK, R A	0101190377	50-250 F	COJIN, D B	0101140988	50-369 G	COCKE, M J	0101230474	50-309
CLARK, R A	0101100490	50-335 P	COJIN, D B	0101140988	50-369 U	COONEY, M J	0101270550	50-309
CLARK, R A	0101100518	50-266 P	COJIN, D B	0101260311	50-369 Q	COONEY, M J	0101270557*	50-309
CLARK, R A	0101100527*	50-266 P	COLGREN, Q D	0101300102	PR	COOPER, C	0101230321	PR
CLARK, R A	0101100543*	50-266 P	COLCOCK, A H	0101200695	50-259 Q	COPELAND, R L	0101070495	RE09
CLARK, R A	0101120051	50-282 P	COLE, R	0101130019*	50-454 Q	COPELAND, J G	0101090355	50-4
CLARK, R A	0101120056*	50-282 P	COLELLD, F	0101140651	PR	COPELAND, J G	0101090595	50-4
CLARK, R A	0101120062*	50-282 P	COLEMAN, R	0101070998	CONTRACT	COPELAND, R L	0101070492	50-5
CLARK, R A	0101140454	50-344 F	COLEMAN, R	0101060341*	CONTRACT	COLEMAN, M	0101150842	PR
CLARK, R A	0101160610	50-309 F	COLEMAN, A C	0101200299	50-272 Q	CORRETT, J S	0101270357	71-5
CLARK, R A	0101100484	50-335 F	COLEMAN, R	0101290696	CONTRACT	CONCERN, R L	0101200022	State
CLARK, R A	0101140458	50-309 P	COLEY, J L	0101220366*	50-566 Q	CORE, C	0101160010	PR
CLARK, R A	0101190277	50-266 F	COLLITZ, J J	0101090313*	50-289 T	CONNELL, E K	0101070531	CGMM
CLARK, R A	0101090090*	50-289 T	COLLINS, J J	0101110806	50-250 Q	CORNMAN, L	0101190065	PR
CLARK, R A	0101140475	50-283 F	COLL, N A	0101140886	50-250 Q	CORNWALL, H	0101290570	PR
CLARK, D	0101060482*	50-265 S	COLL, A	0101160261	50-387 Q	CORRADI, H L	0101290465	NUREG
CLARK, R A	0101220176	50-262 F	COLL, N A	0101160261	50-387 Q	CORREA, M A	0101210586	50-309
CLARK, R A	0101190416	50-317 P	COLL, N A	0101260503	50-250 Q	CORREA, D	0101220351	50-309
CLARK, R A	0101190500	50-330 P	COLLINS, S J	0101100194*	50-271 Q	CORREIA, C	0101270047	50-2
CLARK, R A	0101190617*	50-338 P	COLLINS, R E	0101070223*	50-267 Q	CORREA, M A	0101270735	50-2
CLARK, R A	0101190621*	50-338 P	COLLINS, S	0101160037*	50-271 Q	CORREA, M A	0101270728	50-2
CLARK, R A	0101190623	50-335 P	COLLINS, F H	0101060321*	CONTRACT	CORVELL, O P	0101090802*	50-309
CLARK, R A	0101190626*	50-335 P	COLLINS, J T	0101060105	50-320 R	CORYELL, O P	0101200144*	70-1
CLARK, S	0101120349*	50-293 S	COLLINS, J T	0101090771	50-320 R	CUSORQUE, J E	0101200144*	50-2
CLARK, R A	0101190579	50-338 P	COLMAN, L	0101190093	PR	COSTANTINO, C	0101260144	NUREG
CLARK, R A	0101290802*	50-336 P	COLMBO, R W	0101130517*	50-312 S	COSTANTINO, C	0101260163	NUREG
CLARK, R A	0101290807*	50-336 P	COLMBO, R W	0101150531*	50-312 R	COSTELLO, J R	0101150551*	QA99

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER
COSTELLO, D. J.	8101200397*	50-280 R	CREWS, J. L.	8101660081	50-312 Q	CRUTCHFIELD, D.	8101070115
COSTNER, D. P.	8101300526	PR	CREWS, J. L.	8101210396	50-312 Q	CRUTCHFIELD, D.	8101070126
COTNER, M. L.	8101120407	50-466 D	CREWS, J. L.	8101210133	50-89 Q	CRUTCHFIELD, D.	8101070153
COTNER, M. L.	8101120401	50-250 P	CREWS, J. L.	8101210110	50-397 Q	CRUTCHFIELD, D.	8101070183*
COTNER, B. P.	8101060910	50-530 Q	CRIM, E.	8101190016	PR	CRUTCHFIELD, D.	8101070577
COTTER, B. P.	8101160169	50-413 M	CRIPPLE, D.	8101150350	50-287 H	CRUTCHFIELD, D.	8101100048
COTTER, B. P.	8101160151	50-413 M	CROCKER, H. W.	8101300177*	70-1100	CRUTCHFIELD, D.	8101150333
COTTER, B. P.	8101280041	27-39	CROCKER, H. W.	8101090599	70-820	CRUTCHFIELD, D.	8101070474
COTTE, W. T.	8011250537*	50-327 S	CROCKET, L.	8101130047	50-219 P	CRUTCHFIELD, D.	8101070476
COTTE, W. T.	8101060477*	50-327 S	CROCKER, H. W.	8101280374	50-247 S	CRUTCHFIELD, D.	8101120323
COTTE, W. T.	8101070777*	50-327 S	CRENE, I.	8101260111	PR	CRUTCHFIELD, D.	8101120402
COTTE, W. T.	810113012*	50-327 S	CROSSBY, P. J.	8101050319*	50-217 S	CRUTCHFIELD, D.	8101120402
COTTE, W. T.	8101130443*	50-327 S	CROSSBY, P. J.	8101050299*	50-219 S	CRUTCHFIELD, D.	8101280441
COUTS, J. H.	8101220377*	50-438 A	CROSSBY, P. J.	8101050541*	50-219 S	CRUTCHFIELD, D.	8101260472
COUTS, J. H.	8101100508*	50-423 S	CROSSBY, P. J.	8101150695*	50-219 S	CRUTCHFIELD, D.	8101300246
COUNSILL, W. G.	8101120413*	50-245 F	CROSSBY, P. J.	8101230556*	50-219 S	CRUTCHFIELD, D.	8101070594
COUNSILL, W. G.	8101160587*	50-213 Q	CROSSBY, P. J.	8101230564*	50-219 S	CRUTCHFIELD, D.	8101070610
COUNSILL, W. G.	8101150540*	50-245 Q	CROSSMAN, W. A.	8101070361*	50-382 Q	CRUTCHFIELD, D.	8101070630
COUNSILL, W. G.	8101160560*	50-213 Q	CROSSMAN, W. A.	8101080296*	50-482 Q	CRUTCHFIELD, D.	8101120142
COUNSILL, W. G.	8101140378*	50-326 Q	CROSSMAN, W. A.	8101160178*	50-445 Q	CRUTCHFIELD, D.	8101140047
COUNSILL, W. G.	8101150028	50-213 Q	CROSSMAN, W. A.	8101160369*	50-498 Q	CRUTCHFIELD, D.	8101140805
COUNSILL, W. G.	8101150028	50-213 Q	CROSSMAN, W. A.	8101160063*	50-445 Q	CRUTCHFIELD, D.	8101140055
COUNSILL, W. G.	8101103787	50-213 Q	CROSSMAN, W. A.	8101126096*	50-382 Q	CRUTCHFIELD, D.	8101140059
COUNSILL, W. G.	8101220404	REGD	CROSSMAN, W. A.	8101160766*	50-498 Q	CRUTCHFIELD, D.	8101140065
COUNSILL, W. G.	8101100787	50-213 Q	CROSSMAN, W. A.	8101140556*	50-498 Q	CRUTCHFIELD, D.	8101140070
COUNSILL, W. G.	8101220404	REGD	CROSSMAN, W. A.	8101280530*	50-482 Q	CRUTCHFIELD, D.	8101140072
COUNSILL, W. G.	8101050447	50-213 P	CROSSMAN, W. A.	8101140500*	50-382 Q	CRUTCHFIELD, D.	8101140077
COUNSILL, W. G.	8101050468	50-336 P	CROSSMAN, W. A.	8101210075*	50-458 Q	CRUTCHFIELD, D.	8101200637
COUNSILL, W. G.	8101090002	50-213 P	CROSSMAN, W. A.	8101200508*	50-382 Q	CRUTCHFIELD, D.	8101210173
COUNSILL, W. G.	8101060310	50-213 P	CROSSMAN, W. A.	8101210377*	50-445 Q	CRUTCHFIELD, D.	8101210174
COUNSILL, W. G.	8101050076	50-336 P	CROSS, J. L.	8101126331	50-327 P	CRUTCHFIELD, D.	8101210186
COUNSILL, W. G.	8101160363	50-245 P	CROSS, J. L.	8101220383	50-327 Q	CRUTCHFIELD, D.	8101210222
COUNSILL, W. G.	8101070312	50-213 P	CROSSMAN, W. A.	8101260403	50-498 S	CRUTCHFIELD, D.	8101270130
COUNSILL, W. G.	8101070012	50-213 P	CROSS, J. L.	8101270702	50-327 P	CRUTCHFIELD, D.	8101270150
COUNSILL, W. G.	8101130138	50-213 P	CROSS, J. L.	8101260416	50-327 P	CRUTCHFIELD, D.	8101300598
CHURCHILL, W. G.	8101190031	PR	CROSS, J. L.	8101270647	50-327 P	CRUTCHFIELD, D.	8101200200
CHURCHILL, W. G.	8101090004	50-213 F	CROUSE, R. P.	81013000971*	50-346 Q	CRUTCHFIELD, D.	8101210210
CHURCHILL, W. G.	8101120237	50-213 V	CROUSE, R. P.	8101060170	50-346 Q	CRUTCHFIELD, D.	8101210229
CHURCHILL, W. G.	8101120525	50-213 P	CROUSE, R. P.	8101050626	50-346 Q	CRUTCHFIELD, D.	8101070179
CHURCHILL, W. G.	8101160248	50-213 P	CROUSE, R. P.	8101070200	50-346 Q	CRUTCHFIELD, D.	8101270720
COUNSILL, W. G.	8101090004	50-213 F	CROUSE, R. P.	8101060156	50-346 Q	CRUTCHFIELD, D.	8101230332
COUNSILL, W. G.	8101160248	50-213 P	CROUSE, R. P.	8101050531	50-346 P	CRUTCHFIELD, D.	8101230337
COUNSILL, W. G.	8101120327	50-213 P	CROUSE, R. P.	8101060568*	50-346 P	CRUTCHFIELD, D.	8101230339
COUNSILL, W. G.	8101120327	50-213 P	CROUSE, R. P.	8101060473	50-346 P	CRUTCHFIELD, D.	8101230341
COUNSILL, W. G.	8101200307	50-245 P	CROUSE, R. P.	8101090027	50-346 P	CRUTCHFIELD, D.	8101230343
COUNSILL, W. G.	8101150624	50-336 P	CROUSE, R. P.	8101200185	50-346 Q	CRUTCHFIELD, D.	8101190626
COUNSILL, W. G.	8101270712	50-213 F	CROUSE, R. P.	8101220242	50-346 P	CRUTCHFIELD, D.	8101190644
COUNSILL, W. G.	8101270712	50-213 F	CROUSE, R. P.	8101160461	50-346 P	CRUTCHFIELD, D.	8101190689
COUNSILL, W. G.	8101200293	50-336 P	CROUSE, R. P.	8101280348	50-346 Q	CRUTCHFIELD, D.	8101190704
COUNSILL, W. G.	8101270670	50-245 P	CROUSE, R. P.	8101280348	50-346 Q	CRUTCHFIELD, D.	8101190710
COUNSILL, W. G.	8101290553	50-213 S	CROUSE, R. P.	8101300554*	50-346 Q	CRUTCHFIELD, D.	8101190715
COUNSILL, W. G.	8101290265	50-245 P	CROUSE, R. P.	8101190803	50-346 P	CRUTCHFIELD, D.	8101210149
COUNSILL, W. G.	8101290219	50-245 P	CROUSE, R. P.	8101220575	50-346 P	CRUTCHFIELD, D.	8101210165
COURTIGHT, E. L.	8101270180	NURE0	CROUSE, R. P.	8101220582*	50-346 P	CRUTCHFIELD, D.	8101270134
COWING, S. J.	8101150801	NURE0	CROUSE, R. P.	8101260487	50-346 P	CRUTCHFIELD, D.	8101270142
COWAN, B. Z.	8101140931	70-2909	CROUSE, R. P.	8101230485	50-346 P	CRUTCHFIELD, D.	8101270158
COWAN, B. Z.	8101140931	70-2909	CROUSE, R. P.	8101270676	50-346 P	CRUTCHFIELD, D.	8101230445
COWSILL, C. J.	8101100244*	50-277 Q	CROUSE, R. P.	8101300603	50-346 P	CRUTCHFIELD, D.	8101230451*
COWSILL, C. J.	8101220167*	50-277 Q	CROUSE, R. P.	8101300484	50-346 P	CRUTCHFIELD, D.	8101230458*
COWSILL, C. J.	8101150691*	50-277 Q	CROUT, G. S.	8101070178*	PR	CRUTCHFIELD, D.	8101280477
CRATO, H. D.	8101190292	PR	CROUT, G. S.	8101070186*	PR	CRUTCHFIELD, D.	8101230501
CRANDALL, H. E.	8101070308*	50-187 Q	CROUT, G. S.	8101070170*	PR	CRUTCHFIELD, D.	8101230503*
CRANE, P. A.	8012290008	50-275 Q	CROUT, G. S.	8101070186*	PR	CRUTCHFIELD, D.	8101230503*
CRANE, P. A.	8101060014	50-275 Q	CRON, W. T.	8101090311*	70-1007	CRUTCHFIELD, D.	8101290525
CRANE, P. A.	8101120252	50-133 Q	CRON, W. T.	8101120548	70-824	CRUTCHFIELD, D.	8101290329
CRANE, P. A.	8101130566	50-275 Q	CRON, W. T.	8101210267	70-27	CRUTCHFIELD, D.	8101060035
CRANE, P. A.	8101070206	50-133 Q	CRON, W. T.	8101140948	40-8027	CRUTCHFIELD, D.	8101280460
CRANE, P. A.	8101120547	50-133 Q	CRON, W. T.	8101220197*	70-1257	CRUTCHFIELD, D.	8101300508
CRANE, P. A.	8101050382	50-275 Q	CRON, W. T.	8101280145	40-2061	CRUTCHFIELD, D.	8101300608
CRANE, P. A.	8101060018	50-275 Q	CRONWELL, L. A.	8101080028	PR	CRUTCHFIELD, D.	8101280414
CRANE, P. A.	8101050406	50-133 S	CRONWELL, L. A.	8101140683	PR	CRUTCHFIELD, D.	8101300077
CRANE, P. A.	8101300728*	50-275 F	CRONWELL, L. A.	8101060097	RES	CRUTCHFIELD, D.	8101300082*
CRANE, P. A.	8101220307	50-133 P	CRONWELL, L. A.	8101140113*	50-250 Q	CRUTCHFIELD, D.	8101300089*
CRANE, P. A.	8101210355	50-275 A	CRONWELL, L. A.	8101210069	PR	CRUTCHFIELD, D.	8101210337
CRANE, P. A.	8101270492	50-133 P	CRONWELL, L. A.	8101270161	RES	CRUTCHFIELD, D.	8101210346
CRANE, P. A.	8101270672	50-275 A	CRUTCHFIELD, D.	810140126	50-10 P	CRUTCHFIELD, D.	8101210347
CRANE, P. A.	8101200331	50-275 A	CRUTCHFIELD, D.	8101180019	50-155 P	CRUTCHFIELD, D.	8101210349
CRANER, E.	8101260655	PR	CRUTCHFIELD, D.	8101180034	50-245 P	CRUTCHFIELD, D.	8101220472
CRANFORD, W. T.	8101190541	FOIA	CRUTCHFIELD, D.	8101190112	50-409 P	CRUTCHFIELD, D.	8101280089
CRESSMAN, D.	8101190091	PR	CRUTCHFIELD, D.	8101300367	50-295 P	CRUTCHFIELD, D.	8101280097
CREWS, J. L.	8101100094*	50-312 Q	CRUTCHFIELD, D.	8101300377*	50-255 P	CRUTCHFIELD, D.	8101280072
CREWS, J. L.	8101100066*	50-312 Q	CRUTCHFIELD, D.	8101300390*	50-255 P	CRUTCHFIELD, D.	8101300403
CREWS, J. L.	8101210104	50-206 Q	CRUTCHFIELD, D.	8101160415	50-206 P	CRUTCHFIELD, D.	8101160426
CREWS, J. L.	8101100078	50-312 Q	CRUTCHFIELD, D.	8101290700	NURE0	CRUTCHFIELD, D.	8101300748
CREWS, J. L.	8101210612	50-275 Q	CRUTCHFIELD, D.	8101060320	50-29 P	CRUTCHFIELD, D.	8101300743

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER
CULVER, C M	8101290341*	CONTRACT	DALTROFF, S L	8101130314	50-277 P	DELF, O A	8101130112*
CULVER, M W	8101203294*	50-302 R	DANCE, H C	8101090849*	50-327 0	DELSEL, C	8101130332*
CUMMINGS, J J	8101260314*	FOIA	DANCE, H C	8101100364*	50-327 0	DELVECHIO, A	8101110351*
CUMMINGS, J J	8101260120*	FOIA	DANCE, H C	8101290370*	50-390 0	DEMPSEY, P A	8101060302*
CUMMINGS, J J	8101260105*	50-320 P	DANIELS, F T	8101120070*	50-359 0	DEMPSEY, P A	8101280222*
CUMMINGS, J J	8101260300*	FOIA	DANIELS, H A	8101090111	50-289 H	DENNING, R S	8101279102
CUMMINGS, J J	8101260237*	FOIA	DANIELSON, D H	81011100153*	50-294 0	DENNING, R S	8101260183
CUMMINGS, J J	8101260262*	FOIA	DANIELSON, D H	8101150599*	50-155 0	DENNING, R S	8101060236
CUMMINGS, J J	8101260276*	FOIA	DANIELSON, D H	8101290506*	50-346 0	DENNING, R S	8101070043
CUMMINGS, J J	8101260260*	FOIA	DANIELSON, F T	8101290543*	50-358 0	DENNING, R S	8101070043
CUMMINGS, J J	8101260247*	FOIA	DANIELSON, D H	8101230672*	50-409 0	DENNING, R S	8101270591
CUMMINGS, J J	8101140173*	50-220 P	DANIELSON, D H	8101230687*	50-374 0	DENNING, R S	8101190761
CUMMINGS, D	8101190439	PR	DANIELSON, J J	8101290122*	50-329 0	DENTON, H R	8101190015
CUMMINGHAM, R E	8101090796*	70-821	DANIELSON, D H	8101210986*	50-461 0	DENTON, H R	8101130265
CUMMINGHAM, R E	8012290515	71-9580	DANIELSON, D H	8101290438*	50-254 0	DENTON, H R	8101100133
CUMMINGHAM, R E	8012290532	71-9571	DANIELSON, D H	8101160259*	50-329 0	DENTON, H R	8012110946*
CUMMINGHAM, R E	8012290549	71-9526	DARDEN, D	8101270856	PR	DENTON, H R	8012110612*
CUMMINGHAM, R E	8012290569	71-9539	DAVIDSON, J A	8101270516*	50-348 P	DENTON, H R	8012110905
CUMMINGHAM, R E	8012290590	71-9044	DAVIDSON, D R	8101290169*	50-440 0	DENTON, H R	8012240475
CUMMINGHAM, R E	8101260130	PR	DAVIDSON-ROLLIN	8101260330	PR	DENTON, H R	8101060274
CUMMINGHAM, R G	8101140431	PR	DAVIDSON, D R	8101220121*	50-440 0	DENTON, H R	8101150583*
CUMMINGHAM, A L	8101290539*	50-518 0	DAVIDSON, D R	8101200517	50-440 0	DENTON, H R	8101120003
CUMMINGHAM, O E	8101280178	50-70 F	DAVIDSON, J J	8101100120	NUREO	DENTON, H R	8101150932
CUMMINGHAM, H E	8101270943	NUREO	DAVIDSON, D R	8101220565	50-440 5	DENTON, H R	8101070937
CURDTT, B R	8101200070	50-259 0	DAVIDSON, D R	8101220420	50-440 5	DENTON, H R	8101090540*
CURRAN, B	8101220184	PR	DAVIDSON, D R	8101300450	50-440 A	DENTON, H R	8101150779
CURRAN, J M	8101160513*	50-206 S	DAVIS, D K	8101070012*	FOIA	DENTON, H R	8101150379*
CURRAN, J M	8101210484	50-206 F	DAVIS, J J	8010160586*	50-201 0	DENTON, H R	8101150377*
CURRIE, J M	8101280620	RES	DAVIS, J J	8010230624*	10CFR	DENTON, H R	8101200167
CURTIS, N W	8101090857*	50-387 0	DAVIS, J J	8101060122*	WASTE MGT	DENTON, H R	8101090519*
CURTIS, N W	8101100076*	50-387 0	DAVIS, J J	8101090246*	COMMISSION	DENTON, H R	8101150579
CURTIS, N W	8101090071*	50-387 F	DAVIS, A B	8101200122*	46-8724	DENTON, H R	8101190630
CURTIS, N W	8101090375*	50-387 F	DAVIS, A B	8101060119*	WASTE MGT	DENTON, H R	8101150208
CURTIS, N W	8012310343	50-387 0	DAVIS, A B	8101090074*	50-255 0	DENTON, H R	8101150937
CURTIS, R T	8101210537	50-537 A	DAVIS, A B	8101070113	50-10 0	DENTON, H R	8101140237*
CURTIS, N W	8101193046*	50-387 0	DAVIS, R E	8101290090	RES	DENTON, H R	8101230290
CURTIS, H C	8101220111	PR	DAVIS, A B	8101120016*	50-155 0	DENTON, H R	8101140101
CURTIS, H W	8101190783*	50-387 S	DAVIS, A B	8101120013*	50-155 0	DENTON, H R	8101290694
CURTIS, J R	8101290574*	50-142 0	DAVIS, A B	8101140847*	50-373 0	DENTON, H R	8101290694
CURTIS, N W	8101050332	50-387 S	DAVIS, J J	8101090230	50-201 P	DENTON, H R	8101270710
CURTIS, N W	8101090703	50-387 H	DAVIS, J J	8101090779	50-201 0	DENTON, H R	8101200015
CURTIS, N W	8101130466	50-387 A	DAVIS, A B	8101150525*	50-295 0	DENTON, H R	8101210079
CURTIS, N W	8101130320	50-387 A	DAVIS, A B	8101150674*	50-295 0	DENTON, H R	8101210079
CURTIS, N W	8101270482	50-387 A	DAVIS, A B	8101150779	50-373 0	DENTON, H R	8101210079
CURTIS, N W	8101120189	50-387 K	DAVIS, A B	8101260720	50-346 0	DENTON, H R	8101210106
CURTIS, N W	8101190287	50-387 A	DAVIS, A B	8101150310	50-341 0	DENTON, H R	8101210253
CURTIS, N W	8101210362	50-387 S	DAVIS, A B	8101080399	0A979	DENTON, H R	8101210288
CURTIS, J R	8101200385	50-369 0	DAVIDSON, H T	8101070319*	50-347 A	DENTON, H R	8101210307
CURTIS, N W	8101260370	50-387 A	DAVIS, C E	8101270741	RES	DENTON, H R	8101210310
CURTIS, H W	8101270425	50-387 S	DAVIS, C E	8101290817	NUREO	DENTON, H R	8101290011
CURTIS, N W	8101280150*	50-387 A	DAVIS, A B	8101150076	50-255 0	DENTON, H R	8101290017*
CURTIS, N W	8101300500	50-387 A	DAVIS, A B	8101270960	50-155 0	DENTON, H R	8101280621
CUTCHIN, J M	8101160167	50-289 0	DAVIS, A B	8101220110	50-303 0	DENTON, H R	8101290212
CUTCHIN, J M	8101210221	50-289 T	DAVIS, C J	8101230638	50-482 0	DENTON, H R	8101300575
CUTOLO, B	8101210556	PR	DAVIS, S H	8101230540*	50-317 5	DEPAOLA, R N	8101220544
CWALINA, O	8010070600*	50-10 P	DAVIS, S H	8101300543*	50-318 5	DEPO-PED, C	8101130275
CYBULSKI, P.	8101280265	RES	DANKINS, P	8101300485	50-318 5	DERENZO, S P	8101230507*
CYBULSKI, P.	8101060636	RES	DANKIN, D H	8101140005	71-9001	DERGUE, L R	8101140134
CYBULSKI, P.	8101290691	RES	DAWSON, D H	8101230054*	70-1303	DESEIFE, S	8101250007
CZAJADOWSKI, C J	8101220637	50-298 P	DAY, G	8101260390	PR	DETTLE, R E	8101270630
D'ABRACCI, T	8101300058	PR	DAY, L R	8101220622	RES	DETULLO, H	8101280187
D'ANGELO, A J.	8101220543*	50-508 0	DEALE, V B	8101050625	50-522 0	DEVER, P J	8101300153
D'ABRACCI, T	8101200130	PR	DEALE, V B	8101070808	50-445 0	DEVINE, J B	8101100239*
D'AMLOUITZ, J M	8101270611	50-317 P	DECECCO, J M	8101230973	50-287 H	DEVINE, J B	8101120085*
D'ADONE, C	8101160563	PR	DECK, M	8101270773	PR	DEVINE, J B	8101090538*
DAILE, L C	8101230502	50-491 S	DEEDS, H E	8101090962	NUREO	DEVINE, J B	8101030532
DALE, L F	8101120009	50-416 0	DEEDS, H E	8101090965	NUREO	DEVINE, J B	8101080340*
DALE, L F	8101120123	50-416 0	DEES, K	81012140588	PR	DEVINE, J B	8101150267
DALE, L F	8101050100	50-416 A	DEGENFELDER, E	8101300192	PR	DEVINE, J B	8101120037
DALE, L F	8101060435	50-416 A	DEGUZMAN, H D	8101220376	PR	DEVINE, J B	8101140266
DALE, L F	8101290367	50-416 0	DEGUZMAN, H D	8101220376	PR	DEVINE, J B	8101140271
DALE, L F	8101130226	50-416 A	DELANEY, J C	8012100089*	70-925	DEVINE, J B	8101140275*
DALE, L F	8101150639	50-416 K	DELLELLA, A B	8101270319	50-247 0	DEVINE, J B	8101140381
DALE, L F	8101220474	50-416 0	DELEON, T D	8101150184	PR	DEVINE, J B	8101060587
DALE, L F	8101220294	50-416 A	DELENGE, L G	8101050415	50-373 5	DEVINE, J B	8101060694
DALE, L F	8101220337	50-416 A	DELENGE, L G	8101190352	50-373 K	DEVINE, J B	8101060694
DALE, L F	8101230490	50-416 A	DELENGE, L G	8101140512	50-373 A	DEVINE, J B	8101060696
DALTROFF, B L	8101100211*	50-277 0	DELENGE, L G	8101200245	50-373 A	DEVINE, J B	8101070310*
DALTROFF, S L	8101150073*	50-277 0	DELENGE, L G	8101220360	50-10 P	DEVINE, J B	8101070655*
DALTROFF, S L	8101220135*	50-277 0	DELENGE, L G	8101230433	50-373 5	DEVINE, J B	8101140625
DALTROFF, S L	8101220149*	50-277 0	DELOINGARD, H H	8101200243	50-269 H	DEVINE, J B	8101090776
DALTROFF, S L	8101100775	50-277 0	DELLA RATTIA, A	8101060747*	70-1109	DEVINE, J B	8101070781
DALTROFF, S L	8101140744	50-278 0	DELMAN, J R	8101200081	PR	DEVINE, J B	8101120192
DALTROFF, S L	8101230330*	50-277 F	DELGOS, S	8101200371*	50-315 S	DEVINE, J B	8101090584
DALTROFF, S L	8101090003	50-277 P	DELONO, S	8101290521*	50-315 S	DEVINE, J B	8101090774

[illegible]

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
EARLEY, A. F.	0101280222*	50-322 Q	EISENHUT, D. O.	0101140848	50-247 F	ERICKSON, P. B.	0101050055*	50-322
EARLEY, A. F.	0101280212	50-322 Q	EISENHUT, D. O.	0101050124	50-244 Q	ERICKSON, P. B.	0101100479*	50-322
EASEN, S.	0101200205	50-289 H	EISENHUT, D. O.	0101060420	50-3 P	ERNSF, M. L.	0101050295	REV
EASTMAN, K.	0101280237	50-490 Q	EISENHUT, D. O.	0101120542*	50-279 F	ESHELFLAN, D.	0101060924*	50-322
EASTMAN, J.	0101280338	FR	EISENHUT, D. O.	0101100046	50-220 F	ESPELSTO, M. L.	0101200477	PR
EBERLEIN, F.	0101280310	FOIA	EISENHUT, D. O.	0101220466	50-3 P	ESTES, G.	0101270824	PR
EBERT, M.	0101210280	PR	EISENHUT, D. O.	0101220466	50-3 P	EVANS, L. J.	0101260079	REV
EBNETER, S. D.	0101300107*	50-373 Q	EISENHUT, D. O.	0101220466	50-3 P	EVANS, A. F.	0101260127	50-322
EBNETER, S. D.	0101100524*	50-278 Q	EISENHUT, L. D.	0101200543	RES	EVANS, C. A.	0101100608*	50-322
EBNETER, S. D.	0101140128*	50-272 Q	EISENHUT, D. O.	0101100155	50-269 H	EVANS, N.	0101130089	PR
EBRIGHT, D. J.	0101350179	PR	EISENHUT, D. O.	0101190113	50-10 P	EWING, J. E.	0101140541	PR
EDY, U.	0101060530*	50-209 H	EISENHUT, D. O.	0101050502	50-307 L	FABRE, V. K.	0101130146	PR
ECHLE, C.	0101150510	50-403 H	EISENHUT, D. O.	0101210445	50-3 P	FABRE, L.	0101130150	PR
ECKHART, J. H.	0101300771*	50-361 Q	EISENHUT, D. O.	0101270521	50-352 H	FAHRE, T. C.	0101140232	50-322
ECKHOUT, A.	0101140885	XPORTRIC	EISENHUT, D. O.	0101150163	50-413 A	FAHRE, T. C.	0101200546	50-322
ECCONCHES, H.	0101100610*	50-553 Q	EISENHUT, D. O.	0101150171*	50-413 A	FARBER, R.	0101220154	PR
ECCONCHES, H.	0101150773*	50-369 Q	EISENHUT, D. O.	0101160421*	50-339 P	FARBER, L. A. S.	0101200084	50-322
EDDIE, E. Q.	0101070523	WASTE MOT	EISENHUT, D. O.	0101210642	50-299 P	FARBER, L. A. S.	0101070024	50-322
EDDIE, E. Q.	0101190455	PR	EISENHUT, D. O.	0101170190	50-247 H	FARBER, L. A. S.	0101070024	50-322
EDELSTEIN, D.	0101140954	XPORTRIC	EISENHUT, D. O.	0101150145	50-470 A	FARBER, L. A. S.	0101060078	50-322
EDELSTEIN, D.	0101140959*	XPORTRIC	EISENHUT, D. O.	0101150152	50-202 F	FARBER, L. A. S.	0101060078	50-322
EDGAR, G. L.	0101050506*	50-70 Q	EISENHUT, D. O.	0101190160	50-400 A	FARBER, L. A. S.	0101200154	50-322
EDGAR, G. L.	0101030515*	50-70 Q	EISENHUT, D. O.	0101190589	50-447 A	FARBER, L. A. S.	0101200154	50-322
EDGAR, G. L.	0101030494	50-70 Q	EISENHUT, D. O.	0101290355	50-247 E	FARBER, L. A. S.	0101200299	50-322
EDGAR, G. L.	0101220170	PR	EISENHUT, D. O.	0101160230	50-295 H	FARBER, L. A. S.	0101200299	50-322
EDGAR, E. C.	0101120317*	50-244 B	EISENHUT, D. O.	0101230612	FOIA	FARRAR, A. D.	0101140766*	CON
EDGAR, E. C.	0101160197	50-70 Q	EISENHUT, D. O.	0101200024	50-358 P	FARRAR, J. D.	0101130146	PR
EDGECROTH, P.	0101300330	CONTRACT	EISENHUT, D. O.	0101300251*	50-237 P	FASANO, A. N.	0101150169*	50-322
EDGECROTH, P. J.	0101210572	CONTRACT	EISENHUT, D. O.	0101300373*	50-220 P	FASANO, A.	0101200127	50-322
EDGECROTH, P. J.	0101300205	CONTRACT	EISENHUT, D. O.	0101300387*	50-293 P	FASANO, A.	0101200519	50-322
EDWARDS, J. D.	0101070298*	50-443 F	EISENHUT, D. O.	0101300375*	50-263 P	FASANO, A.	0101230524	50-322
EDWARDS, J. D.	0101300035	PR	EISENHUT, D. O.	0101300409*	50-298 P	FASANO, A. N.	0101200507	50-322
EDWARDS, R. P.	0101220173	PR	EISENHUT, D. O.	0101300411*	50-271 P	FAULKNER, B. B.	0101100103*	50-322
ECKHOUT, A.	0101100499	XPORTRIC	EISENHUT, D. O.	0101300430*	50-331 P	FAULKNER, B. B.	0101210108*	50-322
ECHENSPERGER, W.	0101260396	50-424 A	EISENHUT, D. O.	0101300460*	50-259 P	FAULKNER, B. B.	0101210570	PR
EICHLEIDINGER, C.	0101290676*	50-247 P	EISENHUT, D. O.	0101300467*	50-259 P	FAULKNER, B. B.	0101060397*	50-322
EIDSON, A. F.	0101300153	NUREO	EISENHUT, D. O.	0101300757*	50-333 P	FAULKNER, B. B.	0101210631*	50-322
EISENHUT, D. O.	0101290115	40-8302	EISENHUT, D. O.	0101260653	50-928 A	FAULKNER, B. B.	0101210158*	50-322
EISENHUT, D. O.	0101100504	50-290 P	EISENHUT, D. O.	0101220575	PR	FAULKNER, B. B.	0101200629*	50-322
EISENHUT, D. O.	0101100519	50-250 P	EL-ASHRY, H. T.	0101220411	50-259 P	FAULKNER, B. B.	0101200629*	50-322
EISENHUT, D. O.	0101100532	50-315 P	EL-ASHRY, H. T.	0101220202	50-327 E	FAY, C. W.	0101090113*	50-322
EISENHUT, D. O.	0101100549*	50-315 P	EL-ASHRY, H. T.	0101220310	50-327 S	FAY, C. W.	0101090119*	50-322
EISENHUT, D. O.	0101100563	50-280 P	EL-ASHRY, H. T.	0101230436	50-327 E	FAY, C. W.	0101140127	PR
EISENHUT, D. O.	0101100574*	50-280 P	EL-ASHRY, H. T.	0101230384	50-438 A	FAY, C. W.	0101210375*	50-322
EISENHUT, D. O.	0101100587	50-348 P	EL-ASHRY, H. T.	0101200131*	0A999	FAY, C. W.	0101210315*	50-322
EISENHUT, D. O.	0101100595*	50-348 P	ELLER, V.	0101210182	PR	FAY, C. W.	0101070570	50-322
EISENHUT, D. O.	0101100617	50-334 P	ELLIS, B.	0101050370	50-369 H	FAY, C. W.	0101050422	50-322
EISENHUT, D. O.	0101100628*	50-334 P	ELLIS, J.	0101050523	50-445 Q	FAY, C. W.	0101050448	50-322
EISENHUT, D. O.	0101100629	50-247 P	ELROD, S. A.	0101290361*	50-335 Q	FAY, C. W.	0101120333	50-322
EISENHUT, D. O.	0101100636*	50-247 P	EMERY, D. F.	0101270598*	50-247 H	FAY, C. W.	0101120367*	50-322
EISENHUT, D. O.	0101100646	50-261 P	ENGBERG, E. O.	0101290527*	70-734	FAY, C. W.	0101120201	50-322
EISENHUT, D. O.	0101100654*	50-261 P	ENGELKEN, R. H.	0101130675	50-312 Q	FAY, C. W.	0101200150	50-322
EISENHUT, D. O.	0101100660	50-286 P	ENGELKEN, R. H.	0101060687	70-1470	FAY, C. W.	0101190519*	50-322
EISENHUT, D. O.	0101100666*	50-286 P	ENGELKEN, R. H.	0101220531*	50-508 Q	FAY, C. W.	0101210589	50-322
EISENHUT, D. O.	0101100674	50-295 P	ENGELKEN, R. H.	0101050489	50-206 Q	FAY, C. W.	0101270699	50-322
EISENHUT, D. O.	0101100680*	50-295 P	ENGELKEN, R. H.	0101090496	50-312 Q	FAY, C. W.	0101270710*	50-322
EISENHUT, D. O.	0101100690	50-272 P	ENGELKEN, R. H.	0101090498	50-344 Q	FAY, C. W.	0101150517	50-322
EISENHUT, D. O.	0101100693*	50-272 P	ENGELKEN, R. H.	0101090503	50-528 Q	FAY, C. W.	0101270574*	50-322
EISENHUT, D. O.	0101100700	50-305 P	ENGELKEN, R. H.	0101090504	50-133 Q	FAY, C. W.	0101270560	50-322
EISENHUT, D. O.	0101100706*	50-309 P	ENGELKEN, R. H.	0101090510	50-397 Q	FAY, C. W.	0101270564*	50-322
EISENHUT, D. O.	0101100737	50-3 P	ENGELKEN, R. H.	0101060681	70-2908	FAY, C. W.	0101260410	50-322
EISENHUT, D. O.	0101090387	50-3 F	ENGELKEN, R. H.	0101150022	50-273 Q	FAY, C. W.	0101260340	50-322
EISENHUT, D. O.	0101090449	50-277 F	ENGELKEN, R. H.	0101150025	50-344 Q	FAY, C. W.	0101270666	50-322
EISENHUT, D. O.	0101090453	50-302 F	ENGELKEN, R. H.	0101150027	50-312 Q	FAZIO, P. V.	0101290057	50-322
EISENHUT, D. O.	0101100424	50-3 P	ENGELKEN, R. H.	0101150632	50-206 Q	FAZIO, P. V.	0101290057	50-322
EISENHUT, D. O.	0101050485	50-298 F	ENGELKEN, R. H.	0101150835	50-508 Q	FEDERMAN, J.	0101230003	PR
EISENHUT, D. O.	0101100043	50-263 F	ENGELKEN, R. H.	0101150837	50-460 Q	FEE, W. F.	0101120413*	50-322
EISENHUT, D. O.	0101100058	50-271 F	ENGELKEN, R. H.	0101150638	50-928 Q	FEE, W. F.	0101150540*	50-322
EISENHUT, D. O.	0101100061	50-344 F	ENGELKEN, R. H.	0101130103	50-133 Q	FEE, W. F.	0101290219	50-322
EISENHUT, D. O.	0101120535	50-295 F	ENGELKEN, R. H.	0101130110	50-397 Q	FELDRINGER, J. M.	0101200349	50-322
EISENHUT, D. O.	0101130124	50-282 F	ENGELKEN, R. H.	0101090775	50-133 Q	FETERABEND, C.	0101200303*	50-322
EISENHUT, D. O.	0101130132	50-309 F	ENGELKEN, R. H.	0101070784	50-397 Q	FELDER, T.	0101280415	PR
EISENHUT, D. O.	0101130134	50-335 F	ENGELKEN, R. H.	0101090164	50-397 Q	FELTON, J. M.	0101290730	PR
EISENHUT, D. O.	0101130136	50-317 F	ENGELKEN, R. H.	0101090166	50-133 Q	FELT, R.	0101300635	50-322
EISENHUT, D. O.	0101130139	50-293 F	ENGELKEN, R. H.	0101100635	50-312 F	FELDER, J. E.	0101150293	PR
EISENHUT, D. O.	0101130142	50-368 F	ENGELKEN, R. H.	0101100638	50-206 F	FELDEN, F.	0101160270	PR
EISENHUT, D. O.	0101130165	50-272 F	ENGELKEN, R. H.	0101100940	50-344 F	FELDMAN, J. H.	0101290726	50-322
EISENHUT, D. O.	0101130170	50-315 F	ENGELKEN, R. H.	0101100947	50-273 F	FELTON, J. M.	0101210252	50-322
EISENHUT, D. O.	0101130184	50-250 F	ENGELKEN, R. H.	0101270459	50-528 Q	FELTON, J. M.	0101070529*	50-322
EISENHUT, D. O.	0101130717	50-280 F	ENGLE, L. B.	0101270267	HTSC	FELTON, J. M.	0101090267	50-322
EISENHUT, D. O.	0101140822	50-349 F	ENTWISLE, E. B.	0101270782	50-170 Q	FELTON, J. M.	0101070551	50-322
EISENHUT, D. O.	0101140827	50-286 F	ENTWISLE, E. B.	0101270622	50-170 Q	FELTON, J. M.	0101080244	50-322
EISENHUT, D. O.	0101140830	50-261 F	EPSTEIN, R.	0101140595	PR	FELTON, J. M.	0101120405	50-322
EISENHUT, D. O.	0101140836	50-334 F	ERB, C. M.	0101210038*	50-461 Q	FELTON, J. M.	01012100302	50-322
EISENHUT, D. O.	0101140841	50-303 F	ERB, C. M.	0101160259*	50-329 Q	FELTON, J. M.	0101220437	50-322

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
DEVINE, J. S.	B101090467	XPORTLIC	DIGGS, R. H.	B101090353	50-298 P	DOHERTY, J. F.	B101090314	50-466
DEVINE, J. S.	B101130496	XPORTLIC	DIGGS, R. H.	B101090314*	50-272 P	DOHERTY, J. F.	B101090665	50-466
DEVINE, J. B.	B101100950	XPORTLIC	DIGGS, R. H.	B101070593	50-260 F	DOHERTY, J. F.	B101160184	50-465
DEVINE, J.	B101086977	50-259 A	DIGGS, R. H.	B101140601	50-313 P	DOHERTY, J. F.	B101270289	50-465
DEVINE, J. B.	B101070470	XPORTLIC	DIGGS, R. H.	B101080104	50-272 P	DOHERTY, J. F.	B101280273	50-466
DEVINE, J. D.	B101100670	XPORTLIC	DIGGS, R. H.	B101090441	50-244 F	DOHERTY, J. F.	B101280325	50-466
DEVINE, J. B.	B101100460	XPORTLIC	DIGGS, R. H.	B101190377	50-322 A	DONALDSON, H. H.	B101140487	PR
DEVINE, J. C.	B101100940	XPORTLIC	DIGGS, R. H.	B101070328	50-443 A	DONALDSON, H. H.	B101260207	PR
DEVINE, J. B.	B101130411	XPORTLIC	DIGGS, R. H.	B101100234	50-228 F	DONAT, T. J.	B101070159*	50-369
DEVINE, J. C.	B101130419	XPORTLIC	DIGGS, R. H.	B101100240	50-70 F	DONALDSON, W. J.	B101070451*	50-223
DEVINE, J. B.	B101140260*	XPORTLIC	DIGGS, R. H.	B101200093	50-57 F	DONALDSON, W. J.	B101070455*	50-223
DEVINE, J. C.	B101140492	XPORTLIC	DIGGS, R. H.	B101140595	50-324 P	DONALDSON, W. J.	B101100419	50-220
DEVINE, J. B.	B101140905*	XPORTLIC	DIGGS, R. H.	B101070389*	50-29 P	DONALDSON, W. J.	B101100428*	50-220
DEVINE, J. B.	B101150337	XPORTLIC	DIGGS, R. H.	B101210140	50-335 P	DONALDSON, W. J.	B101070448	50-220
DEVINE, J. B.	B101150625	XPORTLIC	DIGGS, R. H.	B101150408*	50-260 P	DONALDSON, W. J.	B101070450*	50-220
DEVINE, J. B.	B101150473*	XPORTLIC	DIGGS, R. H.	B101260473*	50-222 A	DONNELLY, L. J.	B101260135*	50-452
DEVINE, J. B.	B101150461*	XPORTLIC	DIGGS, R. H.	B101260082*	50-335 P	DONNEAU, A. K.	B101270374	PR
DEVINE, J. B.	B101270441	XPORTLIC	DIGGS, R. H.	B101280171*	50-70 F	DONOHUE, O. J.	B101200594	70-1821
DEVINE, J. C.	B101100521*	XPORTLIC	DIGNAN, T. G.	B101280091	50-443 G	DORAN, H. A.	B101130122*	XPORTLIC
DEVINE, J. B.	B101100551*	XPORTLIC	DIGNAN, T. G.	B101280091	50-443 G	DORAN, H. A.	B101190382	XPORTLIC
DEVINE, J. B.	B101130423*	XPORTLIC	DILLANNI, D. C.	B101120253	50-346 P	DORAN, H. A.	B101190557	XPORTLIC
DEVINE, J. C.	B101130433*	XPORTLIC	DILLINGHAM, M.	B101230346	PR	DORNET, C.	B10113031*	PR
DEVINE, J. B.	B101150256	XPORTLIC	DIMGLIO, A. F.	B101090093	50-193 P	DOUGHERTY, D. J.	B101050334*	40-1341
DEVINE, J. B.	B101260124*	XPORTLIC	DINERSTEIN, R. S.	B101210016	PR	DOUGHERTY, D. J.	B101060770*	50-320
DEVINE, J. C.	B101270076	XPORTLIC	DIPAZZA, R. P.	B101270495	70-6800	DOUGHERTY, D. J.	B101100307*	CONFIRAC
DEVINE, J. B.	B101200540	XPORTLIC	DIRCKS, W. J.	B101210563*	FOIA	DOUGHERTY, D. J.	B101200473*	CONFIRAC
DEVINE, J. B.	B101100499*	XPORTLIC	DIRCKS, W. J.	B101220144*	FOIA	DOUGHERTY, D. J.	B101210553	CONFIRAC
DEVINE, J. C.	B101190751*	XPORTLIC	DIRCKS, W. J.	B101070156*	FOIA	DOUGHERTY, D. J.	B101210550	CONFIRAC
DEVINE, J. C.	B101270205*	XPORTLIC	DIRCKS, W. J.	B101260267*	FOIA	DOUGHERTY, H. R.	B101260216	50-267
DEVINE, J. B.	B101270232*	XPORTLIC	DIRCKS, W. J.	B101260255*	FOIA	DOWNARD, T. R.	B101270249	40-3493
DEVINE, J. B.	B101200453*	XPORTLIC	DIRCKS, W. J.	B101060596*	10CFR	DOYLE, E. H.	B101270286	PROJ
DEVINE, J. B.	B101200460*	XPORTLIC	DIRCKS, W. J.	B101140762	50-344 H	DOYLE, H. K.	B101270286	PROJ
DEVINE, J. B.	B101210580*	XPORTLIC	DIRCKS, W. J.	B101090759	COMMISSION	DRAPEL, Q. H.	B101050370*	50-265
DEVINE, J. U.	B101210614	XPORTLIC	DIRCKS, W. J.	B101230181	SECY	DRAPER, E. L.	B101100176*	50-458
DEVINCENZI, J.	B101230477	G	DIRCKS, W. J.	B101270483*	10CFR	DRAPER, E. L.	B101210670	50-458
DEVINE, J. B.	B101290460	XPORTLIC	DIRCKS, W. J.	B101040646	COMMISSION	DRAPER, E. L.	B101210672	50-458
DEVINE, J. B.	B101270650	XPORTLIC	DIRCKS, W. J.	B101060044	COM			

EASLEY, A. F.	0101280212	50-322	G	EISENHUT, D. G.	0101050124	50-244	P	ERICKSON, D. B.	0101030039	50-3
EASEN, S.	0101200205	50-289	H	EISENHUT, D. G.	0101050124	50-244	P	ERICKSON, P. B.	0101030039	50-3
EASTMAN, A.	0101210029	50-498	G	EISENHUT, D. G.	0101050124	50-244	P	ERICKSON, P. B.	0101030039	50-3
EASTMAN, J.	0101280337	PR		EISENHUT, D. G.	0101120542	50-295	F	ERICKSON, M. L.	0101030039	50-3
					0101160646	50-220	F	ESPINOZA, H. L.	0101280429	PR
EEBLEIN, F.	0101280410	FDIA		EISENHUT, D. G.	0101280466	50-3	P	EVANS, G.	0101280429	PR
EGERT, M.	0101210280	PR		EISENHUT, D. G.	0101280466	50-3	P	EVANS, L. J.	0101280429	PR
EGNETER, S. D.	0101300107	50-333	G	EISENHUT, D. G.	0101280466	50-3	P	EVANS, C. A.	0101280429	PR
EGNETER, S. D.	0101100524	50-278	G	EISENHUT, D. G.	0101300543	465		EVANS, C. A.	0101280429	PR
EGNETER, S. D.	0101140120	50-272	G	EISENHUT, D. G.	0101100135	50-269	H	EVANS, N.	0101130165	PR
EBRIGHT, D. J.	0101300179	PH		EISENHUT, D. G.	0101190113	50-10	P	EWING, J. E.	0101140541	PR
EBY, U.	0101060530	50-289	H	EISENHUT, D. G.	0101050592	50-387	E	FABRE, J. V. K.	0101130146	PR
ECHELE, C.	0101150510	50-483	H	EISENHUT, D. G.	0101210449	50-3	P	FABRE, L.	0101130150	PR
ECQUARDT, J. H.	0101320771	50-361	G	EISENHUT, D. G.	0101070621	53-352	H	FABRE, T. C.	0101140232	50-3
EDKUCHT, A.	0101140085	XPORTRIC		EISENHUT, D. G.	0101150163	50-413	A	FABRE, T. C.	0101280429	PR
EDMONDS, H.	0101100410	50-553	G	EISENHUT, D. G.	0101190171	50-413	A	FABRE, R.	0101280154	PR
EDMONDS, H.	0101190773	50-369	G	EISENHUT, D. G.	0101160421	50-359	P	FARNELL, A. S.	0101070284	50-3
EDDIE, D. O.	0101070523	WASTE MOT		EISENHUT, D. G.	0101210642	50-259	P	FARNELL, A. S.	0101070284	50-3
EDLEMAN, H.	0101190455	PR		EISENHUT, D. G.	0101190130	50-247	H	FARNELL, A. S.	0101070284	50-3
EDLSTEIN, B.	0101140954	XPORTRIC		EISENHUT, D. G.	0101150145	50-470	A	FARNELL, A. S.	0101070284	50-3
EDLSTEIN, B.	0101140959	XPORTRIC		EISENHUT, D. G.	0101150152	50-302	P	FARNELL, A. S.	0101070284	50-3
EDGAR, G. L.	0101050506	50-70	G	EISENHUT, D. G.	0101190168	50-480	A	FARNELL, A. S.	0101280154	50-3
EDGAR, G. L.	0101050515	50-70	G	EISENHUT, D. G.	0101190589	50-447	A	FARNELL, A. S.	0101280154	50-3
EDGAR, G. L.	0101050494	50-70	G	EISENHUT, D. G.	0101190555	50-247	S	FARNELL, A. S.	0101280279	50-3
EDGAR, G. L.	0101220170	PR		EISENHUT, D. G.	0101160560	50-295	H	FARNELL, A. S.	0101280279	50-3
EDGAR, E. C.	0101120317	50-244	G	EISENHUT, D. G.	0101280612	FDIA		FARRAR, A. D.	0101140796	PR
EDGAR, G. L.	0101160197	50-70	G	EISENHUT, D. G.	0101280612	50-338	P	FARRAR, J. D.	0101280382	50-3
EDGECRATH, P.	0101300307	CONTRACT		EISENHUT, D. G.	0101300234	50-237	P	FARRAR, A. H.	0101150137	50-3
EDGEMORTH, P. J.	0101210572	CONTRACT		EISENHUT, D. G.	0101300373	50-230	P	FASANO, A.	0101280124	50-3
EDGEMORTH, P. J.	0101300205	CONTRACT		EISENHUT, D. G.	0101300289	50-293	P	FASANO, A.	0101280124	50-3
EDWARDS, J. D.	0101070298	50-445	F	EISENHUT, D. G.	0101300395	50-263	P	FASANO, A.	0101280524	50-3
EDWARDS, L. D.	0101300305	PR		EISENHUT, D. G.	0101300407	50-298	P	FASANO, A. H.	0101280524	50-3
EDWARDS, R. P.	0101220173	PR		EISENHUT, D. G.	0101300411	50-271	P	FAULKNER, B. H.	0101103103	50-3
EEDKHOUT, J.	0101100497	XPORTRIC		EISENHUT, D. G.	0101300430	50-331	F	FAULKNER, B. H.	0101280508</	

					ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER
					8101290513	50-317 F	FIORELLI, C	
					8101290624	50-134 W	FIORELLI, O	8101290624
					8101290640	50-209 F	FIORELLI, O	8101290640
					8101203072	50-10 H	FIORELLI, O	8101203072
					8101140643	PR	FIORELLI, O	8101140643
					8101260621	PR	FIORELLI, O	8101260621
					8101050498	50-280 H	FIORELLI, O	8101050498
					8101220614	PR	FIORELLI, O	8101220614
					8101160436	50-339 P	FIORELLI, O	8101160436
					8101300269	PR	FIORELLI, O	8101300269
					8101190560	PR	FIORELLI, O	8101190560
					8101050620	40-1341	FIORELLI, O	8101050620
					8101140353	50-327 J	FIORELLI, G	8101140353
					8101200177	PR	FIORELLI, G	8101200177
					8101190442	PR	FIORELLI, G	8101190442
					8101270316	PR	FIORELLI, G	8101270316
					8101160091	CONTRACT	FIORELLI, G	8101160091
					8101090469	50-438 J	FIORELLI, G	8101090469
					8101090517	50-438 J	FIORELLI, G	8101090517
					8101090526	50-327 J	FIORELLI, G	8101090526
					8101090567	50-327 J	FIORELLI, G	8101090567
					8101090406	50-299 J	FIORELLI, G	8101090406
					8101090490	50-299 J	FIORELLI, G	8101090490
					8101090535	50-350 J	FIORELLI, G	8101090535
					8101090647	50-299 J	FIORELLI, G	8101090647
					8101090658	50-390 J	FIORELLI, G	8101090658
					8101090457	50-335 J	FIORELLI, G	8101090457
					8101090464	50-335 J	FIORELLI, G	8101090464
					8101090466	50-302 J	FIORELLI, G	8101090466
					8101090475	50-302 J	FIORELLI, G	8101090475
					8101090478	50-250 J	FIORELLI, G	8101090478
					8101050556	50-375 J	FIORELLI, G	8101050556
					8101090561	50-302 J	FIORELLI, G	8101090561
					8101090566	50-327 J	FIORELLI, G	8101090566
					8101090571	50-290 J	FIORELLI, G	8101090571
					8101090601	50-340 J	FIORELLI, G	8101090601
					8101090462	50-395 J	FIORELLI, G	8101090462
					8101090481	50-290 J	FIORELLI, G	8101090481
					8101090542	50-375 J	FIORELLI, G	8101090542
					8101090550	50-321 J	FIORELLI, G	8101090550
					8101090690	50-321 J	FITZGERALD, J A	8101090690
					8101090695	50-321 J	FITZGERALD, J A	8101090695
					8101140233	50-321 J	FITZGERALD, J A	8101140233
					8101200439	PR	FITZGERALD, J A	8101200439
					8101280447	FOIA	FITZGERALD, J A	8101280447
					8101080172	50-219 C	FITZGERALD, J A	8101080172
					8101090263	50-219 C	FITZGERALD, J A	8101090263
					8101140938	50-219 C	FITZGERALD, J A	8101140938
					8101140607	50-219 C	FITZGERALD, J A	8101140607
					8101050377	50-219 C	FITZGERALD, J A	8101050377
					8101050117	50-219 C	FITZGERALD, J A	8101050117
					8101050211	50-219 C	FITZGERALD, J A	8101050211
					8101050227	50-219 C	FITZGERALD, J A	8101050227
					8101050252	50-219 C	FITZGERALD, J A	8101050252
					8101050469	50-219 C	FITZGERALD, J A	8101050469
					8101160404	50-219 F	FITZGERALD, M J	8101160404
					8101090334	50-219 F	FITZGERALD, M J	8101090334
					8101120216	50-219 F	FITZGERALD, M J	8101120216
					8101130377	50-219 V	FITZGERALD, M J	8101130377
					8101160465	50-219 P	FITZPATRICK, D E	8101160465
					8101160471	50-219 P	FITZPATRICK, D E	8101160471
					8101150492	50-219 S	FITZPATRICK, D E	8101150492
					8101150690	50-219 S	FITZPATRICK, D E	8101150690
					8101239546	50-219 S	FLANNIGAN, R	8101239546
					8101230951	50-219 S	FLANNIGAN, R	8101230951
					8101230660	50-219 S	FLANNIGAN, R	8101230660
					8101230549	50-219 S	FLANNIGAN, R	8101230549
					8101260981	50-217 S	FLANNIGAN, R	8101260981
					8101280083	50-219 R	FLANNIGAN, R	8101280083
					8101190159	FOIA	FLANNIGAN, R	8101190159
					8101260670	50-313 F	FLANNIGAN, R	8101260670
					8101260593	50-299 F	FLANNIGAN, R	8101260593
					8101260714	50-321 F	FLANNIGAN, R	8101260714
					8101260730	50-295 F	FLANNIGAN, R	8101260730
					8101280440	FOIA	FLANNIGAN, R	8101280440
					8101270171	FOIA	FLANNIGAN, R	8101270171
					8101280355	50-247 P	FLANNIGAN, R	8101280355
					8101280355	50-247 P	FLANNIGAN, R	8101280355
					8101280432	FOIA	FLANNIGAN, R	8101280432
					8101280431	FOIA	FLANNIGAN, R	8101280431
					8101280608	FOIA	FLANNIGAN, R	8101280608
					8101280409	FOIA	FLANNIGAN, R	8101280409
					8101290594	50-269 F	FLANNIGAN, R	8101290594
					8101300722	50-275 F	FLANNIGAN, R	8101300722
					8101290593	50-244 F	FLANNIGAN, R	8101290593

PERSONAL ACTION INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
FCSTER, J. E.	8101276506*	50-346 O	GARRETT, P.	0101230269	PR	GLOVER, F. A.	8101233187	50-2
FCSTER, R.	8101160598	PR	GARRITY, J. H.	8101220340	50-309 P	GLOVER, W. H.	8101279741	RES
FCULSHAM, P. A.	8101060565	50-293 J	GARRITY, J. H.	8101271368	50-309 P	GOINY, A. T.	8101156195*	50-2
FOX, C. D.	8101279069*	50-461 O	GARRITY, J. H.	8101296402	50-309 R	GOISY, A. T.	8101153164*	50-2
FOX, O. F.	8101230510*	0A999	GARRITY, J. H.	8101330532	50-309 F	GOETZ, M. H.	8101226524	PR
FOX, O. O.	8101050072	50-369 O	GARVEY, J. J.	8101303586	50-238 R	GOFF, D. L.	8101220399	PR
FRALEY, R. F.	8012100059*	50-592 A	GARY, R. J.	8101270117	50-445 O	GOLD, R. L.	8101210553	CONF
FRAZ, F.	8101140391	50-466 O	GARY, R. J.	8101100726*	50-445 O	GOLDBERG, S. C.	8101050031	50-2
FRAZ, S. D.	8101300840	PR	GARY, R. J.	8101270814	50-445 O	GOLDBERG, S. C.	8101050034	50-2
FRANK, F. D.	8101150328*	CONTRACT	GARY, R. J.	8101100736*	50-445 O	GOLDBERG, J. H.	8101090623	50-4
FRANZ, W.	8101200271*	50-206 P	GARY, R. J.	8101270152	50-445 O	GOLDBERG, S. C.	8101050527	50-3
FRASER, D.	8101160130	PR	GARY, R. J.	8101270137	50-445 O	GOLDBERG, S. C.	8101140230	50-3
FRASER, D. A.	8101210466	50-327 E	GARY, R. J.	8101050318	50-445 A	GOLDBERG, S. C.	8101214203	50-3
FREDERICK, E. J.	8101150590	RES	GARY, R. J.	8101200242	50-445 A	GOLDBERG, S. C.	8101226462	50-1
FREDERICK, E. J.	8101290679	RES	GARY, R. J.	8101200246	50-445 S	GOLDBERG, S. C.	8101276370	50-3
FREEMAN, F.	8101210203	PR	GARY, R. J.	8101200253	50-445 S	GOLDBERG, J. R.	8101296276	PROJ
FREEMAN, R. L.	8101200375	50-259 O	GAUL, R. W.	8101130135*	50-29 P	GOLDEN, J. C.	8101220374*	50-1
FRENCH, L. D.	8101300726*	50-27 S	GAY, O. M.	8101130037	50-445 G	GOLDEN, J. C.	8101290751*	50-1
FREUD, C.	8101210107	PR	GAY, O. M.	8101130037	50-445 G	GOLDMAN, H. L.	8101100211	State
FRIEDLANDER, J.	8012240355	State Prog	GEARS, G.	8101140398*	50-587 G	GOLDMAN, A.	8101232276	PR
FRIEDLAND, D. A.	8101170526	PR	GEHR, A. C.	8101050562	50-275 G	GOLDSMITH, R.	8101220439	50-1
FRIEDEL, F. C.	8101080370	71-401	GEHR, A. C.	8101080018	50-275 G	GOLDSMITH, R.	8101190574	PR
FRIEDEL, F. C.	8101080376*	71-401	GEHR, A. C.	8101050382	50-275 G	GOLDSMITH, J.	8101270579	PR
FRIEDEL, F. C.	8101140152	71-9032	GEHR, A. C.	8101080018	50-275 G	GOLDSMITH, R.	8101210637*	ORG
FRIEDMAN, P.	8101150143	PR	GEHR, A. C.	8101260301	50-275 G	GOLDSMITH, R.	8101210637*	ORG
FRIED, D.	8101190059	PR	GEHR, A. C.	8101280620	50-275 G	GOLLO, J.	8101080721	50-1
FRIEDMAN, S.	8101260605	PR	GEHR, A. C.	8101280620	50-275 G	GOMER, D. A.	8101200596	1000
FRIEDMAN, S.	8101220429*	50-346 B	GELM, C.	8101150160	PR	GOMILAS, E.	8101230031	PR
FROST, S. R.	8101220186*	50-255 O	GEKIN, S.	8101230302	PR	GONZALEZ, G.	8101133255	PR
FROST, S. R.	8101060630	50-155 S	GEORGE, K. D.	8101140446	PR	GODFREY, A. C.	8101050918	50-4
FROST, S. R.	8101060668	50-155 S	GERETY, H. F.	8101270753	50-219 J	GODDARD, B.	8101060526*	50-2
FUNK, D. S. K.	8101300768	NUREQ	GERSTNER, H. C.	8101060731*	50-461 O	GODMAN, L. S.	8101050380*	50-4
FUNK, D. S. K.	8101270692	NUREQ	GETTLER, F. H.	8101090724	REF00	GODMAN, L. S.	8101050371*	50-4
FULLER, J. K.	8101070602	50-267 F	GETTY, B. C.	8101050410*	50-133 S	GODMAN, L. S.	8101060583*	50-4
FUNKERBURO, R. D.	8101140084	State Prog	GIBBONS, T. D.	8101100609*	50-321 O	GODMAN, L. S.	8101140494*	50-4
FUNK, K.	8101210435	PR	GIBSON, T. R.	8101050384	50-329 O	GODWIN, H. L.	8101260134	70-1
FURBUSH, M. H.	8101260301	50-275 O	GIBBS, D. C.	8101160693*	PR	GODMAN, W. D.	8101060032	PR
FURBUSH, H. H.	8101280620	50-275 O	GIBSON, A. F.	8101100693*	50-302 O	GORDON, B.	8101190583	PR
FURR, B. J.	8101050184	50-261 O	GIBSON, G. T.	8101080210*	50-250 O	GOREN, B.	8101210135	PR
FURR, B. J.	8101050638	50-324 O	GIBSON, A. F.	8101150017*	50-369 O	GOREN, J. E.	8101200264	50-2
FURR, B. J.	8101070620	50-324 O	GIBSON, R. B.	8101290105*	CONTRACT	GROSS, C.	8101150205	PR
FURR, B. J.	8101120289	50-261 O	GIDDO, R. O.	8101100600	NUREQ	GROSSICK, L. V.	8101260327*	FOIA
FLAIR, B. J.	8101160005	50-324 O	GIESEKE, J. A.	8101070276	TOPREP	GROSSICK, L. V.	8101260319*	FOIA
FURR, B. J.	8101220412	50-261 O	GILBERT, L. D.	8101100170*	50-445 A	GOTCHY, R. L.	8101230355	50-3
FUSCHEN, O.	8101220392	PR	GILBERT, L. D.	8101140356*	50-498 O	GOTTESFELD, P.	8101190587	PR
GAETON, W.	8101200464	PR	GILBERT, D. E.	8101160702*	50-202 O	GOWER, J.	8101260574	PR
GAFFNEY, E.	8101160075	PR	GILBERT, D. E.	8101070212	50-202 O	GRAEBER, K. L.	8101140471	50-2
GAONON, K.	8101260237	PR	GILBERT, D. E.	8101130118	50-243 O	GRAEBER, K. L.	8101050340	50-3
GAHM, J. H.	8101140489*	50-267 R	GILBERT, D. E.	8101190274	50-243 O	GRAEBER, K. L.	8101120338	50-2
GAHM, J. H.	8101140630*	50-267 S	GILBERT, D. E.	8101140156	50-243 O	GRAEBER, K. L.	8101120336	50-2
GAHM, J. H.	8101140646*	50-267 S	GILBERT, D. E.	8101200145	50-202 O	GRAEBER, K. L.	8101130461	50-2
GAHM, J. H.	8101210410	50-267 S	GILBERT, D. E.	8101200170	50-243 O	GRAEBER, K. L.	8101130451	50-2
GAHM, J. H.	8101210408*	50-267 S	GILBERT, D. E.	8101220390	50-202 O	GRAEBER, K. L.	8101130550	50-3
GAHM, J. H.	8101220421*	50-267 S	GILBER, M. L.	8101080379*	50-305 O	GRAEBER, K. L.	8101130562	50-3
GALLARDI, E.	8101230264	PR	GILINSKY, V.	8101260113*	50-320 P	GRAEBER, K. L.	8101130458	50-2
GALLAGHER, J. H.	8101270728	50-277 P	GILINSKY, V.	8101060052	COMMISSION	GRAEBER, K. L.	8101270730	50-2
GALLEN, K. P.	8101050506*	50-70 O	GILLELAND, J. E.	8101270231*	40-1341	GRAM, P.	8101080392*	CFM
GALLEN, K. P.	8101030506*	50-70 O	GILLELAND, J. E.	8101270251*	40-1341	GRANIER, J. A.	8101300250	PR
GALLEN, K. P.	8101050515*	50-70 O	GILLELAND, J. E.	8101270234*	40-1341	GRANT, W. B.	8101300361*	50-2
GALLEN, K. P.	8101050515*	50-70 O	GILMAN, F. M.	8101140723	NUREQ	GRANT, M.	8101210188	70-8
GALLO, R. M.	8101090649*	50-387 O	GILMAN, J. D.	8101090609*	TOPREP	GRASSO, E.	8101270892*	COM
GALLO, R.	8101150861*	50-387 O	GILMORE, L. W.	8101280150*	50-244 P	GRAVEL, D. T.	8101220255	RES
GALLO, J.	8101090684	PR	GILMORE, L. W.	8101120332*	50-244 P	GRAVELLE, O.	8101290688	PR
GALLO, J.	8101160209	50-155 O	GILMORE, L. W.	8101120342*	50-244 P	GRAVES, R. H.	8101220408	50-2
GALLUCCIO, J.	8101300497	PR	GILMORE, J.	8101270733*	50-255 S	GRAVES, R. H.	8101210576	50-2
GAMBLE, D. H.	8101260173*	FOIA	GINSBERG, T.	8101270222	50-537 A	GRAY, J. R.	8101210656	50-4
GAMMILL, W. P.	8101080007	50-289 P	GINSBERG, T.	8101220654	50-537 A	GRAY, J. R.	8101150103*	50-2
GANO, W. G.	8101210523	TOPREP	GINSBERG, T.	8101270545	50-537 A	GRAY, J. R.	8101190788*	50-2
GANO, W. G.	8101230380	TOPREP	GINSBERG, T.	8101220625	RES	GRAY, J. R.	8101090370	50-5
GANLEY, D. E.	8101220629*	70-371	GINSBERG, T.	8101270065	50-537 A	GRAY, J. R.	8101160550	50-4
GANLEY, D. E.	8101220584*	70-371	GINSBERG, T.	8101260758	50-537 A	GRAY, J. R.	8101140215	50-2
GANLEY, D. E.	8101220577*	70-371	GERARDOT, D. C.	8101100699*	CONTRACT	GRAY, J. R.	8101210204	50-2
GANNIS, S.	8101120196*	50-275 H	GIRON, M. P.	8101160535	PR	GRAY, J. R.	8101210192	50-2
GANNIS, S.	8101280435	FOIA	GISCORBE, A.	8101220282*	PR	GRAYBILL, D.	8101150222	PR
GARCIA, P. J.	8101120154*	40-1162	GITTINGS, E.	8101140610	PR	GREENE, O. A.	8101060107	RES
GARCIA, P. J.	8101120151	40-1162	GLADSTAR, R.	8101150179	PR	GREENMAN, E. G.	8101090688*	50-2
GARCIA, P. J.	8101290043	40-3453	GLADOLA, A. F.	8101060764	50-320 P	GREENMAN, E. G.	8101150558*	50-3
GARCIA, P. J.	8101270054	40-1162	GLADOLA, A. F.	8101200488	CONTRACT	GREENMAN, E. G.	8101160135*	50-3
GARDNER, E. F.	8101050157*	50-289 T	GLADOLA, A. F.	8101160080	CONTRACT	GREENMAN, E. G.	8101160087*	50-2
GARDNER, R. N.	8101140151*	50-461 G	GLADOLA, A. F.	8101200455	CONTRACT	GREENMAN, E. G.	8101150585*	50-2
GARDNER, E. F.	8101050098*	50-289 T	GLADOLA, A. F.	8101290525	CONTRACT	GREENMAN, E. G.	8101220169*	50-2
GARRAHY, J. J.	8101060440*	COMMISSION	GLASSBERO, B.	8101190468	PR	GREENMAN, E. G.	8101300619*	50-2
GARRAHY, J. J.	8101060436*	COMMISSION	GLASSER, L.	8101270844	PR	GREENMAN, E. G.	8101220546*	50-2
GARRAHY, J. J.	8101060436*	COMMISSION	GLEISCHAKER, D.	8101140949	50-275 G	GREEN, H. J.	81011296376	50-3
GARRATT, P.	8101200224	PR	GLQVER, F. A.	8101130400*	50-267 P	GREENE, O. A.	8101260758	50-5

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
GREENE, S	B101130197	PS	GRIER, B H	B101050136	50-219 G	GUMBLE, F W	B101070621*	50-28
GREENMAN, S	B101230204	PR	GRIER, B H	B101050140	50-293 G	GUMBLE, F W	B101270722*	50-28
GREEN, H	B101150425	PR	GRIER, B H	B101050147	50-333 G	GUPPY, J O	B101230209	50-28
GREEN, H J	B101450525	50-327 S	GRIER, B H	B101050144	50-220 G	GUPPY, J O	B101230209	RES
GREEN, H J	B101050715	50-259	GRIER, B H	B101050145	50-245 G	GUPPY, J O	B101220057	RES
GREEN, H J	B101070374	50-327 S	GRIER, B H	B101050149	50-377 P	GUPPY, J O	B101210537	50-53
GREENMAN, E	B101090524	50-271 S	GRIER, B H	B101165046	50-334 P	GUPPY, J O	B101210585	RES
GREEN, H J	B101090677	50-259 S	GRIER, B H	B101190221	70-820	GUPPY, J O	B101220053	RES
GREEN, D	B101130651*	50-259 R	GRIER, B H	B101210215	50-220 G	GUSTON, W H	B101220216	50-36
GREEN, H J	B101150600	50-327 S	GRIER, D H	B101060811	50-266 G	GUSTAVE, R P	B101050200	CONTR
GREEN, H J	B101130429	50-240 S	GRIER, B H	B101060916	50-272 G	GUSTAFSON, B	B1011303110	PR
GREEN, H J	B101130457	50-327 S	GRIER, B H	B101060821	50-209 G	GUSTAVE, R P	B101140835	CONTR
GREEN, H J	B101130369	50-296 S	GRIER, B H	B101060824	50-412 G	GUSTAVE, R P	B101100392	CONTR
GREEN, H J	B101150640	50-270 S	GRIER, B H	B101060829	50-485 G	GUSTAVE, R P	B101090695	CONTR
GREEN, H J	B101160477	50-327 S	GRIER, D H	B101060833	50-516 G	GUSTAVE, R P	B101150217	CONTR
GREEN, H J	B101190593	50-259 S	GRIER, B H	B101060836	50-336 G	GUSTAVE, R P	B101150229	CONTR
GREEN, H J	B101190606	50-296 S	GRIER, B H	B101060840	50-263 G	GUSTAVE, R P	B101150286	CONTR
GREEN, H J	B101130309	50-259 S	GRIER, D H	B101060843	50-244 G	GUTHRIE, G L	B101100857	WRES
GREEN, H J	B101210066	50-327 S	GRIER, B H	B101060847	50-29 G	GUTHRIE, G L	B101220501	WRES
GREEN, H J	B101170490	50-260 S	GRIER, B H	B101050649	50-443 G	GUTHRIE, G L	B101220603	WRES
GREEN, H J	B101210449	50-327 S	GRIER, B H	B101060851	50-3 G	GUTIERREZ, J M	B101050532	50-57
GREEN, H J	B101220495	50-327 S	GRIER, B H	B101060855	50-213 G	GUTIERREZ, J M	B101290142	50-49
GREEN, H J	B101220511	50-327 S	GRIER, B H	B101060860	50-309 G	GUTIERREZ, J M	B101300022	50-49
GREEN, H J	B101163506	50-259 S	GRIER, B H	B101060870	50-317 G	GUTHMAN, R	B101220129	PR
GREEN, H J	B101220444	50-260 S	GRIER, B H	B101060879	50-334 G	GUTHMAN, J	B101070281	50-29
GREEN, H J	B101220525	50-327 S	GRIER, B H	B101165206	70-820	GUY, C A	B101210240	PR
GREEN, H J	B101270572	50-296 S	GRIER, B H	B101160410	70-820	GWYN, T P	B101220070*	50-35
GREEN, H J	B101270668	50-296 S	GRIER, B H	B101050116	50-333 G	GWYN, T P	B101290563*	50-35
GREEN, H J	B101270713	50-296 S	GRIER, B H	B101060123	50-352 G	HAAS, D J	B101140934	WRES
GREEN, H J	B101270725	50-296 S	GRIER, B H	B101060129	50-322 G	HAASS, W P	B101090765	PR
GREEN, H J	B101300507	50-327 S	GRIER, B H	B101060131	50-273 G	HAASS, W P	B1012150262*	CONTR
GREEN, H J	B101300503	50-260 S	GRIER, B H	B101060134	50-219 G	HAASS, W P	B101090870	CONTR
GREEN, H J	B101300511	50-276 G	GRIER, B H	B101060136	50-277 G	HAASS, W P	B101100020	50-41
GREEN, H J	B101300670	50-259 S	GRIER, B H	B101050130	50-327 G	HAASS, W P	B101190235	CONTR
GREEN, H J	B101300682	50-296 S	GRIER, B H	B101060139	50-245 G	HADER, R	B101220322	PR
GREEN, H J	B101300504	50-296 S	GRIER, B H	B101050142	50-410 G	HADDIX, K F	B101210199	PR
GREEN, H J	B101300611	50-296 S	GRIER, B H	B101060144	50-271 G	HADDIX, D	B101270735	PR
GREGG, L R	B101300511*	50-255 G	GRIER, B H	B101060145	50-354 G	HADLEY, K	B101270757	PR
GREGORY, P V	B101270131	WRES	GRIER, B H	B101060148	50-220 G	HAGAN, T F	B101060313	CONTR
GREGORY, W S	B101160808	WRES	GRIER, B H	B101160101	50-309 G	HAGAN, T F	B101090873	CONTR
GREGORY, W S	B101290135	RES	GRIER, B H	B101070942	50-219 G	HAGEY, H	B101100321	CONTR
GRIENER, F C	B101140259	PR	GRIER, B H	B101070044	50-322 G	HAGEY, H	B101150205	CONTR
GRIDLEY, R L	B101130317	WRES	GRIER, B H	B101070047	50-410 G	HAGUE, R L	B101190651*	50-26
GRIER, B H	B101150155*	50-219 G	GRIER, B H	B101070050	50-334 G	HAIG, C	B101270449	PR
GRIER, B H	B101150646*	50-271 G	GRIER, B H	B101070052	50-293 G	HAINES, H	B101290419	50-36
GRIER, B H	B101260782*	70-135	GRIER, B H	B101070055	50-352 G	HAIRFIELD, K J	B101130357	50-230
GRIER, B H	B101090325	50-320 S	GRIER, B H	B101070058	50-380 G	HAIRSTON, C A	B101050220	40-134
GRIER, B H	B101050697	50-206 P	GRIER, B H	B101070060	50-271 G	HAIRSTON, C A	B101060764	50-320
GRIER, B H	B101100335	50-293 P	GRIER, B H	B101070062	50-333 G	HAIRSTON, C	B101070321	CONTR
GRIER, B H	B101100440	50-317 P	GRIER, B H	B101070064	50-220 G	HAIRSTON, C A	B101220045	CONTR
GRIER, B H	B101100081	50-333 F	GRIER, B H	B101070066	50-245 G	HAIRSTON, W O	B101090856	50-264
GRIER, B H	B101060887	50-219 G	GRIER, B H	B101070069	50-277 G	HAIRSTON, C	B101220489	CONTR
GRIER, B H	B101060885	50-309 G	GRIER, B H	B101130090	50-333 G	HAIRSTON, C	B101300307	CONTR
GRIER, B H	B101060883	50-334 G	GRIER, B H	B101130091	50-271 G	HAIRSTON, C	B101160080	CONTR
GRIER, B H	B101060890	50-3 G	GRIER, B H	B101130095	50-277 G	HAIRSTON, C	B101160091	CONTR
GRIER, B H	B101070340	50-213 G	GRIER, B H	B101130097	50-293 G	HAIRSTON, C	B101210572	CONTR
GRIER, B H	B101070390	50-293 G	GRIER, B H	B101130059	50-245 G	HAIRSTON, C	B101300300	CONTR
GRIER, B H	B101070371	50-317 G	GRIER, B H	B101130101	50-219 G	HAIRSTON, C	B101300295	CONTR
GRIER, B H	B101070597	50-465 G	GRIER, B H	B101130103	50-220 G	HAIRSTON, C	B101220455	CONTR
GRIER, B H	B101070395	50-443 G	GRIER, B H	B101150775	50-354 G	HAIRSTON, C	B101210037	CONTR
GRIER, B H	B101070396	50-354 G	GRIER, B H	B101150830	50-352 G	HAIRSTON, W O	B101210485*	50-354
GRIER, B H	B101070398	50-352 G	GRIER, B H	B101150805	50-380 G	HAIRSTON, W O	B101210521*	50-348
GRIER, B H	B101070400	50-287 G	GRIER, B H	B101150808	50-410 G	HAIRSTON, C	B101220060	27-39
GRIER, B H	B101070403	50-410 G	GRIER, B H	B101150812	50-322 G	HAIRSTON, W O	B101130608*	50-348
GRIER, B H	B101070404	50-516 G	GRIER, B H	B101190358	50-244 F	HAIRSTON, C	B1012206525	CONTR
GRIER, B H	B101070407	50-322 G	GRIER, B H	B101190381	50-443 G	HAIRSTON, C	B101160105	CONTR
GRIER, B H	B101070409	50-363 G	GRIER, B H	B101210131	50-213 F	HAIRSTON, W O	B101210430*	50-348
GRIER, B H	B101070411	50-417 G	GRIFFIN, M	B101210178	PR	HAIRSTON, W O	B101220291*	50-348
GRIER, B H	B101070413	50-29 G	GRIMES, B K	B101070782*	50-10 P	HAIRSTON, W O	B101220295*	50-348
GRIER, B H	B101070414	50-271 G	GRIMES, B K	B101050388*	50-275 G	HAIST, D P	B101220643*	50-505
GRIER, B H	B101070415	50-244 G	GRIMES, B K	B101190248	OR0	HALE, C J	B101150460*	04599
GRIER, B H	B101070418	50-272 G	GRICE, R H	B101070584*	50-309 F	HALE, C J	B101150429*	04599
GRIER, B H	B101070419	50-333 G	GRICE, R H	B101200249	50-271 P	HALE, C J	B101150851*	04599
GRIER, B H	B101070421	50-286 G	GRICE, R H	B101270667	50-309 P	HALE, C J	B101230510*	04599
GRIER, B H	B101070423	50-277 G	GROSS, L	B101190637	PR	HALL, R E	B101100178*	50-445
GRIER, B H	B101070425	50-245 G	GROSSMAN, H	B101070010	50-395 G	HALL, R E	B101100269*	50-495
GRIER, B H	B101070427	50-220 G	GROSSMAN, H	B101150008	50-367 G	HALL, R E	B101120076*	50-382
GRIER, B H	B101070428	50-289 G	GROSSMAN, H	B101160726	50-367 G	HALL, R E	B101100766*	50-495
GRIER, B H	B101150140	50-219 G	GROSSMAN, H	B101230091	50-155 G	HALL, R E	B101140596*	50-498
GRIER, B H	B101050118	50-352 G	GROSSMAN, H	B101260224*	50-367 G	HALL, R E	B101210675*	50-498
GRIER, B H	B101050121	50-354 G	GROTHENHUIS, M	B101230558	50-250 P	HALL, R E	B101220508*	50-382
GRIER, B H	B101050125	50-322 G	GRUBB, W B	B101140555	PR	HALL, D	B101150222	PR
GRIER, B H	B101050128	50-410 G	GRUBER, L E	B101060534*	50-284 H	HALL, L F T	B101190247	PR
GRIER, B H	B101050130	50-387 G	GRUNT, J	B101230340	PR	HALL, L F T	B101300263	PR
GRIER, B H	B101050134	50-271 G	GULDEMAN, W G	B101150651*	50-266 G	HALL, R E	B101090204	50-458

HALPERN, J. E.	B101303209	REC'D	PAYNES, J. Q.	B101070218	71-9111	HENDRICK, J. H.	B011193627	SEC
HALTERMAN, H. L.	B101270057	50-70 C	HAYNES, R. C.	B101220543	50-508 Q	HENDRICK, J. M.	B011196641	SEC
HAMIL, K.	B101090866	40-B743	HAYNES, R. C.	B101330771	50-261 Q	HENDRICK, J. M.	B011196657	SEC
HAMILIN, D. R.	B101305824	RES	HAYNES, J. Q.	B101130620	50-206 Q	HENDRICK, J. M.	B101280376	50-2
HAMNETT, P.	B101210234	PR	HAYNES, R. C.	B101270646	50-397 Q	HENDRIX, B.	B101190334	PR
HANAUER, S. H.	B101140129	10CFR	HAYNES, J. Q.	B101160504	50-206 S	HENDRICKSEN, A.	B101210071	PR
HANCHETT, J. Q.	B101190120	50-275 H	HAYNES, J. Q.	B101210132	50-206 Q	HENDRICK, J. H.	B101100003	CONF
HANCHETT, J. Q.	B101170286	50-275 H	HAYNES, J. Q.	B101050376	50-206 V	HENDRICK, J. H.	B101140763	CONF
HANCHETT, J. Q.	B101200209	50-275 H	HAYNES, J. Q.	B101060313	50-206 V	HENDRICKS, J. F.	B101260217	PR
HANCOCK, J. A.	B101070245	REGSD	HAYNES, J.	B101270511	50-205 Q	HENDRICK, J. H.	B101270637	PR
HANCOCK, J. A.	B101090603	50-302 S	HAYNES, J. Q.	B101060024	50-205 Q	HERBY, J. J.	B101160212	PR
HANCOCK, J. A.	B101090614	50-302 S	HAYNE, H.	B101190161	50-275 H	HERBY, L. O.	B101260173	50-5
HANCOCK, J. A.	B101090590	50-302 S	HAYNE, A. J.	B101170089	WASTE MOT	HERZELING, L. C.	B101140714	PR
HANCOCK, J. A.	B101160430	50-302 S	HAYNE, A. J.	B101270158	WASTE MOT	HERPES, J.	B101230310	PR
HANCOCK, J. A.	B101160556	50-302 S	HAYNE, A. J.	B101270394	WASTE MOT	HERREMAN, S.	B101200153	PR
HANCOCK, J. A.	B101170454	50-302 S	HAYNE, A. J.	B101270167	WASTE MOT	HERRT, A. R.	B101090313	50-5
HANCOCK, J. A.	B101210512	50-302 S	HEAD, W. J.	B101220501	40-7059	HERBT, A. R.	B101190113	50-5
HANCOCK, V. J.	B101230444	50-466 D	HEAD, G. F.	B101300638	50-424 A	HERBT, A. R.	B101150774	50-5
HANCOCK, J. A.	B101230417	50-302 B	HEARNE, T. J.	B101260192	50-402 Q	HERBT, A. R.	B101230166	50-5
HAYES, D.	B101270432	PR	HEARNE, T. J.	B101260102	50-482 C	HERBT, A. R.	B101140113	50-2
HAYLEY, K.	B101260594	PR	HEBERT, J. A.	B101220249	REG	HERIG, H.	B101200531	PR
HAYMER, R. U.	B101210590	50-395 D	HEDEMAN, W. H.	B101120173	50-320 F	HERKINS, P. H.	B101120070	50-5
HAYMAH, S.	B101300467	PR	HEDEMAN, W. H.	B101080042	PR	HERL, H. D. H.	B101210345	40-6
HAYMAH, D.	B101090070	50-294 S	HEDEMAN, H.	B101210004	PR	HERMAN, A. A.	B101230165	50-5
HAYMAH, E. J.	B101160147	COMMISSION	HEIDEL, S. A.	B101210193	PR	HERMAN, A. A.	B101280326	50-5
HAYMAH, E. J.	B101160159	COMMISSION	HEIDER, L. H.	B101390052	50-271 Q	HERMANDEZ, C.	B101200771	50-5
HAYMAH, E. J.	B101160135	COMMISSION	HEIDEL, C. H.	B101090009	50-341 K	HERMANDEZ, V. A.	B101090607	50-5
HAYMAH, E. J.	B101160172	COMMISSION	HEIDER, L. H.	B101090533	50-271 P	HERMANDEZ, V. A.	B101090628	50-5
HAYMAH, E. J.	B101160124	COMMISSION	HEIDER, L. H.	B101160447	50-271 P	HERMANDEZ, V. A.	B101070597	50-5
HAYMAH, E. J.	B101290405	10CFR	HEIDER, L. H.	B101300315	50-271 P	HERMANDEZ, V. A.	B101160646	50-5
HAYMAH, E. J.	B101290679	50-311 T	HEIDER, L. H.	B101300487	50-271 P	HERMANDEZ, V. A.	B101190454	50-5
HAYSEN, L. E.	B101200007	71-9070	HEIMAN, W. J.	B101150150	50-267 H	HERMANDEZ, V. A.	B101230455	50-5
HAYSEN, W. A.	B101220516	50-403 Q	HEIMAN, D.	B101190756	XPORTRIC	HEAR, R. K.	B101080509	50-4
HAYSEN, L. E.	B101140139	XPORTRIC	HEINEMANN, J. M.	B101270452	50-250 P	HEBRICK, R. H.	B101200157	50-5
HAYSEN, L. J.	B101200016	71-9145	HEINEMANN, J. M.	B101300408	50-361 Q	HEINICH, H. H.	B101090129	XPORTRIC
HAYSEN, L. J.	B101270143	71-9111	HEISHMAN, R. F.	B101160340	50-223 Q	HESS, P. W.	B101070008	50-5
HAYSEN, L. J.	B101270133	71-9145	HEISHMAN, R. F.	B101100202	50-305 Q	HESS, R. A.	B101120292	RES
HAYSEN, L. J.	B101270137	71-9145	HEISHMAN, R. F.	B101130374	50-373 Q	HEYER, R. S.	B101060146	40-6
HAYSEN, O. H.	B101060909	50-352 H	HEISHMAN, R. F.	B101120066	50-358 Q	HEYER, R. S.	B101200175	40-6
HARDT, B.	B101080412	50-466 Q	HEISHMAN, R. F.	B101160152	50-304 Q	HICKNEY, C. R.	B101140574	90-3
HARDY, M. P.	B101150134	FOIA	HEISHMAN, R. F.	B101070170	50-255 Q	HICKMAN, J. W.	B101270106	RES
HARDY, M. P.	B101150127	FOIA	HEISHMAN, R. F.	B101120019	50-315 Q	HICKSTAND, D. S.	B101280320	50-4
HARLAN, H. F.	B101160308	PR	HEISHMAN, R. F.	B101140524	50-305 Q	HICHT, C. H.	B101270470	WASTE
HARMON, D. W.	B101120023	XPORTRIC	HEISHMAN, R. F.	B101300740	50-266 S	HICHT, C. H.	B101270475	WASTE
HARMON, D. W.	B101140070	XPORTRIC	HEISHMAN, R. F.	B101080079	50-254 Q	HICGINS, J. C.	B101100042	50-3
HARMON, D. W.	B101160210	XPORTRIC	HEISHMAN, R. F.	B101140071	50-275 Q	HICGINS, B.	B101190243	PR
HARRAH, G.	B101200277	50-245 R	HEISHMAN, R. F.	B101090770	50-10 Q	HILCENBRAND, P.	B101210769	40-8
HARRISON, J.	B101190197	50-247 H	HEISHMAN, R. F.	B101140504	50-263 Q	HILL, K.	B101190452	PR
HARRISON, J.	B101190202	50-247 H	HEISHMAN, R. F.	B101090160	50-255 Q	HILL, A. O.	B101200956	50-5
HARRISON, J.	B101190207	50-247 H	HEISHMAN, R. F.	B101090234	50-254 Q	HILLIER, M. A.	B101130010	FOIA
HARRISON, J.	B101190214	50-247 H	HEISHMAN, R. F.	B101160181	50-266 Q	HILLIARD, E. R.	B101150499	50-4
HARRISON, J. J.	B101100378	50-546 Q	HEISHMAN, R. F.	B101100153	50-205 Q	HILLMAN, R. E.	B101230087	50-2
HARRISON, J. J.	B101060306	50-546 Q	HEISHMAN, R. F.	B101150646	50-266 Q	HICKLEY, D. D.	B101150169	50-2
HARRIS, J. R.	B101160604	50-412 Q	HEISHMAN, R. F.	B101160374	50-151 Q	HIND, J. A.	B101050590	70-2
HARRISON, J. J.	B101290166	50-546 Q	HEISHMAN, R. F.	B101160368	50-151 Q	HIND, J. A.	B101060090	50-2
HARRISON, P.	B101060546	50-220 S	HEISHMAN, R. F.	B101150658	50-373 Q	HIND, J. A.	B101160326	50-2
HARRISON, P.	B101070504	50-220 S	HEISHMAN, R. F.	B101150654	50-373 Q	HIND, J. A.	B101060205	50-3
HARRINGTON, W. F.	B101070502	50-286 F	HEISHMAN, R. F.	B101210641	50-409 Q	HIND, J. A.	B101130006	50-2
HARRISON, P.	B101120069	50-220 S	HEISHMAN, R. F.	B101290444	50-331 Q	HIND, J. A.	B101230198	50-2
HARRISON, P.	B101150694	50-220 S	HEISHMAN, R. F.	B101210640	50-409 Q	HIND, J. A.	B101290376	50-1
HARRINGTON, W. F.	B101300466	50-286 F	HEISHMAN, R. F.	B101290550	50-358 Q	HIND, J. A.	B101500500	50-3
HART, R.	B101200321	PR	HEISHMAN, R. F.	B101300788	50-155 Q	HIND, J. A.	B101300520	50-3
HART, P.	B101270528	WASTE MOT	HEISHMAN, R. F.	B101200791	50-159 Q	HINES, E.	B101290770	50-3
HARTMAN, A.	B101260336	PR	HEISHMAN, R. F.	B101210651	50-346 Q	HINES, B.	B101190039	PR
HARTMAN, C. J.	B101130229	50-159 R	HEISHMAN, R. F.	B101290428	50-235 Q	HINES, E.	B101290006	50-3
HARTUNG, L.	B101280033	WASTE MOT	HEISHMAN, R. F.	B101290567	50-202 Q	HINMAN, S. L.	B101220594	PR
HARTZMAN, M.	B101220626	RES	HEISHMAN, R. F.	B101210650	50-346 Q	HIRSCH, M.	B101190311	PR
HARTZLER, E.	B101220136	PR	HEISHMAN, R. F.	B101300276	50-282 Q	HOAG, K. J.	B101260104	PR
HARVEY, N.	B101300552	PR	HEISHMAN, R. F.	B101210645	50-346 Q	HOAGLAND, K. E.	B101130047	50-2
HARWOOD, R.	B101050345	50-304 S	HEISHMAN, R. F.	B101300743	50-266 S	HOCH, N. J.	B101210002	PR
HASLAM, E. F.	B101200640	QA999	HEISHMAN, R. F.	B101210242	50-313 P	HOCKER, H. H.	B101280235	50-2
HASSELL, D. F.	B101280402	50-247 P	HEISHMAN, R. F.	B101210625	50-358 A	HOCKER, H. H.	B101280275	50-2
HASTINGS, E.	B101230247	PR	HEISHMAN, R. F.	B101220190	50-255 Q	HOCKING, O.	B101150134	FOIA
HASTINGS, E. H.	B101290645	PR	HEISHMAN, R. F.	B101300551	50-346 Q	HOCKING, O.	B101150127	FOIA
HAWLAND, P. E.	B101050267	50-202 P	HEISHMAN, R. F.	B101300566	50-346 Q	HODGES, J. W.	B101100320	50-1
HAWERKAMP, D.	B101280524	50-289 S	HEISHMAN, R. F.	B101300574	50-254 Q	HODGE, A. H.	B101130319	PR
HAWERKAMP, D. R.	B101280507	50-289 S	HEISLER, H.	B101130207	PR	HODGES, J. H.	B101090480	50-5
HAWILLAND, C.	B101260348	PR	HELLER, J. K.	B101070181	50-255 Q	HODGES, O. R.	B101009809	50-5
HAWKINS, F. C.	B101210104	50-546 Q	HELLER, J. K.	B101290432	50-255 Q	HODGES, O. R.	B101230566	50-5
HAWKINS, E. F.	B101150876	HISC	HELM, K.	B101100909	XPORTRIC	HOFBERG, S. J.	B101200126	50-2
HAYES, D. W.	B101140151	50-461 Q	HENDERSON, T. K.	B101120296	50-29 P	HOFFMAN, D. P.	B101040171	50-3

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER
HOFFMAN, D P	0101080124	50-155 Q	HOVEY, G K	0101210340	50-320 P	HUNTER, R S	0101190512
HOFFMAN, D P	0101080134	50-155 Q	HOVEY, G K	0101230534	50-320 P	HUNTER, R S	0101280510
HOFFMAN, D P	0101070653	50-255 Q	HOVEY, G K	0101230613	50-320 P	HUNTER, R S	0101230549
HOFFMAN, D P	0101150079	50-255 Q	HOVEY, G K	0101230974	50-320 S	HUNTER, R S	0101260379
HOFFMAN, D P	0101200209	50-255 Q	HOVEY, G K	0101270637	50-320 S	HUNTER, R S	0101270350
HOFFMAN, D P	0101290683	50-155 Q	HOVEY, G K	0101290493	50-320 P	HUNTER, R S	0101300494
HOFFMAN, D P	0101050576	50-155 F	HOWE, J	0101190717	PR	HURST, J	0101260613
HOFFMAN, D P	0101210609	50-155 Q	HOWELL, S H	0101200198	REGD	HUSEBY, D	0101130615
HOFFMAN, D P	0101270654	50-155 Q	HOWELL, R M	0101090631	50-387 Q	HUSEBY, D F	0101230540
HOFFMAN, D P	0101210574	50-155 Q	HOWER, J	0101150207	PR	HACOBEL, F	0101070497
HOFFMAN, D P	0101260730	50-255 F	HOWETT, O P	0101230413	50-336 R	IAHURNO, H	0101190670
HOFFMAN, D P	010114031A	50-255 P	HOYLE, J C	0101300770	50-302 Q	IDEMER, K	0101140595
HOFFMAN, D P	0101200339	50-155 S	HOYLE, J C	0101300378	ACRS	IFFLAND, R R	0101260296
HOFFMAN, D P	0101130416	50-255 P	HOYLE, J C	0101300781	ACRS	IFFLAND, R R	0101260303
HOFFMAN, D P	0101130518	50-155 S	HOYLE, J C	0101300793	ACRS	IFFLAND, R R	0101270736
HOFFMAN, D P	0101120318	50-255 P	HOYLE, J C	0101300804	ACRS	IFFLAND, R R	0101270744
HOFFMAN, D P	0101220395	50-255 Q	HOYLE, J C	0101300658	ACRS	IMBODEN, E	0101200160
HOFFMAN, D P	0101120224	50-155 P	HOYLE, J C	0101300800	ACRS	IMBRO, E V	0101150366
HOFFMAN, D P	0101130386	50-155 P	HOYLE, J C	0101300660	50-209 Q	IMBRO, E V	0101160175
HOFFMAN, D P	0101210415	50-155 S	HOYLE, J C	0101300767	ACRS	IMPRESCIA, R J	0101210278
HOFFMAN, D P	0101200304	50-255 R	HOYLE, J C	0101300848	ACRS	INGRAM, F L	0101120191
HOFFMAN, D P	0101220234	50-155 P	HOYLE, J C	0101300765	50-289 Q	INNERE, A H	0101190502
HOFFMAN, D P	0101230533	50-255 S	HOYLE, J C	0101300775	ACRS	IPPOLITO, T A	0101060336
HOFFMAN, D P	0101230477	50-255 S	HOYLE, J C	0101300633	ACRS	IPPOLITO, T A	0101050474
HOFFMAN, D P	0101230533	50-155 S	HOYLE, A	0101060787	CONTRACT	IPPOLITO, T A	0101100030
HOFFMAN, D P	0101270373	50-155 P	HOYLE, A E	0101200426	CONTRACT	IPPOLITO, T A	0101120373
HOFFMAN, D P	0101280073	50-155 P	HOYLE, J C	0101200382	50-395 M	IPPOLITO, T A	0101100022
HOFFMAN, D P	0101270231	50-155 Q	HPU, Y Y	0101120355	NUREQ	IPPOLITO, T A	0101070166
HOFFMAN, D P	0101290358	50-155 P	HUBBARD, H W	0101140556	50-498 Q	IPPOLITO, T A	0101070162
HOFFMAN, D P	0101290523	50-155 S	HUBBARD, H W	0101280403	50-458 S	IPPOLITO, T A	0101120278
HOFFMAN, A	0101150173	PR	HUBBARD, H W	0101130273	PR	IPPOLITO, T A	0101120279
HOLDE, K	0101220253	PR	HUBBARD, H W	0101130335	PR	IPPOLITO, T A	0101120283
HOLDEN, R D	0101060109	50-332 Q	HUBBARD, H W	0101100194	50-271 Q	IPPOLITO, T A	0101090896
HOLLEY, F	0101160332	PR	HUBSON, S	0101220450	50-220 Q	IPPOLITO, T A	0101100712
HOLLAND, D	0101330200	PR	HUBSON, S	0101220450	50-220 Q	IPPOLITO, T A	0101100717
HOLLAND, D	0101060617	50-237 S	HUBSON, O D	0101160034	50-263 F	IPPOLITO, T A	0101100731
HOLLIDAY, D	0101130274	PR	HUBSON, T B	0101280585	50-498 Q	IPPOLITO, T A	0101210532
HOLLWAY, C J	0101120002	50-452 A	HUBSON, T B	0101280985	50-498 Q	IPPOLITO, T A	0101210539
HOLLWAY, C J	0101120609	50-580 A	HUBSON, T B	0101230192	50-498 Q	IPPOLITO, T A	0101210550
HOLLWAY, C J	0101210031	50-592 A	HUBSON, T B	0101230196	50-498 Q	IPPOLITO, T A	0101210236
HOLLWAY, D	0101120301	REGD	HUBSON, T B	0101280572	50-498 Q	IPPOLITO, T A	0101210543
HOLLIES, E	0101200173	PR	HUBSON, T B	0101230192	50-498 Q	IPPOLITO, T A	0101210557
HOLLIES, J L	0101270572	PR	HUBSON, T B	0101230196	50-498 Q	IPPOLITO, T A	0101210571
HOLLIES, M S	0101140457	50-280 F	HUBSON, T B	0101280577	50-498 Q	IPPOLITO, T A	0101220451
HOLLIV, D	0101300196	70-135	HUBBEL, J G	0101290193	RES	IPPOLITO, T A	0101290033
HOLLWAY, C F	0101220260	RES	HUYER, L J	0101120018	50-155 Q	IPPOLITO, T A	0101290040
HOLLWAY, C F	0101220643	RES	HUYER, L J	0101150919	50-341 Q	IPPOLITO, T A	0101290052
HOLLWAY, C F	0101290682	RES	HUGHES, J	0101080284	50-440 Q	IPPOLITO, T A	0101230503
HOLT, R R	0101280376	50-247 P	HUGHES, G	0101150213	PR	IPPOLITO, T A	0101190391
HOLT, J	0101300556	PR	HUGHES, J	0101270491	50-440 Q	IPPOLITO, T A	0101300629
HOLT, J	0101270047	50-247 Q	HUKILL, H D	0101060632	50-289 Q	IPPOLITO, T A	0101300233
HOLT, P P	0101090445	NUREQ	HUKILL, H D	0101080103	50-289 Q	IPPOLITO, T A	0101300358
HORN, A L	0101120359	NUREQ	HUKILL, H D	0101140581	50-289 Q	IPPOLITO, T A	0101300379
HORCO, D	0101120243	50-329 A	HUKILL, H D	0101140960	50-289 Q	IPPOLITO, T A	0101300386
HORCO, D	0101100740	50-329 A	HUKILL, H D	0101050133	50-289 T	IPPOLITO, T A	0101300396
HORCO, D	0101100322	50-329 A	HUKILL, H D	0101050230	50-289 S	IPPOLITO, T A	0101300402
HORCO, D	0101140815	50-329 A	HUKILL, H D	0101290692	50-289 F	IPPOLITO, T A	0101300417
HOPKINS, B	0101120034	50-315 Q	HUKILL, H D	0101060405	50-289 F	IPPOLITO, T A	0101300753
HOPKINS, B J	0101150271	PR	HUKILL, H D	0101230312	50-289 P	IPPOLITO, T A	0101300646
HOPKINS, T R	0101200222	PR	HUKILL, H D	0101210379	50-289 P	IPPOLITO, T A	0101200271
HORAK, W C	0101210585	RES	HUKILL, H D	0101210574	50-289 Q	IRELAND, J H	0101220250
HORIN, W A	0101050178	50-445 Q	HUKILL, H D	0101210587	50-289 P	IRELAND, J H	0101220332
HORIN, W A	0101050478	50-445 Q	HUKILL, H D	0101210670	50-289 R	IRELAND, J H	0101260462
HORIN, W A	0101160233	50-445 Q	HUKILL, H D	0101260507	50-289 P	IRWIN, M	0101260583
HORIN, W A	0101160233	50-445 Q	HUKILL, H D	0101270592	50-289 P	IRWIN, D	0101230284
HORN, R	0101220157	PR	HUKILL, H D	0101270605	50-289 Q	IRWIN, D P	0101270305
HOROWITZ, J	0101230621	PR	HUKILL, H D	0101270640	50-289 P	IRWIN, B	0101290585
HOSFORD, S B	0101290632	NUREQ	HUKILL, H D	0101270674	50-289 P	IRWIN, D P	0101270315
HOSAEER, R P	0101070485	REGD	HUKILL, H D	0101270721	50-289 S	ISHERWOOD, D	0101300229
HOSSLER, D	0101190136	PR	HUKILL, H D	0101290657	50-289 P	ISLEY, T	0101060705
HOUSE, D R	0101160142	COMMISSION	HUKILL, H D	0101290662	50-289 P	ISLEY, T	0101060745
HOUSTON, H D	0101140944	NUREQ	HUKILL, H D	0101290755	50-289 P	ISLEY, T	0101060757
HOVEY, G K	0101050071	50-320 H	HUNNICUTT, D M	0101070244	50-285 Q	ISOLA, S C	0101200161
HOVEY, G K	0101140760	50-320 Q	HUNNICUTT, D M	0101100236	50-313 Q	ISRAEL, S	0101200389
HOVEY, G K	0101140662	50-320 S	HUNSTAD, A A	0101120277	50-282 R	JABLON, R A	0101090340
HOVEY, G K	0101140730	50-320 Q	HUNSTAD, A A	0101270658	50-282 S	JABLON, R A	0101090360
HOVEY, G K	0101050039	50-289 P	HUNTER, D M	0101260561	PR	JABLON, R A	0101090368
HOVEY, G K	0101050054	50-320 H	HUNTER, D R	0101150195	50-219 Q	JABLON, R A	0101090360
HOVEY, G K	0101050174	50-320 S	HUNTER, V H	0101260054	0A999	JACKMAN, T H	0101260375
HOVEY, G K	0101050419	50-320 S	HUNTER, R S	0101140146	PR	JACKSON, T J	0101300151
HOVEY, G K	0101140650	50-320 S	HUNTER, R S	0101120268	50-315 Q	JACKSON, T J	0101300740
HOVEY, G K	0101190344	50-320 V	HUNTER, R S	0101120315	50-315 Q	JACKSON, R	0101190712
HOVEY, G K	0101230573	50-320 P	HUNTER, R S	0101300073	50-315 Q	JACKSON, J L	0101300217
HOVEY, G K	0101190482	50-320 S	HUNTER, R S	0101090461	50-315 F	JACOBY, M S	0101060104
HOVEY, G K	0101210541	50-320 P	HUNTER, R S	0101130217	50-315 P	JACOBS, A H	0101230387

PERSONAL ACTION INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
JACOBS, A	8101210374	CONTRACT	JACKES, W C	8101140513	50-289 P	KERBLUSEK, S	8101160625	50-
JAKUBEN, L	8101210564	PR	JONES, W C	8101150636*	50-289 P	KERBLUSEK, S	8101290485	50-
JANECEK, R F	8101300577*	50-254 Q	JONES, J L	8101210516*	50-287 S	KERBERT, D	8101090054*	50-
JANECEK, R F	8101080093	50-237 Q	JONES, J L	8101210507*	50-269 S	KEIMIG, R R	8101150546*	50-
JANECEK, R F	8101060376	50-237 P	JONES, J L	8101300432	State Prep	KEIMIG, R	8101280426	50-
JANECEK, R F	8101050566	50-265 P	JONES, J L	8101230441*	50-269 Q	KEIMIG, R	8101280593	50-
JANECEK, R F	8101080144	50-10 P	JONES, B W	8101230164	50-329 G	KEITH, R S	8101050546*	50-
JANECEK, R F	8101120153	50-254 R	JONES, J L	8101270680*	50-270 S	KEITH, R E	8101060795*	50-
JANECEK, R F	8101200135	50-237 Q	JONES, J L	8101270650*	50-287 S	KEITH, R S	8101210451*	50-
JANECEK, R F	8101200126	50-237 P	JONES, W C	8101300513	50-285 S	KEILEY, C	8101260141*	50-
JANECEK, R F	8101260482	50-237 P	JONES, B W	8101280593	50-329 G	KELLER, J H	8101120291	RES
JANECEK, R F	8101260597	50-10 P	JORDAN, A L	8101090577	PR	KELLER, D E	81010703151	50-
JANECEK, R F	8101270661	50-10 P	JORDAN, M J	8101090785*	50-10 Q	KELLEY, D L	8101070744*	50-
JANECEK, R F	8101270481	50-237 P	JORDAN, E L	8101160409	TOPREP	KELLER, J C	8101260170	PR
JANINEK, M	8101270036	State Prep	JORDAN, W S	8101070513	50-443 U	KELLER, A C	8101290560	PR
JANIS, M	8101090155	50-289 H	JORDAN, W S	8101070513	50-443 Q	KELLEY, R H	8101090650*	TOP
JANDOFF, D	8101230006	PR	JORDAN, W S	8101090336	50-443 C	KELLOGG, P J	8101080648*	50-
JANKULESKI, M	8101300544	PR	JORDAN, W S	8101090306	50-443 C	KELLY, P J	8101060706*	50-
JANUSKA, A Q	8101090114*	50-255 Q	JORDAN, E L	8101290742	50-262 S	KELLOGG, P J	8101160266*	50-
JANUSKA, A Q	8101070125*	50-10 Q	JORGENSEN, D L	8101070181*	50-255 Q	KELLY, W D	8101160782*	QAF
JAPE, F.	8101150195*	50-219 Q	JORGENSEN, D L	8101290432*	50-255 Q	KELLY, W D	8101210262*	QAF
JAPE, F.	8101080177*	50-269 Q	JOSTO, J H	8101260011	PR	KELLY, J A	8101160608*	50-
JANEY, L	8101300505	PR	JOV, J M	8101210487*	50-206 R	KELLY, J A	8101070714	50-
JEANVITTO, L	8101160614	PR	JUYCE, P	8101130338	PR	KELLY, J A	8101160374*	50-
JENKINS, G. R	8101080210*	50-250 Q	JUYCE, H	8101130347	PR	KELLY, J A	8101160335	50-
JENKINS, H	8101200163	PR	JDYNER, J H	8101060747*	70-1100	KELLY, F L	8101050123*	50-
JENKINS, D.	8101140603	PR	JDYNER, J H	8101290750*	70-620	KEMP, R L	8101220699	PR
JENKINS, G. R	8101290549*	50-518 Q	JDYNER, J H	8101300196*	70-135	KEPPER, J S	8101216210	50-
JENS, W H	8101090172*	FOIA	JDYNER, J H	8101230523*	70-820	KEPPER, J S	8101230434	50-
JENS, W H	8101070911	PR	JUBACH, R J	8101220557*	50-280 P	KEPPER, T B	8101260190	50-
JENSEN, S E.	8101050096	TOPREP	JULIAN, C J	8101090049*	50-327 Q	KEMPNICH, R	8101220482	PR
JEDRILING, D. H	8101220263*	50-395 A	JULIAN, D.	8101300159	PR	KEMPER, J S	8101070367	50-
JEPSEN, R J	8101290626*	70-2529	JUNUSKA, A Q	8101150640*	50-295 Q	KENDALL, G	8101130286	PR
JEPSEN, R	8101220371	PR	KAGAN, H	8101210546	PR	KENISTON, J	8101190622	PR
JERMAN, P C.	8101280513	ISE	KAHLE, J D	8101060695*	70-143	KENNA, W B	8101060691*	70-
JETT, G W	8101140249*	50-284 Q	KAHLE, J B	8101070802*	50-332 Q	KENNA, W B	8101090790	50-
JOCE, R W	8101160226	50-259 Q	KAHLE, J B	8101200144*	70-1191	KENNA, W B	8101100707*	70-
JOHNS, J R	8101130400*	50-267 P	KAHLE, J B	8101090821*	70-147	KENNA, W B	8101260137*	70-
JOHNS, J R	8101230187	50-267 R	KAHLE, J B	8101100820*	50-261 Q	KENNA, W B	8101090821*	70-
JOHNSEN, J B.	8101060030	ACRS	KAHLE, J B	8101050575*	70-1151	KENNA, W B	8101100610	50-
JOHNSEN, W D	8101100236*	50-313 Q	KAHN, J R	8101060730	FOIA	KENNA, W B	8101050594	70-
JOHNSEN, J M	8101150651	QAF99	KAHN, S	8101260059	PR	KENNA, W B	8101290381	50-
JOHNSEN, A. R.	8101126076*	50-382 Q	KAIN, A	8101200503	PR	KENNA, W B	8101060279	70-
JOHNSEN, J M	8101230510*	QAF99	KATSER, W T	8101270526*	50-349 P	KENNA, W B	8101050573	70-
JOHNSEN, C. R.	8101100160	71-6698	KATSER, W T	8101160476*	50-206 P	KENNA, W B	8101100695	50-
JOHNSON, G F B	8101190499	PR	KATSER, B	8101190446	PR	KENNA, W B	8101230691	50-
JOHNSON, A	8101260717	PR	KALGANI, J	8101300216	PR	KENNEDY, D H	8101130243	50-
JOHNSON, A	8101060087*	50-312 Q	KALIVIANAKIS, N	8011250754	50-254 S	KENYON, T J	8101090968	50-
JOHNSON, A D	8101210130*	50-89 Q	KALIVIANAKIS, N	81010906054	50-234 S	KENYON, T J	8101290197	50-
JOHNSRUD, J H.	8101090321	50-289 Q	KALIVIANAKIS, N	8101090390	50-234 S	KECSTER, G L	8101070408	50-
JOHNSRUD, J H.	8101090330*	50-289 Q	KALIVIANAKIS, N	8101060472	50-263 S	KEOSTER, O L	8101070431	FOIA
JOHNSON, T C	8101270580	50-289 P	KALIVIANAKIS, N	8101060486	50-263 S	KEPPLER, J O	8101090137*	50-
JOHNSON, V. V.	8101270444	50-287 P	KALIVIANAKIS, N	8101130559	50-263 S	KEPPLER, J O	8101050161*	50-
JOHNSRUD, J H.	8101230635	50-289 Q	KALIVIANAKIS, N	8101200307	50-294 R	KEPPLER, J O	8101050206	50-
JOHNSRUD, J H	8101270298	50-387 Q	KALIVIANAKIS, N	8101210463	50-294 R	KEPPLER, J O	8101050207	50-
JOHNSTON, M V.	8101200385	50-369 Q	KALIVIANAKIS, N	8101270753	50-254 S	KEPPLER, J O	8101050214	50-
JOHNSON, J.	8101270636*	50-346 S	KALIVIANAKIS, N	8101270710	50-263 S	KEPPLER, J O	8101050210	50-
JOHNSON, R. L.	8101270928	WASTE MGT	KAMISHLI, J M	8101260468*	50-321 R	KEPPLER, J O	8101050225	50-
JOHNS, W C.	8101140182	50-285 Q	KAMISHLI, J M	8101260527*	50-366 R	KEPPLER, J O	8101050252	50-
JOHNS, W C.	8101120161	50-203 Q	KAMISHLI, J M	8101280197*	50-321 R	KEPPLER, J O	8101050239	50-
JOHNS, W C.	8101160403	50-285 Q	KAMMERER, C	8101090019	50-289 U	KEPPLER, J O	8101050241	50-
JOHNS, W C.	8101120072	50-285 Q	KAMKAKFA, R	8101160505	PR	KEPPLER, J O	8101050349	50-
JOHNS, W C.	8101120131	50-285 Q	KANE, W F	8101100034	50-382 F	KEPPLER, J O	8101050266	50-
JOHNS, W C.	8101160542	50-285 Q	KANE, W	8101140473	50-382 F	KEPPLER, J O	8101050270	50-
JOHNS, W C.	8101120048	50-285 Q	KANE, W	8101270219	50-395 A	KEPPLER, J O	8101050274	50-
JOHNS, J	8101300184	PR	KAPLAN, A L	8012100316*	70-1113	KEPPLER, J O	8101050279	50-
JOHNS, A	8101290695	MUREG	KAPLAN, M	8101160372	PR	KEPPLER, J O	8101050283	50-
JOHNS, K H.	8101290709	PR	KAPLAN, A L	81012279365	71-4906	KEPPLER, J O	8101050287	50-
JOHNS, L	8101190142	FOIA	KAPSALES, J	8101080105	REG2D	KEPPLER, J O	8101050289	50-
JOHNS, T	8101300472	PR	KARIMAN, H	8101260510	50-482 G	KEPPLER, J O	8101060109	50-
JOHNS, D. W	8101050579*	70-1151	KARMAN, M	8101260512	50-482 Q	KEPPLER, J O	8101060110	50-
JOHNS, R K.	8101290649	WASTE MGT	KARMAN, M	8101280124	50-482 Q	KEPPLER, J O	8101060118	50-
JOHNS, W C.	8101060761	50-285 S	KATZ, K	8101260721	PR	KEPPLER, J O	8101060125	50-
JOHNS, A	8101160559	PR	KAUFMAN, N C	8101050062	MUREG	KEPPLER, J O	8101060522	50-
JOHNS, J	8101160376	PR	KAUFMAN, M	8101160550	PR	KEPPLER, J O	8101060527	50-
JOHNS, W C.	8101120300	50-285 S	KAUFMAN, N C	8101300845	RES	KEPPLER, J O	8101060531	50-
JOHNS, W C.	8101130358	50-285 S	KAY, J A	8101070383	50-29 P	KEPPLER, J O	8101060537	50-
JOHNS, J. L.	8101050353*	50-287 S	KAY, J A	8101140361	50-29 P	KEPPLER, J O	8101060547	50-
JOHNS, J. A	8101050325	50-400 A	KAY, J A	8101120293	50-29 P	KEPPLER, J O	8101060548	50-
JOHNS, W. *	8101070349	50-285 P	KAY, J A	8101130130	50-29 P	KEPPLER, J O	8101050552	50-
JOHNS, J. L.	8101090666*	50-287 S	KAY, J A	8101140664	50-29 P	KEPPLER, J O	8101060644	50-
JOHNS, W C.	8101130373	50-285 P	KAY, J A	8101270362	50-29 P	KEPPLER, J O	8101060650	50-
JOHNS, W C.	8101160485	50-285 R	KAY, J A	8101270652	50-29 P	KEPPLER, J O	8101060654	50-
JOHNS, G. W	8101120515	50-329 Q	KAY, J A	8101300481	50-29 P	KEPPLER, J O	8101060658	50-
JOHNS, J. L.	8101300578*	50-270 S	KEATON, R W	8101270361*	50-289 T	KEPPLER, J O	8101060662	50-

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER
KEPPLER, J G	B101050455	50-367 Q	KEPPLER, J G	B101090041	50-341 Q	KINNEY, W W	B1010505
KEPPLER, J G	B101050456	50-345 Q	KEPPLER, J G	B101090044	50-331 Q	KINNEHAN, J D	B1011300
KEPPLER, J G	B101050457	50-483 Q	KEPPLER, J G	B101090048	50-367 Q	KINNEHAN, J D	B1011900
KEPPLER, J G	B101050470	50-235 Q	KEPPLER, J G	B101090054	50-461 Q	KINNEHAN, J D	B1012805
KEPPLER, J G	B101050475	50-252 Q	KEPPLER, J G	B101090056	50-440 Q	KINTNER, L L	B1011400
KEPPLER, J G	B101050454	50-315 Q	KEPPLER, J G	B101090060	50-10 Q	KINTNER, L L	B1011600
KEPPLER, J G	B101050457	50-155 Q	KEPPLER, J G	B101090070	50-155 Q	KINTNER, L L	B1012700
KEPPLER, J G	B101050458	50-10 Q	KEPPLER, J G	B101090075	50-258 Q	KINTNER, L L	B1012100
KEPPLER, J G	B101050471	50-437 Q	KEPPLER, J G	B101150004	50-155 Q	KINTNER, L L	B1012700
KEPPLER, J G	B101050472	50-545 Q	KEPPLER, J G	B101150011	50-231 Q	KINTNER, L L	B1012900
KEPPLER, J G	B101050479	50-367 Q	KEPPLER, J G	B101150010	50-461 Q	KINTNER, L L	B1013000
KEPPLER, J G	B101050480	50-345 Q	KEPPLER, J G	B101150020	50-341 Q	KINTNER, L L	B1013000
KEPPLER, J G	B101050473	50-305 Q	KEPPLER, J G	B101150025	50-267 Q	KIRK, W F	B1012100
KEPPLER, J G	B101050477	50-463 Q	KEPPLER, J G	B101150030	50-373 Q	KIRK, G B	B1012500
KEPPLER, J G	B101050478	50-461 Q	KEPPLER, J G	B101150040	50-10 Q	KIRK, W F	B1012900
KEPPLER, J G	B101050472	50-324 Q	KEPPLER, J G	B101150046	50-440 Q	KIRK, G B	B1012200
KEPPLER, J G	B101050484	50-263 Q	KEPPLER, J G	B101150049	50-263 Q	KIRK, G B	B1012200
KEPPLER, J G	B101050484	50-461 Q	KEPPLER, J G	B101150063	50-358 Q	KIRK, G B	B1012200
KEPPLER, J G	B101050483	50-357 Q	KEPPLER, J G	B101290020	50-329 Q	KIRKPATRICK, R	B1013000
KEPPLER, J G	B101050476	50-155 Q	KEPPLER, J G	B101050170	50-10 Q	KIRSCH, D F	B1013000
KEPPLER, J G	B101050481	50-409 Q	KEPPLER, J G	B101050174	50-155 Q	KIRSCH, D F	B1012100
KEPPLER, J G	B101050470	50-545 Q	KEPPLER, J G	B101050182	50-409 Q	KISTER, H B	B1012200
KEPPLER, J G	B101050471	50-483 Q	KEPPLER, J G	B101050186	50-773 Q	KISTER, H B	B1012100
KEPPLER, J G	B101050444	50-305 Q	KEPPLER, J G	B101050190	50-263 Q	KISTER, H B	B1012800
KEPPLER, J G	B101050444	50-155 Q	KEPPLER, J G	B101050193	50-241 Q	KISTER, H B	B1012600
KEPPLER, J G	B101050500	50-315 Q	KEPPLER, J G	B101050196	50-451 Q	KLEBANOW, A	B1012300
KEPPLER, J G	B101050356	50-358 Q	KEPPLER, J G	B101050199	50-331 Q	KLEEN, M	B1012100
KEPPLER, J G	B101050357	50-367 Q	KEPPLER, J G	B101050202	50-440 Q	KLEINSORGE, W	B1010900
KEPPLER, J G	B101050361	50-263 Q	KEPPLER, J G	B101050203	50-358 Q	KLEINSORGE, W	B1012900
KEPPLER, J G	B101050361	50-324 Q	KEPPLER, J G	B101050210	50-367 Q	KLOPE, A	B1012100
KEPPLER, J G	B101050375	50-461 Q	KEPPLER, J G	B101050499	50-346 Q	KLUWER, M	B1012000
KEPPLER, J G	B101050379	50-546 Q	KEPPLER, J G	B101070292	70-2249	KNAPP, P J	B1012200
KEPPLER, J G	B101050381	50-305 Q	KEPPLER, J G	B101200632	50-249 S	KNAPP, P J	B1013000
KEPPLER, J G	B101050385	50-483 Q	KEPPLER, J G	B101100524	50-353 Q	KNAPP, P J	B1011600
KEPPLER, J G	B101050390	50-409 Q	KEPPLER, J G	B101160579	50-746 Q	KNICELY, J	B1013000
KEPPLER, J G	B101050395	50-305 Q	KEPPLER, J G	B101160621	50-315 P	KNICELEY, J R	B1011300
KEPPLER, J G	B101050475	50-409 Q	KEPPLER, J G	B101190796	50-454 Q	KNIES, R A	B1010500
KEPPLER, J G	B101050477	50-358 Q	KEPPLER, J G	B101210647	50-249 S	KNIGHTON, G W	79040400
KEPPLER, J G	B101050501	50-155 Q	KEPPLER, J G	B101160620	50-263 F	KNIGHT, J	B1010700
KEPPLER, J G	B101050505	50-305 Q	KEPPLER, J G	B101210214	50-358 S	KNIGHTON, G W	83050600
KEPPLER, J G	B101050510	50-463 Q	KEPPLER, J G	B101220182	50-255 Q	KNOP, R C	B1011000
KEPPLER, J G	B101050515	50-546 Q	KEPPLER, J G	B101270123	50-255 S	KNOP, R C	B1010700
KEPPLER, J G	B101050520	50-315 Q	KEPPLER, J G	B101270351	50-373 Q	KNOP, R C	B1011000
KEPPLER, J G	B101050525	50-267 Q	KEPPLER, J G	B101200316	50-341 A	KNOP, R C	B1011400
KEPPLER, J G	B101050529	50-461 Q	KEPPLER, J G	B101270397	50-454 Q	KNOP, R C	B1012200
KEPPLER, J G	B101070020	50-305 Q	KERR, O W	B101090028	State Prog	KNOP, R C	B1012100
KEPPLER, J G	B101070023	50-265 Q	KERR, O W	B101160396	State Prog	KNOP, R C	B1012100
KEPPLER, J G	B101090351	50-255 Q	KERR, O W	B101190730	State Prog	KNIGHT, J B	B1012800
KEPPLER, J G	B101090390	50-254 Q	KERR, O W	B101190721	State Prog	KNIGHT, J B	B1012800
KEPPLER, J G	B101100763	50-6 Q	KERR, J E	B101260517	50-133 Q	KNIX, E	B1012200
KEPPLER, J G	B101050520	50-409 Q	KERRIGAN, J	B101060797	50-311 P	KNUDSON, W H	B1012900
KEPPLER, J G	B101050524	50-329 Q	KERRIGAN, J D	B101390044	50-528 A	KNUTH, D F	B1011400
KEPPLER, J G	B101050526	50-440 Q	KERRIGAN, J D	B101300041	50-529 A	KOCH, L J	B1011400
KEPPLER, J G	B101050533	50-10 Q	KETCHEN, E O	B101100119	50-369 H	KOCH, L J	B1011500
KEPPLER, J G	B101050544	50-461 Q	KETCHEN, E O	B101230629	50-369 H	KOCH, L J	B1010700
KEPPLER, J G	B101050545	50-331 Q	KETCHEN, E O	B101090623	50-275 Q	KOCH, L J	B1010900
KEPPLER, J G	B101050550	50-241 Q	KETCHEN, E O	B101120459	50-275 Q	KOCHER, O C	B1012200
KEPPLER, J G	B101050556	50-315 Q	KETCHEN, E O	B101220010	50-369 Q	KOESTER, Q L	B1010700
KEPPLER, J G	B101050557	50-350 Q	KETZLACH, H	B1010150044	70-33	KOESTER, Q L	B1010700
KEPPLER, J G	B101050562	50-155 Q	KETZLACH, H	B101060796	70-2937	KOESTER, Q L	B1010700
KEPPLER, J G	B101050565	50-262 Q	KETZLACH, H	B101060102	70-2936	KOESTER, Q L	B1012800
KEPPLER, J G	B101050566	50-267 Q	KETZLACH, H	B101070566	70-27	KOESTER, Q L	B1010700
KEPPLER, J G	B101050571	50-546 Q	KETZLACH, H	B101140170	70-2623	KOESTER, Q L	B1010700
KEPPLER, J G	B101050572	50-483 Q	KETZLACH, H	B101210267	70-27	KOESTER, Q L	B1010700
KEPPLER, J G	B101050574	50-305 Q	KEURICK, J R	B101140731	70-2909	KOESTER, Q L	B1010700
KEPPLER, J G	B101050578	50-265 Q	KEURICK, J R	B101140531	70-2907	KOHLER, J E	B1011400
KEPPLER, J G	B101050581	50-346 Q	KEY, W	B101100378	50-546 Q	KOLKEY, M	B1013000
KEPPLER, J G	B101100777	50-5 Q	KEY, W J	B101230687	50-374 Q	KOLTA, P B	B1013000
KEPPLER, J G	B101050549	50-358 A	KEYSER, J	B101210037	CONTRACT	KONIGBERG, A	B1012000
KEPPLER, J G	B101100174	50-266 Q	KIENHOLZ, J	B101140584	50-271 H	KOPACZ, J J	B1012300
KEPPLER, J G	B101100189	50-305 Q	KILLGAARD, K	B101270535	PR	KOPACZ, J J	B101060
KEPPLER, J G	B101080345	50-329 A	KIMEL, H R	B101050157	50-289 T	KOPLEY, K	B1012100
KEPPLER, J G	B101070074	50-246 Q	KIMMEL, J J	B101210327	CONTRACT	KORN, L	B1013000
KEPPLER, J G	B101070077	50-315 Q	KIMMINS, G H	B101140617	50-327 Q	KOTSCH, J L	B1012900
KEPPLER, J G	B101070079	50-329 Q	KINCHELOE, J	B101300928	PR	KOVAR, K N	B1011300
KEPPLER, J G	B101070082	50-282 Q	KING, D	B101300362	PR	KOWAL, K	B1011600
KEPPLER, J G	B101070085	50-546 Q	KINGSLEY, S S	B101120057	71-358	KOWATCH, M	B1012600
KEPPLER, J G	B101070092	50-483 Q	KINKHEAD, D	B101190084	PR	KRAFT, D C	B1011600
KEPPLER, J G	B101070095	50-265 Q	KINKHEAD, L	B101270300	PR	KRASNOFF, J	B1012100
KEPPLER, J G	B101070098	50-305 Q	KINNEHAN, J D	B101290598	70-818	KRASNOFF, J	B1011300
KEPPLER, J G	B101070100	50-255 Q	KINNEHAN, J D	B101290623	70-2327	KREGER, W E	70092100
KEPPLER, J G	B101070105	50-295 Q	KINNEHAN, J D	B101290620	40-8649	KREGER, W E	B1011200
KEPPLER, J G	B101220100	50-315 Q	KINNEHAN, J D	B101290628	40-8003	KREIS, J	B1013000
KEPPLER, J G	B101070627	50-409 Q	KINNEHAN, J D	B101130705	70-1111	KRESS, T S	B1012900
KEPPLER, J G	B101080638	50-263 Q	KINNEHAN, J	B101050539	50-245 S	KRESS, T S	B1012900

BRIDGEMAN, D. C.	0101270365	PR				0101070492*	50-298	S	LESTER, D.	0101300276	PR
BRIDGEMAN, D. C.	0101190520	PR				0101230139	PR		LEVILLE, H. J.	0101226412	PR
BRIDGEMAN, D. C.	0101190651	PR				0101266227	PR		LEWIS, E. J.	0101230346*	50-3
BRIDGEMAN, D. C.	0101210277	50-387	A			0101300330	50-309	A	LEWIS, E. J.	0101230346*	50-3
BRIDGEMAN, D. C.	0101140528	50-255	P			0101210271*	50-352	Q	LEVINE, M. H.	0101230305	RES
BRIDGEMAN, D. C.	0101500174	PR				01012100120*	50-580	A	LEVINE, M. H.	0101276351	RES
BRIDGEMAN, D. C.	0101090160	50-289	H			01012100151*	50-452	A	LEVINE, S.	0101190581	PR
BRIDGEMAN, D. C.	0101220370*	50-339	P			0101050951	50-309	G	LEVINE, S.	0101210486	PR
BRIDGEMAN, D. C.	0101260523	PR				0101126497	50-526	G	LEVINE, S. H.	0101230419	50-3
BRIDGEMAN, D. C.	0101130400	NUREQ				0101146915	50-739	H	LEVY, P.	0101276341	PR
BRIDGEMAN, D. C.	0101130414	NUREQ				0101166741	50-413	H	LEVY, S.	0101260405	50-3
BRIDGEMAN, D. C.	0101140066	REVIEW CRP				0101300199	REIS		LEWIS, R. C.	0101090234*	50-3
BRIDGEMAN, D. C.	0101190024	PR				0101166733	PR		LEWIS, J.	0101072482*	RECO
BRIDGEMAN, D. C.	0101300482	PR				0101170174	PR		LEWIS, R. C.	0101090641*	50-3
BRIDGEMAN, D. C.	0101070531*	50-334	S			0101091600*	CONTRACT		LEWIS, R. C.	0101060155*	50-3
BRIDGEMAN, D. C.	0101130425*	50-334	S			0101170164*	50-289	G	LEWIS, R. C.	0101070152*	50-3
BRIDGEMAN, D. C.	0101130428*	50-334	S			0101150454*	CONTRACT		LEWIS, R. C.	0101160659	50-3
BRIDGEMAN, D. C.	0101130432*	50-334	S			0101060320	CONTRACT		LEWIS, R. C.	0101100251	50-3
BRIDGEMAN, D. C.	0101130436*	50-334	S			0101040347*	CONTRACT		LEWIS, R. C.	0101100623	50-3
BRIDGEMAN, D. C.	0101130443*	50-334	S			0101130555*	CONTRACT		LEWIS, R. C.	0101220419	50-3
BRIDGEMAN, D. C.	0101130515*	50-334	S			0101146375*	CONTRACT		LEWIS, R. C.	0101160626*	50-3
BRIDGEMAN, D. C.	0101190470*	50-334	S			0101300327*	CONTRACT		LEWIS, S.	0101300366	PR
BRIDGEMAN, D. C.	0101190477*	50-334	S			0101270732*	CONTRACT		LEWIS, M. J.	0101230013	PR
BRIDGEMAN, D. C.	0101220387*	50-334	S			0101290105*	CONTRACT		LEWIS, R. C.	0101290323	50-3
BRIDGEMAN, D. C.	0101220397*	50-334	S			0101150631	50-285	P	LEWIS, M. J.	0101060172	PR
BRIDGEMAN, D. C.	0101220384*	50-334	S			0101160495	PR		LEWIS, R. C.	0101090925	50-3
BRIDGEMAN, D. C.	0101230471*	50-334	S			0101160020	PR		LEWIS, R. C.	0101060141	50-3
BRIDGEMAN, D. C.	0101230473*	50-334	G			0101210559	FOIA		LEWIS, R. C.	0101080127	50-3
BRIDGEMAN, D. C.	0101230478*	50-334	S			0101170351	PR		LEWIS, R. C.	0101270357	50-3
BRIDGEMAN, D. C.	0101260634*	50-334	S			0101070205*	50-267	Q	LEWIS, M. J.	0101290156	PR
BRIDGEMAN, D. C.	0101270593*	50-334	S			0101170134	50-267	Q	LEWIS, R. C.	0101090671	50-3
BRIDGEMAN, D. C.	0101190117	PR				0101120425	50-267	P	LEWIS, M.	0101160694	50-3
BRIDGEMAN, D. C.	0101150249*	50-213	Q			0101170369	50-267	P	LEWIS, M.	0101080335	50-3
BRIDGEMAN, D. C.	0101260702	PR				0101130373	50-267	P	LEWIS, S. H.	0101270106	50-3
BRIDGEMAN, D. C.	0101200172	50-289	H			0101130394*	50-267	P	LI, C.	0101150672	50-3
BRIDGEMAN, D. C.	0101150324	50-289	H			0101140151*	50-461	Q	LIRBARKIN, M. W.	0101100341	REVIEW
BRIDGEMAN, D. C.	0101050413*	50-317	S			0101050187*	TOPREC		LIRBARKIN, L.	0101220145	PR
BRIDGEMAN, D. C.	0101130623*	50-317	S			0101060755*	70-143		LIRBARKIN, F. P.	0101070557*	50-3
BRIDGEMAN, D. C.	0101150543*	50-318	S			0101290326*	50-260	Q	LIRBARKIN, F. P.	0101080297*	50-3
BRIDGEMAN, D. C.	0101230526*	50-317	S			0101270347*	50-289	T	LIRBARKIN, F. P.	0101070540*	50-3
BRIDGEMAN, D. C.	0101270684*	50-318	S			0101090610	50-259	P	LICCARDI, R. A.	0101210315	50-3
BRIDGEMAN, D. C.	0101300530*	50-317	S			0101230258	PR		LICCARDI, R. A.	0101270747	50-3
BRIDGEMAN, D. C.	0101270742	RES				0101210267	PR		LICHTENSTEIN, S.	0101260114	NUREQ
BRIDGEMAN, D. C.	0101220374*	50-10	P			0101280033	WASTE MGT		LICHTER, H.	0101190471	PR
BRIDGEMAN, D. C.	0101290475	50-29	P			0101140017*	50-387	Q	LIEBMAN, R. H.	0101210282	PR
BRIDGEMAN, D. C.	0101210070	PR				0101150631	50-285	P	LIEBMAN, P. C.	0101160303	PR
BRIDGEMAN, D. C.	0101150631	50-285	P			0101090016	50-155	Q	LIGONSTEIN, C.	0101220355	PR
BRIDGEMAN, D. C.	0101190632*	PR				0101090022*	50-155	Q	LIM, J. J.	0101300307	NUREQ
BRIDGEMAN, D. C.	0101200525	PR				0101130148	50-155	Q	LINDER, F.	0101080079	50-4
BRIDGEMAN, D. C.	0101210227	PR				0101130154*	50-155	Q	LINDER, F.	0101080107	50-4
BRIDGEMAN, D. C.	0101270502	40-8452				0101130156*	50-155	Q	LINDER, F.	0101050374	50-4
BRIDGEMAN, D. C.	0101140537	PR				0101220436*	50-220	Q	LINDER, F.	0101160433	50-4
BRIDGEMAN, D. C.	0101150366*	COMMISSION				0101140696	50-220	Q	LINDER, F.	0101050326	50-4
BRIDGEMAN, D. C.	0101290647	PR				0101300055	50-220	Q	LINDER, F.	0101060561	50-4
BRIDGEMAN, D. C.	0101270761	PR				0101120335	50-220	S	LINDER, F.	0101090342	50-4
BRIDGEMAN, D. C.	0101190533	PR				0101150677	50-220	S	LINDER, F.	0101300626	50-4
BRIDGEMAN, D. C.	0101210207	PR				0101150501	50-220	P	LINDER, F.	0101160433	50-4
BRIDGEMAN, D. C.	01012310226	NUREQ				0101210595	50-220	P	LINDER, F.	0101200178	50-4
BRIDGEMAN, D. C.	0101220552	RECOG				0101230580	50-220	P	LINDER, F.	0101140491	50-4
BRIDGEMAN, D. C.	0101300507	PR				0101100634*	50-220	Q	LINDER, F.	0101250515	50-4
BRIDGEMAN, D. C.	0101200239	50-289	H			0101120564	XPORTLIC		LINDER, F.	0101220025	50-4
BRIDGEMAN, D. C.	0101200493	PR				0101120373	XPORTLIC		LINDER, F.	0101160181	50-4
BRIDGEMAN, D. C.	0101160048	PR				0101120080	XPORTLIC		LINDER, F.	0101270345	50-4
BRIDGEMAN, D. C.	0101070412	50-322	G			0101220125	PR		LINERMAN, J. J.	0101070547	CAS
BRIDGEMAN, D. C.	0101070449	50-322	G			0101280356	PR		LINERMAN, J.	0101280635	40-4
BRIDGEMAN, D. C.	0101220021*	50-312	F			0101220205	RECOG		LINERMAN, J. J.	0101290087	40-4
BRIDGEMAN, D. C.	0101270675	50-322	Q			0101210013	PR		LINERMAN, J. J.	0101290081	40-4
BRIDGEMAN, D. C.	0101270678*	50-322	Q			0101300112	PR		LIPINSKI, R. J.	0101290062	NUREQ
BRIDGEMAN, D. C.	0101150496*	50-247	P			0101280345	PR		LITTLE, M. S.	0101100361*	50-5
BRIDGEMAN, D. C.	0101160490*	50-280	P			0101070514	50-298	S	LITTLE, M. S.	0101140510	50-5
BRIDGEMAN, D. C.	0101130274*	PR				0101070507	50-298	S	LITTLEJOHN, J.	0101140637	PR
BRIDGEMAN, D. C.	0101210156	PR				0101070360	50-298	S	LITTLE, M. S.	0101290494*	50-5
BRIDGEMAN, D. C.	0101280430*	50-244	P			0101070391	50-298	S	LITTLE, M. S.	0101300308*	50-5
BRIDGEMAN, D. C.	0101120332*	50-244	P			0101070355	50-298	S	LITTLE, M.	0101290337	CON
BRIDGEMAN, D. C.	0101120342*	50-244	P			0101070489	50-298	S	LITTLE, M.	0101270706	50-5
BRIDGEMAN, D. C.	0101300262*	50-244	P			0101070477	50-298	S	LITVOK, D.	0101200312	PR
BRIDGEMAN, D. C.	0101120353*	50-244	P			0101270647	50-298	S	LITVOK, D.	0101230374	PR
BRIDGEMAN, D. C.	0101070047	FOIA				0101270641	50-298	S	LIVERMORE, H. H.	0101160197*	50-5
BRIDGEMAN, D. C.	0101190062	PR				0101130587	50-298	R	LIVERMORE, H. H.	0101140072*	50-5
BRIDGEMAN, D. C.	0101060790*	CONTRACT				0101270715	50-298	S	LLOSCIO, A. T.	0101210046	PT2
BRIDGEMAN, D. C.	0101140011	50-387	Q			0101270775	50-298	S	LOCKE, R. F.	0101070135	50-5
BRIDGEMAN, D. C.	0101200023	50-387	Q			0101140726	50-483	Q	LOEFFLER, T.	0101080372*	COM
BRIDGEMAN, D. C.	0101280628	50-387	Q			0101270334	50-443	Q	LOIS, L.	0101160200	TOP
BRIDGEMAN, D. C.	0101300012	50-239	Q			0101270434	50-443	Q	LOMBARDI, C.	0101150400	PR
BRIDGEMAN, D. C.	0101070511*	50-298	S			0101300018	50-483	Q	LONG, R. L.	0101050150*	50-5

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
LEACH, R. L.	8101270261*	50-289 T	MACDONALD, C. E.	8101270051	71-9072	MARRY, M.	8101260543	50-321 S
LECHMAN, J. S.	81011680127	FR	MACDONALD, C. E.	8101270061	71-5808	MARRY, M.	8101260592	50-321 S
LECHMAN, R. S.	81013003241	PR	MACDONALD, C. E.	8101270068	71-6450	MARRY, M.	8101260601	50-321 S
LEITCHMAN, H.	8101050035*	50-481 G	MACDONALD, C. E.	8101270072	71-9065	MARSH, W. C.	8101060819*	70-143
LEITCHBACK, T. E.	8101290070*	40-8200	MACDONALD, C. E.	8101270076	71-9023	MARSH, W. C.	8101060237*	70-143
LEITCHBACK, T. E.	81012900547	40-8200	MACDONALD, C. E.	8101270084	71-6642	MARSH, W. C.	8101160138*	70-143
LEITCHBACK, R. F.	8101150045*	CONTRACT	MACDONALD, C. E.	8101270026	71-6573	MARSH, J. D. A.	8101210031	FR
LEITCHDALE, P. C.	8101120018*	50-155 Q	MACDONALD, C. E.	8101270031	71-350	MARSH, J. D. A.	8101160358	ACRS
LEITCHDALE, P. C.	8101150078*	50-373 Q	MACDONALD, C. E.	8101270037*	71-378	MARSH, J. D. A.	8101090919	XPORLIC
LEITCH, M.	8101160050*	PR	MACDUFF, R. B.	8101220534*	TCPREP	MARSH, J. D. A.	8101090912	XPORLIC
LEITCHSTEIN, J. J.	8101260147	PR	MACHON, R. D.	8101180035*	50-293 S	MARSH, J. D. A.	8101140703	XPORLIC
LEITCH, E. J.	8101220037*	50-337 P	MACHON, R. D.	8101180046	50-293 S	MARSH, J. D. A.	8101190755	XPORLIC
LEITCH, J. D.	8101070033*	State Prog	MACHON, R. D.	8101190062	50-293 S	MARSH, J. D. A.	8101140703	XPORLIC
LEITCH, J. D.	8101190054	15E	MACHON, R. D.	8101160516	50-293 S	MARSH, J. D. A.	8101160531	PR
LEITCH, J. D.	8101160430	State Prog	MACHON, R. D.	8101260544	50-293 S	MARSH, J. D. A.	8101210019	PR
LUCAS, J.	81011300280	PR	MACIOLEK-BLAME	8101280087*	50-219 R	MARIANO, H.	8101210062	PR
LUCAS, R. D.	8101290081	PR	MACHEV, M.	8101270024	PR	MARINO, L.	8101200535	PR
LUCAS, W. J.	8101210057*	RES	MACHEV, M.	8101300153	NUREG	MARIN, J. C.	8101160446	50-327 S
LUCIFIG, M.	8101220028	RES	MACHURDY, P. H.	8101160128	NUREG	MARIN, J. C.	8101160463	ACRS
LUCIFIG, F.	8101050032	50-463 G	MALDEN, T. J.	8101070022	FOIA	MARIN, J. C.	8101300814	50-327 S
LUCAS, H. J.	8101300020	NUREG	MADEN, T. G.	8101130015	XPORLIC	MARAS, R. A.	8101160018	FR
LUCYVALL, A. E.	8101070037	50-317 V	MADEN, T. G.	8101130119*	XPORLIC	MARSHALL, W. H.	8101090358	50-329 S
LUCYVALL, A. E.	8101150351*	50-317 Q	MADIS, S.	8101270178	FOIA	MARSHALL, W. H.	8101060742*	FOIA
LUCYVALL, A. E.	8101150365*	50-317 Q	MADDOCK, S. O.	8101210454*	50-327 S	MARTINSON, Z. R.	8101330768	NUREG
LUCYVALL, A. E.	8101140944	50-317 Q	MADISEN, A. L.	8101100351*	50-263 Q	MARTIN, T. I.	8101300194*	50-271 J
LUNDVALL, A. E.	8101050437	50-317 F	MADISON, A. L.	8101140510*	50-263 Q	MARTIN, T. J.	8101290781*	50-334 Q
LUNDVALL, A. E.	8101190320	50-317 P	MADON, I. K.	8101270827	50-337 A	MARTIN, T. J.	8101300030*	50-339 1
LUNDVALL, A. E.	8101230537	50-317 Q	MADON, I. K.	8101070215	50-267 Q	MARTIN, T. J.	8101050497*	50-334 S
LUNDVALL, A. E.	8101260477	50-318 Q	MADSEN, G. L.	8101100329	50-290 Q	MARTIN, W. Q.	8101160633*	50-271 Q
LUNDVALL, A. E.	8101330322	50-317 P	MADSEN, G. L.	8101070240	50-285 Q	MARTIN, W. Q.	8101090878	50-333 S
LUNNEY, H.	8101210047	PR	MADSEN, G. L.	8101060275*	50-313 Q	MARTIN, W. Q.	8101060739	70-1100
LUNSFORD, J. L.	8101210275	NUREG	MADSEN, G. L.	8101070247	50-302 Q	MARTIN, R. D.	8101080177*	50-267 Q
LYNCH, L.	8101300105	PR	MADSEN, G. L.	8101100317	50-313 Q	MARTIN, W. Q.	8101290754	70-820
LYNCH, M.	8101140976	PR	MADSEN, G. L.	8101060884	50-313 Q	MARTIN, W. Q.	8101300120	XPORLIC
LYNCH, M.	8101210263	PR	MADSEN, G. L.	8101070158	50-313 Q	MARTIN, W. Q.	8101300126*	

[illegible]

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MCCRE, R N	0101100281*	FOIA	MCCRE, R N	0101100281*	FOIA	MURRAY, M J	0101200046	50-
MCCRE, R N	0101100272*	FOIA	MCCRE, R N	0101100272*	FOIA	MURRAY, T D	0101220424	50-
MCCRE, R N	0101210432	PR	MCCRE, R N	0101210432	PR	MURRAY, T D	0101220434	50-
MCCRE, R N	0101150477	XPORTRIC	MCCRE, R N	0101150477	XPORTRIC	MURRAY, T D	0101270689	50-
MCCRE, R N	0101120031	XPORTRIC	MCCRE, R N	0101120031	XPORTRIC	MURRAY, T D	0101270634	50-
MCCRE, R N	0101280466	PR	MCCRE, R N	0101280466	PR	MURRAY, R C	0101270700	50-
MCCRE, R N	0101280466	PR	MCCRE, R N	0101280466	PR	MURRAY, R C	0101270700	50-
MCCRE, R N	0101090531	XPORTRIC	MCCRE, R N	0101090531	XPORTRIC	MURRAY, R C	0101270700	50-
MCCRE, R N	0101070305	XPORTRIC	MCCRE, R N	0101070305	XPORTRIC	MURRAY, R C	0101270700	50-
MCCRE, R N	0101070652	XPORTRIC	MCCRE, R N	0101070652	XPORTRIC	MURRAY, R C	0101270700	50-
MCCRE, R N	0101260550	PR	MCCRE, R N	0101260550	PR	MURRAY, R C	0101270700	50-
MCCRE, R N	0101140350	XPORTRIC	MCCRE, R N	0101140350	XPORTRIC	MURRAY, R C	0101270700	50-
MCCRE, R N	0101140826	XPORTRIC	MCCRE, R N	0101140826	XPORTRIC	MURRAY, R C	0101270700	50-
MCCRE, R N	0101150467	XPORTRIC	MCCRE, R N	0101150467	XPORTRIC	MURRAY, R C	0101270700	50-
MCCRE, R N	0101150620	XPORTRIC	MCCRE, R N	0101150620	XPORTRIC	MURRAY, R C	0101270700	50-
MCCRE, R N	0101070436	50-334 R	MCCRE, R N	0101070436	50-334 R	MURRAY, R C	0101270700	50-
MCCRE, R N	0101270187	XPORTRIC	MCCRE, R N	0101270187	XPORTRIC	MURRAY, R C	0101270700	50-
MCCRE, R N	0101270218	XPORTRIC	MCCRE, R N	0101270218	XPORTRIC	MURRAY, R C	0101270700	50-
MCCRE, R N	0101160329	XPORTRIC	MCCRE, R N	0101160329	XPORTRIC	MURRAY, R C	0101270700	50-
MCCRE, R N	0101260095	XPORTRIC	MCCRE, R N	0101260095	XPORTRIC	MURRAY, R C	0101270700	50-
MCCRE, J E	0101080080	50-155 G	MCCRE, J E	0101080080	50-155 G	MURRAY, R C	0101270700	50-
MCCRE, J E	0101160104	50-424 A	MCCRE, J E	0101160104	50-424 A	MURRAY, R C	0101270700	50-
MCCRE, J E	0101220001	50-155 G	MCCRE, J E	0101220001	50-155 G	MURRAY, R C	0101270700	50-
MCCRE, J E	0101220017	50-155 G	MCCRE, J E	0101220017	50-155 G	MURRAY, R C	0101270700	50-
MCCRE, J E	0101220020	50-155 G	MCCRE, J E	0101220020	50-155 G	MURRAY, R C	0101270700	50-
MCCRE, J E	0101280326	50-155 G	MCCRE, J E	0101280326	50-155 G	MURRAY, R C	0101270700	50-
MCCRE, J E	0101270781	PR	MCCRE, J E	0101270781	PR	MURRAY, R C	0101270700	50-
MCCRE, J E	0101270037	PR	MCCRE, J E	0101270037	PR	MURRAY, R C	0101270700	50-
MCCRE, J E	0101212051	PR	MCCRE, J E	0101212051	PR	MURRAY, R C	0101270700	50-
MCCRE, J E	0101190620	PR	MCCRE, J E	0101190620	PR	MURRAY, R C	0101270700	50-
MCCRE, J E	0101090050	FOIA	MCCRE, J E	0101090050	FOIA	MURRAY, R C	0101270700	50-
MCCRE, J E	0101210559	PR	MCCRE, J E	0101210559	PR	MURRAY, R C	0101270700	50-
MCCRE, J E	0101130368	50-322 K	MCCRE, J E	0101130368	50-322 K	MURRAY, R C	0101270700	50-
MCCRE, J E	0101140727	50-293 G	MCCRE, J E	0101140727	50-293 G	MURRAY, R C	0101270700	50-
MCCRE, J E	0101270445	PR	MCCRE, J E	0101270445	PR	MURRAY, R C	0101270700	50-
MCCRE, J E	0101070337	50-293 P	MCCRE, J E	0101070337	50-293 P	MURRAY, R C	0101270700	50-
MCCRE, J E	0101090045	50-293 P	MCCRE, J E	0101090045	50-293 P	MURRAY, R C	0101270700	50-
MCCRE, J E	0101190291	50-293 P	MCCRE, J E	0101190291	50-293 P	MURRAY, R C		

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
NICHOLS, T. C.	8101260471	50-395 S	O'BRIEN, K. A.	8101300579	PH	OLMSTEAD, W. J.	8101260611	50-329 J
NICHOLS, T. C.	8101260507	50-395 S	O'BRIEN, H. J.	8101190475	State Prog	OLSEN, A. F.	8101190353	71-524 J
NICHOLS, T. C.	8101260643	50-395 S	O'CONNOR, J. M.	8101270229	RES	OLSON, D. D.	8101210254	PR
NICHOLS, T. C.	8101215934	50-395 A	O'CONNELL, P.	8101260191	PH	OLSON, R. C.	8101290618	53-317 J
NICHOLS, T. C.	8101270496	50-395 V	O'CONNELL, E.	8101270260	WASTE MGT	OLSON, R. C.	8101230486	50-317 J
NICHOLS, T. C.	8101280119	50-395 A	O'CONNELL, J.	8101160412	70-820	OLSON, R. C. L.	8101190164	50-317 J
NICHOLS, T. C.	8101280237	50-395 S	O'CONNELL, J.	8101160413	70-820	OLSON, R. C. L.	8101280434	50-317 J
NICHOLS, T. C.	8101290129	50-395 F	O'CONNELL, J.	8101260414	70-820	OLSON, R. C. L.	8101290769	PR
NICHOLS, P. J.	8101070172	PH	O'HANLON, J. P.	8101070349	50-368 S	OPREA, G. H.	8101120391	50-498 J
NICHOLS, P. J.	8101140116	State Prog	O'KEIL, P.	8101300132	PR	OPREA, G. H.	8101140484	50-498 J
NIEVERGHE, P.	8101060235	PR	O'KEIL, J.	8101050627	50-155 G	OPREA, G. H.	8101270909	50-498 J
NIEVERGHE, P.	8101120331	PR	O'KEIL, J. P.	8101100846	50-302 U	OPREA, G. H.	8101080140	50-498 J
NIEVERGHE, P.	8101290393	50-245 S	O'KEIL, J. P.	8101260019	50-250 G	OPREA, G. H.	8101290780	50-498 J
NIEVERGHE, P.	8101060609	50-321 S	O'KEIL, J. P.	8101160148	70-143 J	OPREA, G. H.	8101270924	50-498 J
NIEVERGHE, P.	8101060609	50-366 S	O'KEIL, J. P.	8101090814	70-143 J	OPREA, G. H.	8101270857	50-498 J
NIELSEN, T.	8101120036	50-321 S	O'KEIL, J. P.	8101050588	50-257 G	OPREA, G. H.	8101270494	50-498 J
NIELSEN, T.	8101260514	50-321 S	O'KEIL, J. P.	8101090577	50-324 G	OPREA, G. H.	8101160434	50-498 J
NIELSEN, T.	8101260528	50-321 S	O'KEIL, J. P.	8101090660	50-321 U	OPREA, G. H.	8101290780	50-498 J
NIELSEN, T.	8101260528	50-321 S	O'KEIL, J. P.	8101090660	50-414 G	OPREA, G. H.	8101220331	50-498 J
NIELSEN, W. A.	8101130525	40-266 J	O'KEIL, J. P.	8101060154	50-393 G	OPREA, G. H.	8101220515	50-498 J
NIELSEN, P. H.	8101220243	50-285 P	O'KEIL, J. P.	8101060203	50-327 U	OPREA, G. H.	8101270718	50-498 J
NIELSEN, P. H.	8101050781	50-498 A	O'KEIL, J. P.	8101060512	50-393 G	OPREA, G. H.	8101080177	50-269 J
NIELSEN, P. H.	8101290709	PR	O'KEIL, J. P.	8101060516	50-488 U	OPREA, G. H.	8101070157	50-369 J
NIELSEN, P. H.	8101070355	70-75	O'KEIL, J. P.	8101060525	50-289 G	OPREA, G. H.	8101260127	50-537 A
NIELSEN, P. H.	8101060703	50-344 G	O'KEIL, J. P.	8101060703	50-261 G	OPREA, G. H.	8101060703	PR
NIELSEN, P. H.	8101060704	XPRTLIC	O'KEIL, J. P.	8101060704	50-344 G	OPREA, G. H.	8101050536	50-302 P
NIELSEN, P. H.	8101060707	70-1257	O'KEIL, J. P.	8101060707	50-302 G	OPREA, G. H.	8101210450	PR
NIELSEN, P. H.	8101060707	70-1257	O'KEIL, J. P.	8101060707	50-424 U	OPREA, G. H.	8101290780	RES
NIELSEN, P. H.	8101210653	70-1257	O'KEIL, J. P.	8101060707	50-437 G	OPREA, G. H.	8101140923	NUREG
NIELSEN, P. H.	8101160362	70-25	O'KEIL, J. P.	8101060707	50-321 G	OPREA, G. H.	8101220515	71-574 J
NIELSEN, P. H.	8101270554	50-133 G	O'KEIL, J. P.	8101060153	50-257 G	OPREA, G. H.	8101090608	50-10 J
NIELSEN, P. H.	8101270554	50-208 G	O'KEIL, J. P.	8101060162	50-416 G	OPREA, G. H.	8101230354	50-289 J
NIELSEN, P. H.	8101270554	70-25	O'KEIL, J. P.	8101060162	50-324 G	OPREA, G. H.	8101270614	50-10 J
NIELSEN, P. H.	8101060142	50-207 G	O'KEIL, J. P.	8101070023	50-518 G	OPREA, G. H.	8101270737	50-10 J
NIELSEN, P. H.	8101220102	50-315 G	O'KEIL, J. P.	8101070023	50-257 G	OPREA, G. H.	8101260650	50-272 S
NIELSEN, P. H.	8101270554	50-346 G	O'KEIL, J. P.	8101070037	50-321 G	OPREA, G. H.	8101200221	50-312 S
NIELSEN, P. H.	8101260197	50-289 H	O'KEIL, J. P.	8101070037	50-416 G	OPREA, G. H.	8101160288	50-324 J
NIELSEN, P. H.	8101150332	PR	O'KEIL, J. P.	8101070037	50-324 U	OPREA, G. H.	8101070628	PR
NIELSEN, P. H.	8101100525	CONTRACT	O'KEIL, J. P.	8101050156	50-259 G	OPREA, G. H.	8101070630	PR
NIELSEN, P. H.	8101260620	50-275 J	O'KEIL, J. P.	8101050156	50-416 G	OPREA, G. H.	8101070582	PR
NIELSEN, P. H.	8101260620	50-275 G	O'KEIL, J. P.	8101050159	50-321 G	OPREA, G. H.	8101200255	50-287 J
NIELSEN, P. H.	8101090822	XPRTLIC	O'KEIL, J. P.	8101050161	50-324 G	OPREA, G. H.	8101090047	TCPEP
NIELSEN, P. H.	8101120027	XPRTLIC	O'KEIL, J. P.	8101050161	50-318 G	OPREA, G. H.	8101220526	TCPEP
NIELSEN, P. H.	8101060655	XPRTLIC	O'KEIL, J. P.	8101100846	50-302 G	OPREA, G. H.	810120559	RES
NIELSEN, P. H.	8101070542	XPRTLIC	O'KEIL, J. P.	8101140205	50-250 P	OPREA, G. H.	8101270763	RES
NIELSEN, P. H.	8101100485	XPRTLIC	O'KEIL, J. P.	8101160831	50-324 G	OPREA, G. H.	8101150195	50-215 G
NIELSEN, P. H.	8101120106	XPRTLIC	O'KEIL, J. P.	8101270676	70-1117	OPREA, G. H.	8101070537	WASTE MGT
NIELSEN, P. H.	8101120188	XPRTLIC	O'KEIL, J. P.	8101220526	50-247 P	OPREA, G. H.	8101200456	PR
NIELSEN, P. H.	8101210105	XPRTLIC	O'KEIL, J. P.	8101140316	50-247 R	OPREA, G. H.	8101050342	50-250 S
NIELSEN, P. H.	8101220587	XPRTLIC	O'KEIL, J. P.	8101060679	50-247 G	OPREA, G. H.	8101090349	50-353 J
NIELSEN, P. H.	8101120158	XPRTLIC	O'KEIL, J. P.	8101090467	50-247 S	OPREA, G. H.	8101090342	50-250 S
NIELSEN, P. H.	8101100474	XPRTLIC	O'KEIL, J. P.	8101090467	50-247 S	OPREA, G. H.	8101090449	50-335 S
NIELSEN, P. H.	8101100480	XPRTLIC	O'KEIL, J. P.	8101060461	50-247 P	OPREA, G. H.	8101090353	50-230 S
NIELSEN, P. H.	8101100475	XPRTLIC	O'KEIL, J. P.	8101060453	50-247 P	OPREA, G. H.	8101090349	50-231 S
NIELSEN, P. H.	8101100442	XPRTLIC	O'KEIL, J. P.	8101060454	50-247 P	OPREA, G. H.	8101090547	50-231 S
NIELSEN, P. H.	8101100453	XPRTLIC	O'KEIL, J. P.	8101270194	50-247 G	OPREA, G. H.	8101130334	50-230 S
NIELSEN, P. H.	8101100461	XPRTLIC	O'KEIL, J. P.	8101130364	50-247 V	OPREA, G. H.	8101130365	50-331 S
NIELSEN, P. H.	8101200446	XPRTLIC	O'KEIL, J. P.	8101220139	50-247 U	OPREA, G. H.	8101130372	50-331 S
NIELSEN, P. H.	8101280394	XPRTLIC	O'KEIL, J. P.	8101220147	50-247 G	OPREA, G. H.	8101130377	50-230 S
NIELSEN, P. H.	8101290477	XPRTLIC	O'KEIL, J. P.	8101220140	50-247 G	OPREA, G. H.	8101130392	50-230 S
NIELSEN, P. H.	8101290653	XPRTLIC	O'KEIL, J. P.	8101290671	50-247 P	OPREA, G. H.	8101210038	70-925
NIELSEN, P. H.	8101290653	XPRTLIC	O'KEIL, J. P.	8101210434	50-247 S	OPREA, G. H.	8101100201	70-238
NIELSEN, P. H.	8101290476	XPRTLIC	O'KEIL, J. P.	8101210591	50-247 P	OPREA, G. H.	8101090343	70-1007
NIELSEN, P. H.	8101070310	50-272 G	O'KEIL, J. P.	8101230582	50-3 R	OPREA, G. H.	8101070626	70-687
NIELSEN, P. H.	8101146700	50-387 G	O'KEIL, J. P.	8101230315	50-247 G	OPREA, G. H.	8101070561	70-371
NOVAK, T. H.	8101130694	50-285 G	O'KEIL, J. P.	8101220262	50-247 P	OPREA, G. H.	8101070564	70-27
NOVAK, T. H.	8101050417	50-302 G	O'KEIL, J. P.	8101230589	50-3 F	OPREA, G. H.	8101280380	PR
NOVAK, T. H.	8101160330	50-315 P	O'KEIL, J. P.	8101270679	50-247 G	OPREA, G. H.	8101120554	70-2627
NOVAK, T. H.	8101150593	50-317 P	O'KEIL, J. P.	8101270724	50-247 S	OPREA, G. H.	8101220212	70-1738
NOVAK, T. H.	8101150692	50-338 F	OWARD, J.	8101220550	PR	OPREA, G. H.	8101140780	70-2373
NOVAK, T. H.	8101100448	50-267 P	OWARD, J.	8101190264	PR	OPREA, G. H.	8101140798	70-1257
NOVAK, T. H.	8101270127	50-285 V	OWARD, J.	8101190497	PR	OPREA, G. H.	8101220192	70-682
NOVAK, T. H.	8101290799	50-336 P	OWARD, J.	8101140858	50-373 G	OPREA, G. H.	8101230319	70-882
NOVAK, T. H.	8101280639	50-313 P	OWARD, J.	8101130389	50-275 A	OPREA, G. H.	8101230323	70-27
NOVAK, T. H.	8101290016	50-70 P	OWARD, J.	8101150333	50-209 H	OPREA, G. H.	8101280410	70-27
NOVAK, T. H.	8101190329	50-322 S	OWARD, J.	8101150358	50-209 H	OWARD, J.	8101060204	50-282 J
NOVAK, T. H.	8101270112	PR	OWARD, J.	8101150358	04997	OWARD, J.	8101190218	PR
NOVAK, T. H.	8101050109	50-322 A	OWARD, J.	8101150358	04997	OWARD, J.	8101200519	50-295 S
NOVAK, T. H.	8101060485	50-322 S	OWARD, J.	8101140614	PR	OWARD, J.	8101120343	50-295 S
NOVAK, T. H.	8101070299	70-2249	OWARD, J.	8101090223	50-275 G	OWARD, J.	8101130536	50-295 S
NOVAK, T. H.	8101230664	PR	OWARD, J.	8101140279	50-275 G	OWARD, J.	8101100521	50-278 J
NOVAK, T. H.	8101270581	40-2259	OWARD, J.	8101140536	50-389 G	OWARD, J.	8101140128	50-361 S
NOVAK, T. H.	8101230278	PR	OWARD, J.	8101160217	50-389 G	OWARD, J.	8101210354	50-361 S
NOVAK, T. H.	8101100103	50-312 G	OWARD, J.	8101200210	50-329 G	OWARD, J.	8101290507	50-361 S
NOVAK, T. H.	8101070537	WASTE MGT	OWARD, J.	8101270737	50-275 G	OWARD, J.	8101130367	PR

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PAPERIELLO, C. J.	8101090114	50-295 Q	PASTERNAK, R. J.	8101210399	50-333 S	PETRICK, H. A.	8101050355	50-333 S
PAPERIELLO, C. J.	8101070125	50-10 Q	PASTERNAK, R. J.	8101260126	50-333 S	PETRICK, H. A.	8101290264	50-333 S
PAPERIELLO, C. J.	8101080420	0A999	PASTVA, M. J.	8101130568	50-324 S	PETRICK, H. A.	8101230565	50-333 S
PAPERIELLO, C. J.	8101132640	50-295 Q	PASTVA, M. J.	8101140514	50-324 S	PETROME, C.	8101300072	50-333 S
PAPERIELLO, C. J.	8101140898	50-373 Q	PASTVA, M. J.	8101200620	50-324 S	PETTERGILL, H.	8101201544	40-333 S
PAPERIELLO, C. J.	8101260729	50-346 Q	PASTVA, M. J.	8101200629	50-325 S	PETTERGILL, H. J.	8101290200	40-333 S
PAPAS, H.	8101090312	DRQ	PASTVA, M. J.	8101130540	50-324 S	PEVENSTEIN, J. E.	8101260459	FOI
PASA, A.	8101200451	PR	PASTVA, M. J.	8101260595	50-325 S	PEVENSTEIN, J. E.	8101200464	FOI
PASK, M. A.	8101230329	PR	PASTVA, M. J.	8101270631	50-325 S	PEVENSTEIN, J. E.	8101260469	FOI
PARKER, W. D.	8101070316	50-413 Q	PASTVA, M. J.	8101270708	50-324 S	PEVENSTEIN, J. E.	8101260474	FOI
PARKER, W. D.	8101070320	50-369 Q	PASTVA, M. J.	8101280382	50-324 S	PEVENSTEIN, J. E.	8101260451	FOI
PARKER, W. D.	8101080148	50-269 Q	PASTVA, M. J.	8101270595	50-329 S	PEVENSTEIN, J. E.	8101260470	FOI
PARKER, W. D.	8101280341	PR	PASTVA, M. J.	8101270695	50-324 S	PHILLIPS, G. S.	8101260557	ACN
PARKER, W. D.	8101070313	50-413 Q	PASTVA, M. J.	8101270794	50-324 S	PHILLIPS, J. H.	8101270519	50-333 S
PARKER, R.	8101210095	PH	PASTVA, M. J.	8101270605	50-324 S	PHILLIPS, G. A.	8101050142	50-333 S
PARKER, W. D.	8101070295	REGOOD	PASTVA, M. J.	8101270607	50-324 S	PHILLIPS, H. P.	8101090114	50-333 S
PARKER, W. D.	8101120038	REGOOD	PASUPATHI, V.	8101290568	50-213 S	PHILLIPS, H. P.	8101070175	50-333 S
PARKER, W. D.	8101070145	50-369 Q	PATENAUC, C. J.	8101230188	RES	PHILLIPS, H. P.	8101150240	50-333 S
PARKER, W. D.	8101150136	50-269 Q	PATON, W. D.	8101050503	50-329 T	PHILLIPS, L.	8101270012	PR
PARKER, W. D.	8101150907	50-369 Q	PATON, W. D.	8101050421	50-329 G	PHILLIPS, L. E.	8101210225	50-333 S
PARKER, W. D.	8101150168	50-369 F	PATON, W. D.	8101050573	50-329 G	PHILPOT, F. T.	8101220380	50-333 S
PARKER, W. D.	8101200237	50-269 P	PATON, W. D.	8101140872	50-329 G	PHILPOT, F. T.	8101240725	7A
PARKER, W. D.	8101160668	50-413 Q	PATON, W. D.	8101270327	50-329 G	PHILPOT, F. J.	8101300164	7A
PARKER, W. D.	8101050107	50-287 P	PATON, W. D.	8101270594	50-329 G	PICKARD, A. R.	8101200532	PR
PARKER, W. D.	8101150765	50-369 Q	PATTERSON, H. G.	8101090507	FOIA	PICKARD, R. C.	8101220372	PR
PARKER, W. D.	8101090949	50-269 P	PATTERSON, J. P.	8101050598	70-27	PIERCE, B. L.	8101220523	REG
PARKER, W. D.	8101090351	50-287 S	PATTERSON, J. L.	8101210369	FR	PIERCE, C.	8101163149	PR
PARKER, W. D.	8101060483	50-269 P	PAITEN, L.	8101260302	PR	PIERSON, H. D.	8101200214	50-333 S
PARKER, W. D.	8101160258	50-269 Q	PATTEN, L. C.	8101260307	PR	PICOTT, D. R.	8101230128	50-333 S
PARKER, W. D.	8101160724	50-369 Q	PATTERSCH, T. L.	8101160488	50-208 H	PICOTT, D. R.	8101230137	50-333 S
PARKER, W. D.	8101070269	50-269 P	PATTON, G. A.	8101330059	FR	PICOTT, D. R.	8101230128	50-333 S
PARKER, W. D.	8101090657	50-207 S	PAUL, T. W.	8101160226	50-259 G	PICOTT, D. R.	8101230177	50-333 S
PARKER, W. D.	8101190462	50-369 F	PAUL, J. J.	8101130371	50-241 H	PILANT, J. H.	8101070542	50-333 S
PARKER, W. D.	8101220133	50-369 A	PAULSON, H. A.	8101230347	50-155 P	PILANT, J. H.	8101080074	50-333 S
PARKER, W. D.	8101290404	50-367 Q	PAULY, S. A.	8101140225	50-409 J	PILANT, J. H.	8101070155	50-333 S
PARKER, W. D.	8101290408	50-413 Q	PAYNE, J. D.	8101290508	PR	PILANT, J. H.	8101200550	50-333 S
PARKER, W. D.	8101200575	50-269 Q	PEARLMAN, C.	8101260559	PR	PILANT, J. H.	8101129150	50-333 S
PARKER, W. D.	8101130404	50-269 P	PEABE, E. A.	8101190177	PR	PILANT, J. H.	8101050465	50-333 S
PARKER, W. D.	8101140600	50-413 S	PECK, C. C.	8101100611	50-6 Q	PILANT, J. H.	8101120162	50-333 S
PARKER, W. D.	8101210213	50-269 Q	PETERS, S. C.	8101270228	FR	PILANT, J. H.	8101160348	50-333 S
PARKER, W. D.	8101290577	50-269 F	PELLLETIER, D. C.	8101150105	PR	PILAT, E. E.	8101080443	50-333 S
PARKER, W. D.	8101290492	50-369 Q	PENCE, W. B.	8101220390	50-318 G	PILKERSHOT, T.	8101190232	PR
PARKER, W. D.	8101160443	50-369 F	PENCE, W. B.	8101130623	50-317 S	PIMSLER, H.	8101280359	PR
PARKER, W. D.	8101260513	50-369 S	PENCE, W. B.	8101230461	50-318 S	PINSKY, R.	8101300094	PR
PARKER, W. D.	8101300576	50-270 S	PENCE, W. B.	8101330538	50-317 S	PIRTLE, G. L.	8101060390	50-333 S
PARKER, W. D.	8101160366	50-269 P	PENDERGRAFT, R.	8101050367	50-368 S	PISCELL, D. H.	8101300422	PR
PARKER, W. D.	8101230493	50-369 A	PENDERGRAFT, R.	8101210514	50-368 R	PITCHER, D.	8101220127	PR
PARKER, W. D.	8101190385	50-269 Q	PEOPLES, D. L.	7911270339	50-10 P	PITTS, M.	8101160160	PR
PARKER, W. D.	8101210511	50-287 S	PEOPLES, D. L.	0003240464	50-237 P	PLESSET, H. B.	8101202078	ACR
PARKER, W. D.	8101210462	50-269 R	PEPPER, A. H.	8101330287	PR	PLESSET, H. B.	8101070545	50-333 S
PARKER, W. D.	8101210493	50-269 P	PERCY, G. W.	8101210345	50-230 P	PLETTMAN, S.	8101230304	50-333 S
PARKER, W. D.	8101210502	50-269 S	PEREZ, M.	8101160540	PR	PLEVER, B.	8101190624	PR
PARKER, W. D.	8101220420	50-269 P	PEREZ, C. A.	8101200327	50-465 Q	PLUMLEE, K. E.	8101300408	50-333 S
PARKER, W. D.	8101220378	50-269 S	PERKINS, J.	8101330669	PR	PLUMLEE, K.	8101280374	50-333 S
PARKER, W. D.	8101230440	50-269 F	PERLMAN, J.	8101060942	CONTRACT	POANNIDI, J.	8101130112	50-333 S
PARKER, W. D.	8101230489	50-269 S	PERLMAN, J.	8101070319	50-367 A	POCHAL, W. F.	8101100525	XP
PARKER, W. D.	8101270640	50-270 S	PERLMAN, J.	8101060770	CONTRACT	POCHAL, W. F.	8101230127	XP
PARKER, W. D.	8101300160	50-369 A	PERLMAN, J.	8101290341	CONTRACT	POCOLO, A. J.	8101270193	RES
PARKER, W. D.	8101300436	50-369 F	PERLMAN, J.	8101270723	50-320 P	POCOLO, A. J.	8101260074	RES
PARKER, W. D.	8101190229	70-371	PERLMAN, J.	8101200471	CONTRACT	POINDEXTER, C. H.	8101060333	50-333 S
PARR, D. D.	8101060353	50-369 A	PERLMAN, J.	8101200480	CONTRACT	POLLARD, R. O.	8101130047	50-333 S
PARTLOW, J. O.	8012100344	70-734	PERLMAN, J.	8101290530	50-70 P	POLLOCK, H. S.	8101070446	50-333 S
PARTLOW, J. O.	8012100327	70-364	PERLMAN, J.	8101290541	50-70 P	POPEROV, P. U.	8101200473	CCN
PARTLOW, J. O.	8101060861	50-409 P	PERLMAN, J.	8101200432	CONTRACT	POPERANTZ, L.	8101200487	PR
PARTLOW, J. O.	8101060873	50-213 P	PERLMAN, J.	8101270741	CONTRACT	POPPAN, R. K.	8101210301	PR
PARTLOW, J. O.	8101150029	70-27	PERLMAN, J.	8101300104	50-390 A	POOLE, D.	8101160438	50-333 S
PARTLOW, J. O.	8101060924	70-820	PERMAL, P.	8101200468	PR	POOLE, D.	8101210512	50-333 S
PARTLOW, J. O.	8101080398	70-143	PERNEY, C. D.	8101220095	50-395 Q	PORTER, W. E.	8101200252	50-333 S
PARTLOW, J. O.	8101120214	70-371	PERRIC, L. D.	8101220228	RES	PORTER, Y. B.	8101200275	PR
PARTLOW, J. O.	8101120219	70-143	PERRY, R. H.	8101220249	RES	PORTER, A.	8101290512	PR
PARTLOW, J. O.	8101190262	70-820	PERRY, L.	8101270340	PR	PORTER, W. L.	8101050416	50-333 S
PARTLOW, J. O.	8101190260	70-1100	PERSON, R.	8101070272	40-299	PORTER, W. L.	8101070062	50-333 S
PARTLOW, J. O.	8101190244	70-143	PERTES, L.	8101220602	PR	PORTER, W. L.	8101160620	50-333 S
PARTNER, A. S.	8101270723	50-320 P	PESCHAU, D. F.	8101050309	50-409 H	PORTER, W. L.	8101260207	50-333 S
PARTNER, A. A.	8101220188	RES	PESL, M.	8101190057	PR	POSE, K.	8101270811	PR
PASI, U.	8101210143	PR	PESTOCE, S.	8101230617	PR	POTAPOV, U.	8101200417	0A9
PASTERNAK, R. J.	8101300074	50-333 Q	PETERSON, H. R.	8101100230	FOIA	POTAPOV, U.	8101150598	0A9
PASTERNAK, R. J.	8101080129	50-333 Q	PETERSON, A. S.	8101080335	50-320 H	POTAPOV, U.	8101260653	0A9
PASTERNAK, R. J.	8101140766	50-333 Q	PETERS, T. J.	8101200544	PR	POTAPOV, U.	8101150450	0A9
PASTERNAK, R. J.	8101140975	50-333 Q	PETERSON, R. W.	8101260245	50-320 Q	POTAPOV, U.	8101210255	0A9
PASTERNAK, R. J.	8101130552	50-333 R	PETERSON, D. W.	8101210380	50-250 P	POTAPOV, U.	8101190760	0A9
PASTERNAK, R. J.	8101203302	50-333 S	PETERSON, H. E.	8101270731	50-265 J	POTAPOV, U.	8101210510	0A9
PASTERNAK, R. J.	8101203306	50-333 S	PETIT, R.	8101140214	50-443 H	POTAPOV, U.	8101150374	0A9
PASTERNAK, R. J.	8101160508	50-333 S	PETIT, R.	8101090160	50-443 H	POTAPOV, U.	8101270970	0A9
PASTERNAK, R. J.	8101210492	50-333 S	PETRIE, E. R.	8101160066	PR	POTAPOV, U.	8101150345	0A9

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
POLAROV, U	810115410*	04999	RATHBURN, D	8101160153*	COMMISSION	REYNOLDS, J R	8101160278	50-275
POLAROV, U	8101230306*	04999	RAVINSBERGER	8101230379*	State Prog	REYNOLDS, H S	8101160233	50-445
POLAROV, U	8101150379	04999	RATHLEBERGER	8101070497	50-395 D	REYNOLDS, H S	8101160233	50-445
POLAROV, U	8101230125	04999	RATTA, A D	8101300196*	70-135	RHADS, O G	8101090869*	50-387
POLAROV, U	8101270750*	04999	RAUSCH, T J	8101070214	50-293 Q	RHADS, O G	8101100244*	50-277
POLAROV, U	8101150441	04999	RAUSCH, T J	81010803273	50-10 Q	RHADS, O G	8101150861*	50-387
POLAROV, U	8101190582	04999	RAUSCH, T J	8101130667	50-373 Q	RHADS, O G	8101060545*	50-289
POLAROV, U	8101200310	04999	RAUSCH, T J	8101303155	50-10 Q	RHADS, O G	8101130239	50-410
POLAROV, U	8101270451	04999	RAUSCH, T J	8101230578	50-373 Q	RHADS, O G	8101300452*	50-410
POLAROV, U	8101150435	04999	RAUSCH, T J	8101280313	50-434 Q	RHADS, O G	8101300100	PR
POLAROV, U	8101150326	04999	RAUSCH, T J	8101280436	50-454 Q	RICCABELLA, P	8101270655*	50-353
POLAROV, U	8101270306*	04999	RAVINSBERGER	8101160208	70-2322	RICE, T R	8101300009	50-353
POLAROV, U	8101210401*	04999	RAYMOND, H J	8101100193*	50-271 Q	RICHARDSON, S D	81012200207	PRQ
POLAROV, U	8101270122*	27-47	RAYMOND, H J	8101160337*	50-271 Q	RICHARDSON, J H	81012200008	PRQ
POLAROV, U	8101150554*	50-324 S	REAVIS, J A	8101210464*	50-269 R	RICHARDSON, C	8101300004	PR
POLAROV, U	8101150553*	50-324 S	REED, C	7903190002	50-10 P	RICHARDSON, J E	81011400356	4150
POLAROV, U	8101270400*	50-324 S	REED, S A	8101140555	PR	RICHING, D	8101270320	PR
POLAROV, U	8101220409*	50-324 S	REED, C	8101130537	50-237 P	RIDGE, R C	8101210169	PR
POLAROV, U	8101230521	PR	REEVES, F P	8101300606	PR	RIDGEWAY, D A	8101270343	50-482
POLAROV, U	8101270119	50-362 A	REEVES, E	8101270106	50-348 Q	RIDGEWAY, D A	8101270360	50-482
POYER, R W	81011250589	40-2259	REGAN, A	8101280425	PR	RIDGEWAY, D A	8101280048	50-482
PRACHUNTHAN, S	8101220326	RES	REGHITTO, A J	81010703165	50-209 H	RIDGEWAY, D A	8101270343	50-482
PRASINOS, P O	8101060104	RES	REHMAN, P F L J	8101270353*	50-445 A	RIDGEWAY, D A	8101270360	50-482
PREDSTIN, G	8101270301	PR	REHM, T A	8101100197	COMMISSION	RIDGEWAY, D A	8101280348	50-482
PRIEDT, J	8101220110	PR	REHM, T A	8101150714	COMMISSION	RIDGEWAY, K R	8101160382*	50-151
PRINCE, P F	8101050742*	50-289 1	REICHENBERG, D	8101070742	50-361 H	RIDGWAY, K R	8101210647*	50-409
PRINCE, P F	8101290749*	50-282 S	REICH, S	8101210544	PR	RIDGWAY, K R	8101210810*	50-111
PRINCE, P F	8101290746*	50-282 S	REID, R W	8101070713	50-346 P	RIDGWAY, K R	8101210810*	50-111
PRINCE, P F	8101290567*	50-263 H	REID, R W	8101150094*	50-289 Q	RIDGWAY, K R	8101210810*	50-111
PRINCE, P F	8101090500*	TCRPREP	REID, R W	8101150084	50-289 Q	RIDGWAY, K R	8101130159	50-247
PUCILLO, A C	8101150129*	CONTRACT	REID, R W	8101080052	50-302 Q	RILEY, M	8101270439	PR
PUCILLO, A C	8101150129*	50-302 Q	REID, R W	8101070175	50-269 P	RINTRA, H	8101260032	PR
PUCILLO, A C	8101080121	50-302 Q	REID, R W	8101090184*	50-269 P	RIRDMAN, H D	8101210579	PR
PUCILLO, A C	8101150174*	FOIA	REID, R W	8101090205*	50-269 P	RISCHLING, J	8101080397*	50-316
PUCILLO, A C	8101210579*	FOIA	REID, R W	8101190786	50-289 F	RISCHLING, J	8101080406*	50-316
PUGH, A J	8101230005	PR	REID, R W	8101190791*	50-289 F	RISCHLING, J L	8101090692*	50-315
QUATTROCIANI, J	8101090496	50-320 J	REID, R W	8101270197	FOIA	RISCHLING, J L	8101200179	50-289
QUICK, D H	8101100026*	50-251 Q	REID, R W	8101120023*	50-313 P	RITTER, M	8101210618	PR
QUIGLEY, T H	8101270320	40-8743	REID, R W	8101070570	50-269 G	RIVERA, A	8101160618	PR
QUIGLEY, T H	8101270320	40-8743	REID, R W	8101070463	50-313 F	RIZZO, R	8101260594	PR
QUILLER, J H	8101140946*	70-143	REID, R W	8101070467	50-346 F	RIZZO, P G	8101150543*	50-318
QUILLER, J H	8101060523	CONTRACT	REID, R W	8101120020	50-277 V	RIZZO, P G	8101230526*	50-317
QUILLER, J H	8101090198	10PREP	REID, R W	8101070565*	50-269 P	RIZZO, P G	8101270684*	50-318
QUILLER, J H	8101130260*	70-261	REID, R W	8101070466	50-277 P	RIZZO, P G	8101300538*	50-310
QUILLER, J H	8101230272	PR	REID, R W	8101070533	50-289 Q	ROBBINS, O	8101270260	WASTE
RACKLE, W H	8101250503*	50-289 H	REID, R W	8101070558	50-269 P	ROBERTS, T H	8101190513	NUREG
RACKLE, W H	8101270320	71-403	REID, R W	8101070558	50-313 P	ROBERTSON, J G	8101140375*	CONTRACT
RACKLE, W H	8101280317	PR	REID, R W	8101090753*	50-313 P	ROBERTSON, J G	8101290591	50-369
RADCEVIC, J P	8101280496*	50-244 P	REID, R W	8101090759*	50-313 P	ROBEY, L	8101200318	PR
RADCEVIC, J P	8101300262*	50-244 P	REID, R W	8101120060	50-312 G	ROBINSON, T	8101120046	50-275
RADCEVIC, J P	8101120353*	50-244 P	REID, R W	8101140626	50-302 P	ROBINETTE, M S	8101270049*	40-1162
RADCEVIC, J P	8101210121	PR	REID, R W	8101050049*	50-289 T	ROBINSON, E B	8101190337	PR
RAGER, M S	8101060527*	50-331 S	REID, R W	8101090470	50-321 P	ROBINSON, D L	8101290573*	50-282
RAGER, M S	8101120326*	50-331 S	REID, R W	8101100440	50-269 V	ROBINSON, D L	8101230654*	50-346
RAGER, M S	8101220343*	50-331 S	REID, R W	8101100441	50-312 Q	ROBINSON, E	8101230079	50-287
RAGER, M S	8101220335*	50-331 S	REID, R W	8101100397*	50-289 F	ROCKMOLD, H C	8101300849*	50-331
RAGER, M S	8101220401*	50-331 S	REID, R W	8101120378	50-111 P	RODRIGUEZ, D	8101190014	PR
RAGER, M S	8101280555*	50-331 S	REID, R W	8101160050	50-346 P	RODRIGUEZ, R J	8101150526	50-312
RAGER, M S	8101220348*	50-331 P	REID, R W	8101160057*	50-346 P	RODMILL, F	8101220120	PR
RACHANDAN, S	8101210401*	10PREP	REID, R W	8101160646*	50-346 P	ROGERS, W G	8101260648*	50-346
RAHIREZ, R O	8101050042*	50-289 T	REID, R W	8101200203	50-289 P	ROGERS, L L	8101200285*	50-338
RAHIREZ, R O	8101130253	PR	REID, R W	8101270799	50-269 P	ROGERS, R C	8101150318	50-289
RAMSEY, R G	8101210212	PR	REID, R W	8101300241	50-313 Q	ROGERS, L L	8101200289*	50-338
RAMSEY, J A	8101270432	PR	REIMANN, F W	8101140079*	50-293 Q	ROHATTO, U S	8101210615	RES
RAMSEY, D L	8101300420	PR	REIMANN, F W	8101090765*	50-10 Q	ROMAN, T H	8101190502*	50-220
RANDAZZA, J B	8101160114*	50-309 Q	REINSTADLER, J	8101270525	PR	ROOD, H	8101060141	50-361
RANDAZZA, J B	8101300693	50-309 Q	REIS, E J	8101290149	50-498 G	ROOD, H	8101200102	50-361
RANDAZZA, J B	8101160153	71-398	REISCH, E	8101160642	PR	ROONEY, M A	8101230049	70-1308
RANDAZZA, J B	8101060320	50-309 P	REKIFO, W	8101300723*	50-245 Q	ROONEY, M A	8101230032	70-1308
RANDAZZA, J B	8101120210	50-309 P	REKIFO, W	8101280524	50-289 S	ROONEY, M A	8101260175	70-1308
RANDAZZA, J B	8101209432*	CONTRACT	REKLEY, M E	8101140379	PR	ROOP, J E	8101270679	50-322
RANDAZZA, J B	8101120229	50-309 V	RENNAR, P A	8101220188	RES	ROOP, J E	8101270679*	50-322
RANDAZZA, J B	8101270740	50-309 P	RENNER, G A	7909170051	RECEIVED	ROOT, L D	8101200399	50-331
RANDAZZA, J B	8101270740	RES	RENSON, S	8101160112	PR	ROOT, L D	8101130631	50-331
RANDAZZA, J B	8101270578*	50-269 R	REQUA, O	8101120213	50-309 H	ROOT, L D	8101050273	50-331
RAPHIN, A	8101190632	50-367 Q	RESEAR, J C	8101120355*	50-336 S	ROOT, L D	8101200466*	50-331
RAPHIN, A	8101200046	50-367 Q	REUS, H S	8101080047	PR	ROOT, L D	8101220386	50-331
RAPHIN, A	8101200149	PR	REYES, E	8101160638	PR	ROOT, L D	8101200300	50-331
RASHID, A	8101140971	PR	REYES, L A	8101210648*	50-346 Q	ROSE, M	8101100135*	50-170
RASHID, A	8101140981	PR	REYNOLDS, H S	8101090478	50-445 C	ROSE, R	8101230372	PR
RASHID, A	8101160352	PR	REYNOLDS, H S	8101050478	50-445 G	ROSE, O A	8101270033	PR
RASHID, A	8101270583*	50-322 C	REYNOLDS, H S	8101190031	PR	ROSENTHAL, A S	8101300135	PR
RASHID, A	8101090055	50-466 Q	REYNOLDS, J R	8101140519	50-275 G	ROSENTHAL, A S	8101200080*	50-592
RASHID, A	8101090055	50-466 Q	REYNOLDS, J R	8101140519	50-275 G	ROSENTHAL, A S	8101200105*	50-580
RATHBURN, D	8101120164*	COMMISSION	REYNOLDS, J R	8101160273*	50-275 G	ROSENTHAL, A S	8101200165*	50-452

ROSENBERGER, M	B101190556	PR	SANDORNI, V	B101210615	RES	SCHNEIDER, F W	B101190557	50
ROSENBERG, S C	B101220173	PH	SANBORN, V	B101210622	RES	SCHMIDT, M	B101210579	50
ROSS, P	B101130306	PR	SANCHEZ, R	B101220410	PR	SCHONFELD, V	B101210665	50
ROSS, M J	B101050133	50-209	SANDERS, M F	B101100553	50-271	SCHROCK, C A	B101050247	50
ROSS, M J	B101050150	50-209	SANDERS, H I	B101060521	50-209	SCHROEDER, F	B101105714	50
ROSS, W J	B101200634	50-272	SANDER, M	B101260560	PH	SCHULZ, R D	B101060575	50
ROSS, W J	B101230350	50-272	SANDER, W	B101260571	PR	SCHUMACHER, M	B101230360	50
ROSS, W J	B101230356	50-334	SAPHIRE, D	B101190576	PR	SCHUMMLY, L	B101160571	50
ROSS, T K	B101200235	50-280	SARGENT, B	B101280542	PR	SCHWARTZ, C D	B101210608	50
ROTELLA, T S	B101220370	50-339	SARSOJ, B	B101130536	50-345	SCHWARTZ, J E	B101230542	50
ROTH, J	B101300177	70-1100	GASSANI, A	B101300630	50-309	SCHWENGER, A	B101060535	50
ROTH, E	B101190665	PR	BAGT, A	B101230648	RES	SCHWENGER, A	B101100556	50
ROTH, L	B101220536	PR	EASTRE, C	B101220649	RES	SCHWENGER, A	B101100564	50
ROTH, T	B101200198	50-269	GASTRE, C	B101260593	RES	SCHWENGER, A	B101210670	50
ROTH, J	B1012310266	1LE	GATTFER, F D, E	B101140291	50-375	SCHWENGER, A	B101220106	50
ROTHE, P H	B101270161	RES	BAUNDERS, Q A	B101220546	40-8693	SCHWENGER, A	B101120111	50
ROTHSCHILD, M U	B101220073	50-445	SAVAGE, Q	B101180663	PR	SCHWENGER, A	B101120114	50
ROTHSCHILD, M U	B101220078	50-445	SAWYER, A J	B101210258	PR	SCHWENGER, A	B101200557	50
ROTHSCHILD, M U	B101220082	50-445	SAWYER, B	B101190367	PR	SCHWENGER, A	B101200563	50
ROUSE, L C	B101200390	40-0511	SAWYER, W W	B101060543	50-207	SCHWENGER, A	B101200567	50
ROUSE, L C	B101100704	70-364	SCALERA, A	B101130102	PR	SCHWENGER, A	B101290527	50
ROUSE, L C	B101100709	70-364	SCALZ, M B	B101190120	PR	SCIMACCA, F W	B101290745	50
ROUSE, L C	B101160236	70-754	SCAND, A	B101260055	PR	SCINTO, J V	B101190568	50
ROUSE, L C	B101290522	70-754	SCARANO, R A	B101230540	40-1162	SCOTT, L	B101300545	50
ROUSE, M A	B101190663	SECV	SCARANO, R A	B101260535	40-1162	SCOTT, P	B101200192	50
ROWE, M D	B101220623	RES	SCARANO, R A	B101060526	40-3453	SCOTT, D J	B101060569	50
ROWLAND, K	B101190154	PH	SCARANO, R A	B101090732	WASTE MOT	SCOTT, D J	B101260571	50
ROWLES, W C	B101220582	50-346	SCARANO, R A	B101070542	WASTE MOT	SCOTT, D J	B101260586	50
ROWSON, F H	B101090756	50-302	SCARANO, R A	B101070532	WASTE MOT	SCOTT, D J	B101060467	50
ROWSON, F H	B101090766	50-302	SCARANO, R A	B101120184	40-0598	SCOTT, D J	B101060570	50
ROY, B S	B101200529	PR	SCARANO, R A	B101290010	WASTE MOT	SCOTT, D J	B101140520	50
RUSENSTEIN, L S	B101270005	50-269	SCARANO, R A	B101280616	40-0594	SCOTT, D J	B101260570	50
RUDJ, L	B101190224	PR	SCARANO, R A	B101280631	40-0594	SCOTT, D J	B101300470	50
RUIYER, Q H	B101130591	50-305	SCARANO, R A	B101290663	40-0200	SCOTT, W J	B101270578	50
RUSHMORE, J W	B101060647	50-220	SCARANO, R A	B101270028	40-0681	SCOTT, D J	B101260586	50
RUSHMORE, J W	B101060639	50-220	SCARANO, R A	B101290595	40-0681	SCOTT, J H	B101230604	50
RUSJECKI, O	B101060626	FOIA	SCATES, D	B101200499	PR	SCOTT, D J	B101270591	50
RUSLING, D H	B101140560	PR	SCIAABRACCO, P	B101200177	PR	SCOTT, D J	B101270591	50
RUSSELL, W T	B101290700	NUREG	SCIAFFSTALL, R	B101050080	50-24	SCRECHFIELD, J	B101260630	50
RUSSELL, W L	B101230587	PR	SCIAFFSTALL, R	B101030555	50-10	SEANAN, R C	B101260634	50
RUSSELL, J E	B101200019	40-6622	SCIAFFSTALL, R	B101050160	50-206	SEAY, J L	B101150673	50
RUSSELL, W T	B101160029	50-10	SCIAFFSTALL, J F	B101290506	50-346	SEAY, J L	B101140042	50
RUSSELL, L B	B101050185	50-317	SCIAFFSTALL, J F	B101210376	PR	SEAY, J L	B101140070	50
RUSSELL, L B	B101050399	50-317	SCIAFFSTALL, J L	B101070500	50-298	SEAY, J L	B101140070	50
RUSSELL, L B	B101050408	50-317	SCIAFFSTALL, R W	B101260310	PR	SEAY, J L	B101140102	50
RUSSELL, L B	B101130597	50-317	SCHERER, A E	B101070196	50-470	SEGE, O	B101140074	50
RUSSELL, L B	B101220380	50-318	SCHERER, A E	B101130284	REVIEW GRP	SEIDLE, W C	B101260570	50
RUSSELL, L B	B101130610	50-318	SCHERER, B J	B101160500	70-2623	SEIDLE, W C	B101100521	50
RUSSELL, L B	B101130617	50-317	SCHERER, A E	B101270709	TUPREP	SEIDLE, W C	B101070561	50
RUSSELL, L B	B101150934	50-310	SCHWEYER, C	B101130172	PR	SEIDLE, W C	B101070561	50
RUSSELL, L B	B101230530	50-317	SCHIFF, R F	B101290061	FOIA	SEIDLE, W C	B101080529	50
RUSSELL, L B	B101230457	50-318	SCHILLING, R K	B101160015	PR	SEIDLE, W C	B101080529	50
RUSSELL, L B	B101230523	50-317	SCHILLING, R K	B101210265	PR	SEIDLE, W C	B101100059	50
RUSSELL, L B	B101270677	50-318	SCHILLING, R K	B101230187	50-267	SEIDLE, W C	B101103171	50
RUSSELL, L B	B101300523	50-317	SCHLOSSER, L A	B101130547	CONTRACT	SEIDLE, W C	B101103260	50
RUSSELL, L B	B101300533	50-318	SCHMADT, N	B101260641	PR	SEIDLE, W C	B101103260	50
RUST, E O	B101260550	PR	SCHMADT, J R	B101260641	50-333	SEIDLE, W C	B101103260	50
RUTBERG, J	B101140893	50-382	SCHMIDT, A D	B101050524	50-250	SEIDLE, W C	B101120673	50
RUTBERG, J	B101100373	70-1739	SCHMIDT, A D	B101050524	50-335	SEIDLE, W C	B101103166	50
RUTBERG, J	B101230591	50-329	SCHMIDT, A D	B101090684	50-250	SEIDLE, W C	B101140540	50
RUTBERG, J	B101070340	FOIA	SCHMIDT, A D	B101050444	50-335	SEIDLE, W C	B101260488	50
RUTBERG, J	B101270640	PR	SCHMIDT, A D	B101160529	PR	SEIDLE, W C	B101140479	50
RUTBERG, J	B101270584	PR	SCHMIDT, A D	B101090560	50-250	SEIDLE, W C	B101260516	50
RUTBERG, J	B101050388	50-275	SCHMIDT, N	B101150283	PR	SEIDLE, W C	B101210245	50
RUTBERG, J	B101190237	PR	SCHMIDT, A D	B101090480	50-251	SEIDLE, W C	B101260592	50
RUTBERG, J	B101220314	PR	SCHMIDT, A D	B101050490	50-251	SEIDLE, W C	B101270525	50
RUTBERG, J	B101190492	PR	SCHMIDT, A D	B101130525	50-250	SEIDLE, W C	B101270572	50
RUTBERG, J	B101290703	NUREG	SCHMIDT, A D	B101130741	50-335	SEIDLE, W C	B101270918	50
RUTBERG, J	B101230304	PR	SCHMIDT, E U	B101150417	RES	SEIDLE, W C	B101290487	50
RUTBERG, J	B101260050	RES	SCHMIDT, A D	B101130545	50-335	SEIDLE, W C	B101270785	50
RUTBERG, J	B101260046	RES	SCHMIDT, A D	B101130540	50-250	SEIDLE, W C	B101080131	50
RUTBERG, J	B101220029	RES	SCHMIDT, A D	B101130553	50-250	SEIDLE, W C	B101100716	50
RUTBERG, J	B101210622	RES	SCHMIDT, H C	B101060462	50-349	SEIDLE, W C	B101100732	50
RUTBERG, J	B101190091	XPORTLIC	SCHMIDT, H C	B101120045	50-220	SEIDLE, W C	B101100748	50
RUTBERG, J	B101280562	XPORTLIC	SCHMIDT, A D	B101210414	50-259	SEIDLE, W C	B101120538	50
RUTBERG, J	B101270012	50-482	SCHMIDT, A D	B101210425	50-250	SEIDLE, W C	B101140479	50
RUTBERG, J	B101270012	PR	SCHMIDT, E R	B101220375	50-260	SEIDLE, W C	B101210072	50
RUTBERG, J	B101060509	50-269	SCHMIDT, E R	B101280548	RES	SEIDLE, W C	B101270904	50
RUTBERG, J	B101270121	40-1341	SCHMIDT, R P	B101280546	50-344	SEIDLE, W C	B101300161	50
RUTBERG, J	B101190697	PR	SCHNAUTZ, C E	B101100298	XPORTLIC	SEIDLE, W C	B101300768	50
RUTBERG, J	B101070534	RES	SCHNAUTZ, C E	B101290812	XPORTLIC	SEIDLE, W C	B101290640	50
RUTBERG, J	B101060097	RES	SCHNAUTZ, C E	B101300490	XPORTLIC	SEIDLE, W C	B101160598	50
RUTBERG, J	B101190003	PR	SCHNEIDER, F W	B101090858	50-272	SEIDLE, W C	B101210927	50
RUTBERG, J	B101230172	50-461	SCHNEIDER, B	B101290639	PR	SEIDLE, W C	B101280272	50
RUTBERG, J	B101230178	50-461	SCHNEIDER, F W	B101100768	50-272	SEIDLE, W C	B101100577	50

[illegible]

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SULLIVAN, C. J.	B10107057	50-185 P	TEDESCO, R. L.	B101070691	50-337 A	THOMPSON, A. J.	B101070633	PR
SUMNER, L. C.	B1011170527	40-2061	TEDESCO, R. L.	B1011166075	50-206 F	THOMPSON, H. L.	B101060906	50-3
SUND, D.	B101290558	FR	TEDESCO, R. L.	B101130710	50-440 A	THOMPSON, W. G.	B101270014	FR
SUTHERLAND, E.	B101160757	FR	TEDESCO, R. L.	B1011146010	50-390 A	THOMPSON, R.	B101270437	PR
SUTHERLIN, R. H.	B101102013	50-329 J	TEDESCO, R. L.	B101073616	50-358 I	THOMPSON, D.	B101130140	50-10
SUTTER, E.	B101280446	PR	TEDESCO, R. L.	B101070524	50-369 A	THOMPSON, D.	B101130159	50-247
SWANN, S. A.	B101150476	50-225 P	TEDESCO, R. L.	B101103018	50-461 A	THOMPSON, D.	B101160554	FR
SWARTY, S. A.	B101160473	50-206 P	TEDESCO, R. L.	B101120257	50-316 A	THOMPSON, D.	B101090185	50-329
SWAN, W. D.	B101100572	50-518 G	TEDESCO, R. L.	B101120265	50-413 A	THOMPSON, S. L.	B101290809	FR
SWANSON, G. T.	B101100705	40-3453	TEDESCO, R. L.	B101120269	50-553 A	THOMPSON, D.	B101290275	50-286
SWANBY, G. T.	B101060593	40-3453	TEDESCO, R. L.	B1011107952	50-424 G	THOMPSON, D.	B101200141	40-6354
SWANBY, G. T.	B101121197	40-3453	TEDESCO, R. L.	B101200301	50-395 F	THOMPSON, F. T.	B1012310388	50-52
SWANBY, G. T.	B101280205	40-3453	TEDESCO, R. L.	B101060554	50-395 A	THORNBURG, H. D.	B101260201	FR
SWANBERG, H.	B101123444	50-329 G	TEDESCO, R. L.	B101090702	50-387 A	THORNBURG, H. D.	B101070649	FR
SWANSON, J.	B101280377	PR	TEDESCO, R. L.	B101190505	50-222 A	TERNEY, R. E.	B101090056	50-289
SWANEY, D. T.	B101120576	50-269 G	TEDESCO, R. L.	B1011150176	50-413 A	TILL, C. E.	B101290819	FR
SWANSON, D. T.	B101112742	50-289 G	TEDESCO, R. L.	B101120176	50-327 E	TILLEY, L.	B101330516	FR
SMART, F. E.	B101130400	50-267 P	TEDESCO, R. L.	B1011150596	50-483 A	TILMAN, A.	B101100711	50-335
SMART, F. E.	B101080005	50-267 G	TEDESCO, R. L.	B101190400	50-327 P	TIKKO, D. R.	B101160467	50-336
SMART, F. E.	B101140191	50-267 G	TEDESCO, R. L.	B101190423	50-397 A	TIKKO, D. R.	B101160468	50-336
SMART, F. E.	B101120143	50-267 G	TEDESCO, R. L.	B101190734	50-361 D	TIKKO, D. R.	B101160470	50-334
SMART, W. H.	B101200166	PR	TEDESCO, R. L.	B101210136	50-275 D	TIKHTSEY, H.	B101260051	PR
SMART, L. L.	B101050094	50-289 T	TEDESCO, R. L.	B101130426	50-454 A	TING, W. W.	B101050143	FR
SMART, L. L.	B101090226	50-289 G	TEDESCO, R. L.	B1011160543	50-654 A	TIGDALE, H.	B101270824	PR
SMART, L. L.	B101140975	50-275 G	TEDESCO, R. L.	B101160966	50-483 C	TITUS, V.	B101230634	PR
SMART, L. L.	B101270734	50-275 G	TEDESCO, R. L.	B101160590	50-410 A	TOBIAS, M. L.	B101290796	FR
SMART, F. E.	B101270629	50-267 P	TEDESCO, R. L.	B101160537	50-352 A	TOBIAS, M. L.	B101290811	FR
SWEET, K.	B101210055	PR	TEDESCO, R. L.	B101200580	50-438 F	TONIN, J. S.	B101270272	50-528
SWEETRAV, A.	B101330057	PR	TEDESCO, R. L.	B101200582	50-395 A	TOBIN, J. S.	B101270306	50-528
SWEETLAND, P.	B101300020	50-309 G	TEDESCO, R. L.	B101210250	50-482 A	TODOROVICH, M. M.	B101140423	PR
SWIFT, W.	B101070534	RES	TEDESCO, R. L.	B101200514	50-361 E	TODOSOV, M.	B101300674	RES
SWYLER, K. J.	B101220523	RES	TEDESCO, R. L.	B101120015	50-438 F	TODT, M.	B101270310	PR
SWYLER, K.	B101290050	RES	TEDESCO, R. L.	B101150058	50-311 P	YUKAR, M.	B101270943	FR
SYLVIA, B. R.	B101070309	50-338 G	TEDESCO, R. L.	B101220109	50-329 A	TOLL, I. S.	B101270873	50-324
SYLVIA, B. R.	B101070707	50-338 G	TEDESCO, R. L.	B101210549	50-307 F	TOLL, I. S.	B101300502	50-325
SYLVIA, B. R.	B101070794	50-338 G	TEDESCO, R. L.	B101270070	50-327 E	TOLL, I. S.	B101300507	50-325
SYLVIA, B. R.	B101150114	50-335 G	TEDESCO, R. L.	B101270110	50-445 A	TOLL, I. S.	B101300568	50-325
SYLVIA, B. R.	B101160696	50-280 D	TEDESCO, R. L.	B101210621	50-361 A	TOLL, I. S.	B101300572	50-325
SYLVIA, B. R.	B101120120	50-280 J	TEDESCO, R. L.	B101270821	50-350 A	TOLL, I. S.	B101230491	50-324
SYLVIA, B. R.	B1012300480	50-339 P	TEDESCO, R. L.	B101270966	50-395 F	TOLL, I. S.	B101050033	50-324
SYLVIA, B. R.	B101120515	50-280 G	TEDESCO, R. L.	B101300219	50-341 A	TOLL, I. S.	B101300565	50-324
SYLVIA, B. R.	B101060345	50-338 P	TEDESCO, R. L.	B101300637	50-350 A	TOLL, I. S.	B101090029	50-324
SYLVIA, B. R.	B101050352	50-338 P	TEDESCO, R. L.	B101300621	50-445 A	TOLL, I. S.	B101050401	50-324
SYLVIA, B. R.	B101060308	50-280 P	TEDESCO, R. L.	B101300791	50-350 A	TOLL, I. S.	B101070370	50-324
SYLVIA, B. R.	B101190357	50-281 G	TEDESCO, R. L.	B101290775	50-395 A	TOLL, I. S.	B101070373	50-324
SYLVIA, B. R.	B101090588	50-339 P	TEDESCO, R. L.	B101300230	50-390 F	TOLL, I. S.	B101070498	50-324
SYLVIA, B. R.	B101090474	50-281 S	TEDESCO, R. L.	B101300818	50-373 A	TOLL, I. S.	B101070365	50-324
SYLVIA, B. R.	B101290396	50-280 G	TEDESCO, R. L.	B101300625	50-307 A	TOLL, I. S.	B101070360	50-324
SYLVIA, B. R.	B1011306248	50-339 V	TEDESCO, R. L.	B101290319	50-373 G	TOLL, I. S.	B101070491	50-324
SYLVIA, B. R.	B101190483	50-280 P	TEDESCO, R. L.	B101290195	50-498 G	TOLL, I. S.	B101070493	50-324
SYLVIA, B. R.	B101200215	50-280 R	TEDESCO, R. L.	B101260766	PR	TOLL, I. S.	B101070502	50-324
SYLVIA, B. R.	B101200218	50-338 P	TEDESCO, R. L.	B101270573	50-269 R	TOLL, I. S.	B101290288	50-324
SYLVIA, B. R.	B101200278	50-338 R	TENZER, B. E.	B101290335	FR	TOLL, I. S.	B101090911	50-324
SYLVIA, B. R.	B101220326	50-338 P	TENZER, B. E.	B101290304	FR	TOLL, I. S.	B101090667	50-325
SYLVIA, B. R.	B101220354	50-280 P	TENZER, B. E.	B101290298	FR	TOLL, I. S.	B101090676	50-325
SYLVIA, B. R.	B101230460	50-339 P	TENZER, B. E.	B101290290	FR	TOLL, I. S.	B101130548	50-324
SYLVIA, B. R.	B101290757	50-338 P	TENZER, B. E.	B101290297	FR	TOLL, I. S.	B101130561	50-324
SYNTHETIC, D.	B101190021	PR	TENZER, B. E.	B101290116	FR	TOLL, I. S.	B101110500	50-324
SZABAT, S.	B101190200	PR	TENZER, B. E.	B101290124	FR	TOLL, I. S.	B101200624	50-324
T'NIEMI, H. D.	B101130551	50-295 S	TENZER, B. E.	B101190840	QA997	TOLL, I. S.	B101200626	50-325
TAKAR, M.	B101060928	50-382 A	TERRY, J.	B101140586	PR	TOLL, I. S.	B101130535	50-324
TALBOT, P.	B101150222	PR	TERRY, J. L.	B101190461	PR	TOLL, I. S.	B101050532	50-324
TAL, J. D.	B101210375	TOPREP	TESAREK, J. J.	B101060767	50-285 B	TOLL, I. S.	B101160826	50-324
TAPIA, J. I.	B101140556	50-498 G	TESAREK, J. J.	B101130387	50-285 S	TOLL, I. S.	B101160581	50-324
TAPIA, J. I.	B101210075	50-458 G	TEST, R. Z.	B101090632	50-213 B	TOLL, I. S.	B101210409	50-324
TATELHAY, J.	B101220487	PR	THIES, A. C.	B101270643	50-287 S	TOLL, I. S.	B101220399	50-325
TAYLOR, R. G.	B101100063	50-445 G	THOM, T.	B101130580	50-259 R	TOLL, I. S.	B101220393	50-325
TAYLOR, D.	B101210307	PR	THOM, T.	B101130601	50-259 R	TOLL, I. S.	B101220405	50-324
TAYLOR, R.	B101140930	PORTALIC	THOMAS, W. D.	B101130112	50-395 A	TOLL, I. S.	B101290586	50-324
TAYLOR, J. J.	B101140796	CONTRACT	THOMAS, R. D.	B101290542	70-734	TOLL, I. S.	B101270627	50-325
TAYLOR, J. H.	B101230730	50-344 S	THOMAS, W. S.	B101190320	PR	TOLL, I. S.	B101270703	50-324
TAYLOR, J. H.	B101210359	TOPREP	THOMAS, B.	B101300010	PR	TOLL, I. S.	B101280278	50-324
TAYLOR, J. H.	B101220490	REVIEW GRP	THOMAS, J. W.	B101220074	PR	TOLL, I. S.	B101270587	50-325
TEDESCO, R. L.	B1011060523	TOPREP	THOMAS, E. B.	B101050077	50-341 K	TOLL, I. S.	B101270688	50-324
TEDESCO, R. L.	B101150311	TOPREP	THOMAS, W. H.	B101200229	50-280 P	TOLL, I. S.	B101270768	50-324
TEDESCO, R. L.	B101060011	50-311 F	THOMAS, W. H.	B101220369	50-339 P	TOLL, I. S.	B101270600	50-324
TEDESCO, R. L.	B101090552	50-390 A	THOMAS, W. H.	B101300193	50-280 P	TOLL, I. S.	B101270800	50-324
TEDESCO, R. L.	B101060119	50-395 A	THOMAS, W. H.	B101300188	50-338 P	TOLL, I. S.	B101100269	50-498
TEDESCO, R. L.	B101060296	50-327 P	THOMPSON, D.	B101290362	FR	TOLL, I. S.	B101290508	50-382
TEDESCO, R. L.	B101060036	50-416 G	THOMPSON, D.	B101090179	FR	TOLL, I. S.	B101050613	50-155
TEDESCO, R. L.	B101060012	50-275 F	THOMPSON, S. L.	B101270861	FR	TOMPKINS, B. A.	B101090107	50-456
TEDESCO, R. L.	B101060059	50-461 A	THOMPSON, D.	B101090202	FR	TOMPKINS, B. A.	B101090341	50-369
TEDESCO, R. L.	B101100016	50-27 F	THOMPSON, D.	B101090213	FR	TOMPKINS, B. A.	B101260598	PR
TEDESCO, R. L.	B101100795	50-311 E	THOMPSON, A. J.	B101070638	PR	TOMPKINS, B. A.	B101090785	50-10
TEDESCO, R. L.	B101070682	50-311 E				TOOLE, Y.	B101290737	50-289

[illegible]

[illegible]

CORPORATE SOURCE INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Aercon Industries Services, Inc.	8101060626	FOIA
Access Corp.	8101050189*	CONTRACT
	8101090399*	CONTRACT
Aerospace Corp.	8101290341*	CONTRACT
Aerotest Operations	8101060429	50-228 F
	8101220323	50-228 P
Agriculture, Dept. of	8101091000*	CONTRACT
	8101120407	50-466 D
	8101120421	50-290 P
Alabama Power Co.	8101050021	50-348 P
	8101090028	50-364 A
	8101090030*	50-364 A
	8101090032*	50-364 A
	8101090856	50-364 Q
	8101100319*	50-348 Q
	8101130602	50-348 B
	8101130608*	50-348 B
	8101140507	50-348 P
	8101140554	50-348 Q
	8101140559*	50-348 Q
	8101190101	50-364 P
	8101210402	50-348 P
	8101210402	50-348 P
	8101210411	50-364 B
	8101210426	50-348
	8101210430*	50-348 B
	8101210481	50-364 R
	8101210485*	50-364 R
	8101210518	50-348 R
	8101210521*	50-348 R
	8101220344	50-364 P
	8101220359	50-348 P
	8101220363*	50-348 P
	8101220365*	50-348 P
	8101230425	50-348 P
	8101260350	50-348 A
	8101260360	50-348 P
	8101260360	50-348 P
	8101260365*	50-364 V
	8101270314	50-348 P
	8101270696	50-348 P
	8101270696	50-348 P
	8101270750	50-348 P
	8101270750	50-348 P
	8101280164	50-364
	8101280288	50-348 S
	8101280291*	50-348 S
	8101280293*	50-348 S
	8101290086	50-348 Q
	8101290334	50-348 Q
	8101290334	50-348 Q
	8101290363	50-348 Q
	8101290363	50-348 Q
	8101290728	50-348 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8101300580	50-348 S
	8101300580	50-348 S
Alaska Holding Center	8101270124	71-404
	8101270126*	71-404
Aldrich Chemical Co., Inc (subs of Sigma-Aldrich Corp.)	8101140954	XPGRTLIC
	8101140959*	XPGRTLIC
Allied Chemical Corp	8101100256	40-3392
	8101190645	71-6273
Allied General Nuclear Services	8101080189	50-332
American Electric Power Co., Inc.	8101140146	PR
	8101070582	PR
American Mining Congress	8101070600	PR
	8101070628*	PR
	8101070638*	PR
American Nuclear Insurers	8101090496	50-320 J
	8101290419	50-369 J
American Nuclear Society	8101270280	50-482 Q
Americans for Nuclear Energy	8101210558	FDIA
Anco Testing Laboratory, Inc.	8101060258*	CONTRACT
Argonne National Laboratory	8101050070*	50-263 P
	8101120053	REVIEW ORP
	8101200010	ACRS
	8101270213	RES
	8101290819	MUREQ
Arizona Public Service Co.	8101060425	50-528 B
	8101060425	50-528 B
	8101060478	50-528 A
	8101060478	50-528 A
	8101060478	50-528 A
	8101060500	50-528 A
	8101060504	50-529 S
	8101060507*	50-528 M
	8101070364	50-528 M
	8101070364	50-528 M
	8101070364	50-528 M
	8101070463	50-528 A
	8101070463	50-528 A
	8101070463	50-528 A
	8101090718	REQD
	8101120098	50-528
	8101120098	50-528
	8101120098	50-528
	8101130329	50-528
	8101210330	50-528
	8101210330	50-528
	8101210335	50-528
	8101210335	50-528
	8101210335	50-528
	8101210338	50-529
	8101220096	50-528
	8101220096	50-528
	8101220096	50-528
	8101220104	50-528
	8101220644	PR

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER
	8101230492	50-520 S		8101210197
	8101230492	50-528 S		8101280205
	8101230492	50-528 S		8101290259
	8101270441	50-528 A	Atomic Industrial Forum	8101160695
	8101290384	PRM		8101160697*
Arkansas Power & Light Co	8101050269	50-313 R		8101220198
	8101050275*	50-313 R	Austria	8101120064
	8101050320	50-313 S		8101120073
	8101050331	50-313 S		8101120080
	8101050336*	50-313 S	Automated Correspondence Systems, Inc	8101060347*
	8101050344	50-313 P		8101070040
	8101050361	50-368 S	BDM Corp	8101060806*
	8101050367*	50-368 S	BLR Owners Group	8101090487
	8101050373	50-368 S		8101090493*
	8101050377*	50-368 S		8101280187
	8101050381	50-368 S	Babcock & Wilcox Co	8101070286*
	8101050387*	50-368 S		8101150353
	8101050418	50-313 P		8101210359
	8101050432	50-368 S		8101220460
	8101050438*	50-313 S		8101230730
	8101050440	50-368 S	Babcock & Wilcox Co., Nuclear Material	8101200003
	8101050452	50-368 S	Div.	
	8101050463	50-313 S		8101260776*
	8101050501*	50-368 S	Baker & Botts	8101090055
	8101050509*	50-368 S		8101230192
	8101050519*	50-368 S		8101230192
	8101050537*	50-313 S		8101230198
	8101060355	50-313 P		8101280577
	8101060355	50-313 P		8101280577
	8101070164*	50-313 Q		8101280585*
	8101070399	50-368 S	Belch, Bingham, Baker, Hawthorne,	8101090877
	8101080434	50-313 F	Williams & Ward	
	8101080434	50-313 F	Delwin, W. A.	8101270057
	8101090223*	50-313 Q	Baltimore Gas & Electric Co.	8101090185
	8101090593	50-313 F		8101090192*
	8101120044	50-313 Q		8101090399
	8101120150	50-313 P		8101090403*
	8101120155	50-313 Q		8101090408
	8101120165	50-313 Q		8101090413*
	8101120174	50-313 Q		8101090437
	8101120344	50-368 S		8101060283
	8101120389*	50-368 S		8101060203
	8101130439	50-368 S		8101060333
	8101130452*	50-368 S		8101060333
	8101130474	50-368 S		8101060571
	8101130484*	50-368 S		8101060571
	8101130543	50-313 S		8101070379
	8101130946*	50-313 S		8101130597
	8101130177	50-313 P		8101130607*
	8101160406	50-313 P		8101130610
	8101190448	50-368 S		8101130615
	8101190451*	50-368 S		8101130617
	8101200247	50-313 P		8101130623
	8101200256	50-368 P		8101140791
	8101200298	50-368 P		8101140944
	8101200399	50-368 S		8101150534
	8101200406*	50-368 S		8101150543
	8101200411	50-368 S		8101150551
	8101200416*	50-368 S		8101150565
	8101210490	50-313 R		8101190164
	8101210494*	50-313 R		8101190320
	8101210509	50-368 R		8101190320
	8101210514*	50-368 R		8101190325
	8101220156	50-313 P		8101190325
	8101220414	50-368 P		8101190802
	8101230536	50-313 P		8101190802
	8101260384	50-313 P		8101190802
	8101260678*	50-313 F		8101190807
	8101260678*	50-313 F		8101220388
	8101260683*	50-313 F		8101220390
	8101270356	50-313 P		8101220434
	8101270877	50-368 S		8101230457
	8101270885*	50-368 S		8101230461
	8101270742	50-313 J		8101230486
	8101290137	PR		8101230486
	8101290536	50-313 R		8101230522
	8101290540*	50-313 R		8101230524
Arkansas, State of	8101140092	State Prog		8101230533
Army, Dept. of	8101100399*	CONTRACT		8101230540
Army, Dept. of, Corps of Engineers	8101220122*	50-329 A		8101260477
Assessment Designs, Inc.	8101150328*	CONTRACT		8101260530
Association of Community Organizations	8101130037	50-448 Q		8101260542
for Reform Now-Texas				8101260530
Atlas Minerals	8101060693	40-3493		8101260542

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Basic Energy Technology Associates Battelle Memorial Institute Battelle Memorial Institute, Columbus Laboratories	8101270611	50-317 P		8101150641	RES
	8101270611	50-317 P		8101210537	50-537 A
	8101270660	50-318 S		8101210544	50-537 A
	8101270677	50-318 S		8101210576	RES
	8101270684*	50-318 S		8101210585	RES
	8101290618*	50-317 F		8101210610	RES
	8101290621*	50-317 F		8101210615	RES
	8101300322	50-317 P		8101210622	RES
	8101300523	50-317 S		8101220023	RES
	8101300530*	50-317 S		8101220029	RES
Battelle Memorial Institute, Pacific Northwest Laboratory	8101300533	50-318 S		8101220049	RES
	8101300538*	50-318 S		8101220053	RES
	8101290729*	50-289 T		8101220057	RES
	8101300361*	50-255 Q		8101220061	RES
	8101060636	RES		8101220076	RES
	8101060923	RES		8101220218	RES
	8101070043	RES		8101220622	RES
	8101070296	TOPREP		8101220623	RES
	8101150609	RES		8101220625	RES
	8101150617	RES		8101220626	RES
Battelle Memorial Institute, Pacific Northwest Laboratory	8101220183	RES		8101220628	RES
	8101220266	RES		8101220631	50-295 P
	8101280087*	50-219 R		8101220637	50-298 P
	8101280548	RES		8101220642	RES
	8101290182	RES		8101230047	RES
	8101290568*	50-213 S		8101230189	RES
	8101290691	RES		8101230200	RES
	8101270761	RES		8101230202	RES
	8101090609*	50-10 P		8101230206	RES
	8101120295	RES		8101230209	RES
Battelle Memorial Institute, Pacific Northwest Laboratory	8101120359	RES		8101230213	RES
	8101120683	RES		8101230636	RES
	8101220220	RES		8101230643	RES
	8101220249	RES		8101230648	RES
	8101220620	RES		8101230654	50-537 A
	8101230566*	50-250 P		8101230662	RES
	8101270889*	NUREG		8101230743	RES
	8101270943	NUREG		8101230751	RES
	8101280531	RES		8101230757	RES
	8101290180	NUREG		8101260144	NUREG
Battelle Memorial Institute, Pacific Northwest Laboratory	8101290763	RES		8101260163	NUREG
	8101100144	40-8452		8101260752	RES
	8101270303	50-329 K		8101260758	50-537 A
	8101060339*	50-317 P		8101260828	RES
	8101070139*	50-133 Q		8101260833	RES
	8101120242	REQD		8101260846	RES
	8101150410*	QA999		8101260849	RES
	8101150446*	QA999		8101260850	RES
	8101210382	TOPREP		8101260856	50-537 A
	8101220581	50-329 S		8101270053	50-537 A
Bell, R. F. MD Bellway Limousine Service, Inc. Bergson, Borland, Margolis & Adler	8101270532	50-528 K		8101270071	RES
	8101290451	50-416 A		8101270112	50-537 A
	8101270217*	40-1341		8101270227	50-537 A
	8101140375*	CONTRACT		8101270391	RES
	8101190157	FOIA		8101270545	50-537 A
	8101070178*	PR		8101270827	50-537 A
	8101070186*	PR		8101290090	RES
	8101190142	FOIA		8101300209	NUREG
	8101270199	FOIA		8101300543	RES
	8101060730	FOIA		8101300674	RES
Blum, B. Boston Edison Co.	8101090485	50-369 Q		8101300682	RES
	8101060565	50-293 J		8101280620	50-275 Q
	8101070387	50-293 P		8101030187*	TOPREP
	8101080356	50-293 S		8101150129*	CONTRACT
	8101080368*	50-293 S		8101160606	71-402
	8101090045	50-293 P		8101060378*	50-335 P
	8101140927	50-293 Q		8101070196	50-470 K
	8101160316	50-293 S		8101130284	REVIEW ORP

B101050033	50-324	S			B10126064
B101050184	50-261	G			B10126064
B101050194*	50-261	G			B10126064
B101050323	50-400	A			B10127035
B101050325	50-400	A			B10127035
B101050325	50-400	A			B10127066
B101050325	50-400	A			B10127066
B101050401	50-324	G			B10127066
B101050401	50-324	G			B10127066
B101050638	50-324	G			B10127066
B101060453	50-261	P			B10127066
B101060463	50-261	P			B10127066
B101060494	50-324	P			B10127070
B101060494	50-324	P			B10127070
B101060587	50-324	P			B10127070
B101060587	50-324	P			B10127070
B101060587	50-324	P			B10127070
B101060678	50-261	G			B10127080
B101060689*	50-261	G			B10127080
B101060800	MUREO				B10127080
B101070365	50-324	G			B10128020
B101070366*	50-324	S			B10128020
B101070370	50-324	S			B10128054
B101070373*	50-324	G			B10128054
B101070437	50-400	S			B10128054
B101070437	50-400	S			B10128054
B101070437	50-400	S			B10128054
B101070437	50-400	S			B10128054
B101070491	50-324	G			B10128054
B101070493*	50-324	G			B10128054
B101070498	50-324	G			B10128054
B101070502*	50-324	G			B10128054
B101070620	50-324	G			B10128054
B101090511	50-324	S			B10128054
B101090657	50-325	S			B10128054
B101090676*	50-325	S			B10128054
B101120389	50-261	G	Carpenter Technology Corp.		B1011403
B101130223	50-400	S	Center for Development Policy		B1010504
B101130237	50-261	R			B1011409
B101130241*	50-261	R	Center for Law in the Public Interest		B1011402
B101130933	50-324	G			B1012703
B101130540*	50-324	S	Central Electric Power Cooperative, Inc.		B1010703
B101130548	50-324	S	Central Iowa Power Cooperative		B1012105
B101130554*	50-324	S	Ch2m Hill, Inc.		B1012202
B101130561	50-324	S	Charlotte, NC		B1012205
B101130568*	50-324	S	Chem-Nuclear Systems, Inc.		B1012205
B101140200	50-400	Q			B1011508
B101140508	50-324	S	Chemtron Corp., Tube Turns Div.		B1010504
B101140514*	50-324	S	Cherry, H. M./Cherry, Flynn & Kanter		B1011300
B101150532	50-324	S			B1011300
B101150538*	50-324	G	Chesapeake Energy Alliance		B1011502
B101150618	50-261	P	Chicago, Univ. of		B1012301
B101150005	50-324	O	Chickering & Gregory		B1012301
B101160005	50-324	G			B1012301
B101160442	50-324	P			B1012301
B101160442	50-324	P	Chonin, N		B1012603
B101160526	50-324	S	Christa-Maria		B0032704
B101160581*	50-324	G			B1010703
B101190414	50-324	P			B1010907
B101190414	50-324	P			B1010602
B101190426	50-261	V	Cincinnati Gas & Electric Co		B1010703
B101190429*	50-261	V			B1011201
B101190609	50-324	P			B1011402
B101190609	50-324	P			B1011402
B101200624	50-324	S			B1011509
B101200626	50-325	S			B1011509
B101200628*	50-324	S			B1012106
B101200629*	50-325	S			B1012304
B101210137*	50-261	F			B1012706
B101210144*	50-261	F			B1012800
B101210217	50-400	G			B1012902
B101210403	50-324	R			B1010505
B101210408*	50-324	R	Citizens Association for Sound Energy		B0121802
			Citizens Concerned About Nuclear Power, Inc.		
B101210460	50-261	G			B1012702
B101220194	RE000		Citizens for Nuclear Reactor Safety, Inc.		B1012103
B101220393	50-325	G	Citizens for Safe Environment		B0122204
B101220396*	50-325	G	Citizens for a Better Environment		B1012005
B101220399	50-325	S	Cleveland Electric Illuminating Co.		B1012201
B101220402*	50-325	S			B1012204
B101220403	50-324	S			B1012201
B101220409*	50-324	S			B1012901
B101220412	50-261	Q			B1013000
B101230066*	50-261	F			B1013000

	8101120104*	50-284	G	8101090005*	50-10	P
	8101270044	40-1162		8101090005*	50-10	P
	8101270049*	40-1162		8101090005*	50-10	P
	8101050208*	CONTRACT		8101090005*	50-10	P
	8101190089	WASTE MGT		8101090005*	50-10	P
	8101270155	WASTE MGT		8101090005*	50-10	P
	8101270394	WASTE MGT		8101090038	50-295	P
	8101270467	WASTE MGT		8101090038	50-295	P
Denver	8101300365*	CONTRACT		8101090064	50-254	S
Eng. Inc	8101280074	MISC		8101090066*	50-254	S
	8101140221	50-208	J	0101090070*	50-254	S
	8101140258	KPORTLYC		8101090088*	50-254	S
	8101220417*	50-368	P	8101090091*	50-254	S
	8101230541*	50-317	G	0101090096*	50-254	S
National Oceanographic	8101300164*	70-1100		8101090103*	50-294	G
Administration	8101070489*	REGCD		8101090244*	50-294	G
	8101050017	50-395	D	8101090608	50-10	J
	8101150223*	CONTRACT		8101090608	50-10	J
Maritime Administration	8101150237*	CONTRACT		8101090608	50-10	J
	8101300586	50-238	R	8101090608	50-10	J
National Bureau of	8101300587*	50-238	R	8101090608	50-10	J
	8101060629	50-184	R	8101090608	50-10	J
	8101060633*	50-184	R	8101090810*	50-254	G
	8101080317	ACRS		8101100301*	50-156	G
Co.	7903190202	50-10	P	8101120153	50-254	R
	7911270337	50-10	P	8101120336	50-295	S
	7911270340*	50-10	P	8101120343*	50-295	S
	0003240464	50-237	P	8101120346	50-295	S
	8009190849*	50-10	P	8101120349*	50-295	S
	8011250354	50-254	S	8101130337	50-237	P
	8011250358*	50-254	S	8101130458	50-295	S
	8012220406*	50-10	P	8101130461	50-295	S
	8101050066	50-265	P	8101130516*	50-295	S
	8101050340	50-304	S	8101130536*	50-295	S
	8101050345*	50-304	S	8101130541	50-295	S
	8101050390	50-294	S	8101130550	50-304	S
	8101050376*	50-294	S	8101130551*	50-295	S
	8101050415	50-373	S	8101130559*	50-304	S
	8101050500	50-10	P	8101130562	50-304	S
	8101050500	50-10	P	8101130571*	50-304	S
	8101060073	50-10	G	8101130598	50-265	S
	8101060376	50-237	P	8101130603*	50-265	S
	0101060467	50-249	S	8101130667	50-373	G
	8101060469	50-249	S	8101140471	50-295	V
	8101060471*	50-249	S	8101140512	50-373	A
	8101060472	50-265	S	8101140620	50-249	G
	8101060479*	50-249	S	8101140623*	50-249	S
	8101060481	50-237	S	8101190352	50-373	K
	8101060482*	50-265	S	8101200135	50-237	G
	8101060484*	50-237	S	8101200135	50-237	G
	8101060486	50-265	S	8101200135	50-237	G
	8101060492*	50-265	S	8101200135	50-237	G
	8101060598	50-237	S	8101200155	50-10	G
	8101060604*	50-237	S	8101200155	50-10	G
	8101060608	50-237	S	8101200155	50-10	G
	8101060617*	50-237	S	8101200155	50-10	G
	8101070214	50-295	G	8101200155	50-10	G
	8101070251	REGCD		8101200155	50-10	G
	8101080093	50-237	G	8101200155	50-10	G
	8101080093	50-237	G	8101200243	50-373	A
	8101080093	50-237	G	8101200296	50-237	P
	8101080117	50-247	G	8101200296	50-237	P
	8101080144	50-10	P	8101200302	50-254	R
	8101090001	50-10	P	8101200302	50-254	R
	8101090001	50-10	P	8101200328	50-373	G
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001	50-10	P	8101210463	50-254	R
	8101090001					

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8101260586	50-237 S		8101130364	50-247 V
	8101260597	50-10 P		8101140316	50-247 R
	8101260597	50-10 P		8101140316	50-247 R
	8101260658*	50-249 S		8101150578*	50-247 R
	8101260671*	50-237 S		8101210434	50-247 R
	8101260659*	50-295 Q		8101210440*	50-247 R
	8101260707*	50-454 Q		8101210459	50-247 R
	8101270481	50-237 P		8101210591	50-247 R
	8101270515	50-10 R		8101220130	50-247 R
	8101270515	50-10 R		8101220147*	50-247 R
	8101270515	50-10 R		8101220315	50-247 R
	8101270520*	50-10 R		8101220362	50-247 R
	8101270520*	50-10 R		8101220362	50-247 R
	8101270520*	50-10 R		8101230582	50-3
	8101270584	50-295 P		8101230582	50-3
	8101270584	50-295 P		8101230589	50-3
	8101270600	50-249 S		8101230589	50-3
	8101270613*	50-249 S		8101270194*	50-247 R
	8101270614	50-10 J		8101270664	50-247 R
	8101270614	50-10 J		8101270679	50-247 R
	8101270614	50-10 J		8101270685*	50-247 R
	8101270614	50-10 J		8101270724	50-247 R
	8101270617	50-295 P		8101270729*	50-247 R
	8101270617	50-295 P		8101290671	50-247 R
	8101270661	50-10 P	Consumers Power Co	81012310225	50-329
	8101270730	50-295 S		8101050132*	50-329
	8101270733*	50-295 S		8101050132*	50-329
	8101270737	50-10 J		8101050145*	50-329
	8101270737	50-10 J		8101050365	50-329
	8101270737	50-10 J		8101050365	50-329
	8101270740	50-265 S		8101050407	50-329
	8101270795*	50-265 S		8101050407	50-329
	8101270763	50-294 S		8101050576*	50-155
	8101270770*	50-294 S		8101050980*	50-155
	8101280613	50-454 Q		8101050600*	50-329
	8101280636	50-454 Q		8101060272*	50-329
	8101290510	50-249 S		8101060630	50-155
	8101290514	50-10 S		8101060635*	50-155
	8101290791*	50-10 P		8101060668	50-155
	8101290791*	50-10 P		8101060674*	50-155
	8101290791*	50-10 P		8101060921	50-155
	8101300470	50-10 P		8101070653	50-295
	8101300470	50-10 P		8101080078	RE000
	8101300577*	50-254 Q		8101080124	50-155
	8101060641*	50-289 Q		8101080134	50-155
	8101060652*	50-289 Q		8101090078	50-329
	8101080047	PR		8101090084	50-329
	8101090447	50-213 P		8101090171*	50-255
	8101060410	50-213 P		8101090513	50-329
	8101070256*	50-213 F		8101090513	50-329
	8101090002	50-213 P		8101090594	50-329
	8101090004	50-213 F		8101090594	50-329
	8101090004	50-213 F		8101120224	50-155
	8101090004	50-213 F		8101120250*	50-329
	8101090012	50-213 P		8101120318	50-255
	8101090626	50-213 S		8101120339	50-155
	8101090632*	50-213 S		8101120379*	50-155
	8101100789	50-213 Q		8101120444	50-329
	8101120237	50-213 V		8101120444	50-329
	8101120325	50-213 P		8101120574	50-155
	8101120327	50-213 P		8101130086	50-155
	8101150028	50-213 Q		8101130229	50-155
	8101160248	50-213 P		8101130233*	50-155
	8101160248	50-213 P		8101130243	50-255
	8101160248	50-213 P		8101130249*	50-255
	8101160580*	50-213 Q		8101130442	50-255
	8101160587*	50-213 Q		8101130445*	50-255
	8101210376	50-213 S		8101130518	50-155
	8101220404	RE000		8101130525*	50-155
	8101220408	50-213 R		8101140336	50-255
	8101220410*	50-213 R		8101140344*	50-255
	8101270712	50-213 F		8101140628	50-255
	8101270882*	COMMISSION		8101140653	50-329
	8101280062	50-358 Q		8101140683	50-329
	8101280304	50-510 Q		8101140968	50-329
	8101290740	50-358 Q		8101140968	50-329
	81012290320	50-247 P		8101140973	50-329
	81012290320	50-247 P		8101150079*	50-255
	8101050348	50-247 S		8101150506	50-255
	8101050353*	50-247 S		8101150391	50-290
	8101060279	50-247 Q		8101190604	50-330
	8101060450	50-247 P		8101200154	50-329

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8101210609	50-155 Q		8101260499	50-488 G
	8101220140*	50-247 Q		8101280331	50-395 M
	8101220186*	50-255 Q	Decision Research, Inc.	8101280114	NJREG
	8101220200*	50-255 Q	Defense, Dept. of, Defense Nuclear Agency	8101270782*	CONTRACT
	8101220234	50-185 P	Delaware, State of	8101300406*	CONTRACT
	8101220250	50-155 J			
	8101220332	50-255 Q	Detroit Edison Co.	8101050080*	50-341 K
	8101220395	50-255 Q		8101050085*	50-341 K
	8101230479	50-255 S		8101050172*	FOIA
	8101230483*	50-255 S		8101050911	PA
				8101210588	50-341 A
	8101230530	50-255 S			
	8101230531*	50-255 S		8101270400	50-16 J
	8101230533	50-155 S		8101290006	50-341 S
	8101230535*	50-155 S	Dignan, T. O.	8101290770*	50-341 Q
	8101230581	50-329 S	Doc-Search Associates	8101280091	50-443 Q
				8101130029	FOIA
	8101260273	50-329 Q			
	8101260273	50-329 Q		8101230175	FOIA
	8101260462	50-255 J	Osherty, J. F.	8101050014	50-466 Q
	8101260480	50-329 Q		8101050063	50-466 Q
	8101260738*	50-255 F	Douglass & Barham	8101050616	50-488 Q
			Duke Power Co.	8101050094	50-269 P
	8101260743*	50-255 F			
	8101270373	50-155 P		8101050094	50-269 P
	8101270390*	50-329 K		8101050101*	50-269 P
	8101270390*	50-329 K		8101050101*	50-269 P
	8101270691	50-155 P		8101050101*	50-269 P
	8101270864*	50-155 Q		8101050107	50-287 P
	8101280093	50-153 P		8101050112*	50-287 P
	8101280299	50-329 Q		8101050351	50-287 S
	8101280299	50-329 Q		8101050355*	50-287 S
	8101280591	50-329 Q		8101050616	50-488 Q
	8101290012	50-329 Q		8101060483	50-269 P
	8101290012	50-329 Q		8101060483	50-269 P
	8101290020*	50-329 Q		8101060483	50-269 P
	8101290020*	50-329 Q		8101060488*	50-269 P
	8101290083*	50-155 Q		8101060488*	50-269 P
	8101290231	50-155 Q		8101060488*	50-269 P
	8101290358	50-155 P		8101060491*	50-269 P
	8101290623	50-155 S		8101060491*	50-269 P
	8101290628*	50-155 S		8101060491*	50-269 P
	8101290980	50-329 R		8101060503	50-269 I
	8101290580	50-329 R		8101070143	50-369 Q
	8101280410	FOIA		8101070253	REGGD
Control Data Corp.	8101270961	WASTE MGT		8101070269	50-269 P
Collar Corp.	8101270178	FOIA		8101070313	50-413 Q
Courier-Kneue	8101070172	PR		8101070316*	50-413 Q
Covington & Burling					
	8101140116	State Prog		8101070320	50-369 Q
	8101280599	50-389 M		8101080148*	50-269 Q
Creare, Inc.	8101060097	REG		8101090062	50-369 Q
	8101070534	REG		8101090062	50-369 Q
	8101270161	REG		8101090657	50-287 S
	8101090706*	CONTRACT		8101090666*	50-287 S
Curtis, O. H.	8101120227*	50-135 P		8101120248	REGGD
O'Apollonia Consulting Engineers, Inc.	8101050326	50-409 F		8101130404	50-269 P
Delcylnd Power Cooperative	8101050374	50-409 S		8101130404	50-269 P
	8101050380*	50-409 S		8101130404	50-269 P
	8101050383	50-409 S		8101140600	50-413 S
	8101050391*	50-409 S		8101150136	50-269 Q
	8101060561	50-409 S		8101150168	50-369 F
	8101060583*	50-409 S		8101150462	50-369 F
	8101080099	50-409 P		8101150765	50-369 Q
	8101080109	50-409 Q		8101150907	50-369 Q
	8101090042	50-409 P		8101160220	50-413 M
	8101140491	50-409 R		8101160258	50-269 Q
	8101140494*	50-409 R		8101160258	50-269 Q
	8101160433	50-409 S		8101160258	50-269 Q
	8101200178	50-409 Q		8101160366	50-269 P
	8101220025	50-409 F		8101160443	50-369 F
	8101270345	50-409 P		8101160443	50-369 F
	8101280320	50-409 T		8101160668*	50-413 Q
	8101280315	50-409 Q		8101160724	50-369 Q
	8101300181	50-409 P		8101160724	50-369 Q
	8101300636	50-409 Q		8101190385	50-269 P
Dees & Moore	8101210294	CONTRACT		8101200229	50-269 P
	8101230539*	50-313 P		8101200575	50-269 Q
Data Composition Services, Inc.	8101090898*	CONTRACT		8101210213	50-269 Q
Dauphin County, PA	8101060956*	50-320 P		8101210213	50-269 Q
	8101070270*	50-320 F		8101210213	50-269 Q
Davis Polk & Wardwell	8101190148	FOIA		8101210462	50-269 F
Devisson, M. T.	8101070319*	50-267 A		8101210462	50-269 F
Devoise & Liberman	8101090478	50-443 Q		8101210462	50-269 F
	8101070028	FOIA		8101210464*	50-269 I
	8101160220	50-413 M		8101210464*	50-269 I
	8101160233	50-443 Q		8101210493	50-269 I
	8101230404	70-2623		8101210493	50-269 I
	8101230442	70-2623			

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8101210493	50-269 P		8101220371	50-334
	8101210502	50-269 S		8101230465	50-334
	8101210507	50-269 S		8101230471	50-334
	8101210511	50-287 S		8101230473	50-334
	8101210516	50-287 S		8101230475	50-334
	8101220133	50-369 A		8101230478	50-334
	8101220133	50-369 A		8101260548	50-334
	8101220138	50-369 A		8101260634	50-334
	8101220138	50-369 A		8101270590	50-334
	8101220378	50-269 S		8101270593	50-334
	8101220378	50-269 S	Dynapac, Inc.	8101300738	50-334
	8101220380	50-269 S		8101300176	50-498
	8101220380	50-269 S		8101300182	50-498
	8101220380	50-269 S	EO&O Idaho, Inc.	8101050062	NUREG
	8101220380	50-269 S		8101050069	NUREG
	8101220428	50-269 P		8101130408	NUREG
	8101220428	50-269 P		8101130414	NUREG
	8101220428	50-269 P		8101150600	REG
	8101230404	50-2623		8101300145	REG
	8101230440	50-269 F		8101300184	50-254
	8101230440	50-269 F		8101300184	50-254
	8101230442	70-2623		8101300179	50-266
	8101230489	50-269 S		8101300186	50-237
	8101230491	50-269 S		8101300197	REG
	8101230493	50-369 A		8101300768	NUREG
	8101230493	50-369 A		8101300822	REG
	8101230496	50-369 A		8101300829	50-234
	8101230496	50-369 A		8101300837	50-309
	8101230502	50-471 S		8101300842	50-10
	8101260209	50-369 Q		8101300845	REG
	8101260499	50-488 Q		8101300847	50-255
	8101260513	50-369 S		8101300849	50-231
	8101260513	50-369 S	EO&O, Inc.	8101120332	50-244
	8101270640	50-270 S		8101120343	50-244
	8101270640	50-287 S		8101120353	50-244
	8101270650	50-287 S		8101280450	50-244
	8101270680	50-270 G		8101300262	50-244
	8101290404	50-369 Q	Ebasco Services, Inc. (subs. of Enserch Corp.)	8101150840	QA999
	8101290404	50-369 Q		8101290116	FOIA
	8101290408	50-413 Q		8101290124	FOIA
	8101290492	50-369 Q		8101290131	FOIA
	8101290591	50-369 J		8101290143	FOIA
	8101290599	50-269 F		8101290151	FOIA
	8101290599	50-269 F		8101290159	FOIA
	8101290599	50-269 F		8101290255	FOIA
	8101290608	50-269 F		8101290261	FOIA
	8101300160	50-369 A		8101290271	FOIA
	8101300436	50-369 F		8101290281	FOIA
	8101300576	50-270 S		8101290287	FOIA
	8101300578	50-270 S		8101290290	FOIA
Duquesne Light Co	8101050321	50-334 P		8101290298	FOIA
	8101050330	50-334 P		8101290304	FOIA
	8101060404	50-412 S		8101290310	FOIA
	8101060430	50-412 S		8101290313	FOIA
	8101070436	50-334 R		8101290317	FOIA
	8101070439	50-334 R		8101290324	FOIA
	8101070524	50-334 S		8101290330	FOIA
	8101070531	50-334 S		8101290335	FOIA
	8101080126	50-334 Q		8101201596	50-284
	8101090548	50-334 Q	Eberline Instrument Corp.	8101140931	70-2909
	8101100781	50-334 Q	Eckert, Seamans, Cherin & Mellott		
	8101100786	50-334 Q		8101070008	FOIA
	8101130421	50-334 S	Edison Electric Institute	8101100208	70-2322
	8101130425	50-334 S	Edlow International Co.	8101120023	XPCRTL1
	8101130428	50-334 S		8101140890	XPCRTL1
	8101130432	50-334 S		8101160218	XPCRTL1
	8101130438	50-334 S		8101280641	50-367
	8101130443	50-334 S	Eichhorn, Eichhorn & Link	8012050440	NUREG
	8101130508	50-334 S	Electric Power Research Institute	8101140796	CONTRACT
	8101130515	50-334 S		8101220346	50-309
	8101130531	50-334 S	Electric Utility Companies Nuclear Transportation Group	8101290049	70-2623
	8101150933	50-334 Q			
	8101160464	50-334 R	Energy Fuels Nuclear, Inc.	8101100023	40-0681
	8101160467	50-334 R	Energy Incorporated	8101230275	71-405
	8101160468	50-334 R		8101230286	71-405
	8101160470	50-334 R	Energy Research & Development Admin. (Presently DOE)	8101260334	FOIA
	8101190279	50-412 S	Energy Resources Co., Inc.	8101150118	FOIA
	8101190467	50-334 S			
	8101190470	50-334 S	Energy Systems Research Group, Inc.	8101270683	50-322
	8101190474	50-334 S	Energy, Dept. of	8101190360	71-9035
	8101190477	50-334 S		8101190398	71-6144
	8101220382	50-334 S		8101290410	10CFR
	8101220384	50-334 S	Energy, Dept. of, Economic Regulatory Administration	8101160142	COMHIS
	8101220387	50-334 S			
	8101220392	50-334 S	Energy, Dept. of, Clinch River Breeder Reactor Plant	8101070495	REG00D

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Entsada, E. B. Environmental Coalition on Nuclear Power	8101090492	50-837		8101130325	50-230
	8101270282	50-170		8101130333	50-335
	8101090321	50-289		8101130334*	50-250
	8101090320*	50-289		8101130339*	50-335
	8101230635	50-289		8101130341	50-335
Environmental Protection Agency	8101270298	50-387		8101130345	50-335
	8101050019	50-250		8101130348	50-250
	8101050056	50-466		8101130353	50-250
	8101050618	40-2061		8101130365*	50-335
	8101080042	PR		8101130372*	50-335
	8101120173*	50-320		8101130377*	50-250
	8101130017*	FOIA		8101130382*	50-250
	8101130537	40-2061		8101140608	50-250
	8101210590	50-395		8101140608	50-250
	8101220297	50-259		8101140886	50-250
Essex Corp.	8101260593	50-395		8101150125	50-250
	8101270591	50-361		8101150595*	50-389
	8101150801	MUREO		8101160261	50-389
	8101220265*	50-395		8101190350	50-280
	8101090912	XPORTLIC		8101190350	50-250
European Communities, Commission of	8101090919	XPORTLIC		8101210092*	50-335
	8101140903	XPORTLIC		8101210098*	50-335
	8101190755	XPORTLIC		8101210162	50-335
	8101130122*	XPORTLIC		8101210209	50-250
				8101210414	50-250
European Organization for Nuclear Research	8101050096	TOPREP		8101210414	50-250
				8101210414	50-250
	8101090047	TOPREP		8101210418*	50-250
	8101090050*	TOPREP		8101210418*	50-250
	8101140139	XPORTLIC		8101210418*	50-250
Exxon Nuclear Co., Inc. (subs. of Exxon Corp.)	8101200007	71-9070		8101210425	50-250
	8101220528	TOPREP		8101210425	50-250
	8101220534*	TOPREP		8101210425	50-250
	8101210582	FOIA		8101210429*	50-250
	8101150142*	FOIA		8101210429*	50-250
FBI Service	8101150149*	FOIA		8101210429*	50-250
	8101070311	40-4492		8101210429*	50-250
	8101080440	80-344		8101220150	50-250
	8101090037	ORG		8101220172	50-389
	8101140249*	50-289		8101230428	50-250
Federal Emergency Management Agency	8101140252*	50-289		8101230428	50-250
	8101290452	50-250		8101230428	50-250
	8101300408	50-361		8101230430*	50-250
	8101160278	50-275		8101230430*	50-250
	8101050324	50-250		8101270008	50-389
Federal Energy Regulatory Commission	8101050328	50-335		8101270043	50-389
	8101050338	50-250		8101270694	50-335
	8101050342*	50-250		8101270703*	50-335
	8101050349*	50-335		8101280078	50-335
	8101050360	50-250		8101280599	50-389
Fischelaker, D. B. Florida Power & Light Co.	8101050363*	50-250	Florida Power Corp.	8101050260	50-302
	8101050392	50-250		8101050264*	50-302
	8101050392	50-250		8101050285</	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER
OH Battis Corp Oage-Babcock Associates, Inc General Atomic Co. (subs. of Gulf Oil Co.)	8101270057	50-70 Q		810106057
	8012100406	PT21		810106057
	8101100307*	CONTRACT		810106056
	8101050024	50-163 R		810106055
	8101050020*	50-163 R		810106064
	8101070225	XPORTLIC		810106064
	8101200005	XPORTLIC		810106065
	8101200006	XPORTLIC		810107033
General Atomic Co. (subs. of Gulf Oil Corp.)	8101120001	REGOD		810107052
General Electric Co	7912310182	REGOD		810107052
	8012100316*	70-1113		810107052
	8012290515	71-5900		810108020
	8012290532	71-5971		810112029
	8012290549	71-5926		
	8012290565	71-4986		810112030
	8012290569	71-5939		810112030
	8012290571*	71-4986		810112031
	8012290590	71-5044		810112035
	3101050178	TOPREP		810112036
	8101050494	50-70 Q		
	8101050506*	50-70 Q		810114055
	8101050515*	50-70 Q		810116010
	8101060892	XPORTLIC		810119033
	8101080121	REGOD		810119033
	8101090190	TCPREP		810119034
	8101090209*	TOPREP		810119034
	8101100861	REG		810122056
	8101120049	REVIEW ORP		810123045
	8101120309*	50-277 P		810123046
	8101130317	NUREG		810123046
	8101140008	71-9001		810123046
	8101140135	REGOD		810126039
	8101140565	PR		810126046
	8101160197	50-70 Q		810126046
	8101160342	TOPREP		810126052
	8101160361*	TCPREP		810126052
	8101190541	FOIA		810126054
	8101210371	TOPREP		810126059
	8101210515	TOPREP		810126060
	8101210523	TOPREP		810126061
	8101210529*	TCPREP		810126062
	8101210531*	TOPREP		810126068
	8101210542	REG		810126071
	8101220224	REG		810126072
	8101220232	REG		810128018
	8101220497	REVIEW ORP		810128019
	8101220649	REG		810129018
	8101220650	REG		810129037
	8101220655	REG		810129037
	8101230038*	70-1308		810129038
	8101230043*	70-1308		810129057
	8101230054*	70-1308		810130037
	8101230059*	70-1308		810130039
	8101230380	TOPREP		810130042
	8101230494*	50-263 Q		
	8101270598	TOPREP	Georgie, State of	810114013
	8101280170	50-70 F	Geotechnical Engineers, Inc.	810105023
	8101280567	XPORTLIC	Gibbs & Hill, Inc. (subs. of Dravo Corp.)	810109072
	8101300028	REG		810123050
General Physics Corp.	8101220569*	50-321 P	Gilbert/Commonwealth Cos.	810106065
General Public Utilities	8012160144	50-219 I		810113010
	8012160154*	50-219 I	Olen Ross, TX	810121035
	8101130048*	50-289 Q	Granbury, TX	810107030
	8101130056*	50-289 P	Gulf States Utilities Co.	810107030
	8101280406*	50-320 P		810110017
General Public Utilities - GPU Service Corp	8101060637*	50-289 Q		810121067
	8101270573	50-289 R		810121067
	8101270753	50-219 J		810122043
	8101280316*	50-289 Q		810127068
Georgia Power Co.	8012240278	50-321 Q		810128030
	8101050235	50-321 S	H. J. Gruy & Associates, Inc.	810127035
	8101050427	50-321 S	Hemel, Park, McCabe & Saunders	810107063
	8101050455	50-366 S	Hanford Engineering Development Laboratory	810110089
	8101050460*	50-366 S		810114053
	8101060514	50-321 S		810122050
	8101060514	50-321 S		810122060
	8101060559	50-366 S	Hannon & Weiss	810123046
	8101060564	50-321 P	Harrisburg Hosp. Harrisburg, PA	810108002
	8101060564	50-321 P	Henry County Health Center, Mt. Pleasant, IA	810107023
	8101060566*	50-366 S	Hobbs Brook Agency, Inc.	810114022
	8101060572	50-366 S		
	8101060573*	50-321 P	Hood County, TX	810107030
			House of Rep.	810106053
				810108039

	8101140846*	70-143		Illinois, State of	8101130010	FOIA
	8101200054	50-320	U		8101140232	50-367
	8101200077	50-170	U		8101200046	50-367
	8101200301	50-289	H		8101290518	50-10
	8101270308*	50-247	H	Illinois, Univ. of, at Chicago Circle	8101080035	PR
se of Rep., Government Operations	8101290789*	50-483	H	Indiana & Michigan Electric Co	8101050356	50-316
	8101050635*	50-320	F		8101050472	50-316
se of Rep., Interior & Insular Affairs	8101130606	50-367	U		8101050546*	50-316
	8012110052*	COMMISBION			8101080384	50-316
	8101060953*	COMMISBION			8101080397*	50-316
	8101060954*	COMMISBION			8101080406*	50-316
se of Rep., Merchant Marine &	8101140046*	70-143			8101090461	50-316
harries	8101140677*	COMMISBION			8101090685	50-316
ing & Urban Development, Dept of					8101090692*	50-316
ston Chronicle	8101230444	50-466	D		8101120268	50-315
ston Lighting & Power Co	8101200404	50-556	Q		8101120268	50-315
	8101080140*	50-498	A		8101120315	50-315
	8101090023	50-498	I		8101120315	50-315
	8101090023	50-498	I		8101130217	50-315
	8101090035	50-466	Q			
	8101120391*	50-498	A		8101140146	PR
	8101120391*	50-498	A		8101190512	50-315
	8101120393*	50-498	A		8101190512	50-315
	8101120393*	50-498	A		8101190515*	50-315
	8101140484*	50-498	Q		8101190515*	50-315
	8101150011	50-466	Q		8101230329	50-315
	8101160454	50-498	B		8101260579	50-315
	8101160454	50-498	B		8101270350	50-316
	8101160454	50-498	B		8101280510	50-315
	8101160460	50-498	B		8101290516	50-315
	8101160460	50-498	B			
	8101220331	50-498	B		8101290521*	50-315
	8101220331	50-498	B		8101300073*	50-315
	8101220319	50-498	B	Indiana & Michigan Power Co.	8101300494	50-315
	8101220515	50-498	B		8101060789	50-316
	8101230192	50-498	Q		8101060795*	50-316
	8101230192	50-498	Q			
	8101230198	50-498	Q		8101200367	50-315
	8101230198	50-498	Q		8101200371*	50-315
	8101270718	50-498	B		8101210443	50-316
	8101270857*	50-498	A	Indiana, State of	8101210451*	50-316
	8101270878*	50-498	Q		8101220072	PR
	8101270909*	50-498	Q	Institute for Resource Management, Inc.	8101220205	REQ00
	8101270924*	50-498	A	Institute of Nuclear Power Operations	8101190500*	50-296
	8101280377	50-498	Q	Interior, Dept of	8012240399*	State, Pr
	8101280377	50-498	Q		8101050079	50-367
	8101280589*	50-498	Q		8101090497	50-395
	8101290494*	50-498	Q	Interior, Dept of, Bureau of Mines	8101200484	CONTRACT
	8101300168*	50-498	Q	Interior, Dept of, Fish & Wildlife Service	8101210380	50-250
ston, Univ. of	8101100325*	CONTRACT			8101270121	40-1341
en Design Group	8101270723*	50-320	P	Interior, Dept of, Geological Survey	8101060577	50-395
	8101060750*	CONTRACT			8101140560	PR
ldt County, CA	8101210342	50-133	P	Interior, Dept of, National Park Service	8101230472	DRQ
ton & Williams	8101070091	FOIA		International Atomic Energy Agency	8101050369	50-367
	8101130384	50-380	Q	(Austria)	8101280573	DRQ
	8101230103	50-338	Q	International Business Development	8101090429	XP00TLIC
	8101270305	PR		International Structural Engineers, Inc	8101300104*	50-390
el Hosp., Detroit, MI	8101280212	50-322	Q	Iowa Electric Light & Power Co.	8012050399	50-331
	8101070297*	70-2249			8101050273	50-331
	8101070299*	70-2249			8101060621	50-331
thological Associates, Inc.	8101140577*	50-320	R		8101060627*	50-331
	8101270578*	50-289	R		810120326	50-331
ho National Engineering Laboratory	8101060104	REB			8101120329*	50-331
	8101070555	50-295	P		8101120334	50-331
	8101100581	50-295	P		8101120336*	50-331
	8101100590	50-344	P		8101130631	50-331
	8101100601	REB			8101200280	50-331
	8101100804	50-409	P		8101200284*	50-331
	8101120291	REB			8101200300	50-331
	8101130711	50-247	P		8101200466*	50-331
	8101140673	50-304	P		8101200475*	50-331
	8101290668	REB			8101220335	50-331
	8101290692	NUREQ			8101220343*	50-331
	8101290703	NUREQ			8101220381	50-331
ho, State of	8101140084	State Prog			8101220385*	50-331
inois Power Co.	8101060731*	50-461	Q		8101220386	50-331
	8101070213	50-461	Q		8101220397	50-331
	8101070444	50-461	B			
	8101090631	50-461	A		8101220401*	50-331
	8101140532	PR		Isham, Lincoln & Beale	8101280550	50-331
	8101150606*	50-461	Q		8101280586*	50-331
	8101280600	50-461	Q		8012110423	50-10
	8101290057	50-461	Q		8101070394	50-329
	8101290057	50-461	Q			
	8101290069*	50-461	Q		8101070394	50-329
					8101090078	50-329
					8101090078	50-329
					8101090084	50-329

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8101090669	50-237 0	Kansas State Univ	8101270527	50-128
	8101090684	PR	Kansas, Univ of	8101160391*	50-148
	8101140969	50-329 0		8101160398*	50-148
	8101140973	50-329 0		8101160404*	50-148
	8101160209	50-155 0		8101160408*	50-148
	8101200154	50-329 0		8101160411*	50-148
	8101260480	50-329 0	Waye, Scholer, Fiernan, Hays & Handler	8101070022	FOIA
	8101280299	50-329 0	Kerr-McGee Chemical Corp (subs of	8101030555	50-10
	8101280299	50-329 0	Kerr-McGee Corp)		
	8101290012	50-324 0	Kerr-McGee Corp	8101100252	43-2561
				8101290533	40-2761
	8101290012	50-329 0			
	8101290020*	50-329 0	Kerr-McGee Nuclear Corp	8101070176*	PR
	8101290020*	50-329 0		8101070186*	PR
Isle of Wight County, VA	8101070613*	50-280 F		8101100162	40-8768
Isotope Products Laboratories	8101100509	XPORTLIC	Lateland Hosp Elkhorn, WI	8101140537	PR
			Laudig, S	8101070049	FOIA
Isabel Walton League of America, Porter County Chapter	8101090102	50-367 0	Lave, L	8101060750*	CONFRA*
	8101160242	50-367 0	Laurence Livermore Laboratory	8101120573	50-244
J F T Acapito & Associates, Inc	8101150127*	FOIA		8101140130	71-5795
	8101150134*	FOIA		8101140923	WREG
Jacksonville, FL	8101270555	50-437 A		8101150496*	50-247
Japan	8101100089	XPORTLIC		8101160690*	50-280
	8101100092	XPORTLIC		8101220188	REG
	8101100099	XPORTLIC		8101220255	REG
	8101100102	XPORTLIC		8101230477	50-206
Jersey Central Power & Light Co	8101050197	50-219 B		8101230480*	50-255
	8101050204*	50-219 S		8101280622*	50-29
	8101050211	50-219 S		8101290193	REG
	8101050219*	50-219 S		8101290674	REG
	8101050223	50-219 S		8101290785	50-255
	8101050229*	50-219 S		8101300009	WREG
	8101050252	50-219 S		8101300225	WREG
	8101050259*	50-219 S	LeBoeuf, Lamb, Leiby & MacRae	81012240365	State Proj
	8101050263	50-219 S		8101050077	50-341
	8101050379	50-219 S		8101150099	FOIA
	8101050469	50-219 S		8101150631	50-255
	8101050541*	50-219 S		8101290049	70-2623
	8101080172*	50-219 F	Lehigh Univ	8101130947	50-219
	8101080179*	50-219 F	Long Island Lighting Co	8101050109	50-322
	8101090034	50-219 P		8101060002*	50-322
	8101120216	50-219 F		8101060485	50-322
	8101130327	50-219 V		8101130368	50-322
	8101140669	50-219 Q		8101170329*	50-322
	8101140938	50-219 Q		8101260470	50-322
	8101150492	50-219 S		8101280222*	50-322
	8101150497*	50-219 S		8101290112	PR
	8101150690	50-219 S	Los Alamos Scientific Laboratory	8101100808	WREG
	8101150695*	50-219 S		8101150337	WREG
	8101160466	50-219 P		8101210271	WREG
	8101160469*	50-219 P		8101210278	WREG
	8101160471*	50-219 P		8101260127	50-337
	8101160484*	50-219 F		8101290135	REG
	8101160489*	50-219 F		8101290327*	70-734
	8101220946	50-219 R		8101290825	WREG
	8101230548*	50-219 R	Louisiana Power & Light Co.	8101070384	50-382
	8101230551	50-219 S		8101070389	50-382
	8101230556*	50-219 S		8101090500	50-382
	8101230560	50-219 S		8101100752*	50-382
	8101230564*	50-219 S		8101220302	50-382
	8101230569	50-219 S	Louisiana, State of	8101140122	State Proj
	8101230574*	50-219 S	Lovelace Biomed & Environmental Research Institute	8101300153	WREG
	8101260581	50-219 S			
	8101260664*	50-219 S	Lowenstein, Newman, Reis, Axelrad & Toll	8101090055	50-466
	8101280083	50-219 R		8101090094	50-276
	8101290546	50-219 S		8101090871	PR
	8101290771*	50-289 P		8101150011	50-466
				8101160261	50-389
Jones, Breun & Clifford KMC, Inc	8101230238	50-133 Q			
	8101050088	50-29 P		8101220621	PR
	8101140578	PR		8101230192	50-498
Kansans for Sensible Energy	8101230638	50-482 Q		8101230198	50-498
Kansas Gas & Electric Co	8101070375	50-482 S		8101230432	50-367
				8101280577	50-498
	8101070388	50-482 S			
	8101070401	50-482 S		8101280599	50-389
	8101070408	50-482 S		8101280641	50-367
	8101070420	50-482 S	Maine Yankee Atomic Power Co.	8101060320	50-306
	8101070426	50-482 S		8101070584*	50-309
				8101070591*	50-309
	8101070431	50-482 S			
	8101070433	50-482 S		8101120210	50-359
	8101070490	50-482 S		8101120229	50-309
	8101140873	PR		8101120233*	50-309
	8101270343	50-482 Q		8101160114*	50-309
				8101220340	50-309
	8101270352	50-482 Q			
	8101270360	50-482 Q		8101270368	50-309
	8101280048	50-482 Q		8101270667	50-309
	8101280497*	50-482 Q		8101270748	50-309

AFFILIATION	NUMBER	CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
ing, State of	8101290302	50-309 R		8101090181*	50-320
	8101290308*	50-309 R		8101090239	50-289
	8101300003	50-309 Q		8101090246*	50-289
	8101303542	50-309 F		8101090419	50-320
	8101300381*	CONTRACT		8101060405	50-289
pletion Intervenor's ort II Owners Group quette Univ	8101050358	50-329 Q		8101060632	50-289
	8101210373*	TOPREP		8101080103	50-289
	8101220003	PR		8101120437	50-289
	8101090457	50-335 J		8101130042	50-289
	8101090457	50-335 J		8101130053	50-289
ark's & McLennan, Inc. - M & M Nuclear Consultants, Inc. Div	8101090463	50-335 J		8101140260	50-320
	8101090464	50-335 J		8101140583	50-289
	8101090464	50-335 J		8101140650	50-320
	8101090466	50-302 J		8101140662	50-320
	8101090469	50-438 J		8101140730	50-320
	8101090469	50-438 J		8101140960	50-289
	8101090475	50-302 J		8101190244	50-320
	8101090478	50-250 J		8101190482	50-320
	8101090478	50-250 J		8101190486*	50-320
	8101090481	50-250 J		8101210740	50-320
	8101090486	50-289 J		8101210379	50-289
	8101090486	50-289 J		8101210379	50-289
	8101090486	50-289 J		8101210469	50-289
	8101090490	50-259 J		8101210471*	50-289
	8101090490	50-259 J		8101210941	50-320
	8101090490	50-259 J		8101210587	50-289
	8101090517	50-438 J		8101210594	50-289
	8101090517	50-438 J		8101220312	50-289
	8101090526	50-327 J		8101230219	50-289
	8101090526	50-327 J		8101230225	50-289
	8101090535	50-390 J		8101230534	50-320
	8101090535	50-390 J		8101230594	50-320
	8101090542	50-395 J		8101230613	50-320
	8101090550	50-321 J		8101230623	50-320
	8101090550	50-321 J		8101260507	50-289
	8101090556	50-338 J		8101260509*	50-289
	8101090556	50-335 J		8101270361*	50-289
	8101090561	50-302 J		8101270367*	50-289
	8101090566	50-327 J		8101270592	50-289
	8101090571	50-250 J		8101270605	50-289
	8101090571	50-250 J		8101270637	50-320
	8101090601	50-348 J		8101270648	50-289
	8101090647	50-259 J		8101270671*	50-320
	8101090647	50-259 J		8101270674	50-289
	8101090647	50-259 J		8101270721	50-289
	8101090650	50-321 J		8101270726*	50-289
	8101090650	50-321 J		8101290493	50-320
	8101090655	50-321 J		8101290520	50-289
	8101090655	50-321 J		8101290593	50-289
	8101090658	50-390 J		8101290652*	50-289
	8101090658	50-340 J		8101290657	50-289
	8101090663	50-327 J		8101290662*	50-289
	8101090663	50-327 J		8101290666*	50-289
	8101130357	50-280 J		8101290729*	50-289
	8101140233	50-321 J		8101290734*	50-289
	8101140353	50-327 J	Miami Valley Power Project	8101290737*	50-289
	8101210586	50-311 J		8101290755	50-289
	8101220351	50-346 J		8101290759*	50-289
	8101220545	50-348 J		8101300488	50-289
	8101270735	50-272 J		8101290726	50-358
yland, State of	8101270738	50-272 J	Michigan, State of Michigan, Univ. of Minerals Exploration Co. (subs. of Union Oil Co. of California)	8101300325*	CONTRACT
	8101190517	50-320 H		8101100129	40-8584
	8101300349*	CONTRACT		8101100134*	40-8584
	8101070362	50-206 P		8101300075*	CONTRACT
	8101100515	EXPORTLIC		8101050100	50-416
achusetts Institute of Technology Johnson Gas Products	8101230032	70-1308	Minnesota, State of	8101050329	50-416
	8101230049	70-1308		8101050329	50-416
	8101260175	70-1308		8101050335*	50-416
	8101270286	PROJ		8101050335*	50-416
	8101050072	50-369 Q		8101050339	50-416
ayer, Brown & Platt	8101050039	50-289 P	Mississippi Power & Light Co	8101050339	50-416
	8101050039	50-289 P		8101050341*	50-416
	8101050064	50-320 H		8101050341*	50-416
	8101050071	50-320 H		8101050346	50-416
	8101050081	50-289 T		8101050346	50-416
Cutchen, Doyle, Brown & Emerson cklenburg County, NC	8101050090*	50-289 T		8101060435	50-416
	8101050098*	50-289 T		8101060442*	50-416
	8101050105*	50-289 T		8101070443	50-416
	8101050111*	50-289 T		8101070445	50-416
	8101050123*	50-289 T		8101120009	50-416
etropolitan Edison Co.	8101050133*	50-289 T		8101120077*	50-416
	8101050150*	50-289 T		8101120123	50-416
	8101050157*	50-289 T		8101120125	50-416
	8101050174	50-320 S			

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8101130226	50-416 A		8101070353*	50-298 0
	8101130226	50-416 A		8101070355	50-298 0
	8101150639	50-416 K		8101070357*	50-298 0
	8101150639	50-416 K		8101070360	50-298 0
	8101190147	50-416 S		8101070363*	50-298 0
	8101220294	50-416 A		8101070477	50-298 0
	8101220294	50-416 A		8101070480*	50-298 0
	8101220337	50-416 A		8101070489	50-298 0
	8101220337	50-416 A		8101070492*	50-298 0
	8101220341	50-416 S		8101070507	50-298 0
	8101220341	50-416 S		8101070511*	50-298 0
	8101220474	50-416 G		8101070514	50-298 0
	8101230482	50-416 S		8101070521*	50-298 0
	8101230482	50-416 S		8101070642	50-298 0
	8101230496	50-416 A		8101080074	50-298 0
	8101230498	50-416 A		8101120050	50-298 0
	8101230500	50-416 S		8101120138	50-298 0
	8101230500	50-416 S		8101120162	50-298 0
	8101230559	50-416 S		8101120167*	50-298 0
	8101230559	50-416 S		8101130587	50-298 0
	8101230607	50-416 S		8101130593*	50-298 0
	8101230607	50-416 S		8101160448	50-298 0
	8101260519	50-416 S		8101270641	50-298 0
	8101260519	50-416 S		8101270643*	50-298 0
	8101260765	50-416 S		8101270649	50-298 0
	8101260765	50-416 S		8101270653*	50-298 0
	8101270088	50-416 S		8101270715	50-298 0
	8101270088	50-416 S		8101270719*	50-298 0
	8101270104	50-416 S		8101270775	50-298 0
	8101270104	50-416 S		8101270784*	50-298 0
	8101270843	50-416 A	Nevada, State of	8101140096	State Prog
	8101290367	50-416 G		8101200022	State Prog
	8101300388	50-416 S	New England Coalition on Nuclear Pollution	8101070513	50-443 Q
	8101300388	50-416 S		8101090306	50-443 Q
	8101300424	50-416 S	New Jersey, State of	8101080185*	50-214 F
	8101300455	50-416 S		8101060127*	WABTE HQ1
	8101300455	50-416 S	New Mexico, State of	8101130115	XPORTLIC
	8101300475	50-416 S	New York International Customs Service, Inc	8101130119*	XPORTLIC
	8101300475	50-416 S		8101280376	50-247 F
Mississippi State Univ	8101130371	50-241 H	New York Univ	8101270229	REH
Mississippi, State of	8101150499	50-416 A	New York Univ Medical Center New York, NY		
Missouri, State of	8101260102	50-482 Q		8101280173	50-37 F
	8101260192*	50-482 Q	New York, State Univ. of. Buffalo	8101100213	State Prog
Mitsubishi International Corp. (subs of Mitsubishi Corp.)	8101140945	XPORTLIC	New York, State of	8101100221	State Prog
	8101140950	XPORTLIC		8101190197*	50-247 F
Mitsui & Co. (U.S.A.), Inc. (Subs of Mitsui & Co., Ltd.)	8101150031	XPORTLIC		8101190202*	50-247 F
	8101150034*	XPORTLIC		8101190207*	50-247 F
	8101260362	XPORTLIC		8101190214*	50-247 F
Mobile Systems	8101210027*	CONTRACT		8101190650	State Prog
	8101140930	XPORTLIC		8101190679	State Prog
Monsanto Research Corp.	8101050506*	50-70 G	Newberry Township TMI Steering Committee	8101300316*	CONTRACT
Morgan, Lewis & Borkius	8101050515*	50-70 Q	Niagara Mohawk Power Corp.	8101200018	50-284 Q
	8101220178	PR		8101050087	50-220 F
Murray & Trettel, Inc	8101220374*	50-10 P		8101060400	50-220 F
	8101220379*	50-10 P		8101060540	50-220 F
	8101220391*	50-10 P		8101060546*	50-220 F
N.M. Newmark Consulting Engineering Services	8101200498*	CONTRACT		8101060639	50-220 F
NBS Corp	8101060457*	50-324 P		8101060647*	50-220 F
	8101060498*	50-324 P		8101070381	50-220 F
	8101190419*	50-324 P		8101070441	50-220 F
	8101220357*	50-280 P		8101070448	50-220 F
	8101280075*	27-39		8101070450*	50-220 F
NJBAC, Inc.	8101280451*	FOIA		8101070451*	50-220 F
	8101280453*	FOIA		8101070455*	50-220 F
	8101280459*	FOIA		8101070500	50-220 F
	8101280464*	FOIA		8101070504*	50-220 F
	8101280469*	FOIA		8101100419	50-220 F
	8101280474*	FOIA		8101100428*	50-220 F
	8101280478*	FOIA		8101120241	50-220 F
National Academy of Sciences	8101100316*	CONTRACT		8101120335	50-220 F
National Audubon Society, Central Midwest Regional Office	8101260249*	50-320 Q		8101120369*	50-220 F
Natural Resources Defense Council	8101160200	70-2623		8101130239	50-410 A
	8101230462	70-2623		8101140696	50-220 F
Navy, Dept. of	8101120042	71-400		8101150501	50-220 F
	8101120054	71-358		8101150502*	50-220 F
	8101120057*	71-358		8101150679	50-220 F
Navy, Dept. of, Naval Research Laboratory	8101160071	CONTRACT		8101150684*	50-220 F
Nebraska Public Power District	8101050466	30-298 P		8101210357	50-220 F
	8101070155*	50-298 Q		8101210593	50-220 F
	8101070351	50-298 S		8101220438*	50-220 F
				8101230580	50-220 F
				8101300055	50-220 F
				8101300452	50-410 F
			Nissho-Iwai American Corp.	8101290806	XPORTLIC

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
P. S. Andersen Pacific Gas & Electric Co	8101150638*	50-285 P	Pennsylvania, Univ. of Personnel Decisions, Inc Philadelphia Electric Co	8101160337*	50-320 F
	8101160403	50-285 Q		8101300093*	CONTRACT
	8101160485	50-285 R		8101220074	PR
	8101160488*	50-285 R		8101140843*	CONTRACT
	8101160542	50-235 Q		8101050265	50-277 S
	8101270731	50-285 J		8101050442	50-277 S
	8101300513	50-285 S		8101070348	50-277 S
	8101300519*	50-280 S		8101070369	50-352 S
	8101140813*	CONTRACT		8101070496	50-277 S
	8012290008	50-275 Q		8101090003	50-277 P
	8101050382	50-275 Q		8101090003	50-277 F
	8101050382	50-275 Q		8101100211*	50-277 Q
	8101050406	50-133 S		8101100775	50-277 Q
	8101050410*	50-133 S		8101120299	50-277 P
	8101060014	50-275 Q		8101120299	50-277 P
	8101060018	50-275 Q		8101120304*	50-277 P
	8101060018	50-275 Q		8101120304*	50-277 P
	8101070135	50-133 Q		8101120308*	50-277 F
	8101070206	50-133 Q		8101120308*	50-277 P
	8101120252	50-133 Q		8101120429	50-277 S
	8101120547	50-133 Q		8101130314	50-277 P
	8101130389	50-275 A		8101140519	50-278 S
	8101130566	50-275 Q		8101140744	50-278 Q
	8101130578	50-133 R		8101150873*	50-277 Q
	8101130585*	50-133 R		8101200266	50-278 S
	8101210555	50-275 A		8101210210	50-352 Q
	8101210555	50-275 A		8101210522	50-277 R
	8101220309	50-103 P		8101210522	50-277 R
	8101260301	50-275 Q		8101210528*	50-277 R
	8101260301	50-275 Q		8101220135*	50-277 Q
	8101270206	PROJ		8101220149*	50-277 Q
	8101270452	50-133 P		8101220149*	50-277 Q
	8101270672	50-275 A		8101220149*	50-277 Q
	8101280620	50-278 Q		8101230348	50-277 S
	8101300331	50-275 A		8101220352	50-278 S
Palos Community Hosp Paramater, Inc	8101300728*	50-275 F	Palos Park, IL Paramater, Inc	8101220468	50-278 S
	8101140527	PR		8101220477	50-277 S
	8101290746*	50-282 S		8101220483	50-277 S
Parsons, Brinkerhoff, Quade & Douglas, Inc	8002030467*	50-333 F	Parsons, Brinkerhoff, Quade & Douglas, Inc	8101220488	50-277 S
	8011250288	40-2259		8101220496*	50-277 S
	8101200019	40-6622		8101230330*	50-277 F
Pennsylvania Power & Light Co	8101270681	40-2259	Philadelphia, PA Philbrick, B S	8101230338*	50-277 F
	8012310383	50-387 Q		8101230434	50-352 U
	8101050332	50-387 S		8101230474	50-277 P
Pennsylvania State Univ	8101050071*	50-387 F	Philadelphia, PA Philbrick, B S	8101230586	50-277 S
	8101090071*	50-387 F		8101260500	50-352 S
	8101090075*	50-387 F		8101260564	50-277 S
	8101090075*	50-387 F		8101270319	50-463 Q
	8101090080*	50-387 F		8101270350	50-277 S
	8101090080*	50-387 F		8101270557*	50-277 S
	8101090703	50-387 H		8101270728	50-277 P
	8101090703	50-387 H		8101280506	50-278 S
	8101090897*	50-387 Q		8101280544	PR
	8101100076*	50-387 S		8101160211	50-352 Q
	8101120189	50-387 K		8101050637	ACRB
	8101120189	50-387 K		8101140934	XPGRLIC
	8101120194*	50-387 K		8101210310	50-344 H
	8101130320	50-387 A		8101220301	40-7869
	8101130466	50-387 A		8101070446	50-142 Q
	8101130466	50-387 A		8101050311	50-344 Q
	8101140861	50-387 Q		8101060028	50-344 Q
	8101150846*	50-387 Q		8101070346	50-344 P
	8101190387	50-387 A		8101120567	50-344 Q
	8101190387	50-387 A		8101130271	50-344 P
	8101190390*	50-387 A		8101130564	50-344 R
	8101190390*	50-387 A		8101130572*	50-344 R
	8101190783*	50-387 S		8101140218	50-344 J
	8101210362	50-387 S		8101190443	50-344 S
	8101260370	50-387 A		8101190445*	50-344 S
	8101260370	50-387 A		8101210293	50-344 P
	8101270423	50-387 S		8101220270	50-344 P
	8101270423	50-387 S		8101220274*	50-344 Q
	8101270482	50-387 A		8101270453	50-344 P
	8101280151	50-387 A		8101270503	50-344 Q
	8101280151	50-387 A		8101270657	50-344 Q
Pennsylvania State Univ	8101280158*	50-387 A	Power Authority of the State of New York	8101280539	50-344 S
	8101280158*	50-387 A		8101280546*	50-344 S
	8101300500	50-387 A		8002050463	50-333 F
Pennsylvania, State of	8101140431	PR	Portland General Electric Co.	8101060476	50-286 P
	8101300419	50-5 P		8101070382	50-286 F
	8101070202	50-387 Q		8101080129	50-333 Q
Pennsylvania, State of	8101070325*	50-320 F	Portland General Electric Co.	8101080407	50-286 P
	8101120506	50-289 Q		8101080416*	50-286 P
	8101120511*	50-289 Q		8101080426*	50-286 P
Pennsylvania, State of	8101070202	50-387 Q	Portland General Electric Co.	8101080407	50-286 P
	8101070325*	50-320 F		8101080416*	50-286 P
	8101120506	50-289 Q		8101080426*	50-286 P
Pennsylvania, State of	8101070202	50-387 Q	Portland General Electric Co.	8101080407	50-286 P
	8101070325*	50-320 F		8101080416*	50-286 P
	8101120506	50-289 Q		8101080426*	50-286 P

	8101090612	50-288	S		8101140643	50-546
	8101090618*	50-333	P		8101220560	REG00
	8101090621*	50-285	S		8101230487	50-546
	8101090694*	50-333	P			
	8101120200	50-333	P		8101290504	50-546
	8101120205*	50-333	P		8101300421*	50-546
	8101120209*	50-333	P	Public Service Co. of New Hampshire	8101230497	50-443
	8101120215	50-333	P		8101280091	50-443
	8101120220*	50-333	P	Public Service Electric & Gas Co. of New Jersey	8101290521	50-354
	8101120226*	50-333	P			
	8101120302	50-333	S		8101290528*	50-354
	8101120306	50-333	S		8101050083	50-272
	8101120310*	50-333	S		8101050497*	50-354
	8101120354*	50-333	S		8101060480	50-354
					8101070190	50-311
	8101130308	50-333	P			
	8101130552	50-333	R		8101070329	50-272
	8101130590*	50-333	R		8101070329	50-272
	8101140966	50-333	Q		8101070340*	50-272
	8101140975	50-333	Q		8101070540*	50-272
					8101070543*	50-272
	8101150645	50-286	V			
	8101160441	50-333	P		8101070343*	50-272
	8101160459	50-333	P		8101070557*	50-272
	8101160508	50-333	S		8101070557*	50-272
	8101160564*	50-333	S		8101070562*	50-272
					8101080299*	50-272
	8101200287	50-286	R			
	8101200290*	50-286	R		8101080299*	50-272
	8101210492	50-333	G		8101080303*	50-272
	8101210496*	50-333	S		8101090643	50-272
	8101210499	50-333	S		8101090651*	50-272
					8101090698	50-272
	8101210506*	50-333	S			
	8101260304	50-333	P		8101090707*	50-272
	8101270654	50-286	S		8101090892*	50-272
	8101270717	50-286	S		8101100760	50-272
	8101270722*	50-286	S		8101120320	50-272
					8101120324*	50-272
	8101270854	50-286	G			
	8101280117	50-333	P		8101120337	50-272
	8101280136	50-333	S		8101120376*	50-272
	8101300074*	50-333	Q		8101130322	50-272
	8101300466	50-286	F		8101130382	50-272
					8101130629	50-311
	8101300592	50-286	P			
	8101300596*	50-286	P		8101130635	50-311
	8101230172	50-461	Q		8101160481	50-272
	8101230172	50-461	Q		8101200357	50-272
	8101230178*	50-461	Q		8101200359*	50-272
					8101200396	50-272
	8101230178*	50-461	Q			
	8101290105*	CONTRACT			8101200391*	50-272
	8101140988	50-369	Q		8101200644*	50-272
	8101270047	50-247	Q		8101200644*	50-272
	8101060448	50-267	V		8101200645*	50-272
					8101200645*	50-272
	8101060556	50-267	V			
	8101070205*	50-267	Q		8101210455	50-311
	8101070211*	50-267	Q		8101210458*	50-311
	8101080085	50-267	Q		8101210476	50-272
	8101090602	50-267	F		8101210482*	50-272
					8101220103	PR
	8101120134	50-267	Q			
	8101120143	50-267	Q		8101230441	50-311
	8101120284	50-267	P		8101260552	50-272
	8101120425	50-267	P		8101260557	50-272
	8101120427*	50-267	P		8101260642*	50-272
					8101260650*	50-272
	8101130369	50-267	P			
	8101130374*	50-267	P		8101270491	50-272
	8101130393	50-267	P		8101270561	50-272
	8101130394*	50-267	P		8101270569*	50-272
	8101130396*	50-267	P		8101270616	50-272
					8101280499	50-272
	8101130398*	50-267	P			
	8101140191	50-267	Q		8101280504	50-272
	8101140486	50-267	R		8101290781*	50-354
	8101140489*	50-267	R	Puerto Rico Electric Power Authority	8101090094	50-376
	8101140625	50-267	S	Puget Sound Power & Light Co	81012310388	50-322
				Quadrex Corp	8101090111	REG00
	8101140630*	50-267	S			
	8101140639	50-267	S	R & D Associates	8101130263	PR
	8101140646*	50-267	S		8101130274*	PR
	8101210406	50-267	S		8101130333	PR
	8101210410*	50-267	S	Reactor Experiments, Inc	8101190756	XPORTL
				Rehab Group, Inc.	8101060321*	CONTRACT
	8101210480	50-267	S			
	8101210488*	50-267	S	Reliance Testing Laboratories, Inc.	8101080370	71-401
	8101220413	50-267	S		8101080376*	71-401
	8101220421*	50-267	S		8101140152	71-903
	8101220948	50-267	V	Rensselaer Polytechnic Inst.	8101270992	REG
				Reuter-Stokes, Inc.	8101100499	XPORTL
	8101220553*	50-267	V			
	8101230187	50-267	R		8101140885	XPORTL
	8101270629	50-267	P	Rhode Island, State of	8101060436*	COMMIS
	8101090015	50-546	A		8101060440*	COMMIS
	8101060449	NUREG			8101060446*	COMMIS
Public Service Co. of Indiana, Inc.						

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Rochester Gas & Electric Corp	8101090098	50-193 P	Schiff, Hardin & Waite	8101120537	50-289 Q
	8101210188	70-820		8101290037	50-461 Q
	7904270289	50-244 P		8101130260*	70-261
	7911140298	50-244 S	Schlumberger Technology Corp	8101270337	71-403
	8101060464	50-244 P		Schlumberger Well Services	8101270342*
	8101060468*	50-244 P	Science Applications, Inc	8101060942*	CONTRACT
	8101080112	50-244 Q		8101200480*	CONTRACT
	8101100401*	50-244 P		8101210578*	CONTRACT
	8101100794	50-244 Q		8101280447	FOIA
	8101120314	50-244 S		8101300291*	CONTRACT
8101120317*	50-244 S	Scientists & Engineers For Secure Energy	8101140423	PR	
8101150495	50-244 P		8101290762*	50-289 P	
8101150520	50-244 P		8101290766*	50-289 P	
8101210299	50-244 P	Senate	8101090022*	50-289 U	
8101210474	50-244 R		8101220371	PR	
8101210476*	50-244 R	Senate, Environment & Public Works	8101270304	50-247 H	
8101210639	50-244 S		8101290667*	50-263 H	
8101230418	50-244 P		8101300033*	50-392 H	
8101230422	50-244 P		8101300208*	50-309 H	
8101270665	50-244 P		8101150088	FOIA	
8101290589*	50-244 F	Shaw, Pittman, Potts & Trowbridge	8012090068	FOIA	
8101300064	50-244 Q		8101120437	50-289 Q	
8101190620	NUREG		8101120454	50-483 Q	
8101140379	PR		8101130042	50-289 Q	
8101280061	40-8697		8101130053	50-289 P	
8101280066	40-8380	8101190479	50-483 Q		
8101290502	40-8452		8101230219	50-289 Q	
8101290539	40-8380		8101230225	50-289 Q	
8101300438	40-8697		8101230609	50-289 Q	
8101200473*	CONTRACT		8101230615	50-483 Q	
8101050160	50-206 P	8101260486	50-483 Q		
8101060095	50-312 Q		8101270343	50-482 Q	
8101060773	50-312 S		8101270382	50-482 Q	
8101060781*	50-312 S		8101270398	50-289 T	
8101070564*	50-312 F		8101270360	50-482 Q	
8101070569*	50-312 F	8101280048	50-482 Q		
8101070656	50-312 Q		8101280307	50-483 Q	
8101100083*	50-312 Q		8101280311	50-289 Q	
8101100090*	50-312 Q		8101290065	PR	
8101120593	50-312 Q		8101290722	50-289 T	
8101120561	50-312 Q	8101070513	50-443 Q		
8101130303	50-312 P		8101080396	50-289 Q	
8101130492	50-312 S		8101090306	50-443 Q	
8101130517*	50-312 S		8101160200	70-2623	
8101150526	50-312 R		8101230238	50-133 Q	
8101150531*	50-312 R	8101230238	50-133 Q		
8101160427	50-312 S		8101060210	XPORTLIC	
8101200221	50-312 S		8101290541*	50-70 P	
8101200281	50-312 S		8101210605	FOIA	
8101200288*	50-312 S		8101060280*	CONTRACT	
8101220021*	50-312 F	8101060321*	CONTRACT		
8101220303	50-312 Q		8101050382	50-275 Q	
8101230598	50-312 S		8101050382	50-278 Q	
8101230602*	50-312 S		8101060018	50-275 Q	
8101270492	50-312 P		8101060018	50-275 Q	
8101270523	50-312 Q	8101280620	50-275 Q		
8101280297	50-312 S		8101060280*	CONTRACT	
8101280302*	50-312 S		8101220094	PR	
8101140949	50-275 Q		8101280210*	40-3483	
8101160278	50-275 Q		8101070307*	50-445 F	
8101190610	RES	810120060	71-102		
8101210325	RES		8101120061*	71-102	
8101270838	NUREG		8101050337	50-395 A	
8101270861	NUREG		8101060380	50-395 V	
8101270974	RES		8101060431	50-395 I	
8101290062	NUREG	8101060434*	50-395 I		
8101290066*	NUREG		8101060438*	50-395 I	
8101290073	RES		8101060441*	50-395 I	
8101290181	RES		8101060445*	50-395 I	
8101290186	RES		8101060474	50-395 D	
8101290213	RES	8101080227*	50-395 Q		
8101290245	RES		8101080417	50-395 A	
8101290279	RES		8101090013	50-395 V	
8101290439	RES		8101090015	50-395 A	
	NUREG		8101090128*	50-395 F	
	NUREG	8101090127*	50-395 F		
7-413	A		8101090489	50-395 K	
7-10	P		8101130089	50-395 A	
7-358	A		8101130098	50-395 Q	
			8101130102	50-395 A	
	0-373	A	8101130112*	50-395 A	
	NUREG			8101130121	50-395 A
	DPREP			8101130126	50-395 A
	DPREP			8101130293	50-395 A

CORPORATE SOURCE INDEX

40

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8101130296*	50-395 A	Standardized Nuclear Unit Power Plant System	8101050082	50-482
	8101150183	50-395 A		8101230565	50-482
	8101160290	50-395 A		8101270264	50-482
	8101160395	50-395 A		8101270690	50-482
	8101200258	50-395 A	State Dept of	8101050487	XPORTLIC
	8101210354	50-395 K	State Dept of, Bureau of Ocean & Internatl Environ & Scientific Affairs	8101090256	XPORTLIC
	8101210358*	50-395 K		8101090822	XPORTLIC
	8101220262	50-395 A		8101090992	XPORTLIC
	8101220557	50-395 S		8101100435	XPORTLIC
	8101230406	50-395 A		8101100442	XPORTLIC
	8101230410*	50-395 A		8101100453	XPORTLIC
	8101260491	50-395 S		8101100461	XPORTLIC
	8101260607	50-395 S		8101100474	XPORTLIC
	8101260643	50-395 S		8101100480	XPORTLIC
	8101270011	50-395 G		8101100485	XPORTLIC
	8101270496	50-395 V		8101120027	XPORTLIC
	8101280119	50-395 A		8101120186	XPORTLIC
	8101280287	50-395 S		8101120188	XPORTLIC
	8101280331	50-395 M		8101120198	XPORTLIC
	8101290129	50-395 F		8101200446	XPORTLIC
North Carolina Public Service Authority	8101290194	50-395 Q		8101210105	XPORTLIC
North Carolina, State of	8101280161	50-395 M		8101220587	XPORTLIC
North Dakota, State of	8101270062*	State Prog		8101280094	XPORTLIC
Southern California Edison Co.	8101200008	PRDJ		8101290457	XPORTLIC
	8101050074	50-206 G		8101290470	XPORTLIC
	8101050376	50-206 V		8101290477	XPORTLIC
	8101050376	50-206 V		8101290683	XPORTLIC
	8101050376	50-206 V		8101140886	50-280
	8101050386	50-395 Q	Steel, Hector & Davis	8101160261	50-389
	8101060024	50-206 Q		8101260503	50-280
	8101060408	50-206 F		8101050473*	50-298
	8101060438*	50-395 I		8101060489*	50-322
	8101060476	50-206 P	Stone & Webster Engineering Corp	8101070536*	50-358
	8101060813	50-206 V		8101090892	REG00
	8101060913	50-206 V		8101200640*	GA999
	8101060913	50-206 V		8101280077*	50-358
	8101060923*	50-206 V		8101210391*	CONTRACT
	8101060923*	50-206 V	Structural Mechanics Associates	8101060002*	50-322
	8101070216	71-9111	Suffolk County, NY	8101280222*	50-322
	8101090460	50-206 P		8101060742*	FOIA
	8101090903	50-395 A	Sun Shipbuilding & Dry Dock Co (subs Sun Co., Inc.)	8101060792*	FOIA
	8101090625	50-361 K		8101060766*	FOIA
	8101090625	50-361 K		8101140467	50-260
	8101130093	50-361 A	Surry County, VA	8101090924	XPORTLIC
	8101130225	50-361 C	Sweden	8101280358	FOIA
	8101130247	50-206 P	Syracuse Univ.		
	8101130289	50-206 P			
	8101130844	50-206 P	TERA Corp.	8101130555*	CONTRACT
	8101130638	50-206 G	Technimet Corp.	8101290746*	50-282
	8101140516	50-361 E		8101290749*	50-282
	8101140516	50-361 E	Teknekron Research, Inc.	8101270727	CONTRACT
	8101160110	50-361 A	Teknekron, Inc.	8101060237*	CONTRACT
	8101160465	50-206 P			
	8101160904	50-206 S	Teledyne Energy Systems	8012290613	71-6744
	8101160913*	50-206 S	Teledyne Isotopes	8101190103*	70-124
	8101200286	50-206 P	Tennessee Valley Authority	8011290336	50-327
	8101210232	50-206 Q		8011290339*	50-327
	8101210384	50-361 S		8101090215	50-327
	8101210384	50-361 S		8101050227*	50-327
	8101210484	50-206 R		8101050241	50-327
	8101210489*	50-206 R		8101050241	50-327
	8101210527	50-206 P		8101050250*	50-327
	8101220180	50-361 A		8101050255*	50-327
	8101220187	50-361 A		8101050255	50-327
	8101230128	50-361 Q		8101050330	50-327
	8101230128	50-361 Q		8101050365	50-438
	8101230128	50-361 Q		8101050365	50-438
	8101230137*	50-361 Q		8101050403	50-328
	8101230137*	50-361 Q		8101050434	50-327
	8101270511	50-206 Q		8101050434	50-327
	8101270517	50-361 Q		8101050439	50-390
	8101270731	50-206 P		8101060466	50-327
	8101290507	50-361 S		8101060477*	50-327
	8101300468	50-206 P		8101060715	50-259
	8101300759*	50-361 Q		8101060727*	50-259
	8012120057	PR		8101070374	50-327
University of Illinois, School of Medicine				8101070377*	50-327
West Fabricating & Welding Co. (subs. of IU International Corp.)	8101200112*	GA999		8101070417	50-438
West Research Institute	8101300217	NUREQ		8101070417	50-438
	8101300824	REB		8101070424	50-438
Wegman & McDermid	8101090348	50-389 M		8101070424	50-438
	8101090360*	50-389 M		8101070429	50-328

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8101080292*	50-518 Q		8101190496	50-296 Q
	8101080307*	50-510 Q		8101190593	50-299 Q
	8101090121*	50-438 Q		8101190603*	50-299 Q
	8101090677	50-259 S		8101190606	50-296 S
	8101090681*	50-259 S		8101190612*	50-296 S
	8101090834*	50-327 Q		8101200233*	50-327 F
	8101090877	RE000		8101200233*	50-327 F
	8101100287*	50-438 Q		8101200237*	50-327 F
	8101100287*	50-438 Q		8101200237*	50-327 F
	8101100381*	50-553 Q		8101210157	50-259 Q
	8101120240	50-327 Q		8101210157	50-259 Q
	8101120240	50-327 Q		8101210157	50-259 Q
	8101120240	50-327 Q		8101210239	50-328 Q
	8101120287	50-328 A		8101210239	50-328 Q
	8101120331	50-327 P		8101210239	50-328 Q
	8101120411	50-327 P		8101210239	50-328 Q
	8101120411	50-327 P		8101210327	50-438 Q
	8101130409	50-259 S		8101210348	50-553 Q
	8101130412*	50-259 S		8101210390	50-510 Q
	8101130429	50-260 S		8101210421	50-390 Q
	8101130436*	50-260 S		8101210421	50-390 Q
	8101130457	50-327 S		8101210421	50-390 Q
	8101130463*	50-327 S		8101210449	50-327 Q
	8101130467	50-296 S		8101210454*	50-327 S
	8101130503*	50-296 S		8101210466	50-327 S
	8101130562	50-259 R		8101220043	50-430 K
	8101130562	50-259 R		8101220044*	50-430 K
	8101130562	50-259 R		8101220058*	50-566 Q
	8101130568*	50-259 R		8101220155	50-327 R
	8101130568*	50-259 R		8101220155	50-327 R
	8101130568*	50-259 R		8101220164*	50-327 R
	8101130568*	50-259 R		8101220202	50-327 U
	8101130593	50-259 R		8101220207	50-553 A
	8101130593	50-259 R		8101220207	50-553 A
	8101130593	50-259 R		8101220211*	50-553 A
	8101130600	50-327 S		8101220291	50-327 P
	8101130601*	50-259 R		8101220291	50-327 P
	8101130601*	50-259 R		8101220311	50-259 U
	8101130601*	50-259 R		8101220311	50-259 U
	8101130612*	50-327 S		8101220311	50-259 U
	8101140474	50-328 S		8101220311	50-259 U
	8101140485	50-328 S		8101220311	50-259 U
	8101140485	50-328 S		8101220311	50-259 U
	8101140485	50-328 S		8101220311	50-259 U
	8101140499	50-918 S		8101220311	50-259 U
	8101140593	50-390 S		8101220311	50-259 U
	8101140593	50-390 S		8101220311	50-259 U
	8101140611	50-438 S		8101220311	50-259 U
	8101140616	50-328 S		8101220311	50-259 U
	8101140616	50-328 S		8101220311	50-259 U
	8101140616	50-328 S		8101220311	50-259 U
	8101140616	50-328 S		8101220372	50-430 A
	8101140616	50-328 S		8101220372*	50-430 A
	8101140616	50-328 S		8101220373*	50-430 A
	8101140616	50-328 S		8101220375*	50-430 A
	8101140627	50-438 S		8101220376	50-259 Q
	8101140636	50-328 S		8101220376	50-259 Q
	8101140866	50-259 Q		8101220376	50-259 Q
	8101150013	50-327 Q		8101220376	50-259 Q
	8101160292	50-259 Q		8101220377*	50-438 A
	8101160418	50-390 A		8101220383	50-327 Q
	8101160418	50-390 A		8101220411	50-259 P
	8101160418	50-390 A		8101220411	50-259 P
	8101160429	50-327 P		8101220411	50-259 P
	8101160462	50-390 S		8101220444	50-260 S
	8101160462	50-390 S		8101220449*	50-260 S
	8101160472	50-327 R		8101220499	50-327 S
	8101160474*	50-327 R		8101220505*	50-327 S
	8101160477	50-327 S		8101220511	50-327 S
	8101160483*	50-327 S		8101220518*	50-327 S
	8101160490	50-260 S		8101220523	50-327 S
	8101160494	50-327 P		8101220532*	50-327 S
	8101160498*	50-260 S		8101230296	50-391 S
	8101160520	50-259 S		8101230311	50-439 S
	8101160525*	50-259 S		8101230384	50-438 A
	8101160739*	50-260 Q		8101230426	50-518 S
	8101190031	50-518 Q		8101230436	50-327 S
	8101190362	50-438 S		8101230436	50-327 S
	8101190588	50-328 S		8101230468	50-393 Q
	8101190400	50-328 S		8101230468	50-393 Q
	8101190405	50-390 S		8101230408	50-438 S
	8101190405	50-390 S		8101230488	50-438 S
	8101190473	50-566 S		8101230542	50-390 S
	8101190480	50-328 S		8101230553	50-390 S
	8101190485	50-328 S		8101230553	50-390 S
	8101190490	50-260 S		8101230562	50-328 S
	8101190494	50-328 S		8101230608	50-390 S
	8101190495*	50-260 S		8101230608	50-390 U

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8101230718	50-518 S		8101300611	50-296 S
	8101260409	50-390 S		8101300619*	50-296 S
	8101260409	50-390 S		8101300620	50-259 S
	8101260416	50-327 P		8101300629*	50-259 S
	8101260418	50-328 P		8101300632	50-296 S
	8101260418	50-390 S		8101300641*	50-296 S
	8101260420*	50-327 P	Teton Exploration Drilling Co. Inc	8101210369	40-8770
	8101260427	50-328 S		8101210370*	40-8778
	8101260427	50-328 S	Texas A & M Univ	8101140154	71-398
	8101260427	50-328 S		8101140163*	71-398
	8101260436	50-328 S		81012290323*	50-247
	8101260436	50-328 S	Texas Instruments, Inc	8101140326*	50-247
	8101260438	50-390 S		8101230604	50-466
	8101260438	50-390 S	Texas Public Interest Research Group	8101070586*	50-213
	8101260446	50-438 S	Texas Tech Univ.	8101070508*	50-10
	8101260446	50-438 S		8101070608*	50-10
	8101260619*	50-259 F		8101070608*	50-10
	8101260619*	50-259 F		8101120149*	50-206
	8101260619*	50-259 F		8101200206*	50-29
	8101260624*	50-259 F		8101210181*	50-245
	8101260624*	50-259 F		8101210223*	50-219
	8101260674*	50-259 F		8101210233*	50-155
	8101260706*	50-259 F		8101270141*	50-409
	8101260706*	50-259 F		8101270156*	50-244
	8101260706*	50-259 F	Texas Utilities Co	8101070298*	50-445
	8101270030	50-328 Q		8101160500	50-445
	8101270231*	40-1341		8101160507*	50-445
	8101270234*	40-1341	Texas Utilities Generating Co	8101050318	50-445
	8101270242*	40-1341		8101050318	50-445
	8101270249	50-390 S		8101050470	50-445
	8101270251*	40-1341		8101090478	50-445
	8101270255*	40-1341		8101060462	50-445
	8101270419	50-438 S		8101100726*	50-445
	8101270427	TOPREP		8101100726*	50-445
	8101270572	50-296 S		8101100738*	50-445
	8101270579*	50-296 S		8101160233	50-445
	8101270609	50-328 S		8101160233	50-445
	8101270622	50-438 S		8101200242	50-445
	8101270639	50-553 S		8101200242	50-445
	8101270647	50-327 P		8101200246	50-445
	8101270659	50-438 S		8101200246	50-445
	8101270662	50-328 A		8101200293	50-445
	8101270668	50-296 R		8101200293	50-445
	8101270673*	50-296 S		8101210666	50-445
	8101270702	50-327 P		8101210666	50-445
	8101270705	50-296 S		8101270117	50-445
	8101270711*	50-296 S		8101270147	50-445
	8101270713	50-296 S		8101270152	50-445
	8101270716*	50-296 S		8101270182	50-445
	8101270732	50-328 S		8101270814	50-445
	8101280505	50-259 Q		8101270814	50-445
	8101280505	50-259 Q	Texas Utilities Services, Inc	8101270347	50-445
	8101280505	50-259 Q	Texas, State of	8101270968	WASTE MGT
	8101280527	50-259 Q	The Nuclear Regulatory Commission	8101290024	NUREG
	8101280527	50-259 Q	Thorne Ecological Institute	8101130400*	50-267
	8101280527	50-259 Q		8101230187	50-267
	8101290236	50-918 Q		8101130031	50-289
	8101290262	50-438 R	Three Mile Island Alert	8101160251	50-289
	8101290262	50-438 R		8101200018	50-289
	8101290269*	50-438 R	Tobin, J. B	8101270272	50-328
	8101290269*	50-438 R		8101270272	50-328
	8101290330	50-259 Q		8101270272	50-328
	8101290350	50-259 Q		8101270306*	50-328
	8101290489	50-918 S		8101270306*	50-328
	8101290550	50-438 S		8101270306*	50-328
	8101290550	50-438 S		8101050626	50-346
	8101290645	50-328 S	Toledo Edison Co.	8101060456	50-346
	8101290651	50-438 S		8101060459*	50-346
	8101290672	50-391 S		8101060473	50-346
	8101290672	50-391 S		8101060581	50-346
	8101300356	50-259 F		8101060588*	50-346
	8101300356	50-259 F		8101060597*	50-346
	8101300356	50-259 F		8101060603*	50-346
	8101300483	50-390 S		8101060610*	50-346
	8101300493	50-259 P		8101060614*	50-346
	8101300493	50-259 P		8101060624*	50-346
	8101300501	50-260 S		8101060667	50-346
	8101300504	50-296 S		8101060680*	50-346
	8101300509	50-327 S		8101060685	50-346
	8101300509	50-327 S		8101060692*	50-346
	8101300511	50-296 S		8101060698	50-346
	8101300512*	50-240 S		8101060709*	50-346
	8101300514*	50-296 S		8101060733	50-346
	8101300520*	50-296 S		8101060745*	50-346
	8101300523*	50-327 S		8101060749	50-346

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8101060757*	50-346 S	United Kingdom	8101290809	XPORALIC
	8101070200	50-346 G	United Nuclear - Homestake Partners	8101070170*	PR
	8101070378	50-346 P		8101070186*	PR
	8101070380*	50-346 P	United Nuclear Corp.	8012100268*	70-734
	8101080110*	50-346 F		8101100026	40-0720
	8101080170	50-346 Q		8101160412*	70-020
	8101090027	50-346 P		8101160413*	70-020
	8101090029*	50-346 P		8101160414*	70-020
	8101130415	50-346 S	United Nuclear Corp.-Naval Products Div.	8101220577*	70-371
	8101130417*	50-346 S		8101220584*	70-371
	8101130521	50-346 R		8101220629*	70-371
	8101130526*	50-346 R		8101290356	71-0006
	8101160461	50-346 P		8101290249	40-3453
	8101190503	50-346 P	Utah, State of	8101050169	50-271 P
	8101190509*	50-346 P	Vermont Yankee Nuclear Power Corp	8101050425	80-271 B
	8101200185	50-346 G		8101050433*	50-271 G
	8101220242	50-346 P		8101060366	80-271 P
	8101220424	50-346 S		8101060389	50-271 P
	8101220429*	50-346 S		8101060416	50-271 V
	8101220435	50-346 S		8101080347	50-271 G
	8101220440*	50-346 S		8101080352*	50-271 U
	8101220575	50-346 P		8101080391	50-271 P
	8101220582*	50-346 P		8101000430	50-271 P
	8101230405	50-346 P		8101070006	50-271 P
	8101260487	50-346 P		8101090533	80-271 P
	8101260493*	50-346 P		8101090539*	80-271 P
	8101270634	50-346 S		8101140707	80-271 J
	8101270636*	50-346 S		8101140913	80-271 U
	8101270676	50-346 P		8101150661	50-271 U
	8101270689	50-346 S		8101150685*	50-271 U
	8101270701*	50-346 S		8101160065*	50-271 G
	8101280348	50-346 G		8101160379	80-271 P
	8101280348	50-346 G		8101160447	80-271 P
	8101300484	50-346 P		8101160627*	50-271 Q
	8101300534*	50-346 G		8101160640*	50-271 Q
	8101300571*	50-346 G		8101200249	50-271 P
	8101300605	50-346 P		8101200388	80-271 P
	8101100276*	70-2479		8101210364	80-271 P
	8101100322*	FOIA		8101210500	80-271 R
	8101100334*	70-2479		8101210505*	80-271 R
	8101100362*	FOIA		8101220489	80-271 G
	8101100368*	FOIA		8101220462*	80-271 U
	8101100375*	FOIA		8101270682	80-271 P
	8101140679	XPORALIC		8101270746	80-271 P
	8101150020	XPORALIC		8101300092	80-271 Q
	8101150026*	XPORALIC		8101300315	80-271 P
	8101190366	XPORALIC		8101300487	80-271 P
	8101200407	40-800		8101090589*	80-131 F
	8101290102	XPORALIC	Vet. Admin. Hosp. Omaha, NE	8012300480	80-339 P
	8101090507	50-186 P	Virginia Electric & Power Co.	8101050352	50-338 P
	8101100393*	70-1739		8101050414	50-200 G
	8101070412	50-322 G		8101050423*	50-200 G
	8101070465	50-322 G		8101050488	50-200 H
	8101270675	50-322 G		8101050488	50-200 H
	8101270678*	50-322 G		8101050488	50-200 H
	8101160120	27-39		8101050488	50-200 H
	8101060770*	50-320 P		8101060308	50-200 P
	8101090929	ACR8		8101060308	50-200 P
	8101270610	40-8584		8101060308	50-200 P
	8101290448	40-8584		8101060308	50-200 P
	8012290618	71-5957		8101060349	50-338 P
	8101060111	NUREG		8101060367	50-338 G
	8101100157	70-687		8101060399*	50-338 G
	8101130123	50-34 P		8101070294	50-338 G
	8101220601	PR		8101070303*	50-338 G
	8101270470*	WASTE MGT		8101070309*	50-338 G
	8101270475*	WASTE MGT		8101070440*	80-338 P
	8101290649	WASTE MGT		8101070442*	80-338 P
	8101290654*	WASTE MGT		8101070454*	80-338 P
	8101120454	50-483 G		8101070454*	50-338 P
	8101120454	50-483 G		8101070457*	50-338 P
	8101140905	50-483 S		8101070487*	80-338 P
	8101140909	50-483 S		8101070602*	80-200 F
	8101190479	50-483 G		8101070607*	80-200 F
	8101230615	50-483 G		8101090474	50-281 G
	8101260486	50-483 G		8101090588	80-339 P
	8101270853*	50-483 G		8101090630	50-339 P
	8101280307	50-483 G		8101090638*	50-339 P
	8101090462	40-8584		8101090641	50-200 G
	8101210329	40-8584		8101090641	50-200 G
	8101120537	50-289 G		8101090652*	50-280 F
	8101260261	50-289 G		8101090661*	50-280 F
				8101120120	50-280 G
				8101120280	50-330 F
				8101120341	80-330 F

	8101080115	REQ00		8101130488*	50-339
	8101090020	50-397	Q	8101130493	50-339
	8101090021*	50-397	Q	8101130528*	50-339
	8101140416	REQ00		8101130534	50-339
	8101140497	50-397	B	8101130539*	50-339
	8101140518	50-397	B		
	8101190347	50-397	A	8101130542*	50-338
	8101190396	50-397	A	8101150114	50-338
	8101210561	50-397	A	8101160436	50-339
	8101220525*	50-508	Q	8101160503*	50-260
	8101270464	50-397	Q	8101160511*	50-280
	8101270471	50-397	Q	8101160696*	50-280
	8101270499	50-397	Q	8101190357	50-281
	8101270505	50-397	Q	8101190483	50-280
	8101270669	50-397	A	8101200218	50-338
	8101270743	50-395	D		
	8101300588*	50-460	Q	8101200229	50-280
Washington Service Bureau, Inc	8101290061	FOIA		8101200229*	50-280
Washington, State of	8101220068	PR		8101200235*	50-280
	8101270941	WASTE MGT		8101200235*	50-280
Washington, Univ. of	8101270201	REQ		8101200235*	50-280
	8101130637	50-445	Q	8101200235*	50-280
West Texas Legal Services	8101120004*	50-3	P	8101200278	50-338
Westchester County, NY	8101270319	50-247	Q	8101200278	50-338
	8101270957	40-1162		8101200285*	50-338
Western Nuclear, Inc. (subs of Phelps				8101200289*	50-338
Edgem Corp. I	8101100015	40-1162			
Western Nuclear, Inc.				8101200289*	50-338
	8101100021	40-1162		8101200295	50-280
Westinghouse Electric Corp	8012290493	71-6400		8101200297*	50-280
	8012290498*	71-6400		8101200333	50-281
	8012290502*	71-6400		8101200335*	50-281
	8101050327*	50-334	P		
	8101050347*	50-395	A	8101200337*	50-281
	8101060832	REQ		8101200339	50-280
	8101070036	REQ		8101200343*	50-280
	8101100298	XPORTLIC		8101200348*	50-280
	8101100525	XPORTLIC			
	8101130138*	50-29	P	8101200351	50-339
	8101130450*	50-255	P	8101200355*	50-339
	8101130584	TOPREP		8101200362	50-338
	8101140569	50-205	P	8101200364*	50-338
	8101140796*	CONTRACT		8101200375	50-339
	8101140931	70-2909			
	8101190330	TOPREP		8101200431	50-338
	8101200134	70-1151		8101200437*	50-338
	8101200420	TOPREP		8101200444	50-339
	8101200423*	TOPREP		8101200452*	50-339
	8101210372	TOPREP			
	8101210375*	TOPREP		8101210439	50-338
	8101210401*	TOPREP		8101210446*	50-338
	8101210483	REVIEW GRP		8101220328	50-339
	8101220279*	50-344	P	8101220354	50-280
	8101220283	PR		8101220369	50-339
	8101220333*	50-338	P		
	8101220333*	50-338	P	8101220370*	50-339
	8101220349*	50-364	P	8101220452	50-338
	8101220426	TOPREP		8101220456*	50-338
	8101220552	REQ00		8101220485	50-281
	8101230109*	50-338	Q	8101220492*	50-281
	8101230222*	TOPREP			
	8101260136	NUREG		8101220614	PR
	8101260317*	GA999		8101230460	50-339
	8101260389*	50-313	P	8101230593	50-339
	8101260516	TOPREP		8101230601*	50-339
	8101260649*	TOPREP		8101230605	50-280
	8101260652*	TOPREP			
	8101260657*	TOPREP		8101230611*	50-280
	8101270519*	50-348	P	8101270582	50-338
	8101270526*	50-348	P	8101270588*	50-338
	8101270955*	GA999		8101270707	50-404
	8101290676*	50-247	P	8101290396	50-280
	8101290812	XPORTLIC			
	8101300490	XPORTLIC		8101290396	50-280
Westinghouse Electric Corp., Nuclear	8101160473*	50-206	P	8101290396	50-280
Energy Systems	8101160475*	50-206	P	8101290757	50-338
				8101300188	50-338
				8101300193	50-280
				8101300562	50-339
				8101300597*	50-339
				8101300706	50-339
				8101300714*	50-339

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Westinghouse Electric Corp., PWR Systems Div WidoFF, Reager, Selikowitz & Adler Wisconsin Electric Power Co	8101210377*	TOPREP		8101090009*	50-271 P
	8101270346	40-1162		8101090321	50-29 P
	8101230211	TOPREP		8101120293	50-29 P
	8101130031	50-289 Q		8101120296*	50-29 P
	81012170579	50-301 S		8101130130	50-29 P
	81012170619*	50-301 S		8101140361	50-29 F
	8101050429	50-266 S		8101140664	50-29 Q
	8101050440*	50-266 S		8101140678*	50-29 P
	8101070570	50-266 Q		8101140682*	50-29 P
	8101090113*	50-266 F		8101140692*	50-29 P
	8101090113*	50-266 F		8101140953	50-29 Q
	8101090115*	50-266 F		8101150021	50-29 Q
	8101090115*	50-266 F		8101150312	50-29 R
	8101090118*	50-266 F		8101150814*	50-29 R
	8101120201	50-266 Q		8101210367*	50-271 P
	8101120333	50-266 S		8101270362	50-29 P
	8101120367*	50-266 S		8101270652	50-29 P
	8101140127	PR		8101300481	50-29 P
	8101150517	50-266 R		8101300703	50-29 S
	8101150519*	50-266 R		8101300726*	50-29 S
	8101160451	50-266 P	York, PA	8101070622*	50-280 F
	8101160451	50-266 P			
	8101200150	50-266 Q			
	8101210589	50-266 P			
	8101210589	50-266 P			
	8101220419*	50-266 Q		8101260379	50-305 P
	8101260340	50-266 F		8101270623	50-305 P
	8101260410	50-266 P		8101280518	50-305 S
	8101270360	50-266 S		8101280322*	50-305 S
	8101270364*	50-266 S		8101280528*	50-305 S
	8101270567	50-266 S		8101280535*	50-305 S
	8101270574*	50-266 S	Wisconsin, State of	8101300363*	50-305 Q
	8101270666	50-266 P		8101220403	50-266 Q
	8101270699	50-266 S	Wisconsin, Univ. of, Madison	8101300187*	CONTRACT
	8101270710*	50-266 S		8101260467	50-156 P
	8101280379	50-266 Q	Wolfbein, S L	8101300337*	CONTRACT
	8101280379	50-266 Q	Worcester Polytechnic Inst	8101160529	50-134 R
	8101280521	50-266 Q		8101290631*	50-134 K
	8101280521	50-266 Q		8101290637*	50-134 K
	8101050047	50-305 P	Wyle Laboratories	8101200291*	50-205 P
Wisconsin Public Service Corp			Wyoming Mineral Corp		
	8101060555	50-305 S		81012180067	40-8502
	8101060574*	50-305 S		81012180073*	40-8502
	8101070650	50-305 Q		8101270944	40-8502
	8101090629	50-305 P		8101270949*	40-8502
	8101090708	50-305 S		8101290115	40-8502
	8101130435	50-305 S	Wyoming, State of	8101290552	40-8504
	8101130440*	50-305 S		8101290109	40-8502
	8101130586	50-305 R		8101290543	40-8729
	8101130591*	50-305 R		8101290401	40-8502
	8101210316	50-305 Q		8101290606	40-8532
	8101210341	50-305 J	XVZYX Information Corp.	8101210953	CONTRACT
	8101220034	50-305 P	Yankee Atomic Electric Co.	8101070383	50-29 P
	8101220114*	50-305 Q		8101080403*	50-271 P
	8101220355	50-305 I		8101080443*	50-271 P
	8101220389	50-305 Q			

REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket, for example, 60-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondescript items are also entered in this column by symbol, for example, AGRS. Those categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the Index entitled "Cross Reference of Enclosures to Principal Documents."

FILE NUMBER	REPORT NUMBER	ACQUISITION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
01-1-10000	01-1-10000	010120000	RES	
01-1-10001	01-1-10001	010120001	RES	
01-1-10002	01-1-10002	010120002	RES	
01-1-10003	01-1-10003	010120003	RES	CRM-77 TR-1006
01-1-10004	01-1-10004	010120004	RES	UCRL-B2222
01-1-10005	01-1-10005	010120005	RES	
01-1-10006	01-1-10006	010120006	RES	
01-1-10007	01-1-10007	010120007	RES	
01-1-10008	01-1-10008	010120008	RES	
01-1-10009	01-1-10009	010120009	RES	
01-1-10010	01-1-10010	010120010	RES	
01-1-10011	01-1-10011	010120011	RES	
01-1-10012	01-1-10012	010120012	RES	
01-1-10013	01-1-10013	010120013	RES	
01-1-10014	01-1-10014	010120014	RES	
01-1-10015	01-1-10015	010120015	RES	
01-1-10016	01-1-10016	010120016	RES	
01-1-10017	01-1-10017	010120017	RES	
01-1-10018	01-1-10018	010120018	RES	
01-1-10019	01-1-10019	010120019	RES	
01-1-10020	01-1-10020	010120020	RES	
01-1-10021	01-1-10021	010120021	RES	
01-1-10022	01-1-10022	010120022	RES	
01-1-10023	01-1-10023	010120023	RES	
01-1-10024	01-1-10024	010120024	RES	
01-1-10025	01-1-10025	010120025	RES	
01-1-10026	01-1-10026	010120026	RES	
01-1-10027	01-1-10027	010120027	RES	
01-1-10028	01-1-10028	010120028	RES	
01-1-10029	01-1-10029	010120029	RES	
01-1-10030	01-1-10030	010120030	RES	
01-1-10031	01-1-10031	010120031	RES	
01-1-10032	01-1-10032	010120032	RES	
01-1-10033	01-1-10033	010120033	RES	
01-1-10034	01-1-10034	010120034	RES	
01-1-10035	01-1-10035	010120035	RES	
01-1-10036	01-1-10036	010120036	RES	
01-1-10037	01-1-10037	010120037	RES	
01-1-10038	01-1-10038	010120038	RES	
01-1-10039	01-1-10039	010120039	RES	
01-1-10040	01-1-10040	010120040	RES	
01-1-10041	01-1-10041	010120041	RES	
01-1-10042	01-1-10042	010120042	RES	
01-1-10043	01-1-10043	010120043	RES	
01-1-10044	01-1-10044	010120044	RES	
01-1-10045	01-1-10045	010120045	RES	
01-1-10046	01-1-10046	010120046	RES	
01-1-10047	01-1-10047	010120047	RES	
01-1-10048	01-1-10048	010120048	RES	
01-1-10049	01-1-10049	010120049	RES	
01-1-10050	01-1-10050	010120050	RES	
01-1-10051	01-1-10051	010120051	RES	
01-1-10052	01-1-10052	010120052	RES	
01-1-10053	01-1-10053	010120053	RES	
01-1-10054	01-1-10054	010120054	RES	
01-1-10055	01-1-10055	010120055	RES	
01-1-10056	01-1-10056	010120056	RES	
01-1-10057	01-1-10057	010120057	RES	
01-1-10058	01-1-10058	010120058	RES	
01-1-10059	01-1-10059	010120059	RES	
01-1-10060	01-1-10060	010120060	RES	
01-1-10061	01-1-10061	010120061	RES	
01-1-10062	01-1-10062	010120062	RES	
01-1-10063	01-1-10063	010120063	RES	
01-1-10064	01-1-10064	010120064	RES	
01-1-10065	01-1-10065	010120065	RES	
01-1-10066	01-1-10066	010120066	RES	
01-1-10067	01-1-10067	010120067	RES	
01-1-10068	01-1-10068	010120068	RES	
01-1-10069	01-1-10069	010120069	RES	
01-1-10070	01-1-10070	010120070	RES	
01-1-10071	01-1-10071	010120071	RES	
01-1-10072	01-1-10072	010120072	RES	
01-1-10073	01-1-10073	010120073	RES	
01-1-10074	01-1-10074	010120074	RES	
01-1-10075	01-1-10075	010120075	RES	
01-1-10076	01-1-10076	010120076	RES	
01-1-10077	01-1-10077	010120077	RES	
01-1-10078	01-1-10078	010120078	RES	
01-1-10079	01-1-10079	010120079	RES	
01-1-10080	01-1-10080	010120080	RES	
01-1-10081	01-1-10081	010120081	RES	
01-1-10082	01-1-10082	010120082	RES	
01-1-10083	01-1-10083	010120083	RES	
01-1-10084	01-1-10084	010120084	RES	
01-1-10085	01-1-10085	010120085	RES	
01-1-10086	01-1-10086	010120086	RES	
01-1-10087	01-1-10087	010120087	RES	
01-1-10088	01-1-10088	010120088	RES	
01-1-10089	01-1-10089	010120089	RES	
01-1-10090	01-1-10090	010120090	RES	
01-1-10091	01-1-10091	010120091	RES	
01-1-10092	01-1-10092	010120092	RES	
01-1-10093	01-1-10093	010120093	RES	
01-1-10094	01-1-10094	010120094	RES	
01-1-10095	01-1-10095	010120095	RES	
01-1-10096	01-1-10096	010120096	RES	
01-1-10097	01-1-10097	010120097	RES	
01-1-10098	01-1-10098	010120098	RES	
01-1-10099	01-1-10099	010120099	RES	
01-1-10100	01-1-10100	010120100	RES	
01-1-10101	01-1-10101	010120101	RES	
01-1-10102	01-1-10102	010120102	RES	
01-1-10103	01-1-10103	010120103	RES	
01-1-10104	01-1-10104	010120104	RES	
01-1-10105	01-1-10105	010120105	RES	
01-1-10106	01-1-10106	010120106	RES	
01-1-10107	01-1-10107	010120107	RES	
01-1-10108	01-1-10108	010120108	RES	
01-1-10109	01-1-10109	010120109	RES	
01-1-10110	01-1-10110	010120110	RES	
01-1-10111	01-1-10111	010120111	RES	
01-1-10112	01-1-10112	010120112	RES	
01-1-10113	01-1-10113	010120113	RES	
01-1-10114	01-1-10114	010120114	RES	
01-1-10115	01-1-10115	010120115	RES	
01-1-10116	01-1-10116	010120116	RES	
01-1-10117	01-1-10117	010120117	RES	
01-1-10118	01-1-10118	010120118	RES	
01-1-10119	01-1-10119	010120119	RES	
01-1-10120	01-1-10120	010120120	RES	
01-1-10121	01-1-10121	010120121	RES	
01-1-10122	01-1-10122	010120122	RES	
01-1-10123	01-1-10123	010120123	RES	
01-1-10124	01-1-10124	010120124	RES	
01-1-10125	01-1-10125	010120125	RES	
01-1-10126	01-1-10126	010120126	RES	
01-1-10127	01-1-10127	010120127	RES	
01-1-10128	01-1-10128	010120128	RES	
01-1-10129	01-1-10129	010120129	RES	
01-1-10130	01-1-10130	010120130	RES	
01-1-10131	01-1-10131	010120131	RES	
01-1-10132	01-1-10132	010120132	RES	
01-1-10133	01-1-10133	010120133	RES	
01-1-10134	01-1-10134	010120134	RES	
01-1-10135	01-1-10135	010120135	RES	
01-1-10136	01-1-10136	010120136	RES	
01-1-10137	01-1-10137	010120137	RES	
01-1-10138	01-1-10138	010120138	RES	
01-1-10139	01-1-10139	010120139	RES	
01-1-10140	01-1-10140	010120140	RES	
01-1-10141	01-1-10141	010120141	RES	
01-1-10142	01-1-10142	010120142	RES	
01-1-10143	01-1-10143	010120143	RES	
01-1-10144	01-1-10144	010120144	RES	
01-1-10145	01-1-10145	010120145	RES	
01-1-10146	01-1-10146	010120146	RES	
01-1-10147	01-1-10147	010120147	RES	
01-1-10148	01-1-10148	010120148	RES	
01-1-10149	01-1-10149	010120149	RES	
01-1-10150	01-1-10150	010120150	RES	
01-1-10151	01-1-10151	010120151	RES	
01-1-10152	01-1-10152	010120152	RES	
01-1-10153	01-1-10153	010120153	RES	
01-1-10154	01-1-10154	010120154	RES	
01-1-10155	01-1-10155	010120155	RES	
01-1-10156	01-1-10156	010120156	RES	
01-1-10157	01-1-10157	010120157	RES	
01-1-10158	01-1-10158	010120158	RES	
01-1-10159	01-1-10159	010120159	RES	
01-1-10160	01-1-10160	010120160	RES	
01-1-10161	01-1-10161	010120161	RES	
01-1-10162	01-1-10162	010120162	RES	
01-1-10163	01-1-10163	010120163	RES	
01-1-10164	01-1-10164	010120164	RES	
01-1-10165	01-1-10165	010120165	RES	
01-1-10166	01-1-10166	010120166	RES	
01-1-10167	01-1-10167	010120167	RES	
01-1-10168	01-1-10168	010120168	RES	
01-1-10169	01-1-10169	010120169	RES	
01-1-10170	01-1-10170	010120170	RES	
01-1-10171	01-1-10171	010120171	RES	
01-1-10172	01-1-10172	010120172	RES	
01-1-10173	01-1-10173	010120173	RES	
01-1-10174	01-1-10174	010120174	RES	
01-1-10175	01-1-10175	010120175	RES	
01-1-10176	01-1-10176	010120176	RES	
01-1-10177	01-1-10177	010120177	RES	
01-1-10178	01-1-10178	010120178	RES	
01-1-10179	01-1-10179	010120179	RES	
01-1-10180	01-1-10180	010120180	RES	
01-1-10181	01-1-10181	010120181	RES	
01-1-10182	01-1-10182	010120182	RES	
01-1-10183	01-1-10183	010120183	RES	
01-1-10184	01-1-10184	010120184	RES	
01-1-10185	01-1-10185	010120185	RES	
01-1-10186	01-1-10186	010120186	RES	
01-1-10187	01-1-10187	010120187	RES	
01-1-10188	01-1-10188	010120188	RES	
01-1-10189	01-1-10189	010120189	RES	
01-1-10190	01-1-10190	010120190	RES	
01-1-10191	01-1-10191	010120191	RES	
01-1-10192	01-1-10192	010120192	RES	
01-1-10193	01-1-10193	010120193	RES	
01-1-10194	01-1-10194	010120194	RES	
01-1-10195	01-1-10195	010120195	RES	
01-1-10196	01-1-10196	010120196	RES	
01-1-10197	01-1-10197	010120197	RES	
01-1-10198	01-1-10198	010120198	RES	
01-1-10199	01-1-10199	010120199	RES	
01-1-10200	01-1-10200	010120200	RES	
01-1-10201	01-1-10201	010120201	RES	
01-1-10202	01-1-10202	010120202	RES	
01-1-10203	01-1-10203	010120203	RES	
01-1-10204	01-1-10204	010120204	RES	
01-1-10205	01-1-10205	010120205	RES	
01-1-10206	01-1-10206	010120206	RES	
01-1-10207	01-1-10207	010120207	RES	
01-1-10208	01-1-10208	010120208	RES	
01-1-10209	01-1-10209	010120209	RES	
01-1-10210	01-1-10210	010120210	RES	
01-1-10211	01-1-10211	010120211	RES	
01-1-10212	01-1-			

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
8101270371	8101270371	RES		NJREG-0400 V4 H01	8101300397	NUREG	
8101270545	8101270545	50-537 A		NJREG-0422 S4	8101270931	50-369 E	
8101270774	8101270774	RES	SAL/IEH3 T-MSLR	NJREG-0485 V3 H01	8101270703	NUREG	
8101270942	8101270942	RES		NJREG-0490	8101270455	50-361 D	
8101270548	8101270548	RES		NJREG-0517 DRFT S5	8101270303*	50-311 P	
8101270551	8101270551	RES		NUREG-0525 R3	8101100128	NUREG	
8101270073	8101270073	RES		NUREG-0540 V2 K09	8101220614	NUREG	
8101270125	8101270125	RES		NUREG-0540 V2 H10	8101270310	NUREG	
8101270151	8101270151	RES		NUREG-0584 R1	8101080256	NUREG	
8101270152	8101270152	RES		NUREG-0610	8101130689*	NUREG	
8101270156	8101270156	RES		NUREG-0623	8101140550	NUREG	
8101270193	8101270193	RES	UCRL-B2224	NUREG-0633	8101140944	NUREG	
8101270213	8101270213	RES		NUREG-0636	8101200545	50-320 P	
8101270243	8101270243	RES	SAL/IEH3 J-PLSR	NUREG-0669 V3	8101260379	NUREG	
8101270245	8101270245	RES		NUREG-0683	8101270220*	50-320 P	
8101270279	8101270279	RES	SAL/IEH3 T-MSLR	NUREG-0683 ERR	8101270214*	50-320 P	
8101270288	8101270288	RES		NUREG-0746 ERR	8101100508*	50-289 F	
8101270674	8101270674	RES		NUREG-0747	8101130402	NUREG	
8101270679	8101270679	RES		NUREG-0752	8101050634*	50-289 T	
8101270682	8101270682	RES	CRNL/HASRD-104	NUREG-0756	8101190400*	50-250 P	
8101270687	8101270687	RES	CRNL/HASRD-104				
8101270691	8101270691	RES	CRNL/HASRD-104	NUREG/BN-0006	8101270706	NUREG	
8101270741	8101270741	RES		NUREG/BN-0007	8101270811	NUREG	
8101270761	8101270761	RES		NUREG/CP-0019	8101120359	NUREG	
8101270763	8101270763	RES		NUREG/CH-0247	8101050697*	TREE-1208	
				NUREG/CR-0773 ERR	8101270989*	NUREG	
8101300078	8101300078	RES	NRC-04-76-215	NJREG/CR-0912 V1	8101300223	NUREG	UCRL-52719 V1
8101300154	8101300154	50-254 P	EQO-EA-5253	8101190620	8101190620	NUREG	
8101300175	8101300175	50-266 P	EQO-EA-5327	NJREG/CR-1070	8101260136	NUREG	CRNL/508-739471
8101300185	8101300185	50-237 P	EQO-EA-5332	NJREG/CR-1132	8101270100	NUREG	PNL-2787
8101300822	8101300822	RES	EQO-LCFT-5310	NJREG/CR-1157 V3	8101270361	NUREG	SAND80-1091
8101300821	8101300821	RES		NUREG/CR-1169	8101140923	NUREG	UCRL-52724
8101300837	8101300837	50-334 P	EQO-EA-5326	NJREG/CR-1171	8101140539	NUREG	HEDL-THE 79-65
8101300837	8101300837	50-309 P	EQO-EA-5324	NJREG/CR-1174	8101130301	NUREG	RH-901-9
8101300842	8101300842	50-10 P	EQO-EA-5325	NJREG/CR-1211	8101060111	NUREG	
8101300845	8101300845	RES	EQO-LCFT-5316	NJREG/CH-1240 V3	8101220603	NUREG	HEDL-THE 80-2
8101300847	8101300847	50-255 F	EQO-EA-5321	NUREG/CR-1240 V4	8101220501	NUREG	HEDL-THE 80-3
8101300849	8101300849	50-331 P	EQO-EA-5280	NJREG/CR-1241	8101100357	NUREG	HEDL-THE 80-4
8222	8101270182*	50-498 Q		NJREG/CR-1274	8101090445	NUREG	CRNL/NUREG/TH-3
2A-80-9-BL1	8101270269*	50-438 R		NJREG/CR-1398	8101260127	50-537 A	LA-8301
3A-164B	8101070286*	50-269 P		NJREG/CR-1465	8101300768	NUREG	EQO-2040
BCL-585-19	8101270569*	50-213 S		NJREG/CH-1507	8101270715	NUREG	SAND80-1267
BML-NJREG-27834	8101270626	RES		NJREG/CR-1510	8101270830	NUREG	SAND80-1277
BML-NJREG-27961	8101270622	RES		NJREG/CR-1518	8101270666*	NUREG	SAND80-0701
BML-NJREG-28109	8101270642	RES		NJREG/CR-1614	8101260114	NUREG	CRNL/508-7656/1
BML-NJREG-28115	8101270623	RES		NJREG/CR-1641	8101270703	NUREG	EQO-2046
BML-NJREG-28343	8101270625	RES		NJREG/CR-1645	8101270131	NUREG	DPST-NUREG-80-1
BML-NJREG-28625	8101220628	RES		NJREG/CR-1717 V3	8101260163	NUREG	BNL-NJREG-51263
BML-NJREG-28682	8101270090	RES		NJREG/CR-1717 V4	8101260144	NUREG	BNL-NJREG-51263
BML-NJREG-28724	8101270637	50-258 P		NJREG/CR-1738	8101270827	50-537 A	BNL-NJREG-51280
BML-NJREG-28750	8101270631	50-295 P		NJREG/CR-1768	8101270817	NUREG	CRNL/NJREG/TH-4
BML-NJREG-28787	8101200682	RES		NJREG/CR-1774	8101050751	NUREG	CRNL/NJREG/TH-4
BML-NJREG-28796	8101300543	RES		NJREG/CR-1787	8101210370	NUREG	LA-8547-M5
BML-NJREG-28797	8101300674	RES		NJREG/CR-1790	8101270811	NUREG	CRNL/NJREG/TH-4
CE-1-A R15	8101090005*	50-10 P		NJREG/CR-1791	8101270796	NUREG	CRNL/NJREG/TH-4
CEN-143(A1)-NP	8101220417*	50-368 P		NJREG/CR-1794 V3	8101210271	NUREG	LA-8593-PR
CEN-145(3) NP	8101230541*	50-317 Q		NJREG/CR-1794 V4	8101270825	NUREG	LA-8596-FR
CENPD-201-A S1	8101270714*	TGPREP		NJREG/CR-1795	8101130047	50-219 P	RE
CGE-03-087	8101270553*	50-358 A		NJREG/CR-1801	8101270319	NUREG	ANL-80-107
CGE-03-144	8101270651*	50-359 A		NJREG/CR-1806	8101270302	NUREG	CRNL/NJREG/TH-4
CT-24821 RO	8101270333*	50-338 P		NJREG/CR-1811	8101150337	NUREG	LA-8607-PR
DIS-NS-01-012	8009150849*	50-10 P		NJREG/CR-1817	8101100800	NUREG	LA-8613-M5
EQO-144R-5311	8101300199	RES		NJREG/CR-1818	8101270943	NUREG	PNL-3583
EPA-520/1-76-010	8101130017*	FOIA		NJREG/CR-1821	8101120575	50-244 P	UCRL-55014
EGDP-ESE-16 R2	8101210377*	TGPREP	5206A	NJREG/CR-1823	8101130414	NUREG	EQO-CAAP-3217
ESRG 80-31	8101270683*	50-322 Q		NJREG/CR-1824	8101130408	NUREG	EQO-CAAP-3219
GP-R-33007	8101270569*	50-321 P		NJREG/CR-1828	8101090762	NUREG	CRNL/NJREG/TH-4
HP256-LP281-LP281	8101230107*	50-338 Q		NJREG/CR-1829	8101090765	NUREG	CRNL/NJREG/TH-4
IE-121	8101270746*	50-282 S	NRC-1E-80/81	NJREG/CR-1833	8101270785	50-255 P	UCRL-33015
LO-111-80-071	8101300145	RES		NJREG/CR-1842	8101270642	NUREG	EQO-2073
NEDD-10466-A ERR 1	8101210531*	TGPREP		NJREG/CR-1871	8101300153	NUREG	LHF-80
NEDD-21894-3	8101230059*	70-130B		NJREG/CR-1880	8101300207	NUREG	BNL-NJREG-51323
NEDD-24057A	8101090209*	TGPREP		NJREG/CR-1885	8101300217	NUREG	
NEDD-24197 R1	8101230494*	50-263 Q		NUS-3696	8101060457*	50-261 P	
NEDD-24229-1	8101120309*	50-277 P	BONE0270	NUS-3697	8101060498*	50-324 P	
NR-AIC-003	8101280074	MISC		NUS-3697 ERR	8101190419*	50-324 P	
NSAC-20	8101190500*	50-296 S	INPO-3	NUS-3735 V1	8101220357*	50-280 P	
NJREG CR-1859	8101300009	NUREG	UCRL-53016	PNL-2980	8101220249	RES	
NJREG-0020 V4 H12	8101300439	NUREG		PNL-2951	8101220620	RES	
NJREG-0030 V3 H03	8101270001	NUREG		RH-77-2-ED-1	8101270242*	40-1341	6173
NJREG-0090 V3 H02	8101140736*	COMMISSION		RH-80-7-502	8101220164*	50-327 R	
NJREG-0330 V3 H05	8101210785	NUREG		RP36A05	8101190518*	50-315 P	
NJREG-0380 V4 H03	8101270967	NUREG		SCP-01 R3	8101130265*	TGPREP	
NJREG-0383 V1 R3	8101130311	NUREG		SECY-77-465	8101100345*	FOIA	
NJREG-0383 V2 R3	8101130374	NUREG		SECY-78-233	8101100314*	FOIA	
NJREG-0383 V3	8101130330	NUREG		SECY-78-423	8101100288*	FOIA	

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8012220449	8012220437	80/11/28	50-10 P	8101050433	8101050425	80/12/24	50-271 S
8012220456	8012220437	80/11/28	50-10 P	8101050438	8101050320	80/12/26	50-313 S
8012230491	8012230485	80/12/16	50-324 S	8101050448	8101050429	80/12/23	50-266 S
8012240379	8012240365	80/11/17	State Prog	8101050449	8101050444	80/12/05	50-335 S
8012290323	8012290320	80/12/19	50-247 F	8101050460	8101050455	80/12/23	50-366 S
8012290463	8012290476	80/12/11	10CFR	8101050473	8101050466	80/12/30	50-290 P
8012290498	8012290495	80/11/20	71-6400	8101050476	8101050469	80/12/19	50-336 P
8012290502	8012290495	80/11/20	71-6400	8101050497	8101050491	80/11/07	50-394 S
8012290571	8012290565	80/12/10	71-4986	8101050501	8101050432	80/12/26	50-368 S
8012290581	8012290577	80/11/26	71-5805	8101050506	8101050494	80/12/29	50-70 Q
8101050508	8101050505	80/12/22	50-483 Q	8101050509	8101050440	80/12/26	50-368 S
8101050502	8101050516	80/12/19	50-155 Q	8101050515	8101050494	80/12/29	50-70 Q
8101050503	8101050524	80/12/16	50-163 R	8101050519	8101050452	80/12/26	50-368 S
8101050504	8101050534	80/12/22	50-289 T	8101050534	8101050480	80/12/10	50-251 S
8101050504	8101050534	80/12/22	50-289 T	8101050536	8101050167	80/12/11	50-302 P
8101050505	8101050534	80/12/22	50-289 T	8101050537	8101050463	80/12/26	50-313 S
8101050506	8101050534	80/12/22	50-289 T	8101050541	8101050469	80/12/23	50-219 S
8101050509	8101050562	80/10/21	WREO	8101050542	8101050484	80/12/03	50-250 S
8101050570	8101050566	80/12/29	50-265 P	8101050546	8101050472	80/12/22	50-316 S
8101050580	8101050577	80/12/31	50-341 K	8101050547	8101050490	80/12/11	50-251 S
8101050585	8101050577	80/12/31	50-341 K	8101050576	8101050570	80/12/29	50-155 F
8101050590	8101050581	80/12/22	50-289 T	8101050579	8101050573	80/12/16	70-1151
8101050598	8101050581	80/12/22	50-289 T	8101050580	8101050570	80/12/29	50-155 F
8101050101	8101050594	80/12/22	50-269 P	8101050589	8101050583	80/12/12	50-131 F
8101050105	8101050581	80/12/22	50-289 T	8101050598	8101050594	80/12/11	70-27
8101050105	8101050102	80/12/10	50-369 A	8101050600	8101050595	80/12/22	50-329 Q
8101050111	8101050581	80/12/22	50-289 T	8101050631	8101050628	80/12/02	COMMISSION
8101050112	8101050107	80/12/22	50-287 P	8101050634	8101050628	80/12/02	COMMISSION
8101050113	8101050110	80/12/02	50-261 P	8101050635	8101050633	80/12/19	50-320 F
8101050123	8101050581	80/12/22	50-289 T	8101060002	8101060001	80/12/31	50-322 Q
8101050132	8101050116	80/12/30	50-329 F	8101060044	8101060041	80/11/24	10CFR
8101050133	8101050581	80/12/22	50-287 T	8101060089	8101060081	80/12/16	50-312 Q
8101050145	8101050116	80/12/30	50-327 F	8101060119	8101060114	80/12/08	WASTE MGT
8101050150	8101050581	80/12/22	50-287 T	8101060122	8101060114	80/12/08	WASTE MGT
8101050157	8101050581	80/12/22	50-287 T	8101060127	8101060114	80/12/08	WASTE MGT
8101050165	8101050162	80/12/23	71-9007	8101060130	8101060114	80/12/08	WASTE MGT
8101050173	8101050171	80/12/23	71-6373	8101060204	8101060194	80/12/15	50-262 F
8101050181	8101050174	80/12/24	50-320 S	8101060237	8101060231	80/12/19	CONTRACT
8101050187	8101050176	80/12/11	TOPHEP	8101060250	8101060249	80/12/18	CONTRACT
8101050169	8101050183	80/12/22	CONTRACT	8101060272	8101060269	80/12/30	50-329 Q
8101050192	8101050185	80/12/29	50-317 S	8101060277	8101060274	80/12/11	50-170 H
8101050194	8101050184	80/11/21	50-261 Q	8101060280	8101060275	80/11/13	CONTRACT
8101050204	8101050197	80/12/22	50-219 S	8101060281	8101060278	80/12/30	50-358 Q
8101050308	8101050200	80/12/02	CONTRACT	8101060287	8101060279	80/12/15	70-143
8101050217	8101050211	80/12/23	50-219 S	8101060290	8101060285	80/12/23	50-295 Q
8101050227	8101050215	80/12/30	50-327 P	8101060291	8101060279	80/12/15	70-143
8101050229	8101050223	80/12/23	50-219 S	8101060292	8101060288	80/12/30	50-335 P
8101050234	8101050220	80/11/13	40-1241	8101060295	8101060279	80/12/15	70-143
8101050246	8101050258	80/12/24	50-289 S	8101060303	8101060297	80/12/30	50-250 P
8101050250	8101050241	80/12/31	50-327 R	8101060306	8101060300	80/11/26	50-546 Q
8101050259	8101050252	80/12/23	50-219 S	8101060311	8101060309	80/12/31	50-250 P
8101050264	8101050260	80/12/31	50-302 P	8101060321	8101060313	80/10/15	CONTRACT
8101050267	8101050262	80/12/22	50-282 P	8101060339	8101060333	80/12/30	50-317 P
8101050275	8101050269	80/12/23	50-313 R	8101060341	8101060328	80/12/31	CONTRACT
8101050282	8101050280	80/12/12	50-466 D	8101060347	8101060328	80/12/31	CONTRACT
8101050288	8101050281	80/11/18	50-498 A	8101060353	8101120271	80/12/29	50-369 A
8101050327	8101050321	80/12/31	50-334 P	8101060378	8101060374	80/10/02	50-335 P
8101050330	8101050321	80/12/31	50-334 P	8101060434	8101060431	80/12/31	50-393 I
8101050335	8101050329	80/12/31	50-416 K	8101060436	8101060432	80/12/03	COMMISSION
8101050336	8101050331	80/12/26	50-313 S	8101060438	8101060431	80/12/31	50-393 I
8101050341	8101050329	80/12/31	50-416 K	8101060440	8101060432	80/12/03	COMMISSION
8101050342	8101050324	80/11/20	50-250 S	8101060441	8101060431	80/12/31	50-393 I
8101050345	8101050340	80/12/24	50-304 Q	8101060442	8101060435	80/12/29	50-416 A
8101050347	8101050337	80/12/30	80-395 A	8101060445	8101060431	80/12/31	50-393 I
8101050349	8101050328	80/11/28	50-335 S	8101060446	8101060432	80/12/03	COMMISSION
8101050363	8101050348	80/12/29	50-247 S	8101060457	8101060453	80/12/31	50-261 P
8101050395	8101050331	80/12/29	50-287 S	8101060459	8101060456	80/12/15	50-346 Q
8101050365	8101050360	80/12/06	50-250 S	8101060468	8101060464	80/12/30	50-244 P
8101050367	8101050361	80/12/26	50-368 S	8101060471	8101060467	80/12/30	50-249 S
8101050377	8101050373	80/12/26	50-368 S	8101060477	8101060466	80/12/30	50-327 S
8101050380	8101050374	80/12/22	50-409 S	8101060479	8101060469	80/12/27	50-249 S
8101050387	8101050381	80/12/26	50-368 S	8101060482	8101060472	80/12/29	50-263 S
8101050388	8101050382	80/12/18	50-275 Q	8101060484	8101060481	80/12/27	50-237 S
8101050391	8101050383	80/12/26	50-409 S	8101060488	8101060483	80/12/29	50-269 P
8101050396	8101050390	80/12/22	50-254 S	8101060489	8101060485	80/12/22	50-322 S
8101050403	8101050399	80/12/20	50-317 S	8101060491	8101060483	80/12/29	50-269 P
8101050410	8101050406	80/12/30	50-133 S	8101060492	8101060486	80/12/29	50-263 S
8101050413	8101050408	80/12/30	50-317 S	8101060498	8101060494	80/12/30	50-324 P
8101050420	8101050417	80/12/11	50-302 P	8101060507	8101060500	80/12/23	50-528 A
8101050423	8101050414	80/12/23	50-280 S	8101060509	8101060503	80/12/30	50-269 I

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
B101060523	B101060513	80/12/30	50-206 V	B101070152	B101070145	80/12/11	50-259 Q
B101060530	B101060524	80/12/24	50-289 H	B101070155	B101070146	80/12/15	50-278 Q
B101060533	B101060524	80/12/24	50-289 H	B101070159	B101070145	80/12/11	50-359 Q
B101060538	B101060524	80/12/24	50-289 H	B101070164	B101070158	80/12/05	50-313 Q
B101060543	B101060524	80/12/24	50-289 H	B101070174	B101070170	80/11/21	50-255 Q
B101060545	B101060524	80/12/24	50-289 H	B101070178	B101070172	80/10/28	FR
B101060546	B101060540	80/12/26	50-289 H	B101070181	B101070170	80/11/21	50-255 Q
B101060551	B101060524	80/12/24	50-289 H	B101070183	B101070179	80/12/18	50-213 P
B101060554	B101060524	80/12/24	50-289 H	B101070186	B101070172	80/10/28	FR
B101060560	B101060524	80/12/24	50-289 H	B101070205	B101070198	80/12/04	50-267 Q
B101060563	B101060524	80/12/24	50-289 H	B101070211	B101070198	80/12/04	50-267 Q
B101060566	B101060559	80/12/30	50-366 S	B101070217	B101070215	80/11/14	50-267 Q
B101060568	B101060524	80/12/24	50-289 H	B101070223	B101070215	80/11/14	50-329 Q
B101060573	B101060564	80/12/31	50-321 P	B101070233	B101070229	80/11/19	50-329 Q
B101060574	B101060555	80/12/30	50-305 S	B101070236	B101070229	80/11/19	50-329 Q
B101060579	B101060572	80/12/30	50-366 S	B101070244	B101070240	80/11/18	50-285 Q
B101060583	B101060561	80/12/30	50-409 P	B101070252	B101070247	80/11/19	50-382 Q
B101060588	B101060581	80/12/26	50-346 S	B101070256	B101070248	80/12/02	50-213 F
B101060593	B101060582	80/12/30	50-321 S	B101070261	B101070257	80/11/14	50-382 Q
B101060596	B101060590	80/12/10	10CFR	B101070270	B101070265	80/12/01	50-320 F
B101060597	B101060581	80/12/26	50-346 S	B101070286	B101070269	81/01/02	50-269 P
B101060599	B101060567	81/01/02	50-339 S	B101070297	B101070292	80/12/22	70-2249
B101060603	B101060581	80/12/26	50-346 S	B101070298	B101070291	80/12/02	50-445 F
B101060604	B101060598	80/12/30	50-237 S	B101070299	B101070292	80/12/22	70-2249
B101060610	B101060581	80/12/26	50-346 S	B101070302	B101070291	80/12/02	50-445 F
B101060614	B101060581	80/12/26	50-346 S	B101070303	B101070294	80/10/14	50-338 Q
B101060617	B101060608	80/12/29	50-237 S	B101070306	B101070301	80/12/04	50-187 Q
B101060624	B101060581	80/12/26	50-346 S	B101070307	B101070291	80/12/02	50-445 F
B101060627	B101060621	80/12/31	50-331 S	B101070309	B101070294	80/10/14	50-338 Q
B101060633	B101060629	80/04/08	50-184 R	B101070310	B101070303	80/12/15	XPDR T L C
B101060635	B101060630	80/12/30	50-155 S	B101070316	B101070313	80/12/03	50-413 Q
B101060637	B101060632	80/11/17	50-289 Q	B101070319	B101070317	80/12/17	50-367 A
B101060641	B101060632	80/11/17	50-289 Q	B101070325	B101070322	80/12/01	50-320 F
B101060647	B101060639	80/12/29	50-220 J	B101070327	B101070324	81/01/05	50-352 T
B101060652	B101060632	80/11/17	50-289 Q	B101070332	B101070324	81/01/05	50-352 T
B101060657	B101060632	80/11/17	50-289 Q	B101070334	B101070331	80/12/11	50-321 Q
B101060660	B101060640	80/12/30	50-321 S	B101070336	B101070331	80/12/11	50-321 Q
B101060669	B101060648	80/12/30	50-366 S	B101070338	B101070331	80/12/11	50-321 Q
B101060674	B101060668	80/12/30	50-155 S	B101070342	B101070331	80/12/11	50-298 S
B101060680	B101060667	81/01/02	50-346 S	B101070353	B101070351	80/11/20	50-298 S
B101060689	B101060678	80/12/30	50-261 S	B101070357	B101070355	80/11/25	50-298 S
B101060692	B101060685	81/01/02	50-346 S	B101070363	B101070360	80/11/19	50-298 S
B101060705	B101060698	81/01/02	50-259 S	B101070369	B101070365	80/12/31	50-324 S
B101060727	B101060715	80/12/30	50-461 Q	B101070373	B101070370	80/12/30	50-324 S
B101060731	B101060721	80/12/11	50-461 Q	B101070377	B101070374	80/12/30	50-327 S
B101060736	B101060724	80/12/22	FOIA	B101070380	B101070378	81/01/02	50-344 P
B101060742	B101060724	80/12/22	FOIA	B101070385	B101070383	80/12/26	50-29 P
B101060748	B101060733	81/01/02	70-1100	B101070439	B101070436	80/12/30	50-334 R
B101060747	B101060739	80/10/31	CONTRACT	B101070440	B101070434	80/12/02	50-338 F
B101060750	B101060743	80/12/14	CONTRACT	B101070443	B101070434	80/12/02	50-338 F
B101060752	B101060724	80/12/22	FOIA	B101070450	B101070448	81/01/03	50-220 Q
B101060757	B101060749	81/01/02	50-346 S	B101070451	B101070448	81/01/03	50-220 Q
B101060759	B101060724	80/12/22	FOIA	B101070452	B101070452	80/12/02	50-338 F
B101060766	B101060724	80/12/22	FOIA	B101070455	B101070448	81/01/03	50-220 Q
B101060769	B101060761	80/12/17	50-285 S	B101070457	B101070452	80/12/02	50-338 F
B101060770	B101060764	80/11/28	50-320 P	B101070468	B101070465	80/12/31	50-322 Q
B101060775	B101060724	80/12/30	50-312 S	B101070478	B101070471	80/12/06	REGD S
B101060781	B101060773	80/12/18	CONTRACT	B101070480	B101070477	80/12/15	50-298 S
B101060790	B101060783	80/12/18	50-316 S	B101070482	B101070471	80/12/06	REGD S
B101060806	B101060800	80/09/17	NUREG	B101070495	B101070471	80/12/06	REGD S
B101060819	B101060812	80/12/24	70-143 P	B101070499	B101070499	80/11/26	50-298 S
B101060861	B101060856	80/12/08	50-213 P	B101070502	B101070498	80/12/31	50-324 S
B101060873	B101060867	80/12/08	50-313 Q	B101070504	B101070500	80/12/29	50-220 S
B101060887	B101060884	80/11/26	50-313 Q	B101070511	B101070507	80/11/18	50-298 S
B101060942	B101060937	80/12/01	COMMISSION	B101070521	B101070514	80/11/14	50-298 S
B101060953	B101060952	80/12/12	COMMISSION	B101070522	B101070518	80/12/01	50-321 F
B101060954	B101060952	80/12/12	50-320 P	B101070526	B101070518	80/12/01	50-321 F
B101060956	B101060955	80/12/30	FOIA	B101070529	B101070515	80/12/01	50-338 F
B101070012	B101070004	80/12/30	50-395 Q	B101070531	B101070524	80/12/26	50-334 S
B101070017	B101070010	80/12/31	FOIA	B101070536	B101070515	80/12/01	50-338 F
B101070053	B101070046	80/12/30	FOIA	B101070537	B101070532	80/12/11	WASTE MGT
B101070070	B101070059	80/12/29	FOIA	B101070540	B101070533	80/12/17	50-272 F
B101070080	B101070076	80/11/25	50-10 Q	B101070543	B101070533	80/12/17	50-272 F
B101070118	B101070113	80/11/25	50-10 Q	B101070545	B101070541	80/12/17	COMMISSION
B101070125	B101070113	80/12/10	50-338 P	B101070546	B101070538	80/12/18	50-289 Q
B101070134	B101070129	80/12/10	50-338 P	B101070550	B101070541	80/12/17	COMMISSION
				B101070557	B101070551	80/11/14	50-272 F
				B101070562	B101070551	80/11/14	50-272 F
				B101070564	B101070559	80/12/16	50-312 F

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
B101070565	B101070558	80/12/18	50-267 P	B101090070	B101090064	80/12/19	50-254 S
B101070569	B101070559	80/12/18	50-312 F	B101090071	B101090067	80/11/13	50-387 F
B101070584	B101070560	80/12/03	50-309 F	B101090075	B101090067	80/11/13	50-387 F
B101070586	B101070577	80/12/08	50-213 P	B101090079	B101090074	80/11/18	50-255 Q
B101070590	B101070582	80/12/04	PR	B101090080	B101090067	80/11/13	50-387 F
B101070591	B101070583	80/12/03	50-309 F	B101090088	B101090064	80/12/19	50-254 S
B101070602	B101070595	80/12/01	50-280 F	B101090091	B101090064	80/12/19	50-254 S
B101070607	B101070595	80/12/01	50-280 F	B101090096	B101090064	80/12/19	50-254 S
B101070608	B101070594	80/12/15	50-10 F	B101090103	B101090064	80/12/19	50-254 S
B101070613	B101070595	80/12/01	50-280 F	B101090113	B101090110	80/12/01	50-266 F
B101070622	B101070595	80/12/01	50-280 F	B101090114	B101090074	80/11/18	50-255 Q
B101070628	B101070600	80/11/07	PR	B101090115	B101090110	80/12/01	50-266 F
B101070638	B101070600	80/11/07	PR	B101090118	B101090110	80/12/01	50-266 F
B101070645	B101070641	80/12/08	PR	B101090121	B101090112	80/12/05	50-438 Q
B101070655	B101070652	80/12/15	XPRTLIC	B101090125	B101090123	80/12/01	50-395 F
B1010800357	B1010800647	80/12/12	PR	B101090127	B101090123	80/12/01	50-395 F
B1010800358	B101080052	80/12/10	50-302 Q	B101090137	B101090132	80/12/09	FOIA
B101080063	B101080079	80/11/28	50-254 Q	B101090142	B101090132	80/12/09	50-237 Q
B101080092	B101080079	80/11/28	50-254 Q	B101090150	B101090132	80/12/09	50-237 Q
B101080137	B101080101	80/12/03	50-346 F	B101090157	B101090132	80/12/09	50-237 Q
B101080110	B101080101	80/12/03	50-346 F	B101090161	B101090132	80/12/09	50-237 Q
B101080114	B101080104	80/12/11	50-272 P	B101090163	B101090132	80/12/09	FOIA
B101080137	B101080133	80/12/01	50-335 F	B101090165	B101090132	80/12/09	FOIA
B101080140	B101080131	80/12/23	50-498 A	B101090169	B101090132	80/12/09	FOIA
B101080142	B101080133	80/12/01	50-335 F	B101090171	B101090168	80/12/08	50-255 Q
B101080145	B101080141	80/12/12	50-269 Q	B101090172	B101090132	80/12/09	FOIA
B101080159	B101080141	80/12/12	50-269 Q	B101090179	B101090132	80/12/09	FOIA
B101080161	B101080141	80/12/12	50-269 Q	B101090183	B101090132	80/12/09	FOIA
B101080172	B101080162	80/12/03	50-219 F	B101090184	B101090175	80/12/10	50-269 P
B101080177	B101080141	80/12/12	50-269 Q	B101090188	B101090132	80/12/09	FOIA
B101080179	B101080162	80/12/03	50-219 F	B101090195	B101090175	80/12/10	50-269 P
B101080186	B101080162	80/12/03	50-219 F	B101090196	B101090132	80/12/09	FOIA
B101080310	B101080206	80/11/17	50-250 Q	B101090202	B101090132	80/12/09	FOIA
B101080327	B101080217	80/12/16	50-395 Q	B101090205	B101090175	80/12/10	50-269 P
B101080333	B101080217	80/12/16	50-395 Q	B101090209	B101090198	81/01/06	TOPREP
B101080357	B101080217	80/12/16	50-395 Q	B101090213	B101090132	80/12/09	FOIA
B101080348	B101080217	80/12/16	50-395 Q	B101090225	B101090214	80/11/28	50-313 Q
B101080358	B101080249	80/12/01	50-282 F	B101090244	B101090234	80/12/09	50-254 Q
B101080366	B101080249	80/12/01	50-282 F	B101090246	B101090238	80/12/05	COMMISSION
B101080371	B101080264	80/11/19	50-440 Q	B101090307	B101090298	80/12/03	FOIA
B101080384	B101080264	80/11/19	50-440 Q	B101090318	B101090298	80/12/03	FOIA
B101080392	B101080267	80/12/05	50-518 Q	B101090330	B101090321	80/12/25	50-287 Q
B101080396	B101080267	80/11/14	50-482 Q	B101090335	B101090328	80/11/17	State Prog
B101080397	B101080274	80/11/14	50-272 P	B101090351	B101090343	80/11/10	70-1007
B101080399	B101080279	80/12/12	50-320 U	B101090360	B101090348	81/01/08	50-389 M
B101080395	B101080294	80/11/14	50-272 P	B101090399	B101090392	80/12/10	CONTRACT
B101080397	B101080267	80/12/05	50-518 Q	B101090493	B101090487	80/12/29	TOPREP
B101080399	B101080301	80/11/18	50-453 Q	B101090538	B101090531	80/12/11	XPRTLIC
B101080318	B101080267	80/12/05	50-518 Q	B101090539	B101090533	81/01/05	50-271 P
B101080326	B101080267	80/12/05	50-518 Q	B101090597	B101090590	81/01/06	50-302 S
B101080331	B101080314	80/12/22	COMMISSION	B101090609	B101090603	81/01/05	50-302 S
B101080335	B101080370	80/12/11	50-320 H	B101090611	B101090604	81/01/06	50-333 P
B101080336	B101080314	80/12/22	COMMISSION	B101090618	B101090604	81/01/06	50-333 P
B101080340	B101080352	80/12/12	XPRTLIC	B101090621	B101090612	81/01/05	50-286 S
B101080343	B101080267	80/12/05	50-518 Q	B101090622	B101090614	81/01/05	50-302 S
B101080352	B101080347	81/01/02	50-271 S	B101090632	B101090626	81/01/05	50-213 S
B101080360	B101080314	80/12/22	COMMISSION	B101090638	B101090630	81/01/02	50-339 S
B101080361	B101080355	80/11/13	50-305 Q	B101090651	B101090643	81/01/02	50-272 S
B101080362	B101080314	80/12/22	50-466 U	B101090652	B101090641	81/01/05	50-280 S
B101080368	B101080356	80/12/29	50-293 S	B101090661	B101090641	81/01/05	50-280 S
B101080375	B101080355	80/11/13	50-305 Q	B101090666	B101090657	81/01/02	50-287 S
B101080375	B101080355	80/11/13	50-305 Q	B101090670	B101090667	81/01/05	50-325 S
B101080376	B101080370	80/12/09	71-401	B101090671	B101090677	80/12/31	50-259 S
B101080392	B101080314	80/12/22	COMMISSION	B101090692	B101090685	81/01/06	50-316 S
B101080397	B101080384	81/01/02	50-316 S	B101090694	B101090684	81/01/06	50-333 P
B101080403	B101080391	80/12/31	50-271 P	B101090706	B101090695	80/12/16	CONTRACT
B101080406	B101080384	81/01/02	50-316 S	B101090707	B101090698	81/01/02	50-272 S
B101080416	B101080407	80/12/30	50-286 P	B101090721	B101090712	80/12/05	50-438 Q
B101080426	B101080399	80/12/13	QAPPP	B101090727	B101090712	80/12/05	50-438 Q
B101080425	B101080407	80/12/30	50-286 P	B101090729	B101090722	80/12/08	WASTE MOT
B101080443	B101080430	80/12/31	50-271 P	B101090739	B101090712	80/12/05	50-438 Q
B101090035	B101090001	81/01/02	50-10 P	B101090746	B101090739	80/07/29	50-302 P
B101090039	B101090036	80/12/31	50-271 P	B101090753	B101090745	80/12/11	50-344 P
B101090021	B101090020	80/12/31	50-397 Q	B101090756	B101090739	80/07/29	50-302 P
B101090022	B101090019	81/01/06	50-289 U	B101090760	B101090745	80/12/11	50-344 P
B101090029	B101090027	81/01/05	50-346 P	B101090766	B101090739	80/07/29	50-302 P
B101090030	B101090028	81/01/06	50-364 A	B101090785	B101090778	80/12/03	50-10 Q
B101090032	B101090028	81/01/05	50-364 A	B101090796	B101090779	80/12/03	70-821
B101090039	B101090047	81/01/05	TOPREP	B101090802	B101090790	80/11/18	50-332 Q
B101090046	B101090054	80/12/19	50-254 S	B101090800	B101090800	80/12/10	50-254 Q

ACCESSION NUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
B101090821	B101090814	80/11/25	70-143
B101090834	B101090825	80/12/11	50-327 Q
B101090838	B101090827	80/12/23	71-9044
B101090841	B101090825	80/12/11	50-327 Q
B101090845	B101090825	80/12/11	50-327 Q
B101090849	B101090825	80/12/11	50-327 Q
B101090852	B101090847	80/11/07	50-272 Q
B101090857	B101090853	80/11/10	50-387 Q
B101090858	B101090847	80/11/07	50-272 Q
B101090862	B101090853	80/11/10	50-387 Q
B101090863	B101090847	80/11/07	50-272 Q
B101090865	B101090853	80/11/10	50-387 Q
B101090869	B101090853	80/11/10	50-387 Q
B101090883	B101090878	80/10/30	50-333 Q
B101090888	B101090847	80/11/07	50-272 Q
B101090893	B101090893	80/12/18	CONTRACT
B101090917	B101090907	80/12/19	71-4906
B101090937	B101090932	80/12/16	50-155 Q
B101090938	B101090935	80/12/11	50-344 P
B101090939	B101090935	80/12/11	50-344 P
B101090940	B101090942	80/12/18	50-155 Q
B101090942	B101090932	80/12/16	50-155 Q
B101090943	B101090941	80/12/12	50-317 P
B101090945	B101090941	80/12/12	50-317 P
B101090947	B101090941	80/12/12	50-317 P
B101090953	B101090950	80/12/19	50-313 P
B101090956	B101090950	80/12/19	50-313 P
B101090959	B101090950	80/12/19	50-313 P
B101091020	B101090958	80/12/17	CONTRACT
B101100008	B101100005	80/12/19	50-313 Q
B101100010	B101100007	80/12/10	COMMISBION
B101100013	B101100011	80/11/21	50-329 Q
B101100021	B101100029	80/11/14	50-290 Q
B101100038	B101100033	80/11/20	50-423 Q
B101100051	B101100049	80/12/12	50-367 Q
B101100056	B101100049	80/12/12	50-367 Q
B101100063	B101100059	80/11/19	50-445 Q
B101100074	B101100067	80/12/18	50-267 Q
B101100076	B101100071	80/11/13	50-387 Q
B101100082	B101100079	80/12/03	50-320 Q
B101100083	B101100078	80/12/04	50-312 Q
B101100086	B101100078	80/12/04	50-312 Q
B101100090	B101100078	80/12/04	50-312 Q
B101100094	B101100078	80/12/04	50-312 Q
B101100097	B101100078	80/12/04	50-312 Q
B101100103	B101100078	80/12/04	50-312 Q
B101100134	B101100129	80/11/20	40-B584
B101100135	B101100133	80/09/23	50-170 U
B101100153	B101100115	80/11/24	50-254 U
B101100163	B101100155	80/12/09	50-289 H
B101100176	B101100166	80/12/03	50-458 Q
B101100178	B101100171	80/11/19	50-445 Q
B101100181	B101100174	80/12/10	50-266 Q
B101100189	B101100182	80/11/12	50-461 Q
B101100193	B101100188	80/12/11	50-309 Q
B101100194	B101100193	80/10/16	50-271 Q
B101100197	B101100182	80/11/12	50-461 Q
B101100198	B101100161	80/12/12	FOIA
B101100203	B101100161	80/12/12	FOIA
B101100207	B101100200	80/12/10	COMMISBION
B101100209	B101100202	80/10/29	50-305 Q
B101100210	B101100161	80/12/12	FOIA
B101100211	B101100204	80/11/13	50-277 Q
B101100212	B101100200	80/12/10	COMMISBION
B101100218	B101100204	80/11/13	50-277 Q
B101100219	B101100200	80/12/10	COMMISBION
B101100222	B101100161	80/12/12	FOIA
B101100224	B101100204	80/11/13	50-277 Q
B101100225	B101100217	80/11/19	50-313 Q
B101100226	B101100200	80/12/10	COMMISBION
B101100230	B101100161	80/12/12	FOIA
B101100232	B101100204	80/11/13	50-277 Q
B101100233	B101100200	80/12/10	COMMISBION
B101100236	B101100217	80/11/19	50-313 Q
B101100238	B101100200	80/12/10	COMMISBION
B101100239	B101100161	80/12/12	FOIA
B101100244	B101100204	80/11/13	50-277 Q
B101100245	B101100200	80/12/10	COMMISBION
B101100251	B101100247	80/10/16	50-445 Q
B101100259	B101100253	80/12/18	50-184 P

ACCESSION NUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
B101100261	B101100161	80/12/12	FOIA
B101100269	B101100260	80/11/19	50-498 Q
B101100271	B101100254	80/11/20	50-3 P
B101100272	B101100161	80/12/12	FOIA
B101100281	B101100161	80/12/12	FOIA
B101100287	B101100279	80/12/22	50-438 Q
B101100288	B101100161	80/12/12	FOIA
B101100296	B101100161	80/12/12	70-2179
B101100301	B101100294	80/12/27	50-456 Q
B101100306	B101100161	80/12/12	FOIA
B101100307	B101100302	80/11/28	CONTRACT
B101100310	B101100161	80/12/12	FOIA
B101100314	B101100161	80/12/12	FOIA
B101100316	B101100311	80/12/18	CONTRACT
B101100319	B101100300	80/12/22	50-348 Q
B101100322	B101100161	80/12/12	FOIA
B101100325	B101100325	80/12/15	CONTRACT
B101100327	B101100161	80/12/12	FOIA
B101100331	B101100308	80/12/22	50-348 Q
B101100335	B101100161	80/12/12	FOIA
B101100337	B101100309	80/12/22	50-348 Q
B101100343	B101100308	80/12/22	50-348 Q
B101100345	B101100161	80/12/12	FOIA
B101100355	B101100348	80/10/09	50-263 Q
B101100354	B101100161	80/12/12	70-2479
B101100356	B101100351	80/11/28	50-327 Q
B101100361	B101100348	80/10/09	50-263 Q
B101100362	B101100161	80/12/12	FOIA
B101100364	B101100351	80/11/28	50-327 Q
B101100368	B101100161	80/12/12	FOIA
B101100375	B101100161	80/12/12	FOIA
B101100378	B101100369	80/11/26	50-546 Q
B101100381	B101100370	80/12/24	50-553 Q
B101100385	B101100161	80/12/12	FOIA
B101100393	B101100161	80/12/12	70-1739
B101100394	B101100370	80/12/24	50-553 Q
B101100399	B101100372	80/12/15	CONTRACT
B101100400	B101100370	80/12/24	50-553 Q
B101100401	B101100161	80/12/12	50-244 P
B101100410	B101100370	80/12/24	50-553 Q
B101100415	B101100161	80/12/12	FOIA
B101100428	B101100419	80/12/19	50-220 Q
B101100448	B101100440	80/12/24	50-269 P
B101100449	B101100441	80/12/24	50-312 Q
B101100462	B101100440	80/12/24	50-269 P
B101100471	B101100440	80/12/24	50-269 P
B101100479	B101100440	80/12/24	50-269 P
B101100503	B101100493	80/12/03	50-271 Q
B101100528	B101100477	80/12/24	50-287 P
B101100519	B101100504	80/09/19	50-250 P
B101100524	B101100512	80/11/25	50-278 Q
B101100527	B101100518	80/12/17	50-265 P
B101100534	B101100518	80/12/17	50-266 P
B101100542	B101100531	80/11/23	50-322 Q
B101100543	B101100510	80/12/17	50-266 P
B101100549	B101100532	80/09/19	50-315 P
B101100557	B101100551	80/12/09	50-272 P
B101100567	B101100551	80/12/09	50-272 P
B101100572	B101100551	80/12/09	50-272 P
B101100574	B101100563	80/09/19	50-283 P
B101100595	B101100587	80/09/19	50-348 P
B101100614	B101100606	80/12/22	50-327 P
B101100620	B101100606	80/12/22	50-327 P
B101100622	B101100617	80/09/19	50-334 P
B101100626	B101100606	80/12/22	50-327 P
B101100636	B101100629	80/09/19	50-247 P
B101100643	B101100646	80/09/19	50-261 P
B101100656	B101100660	80/09/19	50-206 P
B101100672	B101100664	80/11/26	50-518 Q
B101100690	B101100674	80/09/19	50-293 P
B101100699	B101100682	80/11/23	50-321 Q
B101100703	B101100690	80/09/19	50-272 P
B101100702	B101100693	80/12/24	50-333 Q
B101100706	B101100700	80/09/19	50-305 P
B101100707	B101100693	80/12/24	50-333 Q
B101100709	B101100704	80/12/22	70-364
B101100711	B101100695	80/12/24	50-335 Q
B101100717	B101100712	80/12/18	50-271 P
B101100726	B101100716	80/12/22	50-445 Q
B101100727	B101100712	80/12/18	50-271 P

ACCESSION NUMBER					ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
B101100731	B101100712	80/12/18	50-271	P	B101120348	B101120300	80/12/19	50-289	
B101100738	B101100732	80/12/23	50-445	Q	B101120349	B101120346	80/12/31	50-299	
B101100752	B101100748	80/12/23	50-382	Q	B101120353	B101120323	80/12/12	50-244	
B101100766	B101100759	80/11/24	50-492	Q	B101120354	B101120302	81/01/09	50-333	
B101100763	B101100777	80/12/68	50-6	Q	B101120355	B101120351	80/12/31	50-336	
B101100811	B101100777	80/12/08	50-6	Q	B101120358	B101120307	81/01/06	50-321	
B101100820	B101100818	80/11/26	50-261	Q	B101120364	B101120312	81/01/06	50-366	
B101100826	B101100823	80/11/28	50-261	Q	B101120367	B101120333	80/12/23	50-266	
B101100834	B101100829	80/11/28	50-250	Q	B101120369	B101120335	80/12/30	50-220	
B101100846	B101100842	80/12/23	50-302	Q	B101120376	B101120337	81/01/08	50-272	
B101100848	B101100842	80/12/23	50-302	Q	B101120379	B101120337	81/01/06	50-155	
B101100853	B101100842	80/12/23	50-302	Q	B101120385	B101120341	81/01/07	50-358	
B101120004	B101120033	80/12/16	50-3	P	B101120389	B101120344	81/01/07	50-368	
B101120016	B101120013	80/12/03	50-155	Q	B101120391	B101120388	80/12/23	50-498	
B101120018	B101120013	80/12/03	50-155	Q	B101120393	B101120388	80/12/23	50-498	
B101120024	B101120024	80/12/11	50-272	P	B101120413	B101120405	80/11/19	50-245	
B101120026	B101120022	80/12/11	50-272	P	B101120415	B101120405	80/11/19	50-245	
B101120028	B101120019	80/11/24	50-315	Q	B101120427	B101120425	80/12/31	50-267	
B101120039	B101120022	80/12/11	50-272	P	B101120479	B101120460	80/12/02	50-250	
B101120034	B101120019	80/11/24	50-315	Q	B101120483	B101120468	80/12/02	50-250	
B101120056	B101120051	80/12/17	50-282	P	B101120490	B101120489	80/12/02	50-338	
B101120057	B101120054	80/12/03	71-398		B101120495	B101120489	80/12/02	50-338	
B101120059	B101120051	80/12/17	50-282	P	B101120511	B101120506	81/01/06	50-289	
B101120061	B101120060	80/12/03	71-102		B101120528	B101120524	81/01/06	50-409	
B101120262	B101120031	80/12/17	50-282	P	B101120542	B101120535	80/11/24	50-295	
B101120070	B101120066	80/11/13	50-358	Q	B101130017	B101130006	80/12/31	FOIA	
B101120077	B101120074	80/12/24	50-416	Q	B101130019	B101130008	80/12/19	50-454	
B101120081	B101120074	80/12/24	50-416	Q	B101130026	B101130021	80/12/29	50-483	
B101120084	B101120074	80/12/24	50-416	Q	B101130039	B101130033	80/12/22	COMMIS	
B101120086	B101120074	80/12/24	50-416	Q	B101130046	B101130042	81/01/06	50-289	
B101120089	B101120031	80/12/09	XPOR	TLIC	B101130056	B101130053	81/01/05	50-289	
B101120090	B101120074	80/12/24	50-416	Q	B101130107	B101130102	81/01/06	50-395	
B101120096	B101120093	80/11/24	50-382	Q	B101130112	B101130102	81/01/06	50-395	
B101120104	B101120101	80/12/19	50-289	Q	B101130119	B101130115	80/11/19	XPOR	TLIC
B101120111	B101120106	80/12/24	50-364	P	B101130122	B101130115	80/11/19	XPOR	TLIC
B101120114	B101120106	80/12/24	50-364	P	B101130135	B101130130	81/01/06	50-29	
B101120116	B101120106	80/12/24	50-364	P	B101130154	B101130148	81/01/06	50-155	
B101120133	B101120133	80/12/12	50-142	P	B101130158	B101130148	81/01/06	50-155	
B101120137	B101120133	80/12/12	50-142	P	B101130206	B101130198	80/12/24	50-254	
B101120149	B101120142	80/12/15	50-206	P	B101130233	B101130229	81/01/06	50-155	
B101120154	B101120151	80/12/15	40-1162		B101130241	B101130237	81/01/09	50-261	
B101120156	B101120153	80/12/30	50-254	R	B101130249	B101130243	80/12/23	50-235	
B101120164	B101120159	80/12/12	COMMIS	SION	B101130260	B101130213	80/12/23	70-261	
B101120167	B101120162	81/01/06	50-298	P	B101130265	B101130253	81/01/09	TDPREP	
B101120173	B101120159	80/12/12	50-320	P	B101130274	B101130263	80/12/31	PR	
B101120181	B101120178	80/12/24	50-111	P	B101130296	B101130293	81/01/09	50-395	
B101120185	B101120178	80/12/24	50-111	P	B101130325	B101130325	80/12/15	50-250	
B101120194	B101120189	81/01/09	50-387	K	B101130339	B101130333	81/01/06	50-335	
B101120196	B101120191	80/12/16	50-275	H	B101130365	B101130341	80/12/15	50-335	
B101120205	B101120200	81/01/06	50-333	P	B101130372	B101130345	80/12/19	50-335	
B101120209	B101120200	81/01/06	50-333	P	B101130374	B101130369	80/12/31	50-267	
B101120220	B101120215	81/01/06	50-333	P	B101130377	B101130348	80/12/23	50-250	
B101120226	B101120215	81/01/06	50-333	P	B101130382	B101130353	80/12/23	50-250	
B101120227	B101120224	81/01/09	50-155	P	B101130387	B101130358	80/12/22	50-285	
B101120232	B101120228	80/12/10	50-348	P	B101130394	B101130393	81/01/02	50-267	
B101120233	B101120229	81/01/08	50-309	V	B101130396	B101130393	81/01/02	50-267	
B101120235	B101120228	80/12/10	50-348	P	B101130398	B101130393	81/01/02	50-267	
B101120238	B101120228	80/12/10	50-348	P	B101130400	B101130393	81/01/02	50-267	
B101120239	B101120234	80/12/16	50-313	P	B101130412	B101130409	81/01/09	50-259	
B101120245	B101120241	81/01/06	50-220	P	B101130417	B101130415	81/01/06	50-346	
B101120250	B101120243	80/12/19	50-329	A	B101130425	B101130421	81/01/05	50-334	
B101120276	B101120273	80/12/02	50-237	F	B101130428	B101130421	81/01/05	50-334	
B101120279	B101120278	80/12/12	50-220	P	B101130432	B101130421	81/01/05	50-334	
B101120281	B101120278	80/12/12	50-220	P	B101130436	B101130429	81/01/06	50-260	
B101120283	B101120278	80/12/12	50-220	P	B101130438	B101130421	81/01/05	50-334	
B101120288	B101120285	80/12/19	50-3	T	B101130440	B101130435	81/01/09	50-305	
B101120296	B101120293	81/01/06	50-29	P	B101130443	B101130421	81/01/05	50-334	
B101120297	B101120294	81/01/09	50-282	R	B101130445	B101130442	81/01/06	50-255	
B101120303	B101120298	81/01/06	50-321	S	B101130450	B101130442	81/01/06	50-255	
B101120304	B101120299	81/01/09	50-277	P	B101130452	B101130439	81/01/09	50-368	
B101120308	B101120299	81/01/09	50-277	P	B101130463	B101130457	81/01/06	50-327	
B101120309	B101120299	81/01/09	50-277	P	B101130480	B101130468	81/01/06	50-339	
B101120310	B101120306	81/01/09	50-333	S	B101130484	B101130474	81/01/07	50-368	
B101120317	B101120314	81/01/09	50-244	S	B101130488	B101130475	81/01/06	50-339	
B101120324	B101120320	81/01/06	50-272	S	B101130505	B101130469	81/01/06	50-296	
B101120329	B101120326	81/01/06	50-331	S	B101130515	B101130508	81/01/05	50-234	
B101120332	B101120323	80/12/12	50-244	P	B101130516	B101130461	81/01/06	50-295	
B101120335	B101120334	81/01/06	50-331	S	B101130517	B101130492	81/01/05	50-312	
B101120342	B101120323	80/12/12	50-244	P	B101130525	B101130518	81/01/07	50-155	
B101120343	B101120338	80/12/31	50-295	S	B101130526	B101130521	81/01/08	50-346	

EXCLUSION	DATE	ISSUED	CATEGORY
8101130528	8101130493	81/01/04	50-339 S
8101130536	8101130458	81/01/14	50-295 S
8101130539	8101130534	81/01/06	50-339 S
8101130540	8101130535	81/01/09	50-324 S
8101130542	8101130494	81/01/06	50-339 S
8101130546	8101130543	81/01/10	50-311 S
8101130551	8101130541	81/01/07	50-295 S
8101130554	8101130548	81/01/07	50-324 S
8101130559	8101130547	80/12/31	CONTRACT
8101130568	8101130552	81/01/07	50-333 R
8101130559	8101130550	81/01/07	50-304 S
8101130560	8101130561	81/01/07	50-324 S
8101130571	8101130562	81/01/08	50-304 S
8101130572	8101130564	81/01/02	50-244 R
8101130581	8101130575	81/01/09	50-263 R
8101130583	8101130574	80/11/12	50-373 Q
8101130585	8101130578	81/01/07	50-133 R
8101130588	8101130582	81/01/09	50-299 R
8101130591	8101130584	81/01/09	50-305 R
8101130592	8101130574	80/11/12	50-373 Q
8101130593	8101130587	81/01/09	50-298 R
8101130601	8101130593	81/01/09	50-299 R
8101130605	8101130598	80/12/29	50-263 S
8101130607	8101130597	81/01/07	50-317 S
8101130608	8101130602	81/01/06	50-348 S
8101130612	8101130600	81/01/05	50-327 S
8101130613	8101130606	81/01/03	50-367 U
8101130619	8101130610	81/01/05	50-318 S
8101130622	8101130620	80/12/31	COMMISSION
8101130623	8101130617	81/01/09	50-317 S
8101130632	8101130620	80/12/31	COMMISSION
8101130634	8101130620	80/12/31	COMMISSION
8101130637	8101130620	80/12/31	COMMISSION
8101130640	8101130620	80/12/31	COMMISSION
8101130643	8101130620	80/12/31	COMMISSION
8101130646	8101130620	80/12/31	COMMISSION
8101130689	8101130685	79/09/19	NUREG
8101130727	8101130725	80/12/04	COMMISSION
8101140017	8101140011	81/01/09	50-387 O
8101140028	8101140011	81/01/09	50-387 O
8101140037	8101140031	80/12/29	50-483 H
8101140046	8101140038	80/12/29	50-361 Q
8101140053	8101140038	80/12/29	50-361 Q
8101140097	8101140091	80/11/28	50-295 Q
8101140113	8101140108	80/12/02	50-250 Q
8101140120	8101140111	80/12/15	10CFR
8101140128	8101140118	80/11/20	50-272 Q
8101140129	8101140111	80/12/15	10CFR
8101140151	8101140135	80/12/02	50-461 Q
8101140163	8101140154	80/12/09	71-398
8101140173	8101140166	80/12/17	50-220 P
8101140214	8101140208	80/12/24	50-443 H
8101140237	8101140230	81/01/12	50-367 Q
8101140246	8101140239	80/12/22	50-320 H
8101140249	8101140245	81/01/12	50-289 Q
8101140252	8101140245	81/01/12	50-289 F
8101140275	8101140271	80/12/16	XPORTLIC
8101140276	8101140272	81/01/07	50-398 A
8101140326	8101140316	80/12/19	50-247 R
8101140327	8101140162	80/12/23	50-220 P
8101140344	8101140336	81/01/09	50-255 P
8101140360	8101140350	80/12/19	XPORTLIC
8101140375	8101140367	80/12/31	CONTRACT
8101140409	8101140396	80/12/16	REGOQ
8101140484	8101140479	80/12/23	50-498 Q
8101140489	8101140486	81/01/09	50-267 R
8101140494	8101140491	81/01/09	50-407 R
8101140500	8101140495	80/12/05	50-382 Q
8101140510	8101140504	80/12/05	50-263 Q
8101140514	8101140508	81/01/08	50-324 S
8101140531	8101140524	80/11/25	50-305 Q
8101140556	8101140548	80/12/03	50-498 Q
8101140559	8101140554	81/01/12	50-348 Q
8101140577	8101140574	81/01/13	50-320 R
8101140623	8101140620	81/01/02	50-249 S
8101140630	8101140625	81/01/09	50-267 S
8101140646	8101140639	81/01/09	50-267 S
8101140677	8101140666	80/12/12	COMMISSION
8101140678	8101140664	81/01/06	50-27 P
8101140682	8101140664	81/01/06	50-27 P
8101140652	8101140652	81/01/06	50-297 P
8101140725	8101140715	80/12/05	COMMISSION
8101140735	8101140715	80/12/05	COMMISSION
8101140772	8101140765	80/12/09	50-461 Q
8101140779	8101140774	80/12/22	COMMISSION
8101140786	8101140774	80/12/22	COMMISSION
8101140750	8101140774	80/12/22	COMMISSION
8101140796	8101140792	80/12/29	CONTRACT
8101140797	8101140774	80/12/22	COMMISSION
8101140802	8101140774	80/12/22	COMMISSION
8101140911	8101140774	80/12/22	COMMISSION
8101140813	8101140805	80/12/18	CONTRACT
8101140852	8101140818	80/12/18	70-143
8101140843	8101140835	80/12/12	CONTRACT
8101140846	8101140818	80/12/18	70-143
8101140855	8101140852	80/12/09	COMMISSION
8101140859	8101140847	80/12/04	50-373 Q
8101140857	8101140852	80/12/07	COMMISSION
8101140862	8101140852	80/12/07	COMMISSION
8101140865	8101140854	80/12/12	50-250 P
8101140871	8101140852	80/12/09	COMMISSION
8101140881	8101140876	80/12/15	COMMISSION
8101140874	8101140876	80/12/15	COMMISSION
8101140897	8101140876	80/12/15	COMMISSION
8101140899	8101140876	80/12/15	COMMISSION
8101140924	8101140876	80/12/15	COMMISSION
8101140905	8101140876	80/12/19	XPORTLIC
8101140959	8101140934	80/12/19	XPORTLIC
8101140978	8101140936	81/01/13	50-295 Q
8101150017	8101150015	80/12/03	50-369 Q
8101150026	8101150020	80/12/30	XPORTLIC
8101150034	8101150031	80/12/23	XPORTLIC
8101150045	8101150037	80/12/24	CONTRACT
8101150070	8101150065	80/12/18	50-247 P
8101150079	8101150076	80/12/31	50-255 Q
8101150094	8101150084	80/12/05	50-267 Q
8101150103	8101150084	80/12/05	50-289 Q
8101150116	8101150084	80/12/05	50-289 Q
8101150127	8101150107	80/12/30	FOIA
8101150129	8101150120	80/12/22	CONTRACT
8101150131	8101150107	80/12/30	FOIA
8101150142	8101150107	80/12/30	FOIA
8101150149	8101150107	80/12/30	FOIA
8101150155	8101150140	80/12/02	50-219 Q
8101150169	8101150140	80/12/02	50-219 Q
8101150171	8101150163	80/12/23	50-413 A
8101150176	8101150163	80/12/23	50-413 A
8101150180	8101150163	80/12/23	50-413 A
8101150186	8101150163	80/12/23	50-413 A
8101150189	8101150163	80/12/23	50-413 A
8101150195	8101150140	80/12/02	50-219 Q
8101150210	8101150205	80/12/31	CONTRACT
8101150223	8101150217	80/12/24	CONTRACT
8101150237	8101150229	80/12/24	CONTRACT
8101150249	8101150242	80/11/25	50-213 Q
8101150328	8101150286	80/12/29	CONTRACT
8101150366	8101150337	80/12/23	COMMISSION
8101150381	8101150374	80/11/17	0A999
8101150390	8101150379	80/12/18	50-155 Q
8101150394	8101150384	80/12/18	50-250 P
8101150395	8101150359	80/11/26	0A999
8101150397	8101150379	80/12/18	50-155 Q
8101150403	8101150384	80/12/18	50-200 P
8101150410	8101150405	81/01/08	0A999
8101150418	8101150405	81/01/08	0A999
8101150422	8101150405	81/01/08	0A999
8101150425	8101150405	81/01/08	0A999
8101150446	8101150441	80/12/16	0A999
8101150450	8101150441	80/12/16	0A999
8101150454	8101150441	80/12/16	0A999
8101150460	8101150441	80/12/16	0A999
8101150465	8101150457	80/12/17	CRB
8101150472	8101150467	80/12/19	XPORTLIC
8101150481	8101150477	80/12/08	XPORTLIC
8101150496	8101150465	80/12/18	50-247 P
8101150497	8101150492	81/01/09	50-219 S
8101150502	8101150501	81/01/08	50-220 R
8101150514	8101150512	81/01/12	50-29 R
8101150519	8101150517	81/01/12	50-266 R
8101150531	8101150526	81/01/07	50-312 R

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
B101150328	B101150522	81/01/09	50-324 S	B101160259	B101160255	80/12/30	50-329 Q
B101150540	B101150536	80/12/16	50-245 Q	B101160268	B101160264	80/12/05	50-324 Q
B101150542	B101150535	80/12/16	50-245 Q	B101160337	B101160331	80/12/01	50-320 F
B101150543	B101150534	81/01/13	50-318 S	B101160361	B101160342	81/01/12	TOPREF
B101150544	B101150534	80/12/16	50-245 Q	B101160374	B101160368	80/12/10	50-151 Q
B101150546	B101150556	80/12/16	50-245 Q	B101160382	B101160368	80/12/10	50-151 Q
B101150551	B101150549	80/12/10	50-317 Q	B101160391	B101160378	80/12/02	50-148 P
B101150553	B101150549	80/12/10	50-317 Q	B101160392	B101160386	80/12/22	50-282 Q
B101150555	B101150549	80/12/10	50-317 Q	B101160398	B101160370	80/12/02	50-148 P
B101150558	B101150549	80/12/10	50-317 Q	B101160404	B101160378	80/12/02	50-148 P
B101150555	B101150562	80/12/15	50-317 Q	B101160408	B101160378	80/12/02	50-148 P
B101150568	B101150562	80/12/15	50-317 Q	B101160411	B101160378	80/12/02	50-148 P
B101150570	B101150562	80/12/15	50-317 Q	B101160412	B101160410	80/12/15	70-820
B101150572	B101150562	80/12/15	50-317 Q	B101160413	B101160410	80/12/15	70-820
B101150578	B101150575	80/12/17	50-247 Q	B101160414	B101160410	80/12/15	70-820
B101150580	B101150575	80/12/17	50-247 Q	B101160416	B101160415	80/11/28	50-206 P
B101150591	B101150575	80/12/17	50-247 Q	B101160421	B101160417	80/12/29	50-339 P
B101150593	B101150579	80/12/23	MISC	B101160423	B101160417	80/12/29	50-339 P
B101150595	B101150575	80/12/17	50-247 Q	B101160424	B101160417	80/12/29	50-339 P
B101150595	B101150570	81/01/06	50-389 Q	B101160467	B101160464	81/01/06	50-334 R
B101150597	B101150577	80/11/25	50-155 Q	B101160468	B101160464	81/01/06	50-334 R
B101150605	B101150602	81/01/07	50-461 Q	B101160469	B101160466	81/01/06	50-219 P
B101150634	B101150628	80/12/07	50-295 Q	B101160470	B101160464	81/01/06	50-334 R
B101150635	B101150631	81/01/14	50-285 P	B101160471	B101160466	81/01/08	50-219 P
B101150638	B101150631	81/01/14	50-285 P	B101160473	B101160465	81/01/14	50-206 P
B101150640	B101150628	80/12/07	50-295 Q	B101160474	B101160472	81/01/09	50-327 R
B101150651	B101150646	80/12/07	50-266 Q	B101160476	B101160465	81/01/14	50-206 P
B101150658	B101150654	80/12/12	50-373 Q	B101160483	B101160477	81/01/07	50-327 S
B101150663	B101150654	80/12/12	50-373 Q	B101160484	B101160479	81/01/13	50-219 F
B101150684	B101150679	81/01/05	50-220 S	B101160488	B101160485	81/01/08	50-285 R
B101150685	B101150681	81/01/12	50-271 S	B101160489	B101160479	81/01/13	50-219 F
B101150695	B101150690	81/01/09	50-219 S	B101160498	B101160490	81/01/06	50-260 S
B101150769	B101150765	80/12/23	50-369 Q	B101160503	B101160493	81/01/08	50-280 F
B101150773	B101150765	80/12/23	50-369 Q	B101160507	B101160500	81/01/08	50-445 C
B101150787	B101150779	80/12/09	50-373 Q	B101160511	B101160493	81/01/08	50-280 F
B101150819	B101150810	80/12/11	50-341 Q	B101160513	B101160504	80/12/23	50-206 S
B101150840	B101150826	81/01/08	0A999	B101160525	B101160520	81/01/15	50-239 S
B101150845	B101150826	81/01/08	0A999	B101160544	B101160508	81/01/12	50-333 S
B101150846	B101150841	80/12/10	50-387 Q	B101160567	B101160562	80/12/18	50-280 P
B101150850	B101150841	80/12/10	50-387 Q	B101160573	B101160516	81/01/14	50-293 S
B101150851	B101150826	81/01/08	0A999	B101160580	B101160575	80/12/12	50-213 Q
B101150854	B101150841	80/12/10	50-387 Q	B101160581	B101160586	81/01/09	50-324 S
B101150851	B101150841	80/12/10	50-387 Q	B101160587	B101160575	80/12/12	50-213 Q
B101150873	B101150867	80/12/23	50-277 Q	B101160591	B101160575	80/12/12	50-213 Q
B101150875	B101150893	80/12/18	50-317 P	B101160595	B101160575	80/12/12	50-213 Q
B101150890	B101150867	80/12/23	50-277 Q	B101160612	B101160575	80/12/12	50-213 Q
B101150891	B101150867	80/12/23	50-277 Q	B101160613	B101160541	81/01/09	50-245 S
B101150893	B101150892	80/12/24	0A999	B101160624	B101160549	81/01/08	50-336 S
B101150898	B101150892	80/12/24	0A999	B101160627	B101160621	80/12/16	50-271 Q
B101150905	B101150882	80/12/24	0A999	B101160633	B101160621	80/12/16	50-271 Q
B101150910	B101150882	80/12/24	0A999	B101160634	B101160636	81/01/12	50-302 S
B101150935	B101150931	81/01/13	40-B084	B101160640	B101160621	80/12/16	50-271 Q
B101160039	B101160024	80/12/31	50-361 A	B101160646	B101160621	80/12/16	50-271 Q
B101160034	B101160028	81/01/08	50-263 F	B101160653	B101160621	80/12/16	50-271 Q
B101160057	B101160050	81/01/05	50-346 P	B101160668	B101160662	81/01/02	50-413 Q
B101160061	B101160050	81/01/05	50-346 P	B101160671	B101160662	81/01/02	50-413 Q
B101160064	B101160050	81/01/05	50-346 P	B101160679	B101160662	81/01/02	50-413 Q
B101160065	B101160054	80/12/19	50-271 Q	B101160684	B101160662	81/01/02	50-413 Q
B101160072	B101160054	80/12/19	50-271 Q	B101160690	B101160662	80/12/18	50-280 P
B101160077	B101160054	80/12/19	50-271 Q	B101160696	B101160694	81/01/05	50-280 Q
B101160087	B101160054	80/12/19	50-271 Q	B101160697	B101160695	80/12/31	PR
B101160111	B101160105	81/01/08	CONTRACT	B101160699	B101160694	81/01/05	50-280 Q
B101160114	B101160101	80/12/17	50-309 Q	B101160700	B101160694	81/01/05	50-280 Q
B101160123	B101160101	80/12/17	50-309 Q	B101160706	B101160694	81/01/05	50-280 Q
B101160125	B101160116	80/11/26	70-33	B101160728	B101160724	80/12/31	50-369 Q
B101160132	B101160101	80/12/17	50-309 Q	B101160734	B101160724	80/12/31	50-369 Q
B101160135	B101160124	80/12/30	COMMISSION	B101160759	B101160754	80/12/31	50-260 Q
B101160138	B101160131	80/12/30	70-143	B101190103	B101190100	80/12/29	70-124
B101160142	B101160124	80/12/30	COMMISSION	B101190141	B101190113	80/12/09	50-10 P
B101160145	B101160101	80/12/17	50-309 Q	B101190161	B101190128	81/01/02	50-275 H
B101160147	B101160124	80/12/30	COMMISSION	B101190167	B101190154	81/01/09	FOIA
B101160148	B101160131	80/12/30	70-143	B101190176	B101190154	81/01/09	FOIA
B101160153	B101160124	80/12/30	COMMISSION	B101190182	B101190175	81/01/06	COMMISSION
B101160156	B101160152	80/11/13	50-304 Q	B101190197	B101190190	80/12/30	50-247 H
B101160159	B101160124	80/12/30	COMMISSION	B101190202	B101190190	80/12/30	50-247 H
B101160164	B101160124	80/12/30	COMMISSION	B101190207	B101190190	80/12/30	50-247 H
B101160172	B101160124	80/12/30	COMMISSION	B101190214	B101190190	80/12/30	50-247 H
B101160175	B101160167	81/01/14	50-289 Q	B101190277	B101190272	80/12/18	50-412 S
B101160240	B101160231	80/12/08	50-483 Q	B101190325	B101190320	81/01/08	50-317 P

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
B101190329	B101190319	80/12/30	50-322	B101200473	B101200465	80/12/02	CONTRACT
B101190372	B01220437	80/11/28	50-10	B101200475	B101200499	81/01/14	50-331 F
B101190390	B101190387	81/01/09	90-387	B101200480	B101200471	81/01/02	CONTRACT
B101190397	B101140679	80/12/18	90-290	B101200498	B101200487	80/12/22	CONTRACT
B101190408	B101140679	80/12/18	50-250	B101200508	B101200502	80/12/09	50-382 Q
B101190419	B101190414	81/01/13	50-324	B101200508	B101200502	80/12/09	50-382 Q
B101190429	B101190426	80/12/02	50-261	B101200563	B101200557	80/12/29	50-516 A
B101190445	B101190443	81/01/09	90-344	B101200567	B101200557	80/12/29	50-516 A
B101190451	B101190448	81/01/13	50-368	B101200570	B101200566	81/01/07	50-327 J
B101190456	B101190454	81/01/12	90-302	B101200595	B101200586	81/01/07	50-329 O
B101190465	B101190462	81/01/12	50-293	B101200628	B101200624	81/01/08	50-324 S
B101190470	B101190467	81/01/09	50-334	B101200629	B101200626	81/01/08	50-325 S
B101190477	B101190474	81/01/12	90-334	B101200636	B101200634	80/12/22	50-292 P
B101190486	B101190482	81/01/13	50-320	B101200640	B101200639	80/12/16	0A999
B101190488	B101190483	81/01/07	50-280	B101200642	B101200642	81/01/03	50-272 F
B101190495	B101190490	81/01/13	50-260	B101200645	B101200642	81/01/04	50-272 F
B101190500	B101190496	81/01/12	50-296	B101210027	B101210022	81/01/12	CONTRACT
B101190507	B101190502	81/01/14	50-317	B101210058	B101210045	80/12/08	50-458 Q
B101190509	B101190503	81/01/15	50-346	B101210075	B101210045	80/12/08	50-458 Q
B101190514	B101190505	80/12/22	50-322	B101210077	B101210072	80/12/23	50-445 Q
B101190515	B101190512	81/01/12	50-315	B101210089	B101210082	80/12/12	50-461 Q
B101190518	B101190512	81/01/12	50-315	B101210092	B101210085	81/01/08	50-335 F
B101190584	B101190579	81/01/06	50-328	B101210098	B101210085	81/01/08	50-335 F
B101190603	B101190593	81/01/08	50-259	B101210104	B101210097	80/12/15	50-546 Q
B101190612	B101190506	81/01/08	50-296	B101210119	B101210110	80/12/24	50-397 Q
B101190617	B101190608	80/12/30	50-338	B101210137	B101210131	81/01/13	50-261 F
B101190621	B101190608	80/12/30	50-338	B101210138	B101210133	80/12/23	50-69 Q
B101190626	B101190623	80/12/30	50-335	B101210144	B101210131	81/01/13	50-261 F
B101190652	B101190649	80/10/22	71-6273	B101210153	B101210145	80/12/24	50-275 Q
B101190657	B101190649	80/10/22	71-6273	B101210181	B101210173	80/12/15	50-245 P
B101190741	B101190738	81/01/09	50-582	B101210223	B101210216	80/12/17	50-219 F
B101190782	B101190780	80/11/06	0A999	B101210225	B101210221	81/01/16	50-269 T
B101190783	B101190779	80/12/24	50-367	B101210233	B101210229	80/12/17	50-135 P
B101190788	B101190786	80/12/10	50-289	B101210262	B101210255	80/11/03	0A999
B101190791	B101190786	80/12/10	50-289	B101210358	B101210354	81/01/19	50-395 K
B101190797	B101190886	81/01/02	50-275	B101210357	B101210364	81/01/14	50-271 P
B101200062	B101200059	81/01/14	50-322	B101210370	B101210369	81/01/09	40-878 B
B101200112	B101200106	80/11/14	0A999	B101210373	B101210371	81/01/09	TOPREP
B101200117	B101200106	80/11/14	0A999	B101210375	B101210372	81/01/16	TOPREP
B101200118	B101200106	80/11/14	0A999	B101210377	B101210372	81/01/16	TOPREP
B101200121	B101200105	80/11/14	0A999	B101210376	B101210374	80/12/30	CONTRACT
B101200122	B101200104	81/01/06	40-8724	B101210391	B101210381	80/12/31	CONTRACT
B101200126	B101200209	81/01/02	50-275	B101210401	B101210372	81/01/16	TOPREP
B101200131	B101200129	80/11/26	0A999	B101210405	B101210405	81/01/09	50-324 R
B101200137	B101200134	80/12/04	70-1151	B101210406	B101210406	81/01/14	50-267 S
B101200144	B101200134	80/12/04	70-1151	B101210416	B101210414	81/01/10	50-250 R
B101200191	B101200187	80/12/22	50-454	B101210422	B101210415	81/01/14	50-155 R
B101200195	B101200187	80/12/22	50-454	B101210427	B101210425	81/01/10	50-250 R
B101200206	B101200200	80/12/17	50-29	B101210430	B101210426	81/01/15	50-348 S
B101200233	B101200227	81/01/13	50-327	B101210440	B101210434	81/01/15	50-247 S
B101200235	B101200229	81/01/16	50-280	B101210446	B101210439	81/01/15	50-338 S
B101200237	B101200227	81/01/13	50-327	B101210451	B101210443	81/01/13	50-316 S
B101200277	B101200274	81/01/13	50-245	B101210454	B101210449	81/01/14	50-327 S
B101200284	B101200280	81/01/14	50-331	B101210458	B101210455	81/01/12	50-311 R
B101200285	B101200278	81/01/15	50-338	B101210461	B101210462	81/01/15	50-269 R
B101200288	B101200281	81/01/13	50-312	B101210465	B101210463	81/01/02	50-294 R
B101200289	B101200270	81/01/15	50-338	B101210471	B101210469	81/01/15	50-289 R
B101200290	B101200287	81/01/12	50-286	B101210473	B101210470	81/01/06	50-293 R
B101200291	B101200286	80/09/19	50-204	B101210476	B101210474	81/01/14	50-244 R
B101200294	B101200292	81/01/15	50-302	B101210482	B101210475	81/01/12	50-272 R
B101200297	B101200295	81/01/14	50-282	B101210485	B101210481	81/01/14	50-354 R
B101200303	B101200301	81/01/08	50-289	B101210488	B101210480	81/01/14	50-267 S
B101200335	B101200333	81/01/15	50-281	B101210489	B101210484	81/01/07	50-256 R
B101200337	B101200333	81/01/15	50-281	B101210494	B101210490	81/01/15	50-313 R
B101200343	B101200339	81/01/15	50-280	B101210496	B101210492	81/01/15	50-333 R
B101200348	B101200339	81/01/15	50-280	B101210505	B101210500	81/01/14	50-271 R
B101200355	B101200351	81/01/14	50-339	B101210505	B101210499	81/01/15	50-333 S
B101200359	B101200357	81/01/14	50-272	B101210507	B101210502	81/01/15	50-269 S
B101200364	B101200362	81/01/14	50-338	B101210514	B101210509	81/01/15	50-368 R
B101200371	B101200367	81/01/15	50-315	B101210516	B101210511	81/01/14	50-287 S
B101200383	B101200375	81/01/14	50-339	B101210521	B101210518	81/01/13	50-348 R
B101200371	B101200386	81/01/14	50-272	B101210528	B101210522	81/01/09	50-277 R
B101200406	B101200399	81/01/15	50-368	B101210529	B101210523	81/01/12	TOPREP
B101200416	B101200411	81/01/14	50-368	B101210531	B101210523	81/01/12	TOPREP
B101200423	B101200420	80/12/10	TOPREP	B101210533	B101210526	80/12/12	50-329 Q
B101200432	B101200426	81/01/08	CONTRACT	B101210539	B101210532	80/12/23	50-324 P
B101200435	B101200396	81/01/02	EXPORT LIC	B101210545	B101210532	80/12/23	50-324 P
B101200437	B101200431	81/01/14	50-330	B101210550	B101210532	80/12/23	50-324 P
B101200452	B101200444	81/01/14	50-339	B101210557	B101210543	80/12/29	50-324 P
B101200466	B101200458	81/01/14	50-331	B101210563	B101210554	81/01/15	FOIA

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
0101210565	0101210543	01/01/29	50-324 P	0101220396	0101220393	01/01/15	50-325 B
0101210569	0101210554	01/01/15	FOIA	0101220401	0101220397	01/01/14	50-331 B
0101210571	0101210543	01/01/29	50-324 P	0101220402	0101220399	01/01/14	50-325 B
0101210574	0101210554	01/01/15	FOIA	0101220409	0101220405	01/01/15	50-324 B
0101210578	0101210572	01/01/24	CELEBRAT	0101220410	0101220408	01/01/12	50-213 R
0101210601	0101210596	01/01/17	50-312 Q	0101220415	0101220403	01/01/16	50-266 Q
0101210608	0101210604	01/01/28	50-206 Q	0101220417	0101220414	01/01/09	50-368 P
0101210617	0101210612	01/01/07	50-275 Q	0101220421	0101220413	01/01/16	50-267 B
0101210624	0101210620	01/01/28	50-344 Q	0101220427	0101220419	01/01/16	50-340 Q
0101210629	0101210626	01/01/12	50-261 Q	0101220429	0101220424	01/01/16	50-346 B
0101210630	0101210621	01/01/14	50-361 A	0101220430	0101220433	01/01/11	50-220 Q
0101210637	0101210634	01/01/07	CHO	0101220440	0101220435	01/01/16	50-346 B
0101210638	0101210635	01/01/07	50-358 Q	0101220442	0101220433	01/01/11	50-220 Q
0101210641	0101210640	01/01/16	50-409 Q	0101220445	0101220433	01/01/11	50-220 Q
0101210643	0101210640	01/01/16	50-409 Q	0101220449	0101220444	01/01/15	50-260 B
0101210646	0101210645	01/01/23	50-346 Q	0101220450	0101220433	01/01/11	50-220 Q
0101210648	0101210645	01/01/23	50-346 Q	0101220456	0101220452	01/01/15	50-338 B
0101210651	0101210650	01/01/19	50-346 Q	0101220462	0101220459	01/01/16	50-271 B
0101210654	0101210650	01/01/19	50-346 Q	0101220492	0101220485	01/01/12	50-281 Q
0101210655	0101210652	01/01/08	50-271 Q	0101220496	0101220488	01/01/12	50-277 B
0101210659	0101210652	01/01/08	50-271 Q	0101220505	0101220499	01/01/14	50-327 B
0101210659	0101210656	01/01/09	50-341 Q	0101220510	0101220506	01/01/12	50-483 B
0101210660	0101210652	01/01/08	50-271 Q	0101220516	0101220506	01/01/12	50-483 B
0101210661	0101210652	01/01/08	50-271 Q	0101220518	0101220511	01/01/14	50-327 B
0101210662	0101210656	01/01/09	50-341 Q	0101220525	0101220520	01/01/12	50-508 Q
0101210663	0101210652	01/01/08	50-271 Q	0101220531	0101220520	01/01/12	50-508 Q
0101210665	0101210652	01/01/08	50-271 Q	0101220532	0101220523	01/01/15	50-327 B
0101210668	0101210652	01/01/08	50-271 Q	0101220534	0101220528	01/01/20	TOPREP
0101210669	0101210652	01/01/08	50-271 Q	0101220535	0101220520	01/01/12	50-508 Q
0101210671	0101210652	01/01/08	50-271 Q	0101220543	0101220520	01/01/12	50-508 Q
0101220021	0101220018	01/01/08	50-312 F	0101220546	0101220540	01/01/21	50-277 Q
0101220044	0101220043	01/01/16	50-438 K	0101220553	0101220548	01/01/02	50-267 P
0101220050	0101220055	01/01/07	50-566 Q	0101220569	0101220563	01/01/16	50-321 P
0101220060	0101220055	01/01/07	50-566 Q	0101220577	0101220574	01/01/12	70-371
0101220062	0101220055	01/01/07	50-566 Q	0101220581	0101220574	01/01/12	70-371
0101220066	0101220059	01/01/07	50-566 Q	0101220582	0101220575	01/01/15	50-346 P
0101220095	0101220091	01/01/02	50-595 Q	0101220584	0101220574	01/01/12	70-371
0101220102	0101220100	01/01/16	50-315 Q	0101220588	0101220587	01/01/12	70-371
0101220114	0101220110	01/01/07	50-309 Q	0101220593	0101220584	01/01/12	XPORTRLIC
0101220121	0101220116	01/01/09	50-440 Q	0101220616	0101220466	01/01/26	50-3 P
0101220122	0101220109	01/01/08	50-329 A	0101220629	0101220574	01/01/12	70-371
0101220135	0101220126	01/01/17	50-277 Q	0101220632	0101220574	01/01/12	70-371
0101220138	0101220133	01/01/05	50-369 A	0101220634	0101220574	01/01/12	70-371
0101220140	0101220130	01/01/13	50-247 Q	0101220636	0101220574	01/01/12	70-371
0101220141	0101220126	01/01/17	50-277 Q	0101220638	0101220632	01/01/13	70-1308
0101220147	0101220130	01/01/13	50-247 Q	0101220643	0101220632	01/01/13	70-1308
0101220149	0101220126	01/01/17	50-277 Q	0101220654	0101220649	01/01/07	70-1308
0101220153	0101220126	01/01/17	50-277 Q	0101220659	0101220649	01/01/07	70-1308
0101220161	0101220126	01/01/17	50-277 Q	0101220666	0101220658	01/01/08	50-261 F
0101220164	0101220159	01/01/15	50-327 R	01012206109	01012206103	01/01/14	50-338 Q
0101220169	0101220126	01/01/17	50-277 Q	0101220617	0101220618	01/01/15	50-361 Q
0101220186	0101220182	01/01/09	50-255 Q	0101220678	0101220172	01/01/14	50-461 Q
0101220197	0101220192	01/01/06	70-1257	0101220622	0101220211	01/01/20	TOPREP
0101220200	0101220196	01/01/09	50-255 Q	0101220623	0101220218	01/01/02	70-820
0101220211	0101220207	01/01/14	50-553 A	0101220626	0101220275	01/01/18	71-409
0101220265	0101220262	01/01/15	50-395 A	0101220630	0101220298	01/01/20	50-311 P
0101220274	0101220270	01/01/13	50-344 P	0101220632	0101220298	01/01/20	50-311 P
0101220279	0101220270	01/01/13	50-344 P	0101220636	0101220298	01/01/20	50-311 P
0101220333	0101220328	01/01/19	50-338 P	0101220637	0101220319	01/01/14	70-882
0101220343	0101220335	01/01/14	50-331 S	0101220638	0101220319	01/01/14	70-882
0101220346	0101220340	01/01/16	50-339 P	0101220639	0101220326	01/01/15	50-277 F
0101220349	0101220344	01/01/16	50-364 P	0101220640	0101220326	01/01/15	50-277 F
0101220357	0101220354	01/01/19	50-280 P	0101220641	0101220406	01/01/15	50-395 A
0101220363	0101220359	01/01/09	50-348 P	0101220643	0101220411	01/01/15	50-336 R
0101220365	0101220359	01/01/09	50-348 P	0101220643	0101220428	01/01/14	50-250 P
0101220370	0101220369	01/01/16	50-339 P	0101220645	0101220446	01/01/13	50-321 B
0101220373	0101220372	01/01/15	50-438 A	0101220646	0101220446	01/01/13	50-366 B
0101220373	0101220372	01/01/15	50-438 A	0101220647	0101220447	01/01/19	50-302 S
0101220374	0101220368	01/01/19	50-10 P	0101220648	0101220446	01/01/29	50-237 P
0101220375	0101220372	01/01/15	50-438 A	0101220649	0101220457	01/01/20	50-318 B
0101220375	0101220372	01/01/15	50-438 A	0101220653	0101220454	01/01/13	50-321 B
0101220377	0101220372	01/01/15	50-438 A	0101220659	0101220466	01/01/13	50-366 B
0101220379	0101220368	01/01/19	50-10 P	0101220671	0101220465	01/01/15	50-334 B
0101220380	0101220378	01/01/16	50-269 S	0101220673	0101220465	01/01/15	50-334 B
0101220384	0101220382	01/01/14	50-334 S	0101220678	0101220475	01/01/19	50-334 S
0101220385	0101220381	01/01/14	50-331 S	0101220680	0101220477	01/01/13	50-206 P
0101220387	0101220382	01/01/14	50-334 S	0101220683	0101220479	01/01/20	50-255 S
0101220390	0101220388	01/01/08	50-318 S	0101220691	0101220489	01/01/19	50-269 B
0101220391	0101220388	01/01/19	50-10 P	0101220694	0101220490	01/01/20	50-263 Q
0101220392	0101220382	01/01/14	50-334 S	0101220696	0101220493	01/01/12	50-369 A

	DOCUMENT	ISSUED	CATEGORY	ENCLOSURE	DOCUMENT	ISSUED	CATEGORY
B101230503	B101230501	80/12/31	50-237 P	B101260624	B101260611	81/01/15	50-259 F
B101230504	B101230501	80/12/31	50-237 P	B101260626	B101260647	81/01/15	50-321 S
B101230505	B101230501	80/12/31	50-237 P	B101260634	B101260548	81/01/20	50-334 S
B101230507	B101230504	B1/01/08	0A999	B101260637	B101260631	81/01/16	50-324 F
B101230508	B101230506	B1/01/08	0A999	B101260642	B101260552	81/01/15	50-272 S
B101230509	B101230506	B1/01/08	0A999	B101260644	B101260631	81/01/16	50-324 F
B101230510	B101230506	B1/01/08	0A999	B101260649	B101260616	81/01/23	TOPREP
B101230524	B101230522	80/12/18	50-250 P	B101260650	B101260652	81/01/15	50-272 S
B101230526	B101230523	81/01/20	50-317 S	B101260652	B101260616	81/01/20	TOPREP
B101230531	B101230530	81/01/16	50-255 S	B101260657	B101260614	81/01/20	TOPREP
B101230535	B101230533	81/01/20	50-155 S	B101260658	B101260570	81/01/11	50-249 S
B101230537	B101230536	81/01/13	50-313 P	B101260664	B101260581	81/01/16	50-219 G
B101230540	B101230538	81/01/19	50-317 G	B101260671	B101260587	81/01/14	50-237 G
B101230541	B101230537	81/01/21	50-317 Q	B101260673	B101260673	81/01/16	50-313 F
B101230548	B101230546	81/01/14	50-219 R	B101260675	B101260673	81/01/16	50-313 F
B101230556	B101230551	81/01/15	50-219 S	B101260688	B101260592	81/01/15	50-321 S
B101230564	B101230560	81/01/16	50-219 S	B101260689	B101260675	81/01/12	50-295 Q
B101230566	B101230558	81/01/21	50-250 P	B101260693	B101260611	81/01/15	50-259 F
B101230574	B101230569	81/01/16	50-219 S	B101260705	B101260611	81/01/15	50-259 F
B101230601	B101230593	81/01/15	50-339 S	B101260707	B101260693	81/01/12	50-454 Q
B101230602	B101230598	81/01/16	50-312 S	B101260718	B101260714	81/01/16	50-321 F
B101230611	B101230609	81/01/16	50-280 S	B101260724	B101260714	81/01/16	50-321 F
B101230672	B101230667	80/12/11	50-409 Q	B101260729	B101260720	80/12/10	50-346 Q
B101230687	B101230678	80/12/12	50-374 Q	B101260738	B101260732	81/01/16	50-235 F
B101260034	B101260025	80/12/31	F01A	B101260743	B101260732	81/01/16	50-255 F
B101260043	B101260025	80/12/31	50-289 H	B101260776	B101260772	80/12/10	70-135
B101260052	B101260025	80/12/31	F01A	B101260782	B101260772	80/12/10	70-135
B101260060	B101260025	80/12/31	50-289 H	B101260787	B101260772	80/12/10	70-135
B101260064	B101260056	80/11/05	0A999	B101260841	B101260838	80/12/31	REC00
B101260065	B101260029	80/12/31	50-289 H	B101270049	B101270044	80/11/10	40-1162
B101260072	B101260025	80/12/31	50-289 H	B101270062	B101270056	81/01/07	State Prog
B101260081	B101260025	80/12/31	50-289 H	B101270070	B101270064	81/01/22	50-408 Q
B101260087	B101260029	80/12/31	F01A	B101270122	B101270118	80/12/02	27-47
B101260091	B101260025	80/12/31	50-320 H	B101270126	B101270124	80/12/18	71-404
B101260099	B101260025	80/12/31	50-320 H	B101270137	B101270133	80/12/18	71-9145
B101260105	B101260025	80/12/31	50-320 P	B101270141	B101270130	80/12/15	50-409 P
B101260113	B101260025	80/12/31	50-320 P	B101270146	B101270143	80/12/17	71-9111
B101260120	B101260025	80/12/31	F01A	B101270156	B101270150	80/12/15	50-244 P
B101260124	B101260095	81/01/06	XPORL1C	B101270194	B101270190	81/01/13	50-247 Q
B101260128	B101260025	80/12/31	F01A	B101270205	B101270187	80/12/31	XPORL1C
B101260141	B101260025	80/12/31	50-320 P	B101270217	B101270193	81/01/15	40-1341
B101260151	B101260025	80/12/31	50-320 P	B101270231	B101270193	81/01/15	40-1341
B101260161	B101260025	80/12/31	F01A	B101270233	B101270218	80/12/31	XPORL1C
B101260173	B101260025	80/12/31	F01A	B101270234	B101270193	81/01/15	40-1341
B101260188	B101260025	80/12/31	F01A	B101270242	B101270193	81/01/15	40-1341
B101260192	B101260182	81/01/16	50-482 Q	B101270251	B101270193	81/01/15	40-1341
B101260201	B101260025	80/12/31	F01A	B101270255	B101270193	81/01/15	40-1341
B101260208	B101260025	80/12/31	F01A	B101270306	B101270295	81/01/16	50-528 Q
B101260218	B101260025	80/12/31	F01A	B101270342	B101270337	80/12/19	71-403
B101260222	B101260025	80/12/31	F01A	B101270353	B101270347	81/01/16	50-445 A
B101260224	B101260216	81/01/12	50-367 Q	B101270361	B101270358	81/01/19	50-289 T
B101260227	B101260025	80/12/31	F01A	B101270367	B101270358	81/01/19	50-289 T
B101260237	B101260025	80/12/31	F01A	B101270390	B101270385	81/01/21	50-329 K
B101260245	B101260234	81/01/08	50-320 Q	B101270436	B101270431	81/01/12	50-548 A
B101260247	B101260025	80/12/31	F01A	B101270470	B101270467	80/12/08	WASTE MOT
B101260255	B101260025	80/12/31	F01A	B101270473	B101270467	80/12/08	WASTE MOT
B101260260	B101260025	80/12/31	F01A	B101270508	B101270506	81/01/07	50-247 H
B101260267	B101260025	80/12/31	F01A	B101270519	B101270514	81/01/23	50-348 P
B101260276	B101260025	80/12/31	F01A	B101270520	B101270515	81/01/19	50-10 R
B101260282	B101260025	80/12/31	F01A	B101270526	B101270514	81/01/23	50-348 P
B101260288	B101260025	80/12/31	F01A	B101270557	B101270550	81/01/19	50-277 S
B101260298	B101260025	80/12/31	F01A	B101270564	B101270560	81/01/16	50-266 S
B101260308	B101260025	80/12/31	F01A	B101270569	B101270561	81/01/21	50-272 S
B101260314	B101260025	80/12/31	F01A	B101270574	B101270567	81/01/15	50-266 S
B101260317	B101260310	80/12/24	0A999	B101270578	B101270573	81/01/22	50-287 R
B101260319	B101260025	80/12/31	F01A	B101270579	B101270572	81/01/19	50-296 S
B101260329	B101260025	80/12/31	F01A	B101270585	B101270577	81/01/19	50-368 S
B101260334	B101260025	80/12/31	F01A	B101270586	B101270582	81/01/21	50-330 S
B101260339	B101260025	80/12/31	F01A	B101270587	B101270583	80/12/30	WASTE
B101260389	B101260384	81/01/19	50-313 P	B101270593	B101270590	81/01/21	50-334 S
B101260420	B101260416	81/01/20	50-327 P	B101270595	B101270587	81/01/21	50-325 S
B101260468	B101260463	81/01/10	50-321 H	B101270606	B101270600	81/01/23	50-324 S
B101260473	B101260470	81/01/16	50-322 A	B101270613	B101270608	81/01/19	50-249 S
B101260493	B101260487	81/01/15	50-346 P	B101270631	B101270627	81/01/20	50-325 S
B101260509	B101260507	81/01/19	50-289 P	B101270636	B101270634	81/01/21	50-316 S
B101260527	B101260525	81/01/10	50-366 R	B101270645	B101270641	80/12/19	50-298 S
B101260542	B101260539	81/01/14	50-317 H	B101270646	B101270642	81/01/20	50-353 A
B101260547	B101260344	81/01/19	50-293 S	B101270650	B101270643	81/01/22	50-287 S
B101260614	B101260601	81/01/15	50-321 S	B101270651	B101270642	81/01/20	50-358 A
B101260619	B101260611	81/01/15	50-329 F	B101270653	B101270649	80/12/16	50-276 S

ACCESSION NUMBER					ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8101270655	8101270642	81/01/20	50-358 A		8101280303	8101280488	80/12/03	50-482 Q	
8101270658	8101270635	81/01/21	50-282 S		8101280505	8101280488	80/12/03	50-482 Q	
8101270671	8101270637	81/01/16	50-320 S		8101280522	8101280518	81/01/21	50-305 S	
8101270673	8101270668	81/01/17	50-296 S		8101280528	8101280518	81/01/21	50-305 S	
8101270678	8101270675	81/01/23	50-322 S		8101280530	8101280516	80/12/05	50-482 Q	
8101270680	8101270640	81/01/20	50-270 S		8101280535	8101280518	81/01/21	50-305 S	
8101270683	8101270675	81/01/23	50-322 Q		8101280540	8101280536	80/12/04	40-1162	
8101270684	8101270677	81/01/21	50-318 S		8101280546	8101280539	81/01/22	50-344 S	
8101270685	8101270679	81/01/20	50-247 S		8101280551	8101280550	81/01/21	50-331 S	
8101270695	8101270688	81/01/21	50-324 S		8101280571	8101280563	81/01/23	50-261 S	
8101270697	8101270693	81/01/22	50-282 P		8101280585	8101280577	81/01/16	50-498 Q	
8101270700	8101270694	81/01/08	50-335 P		8101280622	8101280477	80/12/29	50-29 P	
8101270701	8101270689	81/01/20	50-346 S		8101280625	8101280621	81/01/13	50-289 H	
8101270708	8101270703	81/01/20	50-324 S		8101290017	8101290011	81/01/09	50-413 Q	
8101270710	8101270694	81/01/09	50-266 S		8101290020	8101290012	81/01/23	50-329 Q	
8101270711	8101270705	81/01/21	50-296 S		8101290022	8101290011	81/01/09	50-413 Q	
8101270714	8101270709	81/01/27	TOPREP		8101290025	8101290012	81/01/23	50-329 Q	
8101270716	8101270713	81/01/20	50-296 S		8101290040	8101290033	80/12/29	50-259 P	
8101270719	8101270715	81/01/13	50-298 S		8101290046	8101290033	80/12/29	50-259 P	
8101270722	8101270717	81/01/22	50-286 S		8101290052	8101290033	80/12/29	50-259 P	
8101270723	8101270706	80/12/30	50-320 P		8101290066	8101290062	80/11/10	NUREG	
8101270726	8101270721	81/01/22	50-289 S		8101290067	8101290035	81/01/13	FOIA	
8101270729	8101270724	81/01/20	50-247 S		8101290069	8101290057	81/01/26	50-461 Q	
8101270733	8101270730	81/01/15	50-295 S		8101290070	8101290063	81/01/07	40-0200	
8101270741	8101270734	81/01/21	CONTRACT		8101290075	8101290055	81/01/13	FOIA	
8101270755	8101270740	81/01/07	50-265 S		8101290082	8101290055	81/01/13	FOIA	
8101270770	8101270763	81/01/06	50-254 S		8101290083	8101290076	81/01/06	50-155 Q	
8101270782	8101270766	81/01/13	CONTRACT		8101290092	8101290055	81/01/13	FOIA	
8101270784	8101270775	81/01/14	50-290 S		8101290098	8101290055	81/01/13	FOIA	
8101270794	8101270788	81/01/22	50-324 S		8101290104	8101290055	81/01/13	FOIA	
8101270805	8101270797	81/01/12	50-269 P		8101290105	8101290096	81/01/16	CONTRACT	
8101270807	8101270800	81/01/23	50-324 S		8101290116	8101290055	81/01/13	FOIA	
8101270831	8101270825	81/01/06	50-272 P		8101290122	8101290099	80/12/11	50-329 Q	
8101270836	8101270825	81/01/06	50-272 P		8101290124	8101290055	81/01/13	FOIA	
8101270842	8101270825	81/01/06	50-272 P		8101290131	8101290055	81/01/13	FOIA	
8101270853	8101270830	81/01/16	50-483 Q		8101290134	8101290130	81/01/16	50-361 D	
8101270857	8101270257	80/12/16	50-498 A		8101290143	8101290055	81/01/13	FOIA	
8101270864	8101270860	81/01/08	50-155 Q		8101290151	8101290055	81/01/13	FOIA	
8101270878	8101270072	80/12/16	50-490 Q		8101290155	8101290149	81/01/26	50-498 Q	
8101270882	8101270879	80/12/11	COMMISSION		8101290159	8101290055	81/01/13	FOIA	
8101270909	8101270904	80/12/23	50-498 Q		8101290166	8101290152	80/12/10	50-546 Q	
8101270924	8101270918	80/12/16	50-498 A		8101290169	8101290160	81/01/08	50-440 Q	
8101270937	8101270934	81/01/09	71-398		8101290171	8101290055	81/01/13	FOIA	
8101270949	8101270944	80/12/16	40-8502		8101290176	8101290055	81/01/13	FOIA	
8101270955	8101270951	81/01/03	0A999		8101290188	8101290055	81/01/13	FOIA	
8101270958	8101270951	81/01/05	0A999		8101290205	8101290055	81/01/13	FOIA	
8101270963	8101270951	81/01/05	0A999		8101290208	8101290203	80/08/14	50-320 P	
8101270965	8101270951	81/01/05	0A999		8101290214	8101290203	80/08/14	50-320 P	
8101270975	8101270970	80/11/17	0A999		8101290220	8101290203	80/08/14	50-320 P	
8101280075	8101280060	81/01/02	27-39		8101290237	8101290055	81/01/13	FOIA	
8101280077	8101280062	81/01/23	50-358 Q		8101290240	8101290227	81/01/16	50-320 H	
8101280082	8101280078	81/01/21	50-335 P		8101290246	8101290055	81/01/13	FOIA	
8101280087	8101280083	81/01/20	50-219 R		8101290255	8101290055	81/01/13	FOIA	
8101280114	8101280105	81/01/26	50-307 Q		8101290261	8101290055	81/01/13	FOIA	
8101280158	8101280151	81/01/23	50-387 A		8101290269	8101290262	81/01/22	50-438 R	
8101280171	8101280178	81/01/22	50-70 F		8101290271	8101290055	81/01/13	FOIA	
8101280197	8101280189	81/01/10	50-321 R		8101290281	8101290055	81/01/13	FOIA	
8101280210	8101280205	80/12/16	40-3453		8101290283	8101290270	80/12/18	50-329 Q	
8101280222	8101280212	81/01/23	50-322 Q		8101290287	8101290055	81/01/13	FOIA	
8101280232	8101280228	81/01/20	50-324 S		8101290290	8101290055	81/01/13	FOIA	
8101280271	8101280288	81/01/23	50-348 S		8101290298	8101290055	81/01/13	FOIA	
8101280275	8101280288	81/01/23	50-348 S		8101290304	8101290055	81/01/13	FOIA	
8101280302	8101280297	81/01/20	50-312 S		8101290308	8101290302	81/01/26	50-309 R	
8101280311	8101280311	81/01/21	50-289 Q		8101290310	8101290055	81/01/13	FOIA	
8101280355	8101280355	81/01/21	50-247 P		8101290313	8101290055	81/01/13	FOIA	
8101280365	8101280365	81/01/21	FOIA		8101290317	8101290055	81/01/13	FOIA	
8101280365	8101280365	81/01/21	50-247 P		8101290324	8101290055	81/01/13	FOIA	
8101280365	8101280365	81/01/21	50-247 P		8101290330	8101290055	81/01/13	FOIA	
8101280365	8101280365	81/01/21	50-320 P		8101290335	8101290055	81/01/13	FOIA	
8101280365	8101280365	81/01/21	50-320 P		8101290341	8101290337	80/12/29	CONTRACT	
8101280365	8101280365	81/01/21	50-320 P		8101290343	8101290055	81/01/13	FOIA	
8101280365	8101280365	81/01/21	50-320 P		8101290349	8101290055	81/01/13	FOIA	
8101280365	8101280365	81/01/21	50-320 P		8101290360	8101290055	81/01/13	FOIA	
8101280365	8101280365	81/01/21	50-320 P		8101290361	8101290359	80/12/19	50-335 Q	
8101280365	8101280365	81/01/21	50-320 P		8101290369	8101290363	80/12/15	50-389 Q	
8101280365	8101280365	81/01/21	50-320 P		8101290378	8101290373	80/12/09	50-390 Q	
8101280365	8101280365	81/01/21	50-320 P		8101290386	8101290381	80/12/12	50-280 Q	
8101280365	8101280365	81/01/21	50-320 P		8101290397	8101290392	81/01/07	10CFR	
8101280365	8101280365	81/01/21	50-320 P		8101290405	8101290392	81/01/07	10CFR	
8101280365	8101280365	81/01/21	50-320 P		8101290410	8101290392	81/01/07	10CFR	

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
B101290115	B101290392	81/01/07	10CFR	B101300164	B101300157	80/11/17	70-1100
B101290120	B101290392	81/01/07	10CFR	B101300168	B101300161	81/01/13	50-498 Q
B101290432	B101290428	80/12/18	50-295 Q	B101300169	B101300157	80/11/17	70-1100
B101290438	B101290434	80/12/18	50-294 Q	B101300173	B101300157	80/11/17	70-1100
B101290449	B101290444	80/12/19	50-331 Q	B101300176	B101300161	81/01/13	50-498 Q
B101290482	B101290478	81/01/12	50-339 P	B101300177	B101300157	80/11/17	70-1100
B101290491	B101290486	80/12/22	50-440 P	B101300182	B101300161	81/01/13	50-498 Q
B101290494	B101290487	80/12/16	50-498 Q	B101300187	B101300183	81/01/26	CONTRACT
B101290506	B101290499	81/01/29	50-346 Q	B101300196	B101300191	80/11/14	70-135
B101290521	B101290516	81/01/23	50-315 S	B101300206	B101300198	81/01/14	50-309 H
B101290527	B101290522	81/01/19	70-754	B101300212	B101300203	81/01/06	50-289 P
B101290528	B101290523	81/01/26	50-195 S	B101300239	B101300223	80/12/19	50-250 P
B101290529	B101290522	81/01/19	70-754	B101300250	B101300223	80/12/19	50-250 P
B101290540	B101290536	81/01/29	50-313 R	B101300254	B101300233	81/01/13	50-237 P
B101290541	B101290538	81/10/29	50-70 P	B101300261	B101300223	80/12/19	50-250 P
B101290542	B101290537	80/12/04	70-734	B101300262	B101300248	80/12/12	50-244 P
B101290549	B101290544	80/12/19	50-518 Q	B101300291	B101300285	80/12/26	CONTRACT
B101290563	B101290558	80/12/16	50-358 Q	B101300294	B101300276	80/12/19	50-282 Q
B101290565	B101290561	80/12/19	50-224 Q	B101300300	B101300276	80/12/19	50-202 Q
B101290568	B101290553	81/01/19	50-213 S	B101300316	B101300312	81/01/26	CONTRACT
B101290573	B101290567	80/12/18	50-282 Q	B101300325	B101300320	81/01/26	CONTRACT
B101290574	B101290569	80/12/16	50-142 Q	B101300328	B101300318	80/12/31	50-295 P
B101290589	B101290583	81/01/27	50-244 F	B101300337	B101300332	81/01/12	CONTRACT
B101290599	B101290594	80/12/19	50-269 F	B101300338	B101300318	80/12/31	50-295 P
B101290608	B101290594	81/01/26	50-269 F	B101300349	B101300344	81/01/26	CONTRACT
B101290618	B101290613	81/01/27	50-317 F	B101300355	B101300351	80/11/28	50-255 Q
B101290621	B101290613	81/01/27	50-317 F	B101300361	B101300351	80/11/28	50-255 Q
B101290622	B101290617	80/12/10	50-261 P	B101300365	B101300359	81/01/26	CONTRACT
B101290625	B101290617	80/12/10	50-261 P	B101300373	B101300358	81/01/17	50-220 P
B101290626	B101290623	80/11/29	70-2529	B101300377	B101300367	80/10/20	50-255 P
B101290631	B101290624	81/01/27	50-134 X	B101300381	B101300372	81/01/26	CONTRACT
B101290637	B101290624	81/01/27	50-134 X	B101300383	B101300367	80/10/20	50-255 P
B101290646	B101290643	80/12/16	50-397 Q	B101300389	B101300379	81/01/13	50-293 P
B101290652	B101290648	81/01/27	50-289 F	B101300390	B101300357	80/10/20	50-255 P
B101290654	B101290649	80/12/16	WASTE MGT	B101300395	B101300386	81/01/13	50-263 P
B101290662	B101290657	81/01/26	50-289 P	B101300406	B101300378	81/01/26	CONTRACT
B101290666	B101290657	81/01/26	50-289 P	B101300409	B101300396	81/01/13	50-298 P
B101290667	B101290659	81/01/02	50-263 H	B101300410	B101300403	81/01/20	50-206 P
B101290675	B101290669	81/01/14	50-311 T	B101300411	B101300402	81/01/13	50-271 P
B101290676	B101290671	81/01/14	50-247 P	B101300416	B101300405	81/01/13	10CFR
B101290729	B101290722	81/01/26	50-289 T	B101300423	B101300413	81/01/14	50-546 Q
B101290734	B101290722	81/01/26	50-269 T	B101300429	B101300398	81/01/28	50-424 A
B101290737	B101290722	81/01/26	50-289 T	B101300430	B101300417	81/01/13	50-331 P
B101290746	B101290742	81/01/23	50-282 S	B101300433	B101300427	80/12/22	50-272 P
B101290749	B101290742	81/01/23	50-282 S	B101300437	B101300427	80/12/22	50-272 P
B101290750	B101290754	80/11/12	70-820	B101300442	B101300437	80/12/22	50-272 P
B101290759	B101290755	81/01/26	50-289 P	B101300440	B101300434	81/01/13	50-259 P
B101290762	B101290755	81/01/26	50-289 P	B101300463	B101300454	80/12/18	50-280 P
B101290766	B101290755	81/01/26	50-289 P	B101300467	B101300444	81/01/13	50-259 P
B101290770	B101290768	81/01/14	50-341 Q	B101300473	B101300454	80/12/18	50-280 P
B101290771	B101290755	81/01/26	50-289 P	B101300491	B101300486	81/01/15	50-251 P
B101290781	B101290779	80/11/25	50-334 Q	B101300495	B101300486	81/01/15	50-251 P
B101290789	B101290783	81/01/06	50-483 H	B101300497	B101300486	81/01/15	50-251 P
B101290791	B101290786	81/01/19	50-10 P	B101300507	B101300502	80/12/01	50-325 S
B101290798	B101290794	81/01/26	CONTRACT	B101300512	B101300501	81/01/26	50-260 S
B101290802	B101290799	81/01/14	50-336 P	B101300514	B101300511	81/01/26	50-296 S
B101290804	B101290799	81/01/14	50-336 P	B101300519	B101300513	81/01/23	50-285 S
B101290807	B101290799	81/01/14	50-336 P	B101300520	B101300504	81/01/27	50-296 S
B101300019	B101300014	80/11/13	50-220 Q	B101300523	B101300507	81/01/22	50-327 S
B101300030	B101300026	80/11/07	50-309 Q	B101300530	B101300523	81/01/23	50-317 S
B101300033	B101300021	81/01/06	50-352 H	B101300538	B101300533	81/01/26	50-318 S
B101300040	B101300034	80/11/12	50-219 Q	B101300554	B101300550	81/01/21	50-346 Q
B101300050	B101300042	81/01/16	50-261 P	B101300563	B101300560	81/01/21	50-305 Q
B101300057	B101300042	81/01/16	50-261 P	B101300571	B101300566	81/01/21	50-346 Q
B101300065	B101300042	81/01/16	50-261 P	B101300572	B101300568	80/12/01	50-325 S
B101300067	B101300059	80/11/03	50-334 Q	B101300577	B101300574	81/01/21	50-254 Q
B101300073	B101300070	81/01/09	50-315 Q	B101300578	B101300576	81/01/09	50-270 S
B101300074	B101300068	80/11/17	50-333 Q	B101300587	B101300586	81/01/26	50-238 R
B101300075	B101300069	81/01/26	CONTRACT	B101300588	B101300583	81/01/26	50-460 Q
B101300080	B101300068	80/11/17	50-333 Q	B101300593	B101300583	81/01/26	50-460 Q
B101300082	B101300077	81/01/12	50-29 P	B101300596	B101300592	81/01/22	50-286 P
B101300085	B101300077	81/01/12	50-29 P	B101300597	B101300592	81/01/09	50-339 S
B101300087	B101300068	80/11/17	50-333 Q	B101300598	B101300583	81/01/26	50-460 Q
B101300089	B101300077	81/01/12	50-29 P	B101300604	B101300583	81/01/26	50-460 Q
B101300093	B101300086	81/01/26	CONTRACT	B101300614	B101300609	81/01/19	50-285 P
B101300104	B101300097	81/01/26	50-390 A	B101300615	B101300611	81/01/27	50-296 S
B101300107	B101300068	80/11/17	50-333 Q	B101300624	B101300609	81/01/19	50-285 P
B101300126	B101300120	80/11/14	EXPORT LIC	B101300629	B101300620	81/01/26	50-259 S
B101300138	B101300134	80/11/09	50-317 Q	B101300641	B101300632	81/01/24	50-296 S
B101300151	B101300143	80/11/10	50-3 Q	B101300696	B101300691	81/01/06	50-263 E

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8101300714	8101300706	81/01/26	50-339 S
8101300715	8101300711	81/01/19	50-224 P
8101300726	8101300703	81/01/26	50-29 S
8101300727	8101300720	80/11/05	50-245 G
8101300728	8101300722	81/01/26	50-275 F
8101300733	8101300722	81/01/26	50-275 F
8101300728	8101300731	81/01/06	50-334 P
8101300740	8101300734	80/11/10	50-286 G
8101300752	8101300730	81/01/14	50-295 F
8101300754	8101300733	81/01/14	50-295 P

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8101300747	8101300753	81/01/13	50-333 P
8101300759	8101300756	81/01/14	50-361 Q
8101300763	8101300756	81/01/14	50-361 Q
8101300766	8101300756	81/01/14	50-361 Q
8101300771	8101300756	81/01/14	50-361 Q
8101300791	8101300788	80/12/17	50-155 Q
8101300796	8101300788	80/12/17	50-155 Q
8101300820	8101300816	81/01/15	50-295 P
8101300827	8101300816	81/01/15	50-295 P
8101300841	8101300836	81/01/14	50-413 A

DEFINITIONS OF DOCKET 50 CATEGORIES

A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

1. Application for construction permit.
2. General Information submitted with construction permit application.
3. Amendments and changes to items 1 and 2.
4. NRC questions, requests for additional information, and applicant responses.
5. Correspondence and documents relating to unresolved design and construction issues.
6. Meeting announcements and summaries of meeting discussions on issues of item 5.
7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
9. Construction Permit, amendments, and correspondence relating to the construction permit.
10. Scheduling of license application submission or review.
11. Environmental review information.
12. Application for operating license.
13. General Information submitted with operating license application.
14. Amendments and changes to items 12 and 13.
15. Correspondence regarding the Final Safety Analysis Report (FSAR).
16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
17. Reports of site visits.
18. Backup technical documents (e.g., topical reports) submitted in support of the application.

B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
2. Amendments and changes to the PSAR.

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

1. Environmental Report (ER) submitted by the utility.
2. Amendments and supplements to the ER.
3. Transmittal and acknowledgement letters.
4. Information on scheduling of submittal or review of ER.
5. NRC questions, requests for additional information, and applicant responses.
6. Federal register notices citing the availability of items 1 and 2.
7. Correspondence relating to the review of ER.
8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
2. Supplements to the DES and FES.
3. Correspondence relating to the DES and FES.
4. Comments from other federal, state and local government agencies.
5. Transmittal and acknowledgement letters.
6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
7. Backup technical documents submitted in connection with above.
8. Federal register notice citing availability of items 1 and 2.
9. Site visits to obtain information for DES or FES.
10. Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process.

3. Correspondence relating to SER.
4. Federal register notices citing availability of items 1 and 2.
5. *Information on scheduling of SER submittals and review.*
6. Requests for additional information for use in preparing SER; responses to such requests.
7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
8. Transmittal and acknowledgement letters.

F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

1. Fire Hazard Protection Plan and surveys.
2. Plant evacuation correspondence.
3. Safeguards Contingency Plans.
4. *Review of Health Physics Program.*
5. Correspondence relating to aforementioned plans.
6. Supplements, changes and revisions to plans.

G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

1. *Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.*
2. Federal register notices regarding hearings.
3. Requests to make appearances at hearings.
4. *Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.*
5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
6. Correspondence to and from intervenors.
7. Board orders and decisions.
8. Petitions for Commission action.
9. *Legal filings and Commission orders and decisions resulting from item 8.*

2. Changes in structure of organization.
3. Changes in service lists.
4. NRC requests to applicant for additional copies of documents.
5. Correspondence from the public requesting information about the facility and NRC responses.
6. Correspondence on strictly administrative matters.
7. Letters of support, concern or opposition to the facility.
8. Correspondence regarding the Local Public Document Rooms (LPDRs).
9. Professional qualification statements not pertaining to the hearing process.

I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

1. Company annual reports.
2. Separately submitted financial information and related correspondence.

J. INSURANCE AND INDEMNITY INFORMATION

1. Indemnity agreements and amendments.
2. Endorsements insurance policies.
3. Other correspondence regarding indemnity and insurance matters.

K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
2. Amendments and changes to the FSAR.
3. Federal register notices citing availability of items 1 and 2.
4. Transmittal and acknowledgement letters.
5. Certificates of service to the FSAR.

1. Limited Work Authorizations (LWA) and amendments.
2. Correspondence pertaining to work performed under LWA's.

M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review".
2. Correspondence where the primary topic of discussion is antitrust matters.
3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
2. Correspondence from ACRS.
3. Announcement of ACRS meetings.
4. Transmittal and acknowledgement letters.
5. ACRS reports.
6. Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.
7. Minutes at ACRS Subcommittee Meetings.

P. OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

1. Operating license, amendments, proposed amendments, changes and related correspondence.
2. Technical specifications and changes.

of the operating license.

7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license.
8. Information on the Standard Review Plan (STP).
9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
11. Owner's group meeting announcements and reports.
12. Quality assurance information.
13. Environmental matters (technical).
14. Emergency core cooling system documents.
15. Radioactive waste information.
16. Correspondence regarding expansion of spent fuel storage pool.
17. Start-up test reports.
18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
19. Reports of site visits.

Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

1. Inspection reports.
2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
3. Responses by applicant to IE correspondence.
4. Applicant's determination of proprietary nature of inspection reports.
5. Letters concerning areas of noncompliance.
6. Pre-service and in-service inspections and procedures.
7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (EN's).
8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

2. Periodic environmental monitoring, effluent testing, or similar reports.
3. Periodic personnel exposure reports.
4. Operational Logbooks:
 - Logbooks on Environmental Data
 - Logbooks on Radiological Data
 - Operations Log on Plant Systems Core
 - Plant Status Summary Sheets.
5. Correspondence or other documents relating to the above listed items.

S. REPORTABLE OCCURRENCES, PNO'S, PNS'S AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes:

1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER's) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences).
2. Potential or possible reportable deficiency reports and related correspondence.
3. Personnel exposure reports.
4. Construction deficiency reports submitted under 10 CFR 50.55e.
5. Preliminary Notification of Occurrence (PNO's) and Preliminary Notification of Safeguards Events (PN's).
6. Environmental Technical Specifications violation reports and Environmental Event reports.
7. Part 21 Reports of defects and noncompliance.
8. Correspondence or other documents relating to items 1-7.

T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
2. Testimony and statements submitted to ASLB and ASLAB.
3. Commission meeting transcripts.
4. NRC staff briefings to the Commission.
5. Statements and written testimony submitted at Commission meeting or hearings.
6. Transcripts of utility briefs to NRC staff.
7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.

inquiries are filed in category H.

1. Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches.
2. Preparatory and backup documents for item 1.
3. Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters.

V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

1. Operator licenses or administrative information bearing on licensing of operators.
2. NRC examination results.
3. Power plant examination summary sheet.

W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward.

1. Application for authority to voluntarily surrender license.
2. Application to dismantle the facility and dispose of component parts.
3. Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
4. Documents relating to disposal of radioactive material and decontamination of the site.
5. Other correspondence relating to above items.
6. All documentation relating to the ongoing operation of the plan, formerly filed in category P.

DEFINITIONS OF NONDOCKETED CATEGORIES

10CFR – Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes:

1. *Sunshine Act Federal Register notices.*
2. *Full, written explanation of closed meetings.*
3. *Certification of General Counsel on closed meetings.*
4. *Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.*
5. *Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.*
6. *Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.*
7. *Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings.*

ACRS – Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

1. *Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.*
2. *ACRS meeting announcements; description of meeting agendas.*
3. *ACRS-generated reports, memoranda and correspondence that are publicly available.*
4. *ACRS consultant reports, comments and related correspondence.*
5. *ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.*

COMMISSION – NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including:

1. *Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.*

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

CONTRACT – NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
2. Solicitations (RFP or IFB) issued by the NRC.
3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
4. Contractual documents and contract modifications, if any.

DISCLOSURE – Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

FOIA – Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year—numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
3. Records or portions of records released in response to specific requests made under FOIA.

GEN TECH IS – Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.

I&E — Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.
2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

MISC — Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

NUREG — NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

1. These reports are normally final work products and are characterized by the following criteria:
 - a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
 - b. They present the results of Commission licensing and policy decisions.
 - c. They present the results of technical research conducted for the Commission.
2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

1. Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility; e.g., EPA has authority to control all radioactive pollutants emitted into the air.
3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

PR – Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
2. Text of the Proposed Rule (PR).
3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

PRM – Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
2. Federal Register cause notices of the filing of the petition.

- petition.
4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE: For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

PROJ – Projects–Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities; and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

1. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

A. Application/Construction Stage

1. Application submitted by the utility.
2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
3. Applicant's Quality Assurance Manual.
4. Early site review information.
5. Backup technical documents submitted in support of the application.
6. Early site visits.

B. Utility PSAR and Amendments

1. PSARs submitted by the utility.
2. Amendments and changes to the PSAR.
3. Transmittal letters.
4. Letters acknowledging receipt of the PSAR.

G. Adjudicatory Correspondence

1. Motions, briefs, orders, *et al.* pertaining to pre-hearing conferences, if any.

M. Antitrust Correspondence

1. Submittals and related material pertaining to the antitrust review.

3. Follow-up correspondence resolving deviations cited.

2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 – Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
3. NRC inspection reports of defects cited.
4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 – Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

1. NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
2. Notices of deviations.
3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

REGGD – Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC

staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are:

1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
2. Revised or newly issued Regulatory Guides.
3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE: For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

RES Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

1. Project description documents.
2. Letter reports of accomplishments and data reports; for example,
 - a. model documentation reports
 - b. code documentation reports
 - c. code verification reports
3. Pre-test prediction reports.
4. "Quick look" reports.
5. Informal experimental data reports and post-irradiation examination analyses.
6. Conceptual design descriptions.
7. Letter reports of foreign travel and site visits by contractors.
8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
10. Staff Research Information Letters (RIIs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

2. Summary minutes of review group meetings representing views expressed, including dissenting views.
3. Research plans and predicted results of major experiments; presentations by research contractors.
4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
5. Internal memoranda relating to topics under discussion.

RM – Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

1. Designations of the presiding officer and any special directions for the conduct of the hearing.
2. Notifications of hearing board meetings.
3. Petitions, motions, testimony and statements submitted by parties to the hearings.
4. Hearing board orders and rulings.
5. Technical reports submitted as evidence in the proceeding.
6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

SECY – Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

STATE PROG – State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting

of major and minor activities regarding such functions as licensing and siting. It includes:

1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:
 - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
 - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations, i.e. decommissioning and facility siting.
3. State Legislative Reports.
4. Agreement State Licensing Statistics Reports.

NOTE For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

TOPREP Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
2. Revisions, modifications and amendments to topical reports.
3. Correspondence between NRC and vendors pertaining to the review of submittals.
4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

WASTE MGT Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

XPORTLIC – Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
3. Commission letters requesting Executive Branch views.
4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
5. Correspondence from foreign governments, international organizations, and members of the public.
6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
7. Filings pursuant to hearing requests or intervention petitions, if any.
8. Hearing records and decisions.
9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

Title List of Documents Made Publicly Available January 1 11, 1981

AUTHOR(S)

FORMING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)

Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20545

SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)

Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20545

TYPE OF REPORT

Monthly

PERIOD COVERED (Inclusive dates)

SUPPLEMENTARY NOTES

ABSTRACT (200 words or less)

2 (Leave blank)

3 RECIPIENT'S ACCESSION NO

5. DATE REPORT COMPLETED

MONTH

February

YEAR

1981

DATE REPORT ISSUED

MONTH

April

YEAR

1981

6 (Leave blank)

8 (Leave blank)

10 PROJECT/TASK/WORK UNIT NO

11. CONTRACT NO

14 (Leave blank)

This document is a monthly publication containing descriptions of information received and generated by the US NRC. This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. The docketed information includes information formerly issued through the U.S. Department of Energy's Technical Information Center under the title *Power Reactor Docket Information (PRDI)*. This document replaces PRDI, which will no longer be prepared. This document contains the following indexes: Personal Author Index, Corporate Source Index, and Report Number Index.

KEY WORDS AND DESCRIPTOR ANALYSIS

17a DESCRIPTORS

IDENTIFIERS OPEN ENDED TERMS

21 NO. OF PAGES